Virtual Survey

- 1. File no.- VIS(2024-25)-PL065-056-075 SVIL Mines
- 2. The survey of one of Marble Mine was done located at Village Gudri, Katni, M.P.
- 3. The survey was done through video call connected by Security Guard Mr. Neeraj Yadav, mobile no. +91-9685951100 on 26/09/2024.
- 4. No proper documents were provided, virtual survey was done on the basis of OVR
- 5. The screenshots and screen recording was done during the virtual survey. The photographs of the property was also taken by the security guard during the survey.
- 6. The total land area of the plant was not covered during the virtual survey
- 7. The plant comprises of Factory Area, Admin Building Area & Workshop.
- 8. All the shed structure were GI shed structure except Shed no. 5 which consists of RCC+GI Shed structure and was half damaged due to fire.
- 9. Shed structure condition was average and water logging was found inside the factory structure.
- 10. There large number of finished marbles present on the marble stands with different sizes and qualities.
- 11. Plant was non-operational since long period of time. Some of the machines are kept in open or stored in water logged area. Electrical panel were fully deteriorated and observed to be
- 12. The Admin building (G+3) was under poor condition and significantly deteriorated.
- 13. There were other machines, such as excavators, loaders, trucks (Volvo), and hydras that were stored outside, not under the roof.
- 14. All the machines were verified on the basis of machine list given in the OVR provided and same was found on site through video call.
- 15. There were large number of marble blocks on the site.
- 16. DG set were in poor condition and most of the parts are missing from it.
- 17. Some machine parts were observed to be missing or stolen; however, according to the information provided, multiple security guards were deployed to safeguard the property following the theft.

For any query feel free to contact