

भारतीय विमानमत्त्र प्राधिकरण ARRORIS AUTHORITY OF NOA

Date: 10:06:2019

Valid Uptor 09-06-2027

No Objection Certificate for Height Clearance

le Die NOR learned by Airport Authorotyc John (AADen our nachtes possibility confered by and at per the provisions of Gove of Sud-(Ministry Cristi Aviation) unleades 8731 (E) that a large 2015 (695 at a great Regular Aircraft Operations.

2. This office in an objection to the construction of the proposed structure as beautie following details.

A STATE OF THE PARTY OF THE PAR	PALMINORTH/B#853019/401474
	Abbiebes Karpet-Gupta
Site Address*	OCHASRA NOS:31/16/2, 25/2, 31/14/1, 17/2, 18, 19/1, 19/2, 20, 21, 22, 35/11, 2/2, 37/1 AND 1 VILLAGE-KASSAR, SECTOR-13, BAHADURGARH, HARVANA, BABAGURGARHJA (Jaryana)
Market	
Site Coordinates	7653 7632 7634 7654 7653 7633 7633 7633 7653 33 56 28 42 07 99, 76 53 33 64 28 42 11 77, 7653 33 98 76 30 31, 76 33 34 62 28 42 07 86, 76 53 39 65 28 42 07 86, 76 53 39 66 28 42 06 19, 76 5 68 42 07 86, 76 53 39 66 28 42 06 19, 76 5
Sity Elevation in Inth's AMSE as submitted by Applicant*	215(CM)
Permissible Top Elevation in mirs Above Mean Sea Level(AMSL)	28S.61M

^{*}As provided by applicant

- 3. This NOC is subject to the terms and conditions as given below:
- a. Permissible Top elevation has been issued on the basis of Site coordinates and Site Elevation submitted by Applicant. AAI neither owns the responsibility on authenic airs the correctness of the site coordinates & site elevation provided by the applicant. If at any mage it intestablished that the actual light in different, this NOC will stand mill and void acid action will be taken as per law. The office in charge of the concentration may initiate action under the Aircraft (Demolition of Obstruction caused by Buildings and Trees etc.) Rules, 1994.
- b. The She coordinates as provided by the applicant in the NOC application has been ployed on the street west map, and satellite map as shown in ANNEXURE, Applicant/Dyne; to ensure that the plotted coordinates corresponds to his/her site in case of any discrepancy. Designated Officer shall be requested for cancellation of the NOC.
- c. Airport operator or his designated representative may visit the site (with prior coordination with applicant or owner) to ensure that NOC terms & conditions are complied with.
- d. The Structure height (including any superstructure) shall be calculated by subtracting the Site elevation in AMSL from the Permissible Top Elevation in AMSL i.e. Maximum Structure Height Permissible Top Elevation minus (-) Site Elevation.
- e. The issue of the NOC is further subject to the provisions of Section 9-A of the Indian Aircraft Act, 1934 and any notifications issued there under from time to time including the Aircraft (Demolition of Obstruction caused by Buildings and Trees etc.) Rules, 1994.

क्षेत्रीय मुख्यालय उत्तरी क्षेत्र, परिचालन कार्यालय परिसर रंगपुरी, नई दिल्ली - 110037 दूरभाष संख्या - 91-11-25653566 Regional headquarter Northern Region. Operational Offices Complex Rangpuri, New Delhi-110 037 Tel: 91-11-25653566

करिर्वाण "हिंदी पत्रों का स्वागत है।"

के के ए क्वीर / K. K. A. KABIR साम्रोतक (ब्रु शंकान्य प्रमान कार्य क्वी / Ceant Mainger (ATM), NR साम्योत विकास प्रमान (Ampute Authority of India प्रमान कर्यात (Operational Offices निर्मु गुल्या केंद्र स्ट्रिक्ट 37/Ranguri, Gunyran Road, Hen Delhi 37



- 6 No radio TA Antenna, lighting arresters, staucase, Munices Deethead water lank and attachments of fixtures of any find shall project above the Permissible Top Electron of 285 61M 64 MSD), as indicated by page 2.

- 1. The applicum will not complain compensation against aircraft hoise, vibrations, damages etc. caused by aircraft operations at or in the
- k. Day markings & night lighting with secondary power supply shall be provided as peralte guidelines specified in chapter 6 and appendix 6 of Civil Aviation Requirement Series B Part I Section 4, available on DGCA India website: www.dpca.nic.in
- L. The applicant is responsible to obtain all other statutory elemances from the concerned authorities including the approval of building plans. This NOS for height elemants is to entire the safe and regular approximant operations and shall not be used as document for any other purpose/claim obtained in high processing of land etc.
- m. This NOCID has been assessed w.r.t I.G.I Airport, Rohini Heliport, Safdarjung Airport Airport (s). NOC has been issued w.r.t, the AAI acrodromes and other licensed civil aerodromes as listed in Schedule-III, Schedule-IV(Part-1), Schedule-IV(Part-2;RCS Airports Only) and Schedule-VII of GSR751(E).
- n. Applicant needs to seek separate NOC from Defence; if the site lies within the jurisdiction of Defence Aerodromes as listed in Schedule-V of GSR751(E). As per Rule 13 of GSR751(E), applicants also need to seek NOC from the concerned State Govt. for sites which lies in the jurisdiction of unlicensed aerodromes as listed in Schedule-IV (Part-2:other than RCS airports) of GSR751(E).
- o. In case of any discrepancy/interpretation of NOC letter, English version shall be valid.
- p. In case of any dispute wat the elevation and/or AGL height; top elevation in AMSL shall prevail.

Chairman NOC Committee

Region Name: NORTH

Address:

General Manager Airports Authority of India, Regional Headquarter, Northern Region, Operational Offices, Gurgaon

Road, New Delhi-110037

Email ID: noc_nr@aai.aero

Contact No: 011-25653551

10.06.2019 के के ए कबीर / K. K. A. KABIR न्द्रवाकान (कर्षु बाजबन प्रकार जाती होन) General Abreson (ATE भारतीय विमानसतान प्राधिकरण Airports Authority of In प्रवास कार्यक / Operational Offices रंतुचै पुरुष हेत, ई देन्ती-17/Rangouri Geogram Road, New Deals 37


Name / Designation / Sign with Date

Prepared By:

Verified By:

क्षेत्रीय मुख्यालय उत्तरी क्षेत्र, परिचालन कार्यालय परिसर रंगपुरी, नई दिल्ली - 110037 दूरभाष संख्या - 91-11-25653566 Regional headquarter Northern Region, Operational Offices Complex Rangpuri, New Delhi-110 037 Tel: 91-11-25653568 " हिंदी पत्रों का स्वागत है ।"

The state of the s	Datanes From Neurest Airport And Bearing			
WIDOK Disease ?	District (Meters / from) Nearth AND	Penda (Pense) from 12457		
HOLAIRON	25903;69 V	303.53		
Robins Heliport	16804 To the control of the control	74988		
NOCID	Alle Alle Alle Alle Alle Alle Alle Alle	29,694		
Process of the second	PAEM/NORTH/B/053019/401	4.74		



Satellite View



HISTORY APPENDING TO BE WELL

Eleno. AAI/RHG/NR/ATM/NOC/20/5/257/999-7001

Copy to

- A Company of the Comp
- The Chief Executive Officer, Delhitotecrational Airport, New Udday Bhawain, I.G.) Airport Terrulpal, 3, New Delhi-110037.
- Standfile.

क्षेत्रीय मुख्यालय. उत्तरी क्षेत्र, प्रचालन कार्यालय: गुड्गांव रोड, नई दिल्ली—110037 दूरमाष : 25652447 फेक्स : 25656451 Regional Headquarters, Northern Region, Operational Offices, Gurgaon Road, New Delhl-110037 Tele.: 25652447 Fax : 25656451 "हिन्दी पत्रों का स्वागत है।" From Assemm Divisional Five OmcerFire Station Officer
Bahaduruarin

Co -: Mus Banjan Jela

AZ 28 IST FLOOR SECTOR IS ROHIN!

Memo No. F\$/2019/299 dated: 19/10/2019

659//-08

Subject: Renewal of No Objection Certificate 15 mt/s. and above height from the fire safety Point of View of the Group & Residential Building at VILLAGE KASSAR SECTION 15 BAHADURGARH DISTRICT THAT AND A KELDEVLOPERS BY LITE:

Reformed to your office No 070421923000243 dated 17705/2019 on the subjects fied Abbyo

Town Name	Fl66r Detail	Heland	90	ind Coverage
TOWER BY	\$612	den:	\$30	1722 SOM
TOWER AS ANDIAS	15x19	44.65 -44.65	378	1977 SOM 1 339 SOM
TOWER AS	S-113	41.65	437	MOS CILE
TOWER AT	S+12	38.60		8.531, SQ14
NH ₄	Basem	ent Area	emarks L	

Your site for the Renewal of the Fire NOC has been inspected by the Team of Fire Station Officers. Bahadurgarh from the satesy Point of View. The means of escape and Fire Protection system were checked and found as per the National Building Code of India, Parie IV guidelines:

In view of the suisfactory fire protection system / arrangement mentioned as above, this office has no objection for occupation from the Fire Safety point of view, with the following conditions:-

- 1) The owner/occupier shall keep duty trained Fire Staff in all three shifts.
- 2) The Fire Protection System tested during inspection shall be maintained properly & always should be in good working condition.
- 3) If any lapse is found in the fire protection system at the time of inspection or detected during outbreak of fire, action will be baken as per jules against you.
- A You are directed to apply for Broadwal of MOCIA totale before 2 month of exploy of your MOC.
- The open set but were larger themselves our ender it shall be theorethy concerned building apparential.
- The owner/occupier shall spirely follow the other applicable rules/regulations/ bythays laid down regarding the safety system. If you fail to comply walt any of the above terms & conditions you will be hable to be punished as per fire ordinance 2009 specially chapter. III Section 31 Sub-Section 1.2 2 of Fire Act 2009.
- 7) You have to perform quarterly Fire Drill in your building as per NBC with intimation to Fire Department and video graphy evidence to be kept as a record which shall be produced at the time of next Renewal; Officials/Residents/R.W.A. should be mentioned in the drill.
- 8) If the Infringements of Byelaws remains un-noticed the Authority reserves the right to amend the NOC as and when any such Infringements comes to notice after giving an opportunity of being heard and the Authority shall stand Indemnified against any claim on this account.

The above Renewal of NOC is valid for One year from the date of issue of this letter Applying renewal of the same well in time shall be the responsibility of owner/occupier.

Remarks:- Verification done



Fire Station Officer,
Digitally signed by TANKHI RAM
Participation 10.19 11:34:15
103:30

Exercising 1

Fire Station Officer,
Digitally signed by TANKHI RAM
Participation of the Station of the Station

