

STATUS OF MAIN EQUIPMENTS AS ON 18.9.96

SL. NO.	DESCRIPTION OF MAIN EQUIPMENTS	NAME OF MANUFACTURE	EXTENT OF DAMAGE	PROPOSED RESTORATION & SOURCE	ESTIMATED EXPENDITURE TO BE INCURRED	ALREADY INCURRED	EXPECTED DATE OF RESTORATION	JUSTIFICATION / STATUS
01.	OFFSET MACHINE	MAN ROLAND GERMANY	COMPLETELY DAMAGED	REPLACEMENT (KBA GERMANY)	485.00	--	DEC - JAN '97	LATEST TECHNOLOGY DEVELOPED HIGH POPULARITY WORLD WIDE AS WELL AS IN INDIA IN LAST COUPLE OF YEAR 3 INSTALLATION HAS BEEN MADE IN INDIA WHEREAS NO INSTALLATION FROM MAN ROLAND IN INDIA.
02.	GRAVURE MACHINE	KBA GERMANY	PARTLY DAMAGED	PARTS REPLACEMENT & REPAIR	103.50 150.00	--	OCT - NOV '97	OFFER FOR REPLACEMENT OBTAINED REPAIRING IS UNDER PROCESS.
03.	LABEL PRINTING MACHINE	PAKTEK TAIWAN	COMPLETELY DAMAGED	REPLACEMENT ITALY	66.50	--	JAN - FEB '97	HIGHER SPEED, MORE THROUGHPUT LATEST TECHNOLOGY, BETTER MACHINE
04.	AUTO DIE-CUTTING CREASING/PUNCHING	SUNGFA TAIWAN	COMPLETELY DAMAGED	REPLACEMENT (BOBST, SWITZERLAND)	68.00	--	DECEMBER '96	LEADER WORLDWIDE ESTABLISHED BASE IN INDIA LARGE NUMBER OF INSTALLATIONS, FASTER MACHINE
	AUTOMATIC FOLDING GLUING MACHINE LINEER FINING	PAKTEK TAIWAN	COMPLETELY DAMAGED	REPLACEMENT (BOBST, SWITZERLAND) KOHMAN, (GERMANY)	23.00 75.00	-- 1.25	DECEMBER '96	LEADER WORLDWIDE, FASTER MACHINE, EASY MAKE READY LESSER WASTAGE, BETTER QUALITY.
06.	CUTTING PUNCHING	PERFEETA GERMANY	PARTLY DAMAGED	REPLACEMENT REPAIR	7.00 5.00	-- 4.00	OCTOBER '96	REPAIRS ALMOST COMPLETED.
07.	P P LAMINATING	SHENG TAIWAN	PARTLY DAMAGED	REPAIRS	2.00	1.00	NOVEMBER '96	60% OF THE REPAIR WORK COMPLETE
08.	HEAT FOILING/ AUTOMATIC DIE EMBOSSEING PRESS	BRANDZEM USA	FULLY DAMAGED	--	--	--	MAY '97	TO BE INSTALLED LATER ON. IF REQUIRED.
09.	CALENDERING	SHENG TAIWAN	PARTLY DAMAGED	REPAIR	1.00	--	DECEMBER '96	REPAIRS UNDER PROCESS.
10.	PLATE MAKING	PAKTEK TAIWAN	COMPLETELY DAMAGED	REPLACEMENT	3.00	--	DECEMBER '96	OFFERS UNDER EVALUATION.
11.	PROOFING MACHINE	SHIN-CHIN TAIWAN	COMPLETELY DAMAGED	REPLACEMENT SPEED MALT (UK)	26.50	--	DECEMBER '96	ARRANGING IMPORT THROUGH OUR OWN FUND L/C APPLIED FOR. HIGHER SPEED & MORE STABLE AND BETTER QUALITY WITH BOTH SIDE PRINTING FACILITY.

STATUS OF MAIN EQUIPMENTS AS ON 18.9.96

SL. NO.	DESCRIPTION OF MAIN EQUIPMENTS	NAME OF MANUFACTURE	EXTENT OF DAMAGE	PROPOSED RESTORATION & SOURCE	ESTIMATED EXPENDITURE TO BE INCURRED	ALREADY INCURRED	EXPECTED DATE OF RESTORATION	JUSTIFICATION / STATUS
01.	OFFSET MACHINE	MAN ROLAND GERMANY	COMPLETELY DAMAGED	REPLACEMENT (KBA GERMANY)	485.00	--	DEC - JAN '97	LATEST TECHNOLOGY DEVELOPED HIGH POPULARITY WORLD WIDE AS WELL AS IN INDIA IN LAST COUPLE OF YEAR 3 INSTALLATION HAS BEEN MADE IN INDIA WHEREAS NO INSTALLATION FROM MAN ROLAND IN INDIA.
02.	GRAVURE MACHINE	KBA GERMANY	PARTLY DAMAGED	PARTS REPLACEMENT & REPAIR	103.50 150.00	---	OCT - NOV '97	OFFER FOR REPLACEMENT OBTAINED REPAIRING IS UNDER PROCESS.
03.	LABEL PRINTING MACHINE	PAKTEK TAIWAN	COMPLETELY DAMAGED	REPLACEMENT ITALY	66.50	---	JAN - FEB '97	HIGHER SPEED, MORE THROUGHPUT LATEST TECHNOLOGY, BETTER MACHINE.
04.	AUTO DIE-CUTTING CREASING/PUNCHING	SUNGFA TAIWAN	COMPLETELY DAMAGED	REPLACEMENT (BOBST, SWITZERLAND)	68.00	---	DECEMBER '96	LEADER WORLDWIDE ESTABLISHED BASE IN INDIA LARGE NUMBER OF INSTALLATIONS. FASTER MACHINE.
	AUTOMATIC FOLDING GLUING MACHINE LINER FIXING	PAKTEK TAIWAN	COMPLETELY DAMAGED	REPLACEMENT (BOBST, SWITZERLAND)	23.00	---	DECEMBER '96	LEADER WORLDWIDE, FASTER MACHINE, EASY MAKE READY LESSER WASTAGE, BETTER QUALITY.
				KOHMAN, (GERMANY)	75.00	1.25		
06.	CUTTING PUNCHING	PERFEETA GERMANY	PARTLY DAMAGED	REPLACEMENT REPAIR	7.00 5.00	--	OCTOBER '96	REPAIRS ALMOST COMPLETED.
07.	P P LAMINATING	SHENG TAIWAN	PARTLY DAMAGED	REPAIRS	2.00	1.00	NOVEMBER '96	60% OF THE REPAIR WORK COMPLETE.
08.	HEAT FOILING/ AUTOMATIC DIE EMBOSSEING PRESS	BRANDZEM USA	FULLY DAMAGED	---	---	---	MAY '97	TO BE INSTALLED LATER ON, IF REQUIRED.
09.	CALENDERING	SHENG TAIWAN	PARTLY DAMAGED	REPAIR	1.00	--	DECEMBER '96	REPAIRS UNDER PROCESS.
10.	PLATE MAKING	PAKTEK TAIWAN	COMPLETELY DAMAGED	REPLACEMENT	3.00	---	DECEMBER '96	OFFERS UNDER EVALUATION.
	PROOFING MACHINE	SHIN-CHIN TAIWAN	COMPLETELY DAMAGED	REPLACEMENT SPEED MALT (UK)	26.50	---	DECEMBER '96	ARRANGING IMPORT THROUGH OUR OWN FUND L/C APPLIED FOR. HIGHER SPEED & MORE STABLE AND BETTER QUALITY WITH BOTH SIDE PRINTING FACILITY.

DESCRIPTION OF EQUIPMENTS	NAME OF MANUFACTURE	EXTENT OF DAMAGE	PROPOSED RESTORATION & SOURCE	ESTIMATED EXPENDITURE TO BE INCURRED	ALREADY INCURRED	EXPECTED DATE OF RESTORATION	JUSTIFICATION / STATUS
12. VARNISHING MACHINE	SHENG TAIWAN	PARTLY DAMAGED	REPAIR	2.00	--	DECEMBER '96	REPAIR UNDER PROCESS.
13. TYING MACHINE	CHING/TSAI TAIWAN	COMPLETELY DAMAGED	REPLACEMENT	2.00	--	DECEMBER '96	OFFERS UNDER EVALUATION.
14. SAWING MACHINE	YING YEN TAIWAN	COMPLETELY DAMAGED	REPLACEMENT (SAME SOURCE)	5.00	--	DECEMBER '96	NOT APPLICABLE
15. HI-SPEED SADDLE STITCHER	JHUNG SHING TAIWAN	COMPLETELY DAMAGED	REPLACEMENT (SAME SOURCE)	6.00	--	DECEMBER '96	NOT APPLICABLEDAS
X 16. PAPER TREATMENT UNIT & COMPRESSOR POLY PRE COATING BRINCO SOFTAL TREATER	INDIAN	PARTLY DAMAGED	REPAIR	20.00	--	MAY '97	UNDER REPAIRS.
		COMPLETELY DAMAGED	REPLACEMENT (SAME SOURCE)	9.20	--	JANUARY '97	NOT APPLICABLE.
ELECTRIC HEATING EQUIPMENT	-	COMPLETELY DAMAGED	---	--	--	--	TO BE INSTALLED LATER ON, IF REQUIRED.
EXTRUSION DIE	-	PARTIALLY DAMAGED	REPAIR	--	--	DECEMBER '96	UNDER ASSESSMENT.
MATERIALS HANDING OVERHEAD CRANE	-	DAMAGED	REPLACEMENT (INDIGENOUS)	5.00	--	DECEMBER '96	NOT APPLICABLE.
17. BALANCING EQUIPMENT (ADDED TO THE PROJECT) STEP & REPEAT							
APPLE COMPUTER	-	DAMAGED	REPLACEMENT (SAME SOURCE)	10.00	--	DECEMBER '96	NOT APPLICABLE.
ACER COMPUTER	-						
RADIANT RND TESTER	-						
SAMPLE CUTTER	-						
PATTERN CONTROL	-	DAMAGED	REPLACEMENT (SAME SOURCE)	5.00	--	DECEMBER '96	NOT APPLICABLE.
MANUAL STIPER	-						
MANUAL PUNCHING	-	PARTLY DAMAGED	REPAIR	0.50	0.50	OCTOBER '96	REPAIRS COMPLETED.
SHEETER MACHINE	-	DAMAGED	REPLACEMENT (SAME SOURCE)	3.00	--	DECEMBER '96	NOT APPLICABLE.

NOTE :- 1) THE ABOVE DATE OF RESTORATION IS SUBJECT TO L/C OPENING STARTING FROM 30.9.96 AND COMPLETION BY 30.12.96.
2) RUPEE CONVERSION IS BASED ON CURRENT FOREIGN EXCHANGE RATES, 1 DM = RS. 24, 1 US\$ = RS. 36
3) ALL EXPENDITURE INCURRED TILL DATE FOR REPAIR WORKS, AS MENTIONED ABOVE, HAVE BEEN MET OUT OF INTERNAL RESOURCES.

DESCRIPTION OF EQUIPMENTS	NAME OF MANUFACTURE	EXTENT OF DAMAGE	PROPOSED RESTORATION & SOURCE	ESTIMATED EXPENDITURE TO BE INCURRED	ALREADY INCURRED	EXPECTED DATE OF RESTORATION	JUSTIFICATION / STATUS
12. VARNISHING MACHINE	SHENG TAIWAN	PARTLY DAMAGED	REPAIR	2.00	--	DECEMBER '96	REPAIR UNDER PROCESS.
13. TYING MACHINE	CHING/TSAI TAIWAN	COMPLETELY DAMAGED	REPLACEMENT	2.00	--	DECEMBER '96	OFFERS UNDER EVALUATION.
14. SAWING MACHINE	YING YEN TAIWAN	COMPLETELY DAMAGED	REPLACEMENT (SAME SOURCE)	5.00	--	DECEMBER '96	NOT APPLICABLE
15. HI-SPEED SADDLE STITCHER	JHUNG SHING TAIWAN	COMPLETELY DAMAGED	REPLACEMENT (SAME SOURCE)	6.00	--	DECEMBER '96	NOT APPLICABLEDQS
X 16. PAPER TREATMENT UNIT & COMPRESSOR POLY PRE COATING BRINCO SOFTAL TREATER	INDIAN	PARTLY DAMAGED	REPAIR	20.00	--	MAY '97	UNDER REPAIRS.
		COMPLETELY DAMAGED	REPLACEMENT (SAME SOURCE)	9.20	--	JANUARY '97	NOT APPLICABLE.
ELECTRIC HEATING EQUIPMENT	-	COMPLETELY DAMAGED	-	--	--	--	TO BE INSTALLED LATER ON, IF REQUIRED.
EXTRUSION DIE	-	PARTIALY DAMAGED	REPAIR	--	--	DECEMBER '96	UNDER ASSESSMENT.
MATERIALS HANDING OVERHEAD CRANE	-	DAMAGED	REPLACEMENT (INDIGENOUS)	5.00	--	DECEMBER '96	NOT APPLICABLE.
17. <u>BALANCING EQUIPMENT (ADDED TO THE PROJECT)</u> <u>STEP & REPEAT</u>							
APPLE COMPUTER	-	DAMAGED	REPLACEMENT (SAME SOURCE)	10.00	--	DECEMBER '96	NOT APPLICABLE.
ACER COMPUTER	-						
RADIANT RIB TESTER	-						
SAMPLE CUTTER	-						
PATTERN CONTROL	-	DAMAGED	REPLACEMENT (SAME SOURCE)	5.00	--	DECEMBER '96	NOT APPLICABLE.
MANUAL STIPER	-						
MANUAL PUNCHING	-	PARTLY DAMAGED	REPAIR	0.50	0.50	OCTOBER '96	REPAIRS COMPLETED.
SHEETER MACHINE	-	DAMAGED	REPLACEMENT (SAME SOURCE)	3.00	--	DECEMBER '96	NOT APPLICABLE.

NOTE :- 1) THE ABOVE DATE OF RESTORATION IS SUBJECT TO L/C OPENING STARTING FROM 30.9.96 AND COMPLETION BY 30.12.96.
2) RUPEE CONVERSION IS BASED ON CURRENT FOREIGN EXCHANGE RATES, 1 DM = RS. 24, 1 US\$ = RS. 36
3) ALL EXPENDITURE INCURRED TILL DATE FOR REPAIR WORKS AS MENTIONED ABOVE HAVE BEEN PAID.