

STATUS OF MAIN EQUIPMENTS AS ON 18.9.96

| SL. NO. | DESCRIPTION OF MAIN EQUIPMENTS                 | NAME OF MANUFACTURE | EXTENT OF DAMAGE   | PROPOSED RESTORATION & SOURCE                      | ESTIMATED EXPENDITURE TO BE INCURRED | ALREADY INCURRED | EXPECTED DATE OF RESTORATION | JUSTIFICATION / STATUS                                                                                                                                                                    |
|---------|------------------------------------------------|---------------------|--------------------|----------------------------------------------------|--------------------------------------|------------------|------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 01.     | OFFSET MACHINE                                 | MAN ROLAND GERMANY  | COMPLETELY DAMAGED | REPLACEMENT (KBA GERMANY)                          | 485.00                               | --               | DEC - JAN '97                | LATEST TECHNOLOGY DEVELOPED HIGH POPULARITY WORLD WIDE AS WELL AS IN INDIA IN LAST COUPLE OF YEAR 3 INSTALLATION HAS BEEN MADE IN INDIA WHEREAS NO INSTALLATION FROM MAN ROLAND IN INDIA. |
| 02.     | GRAVURE MACHINE                                | KBA GERMANY         | PARTLY DAMAGED     | PARTS REPLACEMENT & REPAIR                         | 103.50<br>150.00                     | --               | OCT - NOV '97                | OFFER FOR REPLACEMENT OBTAINED REPAIRING IS UNDER PROCESS.                                                                                                                                |
| 03.     | LABEL PRINTING MACHINE                         | PAKTEK TAIWAN       | COMPLETELY DAMAGED | REPLACEMENT ITALY                                  | 66.50                                | --               | JAN - FEB '97                | HIGHER SPEED, MORE THROUGHPUT LATEST TECHNOLOGY, BETTER MACHINE                                                                                                                           |
| 04.     | AUTO DIE-CUTTING CREASING/PUNCHING             | SUNGFA TAIWAN       | COMPLETELY DAMAGED | REPLACEMENT (BOBST, SWITZERLAND)                   | 68.00                                | --               | DECEMBER '96                 | LEADER WORLDWIDE ESTABLISHED BASE IN INDIA LARGE NUMBER OF INSTALLATIONS, FASTER MACHINE                                                                                                  |
|         | AUTOMATIC FOLDING GLUING MACHINE LINEER FINING | PAKTEK TAIWAN       | COMPLETELY DAMAGED | REPLACEMENT (BOBST, SWITZERLAND) KOHMAN, (GERMANY) | 23.00<br>75.00                       | --<br>1.25       | DECEMBER '96                 | LEADER WORLDWIDE, FASTER MACHINE, EASY MAKE READY LESSER WASTAGE, BETTER QUALITY.                                                                                                         |
| 06.     | CUTTING PUNCHING                               | PERFEETA GERMANY    | PARTLY DAMAGED     | REPLACEMENT REPAIR                                 | 7.00<br>5.00                         | --<br>4.00       | OCTOBER '96                  | REPAIRS ALMOST COMPLETED.                                                                                                                                                                 |
| 07.     | P P LAMINATING                                 | SHENG TAIWAN        | PARTLY DAMAGED     | REPAIRS                                            | 2.00                                 | 1.00             | NOVEMBER '96                 | 60% OF THE REPAIR WORK COMPLETE                                                                                                                                                           |
| 08.     | HEAT FOILING/ AUTOMATIC DIE EMBOSSEING PRESS   | BRANDZEM USA        | FULLY DAMAGED      | --                                                 | --                                   | --               | MAY '97                      | TO BE INSTALLED LATER ON. IF REQUIRED.                                                                                                                                                    |
| 09.     | CALENDERING                                    | SHENG TAIWAN        | PARTLY DAMAGED     | REPAIR                                             | 1.00                                 | --               | DECEMBER '96                 | REPAIRS UNDER PROCESS.                                                                                                                                                                    |
| 10.     | PLATE MAKING                                   | PAKTEK TAIWAN       | COMPLETELY DAMAGED | REPLACEMENT                                        | 3.00                                 | --               | DECEMBER '96                 | OFFERS UNDER EVALUATION.                                                                                                                                                                  |
| 11.     | PROOFING MACHINE                               | SHIN-CHIN TAIWAN    | COMPLETELY DAMAGED | REPLACEMENT SPEED MALT (UK)                        | 26.50                                | --               | DECEMBER '96                 | ARRANGING IMPORT THROUGH OUR OWN FUND L/C APPLIED FOR. HIGHER SPEED & MORE STABLE AND BETTER QUALITY WITH BOTH SIDE PRINTING FACILITY.                                                    |

STATUS OF MAIN EQUIPMENTS AS ON 18.9.96

| SL. NO. | DESCRIPTION OF MAIN EQUIPMENTS                | NAME OF MANUFACTURE | EXTENT OF DAMAGE   | PROPOSED RESTORATION & SOURCE    | ESTIMATED EXPENDITURE TO BE INCURRED | ALREADY INCURRED | EXPECTED DATE OF RESTORATION | JUSTIFICATION / STATUS                                                                                                                                                                    |
|---------|-----------------------------------------------|---------------------|--------------------|----------------------------------|--------------------------------------|------------------|------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 01.     | OFFSET MACHINE                                | MAN ROLAND GERMANY  | COMPLETELY DAMAGED | REPLACEMENT (KBA GERMANY)        | 485.00                               | --               | DEC - JAN '97                | LATEST TECHNOLOGY DEVELOPED HIGH POPULARITY WORLD WIDE AS WELL AS IN INDIA IN LAST COUPLE OF YEAR 3 INSTALLATION HAS BEEN MADE IN INDIA WHEREAS NO INSTALLATION FROM MAN ROLAND IN INDIA. |
| 02.     | GRAVURE MACHINE                               | KBA GERMANY         | PARTLY DAMAGED     | PARTS REPLACEMENT & REPAIR       | 103.50<br>150.00                     | ---              | OCT - NOV '97                | OFFER FOR REPLACEMENT OBTAINED REPAIRING IS UNDER PROCESS.                                                                                                                                |
| 03.     | LABEL PRINTING MACHINE                        | PAKTEK TAIWAN       | COMPLETELY DAMAGED | REPLACEMENT ITALY                | 66.50                                | ---              | JAN - FEB '97                | HIGHER SPEED, MORE THROUGHPUT LATEST TECHNOLOGY, BETTER MACHINE.                                                                                                                          |
| 04.     | AUTO DIE-CUTTING CREASING/PUNCHING            | SUNGFA TAIWAN       | COMPLETELY DAMAGED | REPLACEMENT (BOBST, SWITZERLAND) | 68.00                                | ---              | DECEMBER '96                 | LEADER WORLDWIDE ESTABLISHED BASE IN INDIA LARGE NUMBER OF INSTALLATIONS. FASTER MACHINE.                                                                                                 |
|         | AUTOMATIC FOLDING GLUING MACHINE LINER FIXING | PAKTEK TAIWAN       | COMPLETELY DAMAGED | REPLACEMENT (BOBST, SWITZERLAND) | 23.00                                | ---              | DECEMBER '96                 | LEADER WORLDWIDE, FASTER MACHINE, EASY MAKE READY LESSER WASTAGE, BETTER QUALITY.                                                                                                         |
|         |                                               |                     |                    | KOHMAN, (GERMANY)                | 75.00                                | 1.25             |                              |                                                                                                                                                                                           |
| 06.     | CUTTING PUNCHING                              | PERFEETA GERMANY    | PARTLY DAMAGED     | REPLACEMENT REPAIR               | 7.00<br>5.00                         | --               | OCTOBER '96                  | REPAIRS ALMOST COMPLETED.                                                                                                                                                                 |
| 07.     | P P LAMINATING                                | SHENG TAIWAN        | PARTLY DAMAGED     | REPAIRS                          | 2.00                                 | 1.00             | NOVEMBER '96                 | 60% OF THE REPAIR WORK COMPLETE.                                                                                                                                                          |
| 08.     | HEAT FOILING/ AUTOMATIC DIE EMBOSSEING PRESS  | BRANDZEM USA        | FULLY DAMAGED      | ---                              | ---                                  | ---              | MAY '97                      | TO BE INSTALLED LATER ON, IF REQUIRED.                                                                                                                                                    |
| 09.     | CALENDERING                                   | SHENG TAIWAN        | PARTLY DAMAGED     | REPAIR                           | 1.00                                 | --               | DECEMBER '96                 | REPAIRS UNDER PROCESS.                                                                                                                                                                    |
| 10.     | PLATE MAKING                                  | PAKTEK TAIWAN       | COMPLETELY DAMAGED | REPLACEMENT                      | 3.00                                 | ---              | DECEMBER '96                 | OFFERS UNDER EVALUATION.                                                                                                                                                                  |
|         | PROOFING MACHINE                              | SHIN-CHIN TAIWAN    | COMPLETELY DAMAGED | REPLACEMENT SPEED MALT (UK)      | 26.50                                | ---              | DECEMBER '96                 | ARRANGING IMPORT THROUGH OUR OWN FUND L/C APPLIED FOR. HIGHER SPEED & MORE STABLE AND BETTER QUALITY WITH BOTH SIDE PRINTING FACILITY.                                                    |

| DESCRIPTION OF EQUIPMENTS                                                               | NAME OF MANUFACTURE | EXTENT OF DAMAGE   | PROPOSED RESTORATION & SOURCE | ESTIMATED EXPENDITURE TO BE INCURRED | ALREADY INCURRED | EXPECTED DATE OF RESTORATION | JUSTIFICATION / STATUS                 |
|-----------------------------------------------------------------------------------------|---------------------|--------------------|-------------------------------|--------------------------------------|------------------|------------------------------|----------------------------------------|
| 12. VARNISHING MACHINE                                                                  | SHENG TAIWAN        | PARTLY DAMAGED     | REPAIR                        | 2.00                                 | --               | DECEMBER '96                 | REPAIR UNDER PROCESS.                  |
| 13. TYING MACHINE                                                                       | CHING/TSAI TAIWAN   | COMPLETELY DAMAGED | REPLACEMENT                   | 2.00                                 | --               | DECEMBER '96                 | OFFERS UNDER EVALUATION.               |
| 14. SAWING MACHINE                                                                      | YING YEN TAIWAN     | COMPLETELY DAMAGED | REPLACEMENT (SAME SOURCE)     | 5.00                                 | --               | DECEMBER '96                 | NOT APPLICABLE                         |
| 15. HI-SPEED SADDLE STITCHER                                                            | JHUNG SHING TAIWAN  | COMPLETELY DAMAGED | REPLACEMENT (SAME SOURCE)     | 6.00                                 | --               | DECEMBER '96                 | NOT APPLICABLEDAS                      |
| X 16. PAPER TREATMENT UNIT & COMPRESSOR<br>POLY PRE COATING<br>BRINCO<br>SOFTAL TREATER | INDIAN              | PARTLY DAMAGED     | REPAIR                        | 20.00                                | --               | MAY '97                      | UNDER REPAIRS.                         |
|                                                                                         |                     | COMPLETELY DAMAGED | REPLACEMENT (SAME SOURCE)     | 9.20                                 | --               | JANUARY '97                  | NOT APPLICABLE.                        |
| ELECTRIC HEATING EQUIPMENT                                                              | -                   | COMPLETELY DAMAGED | ---                           | --                                   | --               | --                           | TO BE INSTALLED LATER ON, IF REQUIRED. |
| EXTRUSION DIE                                                                           | -                   | PARTIALLY DAMAGED  | REPAIR                        | --                                   | --               | DECEMBER '96                 | UNDER ASSESSMENT.                      |
| MATERIALS HANDING OVERHEAD CRANE                                                        | -                   | DAMAGED            | REPLACEMENT (INDIGENOUS)      | 5.00                                 | --               | DECEMBER '96                 | NOT APPLICABLE.                        |
| 17. BALANCING EQUIPMENT (ADDED TO THE PROJECT)<br>STEP & REPEAT                         |                     |                    |                               |                                      |                  |                              |                                        |
| AFLE COMPUTER                                                                           | -                   | DAMAGED            | REPLACEMENT (SAME SOURCE)     | 10.00                                | --               | DECEMBER '96                 | NOT APPLICABLE.                        |
| ACER COMPUTER                                                                           | -                   |                    |                               |                                      |                  |                              |                                        |
| RADIANT RND TESTER                                                                      | -                   |                    |                               |                                      |                  |                              |                                        |
| SAMPLE CUTTER                                                                           | -                   |                    |                               |                                      |                  |                              |                                        |
| PATTERN CONTROL                                                                         | -                   | DAMAGED            | REPLACEMENT (SAME SOURCE)     | 5.00                                 | --               | DECEMBER '96                 | NOT APPLICABLE.                        |
| MANUAL STIPER                                                                           | -                   |                    |                               |                                      |                  |                              |                                        |
| MANUAL PUNCHING                                                                         | -                   | PARTLY DAMAGED     | REPAIR                        | 0.50                                 | 0.50             | OCTOBER '96                  | REPAIRS COMPLETED.                     |
| SHEETER MACHINE                                                                         | -                   | DAMAGED            | REPLACEMENT (SAME SOURCE)     | 3.00                                 | --               | DECEMBER '96                 | NOT APPLICABLE.                        |

NOTE :- 1) THE ABOVE DATE OF RESTORATION IS SUBJECT TO L/C OPENING STARTING FROM 30.9.96 AND COMPLETION BY 30.12.96.  
2) RUPEE CONVERSION IS BASED ON CURRENT FOREIGN EXCHANGE RATES, 1 DM = RS. 24, 1 US\$ = RS. 36  
3) ALL EXPENDITURE INCURRED TILL DATE FOR REPAIR WORKS, AS MENTIONED ABOVE, HAVE BEEN MET OUT OF INTERNAL CREDIT.

| DESCRIPTION OF EQUIPMENTS                                                               | NAME OF MANUFACTURE | EXTENT OF DAMAGE   | PROPOSED RESTORATION & SOURCE | ESTIMATED EXPENDITURE TO BE INCURRED | ALREADY INCURRED | EXPECTED DATE OF RESTORATION | JUSTIFICATION / STATUS                 |
|-----------------------------------------------------------------------------------------|---------------------|--------------------|-------------------------------|--------------------------------------|------------------|------------------------------|----------------------------------------|
| 12. VARNISHING MACHINE                                                                  | SHENG TAIWAN        | PARTLY DAMAGED     | REPAIR                        | 2.00                                 | --               | DECEMBER '96                 | REPAIR UNDER PROCESS.                  |
| 13. TYING MACHINE                                                                       | CHING/TSAI TAIWAN   | COMPLETELY DAMAGED | REPLACEMENT                   | 2.00                                 | --               | DECEMBER '96                 | OFFERS UNDER EVALUATION.               |
| 14. SAWING MACHINE                                                                      | YING YEN TAIWAN     | COMPLETELY DAMAGED | REPLACEMENT (SAME SOURCE)     | 5.00                                 | --               | DECEMBER '96                 | NOT APPLICABLE                         |
| 15. HI-SPEED SADDLE STITCHER                                                            | JHUNG SHING TAIWAN  | COMPLETELY DAMAGED | REPLACEMENT (SAME SOURCE)     | 6.00                                 | --               | DECEMBER '96                 | NOT APPLICABLEDQS                      |
| X 16. PAPER TREATMENT UNIT & COMPRESSOR<br>POLY PRE COATING<br>BRINCO<br>SOFTAL TREATER | INDIAN              | PARTLY DAMAGED     | REPAIR                        | 20.00                                | --               | MAY '97                      | UNDER REPAIRS.                         |
|                                                                                         |                     | COMPLETELY DAMAGED | REPLACEMENT (SAME SOURCE)     | 9.20                                 | --               | JANUARY '97                  | NOT APPLICABLE.                        |
| ELECTRIC HEATING EQUIPMENT                                                              | -                   | COMPLETELY DAMAGED | -                             | --                                   | --               | --                           | TO BE INSTALLED LATER ON, IF REQUIRED. |
| EXTRUSSION DIE                                                                          | -                   | PARTIALY DAMAGED   | REPAIR                        | --                                   | --               | DECEMBER '96                 | UNDER ASSESSMENT.                      |
| MATERIALS HANDING OVERHEAD CRANE                                                        | -                   | DAMAGED            | REPLACEMENT (INDIGENOUS)      | 5.00                                 | --               | DECEMBER '96                 | NOT APPLICABLE.                        |
| 17. <u>BALANCING EQUIPMENT (ADDED TO THE PROJECT)</u><br><u>STEP &amp; REPEAT</u>       |                     |                    |                               |                                      |                  |                              |                                        |
| APPLE COMPUTER                                                                          | -                   | DAMAGED            | REPLACEMENT (SAME SOURCE)     | 10.00                                | --               | DECEMBER '96                 | NOT APPLICABLE.                        |
| ACER COMPUTER                                                                           | -                   |                    |                               |                                      |                  |                              |                                        |
| RADIANT RIB TESTER                                                                      | -                   |                    |                               |                                      |                  |                              |                                        |
| SAMPLE CUTTER                                                                           | -                   |                    |                               |                                      |                  |                              |                                        |
| PATTERN CONTROL                                                                         | -                   | DAMAGED            | REPLACEMENT (SAME SOURCE)     | 5.00                                 | --               | DECEMBER '96                 | NOT APPLICABLE.                        |
| MANUAL STIPER                                                                           | -                   |                    |                               |                                      |                  |                              |                                        |
| MANUAL PUNCHING                                                                         | -                   | PARTLY DAMAGED     | REPAIR                        | 0.50                                 | 0.50             | OCTOBER '96                  | REPAIRS COMPLETED.                     |
| SHEETER MACHINE                                                                         | -                   | DAMAGED            | REPLACEMENT (SAME SOURCE)     | 3.00                                 | --               | DECEMBER '96                 | NOT APPLICABLE.                        |

NOTE :- 1) THE ABOVE DATE OF RESTORATION IS SUBJECT TO L/C OPENING STARTING FROM 30.9.96 AND COMPLETION BY 30.12.96.  
2) RUPEE CONVERSION IS BASED ON CURRENT FOREIGN EXCHANGE RATES, 1 DM = RS. 24, 1 US\$ = RS. 36  
3) ALL EXPENDITURE INCURRED TILL DATE FOR REPAIR WORKS AS MENTIONED ABOVE HAVE BEEN PAID.