REPORT FORMAT: V-L3 (Medium) | Version: 6.1\_2018

File No.: RKA/FY18-19/738 Dated:22.12.2018

# **VALUATION REPORT**

**OF** 

# **INDUSTRIAL LAND & BUILDING**

# SITUATED AT M/S ISGEC HEAVY ENGINEERING LTD. , SHARANPUR-KURUKSHETRA ROAD, YAMUNA NAGAR, HARYANA- 135001

#### **OWNER/S**



A/C: M/S ISGEC HEAVY ENGINEERING LTD.

# REPORT PREPARED FOR STATE BANK OF INDIA, OVERSEAS BRANCH, NEW DELHI

\*\*Important - In case of any query/ issue or escalation you may please contact Incident Manager at valuers@rkassociates.org. We will appreciate your feedback in order to improve our services.

NOTE: As per IBA Guidelines please provide your feedback on the report within 15 days of its submission after which report will be considered to be correct.





PART A	SBI FORMAT OF VALUATION REPORT

Name & Address of Branch	State bank of India, Overseas Branch, New Delhi
Name of Customer (s)/ Borrower Unit	M/s ISGEC Heavy Engineering Ltd.

S.NO.	CONTENTS	DESCRIPTION
1.	INTRODUCTION	
a.	Name of Property Owner	M/s ISGEC Heavy Engineering Ltd.
	Address & Phone Number of the Owner	Corporate Office :- Near HCL Technologies, A-4, Vindhyachal Marg, Block A, Sector 24, Noida, Uttar Pradesh 201301 Tel. No. :- 0120 408 5001
b.	Purpose of the Valuation	Periodic Re-valuation of mortgaged asset
C.	Date of Inspection of the Property	20 December 2018
d.	Date of Valuation Report	22 December 2018
e.	Name of the Developer of the Property	Owner them selves
	Type of Developer	Property built from owner self resources

2.	PHYSICAL CHARACTERISTICS OF THE PROPERTY		
a.	Location attribute of the property		
i.	Nearby Landmark	Property itself is a landmark	
ii.	Postal Address of the Property	M/s ISGEC Heavy Engine Kurukshetra Road, Yamuna	
iii.	Area of the Plot/ Land	44.75 acre (2,16,590 sq.yds	)
		Also please refer to Part-B	B Area description of the
		property.All area measurem	
		basis. Verification of the a	rea measurement of the
		property is done only bas	sed on sample random
		checking and not based on fi	ull scale measurement.
iv.	Type of Land	Solid/ On Road Level	
V.	Independent access/ approach to the	Clear independent access is	available
	property		
vi.	Google Map Location of the Property with a	Enclosed with the Report	
	neighborhood layout map	Coordinates or URL:30°04'22.3"N 77°11'56.8"E	
vii.	Details of the roads abutting the property		
	Main Road Name & Width	Saharanpur-kurukshetra	Approx. 30 meter
		Road	
	Front Road Name & width	Saharanpur-kurukshetra	Approx. 30 meter
		Road	
	Type of Approach Road	Bituminous Road	
	Distance from the Main Road	On main road	
viii.	Description of adjoining property	Mixed (residential & Industrial units)	
ix.	Plot No./Gata No.	Please refer the copy of Men	norandum & Article of
		association	

FILE NO.: RKA/FY18-19/738 Page 1 of 45



# M/S ISGEC HEAVY ENGINEERING LTD., YAMUNA NAGAR

X.	Village/ Zone	Habibpur, Mamida & Gadi Gujran
xi.	Sub registrar	Jagadhri
xii.	District	Yamuna Nagar
xiii.	Any other aspect	Valuation is done for the property identified to us by the owner/ owner representative. Responsibility of identifying the correct property to the Valuer/ its authorized surveyor is solely of the client/ owner for which Valuation has to be carried out. At our end we have just cross verified the identification of the property with reference to the documents which client could provide to us for perusal as per our standard checklist of the documents requested from them. Method by which identification of the property is carried out is also mentioned in the report clearly. In case the property mentioned in the Valuation report is not the same on which security mortgage has been or has to be created then please inform the Valuer office immediately.
		Identification of the property is only limited to cross verification from its boundaries at site if mentioned in the provided documents.  Getting cizra map or coordination with revenue officers for site identification is out of scope of this
		assignment and has not been done and has not been done at our end.
		Cross checked from boundaries or address of the property mentioned in the deed  Done from the name plate displayed on the property
	d Identification of the property	☐ Enquired from local residents/ public
	Identification of the property	<ul> <li>☑ Identified by owner/owner's representative</li> </ul>
		□ Identification of the property could not be done properly □ Survey was not done
	Is property clearly demarcatedby permanent/ temporary boundary on site	Demarcated with permanent boundary
	Is the property merged or colluded	No
	with any other property	
	City Categorization	Scale-C City Semi Urban
	5. Characteristics of the locality	Average Within unnotified Industrial area
	Property location classification	Near to Highway Road Facing None
	7. Property Facing	North Facing

FILE NO.: RKA/FY18-19/738 Page 2 of 45





b.	Covered Built-up area de	scription	Total Built-up a	<b>rea</b> :-138146.31sq.mtr
	(Plinth/ Carpet/ Saleable Area)		(1487006.88 sq	.ft.)
			Area Considere	ed for valuation:- 115890 sq.mtr.
			(1247444.91 sq	.ft.)
			-	er to Part C - Area description of the
				ea measurements are on approximate
				on of the area measurement of the
				ne only based on sample random
	Paur darias sabadula a	the Dreperty	cnecking and no	ot based on full scale measurement.
C.	Boundaries schedule of	the Property		
I.				t, since no documents pertaining to
	Are Boundaries matched		the boundaries	of the property has been provided
			to us.	
ii.	Directions	As per Title Deed		Actual found at Site
	East	No information available		Drain & Hamida Village
	West	No information available		Village Gadi Road & Power House
	North	No information available		Kurukshetra-Saharanpur highway
	South	No information	available	Canal

3.	TOWN PLANNING/ ZONING PARAMETE	RS	
a.	Master Plan provisions related to property in terms of Land use	Industrial	
	i. Any conversion of land use done	No information available.	
	ii. Current activity done in the property	Used as Industrial Land & Bu	ilding
	iii. Is property usage as per applicable zoning	Yes	
	iv. Any notification on change of zoning regulation	Not in our knowledge	
	v. Street Notification	Mixed	
b.	Provision of Building by-laws as applicable	PERMITTED	CONSUMED
	i. FAR/ FSI	Please refer to area chart	Please refer to area chart
		description	description
	ii. Ground coverage	do	do
	iii. Number of floors	do	do
	iv. Height restrictions	do	do
	v. Front/ Back/ Side Setback	do	do
C.	Status of Completion/ Occupational certificate	No information provided	No information provided
d.	Comment on unauthorized construction if any	Cannot comment since no copy of approved Map provided to us	
e.	Comment on Transferability of	As per the regulation of DTCP, Haryana	
	developmentalrights		
f.	i. Planning Area/ Zone	DTCP Yamuna Nagar-Jaga	adhri Master Plan 2021
İ	ii. Master Plan currently in force	DTCP Yamuna Nagar-Jaga	adhri Master Plan 2021

FILE NO.: RKA/FY18-19/738 Page 3 of 45



M/S ISGEC HEAVY ENGINEERING LTD., YAMUNA NAGAR

	iii. Municipal limits	Yamuna Nagar Municipal Corporation	
g.	Developmental controls/ Authority	Haryana Urban development Authority (HUDA)	
h.	Zoning regulations	Industrial	
i.	Comment on the surrounding land uses &	No proper zoning regulations imposed. Nearby	
	adjoining properties in terms of uses	properties are of mixed use.	
j.	Comment of Demolition proceedings if any	Not in our knowledge	
k.	Comment on Compounding/ Regularization	Not in our knowledge	
	proceedings		
I.	Any other aspect		
	i. Any information on encroachment	Not known to us	
	ii. Is the area part of unauthorized area/	No (As per general information available)	
	colony		

4.	DOCUMENT DETAILS AND LEGAL ASPECTS OF THE PROPERTY			
a.	Ownership documents provided	Copy of TIR Mo	emorandum & Article of association	NA
b.	Names of the Legal Owner/s	M/s. ISGEC Heavy E	ngineering Ltd	
C.	Constitution of the Property	Free hold, complete t	ransferable righ	ts
d.	Agreement of easement if any	Not required		
e.	Notice of acquisition if any and area under acquisition	Not in our knowledge		
f.	Notification of road widening if any and area under acquisition	Not in our knowledge	Not in our knowledge	
g.	Heritage restrictions, if any	No		
h.	Comment on Transferability of the property ownership	Free hold, complete transferable rights		ts
i.	Comment on existing mortgages/ charges/ encumbrances on the property, if any	Yes	State Ba	nk of India
j.	Comment on whether the owners of the property have issued any guarantee (personal or corporate) as the case may be	Not Known to us		
k.	Building plan sanction:	1	<u> </u>	
	i. Authority approving the plan	Cannot comment as to us	Approved Map	was not provided
	ii. Name of the office of the Authority	Cannot comment as to us	Approved Map	was not provided
	iii. Any violation from the approved Building Plan	Cannot comment as to us	Approved Map	was not provided
l.	Whether Property is Agricultural Land if yes, any conversion is contemplated	No not an agricultural property		
m.	Whether the property SARFAESI complaint	Yes		
n.	i. Information regarding municipal taxes	Telephone Bill	NA	
	(property tax, water tax, electricity bill)	Receipt number	NA	
		Receipt in the name of	of NA	

FILE NO.: RKA/FY18-19/738 Page 4 of 45



# M/S ISGEC HEAVY ENGINEERING LTD., YAMUNA NAGAR

		Tax amount NA
	ii. Observation on Dispute or Dues if any in payment of bills/ taxes	Not in our knowledge
	iii. Is property tax been paid for this property	Not available. Please confirm from the owner.
	iv. Property or Tax Id No.	Not provided
0.	Whether entire piece of land on which the unit	Yes, Mortgaged
	is set up / property is situated has been	
	mortgaged or to be mortgaged	
p.	Qualification in TIR/Mitigation suggested if any	NA
q.	Any other aspect	This is just a Valuation Report of the property identified to us by the owner/ owner representative based on the copy of the documents provided to us.  Legal aspects or Title verification of the property arenot cdone at our end.  Verification of authenticity of documents from originals or cross checking from any Govt. deptt. is not carried out at our end and the copy of the documents provided to us by Bank/ customer has been relied upon in good faith
	Since how long owners owing the     Property	Please refer to the copy of Memorandum & Article of association
	ii. Year of Acquisition/ Purchase	Please refer to the copy of Memorandum & Article of association
	iii. Property presently occupied/ possessed by	Legal Owner
	iv. Title verification	Yes, done by Advocate
	v. Details of leases if any	NA

5.	ECONOMIC ASPECTS OF THE PROPERTY	
a.	Reasonable letting value/ Expected market monthly rental	NA
b.	Is property presently on rent	No
	i. Number of tenants	NA
	ii. Since how long lease is in place	NA
	iii. Status of tenancy right	NA
	iv. Amount of monthly rent received	NA
C.	Taxes and other outgoing	NA
d.	Property Insurance details	NA
e.	Monthly maintenance charges payable	NA
f.	Security charges, etc.	NA
g.	Any other aspect	NA

FILE NO.: RKA/FY18-19/738 Page 5 of 45





6.	SOCIO - CULTURAL ASPECTS OF THE P	ROPERTY
a.	Descriptive account of the location of the property in terms of Social structure of the area in terms of population, social stratification, regional origin, age groups, economic levels, location of slums/squatter settlements nearby, etc.	Semi urban area
b.	Whether property belongs to social infrastructure like hospital, school, old age homes etc.	No

7.	FUNCTIONAL AND U	JTILITARIAN SI	ERVICE	S, FACILIT	IES & AMENITIES	
a.	Description of the functionality & utility of the property in terms of :					
	i. Space allocation			Yes		
	ii. Storage spaces		,	Yes		
	iii. Utility of spaces pr	rovided within the	,	Yes		
	building					
	iv. Car parking facilities	es	`	Yes		
	v. Balconies		1	Vo		
b.	. Any other aspect					
	i. Drainage arrangements			Yes		
	ii. Water Treatment F	Plant		Yes		
	iii. Power Supply	Permanent	,	Yes/ As per sanctioned load		
	arrangements	Auxiliary	,	Yes, DG Set		
	iv. HVAC system		1	No		
	v. Security provisions	S	,	Yes/ Private security guards		
	vi. Lift/ Elevators		ı	No Yes		
	vii. Compound wall/ M	lain Gate				
	viii. Whether gated so	ciety	`	Yes		
	ix. Internal development		<u>.</u>			
	Garden/ Park/	Water bodies	Inter	nal roads	Pavements	Boundary Wall
	Land scraping					
	Yes	Yes		Yes	Yes	Yes

8.	INFRASTRUCTURE AVAILABILITY			
a.	Description of Aqua Infrastructure availability in terms of:			
	i. Water Supply Yes by Submersible			
	ii. Sewerage/ sanitation system	Sewerage/ sanitation system Underground		
	iii. Storm water drainage	Yes		
b.	Description of other Physical Infrastructure facilities in terms of:			
	i. Solid waste management  Yes by the local municipal corporation			
	ii. Electricity Yes			
	iii. Road and Public Transport connectivity Yes			

FILE NO.: RKA/FY18-19/738 Page 6 of 45





	iv. Availability of other public utilities nearby		Transport, Vicinity	Transport, Market, Hospital etc. available in close Vicinity			
c.	Proximity & availability of civic amenities & so			ocial infrastruct	ure		
	School	Hospital	Market	Bus Stop	Railway Station	Metro	Airport
	1 Km.	1 Km.	1 Km.	1 Km.	1 Km.	NA	NA
	Availability of recreation facilities (parks, open spaces etc.)		Parks & Gree	n Spaces are a	vailable within t	he premises.	

9.	MARKETABILITY ASPECTS OF THE PROPERTY:			
a.	Marketability of the property in terms of			
	i. Location attribute of the subject property	Normal		
	ii. Scarcity	Land is easily available on demand in the vicinity.		
	iii. Market condition related to demand and supply of the kind of the subject property in the area	Demand of the subject property is in accordance with the current use/ activity perspective only which is currently carried out in the property.		
	iv. Comparable Sale Prices in the locality	Please refer to Part C: Valuation Assessment of the Property.		
b.	Any other aspect which has relevance on the value or marketability of the property	No		
	i. Any New Development in surrounding area	No NA		
	ii. Any negativity/ defect/ disadvantages in the property/ location	No NA		

10.	ENGINEERING AND TECHNOLOGY ASP	ECTS OF THE PROPERTY	<b>/</b> :	
a.	Type of construction & design	Tin shed mounted on iron pillars, trusses frag structure & RCC load bearing structure on bea column and 9" brick walls		
b.	Method of construction	Regular masonry construction using standard quality material		
C.	Specifications			
	i. Class of construction	Class B construction (Good)	)	
	ii. Appearance/ Condition of structures	Internal -Good		
		External -Good		
	iii. Roof	Floors/ Blocks	Type of Roof	
		Please refer the Building	Please refer the Building	
		Sheet attached below	Sheet attached below	
	iv. Floor height	10-60 feet		
	v. Type of flooring	Vitrified tiles PCC		
	vi. Doors/ Windows	Aluminum flushed doors & windows Wooden frame &		
		panel doors		
	vii. Interior Finishing	Simple Plastered Walls		
	viii. Exterior Finishing	Simple Plastered Walls		

FILE NO.: RKA/FY18-19/738 Page 7 of 45



M/S ISGEC HEAVY ENGINEERING LTD., YAMUNA NAGAR

	ix. Interior decoration/ Special architectural or decorative feature	Simple plain looking structure.		
	x. Class of electrical fittings	External/ Normal quality fittings		
	xi. Class of sanitary & water supply fittings	Internal/ Good quality fitting.		
d.	Maintenance issues	No maintenance issue, struproperly	cture is maintained	
e.	Age of building/ Year of construction	Not known to us	Not known to us	
f.	Total life of the structure/ Remaining life expected	55-65 Years	Since the structure has been maintained properly & renovation of the same has been done from time to time, keeping this in mind the residual age of the building seems to be approx. 25-30 years	
g.	Extent of deterioration in the structure	No major deterioration came into notice through visual observation		
h.	Structural safety	Can't comment due to unavailability of technical information		
i.	Protection against natural disasters viz. Should be able to withstand moderate earthquakes etc.		stand moderate intensity	
j.	Visible damage in the building if any	No visible damages in the structure		
k.	System of air conditioning	Some rooms are covered w	vith windows AC	
	Provision of firefighting	Fire Extinguishers available	9	
m.	Status of Building Plans/ Maps	The company has provided us architect lay out plan the factory, which was not approved by any authority		
	i. Is Building as per approved Map	Can't comment, since copy provided to us.	of approved map was not	
	ii. Details of alterations/ deviations/ illegal	☐ Permissible Alterations	NA	
	construction/ encroachment noticed in the structure from the original approved plan	□Not permitted alteration	NA	
	iii. Is this being regularized	No information provided		

11.	ENVIRONMENTAL FACTORS:			
a.	Use of environment friendly building materials like fly ash brick, other Green building	No		
	techniques if any			
b.	Provision of rainwater harvesting	Yes		
C.	Use of solar heating and lighting systems, etc.	No		
d.	Presence of environmental pollution in the	Normal vehicular & Industrial pollution present		
	vicinity of the property in terms of industries,			
	heavy traffic, etc. if any			

FILE NO.: RKA/FY18-19/738 Page 8 of 45





12.	ARCHITECTURAL AND AESTHETIC QUALITY OF THE PROPERTY:			
a.	Descriptive account on whether the building is Plain looking simple structure			
	modern, old fashioned, etc., plain looking or			
	with decorative elements, heritage value if			
	applicable, presence of landscape elements,			
	etc.			

13.	VALUATION:	
a.	Methodology of Valuation – Procedures	Please refer to Sub-Point 'n' of Point 1 of Part C:
a.	adopted for arriving at the Valuation	Valuation Assessment Factors of the report.
b.	Prevailing Market Rate/ Price trend of the	Please refer to the <b>Sub-Point 'o' of Point 1of Part C</b> :
D.	Property in the locality/ city from property	Valuation Assessment Factors of the report and the
	search sites	screenshot annexure in the report.
C.	Guideline Rate obtained from Registrar's	Please refer to Part C: Valuation Assessment
	office/ State Govt. gazette/ Income Tax	Factors of the report and the screenshot annexure in
	Notification	the report.
d.	Summary of Valuation	For detailed Valuation calculation please refer to
		Point 1, 2, 3 & 4 of the Part C: Valuation
		Assessment Factors of the report.
	i. Guideline Value	NA
	1. Land	NA
	2. Building	NA
	ii. Prospective Fair Market Value	Rs. 3,55,00,00,000/-
	iii. Expected Realizable Value	Rs. 2,83,87,22,930/-
	iv. Expected Forced/ Distress Sale Value	Rs. 2,48,38,82,564/-
	v. Valuation of structure for Insurance	Rs. 81,00,00,000/-
	purpose	
e.	i. Justification for more than 20%	Circle rates are determined by the District
	difference in Market & Circle Rate	administration as per their own theoretical internal
		policy and Market rates are adopted based on current
		practical market dynamics which is explained clearly in Valuation assessment factors.
	ii. Details of last two transactions in the	No authentic last two transactions details could be
	locality/ area to be provided, if available	known. However prospective transaction details as
	recallly, area to be provided, if available	per information available on public domain and
		gathered during site survey is mentioned in <i>Point</i>
		'o'of Part C: Valuation Assessment Factors of the
		report and the screenshots of the references are
		annexed in the reportfor reference.
	<u> </u>	

14.	Declaration	i. The information provided is true and correct to the best of my knowledge and belief.		
	(Also see	ii. The analysis and conclusions are limited by the reported assumptions, limiting		
	Enclosure: 1	conditions and the information came to knowledge during the course of the work. Please		
	Valuer's	see the Assumptions Remarks & Limiting conditions described in Part D: Valuation		
	Remarks)	assessment section of the Report.		

FILE NO.: RKA/FY18-19/738 Page 9 of 45





#### M/S ISGEC HEAVY ENGINEERING LTD., YAMUNA NAGAR

iii.	· · · · · · · · · · · · · · · · · · ·
	Valuation by Banks and HFIs in India, 2011 issued by IBA and NHB, fully understood
	the provisions of the same and followed the provisions of the same to the best of my
	ability and this report is in conformity to the Standards of Reporting enshrined in the
	above Handbook.
iv.	No employee or member of R.K Associates has any direct/ indirect interest in the
	property.
v.	Our authorized surveyor by name of SE Shahid & SE Rajkumar has visited the subject
	property on 20 December 2018 in the presence of the Owner's representative.
vi.	I am a registered Valuer under Section 34 AB of Wealth Tax Act, 1957.
vii.	I/ firm is an approved Valuer under SARFAESI Act – 2002 and approved by the Bank.
viii.	We have submitted Valuation report directly to the Bank.
ix.	This valuation work is carried out by our Engineering team on the request from STATE
	BANK OF INDIA, OVERSEAS BRANCH, NEW DELHI

15.	VALUATION COMPANY DETAILS:				
a.	Name & Address of Valuer	Wealth Tax Registration No.	Signature of the authorized person		
	company				
b.	M/s R.K. Associates Valuers &	2303/ 1988			
	Techno Engineering Consultants				
	Pvt. Ltd. G-183, Preet Vihar, Delhi-				
	110092				
C.	Total Number of Pages in the				
	Report with enclosures				
d.	Engineering Team worked on the	SURVEYED BY: SE Shahid & SE Rajkumar			
	report				
		PREPARED BY: Er. Gaurav Sharma			
		REVIEWED BY: HOD Valuations			

FILE NO.: RKA/FY18-19/738 Page 10 of 45





16.	ENCLOSED DOCUMENTS:	
a.	Layout plan sketch of the area in which the	Google Map enclosed with coordinates
	property is located with latitude and longitude	
b.	Building Plan	Not provided by the owner/ client
C.	Floor Plan	Not provided by the owner/ client
d.	Photograph of the property (including geo- stamping with date) and owner (in case of housing loans, if borrower is available) including a "Selfie' of the Valuer at the site	Enclosed with the report
e.	Certified copy of the approved / sanctioned plan wherever applicable from the concerned office	Not provided by the owner/ client
f.	Google Map location of the property	Enclosed with the Report
g.	Price trend of the property in the locality/city from property search sites viz Magickbricks.com, 99Acres.com, Makan.com etc	No specific price trends available for this location on property search sites.
h.	Any other relevant documents/extracts (All enclosures & annexures to remain integral part & parcel of the main report)	<ul> <li>i. Part B: Area Description of the Property</li> <li>ii. Part C: Valuation Assessment of the Property</li> <li>iii. Part D: Summary of Valuation Report</li> <li>iv. Assumption, Remarks &amp; Limiting conditions</li> <li>v. Valuer's Remark - Page No.7</li> <li>vi. Google Map - Page No.22</li> <li>vii. Photographs - Pages 2</li> <li>viii. Copy of Circle Rate - Pages 25</li> <li>ix. Survey Summary Sheet - Pages 02</li> <li>x. Copy of relevant papers from the property documents referred in the Valuation - Pages 2</li> </ul>

FILE NO.: RKA/FY18-19/738 Page 11 of 45





# PART B AREA DESCRIPTION OF THE PROPERTY - ANNEXURE - I

	Land Area	44.75 acre (2,1	6,590 sq.yds)
	Area adopted on the basis of	MOA & AOA	
	Remarks & observations, if any	Area described	I in various documents is below:
1.	arry	<ul> <li>Plot No sq.yds)</li> <li>In various acres of the various or 7,360</li> <li>In various or 9507</li> <li>Area as peracre or 4,060 Please see</li> <li>Area as peracre or 4,060 Please see</li> </ul>	r MOA & AOA: 44.75 acre (2,16,590 sq.yds)  i. E-67 in Mauza Habibpur & Mamida: 19.5 acres (94,380 us khasras in Village Habibpur: 174 Kanal 19 Marla (21.77 r 1,05,366.8 sq.yds)  us khasras in Village Mamida: 6 Bigha 2 Biswa (1.52 acres 0.83 sq.yds)  us khasras in Village Mamida: 7 Bigha 7 Biswa (1.96 acres sq.yds)  er TIR: 518 Kanal 18.5 Marla + 75 Bigha 8 Biswa (84.04 6,753.6 sq.yds)  attached extract of TIR  r Site Map: 53.778 acres (260285.212 sq.yds)  attached copy of Map
		Permissible (x% of Plot area)	NA
2.	Ground Coverage Area	Proposed(x%)	NA
		Present	NA
		Status	
		Permissible	NA
		Proposed(x%)	NA
3.	FAR	Present	NA
		Status	
4.	Built-up Area considered for Valuation (As per IS 3861-1966)	Covered Area	115890.46 sq.mtr. (1247444.91 sq.ft.)
	Area adopted on the basis of		provided to us by the client
	Remarks & observations, if any	NA	

FILE NO.: RKA/FY18-19/738 Page 12 of 45



# M/S ISGEC HEAVY ENGINEERING LTD., YAMUNA NAGAR

Civil/ Structure of M/s. ISGEC Heavy Engineering Limited, Yamuna Nagar					
S. No.	Name of Building	Type of Structure	<b>Total No. Floors</b>	<b>Total covered</b>	<b>Total Area</b>
1	Pressure Valve- 1	GI sheet roof mounted on iron	Ground	2557.14	27525.05
1	Fressure valve- 1	pillars, trusses frame structure	Giodila 2557.14		27323.03
2	Pressure Valve- 2	GI sheet roof mounted on iron	Ground	7656.82	82418.01
2	Fressure valve- 2	pillars, trusses frame structure	Ground	7030.82	02410.01
3	Pressure Valve- 3	GI sheet roof mounted on iron	Ground	5009.07	53917.63
3	Fressure valve- 5	pillars, trusses frame structure	Ground	3009.07	33917.03
4	Pressure Valve- 4	GI sheet roof mounted on iron	Ground	4220.37	45428.06
*	Tressure valve- 4	pillars, trusses frame structure	Ground	4220.57	43428.00
5	Pressure Valve- 5	GI sheet roof mounted on iron	Ground	1935.70	20835.87
,	Tressure valve- 5	pillars, trusses frame structure	Ground	1333.70	20833.87
6	Pressure Valve- 6	GI sheet roof mounted on iron	Ground	6470.30	69646.31
•	Tressure valve o	pillars, trusses frame structure	Ground	0170.50	
7	New Assembly	GI sheet roof mounted on iron	Ground	4882.21	52552.11
	item / issembly	pillars, trusses frame structure	Ground		
8	Security Post 1	RCC load bearing structure on beam	Ground	15.49	166.73
	5554, 1 551.1	column and 9" brick walls	0.00	255	
9	Water Treatment Plant	RCC load bearing structure on beam	Ground	565.45	6086.50
	Trate: Tradition of the same	column and 9" brick walls	O. Garra	JUJ143	
10	SSM Water Treatment Plant 1	RCC load bearing structure on beam	Ground	32.30	347.68
		column and 9" brick walls	5.53.0		
11	SSM Water Treatment Plant 2	RCC load bearing structure on beam	Ground	2335.52	25139.54
		column and 9" brick walls			
12	Proposed Gas Cylinder	GI sheet roof mounted on iron	Ground	452.87	4874.69
	Godown	pillars, trusses frame structure			
13	Gas Cylinder Godown 1	GI sheet roof mounted on iron	Ground	280.85	3023.07
_	,	pillars, trusses frame structure			
14	Gas Cylinder Godown 2	GI sheet roof mounted on iron	Ground	173.59	1868.52
	•	pillars, trusses frame structure			
15	New Preparation Shop	GI sheet roof mounted on iron	Ground 2384.79 25		25669.88
		pillars, trusses frame structure			

FILE NO.: RKA/FY18-19/738 Page 13 of 45





16	Preparation Shop	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	2498.82	26897.30
17	Iron Store	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	976.03	10505.99
18	Pipe Shop	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	3774.13	40624.74
19	New Tube Shop 1	GI sheet roof mounted on iron pillars, trusses frame structure	Ground 994.21 1		10701.68
20	New Tube Shop 2	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	47.37	509.89
21	Pipe Shop - 2	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	2712.13	29193.37
22	Container Shop	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	1693.52	18229.05
23	Container Paint Shop	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	2306.39	24825.98
24	Old Fabrication (MBD Shop-1)	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	5975.53	64320.60
25	Old Fabrication	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	233.12	2509.30
26	Foundary Shop 1	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	3097.02	33336.32
27	Foundary Shop 2	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	937.45	10090.71
28	Foundary Shop 3	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	3059.64	32933.96
29	Foundary Shop 4	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	Ground 546.17	
30	Foundary Shop 5	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	2171.43 2337	
31	Foundary Office	RCC load bearing structure on beam column and 9" brick walls	G+1 343.32		3695.50
32	Foundary Shop Office	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	342.32	3684.73 28022.67
33	MBD New Shop 1	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	2603.37	
34	MBD New Shop 2	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	371.20	3995.60
35	MBD Office	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	512.77	5519.46
36	Toilet 1	RCC load bearing structure on beam column and 9" brick walls	Ground	24.26	261.13
37	Toilet 2	RCC load bearing structure on beam column and 9" brick walls	Ground	17.68	190.31
38	Toilet 3	RCC load bearing structure on beam column and 9" brick walls	Ground	15.21	163.72
39	Toilet 4	RCC load bearing structure on beam column and 9" brick walls	Ground	14.44	155.43
40	Toilet 5	RCC load bearing structure on beam column and 9" brick walls	Ground	9.47	101.94
41	Toilet 6	RCC load bearing structure on beam column and 9" brick walls	Ground	12.81	137.89
42	Toilet 7	RCC load bearing structure on beam column and 9" brick walls	Ground	18.22	196.12
43	Toilet 8	RCC load bearing structure on beam column and 9" brick walls	Ground	31.54	339.50
44	Toilet 9	RCC load bearing structure on beam column and 9" brick walls	Ground	10.83	116.57
45	Toilet 10	RCC load bearing structure on beam column and 9" brick walls	Ground	22.57	242.94
46	Toilet 11	RCC load bearing structure on beam column and 9" brick walls	Ground	12.42	133.69

FILE NO.: RKA/FY18-19/738 Page 14 of 45



# ASSOCIATES

# M/S ISGEC HEAVY ENGINEERING LTD., YAMUNA NAGAR

47	Toilet 12	RCC load bearing structure on beam column and 9" brick walls	Ground 18.65		200.75
		RCC load bearing structure on beam			
48	Toilet 13	column and 9" brick walls	Ground	32.07	345.20
49	Building 1	GI sheet roof mounted on iron	Ground	215 57	3396.80
49	Building 1	pillars, trusses frame structure	Ground 315.57		5590.60
50	Building 2	GI sheet roof mounted on iron	Ground	223.89	2409.95
		pillars, trusses frame structure			
51	Building 3	GI sheet roof mounted on iron	Ground	84.61	910.74
		pillars, trusses frame structure GI sheet roof mounted on iron			
52	Building 4	pillars, trusses frame structure	Ground	11.44	123.14
		GI sheet roof mounted on iron		21.22	
53	Building 5	pillars, trusses frame structure	Ground	31.09	334.65
54	Building 6	GI sheet roof mounted on iron	Ground	16.50	177.61
54	Building 0	pillars, trusses frame structure	Ground	10.30	177.01
55	Store 1	GI sheet roof mounted on iron	Ground	23.82	256.40
		pillars, trusses frame structure			
56	Store 2	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	33.74	363.18
		GI sheet roof mounted on iron			
57	Store 3	pillars, trusses frame structure	Ground	33.15	356.83
		GI sheet roof mounted on iron			
58	Store 4	pillars, trusses frame structure	Ground	27.75	298.70
59	Store 5	GI sheet roof mounted on iron	Ground	35.49	382.01
33	Store 5	pillars, trusses frame structure	Ground	33.43	302.01
60	Store 6	GI sheet roof mounted on iron	Ground 37.71		405.91
		pillars, trusses frame structure			
61	S.S. Store	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	113.37	1220.31
		GI sheet roof mounted on iron			
62	Building Store	pillars, trusses frame structure	Ground	185.36	1995.22
62	DD CL	GI sheet roof mounted on iron	C I	254.74	2742.02
63	DD Store	pillars, trusses frame structure	Ground	254.74	
64	Chemical Store	GI sheet roof mounted on iron	Ground	233.47	2513.07
	Chemical Store	pillars, trusses frame structure	Ground	255.47	2313.07
65	Main Store	GI sheet roof mounted on iron	Ground	1640.09	17653.93
		pillars, trusses frame structure			
66	Paint Store	RCC load bearing structure on beam column and 9" brick walls	Ground	410.74	4421.21
		GI sheet roof mounted on iron			
67	Fastener Store	pillars, trusses frame structure	Ground	211.04	2271.63
	61 14	GI sheet roof mounted on iron		100.05	2424.07
68	Shed 1	pillars, trusses frame structure	Ground	198.26	2134.07
69	Shed 2	GI sheet roof mounted on iron	Ground	325.19	3500.35
03	Siled 2	pillars, trusses frame structure	Ground	323.19	3300.33
70	Shed 3	GI sheet roof mounted on iron	Ground	54.43	585.88
		pillars, trusses frame structure			
71	Shed 4	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	140.38	1511.05
		GI sheet roof mounted on iron			
72	Shed 5	pillars, trusses frame structure	Ground	64.77	697.18
70	Ch. J.C	GI sheet roof mounted on iron	C 1	47.00	106.55
73	Shed 6	pillars, trusses frame structure	Ground	17.80	191.60
74	Shed 7	GI sheet roof mounted on iron	Ground	55.99	602.68
/4	Jiicu /	pillars, trusses frame structure	Ground	22.22	002.00
75	Shed 8	GI sheet roof mounted on iron	Ground	78.57	845.73
		pillars, trusses frame structure			

FILE NO.: RKA/FY18-19/738 Page 15 of 45





76	Shed 9	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	12.37	133.15
77	Shed 10	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	291.29	3135.45
78	Shed 11	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	11.64	125.29
79	Shed 12	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	24.17	260.17
80	Shed 13	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	26.05	280.40
81	Adda Sheds	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	660.05	7104.78
82	Ambulance Shed	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	20.56	221.31
83	P.V.D Quality	RCC load bearing structure on beam column and 9" brick walls	G+1	2159.88	23248.95
84	P.V.D Industry	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	176.47	1899.52
85	Power Control Centre	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	43.73	470.71
86	Power House	RCC load bearing structure on beam column and 9" brick walls	Ground	77.26	831.63
87	Power House Ped	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	67.16	722.91
88	Canteen 1	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	184.45	1985.42
89	Canteen 2	RCC load bearing structure on beam column and 9" brick walls	Ground	143.85	1548.40
90	Canteen 3	RCC load bearing structure on beam column and 9" brick walls	Ground	127.62	1373.70
91	Canteen 4	RCC load bearing structure on beam column and 9" brick walls	G+1	475.12	5114.19
92	LPG Godown	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	485.66	5227.64
93	Gas Godown	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	237.33	2554.62
94	Cement Godown	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	321.33	3458.80
95	Blasting Room	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	198.94	2141.39
96	Painting Room	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	150.46	1619.55
97	Cobalt Room	RCC load bearing structure on beam column and 9" brick walls	Ground	80.80	869.73
98	Meter Room	RCC load bearing structure on beam column and 9" brick walls	Ground	23.74	255.54
99	PED Offices Extension	RCC load bearing structure on beam column and 9" brick walls	G+2	214.41	2307.91
100	X-Ray Room	RCC load bearing structure on beam column and 9" brick walls	Ground	100.34	1080.06
101	P.V.D Office	RCC load bearing structure on beam column and 9" brick walls	G+2	832.14	8957.15

FILE NO.: RKA/FY18-19/738 Page 16 of 45



# ASSOCIATES

# M/S ISGEC HEAVY ENGINEERING LTD., YAMUNA NAGAR

	2001 11			
Hall 1	=	Ground 94.40		1016.12
Hall 2	RCC load bearing structure on beam	Ground	147.07	1583.06
IA&E Office	RCC load bearing structure on beam column and 9" brick walls	Ground	66.62	717.10
Accounts	GI sheet roof mounted on iron	Ground 55.69		599.45
MD Office	RCC load bearing structure on beam column and 9" brick walls	Ground	129.47	1393.62
Office	RCC load bearing structure on beam column and 9" brick walls	Ground	140.00	1506.96
Commercial	RCC load bearing structure on beam column and 9" brick walls	Ground	79.56	856.38
Purchase	RCC load bearing structure on beam column and 9" brick walls	Ground	118.59	1276.50
Office	RCC load bearing structure on beam	Ground	95.29	1025.70
MBD Office	RCC load bearing structure on beam column and 9" brick walls	Ground	95.22	1024.95
Tool Room	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	280.31	3017.26
Battery Room	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	121.40	1306.75
Switch Room	GI sheet roof mounted on iron pillars, trusses frame structure	Ground 35.30		379.97
Assembly Room	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	Ground 85.22	
Comp. With DG Set Room	GI sheet roof mounted on iron pillars, trusses frame structure	Ground 226.25		2435.36
Ambulance Room	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	29.30	315.39
Work Administration Offices	RCC load bearing structure on beam column and 9" brick walls	G+1	427.66	4603.33
Time Office	RCC load bearing structure on beam column and 9" brick walls	Ground	55.62	598.69
LLOYD'D Office	RCC load bearing structure on beam column and 9" brick walls	Ground	21.55	231.96
Register Office	RCC load bearing structure on beam column and 9" brick walls	Ground	26.44	284.60
Dust Free Office	RCC load bearing structure on beam column and 9" brick walls	Ground	86.64	932.59
R&D ISGEC Office	RCC load bearing structure on beam column and 9" brick walls	Ground	208.43	2243.54
Office Building Electrode Issue Cabin and Toilets	RCC load bearing structure on beam column and 9" brick walls	Ground	253.98	2733.84
Syndicate Office 1	RCC load bearing structure on beam column and 9" brick walls	Ground	395.19	4253.83
Syndicate Office 2	RCC load bearing structure on beam column and 9" brick walls	Ground	320.10	3445.56
Syndicate Office 3	RCC load bearing structure on beam column and 9" brick walls	Ground	98.83	1063.81
State Bank	RCC load bearing structure on beam column and 9" brick walls	Ground	432.19	4652.09
Shop 1	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	67.33	724.74
Shop 2	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	80.88	870.59
	Hall 2  IA&E Office  Accounts  MD Office  Office  Commercial  Purchase  Office  MBD Office  Tool Room  Battery Room  Switch Room  Comp. With DG Set Room  Ambulance Room  Work Administration Offices  Time Office  LLOYD'D Office  Register Office  R&D ISGEC Office  Office Building Electrode Issue Cabin and Toilets  Syndicate Office 1  Syndicate Office 2  Syndicate Office 3  State Bank  Shop 1	RCC load bearing structure on beam column and 9" brick walls  RCC load bearing structure on beam column and 9" brick walls  RCC load bearing structure on beam column and 9" brick walls  Accounts  MD Office  RCC load bearing structure on beam column and 9" brick walls  RCC load bearing structure on beam column and 9" brick walls  RCC load bearing structure on beam column and 9" brick walls  RCC load bearing structure on beam column and 9" brick walls  RCC load bearing structure on beam column and 9" brick walls  RCC load bearing structure on beam column and 9" brick walls  RCC load bearing structure on beam column and 9" brick walls  RCC load bearing structure on beam column and 9" brick walls  RCC load bearing structure on beam column and 9" brick walls  RCC load bearing structure on beam column and 9" brick walls  RCC load bearing structure on beam column and 9" brick walls  GI sheet roof mounted on iron pillars, trusses frame structure  GI sheet roof mounted on iron pillars, trusses frame structure  GI sheet roof mounted on iron pillars, trusses frame structure  GI sheet roof mounted on iron pillars, trusses frame structure  GI sheet roof mounted on iron pillars, trusses frame structure  GI sheet roof mounted on iron pillars, trusses frame structure  Comp. With DG Set Room  GI sheet roof mounted on iron pillars, trusses frame structure  GI sheet roof mounted on iron pillars, trusses frame structure  RCC load bearing structure on beam column and 9" brick walls  RCC load bearing structure on beam column and 9" brick walls  RCC load bearing structure on beam column and 9" brick walls  RCC load bearing structure on beam column and 9" brick walls  RCC load bearing structure on beam column and 9" brick walls  RCC load bearing structure on beam column and 9" brick walls  RCC load bearing structure on beam column and 9" brick walls  SYNDICATE COMPANIES (Color bearing structure on beam column and 9" brick walls  RCC load bearing structure on beam column and 9" brick walls  SYNDICATE COLOR bearing structure on beam col	Hall 1 RCC load bearing structure on beam column and 9" brick walls RCC load bearing structure on beam column and 9" brick walls RCC load bearing structure on beam column and 9" brick walls RCC load bearing structure on beam column and 9" brick walls RCC load bearing structure on beam column and 9" brick walls RCC load bearing structure on beam column and 9" brick walls RCC load bearing structure on beam column and 9" brick walls RCC load bearing structure on beam column and 9" brick walls RCC load bearing structure on beam column and 9" brick walls RCC load bearing structure on beam column and 9" brick walls RCC load bearing structure on beam column and 9" brick walls RCC load bearing structure on beam column and 9" brick walls RCC load bearing structure on beam column and 9" brick walls RCC load bearing structure on beam column and 9" brick walls Ground GI sheet roof mounted on iron pillars, trusses frame structure Switch Room GI sheet roof mounted on iron pillars, trusses frame structure GI sheet roof mounted on iron pillars, trusses frame structure GI sheet roof mounted on iron pillars, trusses frame structure Ambulance Room GI sheet roof mounted on iron pillars, trusses frame structure GI sheet roof mounted on iron pillars, trusses frame structure Ambulance Room GI sheet roof mounted on iron pillars, trusses frame structure RCC load bearing structure on beam column and 9" brick walls Ground RCC load bearing structure on beam column and 9" brick walls Ground COMP With DG Set Room GI sheet roof mounted on iron pillars, trusses frame structure RCC load bearing structure on beam column and 9" brick walls Ground Column and 9" brick walls Ground COMP With DG Set Room GI sheet roof mounted on iron pillars, trusses frame structure RCC load bearing structure on beam column and 9" brick walls Ground Column and 9" brick wa	Hall 1  column and 9° brick walls  RCC load bearing structure on beam column and 9° brick walls  RCC load bearing structure on beam column and 9° brick walls  RCC load bearing structure on beam column and 9° brick walls  Ground 55.69  RCC load bearing structure on beam column and 9° brick walls  RCC load bearing structure on beam column and 9° brick walls  Ground 129.47  RCC load bearing structure on beam column and 9° brick walls  Ground 79.56  RCC load bearing structure on beam column and 9° brick walls  Ground 79.56  RCC load bearing structure on beam column and 9° brick walls  Purchase RCC load bearing structure on beam column and 9° brick walls  Purchase RCC load bearing structure on beam column and 9° brick walls  Ground 95.29  Office RCC load bearing structure on beam column and 9° brick walls  Ground 95.29  Ground 95.29  Ground 95.29  Ground 95.29  Column and 9° brick walls  Ground 95.29  RCC load bearing structure on beam column and 9° brick walls  Ground 95.29  Glisheet roof mounted on iron pillars, trusses frame structure  Ground 96 sheet roof mounted on iron pillars, trusses frame structure  Ground 96 sheet roof mounted on iron pillars, trusses frame structure  Ground 96 sheet roof mounted on iron pillars, trusses frame structure  Ground 96 sheet roof mounted on iron pillars, trusses frame structure  Ground 97 brick walls  Ground 97 brick walls  Ground 98.52  Comp. With DG Set Room 91 sheet roof mounted on iron pillars, trusses frame structure  Ground 97 brick walls  Ground 98.52  Ground 98.52  Comp. With DG Set Room 91 sheet roof mounted on iron pillars, trusses frame structure  Ground 97 brick walls  Ground 98.52  Comp. With DG Set Room 91 sheet roof mounted on iron pillars, trusses frame structure  Ground 97 brick walls  Ground 98.52  Ground 98.52  Ground 98.53  Ground 98.54  Ground 98.54  Ground 98.56  Ground 98.56  Ground 99.56  Ground 99.56  Ground 99.56  Ground 99.56  Ground 99.56

FILE NO.: RKA/FY18-19/738 Page 17 of 45



# M/S ISGEC HEAVY ENGINEERING LTD., YAMUNA NAGAR

131	Shop 3	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	125.16	1347.22
132	Lean to Machine Shop	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	288.38	3104.12
133	Punching 1	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	15.34	165.12
134	Punching 2	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	8.49	91.39
135	Punching 3	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	6.71	72.23
136	Diesel Tank Storage	Under Ground	Ground	301.07	3240.72
137	Diesel Storage Site	Under Ground	Ground	330.63	3558.90
138	E Waste Site	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	36.43	392.13
139	Common Service Deptt.	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	172.33	1854.96
140	PED Maint. Deptt.	RCC load bearing structure on beam column and 9" brick walls	Ground	346.74	3732.31
141	Inspection Deptt.	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	83.93	903.42
142	Shipping & Transport	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	646.52	6959.14
143	ADDA Transport	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	241.65	2601.12
144	Shipping & Transport	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	143.23	1541.73
145	Blasting Foundation	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	68.41	736.37
146	Spot Blasting	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	24.86	267.59
147	Shot Blasting	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	100.57	1082.54
148	Transformer Centre	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	52.39	563.93
149	Telephone Exchange	RCC load bearing structure on beam column and 9" brick walls	Ground	43.94	472.97
150	Air Compressor	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	33.24	357.80
151	Container Shop Air Compressor	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	92.20	992.44
152	MBD Power	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	86.05	926.24
153	Reception	RCC load bearing structure on beam column and 9" brick walls	Ground	76.03	818.39
154	Cashier	RCC load bearing structure on beam column and 9" brick walls	Ground	13.23	142.41
155	Visitors	RCC load bearing structure on beam column and 9" brick walls	Ground	14.07	151.45

FILE NO.: RKA/FY18-19/738 Page 18 of 45



# M/S ISGEC HEAVY ENGINEERING LTD., YAMUNA NAGAR

Workman Shelter	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	172.16	1853.13
Vaccum Packing Section	RCC load bearing structure on beam	Ground	256.48	2760.75
Hazardous Waste Storage Area	GI sheet roof mounted on iron	Ground	84.35	907.94
Automobile Workshop	GI sheet roof mounted on iron	Ground 359 30		3867.51
·	pillars, trusses frame structure  RCC load bearing structure on beam			
Practical Trainning Centre	column and 9" brick walls	Ground	337.70	3635.00
Container Loader	pillars, trusses frame structure	Ground	38.54	414.84
Tool Issue	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	40.12	431.85
Utility	GI sheet roof mounted on iron	Ground	3.49	37.57
Common Service	GI sheet roof mounted on iron	Ground	96.41	1037.76
	pillars, trusses frame structure GI sheet roof mounted on iron			
Car Parking Area	pillars, trusses frame structure	Ground	672.13	7234.81
Parking	RCC load bearing structure on beam column and 9" brick walls on Ground & GI Shed on Iron polls on First Floor	G+1	2253.72	24259.04
Cycle Stand	RCC load bearing structure on beam column and 9" brick walls on Ground & GI Shed on Iron polls on First Floor	nd G+1 130.13		1400.72
Cycle Stand	RCC load bearing structure on beam column and 9" brick walls on Ground & GI Shed on Iron polls on First Floor	d G+1 56.26		605.58
Petrol Pump	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	686.75	7392.18
MBD Pipe Godown	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	347.71	3742.75 3662.24
Syndicate Office	RCC load bearing structure on beam	Ground	340.23	
Store	GI sheet roof mounted on iron	Ground	973.31	10476.71
Shipping & Transport Building	GI sheet roof mounted on iron	Ground	85.40	919.25
Godown	RCC load bearing structure on beam	Ground	97.56	1050.14
Painting Room	RCC load bearing structure on beam	Ground	92.89	999.87
Welding Store	RCC load bearing structure on beam	Ground	395.86	4261.04
5 SI	GI sheet roof mounted on iron			
Pattern Shop	pillars, trusses frame structure	Ground	186.80	2010.72
Welding Store	pillars, trusses frame structure  RCC load bearing structure on beam column and 9" brick walls	Ground Ground	186.80 52.14	561.23
	RCC load bearing structure on beam column and 9" brick walls GI sheet roof mounted on iron			
Welding Store	RCC load bearing structure on beam column and 9" brick walls GI sheet roof mounted on iron pillars, trusses frame structure GI sheet roof mounted on iron	Ground	52.14	561.23
Welding Store  Cocker Room	RCC load bearing structure on beam column and 9" brick walls GI sheet roof mounted on iron pillars, trusses frame structure GI sheet roof mounted on iron pillars, trusses frame structure RCC load bearing structure on beam	Ground Ground	52.14 52.11	561.23 560.91
Welding Store  Cocker Room  MBD Electrical	RCC load bearing structure on beam column and 9" brick walls  GI sheet roof mounted on iron pillars, trusses frame structure  GI sheet roof mounted on iron pillars, trusses frame structure  RCC load bearing structure on beam column and 9" brick walls  GI sheet roof mounted on iron	Ground Ground Ground	52.14 52.11 163.18	561.23 560.91 1756.47
Welding Store  Cocker Room  MBD Electrical  Quality Office	RCC load bearing structure on beam column and 9" brick walls  GI sheet roof mounted on iron pillars, trusses frame structure  GI sheet roof mounted on iron pillars, trusses frame structure  RCC load bearing structure on beam column and 9" brick walls  GI sheet roof mounted on iron pillars, trusses frame structure  GI sheet roof mounted on iron	Ground Ground Ground	52.14 52.11 163.18 103.23	561.23 560.91 1756.47 1111.17
Welding Store  Cocker Room  MBD Electrical  Quality Office  Power House	RCC load bearing structure on beam column and 9" brick walls  GI sheet roof mounted on iron pillars, trusses frame structure  GI sheet roof mounted on iron pillars, trusses frame structure  RCC load bearing structure on beam column and 9" brick walls  GI sheet roof mounted on iron pillars, trusses frame structure	Ground Ground Ground Ground	52.14 52.11 163.18 103.23 173.19	561.23 560.91 1756.47 1111.17 1864.22
	Vaccum Packing Section  Hazardous Waste Storage Area Automobile Workshop  Practical Trainning Centre  Container Loader  Tool Issue  Utility  Common Service  Car Parking Area  Parking  Cycle Stand  Cycle Stand  Petrol Pump  MBD Pipe Godown  Syndicate Office  Store  Shipping & Transport Building  Godown  Painting Room  Welding Store	Vaccum Packing Section  RCC load bearing structure on beam column and 9" brick walls  GI sheet roof mounted on iron pillars, trusses frame structure  RCC load bearing structure on beam column and 9" brick walls  GI sheet roof mounted on iron pillars, trusses frame structure  RCC load bearing structure on beam column and 9" brick walls  GI sheet roof mounted on iron pillars, trusses frame structure  RCC load bearing structure on beam column and 9" brick walls  GI sheet roof mounted on iron pillars, trusses frame structure  GI sheet roof mounted on iron pillars, trusses frame structure  GI sheet roof mounted on iron pillars, trusses frame structure  GI sheet roof mounted on iron pillars, trusses frame structure  GI sheet roof mounted on iron pillars, trusses frame structure  GI sheet roof mounted on iron pillars, trusses frame structure  RCC load bearing structure on beam column and 9" brick walls on Ground & GI Sheed on Iron polls on First Floor  RCC load bearing structure on beam column and 9" brick walls on Ground & GI Sheed on Iron polls on First Floor  RCC load bearing structure on beam column and 9" brick walls on Ground & GI Sheed on Iron polls on First Floor  RCC load bearing structure on beam column and 9" brick walls  GI sheet roof mounted on iron pillars, trusses frame structure  RCC load bearing structure on beam column and 9" brick walls  GI sheet roof mounted on iron pillars, trusses frame structure  Syndicate Office  GI sheet roof mounted on iron pillars, trusses frame structure  Shipping & Transport Building  GI sheet roof mounted on iron pillars, trusses frame structure  Shipping & Transport Building  GI sheet roof mounted on iron pillars, trusses frame structure  RCC load bearing structure on beam column and 9" brick walls  RCC load bearing structure on beam column and 9" brick walls  RCC load bearing structure on beam column and 9" brick walls	Workman Shelter    pillars, trusses frame structure   Ground	Workman Shelter         pillars, trusses frame structure on beam column and 9" brick walls         Ground         172.16           Vaccum Packing Section         RCC load bearing structure on beam column and 9" brick walls         Ground         256.48           Hazardous Waste Storage Area plilars, trusses frame structure         Gi sheet roof mounted on iron pillars, trusses frame structure         Ground         359.30           Practical Trainning Centre         RCC load bearing structure on beam column and 9" brick walls         Ground         337.70           Container Loader         Gi sheet roof mounted on iron pillars, trusses frame structure         Ground         38.54           Tool Issue         Gi sheet roof mounted on iron pillars, trusses frame structure         Ground         3.49           Utility         Gi sheet roof mounted on iron pillars, trusses frame structure         Ground         3.49           Common Service         Gi sheet roof mounted on iron pillars, trusses frame structure         Ground         672.13           Car Parking Area         Gi sheet roof mounted on iron pillars, trusses frame structure         Ground         672.13           Parking         Coload bearing structure on beam column and 9" brick walls on Ground         G+1         2253.72           Cycle Stand         RCC load bearing structure on beam column and 9" brick walls on Ground         G+1         56.26

FILE NO.: RKA/FY18-19/738 Page 19 of 45





Total Covered Area 115890.46			
Ground	ads	8457.69	91038.58
Ground	ost 7 GI sheet roof mounted on iron pillars, trusses frame structure	2.80	30.14
Ground	GI sheet roof mounted on iron pillars, trusses frame structure	63.49	683.41
Ground	Office GI sheet roof mounted on iron pillars, trusses frame structure	36.30	390.73
Ground	GI sheet roof mounted on iron pillars, trusses frame structure	24.00	258.34
Ground	GI sheet roof mounted on iron pillars, trusses frame structure	75.82	816.13
Ground	est 6 RCC load bearing structure on bean column and 9" brick walls	6.80	73.20
Ground	Fice RCC load bearing structure on bean column and 9" brick walls	274.51	2954.83
Ground	t Final Inspection GI sheet roof mounted on iron pillars, trusses frame structure	670.29	7215.00
Ground	ost 5 GI sheet roof mounted on iron pillars, trusses frame structure	5.01	53.93
Ground	ost 4 GI sheet roof mounted on iron pillars, trusses frame structure	2.21	23.79
Ground	ost 3 GI sheet roof mounted on iron pillars, trusses frame structure	5.01	53.93
Ground	GI sheet roof mounted on iron pillars, trusses frame structure	31.07	334.44
Ground	GI sheet roof mounted on iron pillars, trusses frame structure	124.67	1341.95
Ground	GI sheet roof mounted on iron pillars, trusses frame structure	348.41	3750.29
Ground	ost 2 GI sheet roof mounted on iron pillars, trusses frame structure	27.53	296.33
Ground	2nd GI sheet roof mounted on iron pillars, trusses frame structure	44.09	474.58
Ground	GI sheet roof mounted on iron pillars, trusses frame structure	24.13	259.74
Ground	GI sheet roof mounted on iron pillars, trusses frame structure	24.18	260.27
Ground	GI sheet roof mounted on iron pillars, trusses frame structure	16.94	182.34
	GI sheet roof mounted on iron		

#### Note:

- i. Area measurements considered in the Valuation Report pertaining to Land & Building is adopted from relevant approved documents or actual site measurement whichever is less. All area measurements are on approximate basis only.
- ii. All area measurements are on approximate basis. Verification of the area measurement of the property is done based on sample random checking only.
- iii. Area of the large land parcels of more than 2500 sq.mtr or of uneven shape, is taken as per property documents which has been relied upon.

FILE NO.: RKA/FY18-19/738 Page 20 of 45





# PART C VALUATION ASSESSMENT OF THE PROPERTY - ANNEXURE - II

1.	ASSESSMENT FACTORS					
a.	Valuation Type	Land & Building V	alue	Industrial Land & Bui	lding Value	
b.	Scope of the Valuation	Non binding opinion	on on the assessm	nent of Plain Asset Valu	ation of the	
		property identified	by the owner or th	nrough his representativ	/e	
C.	Property Use factor		nt Use	Highest &Be		
			strial	Industr	ial	
d.	Legality Aspect Factor (Refer sub clause I & j of Point 7)	•	cuments produced			
e.	Land Physical factors	Shape	Size	Level	Frontage to depth ratio	
		Irregular	Very Large	On Road Level	Normal frontage	
f.	Property location	City	Locality	Property location	Floor Level	
	category factor	Categorization	Categorization	classification		
		Scale-C City	Average	Near to Highway		
		,	Property within	On wide approach		
			well developed	road		
			Industrial Area	NA		
		Property Facing	North Facing			
g.	Any New Development in	n No				
	surrounding area					
h.	Any specific advantage/	None				
	drawback in the property					
i.	Overall property usability Factor	Normal				
j.	Comment on Property Salability Outlook	Saleability prospe	ct will be in conjun	ection to its current use.		
k.	Comment on Demand &	Presently deman	d of Industrial pr	roperties is low in co	mparison to its	
	Supply in the Market	supply.				
I.	Sale transaction method assumed	market survey e compulsion.	ach acted knowle	length wherein the padgeably, prudently a	nd without any	
m.	Best Sale procedure to realize maximum Value	market survey e compulsion.	ach acted knowle	length wherein the padgeably, prudently a	nd without any	
n.	Methodology/ Basis of	Govt. Guideline	Value: No inform	mation available for in	dustrial & non-	
	Valuation	agricultural land.				
		Market Value:	Land Value is o	calculated on the ba	sis of 'Market	
			• •	building construction val	lue is calculated	
		on the basis of 'Depreciated Replacement Cost approach'				
				les, significant local end	•	
			-	urselves as both buyer		
		similar property	and thereafter ba	ased on this informati	on and various	

FILE NO.: RKA/FY18-19/738 Page 21 of 45





factors of the property, a rate has been judiciously taken seeing the market			
scenario. Kindly please refer below section to know the name & contact			
numbers from whom enquiries have been made.			
market Rate/Price trend of the property and Details of the sources from			Ο.
pathered (from property search sites & local information)		where	
Cross-Section of people	•	i.	
	Contact No.:		
Habitant of subject location	Nature of reference:		
	Size of the Property:		
In Yamuna Nagar, Inside main road	Location:		
, , , , ,	Rates/ Price informed:		
	Any other details/ Discussion		
rates for land nearby our subject property varies from Rs. 18,000-Rs.	held:		
25,000/- per sq.yds.			
Batra Coal Depot		ii.	
	Contact No.:		
	Nature of reference:		
	Size of the Property:		
On Saharanpur-Kurukshetra road	Location:  Rates/ Price informed:		
are in the price range of Rs. 90,000/- per sq.yd. – Rs. 1,10,000/-	Any other details/ Discussion held:		
er the conversation with the local habitants, we were informed that the rates	pted Rates	p. Adopt	p.
and in the nearby vicinity of our subject property varies from Rs. 18,000/- to 25,000/- per sq.yds. Commercial plots are ranging from Rs.90,000/- per sq.yds. 3.1,10,000/- per sq.yds. As per our market research we couldn't come across instance of such a large land parcel transaction. No recent sale or Rates could nown for large land parcels in this locality or within 5 Kms of area.  The rates are related to small residential plots since the area has already come or Abadi. A Municipal Corporation limits.  The assumed that the requirement of transaction of this asset will arise by the conly in case this Industry will become non-operational. Since this area has aly come under Abadi therefore the transaction of land will take place for the ential plotting scheme only as it will be its highest. The best use. While taking consideration it is also kept into mind that HSIIDC Phase — 2 is located nearby the any new Industry will either come in the notified Industrial zone or in a non-	for land in the Rs. 25,000/- to Rs.1,10,0 any instance be known for These rates under Abadi  It is assume Bank only in already commercidential positions that the situation applied Land However, go		ρ.
ever, gover	However, go		

FILE NO.: RKA/FY18-19/738 Page 22 of 45





opposite to the subject property.

In such a scenario the subject land will be developed & sold by some developer for residential & commercial purpose, after deducting the land for internal development & providing basic civic amenities like roads, sewerage, etc. (around 25%), discounting various expenses for creating amenities while developing the subject land (around 20% of total sale consideration) & considering a descent amount of profit of the developer (around 20% of total sale consideration), we are of the view that the fair market value of the subject land should be Rs. 10,500/- per sq.yds. & the same has been adopted for the purpose of this valuation exercise.

Since the land is very large and its sale as such will be little hard and therefore the adopted rates appears to be reasonable in our view.



FILE NO.: RKA/FY18-19/738 Page 23 of 45





2.		VALUATION OF LAND  Applicable	
	Particulars	Govt. Circle/ Guideline Value	Prospective Fair Market Value
a.	Prevailing Rate range	HSIDC Industrial Area:- Rs. 11,000/- per sq.mtr. For Agricultural Land:- Rs. 85,00,000/- per acre For Residential Land:- Rs. 4,000/- per sq.mtr.	Rs. 18,000/ Rs. 25,000/- per sq.yds.
b.	Rate adopted considering all characteristics of the property	No information available for Industrial & Non Agricultural Land	Rs. 10,500/- per sq.yds.
C.	Total Land Area considered (documents vs site survey whichever is less)	NA	44.75 acre (2,16,590 sq.yds)
d.	Total Value of land (A)	NA	Rs. 10,500/- per sq.yds. x 2,16,590 sq.yds.
		NA	Rs. 2,27,41,95,000/-

3.		<u>VA</u>	LUATION OF BUILDING STRU	<u>CTURE</u>
	Particulars		Govt. Circle/ Guideline Value	Prospective Fair Market Value
		Rate range	No information available	Please refer to the building sheet
		3		given below
		Rate adopted	NA	Please refer to the building sheet given below
	Structure	Covered Area	NA	12,47,444.91 sq.ft.
a.	Construction	Class of	IVA	12,47,444.91 Sq.it.
	Value	construction	NA	Class B construction (Good)
		Valuation		Please refer to the building sheet
		Calculation	NA	given below
		Total Value	NA	Rs. 1,27,42,08,664/-
b.	Depreciation p	_	NIA	NA
	(assuming salvage v	value % per year)	NA	(Above replacement rate is calculated after deducting the prescribed depreciation)
C.	Age Factor		NA	Construction older than 15 years
				and Above
d.	Structure Type/ Condition		Pucca (1.0)	Please refer to the building sheet
u.				given below
e.	Construction D	=	NA	Rs. 1,27,42,08,664/-
	Replacement \	/alue <b>(B)</b>		

FILE NO.: RKA/FY18-19/738 Page 24 of 45



# M/S ISGEC HEAVY ENGINEERING LTD., YAMUNA NAGAR

	Valuation	of Civil/ Structure of M/s.	ISGEC Heary	<b>Engineerin</b>	g Limited, Yamuna N	agar	
			Total No.	Total		Adopted	Depreciated
\$. I	Name of Building	Type of Structure	Floor: ▼	COTET -	Total Area & &	rate 6	Replaceme Value
1	Pressure Vessel-1	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	2557.14	27525.05	₹ 1,450.00	₹ 39,911,330
2	Pressure Vessel- 2	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	7656.82	82418.01	₹ 1,450.00	₹ 119,506,115
3	Pressure Vessel- 3	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	5009.07	53917.63	₹ 1,450.00	₹ 78,180,563
4	Pressure Vessel- 4	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	4220.37	45428.06	₹ 1,450.00	₹ 65,870,691
5	Pressure Valve- 5	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	1935.70	20835.87	₹ 1,450.00	₹ 30,212,018
6	Pressure Vessel- 6	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	6470.30	69646.31	₹ 1,450.00	₹ 100,987,148
7	New Assembly	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	4882.21	52552.11	₹ 1,450.00	₹ 76,200,557
8	Security Post 1	RCC load bearing structure on beam column and 9" brick walls	Ground	15.49	166.73	₹ 450.00	₹ 75,030
9	Water Treatment Plant	RCC load bearing structure on beam column and 3" brick walls	Ground	565.45	6086.50	₹ 650.00	₹ 3,956,227
10	SSM Water Treatment Plant 1	RCC load bearing structure on beam column and 3" brick walls	Ground	32.30	347.68	₹ 700.00	₹ 243,374
11	SSM Water Treatment Plant 2	RCC load bearing structure on beam column and 3" brick walls	Ground	2335.52	25139.54	₹ 650.00	₹ 16,340,699
12	Proposed Gas Cylinder Godown	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	452.87	4874.69	₹ 400.00	₹ 1,949,877
13	Gas Cylinder Godown 1	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	280.85	3023.07	₹ 550.00	₹ 1,662,688
14	Gas Cylinder Godown 2	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	173.59	1868.52	₹ 500.00	₹ 934,261
15	New Preparation Shop	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	2384.79	25669.88	₹ 400.00	₹ 10,267,952
16	Preparation Shop	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	2498.82	26897.30	₹ 1,250.00	₹ 33,621,623
17	Iron Store	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	976.03	10505.99	₹ 700.00	₹ 7,354,191
18	Pipe Shop	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	3774.13	40624.74	₹ 1,300.00	₹ 52,812,156
19	New Tube Shop 1	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	994.21	10701.68	₹ 950.00	₹ 10,166,593
20	New Tube Shop 2	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	47.37	509.89	₹ 400.00	₹ 203,956
21	Pipe Shop - 2	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	2712.13	29193.37	₹ 1,200.00	₹ 35,032,041
22	Container Shop	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	1693.52	18229.05	₹ 1,100.00	₹ 20,051,954
23	Container Paint Shop	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	2306.39	24825.98	₹ 1,100.00	₹ 27,308,580
24	Old Fabrication (MBD Shop- 1)	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	5975.53	64320.60	₹ 1,450.00	₹ 93,264,877
25	Old Fabrication	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	233.12	2509.30	₹ 500.00	₹ 1,254,652

FILE NO.: RKA/FY18-19/738 Page 25 of 45



# M/S ISGEC HEAVY ENGINEERING LTD., YAMUNA NAGAR

26	Foundary Shop 1	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	3097.02	33336.32	₹ 1,000.00	₹	33,336,323
27	Foundary Shop 2	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	937.45	10090.71	₹ 850.00	₹	8,577,105
28	Foundary Shop 3	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	3059.64	32933.96	₹ 1,300.00	₹	42,814,154
29	Foundary Shop 4	GI sheet roof mounted on iron	Ground	546.17	5878.97	₹ 950.00	₹	5,585,025
		pillars, trusses frame structure GI sheet roof mounted on iron					-	
30	Foundary Shop 5	pillars, trusses frame structure	Ground	2171.43	23373.27	₹ 1,300.00	₹	30,385,254
31	Foundary Office	RCC load bearing structure on beam column and 9" brick walls	G+1	343.32	3695.50	₹ 600.00	₹	2,217,298
32	Foundary Shop Office	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	342.32	3684.73	₹ 550.00	₹	2,026,603
33	MBD New Shop 1	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	2603.37	28022.67	₹ 1,300.00	₹	36,429,477
34	MBD New Shop 2	GI sheet roof mounted on iron	Ground	371.20	3995.60	₹ 550.00	₹	2,197,578
		pillars, trusses frame structure					_	
35	MBD Office	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	512.77	5519.46	₹ 600.00	₹	3,311,674
36	Toilet 1	RCC load bearing structure on beam column and 3" brick walls	Ground	24.26	261.13	₹ 500.00	₹	130,567
37	Toilet 2	RCC load bearing structure on beam column and 3" brick walls	Ground	17.68	190.31	₹ 500.00	₹	95,154
38	Toilet 3	RCC load bearing structure on beam column and 3" brick walls	Ground	15.21	163.72	₹ 500.00	₹	81,860
39	Toilet 4	RCC load bearing structure on beam column and 9" brick walls	Ground	14.44	155.43	₹ 500.00	₹	77,716
40	Toilet 5	RCC load bearing structure on beam column and 9" brick walls	Ground	9.47	101.94	₹ 500.00	₹	50,968
41	Toilet 6	RCC load bearing structure on beam column and 9" brick walls	Ground	12.81	137.89	₹ 500.00	₹	68,943
42	Toilet 7	RCC load bearing structure on	Ground	18.22	196.12	₹ 500.00	₹	98,060
43	Toilet 8	Beam column and 9" brick walls  RCC load bearing structure on	Ground	31.54	339.50	₹ 500.00	₹	169,748
44	Toilet 9	beam column and 9" brick walls  RCC load bearing structure on	Ground	10.83	116.57	₹ 500.00	₹	58,287
45	Toilet 10	beam column and 9" brick walls RCC load bearing structure on	Ground	22.57	242.94	₹ 500.00	₹	121,472
		beam column and 9" brick walls	2.5414		272,77		Ľ	,-/-
46	Toilet 11	RCC load bearing structure on beam column and 9" brick walls	Ground	12.42	133.69	₹ 500.00	₹	66,844
47	Toilet 12	RCC load bearing structure on beam column and 3" brick walls	Ground	18.65	200.75	₹ 500.00	₹	100,374
48	Toilet 13	RCC load bearing structure on beam column and 3" brick walls	Ground	32.07	345.20	₹ 500.00	₹	172,601
43	Building 1	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	315.57	3396.80	₹ 550.00	₹	1,868,238
50	Building 2	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	223.89	2409.95	₹ 500.00	₹	1,204,976
51	Building 3	GI sheet roof mounted on iron	Ground	84.61	910.74	₹ 450.00	₹	409,834
52	Building 4	pillars, trusses frame structure GI sheet roof mounted on iron	Ground	11.44	123.14	₹ 275.00	₹	33,864
	•	pillars, trusses frame structure						

FILE NO.: RKA/FY18-19/738 Page 26 of 45



# M/S ISGEC HEAVY ENGINEERING LTD., YAMUNA NAGAR

		I Obstantance to the control of						
53	Building 5	GI sheet roof mounted on iron	Ground	31.09	334.65	₹ 350.00	₹	117,128
-+	-	pillars, trusses frame structure GI sheet roof mounted on iron					$\vdash$	
54	Building 6	pillars, trusses frame structure	Ground	16.50	177.61	₹ 275.00	₹	48,842
		GI sheet roof mounted on iron					$\vdash$	
55	Store 1	pillars, trusses frame structure	Ground	23.82	256.40	₹ 350.00	₹	89,739
-		GI sheet roof mounted on iron					$\vdash$	
56	Store 2	pillars, trusses frame structure	Ground	33.74	363.18	₹ 350.00	₹	127,112
		GI sheet roof mounted on iron					<u> </u>	
57	Store 3	pillars, trusses frame structure	Ground	33.15	356.83	₹ 350.00	₹	124,889
	A	GI sheet roof mounted on iron		07.75	200 30	₹ 350.00	-	404 545
58	Store 4	pillars, trusses frame structure	Ground	27.75	298.70	₹ 350.00	₹	104,545
59	Store 5	GI sheet roof mounted on iron	Ground	35.49	382.01	₹ 350.00	₹	133,705
33	Store 5	pillars, trusses frame structure	Ground	33.43	302.01	330.00	`	155,105
60	Store 6	GI sheet roof mounted on iron	Ground	37.71	405.91	₹ 350.00	₹	142,069
	0.0100	pillars, trusses frame structure	arouna	01.11	403.01	. 030.00	`	142,000
61	S.S. Store	GI sheet roof mounted on iron	Ground	113.37	1220.31	₹ 450.00	₹	549,142
	*********	pillars, trusses frame structure					Ľ.	
62	Building Store	GI sheet roof mounted on iron	Ground	185,36	1995.22	₹ 500.00	₹	997,608
		pillars, trusses frame structure						
63	DD Store	GI sheet roof mounted on iron	Ground	254.74	2742.02	₹ 500.00	₹	1,371,011
		pillars, trusses frame structure					-	
64	Chemical Store	GI sheet roof mounted on iron	Ground	233.47	2513.07	₹ 500.00	₹	1,256,536
		pillars, trusses frame structure GI sheet roof mounted on iron					-	
65	Main Store	pillars, trusses frame structure	Ground	1640.03	17653.93	₹ 1,100.00	₹	19,419,322
		RCC load bearing structure on					$\vdash$	
66	Paint Store	beam column and 9" brick walls	Ground	410.74	4421.21	₹ 600.00	₹	2,652,723
		GI sheet roof mounted on iron						
67	Fastener Store	pillars, trusses frame structure	Ground	211.04	2271.63	₹ 500.00	₹	1,135,817
	21 14	GI sheet roof mounted on iron		400.00	0404.03		₹	4007.005
68	Shed 1	pillars, trusses frame structure	Ground	198.26	2134.07	₹ 500.00	۲.	1,067,035
69	Shed 2	GI sheet roof mounted on iron	Ground	325.19	3500.35	₹ 550.00	₹	1,925,190
00	Siled 2	pillars, trusses frame structure	Ground	323.13	3300.33	330.00	`	1,525,150
70	Shed 3	GI sheet roof mounted on iron	Ground	54.43	585.88	₹ 400.00	₹	234,354
	01103 0	pillars, trusses frame structure	4.04.14	54.40	303.00	. 400.00	`	204,054
71	Shed 4	GI sheet roof mounted on iron	Ground	140.38	1511.05	₹ 500.00	₹	755,525
		pillars, trusses frame structure					Ľ.	,
72	Shed 5	GI sheet roof mounted on iron	Ground	64.77	697.18	₹ 400.00	₹	278,874
		pillars, trusses frame structure						
73	Shed 6	GI sheet roof mounted on iron	Ground	17.80	191.60	₹ 275.00	₹	52,690
-+		pillars, trusses frame structure					<del></del>	
74	Shed 7	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	55.99	602.68	₹ 400.00	₹	241,071
-+		GI sheet roof mounted on iron					$\vdash$	
75	Shed 8	pillars, trusses frame structure	Ground	78.57	845.73	₹ 450.00	₹	380,577
		GI sheet roof mounted on iron						
76	Shed 9	pillars, trusses frame structure	Ground	12.37	133.15	₹ 275.00	₹	36,616
	01.140	GI sheet roof mounted on iron	0	004.00	0405.45	* FF0.00	-	430440-
77	Shed 10	pillars, trusses frame structure	Ground	291.29	3135.45	₹ 550.00	₹	1,724,495
70	01.144	GI sheet roof mounted on iron	0	44.6.4	105.00	₹ 275.00	₹	04.450
78	Shed 11	pillars, trusses frame structure	Ground	11.64	125.29	₹ 275.00	<b>_</b>	34,456
79	Shed 12	GI sheet roof mounted on iron	Ground	24.17	260.17	₹ 350,00	₹	91,058
.~	oned iz	pillars, trusses frame structure	Ground	24.11	200.11	350.00	*	31,030

FILE NO.: RKA/FY18-19/738 Page 27 of 45



# M/S ISGEC HEAVY ENGINEERING LTD., YAMUNA NAGAR

Power Nouse   Power flower   Power Nouse   Power flower   Power flower flower   Power flower   Power flower flower   Power flower   Power flower   Power flower flower   Power flower flower   Power flower flower flower   Power flower flower flower flower   Power flower flow	80	Shed 13	ar sneet roor mounted on fron	Ground	26.05	280.40	₹ 350	00	₹	98,141
Power House									Ľ.	
P.V.D Quality   P.C.D Good bearing structure on beam column and 3" brick walls   P.V.D Industry   Gishect roof mounted on iron pillars, trusses frame structure on beam column and 3" brick walls   P.V.D Industry   Gishect roof mounted on iron pillars, trusses frame structure on beam column and 3" brick walls   Power Control Centre   Gishect roof mounted on iron pillars, trusses frame structure on beam column and 3" brick walls   Ground   176.47   1893.52   ₹ 500.00   ₹ 24.	81	Adda Sheds	pillars, trusses frame structure	Ground	660.05	7104.78	₹ 600	.00	₹	4,262,867
Section   Sect	82	Ambulance Shed		Ground	20.56	221.31	₹ 275	.00	₹	60,860
P.Y.D. Industry   pillurs, truscer frame structure   Ground   16.47   1899.52   \$ 500.00   \$ 3	83	P.V.D Quality	-	G+1	2159.88	23248.95	₹ 1,050	.00	₹	24,411,396
Power House   Prover Cload bearing structure   Prover Cload bearing structure   Prover Cload bearing structure   Prover House   Provent House   Prover House   Provent	84	P.V.D Industry		Ground	176.47	1899.52	₹ 500	.00	₹	949,762
Power House Ped   Dishect roof mounted on iron pillars, trusses frame structure of beam column and 3" brick walls   Ground   11.26   Ground   184.45   1385.42   ₹ 500.00   ₹ 3.00	85	Power Control Centre	l	Ground	43.73	470.71	₹ 350	.00	₹	164,748
Power House Ped   pillars, trusses frame structure   Ground   67.16   722.91   ₹ 400.00   ₹ 2   2   2   3   3   3   3   3   4   3   3   3   4   3   3	86	Power House	-	Ground	77.26	831.63	₹ 600	.00	₹	498,976
Pillars, trusces frame structure   Pillars, trusc	87	Power House Ped		Ground	67.16	722.91	₹ 400	.00	₹	289,164
Searce   2	88	Canteen 1		Ground	184.45	1985.42	₹ 500	.00	₹	992,710
30	89	Canteen 2	-	Ground	143.85	1548.40	₹ 650	.00	₹	1,006,461
Signature   Sign	90	Canteen 3	· · · · · · · · · · · · · · · · · · ·	Ground	127.62	1373.70	₹ 650	.00	₹	892,906
Section   Part   Part	91	Canteen 4	_	G+1	475.12	5114.19	₹ 700	.00	₹	3,579,934
93   Gas Godown   pillars, trusses frame structure   Ground   237.33   2534.62   ₹ 500.00   ₹ 1,3     94   Cement Godown   Gil sheet roof mounted on iron   pillars, trusses frame structure   Ground   198.94   2141.39   ₹ 500.00   ₹ 1,3     95   Blasting Room   Gil sheet roof mounted on iron   pillars, trusses frame structure   Ground   198.94   2141.39   ₹ 500.00   ₹ 1,0     96   Painting Room   Gil sheet roof mounted on iron   pillars, trusses frame structure   Ground   150.46   1619.55   ₹ 500.00   ₹ 1,0     97   Cobalt Room   RCC load bearing structure on   beam column and 9" brick walls   Ground   80.80   869.73   ₹ 500.00   ₹ 4     98   Meter Room   RCC load bearing structure on   beam column and 9" brick walls   Ground   23.74   255.54   ₹ 400.00   ₹     99   PED Offices Extension   RCC load bearing structure on   beam column and 9" brick walls   Ground   100.34   1080.06   ₹ 850.00   ₹ 1,3     100   X-Ray Room   RCC load bearing structure on   beam column and 3" brick walls   Ground   100.34   1080.06   ₹ 850.00   ₹ 1,6     101   P.V.D Office   RCC load bearing structure on   beam column and 3" brick walls   Ground   100.34   1080.06   ₹ 850.00   ₹ 1,6     102   Hall 1   RCC load bearing structure on   beam column and 3" brick walls   Ground   147.07   1583.06   ₹ 850.00   ₹ 1,3     103   Hall 2   RCC load bearing structure on   beam column and 3" brick walls   Ground   147.07   1583.06   ₹ 850.00   ₹ 1,3	92	LPG Godown		Ground	485.66	5227.64	₹ 600	.00	₹	3,136,587
Sement Godown   pillars, trusses frame structure   Ground   S21.33   S430.00   ₹ 500.00   ₹ 1.00	93	Gas Godown		Ground	237.33	2554.62	₹ 500	.00	W	1,277,310
Stating Room   pillars, trusses frame structure   Ground   198.94   214.39   ₹ 500.00   ₹ 1,0	94	Cement Godown	l	Ground	321.33	3458.80	₹ 550	.00	W	1,902,338
Painting Room   pillars, trusses frame structure   Ground   150.46   1619.55   \$ 500.00   \$ 6 6 6 6 7 7 8 7 8 8 8 9 7 8 9 8 9 8 9 8 9 8 9 9 9 9	95	Blasting Room		Ground	198.94	2141.39	₹ 500	.00	₹	1,070,695
Sear	96	Painting Room		Ground	150.46	1619.55	₹ 500	.00	₹	809,776
Seam column and 9" brick walls   Ground   23.14   233.34   400.00   ₹	97	Cobalt Room	-	Ground	80.80	869.73	₹ 500	.00	₹	434,866
100   X-Ray Room   RCC load bearing structure on beam column and 3" brick walls   G+2   24.41   2301.31   < 650.00   < 1,3	98	Meter Room	-	Ground	23.74	255.54	₹ 400	.00	₹	102,215
100   X-Hay Room	99	PED Offices Extension	-	G+2	214.41	2307.91	₹ 850	.00	₹	1,961,723
102   Hall 1   RCC load bearing structure on beam column and 3" brick walls   Ground   34.40   1016.12   ₹ 850.00 ₹ 1,8	100	X-Ray Room	_	Ground	100.34	1080.06	₹ 850	.00	₹	918,051
102	101	P.V.D Office	·	G+2	832.14	8957.15	₹ 850	.00	₹	7,613,582
103 Hall 2 RCC load bearing structure on beam column and 9" brick walls  CCC load bearing structure on beam column and 9" brick walls  CCC load bearing structure on beam column and 9" brick walls	102	Hall 1	-	Ground	34.40	1016.12	₹ 850	.00	₹	863,703
DCC lead bearing structure as	103	Hall 2	RCC load bearing structure on	Ground	147.07	1583.06	₹ 850	.00	₹	1,345,602
104 IA%E Office Beam column and 3" brick walls Ground 66.62 717.10 ₹ 700.00 ₹ 5	104	IA&E Office	RCC load bearing structure on	Ground	66.62	717.10	₹ 700	.00	₹	501,968
105 Accounts GI sheet roof mounted on iron pillars, trusses frame structure Ground 55.69 599.45 ₹ 650.00 ₹ 3	105	Accounts		Ground	55.69	599.45	₹ 650	.00	₹	389,641
DCC load having structure on	106	MD Office	RCC load bearing structure on	Ground	129.47	1393.62	₹ 850	.00	₹	1,184,573

FILE NO.: RKA/FY18-19/738 Page 28 of 45



# M/S ISGEC HEAVY ENGINEERING LTD., YAMUNA NAGAR

		RCC load bearing structure on				1		
107	Office	beam column and 9" brick walls	Ground	140.00	1506.96	₹ 850.00	₹	1,280,916
108	Commercial	RCC load bearing structure on beam column and 9" brick walls	Ground	79.56	856.38	₹ 650.00	₹	556,649
109	Purchase	RCC load bearing structure on beam column and 9" brick walls	Ground	118.59	1276.50	₹ 1,050.00	₹	1,340,328
110	Office	RCC load bearing structure on beam column and 9" brick walls	Ground	95.29	1025.70	₹ 750.00	₹	769,276
111	MBD Office	RCC load bearing structure on beam column and 9" brick walls	Ground	95.22	1024.95	₹ 750.00	₹	768,711
112	Tool Room	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	280.31	3017.26	₹ 550.00	₹	1,659,491
113	Battery Room	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	121.40	1306.75	₹ 500.00	₹	653,375
114	Switch Room	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	35.30	379.97	₹ 350.00	₹	132,989
115	Assembly Room	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	85.22	917.31	₹ 450.00	₹	412,789
116	Comp. With DG Set Room	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	226.25	2435.36	₹ 500.00	₹	1,217,678
117	Ambulance Room	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	29.30	315.39	₹ 350.00	₹	110,385
118	Work Administration Offices	RCC load bearing structure on beam column and 9" brick walls	G+1	427.66	4603.33	₹ 750.00	₹	3,452,499
119	Time Office	RCC load bearing structure on beam column and 9" brick walls	Ground	55.62	598.69	₹ 750.00	₹	449,020
120	LLOYD'D Office	RCC load bearing structure on beam column and 9" brick walls	Ground	21.55	231.96	₹ 450.00	₹	104,384
121	Register Office	RCC load bearing structure on beam column and 9" brick walls	Ground	26.44	284.60	₹ 500.00	₹	142,300
122	Dust Free Office	RCC load bearing structure on beam column and 9" brick walls	Ground	86.64	932.59	₹ 650.00	₹	606,185
123	R&D ISGEC Office	RCC load bearing structure on beam column and 9" brick walls	Ground	208.43	2243.54	₹ 1,050.00	₹	2,355,718
124	Office Building Electrode Issue Cabin and Toilets	RCC load bearing structure on beam column and 9" brick walls	Ground	253.98	2733.84	₹ 850.00	₹	2,323,765
125	Syndicate Office 1	RCC load bearing structure on beam column and 9" brick walls	Ground	395.19	4253.83	₹ 650.00	₹	2,764,986
126	Syndicate Office 2	RCC load bearing structure on beam column and 9" brick walls	Ground	320.10	3445.56	₹ 650.00	₹	2,239,612
127	Syndicate Office 3	RCC load bearing structure on beam column and 3" brick walls	Ground	98.83	1063.81	₹ 1,050.00	₹	1,116,996
128	State Bank	RCC load bearing structure on beam column and 9" brick walls	Ground	432.19	4652.09	₹ 850.00	₹	3,954,279
129	Shop 1	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	67.33	724.74	₹ 400.00	₹	289,896
130	Shop 2	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	80.88	870.59	₹ 450.00	₹	391,767
131	Shop 3	Gl sheet roof mounted on iron pillars, trusses frame structure	Ground	125.16	1347.22	₹ 500.00	₹	673,611
132	Lean to Machine Shop	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	288.38	3104.12	₹ 550.00	₹	1,707,267
133	Punching 1	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	15.34	165.12	₹ 275.00	₹	45,408

FILE NO.: RKA/FY18-19/738 Page 29 of 45



# M/S ISGEC HEAVY ENGINEERING LTD., YAMUNA NAGAR

134	Punching 2	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	8.49	91.39	₹	275.00	₹	25,131
135	Punching 3	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	6.71	72.23	₹	275.00	₹	19,862
136	Diesel Tank Storage	Under Ground	Ground	301.07	3240.72	₹	650.00	₹	2,106,466
137	Diesel Storage Site	Under Ground	Ground	330.63	3558.90	₹	650.00	₹	2,313,286
138	E Waste Site	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	36.43	392.13	₹	350.00	₹	137,246
139	Common Service Deptt.	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	172.33	1854.96	₹	500.00	₹	927,480
140	PED Maint, Deptt.	RCC load bearing structure on beam column and 9" brick walls	Ground	346.74	3732.31	₹	700.00	₹	2,612,617
141	Inspection Deptt.	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	83.93	903.42	₹	450.00	₹	406,540
142	Shipping & Transport	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	646.52	6959.14	₹	400.00	₹	2,783,657
143	ADDA Transport	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	241.65	2601.12	₹	500.00	₹	1,300,560
144	Shipping & Transport	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	143.23	1541.73	₹	500.00	₹	770,864
145	Blasting Foundation	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	68.41	736.37	₹	400.00	₹	294,546
146	Spot Blasting	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	24.86	267.59	₹	350.00	₹	93,658
147	Shot Blasting	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	100.57	1082.54	₹	500.00	₹	541,268
148	Transformer Centre	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	52.39	563.93	₹	400.00	N	225,570
149	Telephone Exchange	RCC load bearing structure on beam column and 3" brick walls	Ground	43.94	472.97	₹	500.00	₹	236,485
150	Air Compressor	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	33.24	357.80	₹	350.00	₹	125,228
151	Container Shop Air Compressor	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	92.20	992.44	₹	400.00	₹	396,976
152	MBD Power	Gl sheet roof mounted on iron pillars, trusses frame structure	Ground	86.05	926.24	₹	450.00	₹	416,809
153	Reception	RCC load bearing structure on beam column and 9" brick walls	Ground	76.03	818.39	₹	700.00	₹	572,871
154	Cashier	RCC load bearing structure on beam column and 9" brick walls	Ground	13.23	142.41	₹	450.00	₹	64,083
155	Visitors	RCC load bearing structure on beam column and 9" brick walls	Ground	14.07	151.45	₹	450.00	₹	68,152
156	Workman Shelter	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	172.16	1853.13	₹	500.00	₹	926,565
157	Vaccum Packing Section	RCC load bearing structure on beam column and 9" brick walls	Ground	256.48	2760.75	₹	500.00	₹	1,380,375
158	Hazardous Waste Storage Area	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	84.35	907.94	₹	450.00	₹	408,575
159	Automobile Workshop	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	359.30	3867.51	₹	550.00	₹	2,127,128
160	Practical Trainning Centre	RCC load bearing structure on beam column and 9" brick walls	Ground	337.70	3635.00	₹	750.00	₹	2,726,252
161	Container Loader	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	38.54	414.84	₹	350.00	N	145,196

FILE NO.: RKA/FY18-19/738 Page 30 of 45



# M/S ISGEC HEAVY ENGINEERING LTD., YAMUNA NAGAR

162	Tool Issue	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	40.12	431.85	₹	350.00	₹	151,148
163	Utility	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	3.49	37.57	₹	275.00	₹	10,331
164	Common Service	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	96.41	1037.76	₹	500.00	₹	518,879
165	Car Parking Area	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	672.13	7234.81	₹	350.00	₹	2,532,183
166	Parking	RCC load bearing structure on beam column and 9" brick walls on Ground & GI Shed on Iron polls on First Floor	G+1	2253.72	24259.04	₹	650.00	₹	15,768,377
167	Cycle Stand	RCC load bearing structure on beam column and 3" brick walls on Ground & GI Shed on Iron polls on First Floor	G+1	130.13	1400.72	₹	300.00	₹	420,216
168	Cycle Stand	RCC load bearing structure on beam column and 9" brick walls on Ground & GI Shed on Iron polls on First Floor	G+1	56.26	605.58	₹	400.00	₹	242,233
169	Petrol Pump	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	686.75	7392.18	₹	275.00	₹	2,032,849
170	MBD Pipe Godown	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	347.71	3742.75	₹	550.00	₹	2,058,513
171	Syndicate Office	RCC load bearing structure on beam column and 9" brick walls	Ground	340.23	3662.24	₹	850.00	₹	3,112,900
172	Store	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	973.31	10476.71	₹	950.00	₹	9,952,873
173	Shipping & Transport Building	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	85.40	919.25	₹	450.00	₹	413,661
174	Godown	RCC load bearing structure on beam column and 9" brick walls	Ground	97.56	1050.14	₹	600.00	₹	630,082
175	Painting Room	RCC load bearing structure on beam column and 9" brick walls	Ground	92.89	999.87	₹	500.00	₹	499,934
176	Welding Store	RCC load bearing structure on beam column and 9" brick walls	Ground	395.86	4261.04	₹	550.00	₹	2,343,570
177	Pattern Shop	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	186.80	2010.72	₹	500.00	₹	1,005,358
178	Welding Store	RCC load bearing structure on beam column and 9" brick walls	Ground	52.14	561.23	₹	550.00	₹	308,679
179	Cocker Room	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	52.11	560.91	₹	400.00	₹	224,365
180	MBD Electrical	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	163.18	1756.47	₹	500.00	₹	878,235
181	Quality Office	RCC load bearing structure on beam column and 9" brick walls	Ground	103.23	1111.17	₹	650.00	₹	722,259
182	Power House	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	173.19	1864.22	₹	500.00	₹	932,109
183	MBD-3	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	3298.96	35510.01	₹ 1	1,300.00	₹	46,163,007
184	CS/ Electrical Store	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	17.95	193.21	₹	275.00	₹	53,134
185	ENDG 1st/ 2nd	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	16.96	182.56	₹	275.00	₹	50,203

FILE NO.: RKA/FY18-19/738 Page 31 of 45



#### M/S ISGEC HEAVY ENGINEERING LTD., YAMUNA NAGAR

186	Tee Store	Gl sheet roof mounted on iron pillars, trusses frame structure	Ground	16.94	182.34	₹	275.00	₹ 50,144
187	Union Office	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	24.18	260.27	₹	350.00	₹ 91,096
188	Store 7	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	24.13	259.74	₹	350.00	₹ 90,907
189	ENDG 1st/ 2nd	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	44.09	474.58	₹	350.00	₹ 166,105
190	Security Post 2	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	27.53	296.33	₹	350.00	₹ 103,717
191	Sand Plant	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	348.41	3750.29	₹	550.00	₹ 2,062,657
192	IMF Plant	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	124.67	1341.95	₹	500.00	₹ 670,974
193	Shed 14	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	31.07	334.44	₹	350.00	₹ 117,053
194	Security Post 3	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	5.01	53.93	₹	275.00	₹ 14,830
195	Security Post 4	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	2.21	23.79	₹	275.00	₹ 6,542
196	Security Post 5	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	5.01	53.93	₹	275.00	₹ 14,830
197	Tube Sheet Final Inspection Area	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	670.29	7215.00	₹	550.00	₹ 3,968,251
198	Security Office	RCC load bearing structure on beam column and 9" brick walls	Ground	274.51	2954.83	₹	550.00	₹ 1,625,154
199	Security Post 6	RCC load bearing structure on beam column and 9" brick walls	Ground	6.80	73.20	₹	450.00	₹ 32,938
200	Pipe Store	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	75.82	816.13	₹	450.00	₹ 367,257
201	Gas Room	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	24.00	258.34	₹	300.00	₹ 77,501
202	Pipe Shop Office	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	36.30	390.73	₹	350.00	₹ 136,757
203	Yard Office	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	63.49	683.41	₹	400.00	₹ 273,363
204	Security post 7	GI sheet roof mounted on iron pillars, trusses frame structure	Ground	2.80	30.14	₹	275.00	
205	Internal Roads		Ground	8457.69	91038.58	₹	250.00	₹ 22,759,644
	Total Covered Area			115890.46	1247444.91			₹ 1,274,208,664

#### Remarks

1.All these civil structures has been pertaining to the factory of M/s. ISGEC Heavy Engineering Limited located at Yamuna Nagar.

FILE NO.: RKA/FY18-19/738 Page 32 of 45

<sup>2.</sup> The company has provided us common building sheet comprised of structures of factory M/s. Saraswati Sugar Mill & M/s. ISGEC Heavy Engineering Limited. However, for the Valuation exercise we have strike off the buildings belongs to the company Saraswati Sugar mill from our building sheet.

The covered area of the each facilities has been taken from the information/data provided by the company it self, which is also cross varified by our surveyor at the site doing sample measurment of the some structures.

<sup>3.</sup> No information available to us regarding the year of construction & Height of the each facilities.

<sup>4.</sup> The Valuation of each facilities has been done on the basis of 'Depreciated Replacement Cost approach'.

<sup>5.</sup> There are some of the buildings whose name on the site is different from what has been mentioned in the sheet. Due to large number of buildings we couldn't corect this change and has to go by the sheet provided by the company since it was prepared in line to the Map.

<sup>6.</sup> On our request we have not got the detailed FAR from the company. There are chances that company might have capitalized few Steel structures in the Plant & Machinery. At our end we have taken all the buildings & steel structures in our valuation. To avoid duplicacy Bank may cross check the Building sheet mentioned in the report with that of FAR.





4.	VALUATION OF A	DDITIONAL BUILDING & SITE	AESTHETIC WORKS
	Particulars	Specifications	Depreciated Replacement Value
a.	Add extra for Architectural aesthetic developments, improvements		
b.	(add lump sum cost)  Add extra for fittings & fixtures (doors, windows, wood work, cupboards, modular kitchen, electrical/ sanitary fittings)		
C.	Add extra for services (Water, Electricity, Sewerage, Main gate, Boundary, Lift, Auxiliary power, AC, HVAC, Firefighting etc.)		
d.	Add extra for internal & external development (Internal roads, Landscaping, Pavements, Street lights, Green area development, External area landscaping, Land development, Approach road, etc.)		
e.	Depreciated Replacement Value (C)	NA	

5.		CONSOLIDATED VALUE				
	Particulars	Govt. Circle/ Guideline Value	Prospective Fair Market Value			
a.	Land (A)	NA	Rs. 2,27,41,95,000/-			
b.	Built-Up Unit Value(B)	NA	Rs. 1,27,42,08,664/-			
C.	Additional Building & Site Aesthetic Works Value (C)	NA	NA			
d.	Total Add (A+B+C)	NA	Rs. 3,54,84,03,664/-			
e.	Additional Premium if any					
	Details/ Justification					
f.	Deductions charged if any	Deductions charged if any				
	Details/ Justification	Justification				
g.	Total Prospective Fair Market Value#	NA	Rs. 3,54,84,03,664/-			
h.	Rounded Off		Rs. 3,55,00,00,000/-			
i.	EXPECTED REALIZABLE VALUE^(@ ~20% less)		Rs. 2,83,87,22,930/-			
j.	EXPECTED FORCED/ DISTRESS SALE VALUE*(@ ~30% less)	SS SALE VALUE*(@ Rs.				
k.	Valuation of structure for Insurance purpose	NA	Rs. 81,00,00,000/-			

FILE NO.: RKA/FY18-19/738 Page 33 of 45





	0 1 11 4 16		
6.	Concluding comments if any	a.	Valuation of the asset is done as found on as-is-where basis.
		b.	On our request we have not got the detailed FAR from the
			company. There are chances that company might have capitalized
			few Steel structures in the Plant & Machinery. At our end we have
			taken all the buildings & steel structures in our valuation. To avoid
			duplicacy Bank may cross check the Building sheet mentioned in
			the report with that of FAR.
		C.	Any kind of unpaid statutory, utilities, lease, interest or any other
			pecuniary dues on the asset has not been factored in the
			Valuation.
		d.	Secondary/ Tertiary costs related to asset transaction like Stamp
			Duty, Registration charges, Brokerage, Bank interest etc.
			pertaining to the sale/ purchase of this property are not considered
			while assessing the Market Value.
		e.	As per the scope of the assignment, Value assessment is subject
			to Assumptions, Remarks & Limiting Conditions mentioned in
			Annexure - IV, R.K Associates Important Notes and Valuer's
			Remarks Annexure - V & other enclosed documents with the
			Report which will remain part & parcel of the report. Without these
			enclosures/ documents report shall stand null & void.

(Rupees Three Hundred Fifty Five Crore Only)

FILE NO.: RKA/FY18-19/738 Page 34 of 45





PART D

#### **SUMMARY OF THE VALUATION REPORT - ANNEXURE - III**

S.NO.	CONTENTS		DESCRIPTION	
1.	GENERAL DETAILS			
a.	Report prepared for	Bank		
	Name & Address of Organization	State Bank of India, Overseas Branch, New Delhi.		
	Name of the Borrower	M/s ISGEC Heavy		
d.	Name of Property Owner	M/s ISGEC Heavy	Engineering Ltd.	
e.	Address & Phone Number of the owner	Corporate Office :- Near HCL Technologies, A-4, Vindhyachal Marg, Block A, Sector 24, Noida, Uttar Pradesh 201301 Tel. No. :- 0120 408 5001		
	Type of the Property	Industrial Land & B	uilding	
g.	Type of Loan	Business Loan		
h.	Type of Valuation	Industrial Land & B	uilding value	
i.	Report Type	Plain Asset Valuation	on	
j.	Date of Inspection of the Property	20 December 2018		
k.	Date of Valuation Report	22 December 2018		
I.	Surveyed in presence of	Owner's representative	Mr. R.K Bhardwaj Mob. No. :- 893011	1572
m	Purpose of the Valuation	Periodic Re-valuati	on of the mortgaged	asset
n.	Scope of the Report	Non Binding Opinion on General Prospective Valuation Assessment of the Property identified by Property owner or through its representative		
0.	Out-of-Scope of Report	<ul> <li>i. Verification of authenticity of documents from originals or cross checking from any Govt. deptt. is not done at our end.</li> <li>ii. Legal aspects of the property are out-of-scope of this report.</li> <li>iii. Identification of the property is only limited to cross verification from its boundaries at site if mentioned in the provided documents.</li> <li>iv. Getting cizra map or coordination with revenue officers for site identification is not done at our end.</li> <li>v. Measurement is only limited upto sample random measurement.</li> <li>vi. Measurement of the property as a whole is not done at our end.</li> <li>vii. Drawing Map &amp; design of the property is out of scope of the work.</li> </ul>		
p.	Documents provided for perusal	Documents	Documents Provided	Documents Reference No.
		Requested		Reference No.
		Total <b>03</b> documents	Total <b>03</b> documents	01
		requested.	provided.	
		Property Title	Copy of TIR	By Advocate
		document		Avinash kumar

FILE NO.: RKA/FY18-19/738 Page 35 of 45






		Ар	proved Map	Site	Plan	
		Copy of TIR		Cizra	Мар	
		Change of Land		Memora	ndum &	
		Use		Artic		
				Assoc	ciation	
		Last paid		No	ne	
		Electricity Bill				
q.	Identification of the property			ked from boundaries of the property or		
				tioned in the deed		
		$\boxtimes$	Done from th	e name pla	ate display	ed on the property
		☐ Enquired from		by the Owner's representative		
				from local residents/ public		
				on of the property could not be done properly		not be done properly
			Survey was r	not done		

#### BRIEF DESCRIPTION OF THE PROPERTY UNDER VALUATION

a.

2.



Snapshot of the Asset/ Property Under Valuation

FILE NO.: RKA/FY18-19/738 Page 36 of 45





This valuation report is prepared for the Industrial property situated at the aforesaid address. The total land area of the property as per the copy of High Court Order of year 1962 enclosed in the booklet of Memorandum & Article of Association provided to us is 44.75 Acre (2,16,590 sq.yds.) & the same has been considered for the purpose of this valuation exercise.

We have been provided with various documents pertaining to the land area of the subject property. The land area of different documents varies from one another. The list of the same is given below:-

Land Area Description				
S.r No.	Supported Document	Area (in acre)	Area (in sq.yds.)	
1	As per MOA & AOA		2,16,590	
2	As per TIR		4,06,753.6	
3	As per Site Map		2,60,285.12	
4	As per Google Map		2,02,785 approx.	

However as per our understanding from the site visit inspection, discussion with the company officials & further by carrying out measurement via Google Map, the area of the subject land comes out to be almost same as mentioned in the Memorandum & Article of Association 'of ISGEC Heavy Engineering Limited i.e. 44.75 Acre (2,16,590 sq.yds.). This area is deducting the portion which is used by the Sugar Mill.

ISGEC Heavy Engineering Limited was earlier known as Saraswati Industrial Syndicate Limited

As per the copy of TIR provided to us by the client, ownership of the land belongs to M/s ISGEC Heavy Engineering Limited which was formerly known as M/s Saraswati Industrial Syndicate Limited. M/s Saraswati Industrial Syndicate Limited name has been changed to M/s ISGEC Heavy Engineering Limited dated: 26.08.2011. M/s Saraswati Industrial Syndicate Limited was originally incorporated on 23.01.1933 in the name of M/s Saraswati Sugar Syndicate Limited. The name of M/s Saraswati Sugar Syndicate Limited on 02.05.1963.

As per the High court order dated: 18.08.1961 and 17.08.1962 The Indian Sugar & General Engineering Corporation Ltd. has been taken over by M/s Saraswati Sugar Syndicate Limited (which is now known as M/s ISGEC Heavy Engineering Limited) along with all its assets as mentioned in Schedule Part-I, Part-II (copy of schedule is attached for reference). The land description mentioned in Part-I contains total 44.75 acres (2,16,590 sq.yds). This is the area which is presently also possessed by M/s ISGEC Heavy Engineering Limited. A group company called M/s Saraswati Sugar Mills Ltd. owned Sugar Mill is established opposite to the subject Plant.

Total Land area as shown in the Map provided to us contains 53.778 acres (260285.212 sq.yds) of land which is within the common boundary and is a continuous land as shown in the attached Map.

FILE NO.: RKA/FY18-19/738 Page 37 of 45





Within this bounded area, approximately 38,597 sq.mtr (7.97acres) of the area belongs to M/s Saraswati Sugar Mills Ltd. where its godown buildings, molasses tank and water treatment plant is situated which is not a part of M/s ISGEC Heavy Engineering Limited.

Therefore based on these facts it is assumed that the area given in the court order transferred from M/s The Indian Sugar & General Engineering Corporation Ltd. measuring about 44.75 acres (216590 sq.yds) is the actual area within M/s ISGEC Heavy Engineering Limited since it is matching physically also and same has been considered in the Valuation.

Most of the khasras mentioned in the schedule of the court order (which is part of 44.75 acres taken in the Valuation) is mentioned in the TIR Report also except khasras 313 & 314 which were not mentioned in the TIR Report. Bank can query or sought the additional documents/ information from the company/ panel Advocate to confirm the same. Cizra Map was also provided to us for the Villages Mamida, Habibpur & Gadi Gujaran in which the subject property is situated, however it couldn't match from the khasras mentioned in the schedule of the court order.

A heavy engineering Industrial Plant is set up on the site, in which several buildings & structures are built on GI Shed roofed along with RCC roofed structures. The height of RCC roofed structure varies from 10-15 feet whereas for steel structure height varies from 10-60 feet. We have not been provided with any details describing the age of the building. As per our verbal conversation with the company's official we came to know that the industry is in running condition since 1980, however during the time of our site visit inspection we observed that most of the structures are well maintained & seems to be in good condition. Construction of some new structure was also under progress.

The subject property is used for manufacturing of heavy engineering machinery parts run by M/s ISGEC Heavy Engineering Pvt. Ltd. which is a well renowned company in its segment.

Keeping in mind the large & complex size of the building structures it was not feasible for us to carry out the physical measurement of the same, total constructed area of the subject property is taken as

FILE NO.: RKA/FY18-19/738 Page 38 of 45





per the building sheet provided to us by the client through which the total built-up area of the subject property comes out to be 138146.31 sq.mtr. or 1487006.88 sq.ft. out of which we have considered 115890.46 sq.mtr. or 1247444.91 sq.ft. area which is purely used by ISZEC. Buildings & structures which belongs to M/s Saraswati Sugar Mills Limited has not been considered in this Valuation Report.

There are some of the buildings whose name on the site is different from what has been mentioned in the sheet provided to us by the company. Due to large number of buildings we couldn't correct this change and has to go by the sheet provided by the company since it was prepared in line to the Map matching the numbers.

We have relied upon the area mentioned in the building sheet in good faith and considered the same for the purpose of this valuation exercise. On sample measurement, area of the buildings checked were found to be same.

The subject property is located on main Sharanpur-Kurukshetra road having road width of approx. 30 meter. Basic civic amenities are easily available in the nearby vicinity of the subject property. This area is now within Yamuna Nagar municipal corporation limits and has come under within the main city. Now mostly residential & commercial development is carried out in and around this Industry.

3.	VALUATION SUMMARY	
a.	Total Govt. Guideline Value	NA
b.	Total Prospective Fair Market Value	Rs. 3,55,00,00,000/-
C.	Total Expected Realizable/ Fetch Value	Rs. 2,83,87,22,930/-
d.	Total Expected Distress/ Forced Sale Value	Rs. 2,48,38,82,564/-
e.	Valuation for the purpose of Insurance	Rs. 81,00,00,000/-

4.	ENCLOSURES	
a.	Annexure - IV	Assumptions   Remarks   Limiting Conditions – Page No.19
b.	Annexure - V	Valuer's Remarks - Page No. 21
C.	Annexure - VI	Google Map – Page No. 23
d.	Annexure - VII	Copy of Circle Rate - Page No.24

FILE NO.: RKA/FY18-19/738 Page 39 of 45





# ASSUMPTIONS | REMARKS | LIMITING CONDITIONS - ANNEXURE IV

_	
a.	Information of the average market rates is taken based on the verbal market survey in the subject area from the
	local people, property agents, recent deals, demand-supply, internet postings which has been relied upon. No
	written record is generally available for such market information and only the verbal information has to be relied
	upon.
b.	Forced, compulsion, constraint, obligatory sales transactions data doesn't forms part of the Fair Market Valuation
	exercise.
C.	Sale transaction method of the asset is assumed as free market transaction while assessing Prospective Fair
	Market Value of the asset.
d.	This Valuation report is prepared based on the facts of the property on the date of the survey. However in future
-	property Market may go down, property conditions may change or may go worse, Property reputation may differ,
	Property vicinity conditions may go down or become worse, Property market may change due to impact of Govt.
	policies or effect of World economy, Usability prospects of the property may change, etc. Hence before financing,
	Banker/ FI should take into consideration all such future risk and should loan conservatively to keep the advanced
	money safe in case of the downward trend of the property value.
e.	Valuation of the same asset/ property can fetch different values in different situations. For eg. Valuation of a
О.	running/ operational shop/ hotel/ factory will fetch better value and in case of closed shop/ hotel/ factory it will have
	considerable lower value. Similarly an asset sold directly by an owner in the market will fetch better value and if
	the same asset/ property is sold by any financer due to encumbrance on it will fetch lower value. Hence before
	financing, Banker/ FI should take into consideration all such future risks and should loan conservatively to keep
	the advanced money safe in case of any such situation.
f.	This report is prepared based on the copies of the documents/ information which interested organization or
'-	customer could provide to us out of the standard checklist of documents sought from them and further based on
	our assumptions and limiting conditions. All such information provided to us has been relied upon and we have
	assumed that it is true and correct. Verification or cross checking of the documents provided to us from the
	originals has not been done at our end. If at any time in future it's found or came to our knowledge that
	misrepresentation of facts or incomplete or distorted information has been provided to us then this report will
	automatically become null & void.
- 0	Getting cizra map or coordination with revenue officers for site identification is not done at our end.
g. h.	All area measurements are on approximate basis. Verification of the area measurement of the property is done
11.	only based on sample random checking and not based on full scale measurement. Area of the large land parcels
	of more than 2500 sq.mtr or of uneven shape, is taken as per property documents which has been relied upon.
-:	Legal aspects for eg. ownership rights, lien, charge, mortgage, etc. are not considered in this report. It is assumed
i.	
	and taken into account that the concerned Bank/ Financial Institution has first got the legal verification cleared by
	the competent Advocate before requesting for the Valuation report. In case Valuation is obtained before taking
	legal scrutiny or opinion then it is expected from the Bank to inform back the Valuer timely about such change of
	rights on the property as soon as it comes into the notice of the Bank/ Financer which may affect their charge on
	the mortgage asset so that accordingly Valuation modification can be done only for that portion for which the Bank
	has complete charge/ rights.
j.	Investigation of title of the property and its legal right is beyond the scope of this report. If this property is offered as collateral security, then concerned financial institution is requested to verify & satisfy themselves on the
	l ac collatoral cocurity, then concorned tinancial inctitution ic reduccted to Verity X, caticity themcelves on the
	ownership & legality of the property shown in this valuation report with respect to the latest legal opinion.
k.	ownership & legality of the property shown in this valuation report with respect to the latest legal opinion.  Valuation is done for the property identified to us by the owner/owner representative. Responsibility of identifying
k.	ownership & legality of the property shown in this valuation report with respect to the latest legal opinion.  Valuation is done for the property identified to us by the owner/ owner representative. Responsibility of identifying the correct property to the Valuer/ its authorized surveyor is solely of the client/ owner for which Valuation has to
k.	ownership & legality of the property shown in this valuation report with respect to the latest legal opinion.  Valuation is done for the property identified to us by the owner/ owner representative. Responsibility of identifying the correct property to the Valuer/ its authorized surveyor is solely of the client/ owner for which Valuation has to be carried out. At our end we can just cross verify the identification of the property with reference to the documents
k.	ownership & legality of the property shown in this valuation report with respect to the latest legal opinion.  Valuation is done for the property identified to us by the owner/ owner representative. Responsibility of identifying the correct property to the Valuer/ its authorized surveyor is solely of the client/ owner for which Valuation has to be carried out. At our end we can just cross verify the identification of the property with reference to the documents produced for perusal. Method by which identification of the property is carried out is also mentioned in the report
k.	ownership & legality of the property shown in this valuation report with respect to the latest legal opinion.  Valuation is done for the property identified to us by the owner/ owner representative. Responsibility of identifying the correct property to the Valuer/ its authorized surveyor is solely of the client/ owner for which Valuation has to be carried out. At our end we can just cross verify the identification of the property with reference to the documents produced for perusal. Method by which identification of the property is carried out is also mentioned in the report clearly. It is requested from the Bank to cross check from their own records/ information if this is the same property
k.	ownership & legality of the property shown in this valuation report with respect to the latest legal opinion.  Valuation is done for the property identified to us by the owner/ owner representative. Responsibility of identifying the correct property to the Valuer/ its authorized surveyor is solely of the client/ owner for which Valuation has to be carried out. At our end we can just cross verify the identification of the property with reference to the documents produced for perusal. Method by which identification of the property is carried out is also mentioned in the report clearly. It is requested from the Bank to cross check from their own records/ information if this is the same property for which Valuation has to be carried out to ensure that owner has not misled the Valuer company or
k.	ownership & legality of the property shown in this valuation report with respect to the latest legal opinion.  Valuation is done for the property identified to us by the owner/ owner representative. Responsibility of identifying the correct property to the Valuer/ its authorized surveyor is solely of the client/ owner for which Valuation has to be carried out. At our end we can just cross verify the identification of the property with reference to the documents produced for perusal. Method by which identification of the property is carried out is also mentioned in the report clearly. It is requested from the Bank to cross check from their own records/ information if this is the same property for which Valuation has to be carried out to ensure that owner has not misled the Valuer company or misrepresented the property due to any vested interest.
k.	ownership & legality of the property shown in this valuation report with respect to the latest legal opinion.  Valuation is done for the property identified to us by the owner/ owner representative. Responsibility of identifying the correct property to the Valuer/ its authorized surveyor is solely of the client/ owner for which Valuation has to be carried out. At our end we can just cross verify the identification of the property with reference to the documents produced for perusal. Method by which identification of the property is carried out is also mentioned in the report clearly. It is requested from the Bank to cross check from their own records/ information if this is the same property for which Valuation has to be carried out to ensure that owner has not misled the Valuer company or misrepresented the property due to any vested interest.  In India more than 70% of the geographical area is lying under rural/ remote/ non municipal/ unplanned area
	ownership & legality of the property shown in this valuation report with respect to the latest legal opinion.  Valuation is done for the property identified to us by the owner/ owner representative. Responsibility of identifying the correct property to the Valuer/ its authorized surveyor is solely of the client/ owner for which Valuation has to be carried out. At our end we can just cross verify the identification of the property with reference to the documents produced for perusal. Method by which identification of the property is carried out is also mentioned in the report clearly. It is requested from the Bank to cross check from their own records/ information if this is the same property for which Valuation has to be carried out to ensure that owner has not misled the Valuer company or misrepresented the property due to any vested interest.  In India more than 70% of the geographical area is lying under rural/ remote/ non municipal/ unplanned area where the subject property is surrounded by vacant lands having no physical demarcation or having any display of
	ownership & legality of the property shown in this valuation report with respect to the latest legal opinion.  Valuation is done for the property identified to us by the owner/ owner representative. Responsibility of identifying the correct property to the Valuer/ its authorized surveyor is solely of the client/ owner for which Valuation has to be carried out. At our end we can just cross verify the identification of the property with reference to the documents produced for perusal. Method by which identification of the property is carried out is also mentioned in the report clearly. It is requested from the Bank to cross check from their own records/ information if this is the same property for which Valuation has to be carried out to ensure that owner has not misled the Valuer company or misrepresented the property due to any vested interest.  In India more than 70% of the geographical area is lying under rural/ remote/ non municipal/ unplanned area where the subject property is surrounded by vacant lands having no physical demarcation or having any display of property survey or municipal number / name plate on the property clearly. Even in old locations of towns, small
	ownership & legality of the property shown in this valuation report with respect to the latest legal opinion.  Valuation is done for the property identified to us by the owner/ owner representative. Responsibility of identifying the correct property to the Valuer/ its authorized surveyor is solely of the client/ owner for which Valuation has to be carried out. At our end we can just cross verify the identification of the property with reference to the documents produced for perusal. Method by which identification of the property is carried out is also mentioned in the report clearly. It is requested from the Bank to cross check from their own records/ information if this is the same property for which Valuation has to be carried out to ensure that owner has not misled the Valuer company or misrepresented the property due to any vested interest.  In India more than 70% of the geographical area is lying under rural/ remote/ non municipal/ unplanned area where the subject property is surrounded by vacant lands having no physical demarcation or having any display of property survey or municipal number / name plate on the property clearly. Even in old locations of towns, small cities & districts where property number is either not assigned ornot displayed on the properties clearly and also
	ownership & legality of the property shown in this valuation report with respect to the latest legal opinion.  Valuation is done for the property identified to us by the owner/ owner representative. Responsibility of identifying the correct property to the Valuer/ its authorized surveyor is solely of the client/ owner for which Valuation has to be carried out. At our end we can just cross verify the identification of the property with reference to the documents produced for perusal. Method by which identification of the property is carried out is also mentioned in the report clearly. It is requested from the Bank to cross check from their own records/ information if this is the same property for which Valuation has to be carried out to ensure that owner has not misled the Valuer company or misrepresented the property due to any vested interest.  In India more than 70% of the geographical area is lying under rural/ remote/ non municipal/ unplanned area where the subject property is surrounded by vacant lands having no physical demarcation or having any display of property survey or municipal number / name plate on the property clearly. Even in old locations of towns, small

FILE NO.: RKA/FY18-19/738 Page 40 of 45





	identify the property with 100% surety from the available documents, information & site whereabouts and thus chances of error, misrepresentation by the borrower and margin of chances of error always persists in such cases. To avoid any such chances of error it is advised to the Bank to engage municipal/ revenue department officials to get the confirmation of the property to ensure that the property shown to Valuer/ Banker is the same as for which documents are provided.
m.	If this Valuation Report is prepared for the Flat/ dwelling unit situated in a Group Housing Society or Integrated Township then it is assumed that the Banker or the concerned organization has satisfied themselves with the approval of the Group Housing Society/ particular floor & building before allotting the Valuation case to the Valuer company.
n.	Due to fragmented & frequent change in building/ urban planning laws/ guidelines from time to time, different laws/ guidelines between regions/ states and no strict enforceability of Building Bye-Laws in India specially in non-metro and scale b & c cities & Industrial areas, property owners many times extend or make changes in the covered area/ layout from the approved/ applicable limits. There are also situations where properties are decades old when there was no formal Building Bye-Laws applicable when the construction must have been done. Due to such discrete/ unplanned development in many regions sometimes it becomes tough to determine the exact lawful situation on ground for the Valuer. In case nothing specific is noted on the covered built-up area considered in the Valuation Report, the covered area present on the site as per site survey will be considered in the Valuation.
0.	In case of Valuation of Plant & Machinery or equipment, condition of machines is evaluated by visual observation only. No technical/ mechanical testing of any kind has been carried out at our end to ascertain the condition and efficiency of the machines. Valuation of Plant & Machinery is done on the basis of physical existence of the assets rather than their technical expediency.
p.	Secondary/ Tertiary costs related to asset transaction like Stamp Duty, Registration charges, Brokerage, Bank interest, etc. pertaining to the sale/ purchase of this property are not considered while assessing the Market Value.
q.	Any kind of unpaid statutory, utilities, lease, interest or any other pecuniary dues on the asset has not been factored in the Valuation.
r.	Valuation is a subjective field and opinion may differ from consultant to consultant. To check the right opinion, it is important to evaluate the methodology adopted and various data point/ information/ factors/ assumption considered by the consultant which became the basis for the Valuation report before reaching to any conclusion.
S.	At the outset, it is to be noted that Value analysis of any asset cannot be regarded as an exact science and the conclusions arrived at in many cases will, of necessity, be subjective and dependent on the exercise of individual judgment. Given the same set of facts and using the same assumptions, expert opinions may differ due to the number of separate judgment decisions, which have to be made. Therefore, there can be no standard formulae to establish an indisputable exchange ratio. In the event of a transaction, the actual transaction value achieved may be higher or lower than our indicative analysis of value depending upon the circumstances of the transaction. The knowledge, negotiability and motivations of the buyers and sellers and the applicability of a discount or premium for control will also affect actual price achieved. Accordingly, our indicative analysis of value will not necessarily be the price at which any agreement proceeds. The final transaction price is something on which the parties themselves have to agree. However our Valuation analysis can definitely help the stakeholders to make them informed and wise decision about the Value of the asset and can help in facilitating the arm's length transaction.

#### **R.K ASSOCIATES IMPORTANT NOTES:**

- 1. <u>DEFECT LIABILITY PERIOD</u> In case of any query/ issue or escalation you may please contact Incident Manager by writing at valuers @rkassociates.org. We ensure 100% accuracy in the Calculations done, Rates adopted and various other data points & information mentioned in the report but still can't rule out typing, human errors or any other mistakes. In case you find any mistake, variation, discrepancy or inaccuracy in any data point of the report, please help us by bringing all such points into our notice in writing at <u>valuers @rkassociates.org</u> within 30 days of the report delivery, to get these rectified timely, failing which R.K Associates won't be held responsible for any inaccuracy in any manner. Also if we will not hear back anything from you within 30 days, we will assume that report is correct in all respect and no further claim of any sort will be entertained thereafter. We would welcome and appreciate your feedback & suggestions in order to improve our services.
- 2. <u>COPYRIGHT FORMAT</u> This report is prepared on the copyright format of R.K Associates to serve our clients in the best possible way. Legally no one can copy or distribute this format without prior approval from R.K Associates. It is meant only for the organization as mentioned on the cover page of this report. Distribution or use of this format other than R.K Associates will be seen as unlawful act and necessary legal action can be taken against the defaulters.

#### IF REPORT IS USED FOR BANK/ FIS

FILE NO.: RKA/FY18-19/738 Page 41 of 45

#### M/S ISGEC HEAVY ENGINEERING LTD., YAMUNA NAGAR



**NOTE:** As per IBA Guidelines in case the valuation report submitted by the valuer is not in order, the banks / Fls shall bring the same to the notice of the valuer within 15 days of submission for rectification and resubmission. In case no such communication is received, it shall be presumed that the valuation report has been accepted.

At our end we have not verified the authenticity of any documents provided to us. Bank is advised to verify the genuineness of the property documents before taking any credit decision.

#### **VALUER'S REMARKS – ANNEXURE V**

1.	Fair Market Value#suggested by the competent Valueris that prospective estimated amount of the subject asset/
	property in his expert & prudent opinionwithout any prejudiceafter he has carefully & exhaustively evaluated all the
	facts & information related the subject asset at which the subject asset/ property should be exchanged between a
	willing buyer and willing seller at an arm's length transaction after proper marketing, wherein the parties, each
	acted knowledgeably, prudently and without any compulsion on the date of the Valuation.
2.	Realizable Value <sup>^</sup> is the minimum prospective value of the property which it may be able to realize at the time of
	actual property transaction factoring in potential prospects of deep negotiations carried out between the buyer &
	seller for ultimately finalizing the transaction. Realizable value may be 10-20% less of the Fair Market Value
	depending on the various salability prospects of the subject property.
3.	Forced/ Distress Sale Value* is the value when the property has to be sold due to any compulsion or constraint
J.	like financial encumbrances, dispute, as a part of a recovery process, any defect in the property, having unclear
	title or any such sort of condition or situation. In this type of sale minimum disposable value is assessed which
	varies from 20-35% less from the Fair Market Value based on the nature, size &salability prospects of the
	property. In this type of sale negotiation power of the buyer is always more than the seller and eagerness of selling
	the property is more than buying it. Therefore the Forced/ Distress Sale Value always fetches less value.
4.	Best rates are rationally adopted based on the facts of the case came to our knowledge during the course of the
	assignment considering many factors like nature of the property, size, location, approach, market situation and
	trends.
5.	Construction rates are adopted based on present replacement cost of construction and calculating applicable
	depreciation & deterioration factor as per its existing condition, specifications based on the visual observation of
	the structure. No structural, physical tests have been carried out in respect of it.
6.	This Valuation report is prepared based on the facts of the property on the date of the survey. However in future
	property Market may go down, property conditions may change or may go worse, Property reputation may differ,
	Property vicinity conditions may go down or become worse, Property market may change due to impact of Govt.
	policies or effect of World economy, Usability prospects of the property may change, etc. Hence before financing,
	Banker/ FI should take into consideration all such future risk and should loan conservatively to keep the advanced
	money safe in case of the downward trend of the property value.
7.	Valuation of the same asset/ property can fetch different values in different situations. For eg. Valuation of a
	running/ operational shop/ hotel/ factory will fetch better value and in case of closed shop/ hotel/ factory it will have
	considerable lower value. Similarly an asset sold directly by an owner in the market will fetch better value and if
	the same asset/ property is sold by any financer due to encumbrance on it will fetch lower value. Hence before
	financing, Banker/ FI should take into consideration all such future risk and should loan conservatively to keep the
	advanced money safe in case of any such situation.
8.	No employee or member of R.K Associates has any direct/ indirect interest in the property.
9.	Sale transaction method of the asset is assumed as free market transaction while assessing Fair Prospective
	Market Value of the asset.
10.	Area measurements considered in the Valuation Report pertaining to Land & Building is adopted from relevant
	approved documents or actual site measurement whichever is less. All area measurements are on approximate
	basis only.
11.	This report is having limited scope as per its fields to provide only the general basic idea of the value of the
• • • •	property prevailing in the market based on the documents/ data/ information provided by the client. The suggested
	value should be considered only if transaction is happened as free market transaction.
12.	The condition assessment and the estimation of residual economic life of the structure is based on the visual
14.	observations and appearance found during the site survey. We have not carried out any structural design or
42	stability study; nor carried out any physical tests to assess structural integrity & strength.
13.	This report is prepared based on the copies of the documents/ information which interested organization or
	customer could provide to us out of the standard checklist of documents sought from them and further based on
	our assumptions and limiting conditions. All such information provided to us has been relied upon and we have
	assumed that it is true and correct. Verification or cross checking of the documents provided to us from the
	originalshas not been done at our end. If at any time in future it's found or came to our knowledge that

FILE NO.: RKA/FY18-19/738 Page 42 of 45




# M/S ISGEC HEAVY ENGINEERING LTD., YAMUNA NAGAR

	misrepresentation of facts or incomplete or distorted information has been provided to us then this report will automatically become null & void.
14.	Investigation of title of the property and its legal right is beyond the scope of this report. If this property is offered as collateral security, then concerned financial institution is requested to verify & satisfy themselves on the ownership & legality of the property shown in this valuation report with respect to the latest legal opinion.
15.	Value varies with the Purpose/ Date/ Condition of the market. This report should not to be referred if any of these points are different from the one mentioned aforesaid in the Report. The Value indicated in the Valuation Report holds good only upto the period of 3 months from the date of Valuation.
16.	Analysis and conclusions adopted in the report are limited to the reported assumptions, conditions and information came to our knowledge during the course of the work.
17.	This report is prepared on the RKA V-L3 (Medium) Valuation format as per the client requirement, charges paid and the time allotted. This report is having limited scope as per its fields to provide only the general estimated basic idea of the value of the property prevailing in the market based on the information provided by the client. The Valuation assessed in this Valuation Report should hold good only if transaction is happened as per free market transaction. No detailed analysis or verification of the information is carried upon pertaining to the value of the subject property. No claim for any extra information will be entertained whatsoever be the reason. For any extra work over and above the fields mentioned in the report will have an extra cost which has to be borne by the customer.
18.	This is just an opinion report and doesn't hold any binding on anyone. It is requested from the concerned Client/Bank/ Financial Institution which is using this report for mortgaging the property that they should consider all the different associated relevant & related factors also before taking any business decision based on the content of this report.
19.	All Pages of the report including annexures are signed and stamped from our office. In case any paper in the report is without stamp & signature then this should not be considered a valid paper issued from this office.
20.	Defect Liability Period is <u>30 DAYS</u> . We request the concerned authorized reader of this report to check the contents, data and calculations in the report within this period and intimate us in writing if any corrections are required or in case of any other concern with the contents or opinion mentioned in the report. Corrections only related to typographical, calculation, spelling mistakes will be entertained within the defect liability period. No request for any illegitimate value revision, date change or any other change will be entertained other than the one mentioned above.
21.	R.K Associates encourages its customers to give feedback or inform concerns over its services through proper channel at <b>valuers@rkassociates.org</b> in writing within 30 days of report delivery. After this period no concern/complaint/proceedings in connection with the Valuation Services can be entertained due to possible change in situation and condition of the property.
22.	Our Data retention policy is of <u>ONE YEAR</u> . After this period we remove all the concerned records related to the assignment from our repository. No clarification or query can be answered after this period due to unavailability of the data.
23.	This Valuation report is governed by our (1) Internal Policies, Processes & Standard Operating Procedures, (2) R.K Associates Quality Policy, (3) Valuation & Survey Best Practices Guidelines formulated by management of R.K Associates, (4) Information input given to us by the customer and (4) Information/ Data/ Facts given to us by our field/ office technical team. Management of R.K Associates never gives acceptance to any unethical or unprofessional practice which may affect fair, correct & impartial assessment and which is against any prevailing law. In case of any indication of any negligence, default, incorrect, misleading, misrepresentation or distortion of facts in the report then it is the responsibility of the user of this report to immediately or atleast within the defect liability period bring all such act into notice of R.K Associates management so that corrective measures can be taken instantly.
24.	R.K Associates never releases any report doing alterations or modifications from pen. In case any information/ figure of this report is found altered with pen then this report will automatically become null & void.
25.	If this report is prepared for the matter under litigation in any Indian court, no official or employee of R.K Associates will be under any obligation to give in person appearance in the court as a testimony. For any explanation or clarification, only written reply can be submitted on payment of charges by the plaintiff or respondent which will be 10% of the original fees charged where minimum charges will be Rs.2500/

FILE NO.: RKA/FY18-19/738 Page 43 of 45



#### **GOOGLE MAP LOCATION - ANNEXURE VI**





FILE NO.: RKA/FY18-19/738 Page 44 of 45



# **Layout Plan - ANNEXURE VII**

