



OM TECHNO SERVICES

538, Jadhav Sankul, Ashok Nagar, Satpur, Nashik - 422 012. Mob.07350456480,9325413165
E-mail : pawargorakh523@gmail.com / omtech538@gmail.com

Ref. No. :Ots/st/spl/221

Date: 23.6.2019 201

FORM NO. 1 A

(Rule 3A)

CERTIFICATE OF STABILITY

- 1) Name of Factory : M/s Shalimar Paint Ltd
- 2) Village, Town & District In which the
Factory is Situated : Gat No. 121(B),126,127,132,133(B), 134(B),141
At. Gonde Dhumla, Tal-Igatpuri, Dist- Nasik
Nashik -Mumbai Road
- 3) Full Postal Address of Factory : Village -AS ABOVE
- 4) Name of Occupier Of The Factory : Shri. Surender Kumar Bhatia
- 5) Nature of manufacturing processes : Mfg. of Paints, Varnish, Resin, Thinner & Packaging
- 6) Number of floors on which the
Workers will be employed : Ground +1st+Mazenine Structures as per plan

I certify that I have inspected the premises the plans of which have been approved by Joint Chief Inspector Nashik by wide letter No.121600000017380 dated 18.01.2019 & Continuation with the previous plans approval Nos. 121600000011665 dated 23.2.2017 , PLN/165-2015/MSP/SGK/7467-68/15 Dated 10.11.2015, PLN/132/RMJ/SGK/5908-14/12 Dated 30.8.2012 , PLN/13-91/GRG/RTC/812-41 dated 3.1.1992 & examined the various parts including the foundations with special reference to the machinery , plant etc that have been installed. I am/ we are of the opinion that all the works of engineering construction in the premises are structurally sound & that their found stable and not be endangered by their present use as a factory /part of the factory for the Manufacture of Paints, Varnish, Resin, Thinner & Packaging. Which the machinery, plant etc. installed are intended

Signature

For OM TECHNO SERVICES

Name
Qualification
Date : 23.6.2019



Abhijit Dighole
B.E. (Civil), M.I.E., M.B.A.
Regn. No. M-128342-6

NOTE:- The validity of stability certificate is Five Year from the date of issue. But after Extension, Alteration, Repairs or Addition /Deletion of any work of Engineering construction, in structures/ Building & Replacement or Addition of Machinery in the Plant. It Needs to be Renewed As per MFR 3A