

VIS (2024-25) - PL 246-210-271


rk ASSOCIATES
 REINFORCING YOUR BUSINESS

File No.	RKA/DNCR/...../.....
Date of Receiving	July 20, 2024.

M/s Shri Dakshineshwar
 Maa Polyfabs Ltd.
 Village -
 Ambriya, West Bengal.

CASE COLLECTION FORMAT (INDUSTRIAL PLANT SURVEY FORM)

(Version 2.1) | Date of implementation: 9.02.2011 | Date of Revision: 04.01.2018, 30.01.2020

Items	Assigned To	Assigned to Date	To be completed by date	Submitted On date	Grade	HOD Engg. Signature
File Received By	Rajat	NA	NA			NA
Survey	Rajat/ Kishanu					
Preparation						

A - Very Good, B - Satisfactory, C - Average, D - Poor, E - Extremely Poor

File Returned to HOD Engg. unprepared due to reason	<input type="checkbox"/> Proper documents not received, <input type="checkbox"/> Survey not done properly, <input type="checkbox"/> Survey Form not properly filled, <input type="checkbox"/> Market survey for rates is not properly done, <input type="checkbox"/> Identification is not clearly done, <input type="checkbox"/> Measurement is not properly done, <input type="checkbox"/> Photographs not clearly taken, <input type="checkbox"/> Selfie/ Owner or owner representative photo not taken, <input type="checkbox"/> Owner/ owner representative signature not taken, <input type="checkbox"/> Google Map not taken, <input type="checkbox"/> Survey summary sheet not filled
---	---

In case File is returned by the preparer - HOD Engg. comment & Signature	<input type="checkbox"/> Minor defects in the survey hence approved for preparation with warning to Surveyor. Report preparer to collect the missing information on his own. <input type="checkbox"/> Major defects in the survey. Survey has to be done again.
--	--

GENERAL DETAILS

1.	Proposal or Ref. No.				
2.	Type of Service	<input checked="" type="checkbox"/> Valuation Report			
3.	Type of customer	<input checked="" type="checkbox"/> Bank	<input type="checkbox"/> PSU	<input type="checkbox"/> NBFC	<input type="checkbox"/> Corporate
		<input type="checkbox"/> Company	<input type="checkbox"/> Private client	<input type="checkbox"/> Direct client through Bank	
4.	Bank/ FI/ Organization Name & Address	SBI IFB, Kolkata			
5.	Case Allotment Officer/ Fees paying party Details	Name	Contact Number	Email Id	
		Mukut Roy.	9073159082	amt1.ifbkol@sbicoin	
6.	Case Type	<input type="checkbox"/> Case for Fresh Account		<input checked="" type="checkbox"/> Case for existing account/ customer	
7.	Fees Details	Amount of Fees	Advance Amount if any	Payment will be paid by	
		40000+GST + OPE (this is just a approximate fee)		<input checked="" type="checkbox"/> Bank	<input type="checkbox"/> Customer
8.	Billing Details	Billed To Party Name	GSTIN		
		Shri Dakshineshwar Maa Polyfabs Ltd.	19AAXCS7468J1Z5		

** Bank will pay as per SBI valuation fee structure.

CASE DETAILS

1.	Name of the Industry/ Account	M/s Shri Dakshnieshwari Maa Polyfabs Ltd.		
2.	Type of Property	<input type="checkbox"/> Small Manufacturing Unit, <input checked="" type="checkbox"/> Medium Scale Industrial Unit, <input type="checkbox"/> Large Scale Industrial Plant, <input type="checkbox"/> Very Large Scale Industrial Plant		
3.	Owner/ Applicant Details	Name	Contact Number	Email Id
		Same as A/c name	—	—
4.	Account Name	”		
5.	Plant Address	Village - Amriya, P.O. - Ati, P.S. - Dadpur, Babganu Gram Panchayat, PIN - 712305.		
6.	Who will coordinate on site for the site survey	Name	Contact Number	
	sk. Minazul Haque		8583808559.	
7.	Preferred time of survey	Date	Time	
		09/08/2024		—
8.	Documents Received (Any one ownership document and approved site plan/ map is must)	<p>1. Ownership Documents: <input type="checkbox"/> Sale Deed, <input type="checkbox"/> Power of Attorney, <input type="checkbox"/> Will Relinquishment Deed, <input type="checkbox"/> Transfer Deed, <input type="checkbox"/> Conveyance Deed, <input type="checkbox"/> Allotment Letter, <input type="checkbox"/> Possession Letter, <input type="checkbox"/> Agreement to Sell, <input checked="" type="checkbox"/> Mortgage Deed, <input checked="" type="checkbox"/> Indenture of Mortgage</p> <p>2. Map: <input type="checkbox"/> Cizra Map, <input checked="" type="checkbox"/> Sanctioned Map, <input type="checkbox"/> Site Plan for Unit-1.</p> <p>3. Project Approval Documents: <input type="checkbox"/> Factory Registration, <input type="checkbox"/> Memorandum of Understanding with the State Govt., <input type="checkbox"/> Industrial Entrepreneurs Memorandum, <input checked="" type="checkbox"/> Environment Clearance, <input checked="" type="checkbox"/> Fire NOC</p> <p>4. Any Other document: <input type="checkbox"/> TIR Report, <input type="checkbox"/> Old Valuation Report, <input type="checkbox"/> Plant & Machinery Inventory Sheet, <input type="checkbox"/> Fixed Asset Register, <input type="checkbox"/> Building Area Statement, <input checked="" type="checkbox"/> CLU Document, <input type="checkbox"/> Detailed Project Report, <input type="checkbox"/> Invoices of the Major Equipment's, <input type="checkbox"/> Daily Performance Report, <input type="checkbox"/> TEV Report, <input type="checkbox"/> LIE Report, <input type="checkbox"/> Production data of last one week, <input type="checkbox"/> Plant maintenance log, <input checked="" type="checkbox"/> Copy of last paid Electricity Bill, <input checked="" type="checkbox"/> Copy of municipal tax receipt</p> <p><input type="checkbox"/> Any other:</p> <p>5. No documents provided: <input type="checkbox"/></p>		
9.	Special Instructions if any:			
10.	<p>I agree to pay the amount mentioned above for the preparation of Valuation Report. I agree that I'll not put pressure on Valuer firm to distort any facts and would not try to influence any member or official of the firm in the ill spirit or vested interest and to benefit any individual or organization by any means illegitimately.</p> <p>sk. Minazul Haque Customer Signature. 09/08/24</p>			

IMPORTANT INSTRUCTIONS

*FILE PREPARER TO START PREPARING THE FILES ONLY AFTER ENSURING THE STATUS OF ALL THE BELOW POINTS IS COMPLETED. FOR ANY EXCEPTION PLEASE BRING IT INTO NOTICE OF SENIOR GENERAL MANAGER (OPERATIONS), OTHERWISE PENAL ACTION WILL BE TAKEN AGAINST THE FILE PREPARER.

1.	Please do not accept the case if you do not have proper documents.
2.	Understand the nature of Industry before moving for survey
3.	Study the Plant Inventory sheet or FAR properly before moving for survey
4.	Firstly please take & study the current applicable ownership documents of the property which needs to get surveyed.
5.	Mark the Owner/ Area/ Boundaries mentioned in the ownership documents with bold florescent marker pen before moving for the survey. During site survey if any difference is found in the above fields from the ownership documents then please contact the owner immediately to know the reason for the difference.
6.	Identify the Property clearly by matching the boundaries and area mentioned in the property papers.
7.	Check whether Building Measurement Area is given in the Map or if they have any Building Area sheet or if self-measurement has to be carried out before moving for survey.
8.	Take Google Map location.
9.	Take one photograph of the property along with abutting road.
10.	Take nearby photographs of the Property.
11.	Check Jurisdiction Municipal Limits & Ward Name.
12.	Fill the details in the Survey form and tick the appropriate option clearly.
13.	In case customer is found providing misleading information to you or trying to influence you by money or cash then immediately report to the Management & Bank.

S.No.	CHECKLIST	STATUS
1.	IS PURPOSE OF THE ASSIGNMENT UNDERSTOOD CLEARLY	<input checked="" type="checkbox"/>
2.	IS WORK ORDER/ EMAIL/ CESA FORM FORMALITY COMPLETED	<input checked="" type="checkbox"/>
3.	FOR PRIVATE CASE OR FOR FRESH CASE 50% ADVANCE IS RECEIVED	<input type="checkbox"/> <i>Existing Case</i>
4.	IS DOCUMENT CHECKLIST PROVIDED TO THE CUSTOMER	<input checked="" type="checkbox"/>

S.NO.	CHECKLIST	STATUS
1.	Check nearby prominent landmark	<input checked="" type="checkbox"/>
2.	DO CLEAR IDENTIFICATION OF THE PROPERTY	<input checked="" type="checkbox"/>
3.	Match the boundaries of the property and its directions with the help of compass or sun direction	<input checked="" type="checkbox"/>
4.	Do sample measurement	<input checked="" type="checkbox"/>
5.	CHECK IF ANY BUILDING VIOLATIONS DONE	<input checked="" type="checkbox"/>
6.	Click multiple proper photographs of the property from inside-out	<input checked="" type="checkbox"/>
7.	Take selfie with the available representative	<input checked="" type="checkbox"/>

8.	Send Google Map location at maps@rkassociates.org	<input checked="" type="checkbox"/>
9.	Check municipal jurisdiction	<input checked="" type="checkbox"/>
10.	Check Main road name & width and its distance from the subject property	<input checked="" type="checkbox"/>
11.	Check Lane width on which property is located	<input checked="" type="checkbox"/>
12.	Check any defects or negativity in the property	Cannot <input type="checkbox"/> Comment
13.	CONFIRM PROPERTY RATES LOCALLY	<input checked="" type="checkbox"/>
14.	CHECK NEARBY DEVELOPMENT	<input checked="" type="checkbox"/>

SPECIAL INSTRUCTIONS:

1. During Survey please follow the blocks mentioned in the plant layout and clearly mention the details of each block. Use separate sheet wherever space is not adequate in the form.
2. During survey please keep P&M inventory sheet in hand and cross check the machines from the list.
3. Mention type, height & area of shed of each block clearly.
4. Take photographs of the machines including its machine plate.
5. In case machine is not in running condition then test the condition of the machine by moving its lever, pulley and check oil condition.

SURVEY GRADING MATRIX	
GRADE	PARAMETERS/ CRITERIA
A	In case all the points below are done properly, timely with full care and diligence: <ol style="list-style-type: none"> 1. Survey started with proper work order and knowing the source of payment. 2. Survey done with proper documents. 3. Done complete homework and studied the documents properly with highlighting the main points before moving for the survey. 4. Chosen correct survey form as per the property type. 5. All fields of Survey form are properly filled. 6. All site special observations and negative and positive factors are clearly mentioned. 7. Self & client signatures taken on survey form. 8. Property rates information properly taken, mentioned and verified. 9. Site rough sketch plan made. 10. Proper photographs taken. 11. Selfie with property taken. 12. Selfie and owner photograph with property taken.
B	In case of 3 minor mistakes in any of the above points except Point 1, 2, 3, 4, 6, 8, 10, 11, 12 but all the points are covered.
C	In case of more than 3 minor mistakes and any 1 major mistake in any of the above points and if any points are completely missing except Point 1, 2, 3, 4, 6, 8, 10, 11, 12.
D	In case of 1 major mistake or missing of any 1 point out of 1, 2, 3, 4, 6, 8, 10, 11, 12.
E	In case of more than 1 major mistakes or missing of more than 1 point out of 1, 2, 3, 4, 6, 8, 10, 11, 12.

Note (Survey Grading Matrix):

1. For special assignments like LIE, Stock Valuation, etc. where till date survey format is not specified or released, in such cases point wise site observation report has to be submitted by the Surveyor duly signing it properly. Without signed Site Observation report, Point 4 will be considered as not done and will fall under Category E.
2. Similar Grading Matrix is issued for Case Collection & Report Preparation as well.

Note (Overall Grading Matrix):

1. In case client reports any careless mistake in the report for which revision has to be done in the report then in that case Grading Matrix may be revised and Grade E will be awarded.

INDUSTRIAL PLANT SURVEY FORM

(FOR INDUSTRIAL PROPERTIES ONLY)

(Version 2.0) | Date of implementation: 9.02.2011 | Date of Revision: 04.01.2018, 15.06.2019

VIS (2024-25) - PL 246 - 210 - 271

File No. RKA/DNCRT...../.....

Date: 09.08.2024

Time: —

GENERAL DETAILS

1.	Name of the Surveyor	Rajat / Kishanu	
2.	Property shown by	<input type="checkbox"/> Owner/ Director, <input checked="" type="checkbox"/> Company Representative, <input type="checkbox"/> No one was available, <input type="checkbox"/> Property is locked, survey could not be done from inside	
		Name	Contact No.
		Sk. Minarul Haque.	8583808559
3.	Survey Type	<input type="checkbox"/> Full survey (inside-out with approximate measurements & photographs), <input checked="" type="checkbox"/> Full survey (inside-out with approximate sample random measurements & photographs), <input type="checkbox"/> Half Survey (Approximate sample random measurements from outside & photographs), <input type="checkbox"/> Only photographs taken (No measurements)	
4.	Reason for Half survey or only photographs taken NA	<input type="checkbox"/> Property was locked, <input type="checkbox"/> Possessee didn't allow to inspect the property, <input type="checkbox"/> NPA property so owner was hostile and survey couldn't be carried out, <input type="checkbox"/> Under construction property, <input type="checkbox"/> Very Large irregular Property, practically not possible to measure the entire area, <input type="checkbox"/> Any other reason:	
5.	How Property is Identified	<input type="checkbox"/> From schedule of the properties mentioned in the deed, <input type="checkbox"/> From name plate displayed on the property, <input checked="" type="checkbox"/> Identified by the owner/ owner representative, <input type="checkbox"/> Enquired from nearby people, <input type="checkbox"/> Identification of the property could not be done, <input type="checkbox"/> Survey was not done	
6.	Type of Industry	<input type="checkbox"/> Small Manufacturing Unit, <input checked="" type="checkbox"/> Medium Scale Industrial Unit, <input type="checkbox"/> Large Scale Industrial Plant, <input type="checkbox"/> Very Large Scale Industrial Plant	
7.	Property Measurement	<input type="checkbox"/> Self-measured, <input checked="" type="checkbox"/> Sample measurement only, <input type="checkbox"/> No measurement	
8.	Reason for no measurement NA	<input type="checkbox"/> Property was locked/ sealed, <input type="checkbox"/> Owner/ possessee didn't allow it, <input type="checkbox"/> NPA property so didn't enter the property, <input type="checkbox"/> Very Large Property, practically not possible to measure the entire area <input type="checkbox"/> Any other Reason:	
9.	Purpose of Valuation	<input type="checkbox"/> Value assessment of the asset for creating collateral mortgage <input checked="" type="checkbox"/> Periodic Re-Valuation for Bank, <input type="checkbox"/> Distress sale for NPA A/c.,	

	<input type="checkbox"/> For DRT Recovery purpose, <input type="checkbox"/> For Insolvency purpose, <input type="checkbox"/> Capital Gains Wealth Tax purpose, <input type="checkbox"/> Partition purpose, <input type="checkbox"/> General Value Assessment, <input type="checkbox"/> For company merger & amalgamation purpose, <input type="checkbox"/> For any other purpose:
10. Type of Loan	<input type="checkbox"/> Project Loan, <input type="checkbox"/> Term Loan, <input type="checkbox"/> CC Limit enhancement, <input type="checkbox"/> Cash Credit Limit, <input type="checkbox"/> Industrial Loan, <input type="checkbox"/> Business Loan, <input type="checkbox"/> NA
11. Loan Amount	_____

OWNERSHIP DETAILS

1. Name of the Industry	Same as Pg-2.
2. Legal Owner Name/s	11
3. Property Purchaser Name	11
4. Plant Address under Valuation	11
5. Present Residence Address of the Owner/ Director	11
6. Property constitution	<input checked="" type="checkbox"/> Free Hold, <input type="checkbox"/> Lease Hold

LOCATION DETAILS

	East	West	North	South
1. Adjoining Properties (Match it with papers with the help of compass or Sun direction and also confirm it with nearby people)	Vacant Agricultural Land.	Curvent / NH-2 Service Road.	Vacant Agricultural Land.	Vacant Agricultural Land.
2. Property Facing	<input type="checkbox"/> East Facing, <input type="checkbox"/> North Facing, <input checked="" type="checkbox"/> West Facing, <input type="checkbox"/> South Facing, <input type="checkbox"/> North-East Facing, <input type="checkbox"/> South-West Facing, <input type="checkbox"/> South-East Facing, <input type="checkbox"/> North-West Facing			
3. Landmark	Itself is a Landmark. (Cor Mallick Model School)			
4. Ward Name/ No.	Under Gram Panchayat			
5. Zone Name	Amrta.			
6. Main Road Name & Width	Name	Width	Distance from property	
	NH-2.	50ft (Approx).	Adjacent	
7. Approach Road Name & Width	_____			
8. Are proper road facilities available?	<input checked="" type="checkbox"/> Yes, <input type="checkbox"/> No			
9. Type of Approach Road	<input type="checkbox"/> Bituminous, <input checked="" type="checkbox"/> Metalled, <input type="checkbox"/> Cement concrete, <input type="checkbox"/> Concrete paver block, <input type="checkbox"/> Brick khadanja, <input type="checkbox"/> Mud surfacing, <input type="checkbox"/> Broken potholed metalled road, <input type="checkbox"/> No proper approach road available, <input type="checkbox"/> Very narrow approach road towards the property			

Location characteristics	<input type="checkbox"/> Within well-developed notified Industrial area, <input type="checkbox"/> Within averagely maintained Industrial area, <input type="checkbox"/> Within un-notified Industrial area, <input type="checkbox"/> Within Main city, <input type="checkbox"/> Within city suburbs, <input type="checkbox"/> Within urban developed Area, <input type="checkbox"/> Within urban developing zone, <input type="checkbox"/> Within urban undeveloped area, <input type="checkbox"/> Within urban remote area, <input type="checkbox"/> Within commercial area, <input type="checkbox"/> Within Institutional area, <input type="checkbox"/> Out of municipal limits, no civic infrastructure available, <input checked="" type="checkbox"/> Within rural village area, <input type="checkbox"/> In interiors, <input type="checkbox"/> Within Backward area, <input type="checkbox"/> Within Remote area												
1. Classification of the Locality	<input type="checkbox"/> Urban developed, <input type="checkbox"/> Urban developing, <input type="checkbox"/> Semi Urban, <input checked="" type="checkbox"/> Rural, <input type="checkbox"/> Backward, <input type="checkbox"/> Industrial, <input type="checkbox"/> Institutional												
2. Location consideration	<input type="checkbox"/> Corner Plot, <input type="checkbox"/> 2 side open, <input type="checkbox"/> 3 side open, <input type="checkbox"/> On >30' wide road, <input type="checkbox"/> Near to Metro station, <input type="checkbox"/> Near to Market, <input checked="" type="checkbox"/> Near to Highway, <input type="checkbox"/> Entrance North-East Facing, <input type="checkbox"/> Ordinary location within locality, <input type="checkbox"/> Good Location within the locality, <input type="checkbox"/> Normal Location within the locality, <input type="checkbox"/> Average Location within locality, <input type="checkbox"/> Poor location within the locality, <input type="checkbox"/> Property towards end of the locality, <input type="checkbox"/> Any other												
13. Is Plant part of notified Industrial Area? If yes then name of Industrial area/ estate & governing authority managing it.	<input type="checkbox"/> Yes, <input checked="" type="checkbox"/> No <div style="border: 1px solid black; height: 20px; width: 100%;"></div>												
14. Proximity to civic amenities <i>As per Representative.</i>	<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 15%;">School</th> <th style="width: 15%;">Hospital</th> <th style="width: 15%;">Market</th> <th style="width: 15%;">Metro</th> <th style="width: 20%;">Railway Station</th> <th style="width: 20%;">Airport</th> </tr> </thead> <tbody> <tr> <td>2-3km</td> <td>11Km.</td> <td><1KM</td> <td>—</td> <td>3-4KM (Chandrapur)</td> <td>4.6 km.</td> </tr> </tbody> </table>	School	Hospital	Market	Metro	Railway Station	Airport	2-3km	11Km.	<1KM	—	3-4KM (Chandrapur)	4.6 km.
School	Hospital	Market	Metro	Railway Station	Airport								
2-3km	11Km.	<1KM	—	3-4KM (Chandrapur)	4.6 km.								
15. Any new development in surrounding area	<i>Widening of NH-2.</i>												
16. Jurisdiction limits	<input type="checkbox"/> Nagar Nigam, <input type="checkbox"/> Nagar Panchayat, <input checked="" type="checkbox"/> Gram Panchayat, <input type="checkbox"/> Nagar Palika Parishad, <input type="checkbox"/> Area not within any municipal limits												
17. Jurisdiction Development Authority Name	Name: <i>Babnan Gram Panchayat.</i> <input type="checkbox"/> Area not within any development authority limits												
18. Municipality/ Municipal Corporation Name	Name: <i>Babnan Gram Panchayat.</i>												

		<input type="checkbox"/> Area not within any municipal limits
19.	Surrounding land uses and adjoining/ nearby establishment details	Agricultural / Industrial.
20.	Is the location proper for the subject industry?	Yes.
21.	Is it a standalone Industry in this area? is it a belt for the subject nature of Industry?	Yes.
22.	In case Industry gets closed then does the land can be used for any other purpose?	—

PHYSICAL DETAILS			
1.	Land Area	As per Title deed 6.865 Acres.	As per Map —
		As per site survey 9.28 Acre (As per Google Earth).	
		Area as per mortgage deed: 6.865 Acre (As per docx provided to us.)	
2.	Any conversion to the land use	Yes Yes	No (please refer to the docx)
3.	Land Type	<input checked="" type="checkbox"/> Solid, <input type="checkbox"/> Rocky, <input type="checkbox"/> Marsh Land, <input type="checkbox"/> Reclaimed Land, <input type="checkbox"/> Water logged	
4.	Shape of the Land	<input type="checkbox"/> Square, <input type="checkbox"/> Rectangular, <input type="checkbox"/> Trapezium, <input type="checkbox"/> Triangular, <input type="checkbox"/> Trapezoid, <input checked="" type="checkbox"/> Irregular, <input type="checkbox"/> NA	
5.	Level of Land	<input type="checkbox"/> On road level, <input checked="" type="checkbox"/> Below road level, <input type="checkbox"/> Above road level, <input type="checkbox"/> NA	
6.	Frontage to depth ratio	<input checked="" type="checkbox"/> Normal frontage, <input type="checkbox"/> Less frontage, <input type="checkbox"/> Large frontage, <input type="checkbox"/> NA	
7.	Are Boundaries matched	<input checked="" type="checkbox"/> Yes, <input type="checkbox"/> No, <input type="checkbox"/> No relevant papers available to match the boundaries, <input type="checkbox"/> Boundaries not mentioned in available documents, <input type="checkbox"/> Very large land parcel forming multiple lands so not possible to match it with papers	
8.	Is Independent access available to the property	<input checked="" type="checkbox"/> Clear independent access is available, <input type="checkbox"/> Access is available in sharing of other adjoining property, <input type="checkbox"/> No clear access is available, <input type="checkbox"/> Access is closed due to dispute, <input type="checkbox"/> Land locked	
9.	Is property clearly demarcated with permanent boundaries?	<input checked="" type="checkbox"/> Yes, <input type="checkbox"/> No, <input type="checkbox"/> Only partially, <input type="checkbox"/> Only with Temporary boundaries,	
10.	Is the property merged or colluded with any other property	Cannot Comment	
11.	Is complete property mortgaged with the Bank under valuation or only portion of it?	No, only 6.865 Acres is mortgage to bank as per document provided to us.	
12.	Property possessed by at the time of survey	<input checked="" type="checkbox"/> Owner, <input type="checkbox"/> Vacant, <input type="checkbox"/> Lessee, <input type="checkbox"/> Under Construction, <input type="checkbox"/> Couldn't be Surveyed, <input type="checkbox"/> Property was locked, <input type="checkbox"/> Bank sealed, <input type="checkbox"/> Court sealed	
13.	Current activity carried out in the property	<input checked="" type="checkbox"/> Industrial, <input type="checkbox"/> Vacant, <input type="checkbox"/> Locked, <input type="checkbox"/> Sealed <input type="checkbox"/> Any other use:	

1
Please Note -

As per Mortgaged Deed land area is 6.865 Acre. However during the site survey we get around 9.28 Acre on Google Earth (Demarketed with the help of company representative).

When asked ~~to~~ about the extra portion they said company had a expansion of plant few years ~~ago~~ back, for now we have to consider plant as a whole. He is unable to demarcate only 6.865 acre of land from the whole land parcel. Informed there to bankers they are trying to provide land deeds for remaining portion so that we can conclude our report including all factory land area.

Also note they had only provided approve plan for Unit-1, we have requested them to provide approve plan for Unit-2 as well.

We have taken measurements of 90-95%. Building/Blocks present there, few of buildings are not matched with approve plan of Unit-1, also there are multiple building/blocks present there at Unit-1 which is not shown in approve plan.

* Requesting preparer to consider these points while preparation of file.

BUILDING/ CONSTRUCTION/ UTILITY DETAILS

Construction Status		<input checked="" type="checkbox"/> Built-up property in use, <input type="checkbox"/> Under construction, <input type="checkbox"/> No construction										
Covered Built-up Area		As per Title deed	As per Map	As per site survey								
RCC		Seperate	Sheet	Provided								
Shed												
3.	Building Type	<input checked="" type="checkbox"/> RCC Framed Structure, <input checked="" type="checkbox"/> Load bearing Pillar Beam column, <input type="checkbox"/> Ordinary brick wall structure, <input checked="" type="checkbox"/> Shed mounted on Iron trusses & Pillars, <input type="checkbox"/> Scrap abandoned structure										
4.	Appearance/ Condition of the Building	Internal - <input type="checkbox"/> Excellent, <input type="checkbox"/> Very Good, <input type="checkbox"/> Good, <input checked="" type="checkbox"/> Ordinary, <input type="checkbox"/> Average, <input type="checkbox"/> Poor <input type="checkbox"/> Under construction, <input type="checkbox"/> No Survey External - <input type="checkbox"/> Excellent, <input type="checkbox"/> Very Good, <input type="checkbox"/> Good, <input checked="" type="checkbox"/> Ordinary, <input type="checkbox"/> Average, <input type="checkbox"/> Poor <input type="checkbox"/> Under construction										
5.	Maintenance of the Building	<input type="checkbox"/> Very Good, <input checked="" type="checkbox"/> Average, <input type="checkbox"/> Poor, <input type="checkbox"/> Under construction										
6.	Age of Building/ Recent Improvements done	Unit 1 - (2017 - 2018) Unit 2 - (2020 - 2021)										
7.	Maintenance of the Building	<input type="checkbox"/> Very Good, <input checked="" type="checkbox"/> Average, <input type="checkbox"/> Poor										
8.	Any defects in the building	<input type="checkbox"/> Maintenance issues, <input type="checkbox"/> Finishing issues, <input type="checkbox"/> Seepage issues, <input type="checkbox"/> Water supply issues, <input type="checkbox"/> Electricity issues, <input type="checkbox"/> Structural issues, <input type="checkbox"/> Visible cracks in the building										
9.	Any violation done in the property (Only got Approve Map for Unit-1)	<input type="checkbox"/> Construction done without Map, <input type="checkbox"/> Construction not as per approved Map, <input type="checkbox"/> Extra covered without sanctioned Map, <input type="checkbox"/> Joined adjacent property, <input type="checkbox"/> Encroached adjacent area illegally										
10.	Boundary Wall (Only for individual property)	<input checked="" type="checkbox"/> Yes, <input type="checkbox"/> No, <input type="checkbox"/> Common boundary wall of a complex <table border="1"> <thead> <tr> <th>Running Mtr.</th> <th>Height</th> <th>Width</th> <th>Finish</th> </tr> </thead> <tbody> <tr> <td>908 m.</td> <td>10 ft</td> <td>10 in</td> <td>Simple Plasterd. Bolick wall</td> </tr> </tbody> </table>			Running Mtr.	Height	Width	Finish	908 m.	10 ft	10 in	Simple Plasterd. Bolick wall
Running Mtr.	Height	Width	Finish									
908 m.	10 ft	10 in	Simple Plasterd. Bolick wall									
11.	Garden/ Landscaping	<input checked="" type="checkbox"/> Yes, <input type="checkbox"/> No, <input type="checkbox"/> Beautiful, <input type="checkbox"/> Ordinary										
12.	Parking facilities	<input checked="" type="checkbox"/> Available within the property <input type="checkbox"/> Not available within the property	<input checked="" type="checkbox"/> On Ground, <input type="checkbox"/> In Basement, <input type="checkbox"/> On stilt <input type="checkbox"/> On road, <input type="checkbox"/> Acute parking problem									
13.	Special Comments if any											

NOTE: Use table below to mention the individual building/ shed/ blocks details. Mentioned Type of construction (RCC/ Corrugated GI Shed Mounted on Brick Wall or Iron Pillars & Trusses/ Corrugated Colored GI Shed/ Simple GI Shed/ Simple Tin Shed), Height & Area of each block in the table below.

S.No.	Block/ Building Name	Total Slabs/ Floors	Floor wise height	Year of construction	Type of construction	Structure condition	Area in Sq.ft
01.	Re-process plant shed	GF	(Unit -1) H-27ft middle		GI shed, Brick wall, Form truss PCC flooring	Average	L-47.3m B-15m
02.	Labour Quater Building near RP plant	G+2	H-10ft (Approx)/ Floor		RCC	"	Area → 2824 sq. ft Per Floor (By Google Earth)
03.	Labour Canteen	G+2	"		RCC	"	L-91.8ft B-19ft Approx.
04.	DG shed	GF	H-19ft (Avg)		GI shed, Iron pillar PCC flooring	"	L-68ft B-27ft
05.	Senior staff Quater X 3 (Building)	G+2	H-10ft Approx/ Floor.		RCC	"	(Area-954 sq. ft) Per Floor By Google Earth.
06.	Labour Quater-2 (near senior staff Quater)	G+2	"		RCC	"	(Area-1240 sq. ft per Floor) By Google Earth
07.	Staff Quater Building X 2 (Buildings)	G+2	"		RCC	"	(Area-1170 sq. ft per Floor) #(1170).
08.	Staff Quater Shale Building.	G+2	"		RCC	"	(Area-626 sq. ft per Floor) By Google Earth
09.	Labour Quater	G+2	"		RCC	"	(Area-2750 sq. ft per Floor) By Google Earth
10.	Electrical transformer Panel Room	GF	H-13ft		RCC	"	L-86ft B-24ft (Approx)
11.	Chiller shed	GF	H-25ft (Avg)		GI shed, Iron truss, Pillar PCC flooring	"	L-47ft B-17.6ft
12.	Office Building	G+2	H-10ft Approx/ Floor		RCC	"	L-57ft B-36ft * (for top floor Area-1477 sq. ft as it is small in the compar to 1st floor.
13.	Unit-1 Main shed	GF + Mezzanine floor	Total H-52ft Mezzanine H-22ft		GI shed, Iron truss, Brick wall, PCC flooring	"	(L-135m) B-57m) By Google Earth.
14.	Unit-1 Security Room	GF	H-10ft Approx.		RCC	"	L-12ft B-10ft
15.	Unit-1 Pump House.	GF	H-9ft (Avg)		GI shed, Brick wall	"	L-14ft B-12ft
16.	Lathe shed.	GF	H-9.2ft (Approx Avg)		GI shed, Brick wall	"	L-42.9ft B-17.3ft
17.	Waste material shed	GF	H-10ft (Avg)		Tin shed, Iron Rod Brick wall	"	(743 sq. ft) Area- Google Earth
18.	Gents & Ladies toilets.	GF	"		Brick wall GI shed	" Page 10 of 17	(814 sq. ft) Area by Google Earth

	Block/ Building Name	Total Slabs/ Floors	Floor wise height	Year of construct ion	Type of construction	Structure condition	Area in Sq.ft
01.	Security Room (Main Gate).	GF	H-9.7ft (UNIT-2)		RCC with PCC floor.	Average	L-13.52ft B-11.39ft
02.	Boiler shed (attached to Roto shed Unit-2)	GF	H-25 ft Approx		GI shed, Iron truss, Brick wall	"	L-50 ft B-25 ft
03.	Roto shed Unit-2 with Mezzanine floor	GF + Mezzanine	Total H-45ft Mezzanine floor at H-21ft		GI shed, Iron truss, Brick wall, PCC flooring	"	L-155 ft B-40ft
04.	Waste material shed (Behind Roto shed)	GF	H-13.3ft Average		GI shed, Iron truss, Brick wall	"	L-73.73 ft B-24.15 ft
05.	Unit 20 -2 (Main shed)	GF	H-63 ft (Max).		GI shed, Iron truss, brick wall, Industrial flooring.	"	L-110m B-70m By Approx (Google Earth)
	Attached Raw material shed & Chiller plant shed.	GF + Mezzanine	Total H-41ft Mezzanine H-16.89 ft		GI shed, Iron truss, Brick wall, PCC flooring	"	L-180 ft. B-25 ft
06.	Finishing Building (Inside Unit-2 main shed.)	G+2	H-12ft Approx.		Iron truss, GI shed, PCC, Brick wall RCC Industrial flooring at GF.	"	L-164 ft B-108 ft (Approx)
07.	Electrical transformer Panel Room Unit-2	GF	H-13ft Approx		RCC	"	L-91ft B-23 ft Approx
08.	Unit-2 staff Quater Building (top floor is little small)	G+3	H-9ft/ floor approx		RCC	"	L-75ft B-49.6ft * L-68 ft Per top floor.
09.	D4 shed Unit-2	GF	(H-22ft) (Average)		Iron truss, GI shed PCC flooring	"	L-75 ft B-41.7 ft Approx.
10.	Zig-zag shape toilets Unit-2.	GF	H-9ft (Avg) Approx		GI shed, Brick wall.	"	Area → 1279 sq. ft (By Google Earth)
11.	Pump House Unit-2	GF	H-8ft (Avg) Approx		Asbestos shed Brick wall	"	L-31ft B-18ft
12.	Bike/Cycle shed with Assembly point	GF	H-10ft (Avg) Approx.		RCC pillars, Asbestos shed PCC flooring	"	Area → 2550 sq. ft (Google Earth)
13.	Security Room Unit-2	GF	H-9.5ft Approx.		RCC	"	L-10 ft B-9 ft (Approx)
* *	There are 2 Canopy Canopy shed at Unit-2 (main shed						
and	" " " " " with Roto shed (Unit-2)						

* H of Canopy shed are around - 25ft (Avg)

If required you can measure the area by Google Earth for those.

LAND RATES INFORMATION DETAILS

Gather information on the basis of the factors like Area location, Property location, Floor level, Block, Position, Frontage, Width of lane/ road in front of the property, Nearby development

1.	Demand & Supply condition in the Market for such properties	<input type="checkbox"/> Very Good, <input type="checkbox"/> Good, <input type="checkbox"/> Average, <input type="checkbox"/> Low	
2.	At what True rate Owner bought this Property	Year of purchase	
		Purchase Price	
3.	Minimum Rate in the locality		
4.	Maximum Rate in the locality		
5.	Local Information gathered during Site survey (Minimum 2 enquiries are must):		
	1. Name:	Vikas Munot (Q Industrial Park).	
	Contact No.	9007799966	
	Sale Purchase Rate	For 2 Bigha plot Re 1.40 Cr asking.	
	Rental Rate	—	
	Comments	As per discussion, at he got industrial land available just opposite to our concerned property in Q Industrial park with all industrial amenities and with developed land, boundary wall, gate price will be Re 1.40 Cr for 2 Bigha land It is also listed in 23 acres. (price may get negotiated for large parcel little bit).	
	2. Name:	Utpal Karmakar lottery shop (Nearby people)	
	Contact No.	7602958746	
	Sale Purchase Rate	Re 2.5 to Re 3/ace / Kathas or 50-60/acs / Bigha.	
	Rental Rate		
	Comments	He got one property of 14 Bighas near to our factory by 200-200m adjacent to NH Road (frontage approx 150 ft) Developed plot with boundary wall asking price is 50 to 60/acs / Bighas.	

Surveyor Name: Rajat / Vishnu

Signature: 

Date:

09/08/2024.

✓

CASE NO.

UNDERTAKING BY THE CUSTOMER

I confirm that the property is inspected in front of me and I have provided all the information true related to the property to the best of my knowledge. I understand that any false or manipulative information provided by me will be considered as cheating with the professional organization since it will lead to incorrect valuation report and I'd be solely responsible for this unlawful act and will bear the charges for the changes/ modifications which have to undergo due to the false information. I also undertake that I haven't given any cash or in kind to any member of R.K Associates to influence the Value of the Property or favor any individual or organization and the same is not accepted or asked by the member of R.K Associates. Any such act will lead to cancellation of the material prepared by R.K Associates with forfeiting of the fees and I'll be completely responsible for its repercussions and legal actions taken for it.

IMPORTANT: We have not authorized any of our Surveyor to take Cash or kind from the customers in any situation. In case Surveyor or any member of R.K Associates asks for any money or kind from you then kindly please inform on number +91-9999597597. Our Valuation process is very stringent and have multiple check points to ensure correct & error free reports to keep the lending agency risk free. In case Surveyor claims that he would be able to arbitrary effect the Valuation figures unfairly or as per your requirement & need then he is making a false claim to you and we request you to complaint such act immediately on the number provided above.

Name: Sk. Minazul Haque
Signature: Sk Minazul 09/08/24
Mobile No.: 8583808559
Date: 09/08/24.

UNDERTAKING BY THE SURVEYOR

I confirm that I have carried out the Survey of the property properly as per the fair professional best practices and Valuation & Survey policy guidelines issued by the organization. I have not taken any cash or kind from the customer or given the customer any wrong or false information or have made any false claims for arbitrary providing the Property Valuation as per one's need or requirement by distorting the facts. In case at any point of time it is found that I have done any kind of fraudulent activity in this case and misled the company then I understand its legal consequences and appropriate penal action which company can take against me. Also in regard to it any monetary or reputation loss will be recovered from me by the company.

Surveyor Name: Rajat / Wishanu
Signature: [Signature]
Date: 09/08/24.

✓

CASE NO.

UNDERTAKING BY THE PREPARER

I confirm that this Valuation Report is prepared as per the fair professional best practices and Valuation & Survey Policy Guidelines issued by the organization. I also confirm that without any personal interest, partiality or prejudice I have worked on the Valuation work of this case. Rates adopted for the asset is based on various facts, information collected from the site came to my knowledge during the course of the assignment and I have taken all sincere efforts to review & confirm this data/ information from all different angles using my prudent approach without any biasedness or pressure. I have prepared the report based on true facts & information as per best of my knowledge & case facts. I understand that any false information provided by me will lead to the incorrect valuation report and I'd be solely responsible for it and will bear the losses which will be put on the Company in form of monetary or reputation loss by its client or statutory bodies.

I also undertake that I did not come into any influence by the customer, Bank representative (officer or agent), colleagues, coworkers or any other person to arbitrary change the Valuation figures or facts unethically or illegitimately which may put the public money at risk which is in the form of Bank deposits.

In case at any point of time in future I am found guilty of illegitimately distorting the facts in the Valuation or any other professional services which company offers in the market on being influenced by the customer or Bank representative (officer or agent) or for whatsoever may be the reason then I'd solely responsible of any such act and I understand that the Company shall take appropriate legal action against me which may include suspension from the current roles & responsibilities or termination from the employment with immediate effect.

I also undertake that I have not taken any cash, favor or in kind from the customer for favoring any individual or organization by unfair means.

I also undertake that I'll not prepare any report on incomplete Survey form which is not properly filled as per the Company guidelines and in case I am preparing it which is creating an incorrect report then I'd be responsible for its consequences.

Preparer Name:

Signature:

Date:

SURVEY SUMMARY SHEET
 (TO BE ENCLOSED WITH VALUATION REPORT)
 (Version 1.0) | Date of implementation: 10.04.2017

Every Valuation report at R.K Associates is prepared based on the thorough survey of the property carried out by our Engineering Surveyor. This Survey Summary Sheet is for the information of Banker/ concerned interested organization. Detailed Survey Form can also be made available to the interested organization in case it is required to cross check what information our surveyor has given in site inspection report based on which Valuation report is prepared.

1.	File No.	✓ 18 (2024-25) - PL 246-210-271.						
2.	Name of the Surveyor	Rajat / Kishanu						
3.	Borrower Name	Same as pg. no. 2						
4.	Name of the Owner	"						
5.	Property Address which has to be valued	"						
6.	Property shown & identified by at spot	<input type="checkbox"/> Owner, <input checked="" type="checkbox"/> Representative, <input type="checkbox"/> No one was available, <input type="checkbox"/> Property is locked, survey could not be done from inside <table border="1"> <thead> <tr> <th>Name</th> <th>Contact No.</th> </tr> </thead> <tbody> <tr> <td>Mr. Sh Minazul Haque</td> <td>85883808559</td> </tr> </tbody> </table>			Name	Contact No.	Mr. Sh Minazul Haque	85883808559
Name	Contact No.							
Mr. Sh Minazul Haque	85883808559							
7.	How Property is Identified by the Surveyor	<input type="checkbox"/> From schedule of the properties mentioned in the deed, <input type="checkbox"/> From name plate displayed on the property, <input checked="" type="checkbox"/> Identified by the owner/ owner representative, <input type="checkbox"/> Enquired from nearby people, <input type="checkbox"/> Identification of the property could not be done, <input type="checkbox"/> Survey was not done						
8.	Are Boundaries matched	<input type="checkbox"/> Yes, <input type="checkbox"/> No, <input checked="" type="checkbox"/> No relevant papers available to match the boundaries, <input type="checkbox"/> Boundaries not mentioned in available documents						
9.	Survey Type	<input checked="" type="checkbox"/> Full survey (inside-out with measurements & photographs) <input type="checkbox"/> Half Survey (Measurements from outside & photographs) <input type="checkbox"/> Only photographs taken (No measurements)						
10.	Reason for Half survey or only photographs taken	<input type="checkbox"/> Property was locked, <input type="checkbox"/> Possessee didn't allow to inspect the property, <input type="checkbox"/> NPA property so couldn't be surveyed completely						
11.	Type of Property	<input type="checkbox"/> Flat in Multistoried Apartment, <input type="checkbox"/> Residential House, <input type="checkbox"/> Low Rise Apartment, <input type="checkbox"/> Residential Builder Floor, <input type="checkbox"/> Commercial Land & Building, <input type="checkbox"/> Commercial Office, <input type="checkbox"/> Commercial Shop, <input type="checkbox"/> Commercial Floor, <input type="checkbox"/> Shopping Mall, <input type="checkbox"/> Hotel, <input checked="" type="checkbox"/> Industrial, <input type="checkbox"/> Institutional, <input type="checkbox"/> School Building, <input type="checkbox"/> Vacant Residential Plot, <input type="checkbox"/> Vacant Industrial Plot, <input type="checkbox"/> Agricultural Land						
12.	Property Measurement	<input type="checkbox"/> Self-measured, <input checked="" type="checkbox"/> Sample measurement, <input type="checkbox"/> No measurement						
13.	Reason for no measurement	<input type="checkbox"/> It's a flat in multi storey building so measurement not required <input type="checkbox"/> Property was locked, <input type="checkbox"/> Owner/ possessee didn't allow it, <input type="checkbox"/> NPA property so didn't enter the property, <input type="checkbox"/> Very Large Property, practically not possible to measure the area within limited time <input type="checkbox"/> Any other Reason:						
14.	Land Area of the Property	As per Title deed	As per Map	As per site survey				
		6.865 Acre	—	9.28 Acre (Google Earth)				
15.	Covered Built-up Area	As per Title deed	As per Map	As per site survey				
		Separate sheet provided.						
16.	Property possessed by at the time of survey	<input checked="" type="checkbox"/> Owner, <input type="checkbox"/> Vacant, <input type="checkbox"/> Lessee, <input type="checkbox"/> Under Construction, <input type="checkbox"/> Couldn't be Surveyed, <input type="checkbox"/> Property was locked, <input type="checkbox"/> Bank sealed, <input type="checkbox"/> Court sealed						
17.	Any negative observation of the	—						

property during survey	
Is Independent access available to the property	<input checked="" type="checkbox"/> Clear independent access is available, <input type="checkbox"/> Access available in sharing of other adjoining property, <input type="checkbox"/> No clear access is available, <input type="checkbox"/> Access is closed due to dispute
19. Is property clearly demarcated with permanent boundaries?	<input checked="" type="checkbox"/> Yes, <input type="checkbox"/> No, <input type="checkbox"/> Only with Temporary boundaries
20. Is the property merged or colluded with any other property	Cannot Comment (Maybe yes).
21. Local Information References on property rates	Please refer attached sheet named 'Property rate Information Details.'

Endorsement:

1. Signature of the Person who was present from the owner side to identify the property:

Undertaking: I have shown the correct property and provided the correct information about the property to the surveyor of R.K Associates to the best of my knowledge for which Valuation has to be prepared. In case I have shown wrong property or misled the valuer company in any way then I'll be solely responsible for this unlawful act.

- a. Name of the Person: SK. Minazul Haque
b. Relation: Employee
c. Signature: SK Minazul 09/08/24
d. Date: 09/08/24

In case not signed then mention the reason for it: ☐ No one was available, ☐ Property is locked, ☐ Owner/representative refused to sign it, ☐ Any other reason:

2. Surveyor Signature who did site inspection:

Undertaking: I have inspected the property and cross verified the property details at site to the extent of a. Matching boundaries of the property, b. Sample measurement of its area, c. Physical condition, d. Property rates as per local information with what is mentioned in the property documents provided to me by the Bank/interested organization. I have not come under influence of anyone during site inspection and have only recorded the true and factual details in the survey form which I come across during the site survey. I understand that giving any manipulative information in the survey form will lead to incorrect Valuation report which is an unlawful act and I'll be solely responsible for doing it.

- a. Name of the Surveyor: Rajat Wiskanu
b. Signature: [Signature]
c. Date: 09/08/24.