	RKA/DNCR//
Date of Receiving	08/03/22
File Receiver Name	Abhishek. Shanbhag.



CASE COLLECTION FORM (Version 5.0) Date of implementation: 9.02.2011 | Last Revision: 30.01.2020 | Latest Revision: 31.10.2020

	Items	Assigned To	Assigned to Date	To be completed by date	Submitted On date	Grade	HOD Engg. Signature	
File F	Received By	Abhishete S	NA	NA				
Surve	ЭУ	Athishek.s & Diperh.B						
Prepa	aration		Kor to					
	A - Very Good, E	B - Satisfactory, C -	Average, D -	Poor, E - Extre	emely Poor		14 1-4	
Engg	File Returned to HOD Engg. unprepared due to reason □ Survey not done properly, □ Survey Form not properly filled, □ Market survey for rates is not properly done, □ Identification is not clearly done, □ Measurement is not properly done, □ Photographs not clearly taken, □ Selfie/ Owner or owner representative photo not taken, □ Owner/ owner representative signature not taken, □ Google Map not taken, □ Survey summary sheet not filled							
by th	se File is returned e preparer - HOD . comment & ature	Surveyor. Rep	ort preparer t	survey hence of collect the mines. Survey has	ssing informa	tion on his ov	with warning to wn.	
			GENERA	L DETAILS		Kirish k		
1.	Proposal/ Work C Ref. No.	Order or VI	S (2021	-22) - PL	1054-	897 -	1174	
2.	Type of Service	1/	the second secon	☐ Constructionates, ☐ TEV Re		te, □ Cost v	etting certificate	
3.	Type of customer	✓ Bank		□ PSU	□ NBFC	☐ Corporate		
	Donk/ El/ Organiz	□ Com		☐ Private client				
4.	Bank/ FI/ Organiz Name & Address	ation	el & F	IND " WILL	, atom	out out	fe farade,	
5.	Case Allotment O	fficer/	Name	Contac	t Number	E	mail ld	
	Fees paying party Details Rohy Vishuakerma 9820744937 MCC 6294@pn							
6.	Case Type		☐ Case for Fresh Account ☐ Case for exiting account/ cus				ount/ customer	
7.	Fees Details	Amour	nt of Fees	Advance Amo	ount if any	Fees will be paid by		
		Ree st	rutwel	-		✓ Bank □ Customer		
8.	Billing Details	and a section and a section of the	Billed To Pa	Market and the second second second	THE RESIDENCE OF THE PERSON NAMED IN COLUMN	GST		

		CASE DETAIL	S	ALC STATE OF	及各名的是2.10mm。12.10mm。2					
1.	Type of Property	Commercial Land	and	Building						
2.	Purpose of Valuation/ Assignment	☐ Value assessment of the asset for creating new collateral mortgage								
	\	Periodic Re-Valuation for Bank, □ Distress sale for NPA A/c.,								
		☐ For DRT Recovery purpo			ılth Tax purpose					
		☐ Partition purpose, ☐ Gen	eral Value	Assessment						
		☐ Any other:								
3.	Owner/ Applicant Details	Name	Contac	ct Number	Email Id					
		Bhanvarideri			valentine textile @					
		Vachansingh Balia			Jahoo. com.					
4.	Account Name	Valentine Textile	Co. Pv	t Ltd.						
5.	Property Address Shubham	561 Kombadpada	Road,	Groky N	lagar, Near					
		Valentine Textile 561 Kombadpada Shivaji chowk, Sr. No 46 A/2 CTS1	BHI wan	di, Mahar	oghta - 421302.					
6.	Who will coordinate on									
	site for the site survey	Ariun.		9322071000						
7.	Preferred time of survey	Date 09/03/22			· Pm					
8.	Documents Received (Any one ownership document and approved site plan/ map is must)	receipt, ☐ House Tax de 4. Any Other document: ☐ ☐ Old Valuation Report 5. No documents provided	linquishme Allotment I pproved Ma y Bill & pay mand & pay I CLU, I	nt Deed, □ Tra Letter, □ Poss ap, □ Site Plar yment receipt, yment receipt	ansfer Deed, lession Letter Water Bill & payment Agreement to Sale,					
9.	Documents received from	Banker								
10.	Special Instructions if any:	Banker								
11.	on Valuer firm to distort any	lentioned above for the preparation and would not try to influe tany individual or organization by	nce any me	mber or official	ree that I'll not put pressure of the firm in the ill spirit or					

	File No. RKA/DNCR//							
	FILE RECEIVER CASE COLLECTION PROCESS COMPLIANCE CHECKLIST (To be filled by Surveyor)							
S.NO.	COMPLIANCE CHECKLIST	STATUS	APPROVER SIGNATURE/ REMARKS IN CASE OF ANY (X)					
1.	Is Case collection Form properly filled by Receiver?	V V						
2.	Is purpose of the assignment understood clearly by the receiver?							
3.	Has receiver checked if this is a new case or existing case of the Bank?	D						
4.	Has receiver fixed the fees with the manager/ client and sent quotation properly or have taken approval of the work over email?	J						
5.	Has receiver taken proper Work Order/ Email/ CESA form formality?	Ø						
6.	In case of private case or for fresh case 50% advance is received?							
7.	Is document checklist email sent to the customer?							
8.	Has the received documents is having 'documents							

<u>IMPORTANT INSTRUCTIONS TO SURVEYOR</u>

provided by stamp'?

No. 17	The state of the s
1.	Please fill the above compliance checklist before moving for the survey.
2.	Please do not do the survey if you do not have proper documents.
3.	For Vacant Plot/ Land - Cizra Map/ Master/ Zonal/ Site Plan is must to identify the Plot. For Agriculture or converted land from agriculture - Mutation documents, CLU is must.
4.	Firstly please first study the documents of the property which needs to get surveyed.
5.	Mark the Owner/ Area/ Boundaries mentioned in the ownership documents with bold florescent marker pen before moving for the survey. During site survey if any difference is found in the above fields from the ownership documents then please contact the owner immediately to know the reason for the difference.
6.	Confirm ongoing property rates in the subject location through public domain, property sites and contact dealers to show you the available properties in that area during your survey.
7.	Identify the Property clearly by matching the boundaries and area mentioned in the property papers.
8.	Do sample physical or google measurements of the property.
9.	a. Take owner/ representative photograph along with the property. b. Take your selfie along with the property and the owner/ representative. c. Take full scale photo of the property with gate. d. Take photo of the property along with abutting road, towards left, right and center. e. Take multiple photos of inside-out of the property. f. Take nearby photographs of the Property. g. Take a short video to cover property and neighborhood.
10.	Take Google Map location.
11.	Check main road name & width and approach road width and distance of property from main road.
12.	Check Jurisdiction Municipal Limits & Ward Name.
13.	Fill each column of survey form diligently in detail and tick the appropriate option clearly.
14.	Check any defects or negativity in the property and comment in detail on survey form.
15.	Do extensive market rate enquiries and confirm for any recent past transactions.
16.	In case customer appears to be providing misleading information to you or trying to influence you by money or cash then immediately report to the Management & Bank.

	SURVEY GRADING MATRIX
ADE	PARAMETERS/ CRITERIA
A	In case all the points below are done properly, timely with full care and diligence:
	 Survey started with proper work order and knowing the source of payment. Survey done with proper documents. Done complete homework and studied the documents properly with highlighting the main points before moving for the survey. Chosen correct survey form as per the property type. All fields of Survey form are properly filled. All site special observations and negative and positive factors are clearly mentioned. Self & client signatures taken on survey form. Property rates information properly taken, mentioned and verified. Site rough sketch plan made. Proper photographs taken. Selfie with property taken. Selfie and owner photograph with property taken.
В	In case of 3 minor mistakes in any of the above points except Point 1, 2, 3, 4, 6, 8, 10, 11, 12 but all the points are covered.
С	In case of more than 3 minor mistakes and any 1 major mistake in any of the above points and if any points are completely missing except Point 1, 2, 3, 4, 6, 8, 10, 11, 12.
D	In case of 1 major mistake or missing of any 1 point out of 1, 2, 3, 4, 6, 8, 10, 11, 12.
E	In case of more than 1 major mistakes or missing of more than 1 point out of 1, 2, 3, 4, 6, 8, 10, 11, 12.

Note (Survey Grading Matrix):

- For special assignments like LIE, Stock Valuation, etc. where till date survey format is not specified or released, in such cases point wise site observation report has to be submitted by the Surveyor duly signing it properly. Without signed Site Observation report, Point 4 will be considered as not done and will fall under Category E.
- 2. Similar Grading Matrix is issued for Case Collection & Report Preparation as well.

Note (Overall Grading Matrix):

1. In case client reports any careless mistake in the report for which revision has to be done in the report then in that case Grading Matrix may be revised and Grade E will be awarded.

	SURVEY PROCESS COMPLIANCE CHECKLIST	美国的
1	(To be submitted by Surveyor with each Survey)	
S.NO.	COMPLIANCE CHECKLIST POINTS	STATUS
1.	Did you take proper property documents to carry out the survey? (only land doc. availa	ble 1
2.	Have you properly studied & highlighted Owner/ Area/ Boundaries in the property	12
	documents with bold florescent before moving for the survey? (only land area)	
3.	Did you check prominent landmark nearby the subject property and mentioned in the survey form?	Q
4.	Did you identified the Property clearly by matching the boundaries and area mentioned in the property papers?	
5.	Did you check if property is merged with any other property or it is an independent property?	
6.	Did you do sample physical or google measurements of the property in case of property more than 2500 sq.mtr?	
7.	Did you check for any building violations in the property?	Ø
8.	Did you check municipal limits/ jurisdiction/ ward?	V
9.	Did you take Google Map location and shared it to Maps whatsapp group?	Ø
10.	Did you check Main road name & width and its distance from the subject property?	A
11.	Did you check approach Lane width on which property is located?	
12.	Have you taken property full scale photograph with gate?	A
13.	Have you taken owner/ representative photograph with the property?	M
14.	Have you taken your selfie with the property along with owner/ representative?	
15.	Have you taken photograph of the property along with abutting road and towards left and right of the property?	A
16.	Have you taken multiple photographs of the property from inside-out?	, D
17.	Did you check nearby development and whereabouts and commented on survey form?	<i>J</i>
18.	Did you check any defects or negativity in the property in terms of location, legality, disputes, marketability, salability, etc. and commented on survey form in detail?	A
19.	Have you filled all the columns of survey form including survey summary sheet properly?	
20.	Did you draw site key plan (location map)?	
21.	Did you draw rough site sketch plan?	
22.	Have you taken self-attested documents from owner/ representative and stamped "documents provided by stamp"?	
23.	Did you check any defects or negativity in the property in terms of location, legality, disputes, marketability, salability, etc. and commented on survey form in detail?	Ø
24.	Have you confirmed any recent past transactions during market enquiries and enquired property rates locally very rigorously?	Ø
25.	Did you take signatures of the owner/ representative on undertaking and survey summary sheet?	
26.	Did you signed the undertaking?	Ø

For File No.	100 (2.21.12) OL 10CL CC	1171
	VIS (2021-22)-PL 1054-897	- 1170
Surveyor Name	Abhishek & Dipesh	
Signature	Deservice.	
Date	09/03/22	

GENERAL SURVEY FORM
(FOR PROPERTIES OTHER THAN FLATS)
(Version 5.0)
Date of implementation: 9.02.2011 | Last Revision: 04.01.2018 | Latest Revision: 31.10.2020

File No. RKA/DNCR//	Date:	09/03/22	Timer	Spm	
	Date.		l ime:		

		GENERAL DETAILS	的推荐的位置的 中心之间的				
1.	Name of the Surveyor	Abhisher. 5 4 Dipesh . B					
2.	Property shown by	☐ Owner, ☐ Representative, ☐ No one was available, ☐ Property is					
		locked, survey could not be done from inside					
		Name Contact No.					
		Full survey (inside-out with measure)	9322071000				
3.	Survey Type	Full survey (inside-out with measure	surements & photographs)				
		☐ Half Survey (Measurements from					
		☐ Only photographs taken (No me	asurements)				
4.	Reason for Half survey or only		essee didn't allow to inspect the				
	photographs taken NA.	property, ☐ NPA property so could	n't be surveyed completely				
5.	How Property is Identified	☐ From schedule of the propertie	s mentioned in the deed, 🗸 From				
			perty, Identified by the owner/				
		owner representative, 🗸 Enquired					
			ıld not be done, □ Survey was not				
6	Type of Droporty	done	Desidential Heres D Levy Biss				
6.	Type of Property	☐ Flat in Multistoried Apartment, [
		Building, Commercial Office,	r Floor, Commercial Land &				
		Floor, Shopping Mall, Hotel,					
		☐ School Building, ☐ Vacant Residential Plot, ☐ Vacant Industrial Plot, ☐ Agricultural Land					
7.	Property Measurement	Self-measured, ☐ Sample meas	surement only, No measurement				
8.	Reason for no measurement	☐ It's a flat in multi storey building					
		☐ Property was locked, ☐ Owner/	poscessee didn't allow it,				
	A A	☐ NPA property so didn't enter the	e property, Very Large Property,				
	ALCOHOLD THE STATE OF THE STATE	practically not possible to measi	ure the entire area □ Any other				
		Reason:					
9.	Purpose of Valuation	☐ Value assessment of the asset f	or creating new collateral mortgage				
		Periodic Re-Valuation for Bank,					
		☐ For DRT Recovery purpose, ☐					
		☐ Partition purpose, ☐ General Va					
10.	Type of Loan		Over Loan, Home Improvement				
	Business loan		Construction Loan, ☐ Educational				
			oan, ☐ Term Loan, ☐ CC Limit				
44	Lean Amount	enhancement, Cash Credit Limit	., 🗆 IIIUUSIIIAI LOAII, 🗀 NA				
11.	Loan Amount						

Current owner - Mr. Vachan Singh

4		OWNERSHIP DETAILS
1.	Legal Owner Name/s	Bhanvarideri Vachaneligh Balia
2.	Property Purchaser Name	Bhanvarddeni Vacharingh Balla
3.	Property Address under Shub ham Palous	Near Shivayi chowk, Bhiwandi, Maharashtra- 42130
4.	Present Residence Address of the Owner/ Purchaser	Sr. No 46 A/2 CTS No. 3374.
5.	Property constitution	✓ Free Hold, ☐ Lease Hold

Market 1		LOCATIO	ON DETA	<u>ILS</u>					
1.	Adjoining Properties	East		West	N	orth	Sc	outh	
	(Match it with papers with the help	Kompadpa	ida 1	Crish na expartment	Sukho	inoni	Palo	unde	
	of compass or Sun direction and	Road.		apartment	Apori	ments	che	.) Luc	
	also confirm it with nearby people)	East Facing, ☐ North Facing, ☐ West Facing, ☐ South Facing,							
2.	Property Facing MW	East Facir	ng, 🗆 Nort	h Facing, □	West Fa	cing, ⊔ So	outh Fac	ing,	
	5-N	☐ North-Eas	t Facing, [☐ South-Wes	st Facing	, ☐ South-	-East Fa	cing,	
	E	☐ North-Wes	st Facing						
3.	Landmark Entry	New SI	nivaji (howk.				Law of the	
4.	Ward Name/ No.	11-11-11			Jan.				
5.	Zone Name	-							
6.	Main Road Name & Width	Nan	ne	Wid	th	Distanc	e from	property	
	Shivaji Chewk Ro	Kontako	the Room	- Aprox	25-30f	+ Build	ling R	wad	
7.	Approach Road Name & Width	Dambar	Dada No	1000,				ouch,	
8.	Location consideration of the	☐ Within Ma	ain city, \square	Within Goo	d Urban	developed	I Area, [✓ Within	
	Society	developing a	rea, □ Hiç	ghly posh loc	ality, □ \	ery Good,	☐ Goo	d,	
		☐ Ordinary,	☐ In inte	riors, Rem	note area	, □ Backw	vard, 🗆	Average,	
		□ Poor							
	L. Z. dwarz	Marian Service III Sell	:-	al Cosing C	V Dood I	Fooing D	Entranc	o North	
9.	Special Location consideration		1	ool Facing,	A Koad I	-acing, \Box	Lilliand	e North-	
	of the property	East Facing,	V				igaska u Str		
10.	Characteristics of the locality	☐ Urban de	veloped,	Urban deve	eloping, [Semi Urb	oan, 🗆 F	Rural,	
		□ Backward	/ Indust	rial, 🗆 Institu	tional				
11.	Category of Society/ locality	☐ High End	Norma	ıl, □ Affordal	ole Group	Housing,	□ EWS	i, □ HIG,	
	Category of Goodety/ locality	☐ MIG, ☐ L							
12.	Utilities/ Facilities in the locality			Landscaping					
	None	☐ Club House, ☐ Walk Trails, ☐ Kids play zone, ☐ 100% Power							
10	Descipite to civin amonition	Backup School	Hospital	Market	Metro	Railway	Station	Airport	
13.	Proximity to civic amenities			350m		5.2			
	Any navy days language in	220m	140 m		under 1		rm	42 Km	
14.	Any new development in	Metor con	struction		construction construction	90			
the ba	surrounding area	900	707		م آه ۾ اورنگ	y - 14 15 1			

4	Jurisdiction limits					
1		□ Nagar Nigam, □ Na	gar Panchayat, 🗆 Grar	n Panchayat, 🗆 Nagar		
40		Palika Parishad, Area	a not within any municipa	l limits		
16.	Jurisdiction Development	\square DDA, \square GDA, \square NOIDA, \square GNIDA, \square YEIDA, \square HUDA, \square KMDA,				
	Authority Name	☐ MDDA, ☐ Any other Development Authority:				
		☐ Area not within any development authority limits				
17.	Municipal Corporation Name	□ NDMC, □ SDMC, □ EDMC, □ Ghaziabad Municipal Corporation,				
	Shahar Mahanagar	☐ Gurgaon Municipal C				
	Il'h	☐ Kolkata Municipal Co	orporation, Dehradun	Municipal Corporation,		
	Palik or	☐ Area not within any municipal limits, ☐ Any other Munici				
		Corporation/ Municipality	r. Caralla and Caralla			
		PHYSICAL DETAIL	S			
1.	Land Area	As per Title deed	As per Map	As per site survey		
		501.67 Sq.m	(Ormogle) 518 Sq. M			
2.	Any conversion to the land use		37.10			
		N.A Land.				
3.	Land Type		☐ Marsh Land, ☐ Recla	aimed Land, Water		
		logged, □ Land locked				
4.	Shape of the Land		ular, 🗆 Trapezium, 🗆 Tr	iangular, □ Trapezoid,		
77.5		☐ Irregular, ☐ NA				
5.	Level of Land		low road level, □ Above			
6.	Frontage to depth ratio	AND RESIDENCE OF THE PARTY OF T	Less frontage, □ Large t			
7.	Are Boundaries matched		No relevant papers av	All the control of th		
			ries not mentioned in ava			
8.	Is Independent access available to the property		access is available, [E Tourselle The Land Control		
	to the property		ning property, No clea	ar access is available,		
		☐ Access is closed du				
9.	Is property clearly demarcated with permanent boundaries?	☐ Yes, ☐ No, ☐ Only	with Temporary boundar	ies Not on all		
10.	Is the property merged or	One side of co	mpound is comm	non wall of		
11	colluded with any other property	adjacent Buil	ച്ച · ☑ Lessee, □ Under Co	netruction		
11.	Property possessed by at the time of survey		perty was locked, D B			
		sealed				
12.	Current activity carried out in the property	Residential purpo	ose, ☐ Commercial p☐ Vacant, ☐ Locked, ☐	urpose, Godown,		
	p.oporty	L Onice, La mudsulai,	vacant, L Locked, L	Truly other use.		
With the same of t	BUILDING	G/ CONSTRUCTION/ U	TLITY DETAILS			
1.	Construction Status		n use, □ Under construc	tion, □ No construction		
10000000		¥				

Tick one on the basis of which valuation is to be calculated)	1	Covered Built-up Area	☐ Covered Area, ☐	Floor Area,	Super Are	a, Carpet Area
valuation is to be calculated)	/		As per Title deed	As per M	Мар	As per site survey
Building Store Building Store			-	-		20,327.04 Ft
Soliding Type Cabins Cubicles Cabins Cabin	3.		G+3	IX L. Fred		
Cabins/ Cubicles 6. Building Type Crotinary brick wall structure, Load bearing Pillar Beam column Ordinary brick wall structure, Iron trusses & Pillars, Scrap abandoned structure Roof RCC, RCC, GI Shed, Tin Shed, Stone Patla Delight: Grante, PoP Punning, POP False Celling, Coved roof, No plaster Vitrifed tiles, Grante, Italian Marble, Pavers, Chequered Tiles, Brick Tiles, No Flooring, Under construction, Any other type: Internal Excellent, Very Good, Good, Ordinary, Average, Poor Under construction No Survey External Excellent, Very Good, Good, Ordinary, Average, Poor Under construction No Survey Simple plastered walls, Brick walls without plaster, Designer textured walls, POP punning, Coved roof, Under construction Simple plastered walls, Brick walls without plaster, Designer textured walls, PoP punning, Coved roof, Under construction Simple plastered walls, Brick walls without plaster, Designer textured walls, PoP punning, Coved roof, Under construction Simple plastered walls, Brick walls without plaster, Designer textured walls, PoP punning, Coved roof, Under construction, No Survey Simple plastered walls, Brick walls without plaster, Designer textured walls, Brick walls without p	4.	Floor on which property is situated	Cn + 3			
Ordinary brick wall structure,	5.	Cabins/ Cubicles	-			
Ordinary brick wall structure,	6.	Building Type	RCC Framed Str	ucture, Loa	ad bearing	Pillar Beam column,
Abandoned structure Abandoned structure A Make: RBC, RCC, GI Shed, Tin Shed, Stone Patia B. Height: G. Finish: Simple plaster, POP Punning, POP False Ceiling, Coved roof, No plaster Pop Punning, POP False Ceiling, Coved roof, No plaster Pop Punning, POP False Ceiling, Coved roof, No plaster Pop Punning, POP False Ceiling, Coved roof, No plaster Pop Punning, POP False Ceiling, Coved roof, No plaster Pop Punning, POP False Ceiling, Coved roof, No plaster Pop Punning, POP False Ceiling, Coved roof, No plaster Pop Punning, POP False Ceiling, Coved roof, Pop Punning, Pop Punni			☐ Ordinary brick wa	Il structure, □	Iron truss	ses & Pillars, Scrap
Roof			abandaned structure			
b. Height: fg	7.	Roof	a. Make: RBC,	RCC, G	I Shed, [☐ Tin Shed, ☐ Stone
C. Finish: Simple plaster, POP Punning, POP False Ceiling, Coved roof, No plaster Vitrified tiles, Ceramic Tiles, Simple marble, Marble chips, Mosaic, Granite, Italian Marble, Kota stone, Wooden, PCC, Imported Marble, Pavers, Chequered Tiles, Brick Tiles, No Flooring, Under construction, Any other type: Internal - Excellent, Very Good, Good, Ordinary, Average, Poor Under construction, No Survey External - Excellent, Very Good, Good, Ordinary, Average, Poor Under construction No Survey External - Excellent, Very Good, Good, Ordinary, Average, Poor Under construction Excellent, Very Good, Good, Ordinary, Average, Poor Under construction Excellent, Very Good, Good, Ordinary, Average, Poor Under construction Excellent, Very Good, Good, Ordinary, Average, Poor Under construction Excellent, Very Good, Good, Ordinary, Average, Below average, Under construction No Survey Simple plastered walls, Brick walls without plaster, Designer textured walls, Porch, Under construction Simple plastered walls, Brick walls without plaster, Designer textured walls, Porch, Under construction Simple with no cupboard, Ordinary with cupboard, Ordinary fixtures & fittings, Fancy lights, Chandeliers, Concealed lightning, Under construction, No Survey External, Internal Excellent, Very Good, Good, Simple, Ordinary,			b Height: Pa	1	/	
Ceiling,			- Finish C Simp	la plaster 🗸	POP Pui	nning 7 POP False
Stripte Stri			C. Finish:	roof \square No pla	aster	9, 7
Chips, Mosaic, Granite, Italian Marble, Rota stone, Wooden, PCC, Imported Marble, Pavers, Chequered Tiles, Brick Tiles, No Flooring, Under construction, Any other type:	8	Flooring	☐ Vitrified tiles ☐	Ceramic Tiles	Simp	ole marble, Marble
Wooden, PCC, Imported Marille, Pavers, or Northectors Tiles, Brick Tiles, No Flooring, Under construction, Any other type:	0.	Different or	chips ☐ Mosaic ☐ Granite. ☐ Italian Marble, ☑ Kota stone,			
Supperance Towns Tiles, Brick Tiles, No Flooring, Under construction, Any other type:		Metoda,	☐ Wooden ☐ PCC	□ Imported N	⁄larble, □	Pavers, ☐ Chequered
Other type:		different 1-1000s.	Tiles, ☐ Brick Tiles,	☐ No Flooring	, 🗆 Unde	r construction, \square Any
Building			other type:			The state of the s
External - Excellent, Very Good, Good, Ordinary, Average, Poor Under construction	9.	Appearance/ Condition of the	Internal - Excel	lent, □ Very	Good, □	Good, Ordinary,
Average,		Building	☐ Average, ☐ Poor	☐ Under const	ruction, \Box	No Survey
10. Maintenance of the Building			External - Exce	llent, Very	Good, □	I Good, ☐ Ordinary,
Interior decoration			☐ Average, ☐ Poor	☐ Under const	ruction	
Average, Below average, Under construction, No Survey Simple plastered walls, Brick walls without plaster, Designer textured walls, POP punning, Coved roof, Under construction, No Survey	10.	Maintenance of the Building	☐ Very Good, ☑ Ave	erage, Poor,	□ Under	construction
Designer textured walls,	11.	Interior decoration	☐ Average, ☐ Below	average, U	nder const	truction, No Survey
Under construction, □ No Survey 3.	12.	Interior Finishing	Simple plastered v	valls, Brick v	valls withou	ut plaster,
Simple plastered walls, Brick walls without plaster, Architecturally designed or elevated, Brick tile Cladding, Structural glazing, Aluminum composite panel cladding, Glass façade, Domb, Porch, Under construction Simple with no cupboard, Ordinary with cupboard, Normal Modular with chimney, High end Modular with chimney, Under construction, No Survey External, Internal Ordinary fixtures & fittings, Fancy lights, Chandeliers, Concealed lightning, Under construction, No Survey External, Internal Excellent, Very Good, Good, Simple, Average, Below average, Under construction, No Survey Jet pump, Submersible, Jal board supply Excellent, Very Good, Good, Simple, Ordinary, Average, Below Average, No wooden work, No survey Mayer age, Below Average, Below Average, No wooden work, No survey Mayer age, Below Average, No wooden work, No survey Mayer age, Below Average, No wooden work, No survey Mayer age, Below Average, No wooden work, No survey Mayer age, Below Average, No wooden work, No survey Mayer age, Below Average, No wooden work, No survey Mayer age, Mayer age, No wooden work, No survey Mayer age, Mayer age, No wooden work, No survey Mayer age, Mayer age, No wooden work, No survey Mayer age, Mayer age, No wooden work, No survey Mayer age, Mayer age, No wooden work, No survey Mayer age, Mayer age, Mayer age, Mayer age, Mayer age, No wooden work, No survey Mayer age, Mayer ag			☐ Designer textured	walls, POP	punning, [☐ Coved roof,
Architecturally designed or elevated, Brick tile Cladding, Structural glazing, Aluminum composite panel cladding, Glass façade, Domb, Porch, Under construction Simple with no cupboard, Ordinary with cupboard, Normal Modular with chimney, High end Modular with chimney, Under construction, No Survey External, Internal Ordinary fixtures & fittings, Fancy lights, Chandeliers, Concealed lightning, Under construction, No Survey External, Internal Excellent, Very Good, Good, Simple, Average, Below average, Under construction, No Survey Jet pump, Submersible, Jal board supply Excellent, Very Good, Good, Simple, Ordinary, Average, Below Average, No wooden work, No survey 19. Age of Building/ Recent Mprov 2 b 100 Mprovements done			☐ Under construction	, ☐ No Survey		
Architecturally designed or elevated, Brick tile Cladding, Structural glazing, Aluminum composite panel cladding, Glass façade, Domb, Porch, Under construction Simple with no cupboard, Ordinary with cupboard, Normal Modular with chimney, High end Modular with chimney, Under construction, No Survey External, Internal Ordinary fixtures & fittings, Fancy lights, Chandeliers, Concealed lightning, Under construction, No Survey External, Internal Excellent, Very Good, Good, Simple, Average, Below average, Under construction, No Survey Jet pump, Submersible, Jal board supply Excellent, Very Good, Good, Simple, Ordinary, Average, Below Average, No wooden work, No survey Aprox 2 b Jens No wooden work, No survey Jet pump Submersible, Jal board supply Aprox 2 b Jens No wooden work, No survey Jet pump Below Average, No wooden work, No survey Jet pump Submersible, Jens No wooden work, No survey Jet pump Submersible, Jens No wooden work, No survey Jens No wooden work, No survey Jet pump Submersible, Jens No wooden work, No survey Jet pump Submersible, Jens No wooden work, No survey No wooden work, N	13.	Exterior Finishing				
Glass façade, □ Domb, □ Porch, □ Under construction						
Simple with no cupboard, □ Ordinary with cupboard, □ Normal Modular with chimney, □ High end Modular with chimney, □ Under construction, □ No Survey □ External, □ Internal □ Ordinary fixtures & fittings, □ Fancy lights, □ Chandeliers, □ Concealed lightning, □ Under construction, □ No Survey □ External, □ Internal □ Excellent, □ Very Good, □ Good, □ Simple, □ Average, □ Below average, □ Under construction, □ No Survey □ Particular of the survey □ Description of the survey			☐ Structural glazing,	☐ Aluminum o	composite	panel cladding,
Modular with chimney, ☐ High end Modular with chimney, ☐ Under construction, ☐ No Survey 15. Class of Electrical fittings ☐ External, ☐ Internal ☐ Ordinary fixtures & fittings, ☐ Fancy lights, ☐ Chandeliers, ☐ Concealed lightning, ☐ Under construction, ☐ No Survey 16. Class of Sanitary/ Plumbing & ☐ Excellent, ☐ Very Good, ☐ Good, ☐ Simple, ☐ Average, ☐ Below average, ☐ Under construction, ☐ No Survey 17. Water arrangements ☐ Jet pump, ☐ Submersible, ☐ Jal board supply ☐ Excellent, ☐ Very Good, ☐ Good, ☐ Simple, ☐ Ordinary, ☐ Average, ☐ Below Average, ☐ No wooden work, ☐ No survey 19. Age of Building/ Recent ☐ Mayox 20 10000000000000000000000000000000000			☐ Glass façade, ☐ [Domb, ☐ Porch	ı, ⊔ Under	construction
Class of Electrical fittings	14.	Kitchen	☐ Simple with no cu	ipboard, U Ord	dinary with	cupboard, U Normal
15. Class of Electrical fittings	la la	ou 7 4 61 026.			wodulal w	nun chimiley, 🗆 Onder
Ordinary fixtures & fittings, ☐ Fancy lights, ☐ Chandeliers,☐ Concealed lightning, ☐ Under construction, ☐ No Survey 16. Class of Sanitary/ Plumbing & water supply fittings ☐ Excellent, ☐ Very Good, ☐ Good, ☐ Simple, ☐ Average, ☐ Below average, ☐ Under construction, ☐ No Survey 17. Water arrangements ☐ Jet pump, ☐ Submersible, ☐ Jal board supply 18. Fixed Wooden Work ☐ Excellent, ☐ Very Good, ☐ Good, ☐ Simple, ☐ Ordinary, ☐ Average, ☐ Below Average, ☐ No wooden work, ☐ No survey 19. Age of Building/ Recent ☐ Aprox 20 1000 ☐ Aprox 2		Ol CEL Minds				
Concealed lightning, □ Under construction, □ No Survey External, □ Internal □ Excellent, □ Very Good, □ Good, □ Simple, □ Average, □ Below average, □ Under construction, □ No Survey □ Jet pump, □ Submersible, □ Jal board supply □ Excellent, □ Very Good, □ Good, □ Simple, □ Ordinary, □ Average, □ Below Average, □ No wooden work, □ No survey □ Age of Building/ Recent Aprox 2 o years □ Apr	15.	Class of Electrical fittings			Fancy lie	ohts Chandeliers
16. Class of Sanitary/ Plumbing & water supply fittings						
water supply fittings □ Excellent, □ Very Good, □ Good, □ Simple, □ Average, □ Below average, □ Under construction, □ No Survey 17. Water arrangements □ Jet pump, □ Submersible, □ Jal board supply □ Excellent, □ Very Good, □ Good, □ Simple, □ Ordinary, □ Average, □ Below Average, □ No wooden work, □ No survey 19. Age of Building/ Recent Improvements done	16	Class of Sanitary/ Plumbing &	External Intern	al		
Below average, □ Under construction, □ No Survey 17. Water arrangements □ Jet pump, □ Submersible, □ Jal board supply 18. Fixed Wooden Work □ Excellent, □ Very Good, □ Good, ☑ Simple, □ Ordinary, □ Average, □ Below Average, □ No wooden work, □ No survey 19. Age of Building/ Recent Aprox 20 years — — — — — — — — — — — — — — — — — —	10.		☐ Excellent, ☐ Very	Good, ☐ Good	d, Simpl	le, □ Average,
17. Water arrangements □ Jet pump, □ Submersible, □ Jal board supply 18. Fixed Wooden Work □ Excellent, □ Very Good, □ Good, □ Simple, □ Ordinary, □ Average, □ Below Average, □ No wooden work, □ No survey 19. Age of Building/ Recent □ Aprox 20 years □ —			☐ Below average, ☐	Under constru	iction, 🗆 N	lo Survey
18. Fixed Wooden Work □ Excellent, □ Very Good, □ Good, □ Simple, □ Ordinary, □ Average, □ Below Average, □ No wooden work, □ No survey 19. Age of Building/ Recent Improvements done	17.	Water arrangements	☐ Jet pump, ☐ Subr	nersible, 🗆 Jal	board sup	pply
Average, □ Below Average, □ No wooden work, □ No survey 19. Age of Building/ Recent Aprox 20 years - □ Improvements done Aprox 20 years - □	1000	West Control of the C				
Improvements done			☐ Average, ☐ Below	v Average, 🗆 N	lo wooden	work, □ No survey
20 Maintenance of the Building	19.		Aprox 20 yes	rs.	-	
_U,	20.		☐ Very Good, ☐ Ave	erage, Poor		

1	Any defects in the building					
1				hing issues, □ See		
1	None	☐ Water supply issues, ☐ Electricity issues, ☐ Structural issues,				
		☐ Visible cracks in the building				
22.	Any violation done in the property	☐ Construction done without Map, ☐ Construction not as per				
	None.	approved Map.	☐ Extra covered	without sanctione	ed Map. Joined	
	"OVA"		adjacent property, □ Encroached adjacent area illegally			
23.	Boundary Wall (Only for individual	☐ Yes, ☐ No, ☑ Common boundary wall of a complex				
	property) common boundary	Running Mtr.	Height	Width	Finish	
	wall is not on all sides.		- Tieight	- Vidui	-	
24.	Lift/ elevators	□ Passenger/ □ Commercial				
	No	Make:		Capacity:		
25.	Power backup	☐ Inverter, ☐ [OG Set			
	No.	Make:		Capacity:		
26.	Garden/ Landscaping	☐ Yes, ☑ No, I	☐ Beautiful, ☐ O	rdinary		
27.	Parking facilities .	☐ Available within the property ☐ On Ground, ☐ In Basem			☐ In Basement,	
				☐ On stilt		
		☐ Not availa	ble within the	On road,	Acute parking	
00		ргорепу		problem		
28.	Special Comments/ Observations, if any	Giround FI	our on Rer	t. No Photo	s of Groundt	
	ii aiiy	Third Floor	on Rent,			
				. 1 k	ر د اماله .	
		Don Cide /	Buck cide)	and boundary	avalubit -	
	MARKETABII	ITY SELABIL	TY/UTLITY DE	TAILS		
1.	Any issues in marketability of the	☐ Yes, ☑ No				
	property?	V	se of No: 1 Lo	ocation, 🗸 Surrou	nding. 🗆 Legal	
			mand, □ Shape, [
		doposie,		_ ,, o		
2.	How is Demand & Supply condition	Demand □ V	ery Good, 🗹 Goo	d, □ Average, □ L	ow, Poor	
	in the Market of such properties?			d, ☑ Average, □ L		
3.	Is property easily sellable &	, ✓ Yes, □ No		,	,	
J.	marketable?		T. ve ic Man	oly and yo	cant land	
		Sommond.	nere 13	ely any va	n he for	
		SWWEN SI	Le Todusta's	I plots can be	bund in	
4.	How is the current utility of the	☐ Excellent, ☐	Very Good, □ Go	ood, ☑ Average, □	Low, Poor	
	property?			(Yadius of		
5.	At what True rate Owner bought	Year of purchas	e			
	this Property?	Purchase Price				
6.	Present expected Sale Value of the					
0.	overall property?					
		Andrew Mineral Conference				

BLANK PAGE FOR PROVIDING ANY ADDITIONAL DETAILS/INFORMATION

Terrace? (56.615 x 89.76 ft) x 100rs.

Tin Shed ! height = 12.98 Ft.

Building troops; (97+3) floors



Height: 1st floor: - 9.33ft.


2nd floor :- 9.19 ft

(on Rent) 3rd ADOV! - 9.29 Ft

(on Rent) Ground Floor: - 9.25 Ft.

NOTE ! 1) Compound wall on 2 sides only. one side open to soud (Road Javing) one wall of other Building. common. one side not accessible (Back side). very difficult in this area to find 2) Commercial land is vacant land in nearby to survey site. There are 10 CWI: Boundary wall present. Compound Wall CW2 Cw2: - Boundary wari present but not ah Plot. CW3 distrightion * CW3; - it is wall of CW4 adjacent building. ROOM CW4 := open to Jand. Page 11 of 15

DRAW SITE KEY PLAN & SKETCH PLAN



Page 12 of 15

	(Availa	ble for Sale or Subject	I ransaction already	NFORMATION DETA happened in past)	
NO		Property	Comparable 1	Comparable 2	Comparable 3
1.	Name (source of information)	NA	Mr. Graikwad	Spertage Sure	
2.	Contact No.	NA	9273773501	935939173	3 9004226866
3.	Type of source of information (Seller/ Property dealer/ nearby people)	NA	Local f property dealer	property derler	Property dealer.
4.	Rates/ Price informed (in Rs. with unit)	NA	1) Residencial Flot: 3.5 K/Sq-FF	Torsait built	2K Per Sq. F 3K industrial p
5.	Rates Type (Sale/ Buy)	NA	7 to 8k per	Buy.	Buy.
6.	Shape of the Property (Square, Rectangular, Irregular)		sq.f. builtup		
7.	Area/ Size of the Property			Aprox 380 sq. Floot	
8.	Legal Status (clear, negative, weak)/ No. of owners		Clear?	Utar	clear
9.	Location/ surrounding/ neighborhood comparison with the subject property (Similar, Lower, Better, Highly Better than the subject Property)	Base Case	Swirounding.	News by to survey sitt.	Swaroundin
10.	Distance from the subject Property	0	within 200 to 300 m.	Aprox 300 to	with IKM to 1.5 Km Bon Shivaii Chowk.
11.	Other factors (Comer, 2 side open, North-East facing, Park facing, Legal/ Financial encumbrance, etc.)		_		
12.	Approach road width		Same	- 1	
13.	Level of Land (Below/ On/ Above road level)		Same	-	e de la company
14.	Frontage to depth ratio (Normal, Less, Large)		Normal	Normal	- ,
15.	Present Use		Communical, Residencial.	Residencial.	Inclustrial / Commercial plo
16.	Any other details/ Discussion held		The Rotes informed are near to survey site. At Shiraji chowk (main chowk). Appox 200m from	_	the said that around shiveying thouse, Bhive and Industrial communational is around
17.	Present expected Sale Value of the overall property?		Survey site, the rate of		2k to 3k per sq.ft. But la
			communial shop of 700 sq. ft builtupis around 25 K/per sq.ft 8		age 13 of 15 will be in vicinity radius of 1 km to 2 km from

Scanned with CamScanner

UNDERTAKING BY THE CUSTOMER

I confirm that I have made the inspection of the subject property to the surveyor of R.K Associates, which is correct property in question for which the documents have been provided/ submitted by me. I further confirm that I am aware of all the information related to the subject property and I have provided all its information to the surveyor true to the best of my knowledge. I understand that any false or manipulative information provided by me will be considered as cheating with the professional organization since it will lead to incorrect valuation report and I'd be solely responsible for this unlawful act and will bear the charges for the changes/modifications which have to undergo due to the false information. I also undertake that I have not given any cash or in kind to any member of R.K Associates to influence the Value of the Property or favor any individual or organization and the same is not accepted or asked by the member of R.K Associates. Any such act will lead to cancellation of the material prepared by R.K Associates with forfeiting of the fees and i'll be completely responsible for its repercussions and legal actions taken for it.

IMPORTANT: We have not authorized any of our person/ Surveyor to take Cash or kind from the customers in any situation. In case Surveyor or any member of R.K Associates asks for any money or kind from you then kindly please inform on number +91-9958632707, 0120-4110117. Our Valuation process is very stringent and have multiple check points to ensure correct & error free reports to keep the lending agency risk free. In case Surveyor claims that he would be able to arbitrary effect the Valuation figures unfairly or as per your requirement & need, then he is making a false claim to you and we request you to complaint such act immediately on the number provided above.

Name	Mr Vachansingh. Bolia.		
Relationship with owner	owner		
Signature			
Mobile No.	9821925508		
Date	09/03/22		

UNDERTAKING BY THE SURVEYOR

I confirm that I have carried out the Survey of the property properly as per the fair professional best practices and Valuation & Survey policy guidelines issued by R.K Associates. I have not taken any cash or kind from the customer nor have I come into any kind of influence of the customer / bank for arbitrary providing the Property Valuation as per one's need. I further state that I have not given any assurances to the customer nor given any wrong or false information or statement. In case at any point of time it is found that I have done any kind of fraudulent activity in this case and misled the company then I understand its legal consequences and appropriate penal action which company can take against me. Also in regard to it any monetary or reputation loss will be recovered from me by the company.

For File No.	VIS (2021-22)-PLIDS4-897-1174
Surveyor Name	Abhishek.s & Diegh B
Signature	a Dedutte.
Date	09/13/22

UNDERTAKING BY THE PREPARER

I confirm that this Valuation Report is prepared as per the fair professional best practices and Valuation & Survey Policy Guidelines issued by the organization. I also confirm that without any personal interest, partiality or prejudice, I have worked on this Valuation assignment. Rates adopted for the asset is based on various facts, information collected from the site came to my knowledge during the course of the assignment and I have taken all sincere efforts to review, cross check & confirm this data/ information from all different angles using my prudent approach without any biasedness or pressure. I have prepared the report based on true facts & information as per best of my knowledge & case facts. I understand that any false information provided by me will lead to the incorrect valuation report and I'd be solely responsible for it and will bear the losses which will be put on the Company in form of monetary or reputation loss by its client or statutory bodies.

I also undertake that I did not come into any influence by the customer, Bank representative (officer or agent), colleagues, coworkers or any other person to arbitrary change the Valuation figures or facts unethically or illegitimately which may put the public money at risk which is in the form of Bank deposits.

In case at any point of time in future, if I am found guilty of illegitimately distorting the facts in the Valuation or any other professional services which company offers in the market on being influenced by the customer or Bank representative (officer or agent) or for whatsoever reason then I'd solely responsible of any such act and I understand that the Company can take appropriate legal action against me which may include suspension from the current roles & responsibilities or termination from the employment with immediate effect.

I also undertake that I have not taken any cash, favor or in kind from the customer for favoring any individual or organization by unfair means.

I also undertake that I'll not prepare any report on incomplete Survey form which is not properly filled as per the Company guidelines and in case I am preparing it which is creating an incorrect report then I'd be responsible for its consequences.

For File No.		
Preparer Name		
Signature		
10-4		
Date	DATE OF THE STATE	



Enclosure: 6

SURVEY SUMMARY SHEET (TO BE ENCLOSED WITH VALUATION REPORT)

(Version 1.0) | Date of implementation: 10.04.2017

Every Valuation report at R.K Associates is prepared based on the thorough survey of the property carried out by our Engineering Surveyor. This Survey Summary Sheet is for the information of Banker/ concerned interested organization. Detailed Survey Form can also be made available to the interested organization in case it is required to cross check what information our surveyor has given in site inspection report based on which Valuation report is prepared.

1.	File No.	VIS (2021-24)-PL	1054-897 -11	74				
2.	Name of the Surveyor		resh.					
3.	Borrower Name	MIS Valentine Tex	offe Co. Put. Ltd					
4.	Name of the Owner	Oil Sal della Sal della Sh						
5.	Property Address which has to be	Shubbara palace Shi Ko	embadrad Kord, brok	ul Nagar, Neur land				
Э.	valued	shivaji chowk Rhamon	Sr. No 46 A/2 CTS	No. 3374, Bhiwand				
6.	Property shown & identified by at	☐ Owner, ☐ Representative,	☐ No one was available, L	Mahoryhta -421				
	spot	could not be done from inside		Contact No.				
		Name	2000	And the Additional Control of the Co				
		Arjun	93220	71000				
7.	How Property is Identified by the	☐ From schedule of the prop	perties mentioned in the	deed, or Front Hame place				
	Surveyor	displayed on the property,	Identified by the owner,	owner representative,				
		Enquired from nearby people,	, \square Identification of the p	roperty could not be done,				
		☐ Survey was not done	☐ Survey was not done ☐ Yes, ☐ No, ☐ No relevant papers available to match the boundaries,					
8.	Are Boundaries matched	☐ Yes, ☐ No, ☐ No rele	evant papers available to	match the boundaries,				
			Boundaries not mentioned in available documents					
9.	Survey Type	Full survey (inside-out with	Full survey (inside-out with measurements & photographs)					
J.			☐ Half Survey (Measurements from outside & photographs)					
		☐ Only photographs taken (No	o measurements)					
10.	Reason for Half survey or only	☐ Property was locked, ☐ Po	ossessee didn't allow to ins	pect the property, \(\square\) NPA				
10.	photographs taken NA	property so couldn't be survey	ed completely					
11.	Type of Property	☐ Flat in Multistoried Apartme	ent, Residential House,	☐ Low Rise Apartment, ☐				
	The state of the s	Residential Builder Floor, Co	ommercial Land & Building	, Commercial Office,				
		Commercial Shop, Commer	rcial Floor, Shopping M	all, Hotel, Industrial,				
		☐ Institutional, ☐ School Buil	lding, 🗆 Vacant Residentia	I Plot, Vacant Industrial				
		Plot, ☐ Agricultural Land						
12.	Property Measurement	☑ Self-measured, ☐ Sample n	measurement, \square No meas	urement				
13.	Reason for no measurement	☐ It's a flat in multi storey bui	ilding so measurement not	required				
13.		☐ Property was locked, ☐ Owner/ possessee didn't allow it, ☐ NPA property so didn't enter the property, ☐ Very Large Property, practically not possible to						
	NA							
		measure the area within limite	ed time \square Any other Reaso	n:				
	Land Association Deposits	As per Title deed	As per Map (9009)	As per site survey				
14.	Land Area of the Property		518 Sq.m					
	a I B. th Area	As per Title deed	As per Map	As per site survey				
15.	Covered Built-up Area	- As per fille deed	-	20,327.04 Ft				
16	Property possessed by at the time of	Owner, U Vacant, Lesse	ee. Under Construction					
16.	survey ·	☐ Property was locked, ☐ Ban	nk sealed, Court sealed					
17.	Any negative observation of the	Building plan not		ng Survey.				
		So are of Buildin	ny calculated, or	site is 1 by				
		C. L. Latil	1 Tables	allian by 1. Co. 2				
		Calculating area of	r louise 4 h	multiply by 4 (on+3)				
		only land down	nent & old waln	ation report available				
		day's Chinas	(00 000					
	during Survey.							

18.	Is Independent access available to the property	Clear independent access is available, Access available in sharing of other adjoining property, No clear access is available, Access is closed due to dispute
19.	Is property clearly demarcated with permanent boundaries?	☐ Yes, ☐ No, ☐ Only with Temporary boundaries permanent boundary
20.	Is the property merged or colluded with any other property	No. On 2 sides, Boundary ut
21.	Local Information References on property rates	Please refer attached sheet named 'Property rate Information Details.'
	property rates	4th side 15

Undertaking: I have shown the correct property and provided the correct information about the property to the surveyor of R.K Associates to the best of my knowledge for which Valuation has to be prepared. In case I have shown wrong property or misled the valuer company in any way then I'll be solely responsible for this unlawful act.

a. 1	Name of the Person:	Vachansingh .	Balia
------	---------------------	---------------	-------

Relation: Signature:

d. Date:

In case not signed then mention the reason for it: \square No one was available, \square Property is locked, \square Owner/ representative refused to sign it, \square Any other reason:

2. Surveyor Signature who did site inspection:

Undertaking: I have inspected the property and cross verified the property details at site to the extent of a. Matching boundaries of the property, b. Sample measurement of its area, c. Physical condition, d. Property rates as per local information with what is mentioned in the property documents provided to me by the Bank/ interested organization. I have not come under influence of anyone during site inspection and have only recorded the true and factual details in the survey form which I come across during the site survey. I understand that giving any manipulative information in the survey form will lead to incorrect Valuation report which is an unlawful act and i'll be solely responsible for doing it.

a. Name of the Surveyor: Abhishek. S & Dipesh. B
b. Signature: Steedatte
c. Date: 09/03/2 L