



## CASE COLLECTION FORM (Version 5.0) Date of implementation: 9.02.2011 | Last Revision: 30.01.2020 | Latest Revision: 31.10.2020

Date of imple	ementation	.UZ.ZU     Last N	VISION.			HOD Frag
Items	Assigned	To Assigned to Date	completed by date	Submitted On date	Grade	HOD Engg. Signature
Received By	Abhishek	·S NA	NA			
ey	Dipesh Bedmutt	ra				
	1.1					
A - Very Good, E	3 - Satisfactor	y, C - Average, D	- Poor, E - Exti	remely Poor	J. Ellad [	Market survey for
. unprepared due	rates is r properly represen	not properly done, done, Photo ntative photo not to the Map not taken,	ographs not c aken, □ Owne □ Survey sum	clearly taken, er/ owner repre mary sheet not	☐ Selfie/ esentative s filled	Owner or owner gnature not taken,
e preparer - HOD . comment &	Surveyor	defects in the sur	vey. Survey has	s to be done ag	jain.	wn.
		GENER	AL DETAILS	7.1	0.00	
Proposal/ Work C	Order or	VIS ( 2	021-22)-	PL 1056 -	899	
Ref. No.						eting portificate
Type of Service	iZ	Valuation Report Other CE Certific	cates,   TEV F	Report, LIE		
Type of customer	<u></u>		□ Private clier	nt Direct	client throu	gh Bank
	ration Ba	ank of Barada	int, Nr. VI	dhan Bhava	n, Mumb	41 4000 4
		Name	Conta	ct Number		inan ia
		Shaileth	880		con	D bank of bevioda.
Case Type		☐ Case for Fres	sh Account	✓ Case fo	or exiting ac	count/ customer
10 Table 10	-	Amount of Fees	Advance Am	nount if any	Fees w	vill be paid by
	1	0,000 f GST	-		✓ Bank	□ Customer
		Billed To P			GS	
	Received By  aration  A - Very Good, Exturned to HOD, unprepared due ason  se File is returned to preparer - HOD, comment & ature  Proposal/ Work Cature  Type of Service  Type of customer  Bank/ FI/ Organiz Name & Address Case Allotment Case	Received By  Assigned  Received By  Abhishek  A - Very Good, B - Satisfactor  Returned to HOD  unprepared due ason  Beginnth  Goog  See File is returned preparer - HOD  comment & ature  Proposal/ Work Order or Ref. No.  Type of Service  Type of customer  Bank/ Fl/ Organization Name & Address  Case Allotment Officer/ Fees paying party Details  Case Type  Fees Details	Received By  Assigned To Received By  Abhishek 'S  NA  A - Very Good, B - Satisfactory, C - Average, D Returned to HOD  unprepared due ason  See File is returned properly done, Photorepresentative photo not to Google Map not taken,  See File is returned Major defects in the Surveyor. Report preparer Proposal/ Work Order or Ref. No.  Type of Service  Type of customer  Bank/ FI/ Organization Name & Address  Case Allotment Officer/ Fees paying party Details  Assigned to Date  NA  Assigned To  NA  Assigned To  NA  Sequently  Survey not done properates in the properates in the Surveyor. Report preparer  Case Allotment Officer/  Name  Shailath  Case Type  Case Type  Case for Fres	Received By  Abhishek 'S  NA  NA  A - Very Good, B - Satisfactory, C - Average, D - Poor, E - Extractery are son  Returned to HOD  unprepared due ason  See File is returned by done, Songle Map not taken, Survey sum son  See File is returned by done, Songle Map not taken, Survey sum son  See File is returned by done, Survey honce or Report preparer to collect the major defects in the survey. Survey have some some solution of the survey. Survey have some some see File is returned by done, Major defects in the survey hence of Surveyor. Report preparer to collect the major defects in the survey. Survey have some some solution of the survey. Survey have some some solution of the survey. Survey have so survey have some solution of the survey. Survey have some solution of the survey. Survey have some solution of the survey have solution of the survey survey. Survey have solution of the survey	Received By	Items

表記書		CASE DETAILS						
1.	Type of Property	commercial office	0 00	nit				
2.	Purpose of Valuation/	☐ Value assessment of the asset for creating new collateral mortgage						
	Assignment	Periodic Re-Valuation for Ba	ank, 🗆 D	istress sale fo	r NPA A/c.,			
		☐ For DRT Recovery purpose,						
		☐ Partition purpose, ☐ Genera						
		☐ Any other:						
3.	Owner/ Applicant Details	Name	Contac	t Number	Email Id			
		SMC Inprastructures	Praka	sh · shelar				
		Put - Ltd	8 65	7913566				
4.	Account Name	M/S SMC Infrastruc						
5.	Property Address	Final Plot No. 441 Akruti SMC Buildin Distr Thane - 400601	Unit	No. 101	First Floor,			
		ARRITI SMC Ruildis	a bl	anat vil	lace Panthoak hadi			
		Distr Thank - 400601	10, 1	in pact, "	roge Timent Trans			
6.	Who will coordinate on	Name		Co	ntact Number			
	site for the site survey	i) Prakash shelar		8657913	3566			
		2) Sudhir Athavale		022 25	5334143			
7.	Preferred time of survey	Date 09/03/2022		Time     1   1	45 pm			
8.	Documents Received (Any one ownership document	1. Ownership Documents:			Control of the Contro			
	and approved site plan/ map is	☐ Registered Will, ☐ Reling	CONTRACTOR CONTRACTOR CONTRACTOR					
Silen	must)	☐ Conveyance Deed, ☐ Allotment Letter, ☐ Possession Letter						
		<ol> <li>Map: □ Cizra Map, □ Approved Map, □ Site Plan</li> <li>Utility Bills: □ Electricity Bill &amp; payment receipt, □ Water Bill &amp; payment</li> </ol>						
		receipt,  House Tax demand & payment receipt						
		4. Any Other document: □ C			Agreement to Sale,			
		☐ Old Valuation Report			unent			
		5. No documents provided:		0				
9.	Documents received							
	from	Customer		na magazina ana				
10.	Special Instructions if any:							
11.		entioned above for the preparation of						
		facts and would not try to influence any individual or organization by any			or the firm in the ill spirit or			
	vosted interest and to benefit	any maividual of organization by any	y means i	подішналету.				
	Customer Signature:							

	FILE RECEIVER CASE COLLECTION PROCESS COMPLIANCE CHECKLIST  (To be filled by Surveyor)							
S.NO.	COMPLIANCE CHECKLIST	STATUS	APPROVER SIGNATURE/ REMARKS IN CASE OF ANY (X)					
1.	Is Case collection Form properly filled by Receiver?	Ø						
2.	Is purpose of the assignment understood clearly by the receiver?							
3.	Has receiver checked if this is a new case or existing case of the Bank?	N N						
4.	Has receiver fixed the fees with the manager/ client and sent quotation properly or have taken approval of the work over email?							
5.	Has receiver taken proper Work Order/ Email/ CESA form formality?	<b>y</b>						
6.	In case of private case or for fresh case 50% advance is received?							
7.	Is document checklist email sent to the customer?							
8.	Has the received documents is having 'documents provided by stamp'?							

#### IMPORTANT INSTRUCTIONS TO SURVEYOR

1.	Please fill the above compliance checklist before moving for the survey.
2.	Please do not do the survey if you do not have proper documents.
3.	For Vacant Plot/ Land – Cizra Map/ Master/ Zonal/ Site Plan is must to identify the Plot. For Agriculture or converted land from agriculture – Mutation documents, CLU is must.
4.	Firstly please first study the documents of the property which needs to get surveyed.
5.	Mark the Owner/ Area/ Boundaries mentioned in the ownership documents with bold florescent marker pen before moving for the survey. During site survey if any difference is found in the above fields from the ownership documents then please contact the owner immediately to know the reason for the difference.
6.	Confirm ongoing property rates in the subject location through public domain, property sites and contact dealers to show you the available properties in that area during your survey.
7.	Identify the Property clearly by matching the boundaries and area mentioned in the property papers.
8.	Do sample physical or google measurements of the property.
9.	a. Take owner/ representative photograph along with the property. b. Take your selfie along with the property and the owner/ representative. c. Take full scale photo of the property with gate. d. Take photo of the property along with abutting road, towards left, right and center. e. Take multiple photos of inside-out of the property. f. Take nearby photographs of the Property. g. Take a short video to cover property and neighborhood.
10.	Take Google Map location.
11.	Check main road name & width and approach road width and distance of property from main road.
12.	Check Jurisdiction Municipal Limits & Ward Name.
13.	Fill each column of survey form diligently in detail and tick the appropriate option clearly.
14.	Check any defects or negativity in the property and comment in detail on survey form.
15.	Do extensive market rate enquiries and confirm for any recent past transactions.
16.	In case customer appears to be providing misleading information to you or trying to influence you by money or cash then immediately report to the Management & Bank.

A COMM	SURVEY GRADING MATRIX							
RADE	PARAMETERS/ CRITERIA							
A	In case all the points below are done properly, timely with full care and diligence:							
	<ol> <li>Survey started with proper work order and knowing the source of payment.</li> <li>Survey done with proper documents.</li> <li>Done complete homework and studied the documents properly with highlighting the main points before moving for the survey.</li> <li>Chosen correct survey form as per the property type.</li> <li>All fields of Survey form are properly filled.</li> <li>All site special observations and negative and positive factors are clearly mentioned.</li> <li>Self &amp; client signatures taken on survey form.</li> <li>Property rates information properly taken, mentioned and verified.</li> <li>Site rough sketch plan made.</li> <li>Proper photographs taken.</li> <li>Selfie with property taken.</li> <li>Selfie and owner photograph with property taken.</li> </ol>							
В	In case of 3 minor mistakes in any of the above points except Point 1, 2, 3, 4, 6, 8, 10, 11, 12 but all the points are covered.							
С	In case of more than 3 minor mistakes and any 1 major mistake in any of the above points and if any points are completely missing except Point 1, 2, 3, 4, 6, 8, 10, 11, 12.							
D	In case of 1 major mistake or missing of any 1 point out of 1, 2, 3, 4, 6, 8, 10, 11, 12.							
E	In case of more than 1 major mistakes or missing of more than 1 point out of 1, 2, 3, 4, 6, 8, 10, 11, 12.							

Note (Survey Grading Matrix):

- For special assignments like LIE, Stock Valuation, etc. where till date survey format is not specified or released, in such cases point wise site observation report has to be submitted by the Surveyor duly signing it properly. Without signed Site Observation report, Point 4 will be considered as not done and will fall under Category E.
- 2. Similar Grading Matrix is issued for Case Collection & Report Preparation as well.

Note (Overall Grading Matrix):

1. In case client reports any careless mistake in the report for which revision has to be done in the report then in that case Grading Matrix may be revised and Grade E will be awarded.

1000	SURVEY PROCESS COMPLIANCE CHECKLIST					
(To be submitted by Surveyor with each Survey)						
S.NO.	COMPLIANCE CHECKLIST POINTS	STATUS				
1.	Did you take proper property documents to carry out the survey?	A				
2.	Have you properly studied & highlighted Owner/ Area/ Boundaries in the property documents with bold florescent before moving for the survey?					
3.	Did you check prominent landmark nearby the subject property and mentioned in the survey form?					
4.	Did you identified the Property clearly by matching the boundaries and area mentioned in the property papers?					
5.	Did you check if property is merged with any other property or it is an independent property?	A				
6.	Did you do sample physical or google measurements of the property in case of property more than 2500 sq.mtr?					
7.	Did you check for any building violations in the property?					
8.	Did you check municipal limits/ jurisdiction/ ward?	II.				
9.	Did you take Google Map location and shared it to Maps whatsapp group?					
10.	Did you check Main road name & width and its distance from the subject property?					
11.	Did you check approach Lane width on which property is located?					
12.	Have you taken property full scale photograph with gate?					
13.	Have you taken owner/ representative photograph with the property?					
14.	Have you taken your selfie with the property along with owner/ representative?	<b>A</b> A				
15.	Have you taken photograph of the property along with abutting road and towards left and right of the property?					
16.	Have you taken multiple photographs of the property from inside-out?	A				
17.	Did you check nearby development and whereabouts and commented on survey form?					
18.	Did you check any defects or negativity in the property in terms of location, legality, disputes, marketability, salability, etc. and commented on survey form in detail?					
19.	Have you filled all the columns of survey form including survey summary sheet properly?					
20.	Did you draw site key plan (location map)?					
21.	Did you draw rough site sketch plan?					
22.	Have you taken self-attested documents from owner/ representative and stamped "documents provided by stamp"?					
23.	Did you check any defects or negativity in the property in terms of location, legality, disputes, marketability, salability, etc. and commented on survey form in detail?					
24.	Have you confirmed any recent past transactions during market enquiries and enquired property rates locally very rigorously?					
25.	Did you take signatures of the owner/ representative on undertaking and survey summary sheet?	Ź				
26.	Did you signed the undertaking?	VÓ				

For File No.	VIS (2021-22) - PL 1056 - 899
Surveyor Name	Dipeth Bedmutha
Signature	DeBedmetha -
Date	09/03/22

# GENERAL SURVEY FORM (FOR PROPERTIES OTHER THAN FLATS) (Version 5.0) Date of implementation: 9.02.2011 | Last Revision: 04.01.2018 | Latest Revision: 31.10.2020

File No. RKA/DNCR//	Date:	09/03/22	Time:	11.45pm	
FILE INO. INTOVIDING INT	Date.	1/05/			

		GENERAL DETAILS	1000000 ASSESSED (1980) 1980 ASSESSED (1980) 1980 ASSESSED (1980) 1980 ASSESSED (1980) ASSESSED (1980) ASSESSED				
1.	Name of the Surveyor	Dipush Bedmutha					
2.	Property shown by	☐ Owner, ☐ Representative, ☐ No one was available, ☐ Property is					
		locked, survey could not be done from inside					
		Name Contact No.					
		1) Prakash Shelar 2) Sudhix Athanale	8657913566				
3.	Survey Type		surements & photographs)				
	Sample Measwemen	Half Survey (Measurements from	m outside & photographs)				
	Survey Type Sample Measurement from Insite & Complete photos of office	☐ Only photographs taken (No me	easurements)				
4.	Reason for Half survey or only	☐ Property was locked, ☐ Poss	sessee didn't allow to inspect the				
	photographs taken was .	property, ☐ NPA property so could	n't be surveyed completely				
5.	How Property is Identified	☐ From schedule of the properties	es mentioned in the deed, V From				
		name plate displayed on the pro	perty, Identified by the owner/				
		owner representative, ☐ Enquired	from nearby people,				
		☐ Identification of the property con	uld not be done, □ Survey was not				
		done					
6.	Type of Property		☐ Residential House, ☐ Low Rise				
		Apartment,   Residential Builder Floor,   Commercial Land					
		Building, ☐ Commercial Office, ☐ Commercial Shop, ☐ Comm					
		Floor, □ Shopping Mall, □ Hotel, □ Industrial, □ Institutional,					
		☐ School Building, ☐ Vacant Residential Plot, ☐ Vacant Industrial					
		Plot,  Agricultural Land					
7.	Property Measurement	V	surement only,   No measurement				
8.	Reason for no measurement	☐ It's a flat in multi storey building					
	large office	☐ Property was locked, ☐ Owner/	/ ~				
	Large Office (Sample Measurement taken)		e property, Very Large Property,				
	+aken		ure the entire area □ Any other				
		Reason:					
9.	Purpose of Valuation	□ Value assessment of the asset t	for an otime and all the land				
9.	Fulpose of Valuation	Periodic Re-Valuation for Bank,	for creating new collateral mortgage				
1 7 8			Capital Gains Wealth Tax purpose				
		☐ Partition purpose, ☐ General V					
10.	Type of Loan		e Over Loan,   Home Improvement				
10.	Business loan		Construction Loan,   Educational				
	Dusines		oan, ☐ Term Loan, ☐ CC Limit				
		enhancement, □ Cash Credit Limit					
11.	Loan Amount	The state of the s	.,				
100							

-	。	OWNERSHIP DETAILS
1.	Legal Owner Name/s	SMC Infrastructures Pvt. Ltd
2.	Property Purchaser Name	SMC Infrastructures Put. Ltd.
3.	Property Address under	
	Valuation	Final Plot. No 441, Unit No. 101, First Flors, ARRUH'SMC Building, Khopat, Village, Panchpakhdi,
4.	Present Residence Address of	Dist. Thank, 400601.
	the Owner/ Purchaser	
5.	Property constitution	☐ Free Hold, ☐ Lease Hold

<u>LOCATION DETAILS</u>							
Adjoining Properties	East	The state of the s	West		orth	South	
(Match it with papers with the help	Doit NO.	Bu	Iding	at V	ibjoyer	Lal Bahadur	
of compass or Sun direction and		u	mpound,	of	fice .	Shastri Road	
also confirm it with nearby people)		Int	ernal Road	· (unit 1	6.101 A)		
Property Facing \$ \$\tau \times \times	☐ East Faci	ng, 🗆 Nort	h Facing, □	West Fac	ing, 🗆 Sout	th Facing,	
	☑ North-Eas	st Facing, [	☐ South-We	est Facing,	☐ South-E	ast Facing,	
E   h	The same of the sa						
Landmark	MSRTC	Bus	depot	Works	rop.		
Ward Name/ No.	-						
Zone Name							
Main Road Name & Width		ne	Wie	dth	Distance 1	from property	
Lal Bahadur Sharts	Rd/ Khopa	it Rd.	Aprox	40-45	Buildie	ng Road Taxel	
Approach Road Name & Width				€ <del>L</del>		1	
Location consideration of the	Within Ma	ain city, 💆	Within God	od Urban o	developed A	Area, □ Within	
Society		_					
	Ordinary,		iois, 🗆 ivei	note area,	_ Dackwar	u, 🗆 / Weldge,	
	□ Poor			,			
	☐ Park Facing, ☐ Pool Facing, ☐ Road Facing, ☐ Entrance North-						
Special Location consideration	☐ Park Fac	ing, 🗆 Po	ol Facing, [	Road F	acing, □ E	ntrance North-	
Special Location consideration of the property	La Markette and Comban		Automotive to the state of		acing, 🗆 E	ntrance North-	
of the property	East Facing,	☐ Sunligh	t facing	Buil	ding.		
	East Facing,  Urban dev	☐ Sunligh	t facing Urban deve	لگيرا eloping, □	ding.		
of the property	East Facing,	☐ Sunligh	t facing Urban deve	لگيرا eloping, □	ding.		
of the property	East Facing,  ☐ Urban dev  ☐ Backward,	□ Sunligh veloped, □ , □ Industri	t facing Urban deve ial, □ Institu	કુર્પો eloping, □ utional	dൂറു Semi Urbar		
of the property  Characteristics of the locality	East Facing, Urban dev Backward, High End, MIG, D L	□ Sunligh veloped, □ , □ Industri , □ Normal	t facing  Urban deve ial, □ Institu , □ Afforda	ßั้นใ eloping, □ utional ble Group	dเ๊าสู่ • Semi Urbar Housing, □	n, □ Rural,	
of the property  Characteristics of the locality	East Facing, Urban dev Backward, High End, MIG, L	□ Sunligh veloped, □ , □ Industri , □ Normal IG sarden, □ t	t facing  Urban deve ial, □ Institu , □ Afforda  andscaping	Buil eloping, □ utional ble Group g, □ Swim	dົ້າຊີ ' Semi Urbar Housing, □ ming Pool, [	n, □ Rural, EWS, □ HIG, □ Gym,	
of the property  Characteristics of the locality  Category of Society/ locality	East Facing, Urban dev Backward, High End, MIG, L Lifts, G	□ Sunligh veloped, □ , □ Industri , □ Normal IG sarden, □ t	t facing  Urban deve ial, □ Institu , □ Afforda  andscaping	Buil eloping, □ utional ble Group g, □ Swim	dົ້າຊີ ' Semi Urbar Housing, □ ming Pool, [	n, □ Rural,	
of the property  Characteristics of the locality  Category of Society/ locality  Utilities/ Facilities in the locality	East Facing, Urban dev Backward, High End, MIG, L Lifts, G Club Hou Backup	Sunlight veloped, □ Industrict Normal IG Sarden, □ Sarde	t facing  Urban develoal, □ Institu , □ Afforda  andscaping	Buildeloping, □ utional ble Group g, □ Swim □ Kids pla	Housing, □ ming Pool, [ y zone, ✓	n, □ Rural, EWS, □ HIG, □ Gym, 100% Power	
of the property  Characteristics of the locality  Category of Society/ locality	East Facing, Urban dev Backward, High End, MIG, L Lifts, G Club Hou Backup School	Sunlight veloped, □ , □ Industrict Normal IG arden, □ to use, □ Wa	t facing  Urban deveraged in the control of the co	Buildeloping, □ utional ble Group g, □ Swim □ Kids pla	dາົດຊູ້ Semi Urbar Housing, □ ming Pool, [ y zone, ☑ Railway Sta	n, □ Rural, □ EWS, □ HIG, □ Gym, □ 100% Power	
of the property  Characteristics of the locality  Category of Society/ locality  Utilities/ Facilities in the locality  Proximity to civic amenities	East Facing, Urban dev  Backward, High End, MIG, L Lifts, G Club Hou Backup School  180 m	Sunlight veloped,  Industrict Normal IG Sarden,  Wase,  Wase,  Wase Hospital	t facing  Urban development  ial, □ Institut  , □ Affordat  andscaping  alk Trails, □  Market  700 m	Buildeloping, □ utional ble Group g, □ Swim □ Kids pla	Housing, Demi Urbar	n, □ Rural,  I EWS, □ HIG,  □ Gym,  I 100% Power  ation   Airport	
of the property  Characteristics of the locality  Category of Society/ locality  Utilities/ Facilities in the locality	East Facing, Urban dev Backward, High End, MIG, L Lifts, G Club Hou Backup School	Sunlight veloped,  Industrict Normal IG Sarden,  Wase,  Wase,  Wase Hospital	t facing  Urban deverage ial, □ Institut , □ Afforda  Landscaping alk Trails, □  Market  700 m	Buildeloping, Dutional ble Group g, D Swim Kids pla	Housing, Deming Pool, In y zone, Deming Pool, In y zon	n, □ Rural,  I EWS, □ HIG,  □ Gym,  I 100% Power  ation   Airport  1 2 3 Km  Mumbi	
of the property  Characteristics of the locality  Category of Society/ locality  Utilities/ Facilities in the locality  Proximity to civic amenities	East Facing, Urban dev  Backward, High End, MIG, L Lifts, G Club Hou Backup School  180 m	Sunlight veloped,  Industrict Normal IG Sarden,  Wase,  Wase,  Wase Hospital	t facing  Urban development  ial, □ Institut  , □ Affordat  andscaping  alk Trails, □  Market  700 m	Buildeloping, □ utional ble Group g, □ Swim □ Kids pla	Housing, Daniel Housing, Danie	n, □ Rural,  I EWS, □ HIG,  □ Gym,  1 100% Power  ation   Airport	
	of compass or Sun direction and also confirm it with nearby people)  Property Facing Sunday Sunday Sunday Shark Sh	of compass or Sun direction and also confirm it with nearby people)  Property Facing	Property Facing   Bast Facing, North-East Facing, North-East Facing, North-West Facing North-West Faci	Property Facing ☐ East Facing, ☐ North Facing, ☐ North-East Facing, ☐ South-West Facing  Landmark  Ward Name/ No.  Zone Name  Main Road Name & Width  Lo1 Bahaduh Shasha  Approach Road Name & Width  Location consideration of the  Society  □ Ordinary, ☐ In interiors, ☐ Ren	Property Facing ☐ East Facing, ☐ North Facing, ☐ West Facing, ☐ North-East Facing, ☐ South-West Facing, ☐ North-West Facing, ☐ North-East Facing, ☐ South-West Facing, ☐ North-East Facing, ☐ North-East Facing, ☐ North-East Facing, ☐ North-East Facing, ☐ South-West Facing, ☐ North-East Facing, ☐ North-E	of compass or Sun direction and also confirm it with nearby people)  Property Facing  □ East Facing, □ North Facing, □ West Facing, □ South-West Facing, □	

/								
<i>δ</i> .	Jurisdiction limits	☐ Nagar Nigam, ☐ Na	igar Panchayat, □ Gran	n Panchayat, □ Nagar				
/	Thank Municipal Corporation	Palika Parishad, ☐ Area	Palika Parishad, □ Area not within any municipal limits					
16.	Jurisdiction Development	$\square$ DDA, $\square$ GDA, $\square$ NOIDA, $\square$ GNIDA, $\square$ YEIDA, $\square$ HUDA, $\square$ KMDA,						
	Authority Name	☐ MDDA, ☐ Any other	Development Authority:					
	Thank runicifal corporation.	☐ Area not within any d	evelopment authority limi	its				
17.	Municipal Corporation Name	□ NDMC, □ SDMC, □	] EDMC, □ Ghaziabad	Municipal Corporation,				
	Thank Municipal	☐ Gurgaon Municipal C	orporation, 🏻 Faridabad	Municipal Corporation,				
	Thank Municipal Corporation.	☐ Kolkata Municipal Corporation, ☐ Dehradun Municipal Corporation,						
			ny municipal limits, 🗆					
		Corporation/ Municipality						
1	Land Area	PHYSICAL DETAIL As per Title deed	As per Map	As per site survey				
1.	Land Alea	As per title deed						
0	Any conversion to the land use							
2.	Any conversion to the land use	NA .						
3.	Land Type	Solid, ☐ Rocky, ☐ Marsh Land, ☐ Reclaimed Land, ☐ Water						
		logged, □ Land locked						
4.	Shape of the Land	☐ Square, ☐ Rectang	ular, 🛘 Trapezium, 🗘 Tr	riangular, □ Trapezoid,				
		☐ Irregular, ☐ NA						
5.	Level of Land	☐ On road level, ☐ Be	elow road level, 🛭 Above	road level, □ NA				
6.	Frontage to depth ratio	☐ Normal frontage, ☐	Less frontage, Large	frontage, □ NA				
7.	Are Boundaries matched	☐ Yes, ☐ No, ☑	No relevant papers av	vailable to match the				
		boundaries,   Boundaries	aries not mentioned in ava	ailable documents				
8.	Is Independent access available	Clear independent	access is available, [	Access available in				
	to the property	sharing of other adjoin	ning property,   No cle	ar access is available,				
		☐ Access is closed du						
9.	Is property clearly demarcated with permanent boundaries?	✓ Yes, □ No, □ Only	with Temporary boundar	ries (Steel Fencing				
10.	Is the property merged or	No.						
	colluded with any other property		□ Lossoo □ Under Co	postruction \( \subseteq \text{Couldn't} \)				
11.	Property possessed by at the time of survey	☐ Owner, ☐ Vacant, ☐ Lessee, ☐ Under Construction, ☐ Couldn't be Surveyed, ☐ Property was locked, ☐ Bank sealed, ☐ Court						
		sealed						
12.	Current activity carried out in the		ose, ☑ Commercial p □ Vacant, □ Locked, □					
	property	Unice, Difficultial,	_ vacant, _ conca, c	,				
	and the second line of the secon	V OO VOTELLOTION						
		CONSTRUCTION/U		<b>以新闻的《新闻》</b>				
1.	Construction Status	Built-up property i	n use,   Under construc	ction,   No construction				

1	Covered Built-up Area	☐ Covered Area, ☐	Floor Area,   St	uper Are	a, Carpet Area	
1		As per Title deed	As per Ma	р	As per site survey	
	(Tick one on the basis of which valuation is to be calculated)	1085.40 m2	-		7895, 3 Ft	
3.	Total Number of Floors in the Building	Basement +	W + 3 F	loves		
4.	Floor on which property is situated	13+ Floor.			1)	
5.	Type of Unit/ Number of Rooms/ Cabins/ Cubicles	Multiple T	abin (pla	n Ser	it on email)	
6.	Building Type	RCC Framed Str	ucture,   Load	bearing	Pillar Beam column,	
		☐ Ordinary brick wa	Il structure,   Ir	ron truss	es & Pillars,   Scrap	
7.	Roof	a. Make: □ RBC, Patla	RCC, GI	Shed, □	] Tin Shed, □ Stone	
		h Height:	11.73 ft			
	Contract to the second	c Finish:  Simp	le plaster.   F	POP Pui	nning, POP False	
		O-III TV Could	roof   No plas	ter		
8.	Flooring	Uitrified tiles, ☐ Ceramic Tiles, ☐ Simple marble, ☐ Marble chips, ☐ Mosaic, ☐ Granite, ☐ Italian Marble, ☐ Kota stone, ☐ Wooden, ☐ PCC, ☐ Imported Marble, ☐ Pavers, ☐ Chequered Tiles, ☐ Brick Tiles, ☐ No Flooring, ☐ Under construction, ☐ Any other type: ☐ Internal - ☐ Excellent, ☐ Very Good, ☐ Good, ☐ Ordinary,				
	Appearance/Condition of the	Internal - D Excel	ent 🗆 Very G	Good. $\square$	Good, ☐ Ordinary,	
9.	Appearance/ Condition of the	□ Average, □ Poor	□ Under constru	ction.	No Survey	
	Building	Average,   Foor	lant Very G	and $\square$	Good, ☐ Ordinary,	
		□ Average, □ Poor	☐ Under constru	ction		
10.	Maintenance of the Building	✓ Very Good, ✓ Ave	erage,  Poor,	Under (	construction	
11.	Interior decoration	☐ Excellent ☐ Ve	ry Good, G	ood, 🗆	Simple, ☐ Ordinary,	
11.	Interior decoration	☐ Average, ☐ Below	average, 🗆 Und	der const	truction,   No Survey	
12.	Interior Finishing	Simple plastered walls,   Brick walls without plaster,				
	Maril Control of the Property	☐ Designer textured walls, ☐ POP punning, ☐ Coved roof,			Coved roof,	
		□ Under construction	, □ No Survey			
13.	Exterior Finishing				alls without plaster,	
					Brick lile Cladding,	
		☐ Structural glazing,				
		☐ Glass façade, ☐ ☐	omb, L Porch, I	Under	construction Normal	
14.	Kitchen	Modular with chimner	/ THich end M	lodular w	cupboard, □ Normal rith chimney, □ Under	
		construction, □ No S		o daidi ii	, 0	
15.	Class of Electrical fittings	External, Intern				
13.	Class of Electrical fittings			Fancy lig	ghts,   Chandeliers,	
		☐ Concealed lightning				
16.	Class of Sanitary/ Plumbing &	✓ External, ✓ Intern	al			
	water supply fittings	☐ Excellent, ☐ Very	Good, Good,	☐ Simpl	le, □ Average,	
		☐ Below average, ☐ Under construction, ☐ No Survey				
17.	Water arrangements	☐ Jet pump, ☐ Subr	nersible, 🗸 Jal b	oard sup	oply	
18.	Fixed Wooden Work				Simple, ☐ Ordinary,	
		☐ Average, ☐ Below	/ Average, ⊔ No	wooden	work, ⊔ No survey	
19.	Age of Building/ Recent	Aprox 14 year	N -	_		
	Improvements done					
20.	Maintenance of the Building	☐ Very Good, ☐ Ave	rage, $\square$ Poor			

. /	16 1 2 11 1 11 11				
1.	Any defects in the building	☐ Maintenance issues, ☐ Finishing issues, ☐ Seepage issues,			
	NO.	☐ Water supply issues, ☐ Electricity issues, ☐ Structural issues,			
1		☐ Visible cracks in the building			
22.	Any violation done in the property	☐ Construction done without Map, ☐ Construction not as per			
22.	, any and an are property				
	No.	approved Map, ☐ Extra covered without sanctioned Map, ☐ Joined			
		adjacent property,   Encroached adjacent area illegally			
23.	Boundary Wall (Only for individual	☐ Yes, ☐ No, ☐ Common boundary wall of a complex			
	property)	Running Mtr. Height Width Finish			
24.	Lift/ elevators	□ Passenger/ □ Commercial			
	4 lifts.	Make: City lifts, Capacity: 15 people			
		1020kg.			
25.	Power backup	☑ Inverter, ☑ DG Set			
		Make: Capacity:			
26.	Garden/ Landscaping	☐ Yes,, ☑ No, ☐ Beautiful, ☐ Ordinary			
27.	Parking facilities	☐ Available within the property ☐ On Ground, ☐ In Basement,			
21.	Tarking racinges	☐ On stilt			
		☐ Not available within the ☐ On road, ☐ Acute parking			
		property			
28.	Special Comments/ Observations,	Earlier Name of Building was Akruti			
	if any	smc Building.			
		No 1 1 1 1 CMC Co			
		Now Name of Building is SMC Square. They have 21 parkings I'm bosement.			
ais Filitaria ka					
的连续联	是我们是在对于这一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个	LITY/ SELABILITY/ UTLITY DETAILS			
1.	Any issues in marketability of the	☐ Yes, ☐ No			
	property?	Reason in case of No: La Location, La Surrounding, La Legal			
		Reason in case of No: ☐ Location, ☐ Surrounding, ☐ Legal aspects, ☐ Demand, ☐ Shape, ☐ Any Other:			
2.	How is Demand & Supply condition				
	in the Market of such properties?	Supply ☐ Very Good, ☐ Good, ☐ Average, ☐ Low, ☐ Poor			
3.	Is property easily sellable &	∠ Yes, □ No			
	marketable?	Comments:			
4.	How is the current utility of the	☐ Excellent, ☐ Very Good, ☐ Good, ☐ Average, ☐ Low, ☐ Poor			
-	property?	Year of purchase			
5.	At what True rate Owner bought this Property?				
	una rioperty:	Purchase Price -			
6.	Present expected Sale Value of the				
	overall property?				

#### BLANK PAGE FOR PROVIDING ANY ADDITIONAL DETAILS/INFORMATION

Measurement:

I) Width= 11.18 ft + 65.92 ft. = 77.1 ft

length= 68.88 ft + 15.91 ft. = 84.79 ft

Height= 11.73 ft.

Area 1= 6537.30 ft<sup>2</sup>

Area 1= 6537.30 ft.

Labin unit length= 31.90 ft.

Area 2 = 1358.3 ft<sup>2</sup>

Area 2 = 1358.3 ft<sup>2</sup>


NOTE: - 1) Earlier bailding name was
Akouti SMC building.

Now the name has changed to

SMC Square.

2) Total 21 parkings as in basement

for their office unit.



Page 12 of 15

.No	Particulars	Subject	Comparable 1	Comparable 2	Comparable 3
	Name (source of	Property NA	C 1	N	0 ,
1.	information)	INA	Sweesh	Jogesh	Ravi
2.	Contact No.	NA	9082365475	9664540000	927377350
3.	Type of source of information (Seller/ Property dealer/ nearby	NA	property	property dealer	Property de
4	people) Rates/ Price informed	NA		Aprox	14× to 15 K
4.	(in Rs. with unit)	INA	15K to 16K/ carpet area	Aprox 14K to 16K carpet area	poi sq. At
5.	Rates Type (Sale/ Buy)	NA	Buy.	Bruy,	Buy.
6.	Shape of the Property (Square, Rectangular, Irregular)		-	-	
7.	Area/ Size of the Property		5000 to 6000 Sq. ft carpet	5000 to 6000 ex2 carpet.	4000 to 5000 sq. ft carpet
8.	Legal Status (clear, negative, weak)/ No. of owners	ALTERNATION OF THE STREET, STR	Clear	clear	clear
9.	Location/ surrounding/ neighborhood comparison with the subject property (Similar, Lower, Better, Highly Better than the subject Property)	Base Case	Same building.	Same building.	similar (sworounding to survey site)
10.	Distance from the subject Property	0	Same building	Same building	& near by.
11.	Other factors (Comer, 2 side open, North-East facing, Park facing, Legal/ Financial encumbrance, etc.)		— · · ·		
12.	Approach road width		Same	Same	Same
13.	Level of Land (Below/ On/ Above road level)		Same	Same	Same
14.	Frontage to depth ratio (Normal, Less, Large)		Same,	Same	Same
15.	Present Use		Connerval	commercial	connerv'al
16.	Any other details/ Discussion held	NA	-	depending upon if office is furnished or write	Around 15K/
17.	Present expected Sale Value of the overall property?			from 14k to 16 K per sq.fl- corpet.	

#### UNDERTAKING BY THE CUSTOMER

I confirm that I have made the inspection of the subject property to the surveyor of R.K Associates, which is correct property in question for which the documents have been provided/ submitted by me. I further confirm that I am aware of all the information related to the subject property and I have provided all its information to the surveyor true to the best of my knowledge. I understand that any false or manipulative information provided by me will be considered as cheating with the professional organization since it will lead to incorrect valuation report and I'd be solely responsible for this unlawful act and will bear the charges for the changes/ modifications which have to undergo due to the false information. I also undertake that I have not given any cash or in kind to any member of R.K Associates to influence the Value of the Property or favor any individual or organization and the same is not accepted or asked by the member of R.K Associates. Any such act will lead to cancellation of the material prepared by R.K Associates with forfeiting of the fees and i'll be completely responsible for its repercussions and legal actions taken for it.

IMPORTANT: We have not authorized any of our person/ Surveyor to take Cash or kind from the customers in any situation. In case Surveyor or any member of R.K Associates asks for any money or kind from you then kindly please inform on number +91-9958632707, 0120-4110117. Our Valuation process is very stringent and have multiple check points to ensure correct & error free reports to keep the lending agency risk free. In case Surveyor claims that he would be able to arbitrary effect the Valuation figures unfairly or as per your requirement & need, then he is making a false claim to you and we request you to complaint such act immediately on the number provided above.

Name	Prakash Shelar		
Relationship with owner	Employee		
Signature	Peph.		
Mobile No.	8657913566		
Date	09/03/22		

#### UNDERTAKING BY THE SURVEYOR

I confirm that I have carried out the Survey of the property properly as per the fair professional best practices and Valuation & Survey policy guidelines issued by R.K Associates. I have not taken any cash or kind from the customer nor have I come into any kind of influence of the customer / bank for arbitrary providing the Property Valuation as per one's need. I further state that I have not given any assurances to the customer nor given any wrong or false information or statement. In case at any point of time it is found that I have done any kind of fraudulent activity in this case and misled the company then I understand its legal consequences and appropriate penal action which company can take against me. Also in regard to it any monetary or reputation loss will be recovered from me by the company.

For File No.	VIS (2021-22)-PL1056-899
Surveyor Name	Dipesh Bedmutha
Signature	Disedmenths
Date	09/03/22

#### UNDERTAKING BY THE PREPARER

I confirm that this Valuation Report is prepared as per the fair professional best practices and Valuation & Survey Policy Guidelines issued by the organization. I also confirm that without any personal interest, partiality or prejudice, I have worked on this Valuation assignment. Rates adopted for the asset is based on various facts, information collected from the site came to my knowledge during the course of the assignment and I have taken all sincere efforts to review, cross check & confirm this data/ information from all different angles using my prudent approach without any biasedness or pressure. I have prepared the report based on true facts & information as per best of my knowledge & case facts. I understand that any false information provided by me will lead to the incorrect valuation report and I'd be solely responsible for it and will bear the losses which will be put on the Company in form of monetary or reputation loss by its client or statutory bodies.

I also undertake that I did not come into any influence by the customer, Bank representative (officer or agent), colleagues, coworkers or any other person to arbitrary change the Valuation figures or facts unethically or illegitimately which may put the public money at risk which is in the form of Bank deposits.

In case at any point of time in future, if I am found guilty of illegitimately distorting the facts in the Valuation or any other professional services which company offers in the market on being influenced by the customer or Bank representative (officer or agent) or for whatsoever reason then I'd solely responsible of any such act and I understand that the Company can take appropriate legal action against me which may include suspension from the current roles & responsibilities or termination from the employment with immediate effect.

I also undertake that I have not taken any cash, favor or in kind from the customer for favoring any individual or organization by unfair means.

I also undertake that I'll not prepare any report on incomplete Survey form which is not properly filled as per the Company guidelines and in case I am preparing it which is creating an incorrect report then I'd be responsible for its consequences.

For File No.	
Preparer Name	
Signature	
Date	





## SURVEY SUMMARY SHEET (TO BE ENCLOSED WITH VALUATION REPORT)

(Version 1.0) | Date of implementation: 10.04.2017

Every Valuation report at R.K Associates is prepared based on the thorough survey of the property carried out by our Engineering Surveyor. This Survey Summary Sheet is for the information of Banker/ concerned interested organization. Detailed Survey Form can also be made available to the interested organization in case it is required to cross check what information our surveyor has given in site inspection report based on which Valuation report is prepared.

ow Property is Identified by the curveyor  The Boundaries matched  The Boundaries matched	Dipes Bedwie  MS SMC Infa  MS SMC Infa  Final Plet No. 441  building, Khapat Vi  Owner, Representative  could not be done from insi  Name  Prakas Shelve She	Sudhis Prakay  or of sce No 101,  lage fanch path a  ve, No one was availab  ide  Sudhis Prakay  properties mentioned in  Identified by the ow  ple, Identification of the  relevant papers available  ed in available documents  with measurements & phote  ents from outside & phote  (No measurements)	Contact No.  h.S. 1857913566  the deed, 7 From name plat yner/ owner representative, 1 he property could not be done to match the boundaries tographs)			
ow Property is Identified by the curveyor  The Boundaries matched  The Boundaries matched	Final Plot No. 441    Owner,   Representative could not be done from insimal number of the property of the pro	office No. 10/, last Panch paths ve, No one was available of the own ple, Identified by the own ple, Identification of the relevant papers available of in available documents with measurements & photents from outside & photents (No measurements)	Contact No.  Contact No.  1. S . 8657913566  The deed, From name plate yield of the property could not be done to match the boundaries to graphs)			
ow Property is Identified by the curveyor  The Boundaries matched  The Boundaries matched	Could not be done from instance  Name  Prakes Shelve  From schedule of the property and the property was not done  Yes, No, No Boundaries not mention and Half Survey (Inside-out word)  Half Survey (Measurement only photographs taken)  Property was locked,	relevant papers available din available documents with measurements & photon (No measurements)	Contact No.  1.5 . 8657913566  The deed, From name plate of the property could not be done  the property could not be done  the to match the boundaries of the property of the boundaries of the property of the boundaries of the b			
ow Property is Identified by the curveyor  The Boundaries matched  The Boundaries matched	Could not be done from instance  Name  Prakes Shelve  From schedule of the property and the property was not done  Yes, No, No Boundaries not mention and Half Survey (Inside-out word)  Half Survey (Measurement only photographs taken)  Property was locked,	relevant papers available din available documents with measurements & photon (No measurements)	Contact No.  1.5 . 8657913566  The deed, From name plate of the property could not be done  the property could not be done  the to match the boundaries of the property of the boundaries of the property of the boundaries of the b			
ow Property is Identified by the curveyor  The Boundaries matched  The Boundaries matched	Could not be done from instance  Name  Prakes Shelve  From schedule of the property and the property was not done  Yes, No, No Boundaries not mention and Half Survey (Inside-out word)  Half Survey (Measurement only photographs taken)  Property was locked,	relevant papers available din available documents with measurements & photon (No measurements)	Contact No.  1.5 . 8657913566  The deed, From name plate of the property could not be done  the property could not be done  the to match the boundaries of the property of the boundaries of the property of the boundaries of the b			
ow Property is Identified by the curveyor  The Boundaries matched  The Boundaries matched	Could not be done from instance  Name  Prakes Shelve  From schedule of the property and the property was not done  Yes, No, No Boundaries not mention and Half Survey (Inside-out word)  Half Survey (Measurement only photographs taken)  Property was locked,	relevant papers available din available documents with measurements & photon (No measurements)	Contact No.  1.5 . 8657913566  The deed, From name plate of the property could not be done  the property could not be done  the to match the boundaries of the property of the boundaries of the property of the boundaries of the b			
re Boundaries matched  urvey Type all photos of  office taken.  mple Measurement  as office vory large eason for Half survey or only	Prakask Shelary  ☐ From schedule of the property and the property of the prop	properties mentioned in properties mentioned in ple, Identified by the own ple, Identification of the relevant papers available in available documents with measurements & photents from outside & photents (No measurements)	the deed, From name plat viner/ owner representative, I the property could not be done the to match the boundaries tographs)			
re Boundaries matched  urvey Type all photos of  office taken.  mple Measurement  as office vory large eason for Half survey or only	☐ From schedule of the prodisplayed on the property. Enquired from nearby peo ☐ Survey was not done ☐ Yes, ☐ No, ☐ No ☐ Boundaries not mention. ☐ Full survey (inside-out wow Half Survey (Measurement of Donly photographs taken) ☐ Property was locked, ☐	properties mentioned in properties mentioned in ple, Identified by the own ple, Identification of the relevant papers available in available documents with measurements & photents from outside & photents (No measurements)	the deed, From name plate, representative, I he property could not be done le to match the boundaries tographs)			
re Boundaries matched  urvey Type all photos of  office taken.  mple Measurement  as office vory large eason for Half survey or only	Enquired from nearby peo Survey was not done Yes, No, No Boundaries not mention Full survey (inside-out w Half Survey (Measureme Only photographs taken	relevant papers available of in available documents with measurements & photents from outside & photents (No measurements)	le to match the boundaries s tographs)			
urvey Type all photos of office taken.  In ple measurement as office vory large peason for Half survey or only	☐ Yes, ☐ No, ☐ No ☐ Boundaries not mention ☐ Full survey (inside-out w ☐ Half Survey (Measureme ☐ Only photographs taken ☐ Property was locked, ☐	ed in available documents with measurements & phote ents from outside & phote (No measurements)	tographs) graphs)			
urvey Type all photos of office taken.  In ple measurement as office vory large peason for Half survey or only	☐ Boundaries not mention ☐ Full survey (inside-out w ☐ Half Survey (Measureme ☐ Only photographs taken ☐ Property was locked, ☐	ed in available documents with measurements & phote ents from outside & phote (No measurements)	tographs) graphs)			
mple Measuremen Targe ) as office vory Targe ) eason for Half survey or only	☐ Full survey (inside-out w  ☐ Half Survey (Measureme ☐ Only photographs taken ☐ Property was locked, ☐	vith measurements & photents from outside & photents (No measurements)	tographs) ographs)			
mple Measuremen Targe ) as office vory Targe ) eason for Half survey or only	☐ Half Survey (Measurement ☐ Only photographs taken☐ Property was locked, ☐	ents from outside & photo (No measurements)	ographs)			
mple Measuremen Targe ) as office vory Targe ) eason for Half survey or only	☐ Only photographs taken☐ Property was locked, ☐	(No measurements)	San A Carlo Market Commence			
eason for Half survey or only	☐ Property was locked, ☐	(No measurements)  Possessee didn't allow t				
eason for Half survey or only	☐ Property was locked, ☐	Possessee didn't allow t	Only photographs taken (No measurements)			
notographs taken	☐ Property was locked, ☐ Possessee didn't allow to inspect the property, ☐ NPA property so couldn't be surveyed completely					
rpe of Property	☐ Flat in Multistoried Apartment, ☐ Residential House, ☐ Low Rise Apartment, ☐ Residential Builder Floor, ☐ Commercial Land & Building, ☐ Commercial Office, ☐ Commercial Shop, ☐ Commercial Floor, ☐ Shopping Mall, ☐ Hotel, ☐ Industrial, ☐ Institutional, ☐ School Building, ☐ Vacant Residential Plot, ☐ Vacant Industrial Plot, ☐ Agricultural Land					
operty Measurement	✓ Self-measured ✓ Samp	le measurement, 🗆 No n	neasurement			
Large office Large Measurement	☐ Property was locked, ☐ didn't enter the property	Owner/ possessee didn , 🗹 Very Large Proper	't allow it, $\square$ NPA property s ty, practically not possible t			
nd Area of the Property	As per Title deed	As per Map	As per site survey			
vered Built-up Area	As per Title deed	As per Map	As per site survey			
Total Built up / II cu			7895. 3 Ft 2			
operty possessed by at the time of vey	Owner, 🗆 Vacant, 🗆 Le		ction,   Couldn't be Surveyed			
- T	ason for no measurement large office comple Measurement taken) Id Area of the Property vered Built-up Area perty possessed by at the time of very	It's a flat in multi storey   Property was locked,   didn't enter the property measure the area within line   As per Title deed   1085.4 m <sup>2</sup>   perty possessed by at the time of   Owner,   Vacant,   Li	It's a flat in multi storey building so measurement   Property was locked,   Owner/ possessee didn't enter the property,   Very Large Proper measure the area within limited time   Any other R			

	property during survey	
18.	Is Independent access available to the property	Clear independent access is available,  Access available in sharing of other adjoining property,  No clear access is available,  Access is closed due to dispute
19.	Is property clearly demarcated with permanent boundaries?	✓ Yes, ☐ No, ☐ Only with Temporary boundaries
20.	Is the property merged or colluded with any other property	ND
21.	Local Information References on property rates	Please refer attached sheet named 'Property rate Information Details.'

#### **Endorsement:**

### 1. Signature of the Person who was present from the owner side to identify the property:

Undertaking: I have shown the correct property and provided the correct information about the property to the surveyor of R.K Associates to the best of my knowledge for which Valuation has to be prepared. In case I have shown wrong property or misled the valuer company in any way then I'll be solely responsible for this unlawful act.

unlawful act.			
<ul> <li>a. Name of the P</li> <li>b. Relation:</li> <li>c. Signature:</li> <li>d. Date: 09/</li> </ul>	erson: Prakash Employel 824. 03/12 then mention the reasonsed to sign it,  Any other	n for it: □ No one was	available, ☐ Property is locked, ☐ Owner/
гергезелания			

#### 2. Surveyor Signature who did site inspection:

Undertaking: I have inspected the property and cross verified the property details at site to the extent of a. Matching boundaries of the property, b. Sample measurement of its area, c. Physical condition, d. Property rates as per local information with what is mentioned in the property documents provided to me by the Bank/ interested organization. I have not come under influence of anyone during site inspection and have only recorded the true and factual details in the survey form which I come across during the site survey. I understand that giving any manipulative information in the survey form will lead to incorrect Valuation report which is an unlawful act and i'll be solely responsible for doing it.

a.	Name of the	Surveyor:	Direch	Bedmutha
b.	Signature:	D Bed.	nites "	
	Date:	09/03		