



SURVEY SUMMARY SHEET (TO BE ENCLOSED WITH VALUATION REPORT)

(Version 1.0) | Date of implementation: 10.04.2017

Every Valuation report at R.K Associates is prepared based on the thorough survey of the property carried out by our Engineering Surveyor. This Survey Summary Sheet is for the information of Banker/ concerned interested organization. Detailed Survey Form can also be made available to the interested organization in case it is required to cross check what information our surveyor has given in site inspection report based on which Valuation report is prepared.

| 1. | File No. | | | |
|--------|--|---|--------------------------------------|------------------------------|
| 2. | Name of the Surveyor | Abhirt Ghate | | |
| 3. | Borrower Name | 3 | | |
| 4. | Name of the Owner | MIS. Cardamon Legitics Ascets (I) RA. Ltd. | | |
| 5. | Property Address which has to be valued | MIS. Cardamon Legitics Accts (I) Rs. Ltd. Act Mo-1, Chaken MIDC Phase -II, Pune | | |
| 6. | Property shown & identified by at | ☐ Owner, ☐ Representative, ☐ No one was available, ☐ Property is locked, survey | | |
| | spot | could not be done from inside | | |
| | 2 | Name | | Contact No. |
| | | Mr. Airt Patil | 8605 | 505327. |
| 7. | How Property is Identified by the | From schedule of the pro | operties mentioned in the | deed, From name plate |
| 28 | Surveyor | displayed on the property, \(\square\) Identified by the owner/ owner representative, \(\square\) | | |
| | Tables to Colds (* Colds) | Enquired from nearby peopl | e, \square Identification of the p | roperty could not be done, |
| | | ☐ Survey was not done | | |
| 8. | Are Boundaries matched | Yes, No, No relevant papers available to match the boundaries, | | |
| 0. | Ale Boundaries | ☐ Boundaries not mentioned | | |
| 9. | Survey Type | | | aphs) |
| 9. | Julyey Type | ☐ Ħalf Survey (Measurements from outside & photographs) | | |
| | | ☐ Only photographs taken (I | | |
| | Reason for Half survey or only | ☐ Property was locked, ☐ | ossessee didn't allow to in: | spect the property, NPA |
| 10. | photographs taken | property so couldn't be surve | | |
| - 11 | Type of Property | ☐ Flat in Multistoried Apartment, ☐ Residential House, ☐ Low Rise Apartment, ☐ | | |
| 11. | Type of Property | Residential Builder Floor, Commercial Land & Building, Commercial Office, | | |
| | | Commercial Shop, ☐ Comm | ercial Floor, Shopping M | lall, ☐ Hotel, ☐ industrial, |
| | | ☐ Institutional, ☐ School Bu | uilding, Vacant Residentia | al Plot, Vacant Industrial |
| | | Plot, ☐ Agricultural Land | | |
| | | ☐ Self-measured, ☐ Sample measurement, ☐ No measurement | | |
| 12. | Property Measurement | ☐ It's a flat in multi storey building so measurement not required | | |
| 13. | Reason for no measurement | ☐ Property was locked, ☐ Owner/ possessee didn't allow it, ☐ NPA property so | | |
| | | didn't enter the property, | Very Large Property, | practically not possible to |
| | | measure the area within limi | ted time Any other Reason | on: |
| | | | | |
| 14. | Land Area of the Property | As per Title deed | As per Map | As per site survey |
| 3.7.37 | | 152000 Sq mtr. | 125000 8ti west | 152000 |
| 15. | Covered Built-up Area | As per Title deed | As per Map | As per site survey |
| | The state of the s | | | Coulde's be Supremed |
| 16. | Property possessed by at the time of survey | ☐ Owner, ☐ Vacant, ☐ Cessee, ☐ Under Construction, ☐ Couldn't be Surveyed, | | |
| | | ☐ Property was locked, ☐ Bank sealed, ☐ Court sealed | | |
| 17 | Any negative observation of the | Ni/ | | |

| #- | property during survey | |
|-----|--|---|
| 18. | Is Independent access available to the property | ☐ Clear independent access is available, ☐ Access available in sharing of other adjoining property, ☐ No clear access is available, ☐ Access is closed due to dispute |
| 19. | Is property clearly demarcated with permanent boundaries? | ☐ Yes, ☐ No, ☐ Only with Temporary boundaries |
| 20. | Is the property merged or colluded with any other property | No. |
| 21. | Local Information References on property rates | Please refer attached sheet named 'Property rate Information Details.' |

Endorsement:

1. Signature of the Person who was present from the owner side to identify the property:

Undertaking: I have shown the correct property and provided the correct information about the property to the surveyor of R.K Associates to the best of my knowledge for which Valuation has to be prepared. In case I have shown wrong property or misled the valuer company in any way then I'll be solely responsible for this unlawful act.

Name of the Person: Mr. Ajit Patil

c.

In case not signed then mention the reason for it: \Box No one was available, \Box Property is locked, \Box Owner/ representative refused to sign it, \(\sigma\) Any other reason:

2. Surveyor Signature who did site inspection:

Undertaking: I have inspected the property and cross verified the property details at site to the extent of a. Matching boundaries of the property, b. Sample measurement of its area, c. Physical condition, d. Property rates as per local information with what is mentioned in the property documents provided to me by the Bank/ interested organization. I have not come under influence of anyone during site inspection and have only recorded the true and factual details in the survey form which I come across during the site survey. I understand that giving any manipulative information in the survey form will lead to incorrect Valuation report which is an unlawful act and i'll be solely responsible for doing it.

Name of the Surveyor: Abhijit Ghate
Signature: Qual
Date: 2315 | 2222