REPORT FORMAT: V-L3 (Medium) | Version: 8.0_2019

File No.: RKA/FY19-20/712

Dated: 05.02.2020

VALUATION ASSESSMENT

OF

INDUSTRIAL LAND & BUILDING

SITUATED AT

PLOT NO. F-73 & F-74, EPIP, RIICO INDUSTRIAL AREA, NEEMRANA, DISTRICT ALWAR, RAJASTHAN

OWNER/S

M/S. SCHON ULTRAWARES PVT. LTD.

A/C: M/S. SCHON ULTRAWARES PVT. LTD.

REPORT PREPARED FOR

STATE BANK OF INDIA, SAM-II BRANCH, JAWAHAR VAYAPAR BHAWAN, NEW DELHI

**Important - In case of any query/ issue or escalation you may please contact Incident Manager at valuers@rkassociates.org. We will appreciate your feedback in order to improve our services.

NOTE: As per IBA Guidelines please provide your feedback on the report within 15 days of its submission after which report will be considered to be correct.

VALUATION ASSESSMENT





PART A

SBI FORMAT OF REPORT ON VALUATION

Name & Address of Branch	State Bank of India, SAM-II Branch, Jawahar Vayapar
	Bhawan, New Delhi
Name of Customer (s)/ Borrower Unit	M/s. Schon Ultrawares Pvt. Ltd.

S.NO.	CONTENTS	DESCRIPTION	
1.	INTRODUCTION		
a.	Name of Property OwnerM/s. Schon Ultrawares Pvt. Ltd.		
	Address & Phone Number of the Plot No. F-73 & F-74, EPIP, RIICO Industrial Area		
	Owner	Neemrana, Dist. Alwar, Rajasthan	
b.	Purpose of the Valuation	For Distress Sale of mortgaged assets under NPA a/c	
C.	Date of Inspection of the Property	29 January 2020	
d.	Date of Valuation Report	4 February 2020	
e.	Name of the Developer of the	M/s. Schon Ultrawares Pvt. Ltd.	
	Property		
	Type of Developer	Property built by owner's themselves	

PHYSICAL CHARACTERISTICS OF THE PROPERTY 2.

BRIEF DESCRIPTION OF THE PROPERTY UNDER VALUATION



Snapshot of the Asset/ Property Under Valuation

Schon Ultrawares Pvt. Ltd., Established in the year 2000 is a recognized company across the globe, engaged in manufacturing, exporting and presenting an extensive range of biodegradable tableware such as Plates, Bowls, Trays, Clamshell Boxes, Wall Panel and Pulp Molded Packaging.

REINFORCING YOUR BUSINESS

VALUATION ASSESSMENT M/S. SCHON ULTRAWARES PRIVATE LIMITED

"**Grabeco**" biodegradable Tableware are broadly accepted and highly appreciated as the best option for serving and catering food for choice for the occasion including parties, weddings, business or social events, school outing, family picnic or social events. Finest quality and alluring designs of the products have encouraged our customers to always extend their loyalty and support to the company.

The complete product range offered by them is produced using excellent quality fibrous material from the tree-free natural renewable resource like sugarcane bagasse.

CIVIL/STRUCTURES VALUATION- M/S. SCHON ULTRAWARES PRIVATE LIMITED(NEEMRANA PLANT)							
Block Name	Floor wise Height(mtrs)	Year of construction	Type of Construction	Structure condition	Usability	Area (in sq. mtr.)	Area (in sq. ft.
Basement	12.75	2014	RCC load bearing structure on beam column and 9" brick walls	Good	Hall Used as Store	421.059803	4532.25
Ground Floor	12.25	2014	RCC load bearing structure on beam column and 9" brick walls	Good	Office, Reception, Admin Area	421.059803	4532.25
First Floor	11	2014	RCC load bearing structure on beam column and 9" brick walls	Good	Vacant Space(Only Superstructure. Not finished from inside)	421.059803	4532.25
Ground Floor-Tin shed	25.87	2014	Plain Tin shed roof mounted on iron pillars, trusses frame structure resting on brick wall	Good	Production area	1272.04143	13692.14
Security Room	9	2014	RCC load bearing structure on beam column and 9" brick walls	Good	Security	9.2903	100.00
Pannel Room	9	2014	RCC load bearing structure on beam column and 9" brick walls	Good	Pannel	9.2903	100.00
Transformer Room	9	2014	RCC load bearing structure on beam column and 9" brick walls	Good	Transformer	9.2903	100.00
Circuit Room	9	2014	RCC load bearing structure on beam column and 9" brick walls	Good	Circuit	9.2903	100.00
1. Buildings area is as per the information provided by the company.							
	Basement Ground Floor First Floor Ground Floor-Tin shed Security Room Pannel Room Transformer Room Circuit Room	Block Name Floor wise Height(mtrs) Basement 12.75 Ground Floor 12.25 First Floor 11 Ground Floor-Tin shed 25.87 Security Room 9 Pannel Room 9 Transformer Room 9 Circuit Room 9	Block NameFloor wise Height[mtrs]Year of constructionBasement12.752014Ground Floor12.252014First Floor112014Ground Floor-Tin shed25.872014Security Room92014Pannel Room92014Transformer Room92014Circuit Room92014	Block Name Floor wise Height(mtrs) Year of construction Type of Construction Basement 12.75 2014 RCC load bearing structure on beam column and 9" brick walls Ground Floor 12.25 2014 RCC load bearing structure on beam column and 9" brick walls First Floor 11 2014 RCC load bearing structure on beam column and 9" brick walls Ground Floor-Tin shed 25.87 2014 RCC load bearing structure on beam column and 9" brick walls Security Room 9 2014 Plain Tin shed roof mounted on iron pillars, trusses frame structure resting on brick walls Pannel Room 9 2014 RCC load bearing structure on beam column and 9" brick walls Transformer Room 9 2014 RCC load bearing structure on beam column and 9" brick walls Circuit Room 9 2014 RCC load bearing structure on beam column and 9" brick walls Circuit Room 9 2014 RCC load bearing structure on beam column and 9" brick walls	Block NameFloor wise Height(mtrs)Year of constructionType of ConstructionStructure conditionBasement12.752014RCC load bearing structure on beam column and 9" brick wallsGoodGround Floor12.252014RCC load bearing structure on beam column and 9" brick wallsGoodFirst Floor112014RCC load bearing structure on beam column and 9" brick wallsGoodGround Floor-Tin shed25.872014Plain Tin shed roof mounted on iron pillars, trusses frame structure resting on brick wallGoodSecurity Room92014RCC load bearing structure on beam column and 9" brick wallsGoodPannel Room92014RCC load bearing structure on beam column and 9" brick wallsGoodTransformer Room92014RCC load bearing structure on beam column and 9" brick wallsGoodCircuit Room92014RCC load bearing structure on beam column and 9" brick wallsGoodCircuit Room92014RCC load bearing structure on beam column and 9" brick wallsGood	Block Name Floor wise Height(mtrs) Year of construction Type of Construction Structure condition Usability Basement 12.75 2014 RCC load bearing structure on beam column and 9" brick walls Good Hall Used as Store Ground Floor 12.25 2014 RCC load bearing structure on beam column and 9" brick walls Good Hall Used as Store First Floor 11 2014 RCC load bearing structure on beam column and 9" brick walls Good Vacant Space[Only Superstructure. Not finished from inside] Ground Floor-Tin shed 25.87 2014 Plain Tin shed roof mounted on iron pillars, trusses frame structure on beam column and 9" brick walls Good Production area Security Room 9 2014 RCC load bearing structure on beam column and 9" brick walls Good Security Pannel Room 9 2014 RCC load bearing structure on beam column and 9" brick walls Good Pannel Transformer Room 9 2014 RCC load bearing structure on beam column and 9" brick walls Good Pannel Circuit Room 9 2014 RCC load bearing structure on beam column and 9" brick walls <	Block Name Hoor wise Height(mtrs) Year of construction Type of Construction Structure condition Usability Area (in sq. mtr.) Basement 12.75 2014 RCC load bearing structure on beam column and 9" brick walls Good Hall Used as Store 421.059803 Ground Floor 12.25 2014 RCC load bearing structure on beam column and 9" brick walls Good Hall Used as Store 421.059803 First Floor 11 2014 RCC load bearing structure on beam column and 9" brick walls Good Vacant Space(Only Superstructure. Not finished from inside) 421.059803 Ground Floor-Tin shed 25.87 2014 Plain Tin shed roof mounted on iron pillars, trusses frame structure resting on brick wall Good Production area 1272.04143 Security Room 9 2014 RCC load bearing structure on beam column and 9" brick walls Good Production area 1272.04143 Transformer Room 9 2014 RCC load bearing structure on beam column and 9" brick walls Good Pannel 9.2903 Circuit Room 9 2014 RCC load bearing structure on beam column and 9" brick walls Good

2. Appropriate Plinth Area (per sq. ft.) is taken as per the type of structure & condition of the buildings during the site survey.

This subjected property is being used for the industrial purpose. The property is on lease for 99 yrs. and the transaction is done in two part. Lease deed for first plot (F-73) was done in Aug, 2006 and for the second plot (F-74) was done in Aug, 2013. The property is well maintained and in very good condition as seen in pictures. The said property is basement plus ground plus one floor building and 1 GI Roofed structured over brick walls as production shop floor, 1 security office near main gate, and 3 small structures used as control circuit room or switch yard room. They are using basement as store room, ground floor as reception and admin office which is well maintained and having fall ceiling and remaining part as cutting area. The first floor is vacant but construction is not completed of this floor. The overall land Area is 4088 sq mtr. Total Covered area is 2572.38 sq mtr.

The subject property is located in the well-developed RIICO, EPIP industrial area of Neemrana. This property is clearly approached by the industrial road and only 1.5 Km from the Delhi-Jaipur Highway.

This report only contains general assessment & opinion on the Guideline Value and the indicative, estimated Market Value of the property for which Bank has asked to conduct the Valuation and found as per the information given in the copy of documents provided to us and/ or confirmed by the owner/ owner representative to us at site which has been relied upon in good faith. It doesn't contain any other recommendations of any sort.

a.	Location attribute of the property
i.	Nearby Landmark

Havells India Ltd.



ii.	Postal Address of the Property	Plot No. F-73 & F-74, EPIP, RIICO Industrial Area		
iii.	Area of the Plot/ Land		mrana, Dist. Alwar, Rajasthan.	
	Area of the Flot/ Land		rox. 4088 sq. mtr. please refer to Part-B Area	departmention of the property
			measurements considered	
			oted from relevant approved	-
		-	surement whichever is less.	
			surement of the property is d	
			lom checking.	one only based on sample
iv.	Type of Land		Land	
V.	Independent access/ approach to the		r independent access is availa	ble
	property			
vi.	Google Map Location of the Property		osed with the Report	
	with a neighborhood layout map		rdinates or URL: 27°57'46.0"N	76°21'33.4"E
vii.	Details of the roads abutting the propert			
	i.Main Road Name & Width		onal Highway	160 ft.
	ii. Front Road Name & width		strial Road	15 ft.
	iii. Type of Approach Road		ninous Road	
	iv. Distance from the Main Road		rox. 1.5 Km away from the Nat	
viii.	Description of adjoining property		ied Industrial area so all adjac	ent land use is Industrial
ix.	Plot No./ Survey No.		No- F-73 & F-74	
Х.	Zone/ Block		P, Industrial Area	
xi.	Sub registrar		mrana	
xii.	District	Alwa		
xiii.	Any other aspect	Valuation is done for the property found as information given in the copy of documents provid and/ or confirmed by the owner/ owner representative site.		documents provided to us
		site Valu	ing cizra map or coordinatior identification is a separate ac ation services.	tivity and is not part of the
	a) Identification of the property	\boxtimes	From Schedule of the Proper	5
	<i>,</i> , , , , , , , , , , , , , , , , , ,	Done from the name plate displayed on the property		
	(Property found as per the			
	information given in the			
	documents provided to us and/ or confirmed by the owner/	\boxtimes	Identified by owner's represe	ntative
	owner representative to us on		Identification of the property of	could not be done properly
	site.)		Survey was not done	
	b) Type of Survey	Full survey (inside-out with		imate measurements &
	b) Type of Survey	phot	ographs).	
	c) Is property clearly demarcated			dary
	by permanent/ temporary			
	boundary on site			
	d) Is the property merged or	No.	It is an independent single bou	inded property
colluded with any other property				



	e) City Categorization		Scale-C City		Urban developing	
f) Characteristics of the locality		Good		Within urban developing		
						zone
	g) Property location cla	ssification	2 Side Open	No	ne	None
	h) Property Facing		South-East Facing			
	Covered Built-up area des	cription	Approx. 2572.38 sq.mtr.			
	(Plinth/ Carpet/ Saleable Area)		Also please refer to Pa Area measurements of adopted from relevant measurement whichev measurement of the pa random checking.	considered i t approved ver is less.	n the Va docume Verifica	aluation Report is nts or actual site ation of the area
b.	Boundaries schedule of	1				
i.	Are Boundaries matched		Yes from the available	documents		
ii.	Directions	As pe	er Sale Deed/TIR	Ac	tual fou	nd at Site
	East		Road		Roa	ad

П.	Directions	As per Sale Deed/TIR	Actual found at Site
	East	Road	Road
	West	Land	Vacant land
	North	Other Property	Other Factory
	South	Road	Road
	Codin	Noad	Road

3.	TOWN PLANNING/ ZONING PARAMETE	RS	
a.	Master Plan provisions related to property in	Industrial	
	terms of Land use		
	i. Any conversion of land use done	Not Applicable	
	ii. Current activity done in the property	Industrial purpose	
	iii. Is property usage as per applicable	Yes used as Industrial as p	er zoning
	zoning		
	iv. Any notification on change of zoning	No	
	regulation		
	v. Street Notification	Industrial	
b.	Provision of Building by-laws as applicable	PERMITTED	CONSUMED
	i. FAR/ FSI	Please refer to area chart	Please refer to area chart
		description	description
	ii. Ground coverage	do	do
	iii. Number of floors	do	do
	iv. Height restrictions	do	do
	v. Front/ Back/ Side Setback	do	do
C.	Status of Completion/ Occupational	No information provided	No information provided
	certificate		
d.	Comment on unauthorized construction if any	Cannot comment since no	approved map given to us
e.	Comment on Transferability of	As per regulation of RIICO	
	developmentalrights		
f.	1. Planning Area/ Zone	RIICO Industrial Area	
	2. Master Plan currently in force	RIICO Industrial Area	
	3. Municipal limits	Area not within Municipal li	mits
g.	Developmental controls/ Authority	Rajasthan State Industrial I	Development and



		Investment Corporation (RIICO)
h.	Zoning regulations	Industrial
i.	Comment on the surrounding land uses & adjoining properties in terms of uses	Notified Industrial area so all adjacent land use is Industrial
j.	Comment of Demolition proceedings if any	No information available to us
k.	Comment on Compounding/ Regularization proceedings	No information available to us
١.	Any other aspect	
	i. Any information on encroachment	No
	ii. Is the area part of unauthorized area/ colony	No (As per general information available)

4.	DOCUMENT DETAILS AND LEGAL ASPE	CTS OF THE PROPER	RTY
a.	Ownership documents provided	Lease Deed	
b.	Names of the Legal Owner/s	M/s. Schon Ultrawares F	Pvt. Ltd.
C.	Constitution of the Property	Lease hold, have to take	e NOC in order to transfer
d.	. Agreement of easement if any Not required, subject property is on road		operty is on road
e.	Notice of acquisition if any and area under acquisition	No, as no information is	available on public domain
f.	Notification of road widening if any and area under acquisition	No, as no information is	available on public domain
g.	Heritage restrictions, if any	No	
h.	Comment on Transferability of the property ownership	Lease hold, have to take	NOC in order to transfer
i.	Comment on existing mortgages/ charges/ encumbrances on the property, if any	Yes	State Bank of India
j.	Comment on whether the owners of the property have issued any guarantee(personal or corporate) as the case may be	Not Known to us	NA
k.	Building plan sanction:		
	i. Authority approving the plan	RIICO	
	ii. Name of the office of the Authority	RIICO	
	iii. Any violation from the approved Building Plan	Approved building plan comment	not available, hence cannot
I.	Whether Property is Agricultural Land if yes, any conversion is contemplated	No not an agricultural pr	operty
m.	Whether the property SARFAESI complaint	Yes	
n.	i. Information regarding municipal taxes	Property Tax	No information available
	(property tax, water tax, electricity bill)	Water Tax	No information available
		Electricity Bill	No information available
	ii. Observation on Dispute or Dues if any in payment of bills/ taxes	No such information can	ne to knowledge on site
	iii. Is property tax been paid for this property	Company to provide this	information
	iv. Property or Tax Id No.	Not provided	
0.	Whether entire piece of land on which the unit	Yes, mortgaged	



	is set up / property is situated has been	
	mortgaged or to be mortgaged	
р.	Qualification in TIR/Mitigation suggested if any	Cannot comment since copy of TIR not made available to us
q.	Any other aspect	This is just an opinion report on Valuation based on the copy of the documents/ information provided to us by the client and has been relied upon in good faith of the property found as per the information given in the documents provided to us and/ or confirmed by the owner/ owner representative to us on site. Legal aspects, Title verification, Verification of authenticity of documents from originals or cross checking from any Govt. deptt. of the property have to be taken care by legal expert/ Advocate.
	i. Since how long owners owing the Property	13-years
	ii. Year of Acquisition/ Purchase	Year- 2006
	iii. Property presently occupied/ possessed by	Owner
	iv. Title verification	Legal aspects or Title verification have to be taken care by competent advocate.
	v. Details of leases if any	NA

5.	ECONOMIC ASPECTS OF THE PROPERTY		
a.	Reasonable letting value/ Expected market monthly rental	NA	
b.	Is property presently on rent	No	
	a) Number of tenants	NA	
	b) Since how long lease is in place	NA	
	c) Status of tenancy right	NA	
	d) Amount of monthly rent received	NA	
C.	Taxes and other outgoing	Company to provide this information	
d.	Property Insurance details	Company to provide this information	
e.	Monthly maintenance charges payable	Company to provide this information	
f.	Security charges, etc.	Company to provide this information	
g.	Any other aspect	NA	

6.	SOCIO - CULTURAL ASPECTS OF THE PROPERTY		
a	Descriptive account of the location of the property in terms of Social structure of the area in terms of population, social stratification, regional origin, age groups, economic levels, location of slums/squatter settlements nearby, etc.		
b.	Whether property belongs to social infrastructure like hospital, school, old age	No	



homes etc.

7.	FUNCTIONAL AND UTILITARIAN SERVICES, FACILITIES & AMENITIES					
a.	Description of the funct	Description of the functionality & utility of the property in terms of :				
	a. Space allocation	า		Yes		
	b. Storage spaces			Yes		
	c. Utility of spaces	provided within th	e	Yes		
	building					
	d. Car parking faci	lities		Yes		
	e. Balconies			No		
b.	Any other aspect					
	a. Drainage arrang	gements		Yes		
	b. Water Treatmer	nt Plant		No		
	c. Power Supply	Permanent		Yes		
	arrangements	Auxiliary		Yes, D.G sets		
	d. HVAC system			No, only individual ACs installed		
	e. Security provision	ons		Yes/ Private security guards		
	f. Lift/ Elevators			No		
	g. Compound wall	/ Main Gate		Yes		
	h. Whether gated	society		No		
	i. Internal development					
	Garden/ Park/ Water bodies In		Int	ernal roads	Pavements	Boundary Wall
	Land scraping					
	No	No		No	Yes	Yes

8.	INFRASTRUCTURE AVAILABILITY						
a.	Description of	Aqua Infrastruc	ture availability	in terms of:			
	i. Water S	upply		Yes	Yes		
	ii. Sewerag	ge/ sanitation sy	/stem	Undergrou	und		
	iii. Storm w	ater drainage		Yes			
b.	Description of	other Physical I	Infrastructure fa	acilities in terms	s of:		
	a. Solid waste management			Yes, by se	Yes, by selves		
	b. Electric	city		Yes	Yes		
	c. Road a	nd Public Trans	sport connectiv	ity Yes	/ Yes		
	d. Availab	d. Availability of other public utilities			Transport, Market, Hospital etc. available in close		
	nearby			vicinity	vicinity		
i.	Proximity & av	ailability of civic	amenities & so	ocial infrastruct	ure		
	School	Hospital	Market	Bus Stop	Railway Station	Metro	Airport
	2.2 Km	2.1 Km	1 Km	4.7 Km	25 Km	-	106 Km
	Availability of recreation facilities (parks, open				oping area ar		facilities are
	spaces etc.)			planned to be	developed nea	ırby	





9.	MARKETABILITY ASPECTS OF THE PROPERTY:			
i.	Marketability of the property in terms of			
	i. Location attribute of the subject property	Average		
	ii. Scarcity	Similar kind of properties are easily available on demand.		
	 iii. Market condition related to demand and supply of the kind of the subject property in the area 	Demand is related to the current use of the property only and only limited to the selected type of buyers		
iv. Comparable Sale Prices in the locality		Please refer to Part C: Valuation Assessment of the Property.		
ii.	Any other aspect which has relevance on the value or marketability of the property	No		
	i. Any New Development in surrounding area	No		
	 ii. Any negativity/ defect/ disadvantages in the property/ location 	No		

10.	ENGINEERING AND TECHNOLOGY ASP	ECTS OF THE PROPERT	Y:	
a.	Type of construction & design	•	mn structure on RCC slab and	
		GI shed iron pillar, trusses fra	me structure	
b.	Method of construction	Construction done using	g professional contractor	
		workmanship based on arc	hitect plan	
C.	Specifications			
	a. Class of construction	Class B construction (Good	(b	
	b. Appearance/ Condition of structures	Internal -Good		
		External - Good		
	c.Roof	Floors/ Blocks	Type of Roof	
		Main Building and Shed	RCC, GI Sheet	
	d. Floor height	Please refer to the Building	Sheet	
	e. Type of flooring	Vitrified tiles, PCC, Epoxy		
	f. Doors/ Windows	Wooden frame with glass panel windows, Wooden		
		frame & panel doors		
	g. Interior Finishing	Simple Plastered Walls,		
	h. Exterior Finishing	Simple plastered walls		
	i. Interior decoration/ Special architectural	Simple plain looking structure.		
	or decorative feature			
	j. Class of electrical fittings	Internal/ Normal quality fittings used		
	k.Class of sanitary & water supply fittings	Internal/ Normal quality fitti	ngs used	
d.	Maintenance issues	No maintenance issue,	structure is maintained	
		properly		
e.	Age of building/ Year of construction	Approx. 4-5 years	Around year-2014	
f.	Total life of the structure/ Remaining life		Approx. 55-60 years	
	expected	Approx. 60-65 years	subject to proper and	
			timely maintenance	
g.	Extent of deterioration in the structure	No deterioration came in	nto notice through visual	





		observation
h.	Structural safety	Structure built on RCC technique so it can be assumed as structurally stable. However no structural
		stability certificate is available
i.	Protection against natural disasters viz.	Since this is a RCC structure so should be able to
	earthquakes etc.	withstand moderate intensity earthquakes. Comments
		are been made only based on visual observation and
		not any technical testing.
j.	Visible damage in the building if any	No visible damages in the structure/ First floor is not
		completed only super structure
k.	System of air conditioning	Partially covered with window/ split ACs
Ι.	Provision of firefighting	Fire Extinguishers available
m.	Status of Building Plans/ Maps	Sanctioned Map not provided to us
	1. Is Building as per approved Map	Cannot comment since no approved map given to us
	2. Details of alterations/ deviations/ illegal	Permissible Alterations NA
	construction/ encroachment noticed in	
	the structure from the original approved	□Not permitted alteration NA
	plan	
	3. Is this being regularized	No information provided

11.	ENVIRONMENTAL FACTORS:		
a.	Use of environment friendly building materials like fly ash brick, other Green building techniques if any	Not known to us	
b.	Provision of rainwater harvesting	No	
C.	Use of solar heating and lighting systems, etc.	No	
d.	Presence of environmental pollution in the vicinity of the property in terms of industries, heavy traffic, etc. if any	No	

12.	ARCHITECTURAL AND AESTHETIC QUALITY OF THE PROPERTY:		
a.	Descriptive account on whether the building is	Plain looking simple structure	
	modern, old fashioned, etc., plain looking or with decorative elements, heritage value if applicable, presence of landscape elements, etc.		

13.	VALUATION:		
i.	Methodology of Valuation – Procedures		
	adopted for arriving at the Valuation	Valuation Assessment Factors of the report.	
i.	Prevailing Market Rate/ Price trend of the	Please refer to the Sub-Point 'o' of Point 1 of Part	
	Property in the locality/ city from property	C: Valuation Assessment Factors of the report and	
	search sites	the screenshot annexure in the report.	
i.	Guideline Rate obtained from Registrar's	Please refer to Part C: Valuation Assessment	
	office/ State Govt. gazette/ Income Tax	Factors of the report and the screenshot annexure in	



	Notifi	cation	the report.
<i>(</i> .	Summary of Valuation		For detailed Valuation calculation please refer to
			Points 1, 2, 3, 4, 5 & 6 of the Part C: Valuation
			Assessment Factors of the report.
	i.	Guideline Value	Rs. 1,83,96,000/- (Land Only)
		a. Land	Rs. 1,83,96,000/-
		b. Building	
	ii.	Indicative Prospective Estimated	Rs. 5,17,00,000/-
		Fair Market Value	
	iii.	Expected Estimated Realizable Value	Rs. 4,39,45,000/-
	iv.	Expected Forced/ Distress Sale Value	Rs. 3,87,75,000/-
	v.	Valuation of structure for Insurance purpose	Rs. 2,25,00,000/-
·.	i.	Justification for more than 20% difference in Market & Circle Rate	Circle rates are determined by the District administration as per their own theoretical internal policy for determining the minimum valuation of the property for property registration purpose and Market rates are adopted based on prevailing market dynamics which is explained clearly in Valuation assessment factors.
	ii.	Details of last two transactions in the locality/ area to be provided, if available	No authentic last two transactions details could be known. However prospective transaction details as per information available on public domain and gathered during site survey is mentioned in <i>Point 'o'</i> of Part C: Valuation Assessment Factors of the report and the screenshots of the references are annexed in the report for reference.

14.	Declaration	a. The information provided by us is true and correct to the best of my knowledge and belief.
		b. The analysis and conclusions are limited by the reported assumptions, limiting conditions, remarks and the information came to knowledge during the course of the work. Please see the Assumptions, Remarks & Limiting conditions described in the Report.
		c. I/ firm have read the Handbook on Policy, Standards and Procedures for Real Estate Valuation by Banks and HFIs in India, 2011 issued by IBA and NHB, fully understood the provisions of the same and followed the provisions of the same to the best of my ability and this report is in conformity to the Standards of Reporting enshrined in the above Handbook.
		d. No employee or member of R.K Associates has any direct/ indirect interest in the property.
		e. Our authorized surveyor SE Inderjeet Rathee has visited the subject property on 29 January 2020 in the presence of the owner's representative.
		f. I am a registered Valuer under Section 34 AB of Wealth Tax Act, 1957.
		g. I/ firm is an approved Valuer under SARFAESI Act – 2002 and approved by the Bank.
		h. We have submitted Valuation report directly to the Bank.



			ied out by our Engineering team on the request from Stat ranch, Jawahar Vayapar Bhawan, New Delhi.
15.	VALUATION COMPANY DETA	•	ranch, Jawanar Vayapar Dhawan, New Denn.
a. b.	Name & Address of Valuer company Engineering Team worked on the	M/s R.K. Ass D-39, 2nd Flo	ociates Valuers & Techno Engineering Consultants Pvt. Ltd. oor, Red FM Road, Sector 2, Noida, Uttar Pradesh 201301 BY: SE Inderjeet Rathee
	report	PREPARED	BY: SE Inderjeet Rathee
		REVIEWED	BY: HOD Valuations
16.	ENCLOSED DOCUMENTS:		
a.	Layout plan sketch of the area property is located with latitude an		Google Map enclosed with coordinates
b.	Building Plan		Only architect Map was provided by the owner/ clien Sanctioned Building Plan not available.
C.	Floor Plan		Not provided by the owner/ client
d.	Photograph of the property (ind stamping with date) and owner housing loans, if borrower is including a "Selfie' of the Valuer at	(in case of s available)	Enclosed with the report
e.	Certified copy of the approved , plan wherever applicable from th office		Not provided by the owner/ client
f.	Google Map location of the proper	rty	Enclosed with the Report
g.	Price trend of the property in the from property search Magickbricks.com, 99Acres.com, etc	sites viz	Enclosed with the Report
h.	Any other relevant documents/ext (All enclosures & annexures to remain & parcel of the main report)		 i. Part B: Area Description of the Property ii. Part C: Valuation Assessment of the Property iii. Part D: Summary of the Valuation Repo iv. Google Map v. Photographs vi. Survey Summary Sheet vii. Valuer's Remark viii. Copy of relevant papers from the property documents referred in the Valuation
i.	Total Number of Pages in the Repo enclosures	ort with	35



PART B

AREA DESCRIPTION OF THE PROPERTY

	Land Area	4889.20 sq.yds (4088 s	sq.mtr)	
1.	Area adopted on the basis of	Property documents only since site measurement couldn't be carried out		
	Remarks & observations, if	NA		
	any			
		Permissible	No information available to us	
2	Cround Coverage Area	(x% of Plot area)		
2.	Ground Coverage Area	Proposed (x%)	No information available to us	
		Present Status	No information available to us	
	FAR	Permissible	No information available to us	
3.		Proposed (x%)	No information available to us	
		Present Status	No information available to us	
	Constructed Area considered			
	for Valuation	Covered Area	2572.38 sq.mtr (15633 sq.ft)	
4.	(As per IS 3861-1966)			
ч.	Area adopted on the basis of	Site survey measurement only since no relevant document was available		
	Remarks & observations, if	NA		
	any			

Note:

- e. Area measurements considered in the Valuation Report pertaining to Land & Building is adopted from relevant approved documents or actual site measurement whichever is less. All area measurements are on approximate basis only.
- **f.** Verification of the area measurement of the property is done based on sample random checking only.
- g. Area of the large land parcels of more than 2500 sq.mtr or of uneven shape, is taken as per property documents which has been relied upon.
- h. Drawing Map, design & detailed estimation of the property/ building is out of scope of the Valuation services.

VALUATION ASSESSMENT

M/S. SCHON ULTRAWARES PRIVATE LIMITED



PART C

VALUATION ASSESSMENT OF THE PROPERTY

a.		ASSESS	MENT FACTO	RS		
a.	Valuation Type	Land & Building Val	lue		Industrial Value	Land & Building
b.	Scope of the Valuation	Non binding opinion on the assessment of Plain Asset Valuation of the property is done for the property found as per the information given in the documents and/ or confirmed by the owner/ owner representative.				
C.	Property Use factor	Current Use Highest & Best Use				
		Indus	strial		Indu	strial
d.	Legality Aspect Factor	Assumed to be positive as per copy of documents & information produced to us. However Legal aspects of the property have to be taken care by Bank empanelled competent Legal expert/ Advocate. Verification of authenticity of documents from originals or cross checking from any Govt. deptt. has to be taken care by Bank empanelled Legal expert Advocate.		aken care by Bank or cross checking		
e.	Land Physical factors	Shape	Size		Level	Frontage to
		Destangle	Normal		Road Level	depth ratio
f.	Property location	Rectangle City	Normal Locality		roperty	Normal frontage Floor Level
1.	category factor	Categorization	Categorizatio	n lo clas	ocation sification	
		Scale-C City	Ordinary		ide Open	NA
		Urban developing	Within urban developing zon		to Highway rner Plot	
		Property Facing	North-East Fac	ing		
g.	Any New Development in surrounding area	None				
h.	Any specific advantage/ drawback in the property	No				
i.	Overall property usability Factor	Good				
j.	Comment on Property Salability Outlook	Not so easilly sellab	ble due to current	economic	condition	
k.	Comment on Demand & Supply in the Market	The demand for such properties should be good under normal circumstances and the availability of such properties will also not be high, but the market is not very robust due to the current economic conditions.				
Ι.	Any other aspect which has relevance on the value or marketability of the property	NA Valuation of the same asset/ property can fetch different values under different circumstances & situations. For eg. Valuation of a running/ operational shop/ hotel/ factory will fetch better value and in case of closed shop/ hotel/ factory it will have considerable lower value. Similarly an asset sold directly by an owner in the open market through free market transaction then it will fetch better value and if the same asset/ property is sold by any financer due to encumbrance on it, will fetch lower value. Hence before				



		financing, Lender/ FI should take into consideration all such future risks while financing.
		This Valuation report is prepared based on the facts of the property & market situation on the date of the survey. It is a well-known fact that the market value of any asset varies with time & socio-economic conditions prevailing in the country. In future property market may go down, property conditions may change or may go worse, property reputation may differ, property vicinity conditions may go down or become worse, property market may change due to impact of Govt. policies or effect of World economy, usability prospects of the property may change, etc. Hence before financing, Banker/ FI should take into consideration all such future risk while financing.
m.	Sale transaction method assumed	Free market transaction at arm's length wherein the parties, after full market survey each acted knowledgeably, prudently and without any compulsion.
n.	Best Sale procedure to realize maximum Value	Free market transaction at arm's length wherein the parties, after full market survey each acted knowledgeably, prudently and without any compulsion.
0.	Methodology/ Basis of	Govt. Guideline Value: Circle rate of Rajasthan Government
	Valuation	Market Value: Land Value is calculated on the basis of 'Market Comparable
		Sales approach' and Building construction value is calculated on the basis of
		'Depreciated Replacement Cost approach'
		Valuation of the asset is done as found on as-is-where basis.
		Valuation is done based on the Valuation best practices, standard operating procedures and definitions prescribed by various organizations like IVSC, Income Tax of India, etc. as defined under.
		For knowing comparable market rates, significant discreet local enquiries have been made from our side representing ourselves as both buyer and seller for the similar properties in the subject area and thereafter based on this information and various factors of the property, a rate has been judiciously taken considering the market scenario.
		References regarding the prevailing market rates are based on the verbal/ informal/ secondary/ tertiary information collected during market survey in the subject area from the local people, property consultants, recent deals, demand-supply, internet postings which are relied upon. No written record is generally available for such market information and only the verbal information has to be relied upon.
		Market Rates are rationally adopted based on the facts of the property that came to our knowledge during the course of the assignment considering many factors like nature of the property, size, location, approach, market situation and trends.
		The indicative value has been suggested based on the prevailing market rates that came to our knowledge during secondary & tertiary market researches and does not split into formal & informal payment components.
		Secondary/ Tertiary costs related to asset transaction like Stamp Duty, Registration charges, Brokerage, Bank interest, selling cost, marketing cost, etc. pertaining to the sale/ purchase of this property are not considered while assessing the indicative estimated Market Value.
		This report includes both, Govt. Guideline Value and Indicative Estimated Prospective Fair Market Value. As per the current market practice, in most of the cases, formal transaction takes place for an amount less than the actual transaction amount and rest of the payment is normally done informally.



	Construction rates are adopted based on the present market replacement cost of construction and calculating applicable depreciation & deterioration factor as per its existing condition & specifications based on only visual observation of the structure. No structural, physical tests have been carried out in respect of it.
	Construction rates are adopted based on the plinth area rates prevailing in the market for the structure as a whole and not based on item wise estimation or Bills of Quantity method.
	The condition assessment and the estimation of the residual economic life of the structure is only based on the visual observations and appearance found during the site survey. We have not carried out any structural design or stability study; nor carried out any physical tests to assess structural integrity & strength.
	Sale transaction method of the asset is assumed as free market transaction while assessing Indicative & Estimated Fair Prospective Market Value of the asset.
	Any kind of unpaid statutory, utilities, lease, interest or any other pecuniary dues on the asset has not been factored in the Valuation.
	This Valuation is conducted based on the macro analysis of the asset/ property considering it in totality and not based on the micro, component or item wise analysis. Analysis done is a general assessment and is not investigative in nature
	Fair Market Value [#] suggested by the competent Valuer <u>is that prospective estimated</u> <u>amount</u> in his expert & prudent opinion of the subject asset/ property without any prejudice after he has carefully & exhaustively evaluated the facts & information came in front of him related to the subject asset at which the subject asset/ property should be exchanged between a willing buyer and willing seller at an arm's length transaction in an open & unrestricted market, after proper marketing, wherein the parties, each acted knowledgeably, prudently and without any compulsion on the date of the Valuation.
	Forced, under compulsion & constraint, obligatory sales transactions data doesn't indicate the Fair Market Value.
	Realizable Value^ is the minimum prospective estimated value of the property which it may be able to realize at the time of actual property transaction factoring in the potential prospects of deep negotiations carried out between the buyer & seller for ultimately finalizing the transaction across the table. Realizable value may be 10-20% less than the Fair Market Value depending on the various salability prospects of the subject property and the needs of the buyer & the seller.
	Forced/ Distress Sale Value * is the value when the property has to be sold due to any compulsion or constraint like financial encumbrances, dispute, as a part of a recovery process, any defect in the property, legal issues or any such condition or situation. In this type of sale, minimum fetch value is assessed which can be 25-40% less than the estimated Fair Market Value based on the nature, size & salability prospects of the property. In this type of sale, negotiation power of the buyer is always more than the seller and eagerness & pressure of selling the property is more than buying it. Therefore the Forced/ Distress Sale Value will always fetch significantly less value compare to the estimated Fair Market Value.
	Liquidation Value is the amount that would be realized when an asset or group of assets are sold on a piecemeal basis that is without consideration of benefits (or detriments) associated with a going-concern business. Liquidation value can be either in an orderly transaction with a typical marketing period or in a forced transaction with a shortened marketing period.



		underste different legal te describe the use The Co	The between Cost, Price & Value: Generally these words are used and ood synonymously. However in reality each of these has a completely t meaning, premise and also having different definitions in the professional & rms. Therefore to avoid confusion, it is our professional responsibility to be the definitions of these words to avoid ambiguity & confusion in the minds of r of this report. St of an asset represents the actual amount spend in the construction/ actual of the asset.
			<i>ce</i> is the amount paid for the procurement of the same asset.
		depends supply, outlook,	lue is defined as the present worth of future rights in the property/asset and s to a great extent on combination of various factors such as demand and market situation, purpose, situation & needs of the buyer & seller, saleability usability factor, market perception & reputation. needs of the buyer & seller, ity outlook, usability factor, market perception & reputation.
		since th	re in actual for the same asset/ property, cost, price & value remain different ese terms have different usage & meaning.
р.		-	ate/Price trend of the property and Details of the sources from where
	the information is gathered (from p		
	Name:		Mr. Anil Sharma
	Contact No.:		9928068205
	Nature of reference:		Property Consultant
	Size of the Property:		4000-5000 sq. mtr
	Location:		RIICO Neemrana
	Rates/ Price	informed:	Rs. 4,000/- to Rs. 5,000/- per sq. mtr
	Any other details/ Discussion held:		As per our discussion all the plots are now available in Re-sale and if any plot sells by RIICO then it will available only in auction and then rates may
			go high up to Rs. 5,500/- to Rs. 6,000/- per sq. mtr.
	V Name:		Mr. Manoj Pardhan
	Contact No.:		9829326471
	Nature of ref		Property Consultant
	Size of the P	roperty:	4000-5000 sq. mtr
	Location:		RIICO Neemrana
	Rates/ Price		Rs. 5,000/- to Rs. 6,000/- per sq. mtr
	Any other details/ Discussion held:		Easily available for Purchase purpose.
	V Name:		Mr. Pramod Kumar
	Contact No.:		9829137361
	Nature of ref		Property Consultant
	Size of the P Location:	торепу:	4000-5000 sq. mtr
	Rates/ Price	informad:	RIICO Neemrana
		tails/ Discussion	Rs. 4,000/- to Rs. 5,000/- per sq. mtr Resale of plot is bit difficult in this area.
	held	allis/ Discussion	Resale of plot is bit difficult in this area.
	NOTE: The given i	information abov	e can be independently verified to know its authenticity.
q.	Adopted Rates	The location of	of the subject property is in the developing area of RIICO, EPIP,
•	Justification		mand of the property is not so good. The property is being used for
		the Industrial p	
	1		



for industrial purpose. Hence taking into consideration all these factors like size	and
shape of the plot, location of the property, market condition, rate ratio for the lan	
current activity on the land, we are of the view that the appropriate rate range	
such a land parcel cumulatively can be considered between Rs.4,000/- to Rs.5,5	
per sq.mtr and for the valuation purpose we have adopted Rs.4,750/- per sq.	mtr
which appears to be reasonable in our view.	

b.			
	Particulars	Govt. Circle/ Guideline Value	Indicative & Estimated Prospective Fair Market Value
i.	Prevailing Rate range	Rs.4,500/- per sq.mtr	Rs.4,000/- to Rs.5,000/- per sq.mtr
ii.	Rate adopted considering all characteristics of the property	Rs.4,500/- per sq.mtr	Rs.4,750/- per sq.mtr
iii.	Total Land Area considered (documents vs site survey whichever is less)	4088 sq.mtr (4889.20 sq.yds)	4088 sq.mtr (4889.20 sq.yds)
iv	Total Value of land (A)	4088 x Rs.4,500/-per sq.mtr	4088 x Rs.4,750/- per sq.mtr
iv.	Total value of land (A)	Rs.1,83,96,000/-	Rs.1,94,18,000/-

C.		VALUATION OF BUILDING STRUCTURE		
	Particulars		Govt. Circle/ Guideline Value	Indicative & Estimated Prospective Fair Market Value
		Rate range		Please refer to the attached sheet below
		Rate adopted		Please refer to the attached sheet below
a.	Structure Construction Value	Covered Area		Please refer to the attached sheet below
а.		Class of construction	Class B construction (Good)	Class B construction (Good)
		Valuation Calculation		Please refer to the attached sheet below
		Total Value		Rs. 2,87,86,722/-
b.	Depreciation pe (assuming salvage va	-	NA	NA (Above replacement rate is calculated after deducting the prescribed depreciation)
C.	Age Factor		2000 onwards	2-5 years old construction
d.	Structure Type/	Condition		RCC framed pillar, beam, column structure on RCC slab/ Good
e.	Estimated Cons Depreciated Re Value (B)			Rs. 2,87,86,722/-

d.	VALUATION OF ADDITIONAL BUILDING & SITE AESTHETIC WORKS		
	Particulars	Specifications	Depreciated Replacement Value



Ary, Lift, Auxiliary power, AC, Firefighting etc.) extra for internal & nal development al roads, Landscaping, Pavements, lights, Green area development, al area landscaping, Land poment, Approach road, etc.)	wall, Gate, etc.	Rs.20,00,000/- Rs. 15,00,000/-
ary, Lift, Auxiliary power, AC, Firefighting etc.)	wall, Gate, etc.	KS.20,000,000/-
extra for services , Electricity, Sewerage, Main gate,	Lump sum Value For boundary	Be 20.00.000/
windows, wood work, cupboards, ar kitchen, electrical/ sanitary		
etic developments, ovements		
	extra for Architectural netic developments, ovements mp sum cost) extra for fittings & fixtures windows, wood work, cupboards, ar kitchen, electrical/ sanitary	extra for services



PART D

CONSOLIDATED VALUATION ASSESSMENT OF THE PROPERTY

S.No.	Particulars	Govt. Circle/ Guideline Value	Indicative & Estimated Prospective Fair Market Value
1.	Land (A)	Rs. 1,83,96,000/-	Rs. 1,94,18,000/-
2.	Structure Construction Value (B)		Rs. 2,87,86,722/-
3.	Additional Building & Site Aesthetic Works Value (C)		Rs. 35,00,000/-
4.	Total Add (A+B+C)	Rs. 1,83,96,000/-	Rs. 5,17,04,722/-
5.	Additional Premium if any Details/ Justification		
6.	Deductions charged if any Details/ Justification		
7.	Total Indicative & Estimated Prospective Fair Market Value [#]		Rs. 5,17,04,722/-
8.	Rounded Off		Rs. 5,17,00,000/-
9.	Expected Realizable Value [^] (@ ~15% less)		Rs. 4,39,45,000/-
10.	Expected Forced Distress Sale Value* (@ ~25% less)		Rs. 3,87,75,000/-
11.	Valuation of structure for Insurance purpose		Rs. 2,25,00,000/-

12.	Concluding Comments &	a. This Valuation report is prepared based on the copies of the	
	Disclosures if any	documents/ information which interested organization or	
		customer could provide to us out of the standard checklist of	
		documents sought from them and further based on our	
		assumptions and limiting conditions. All such information	
		provided to us has been relied upon in good faith and we have	
		assumed that it is true and correct.	
		b. Legal aspects for eg. investigation of title, ownership rights,	
		lien, charge, mortgage, lease, verification of documents from	
		originals, etc. has to be taken care by legal experts/ Advocates.	
		c. This report only contains opinion based on technical & market	
		information which came to knowledge during course of the	
		assignment. It doesn't contain any recommendations.	
		d. This report is prepared following our Standard Operating	
		Procedures & Best Practices, Limitations, Conditions,	
		Remarks, Important Notes, Valuation TOR.	

(Rupees Five Crores Seventeen Lakhs Only)

VALUATION ASSESSMENT

M/S. SCHON ULTRAWARES PRIVATE LIMITED



PART E

SUMMARY OF THE VALUATION REPORT

S.NO.	CONTENTS	DESCRIPTION				
1.	GENERAL DETAILS					
a.	Report prepared for	Bank				
b.	Name & Address of Organization	State Bank of India, SAM-II Branch, Jawahar Vayapar Bhawan, New Delhi.				
C.	Name of Borrower unit	M/S. Schon Ultrawares F	N/t I td			
d.	Name of Property Owner	M/S. Schon Ultrawares F				
	Address & Phone Number of the	Plot No. F-73 & F-74, E		Aroa Noomrana		
e.	owner	Dist. Alwar, Rajasthan.		Alea, Neemiana,		
f.	Address of the property under	Plot No. F-73 & F-74, E	PIP RIICO Industrial	Area Neemrana		
	Valuation	Dist. Alwar, Rajasthan.				
g.	Type of the Property	Industrial Land & Building	9			
h.	Type of Loan	Term Loan				
i.	Type of Valuation	Industrial Land & Building	g value			
j.	Report Type	Plain Asset Valuation	-			
k.	Date of Inspection of the Property	29 January 2020				
I.	Date of Valuation Report	5 February 2020				
m.	Surveyed in presence of	Owner's representative Mr. Sumit Juneja				
n.	Purpose of the Valuation	For Distress Sale of mort	gaged assets under N	IPA a/c		
0.	Scope of the Report	Non binding opinion on indicative estimated prospective				
		valuation assessment of the property identified by property owner or through its representative				
р.	Important Disclosures	 i. Legal aspects of the property have to be taken care by legal expert/ advocate. ii. Verification of authenticity of documents from originals or cross checking from any Govt. deptt. has to be taken care by legal expert/ advocate. iii. This is just an opinion report on Valuation based on the copy of the documents/ information provided to us by the client which has been relied upon in good faith of the property found as per the information given in the documents provided to us and/ or confirmed by the owner/ owner representative to us on site. iv. Getting cizra map or coordination with revenue officers for site identification is a separate activity and is not part of the Valuation services. v. Measurement verification is only limited up to sample random measurement against the documents produced to us. VI. Drawing Map & design of the property is out of scope of the Valuation services. 				
q.	Documents provided for perusal	Documents Requested	Documents Provided	Documents Reference No.		
		Total 03 documents	Total 03			



		requested.		documents provided				
			Property Title document	Sale Deed				
			Approved Map	Unapproved Map				
		Olo	d Valuation Report	Old Valuation Report				
r.	Documents received from	Bank						
S.	Identification of the property	Cross checked from Schedule of the property mentioned in the deed						
		Done from the name plate displayed on the property						
		\boxtimes	Identified by theOwner's representative					
			Enquired from local residents/ public					
		□ Identification of the property could not be done properly						
		□ Survey was not done						

2.	VALUATION SUMMARY	
a)	Total Govt. Guideline Value	Rs. 1,83,96,000/-
b)	Total Indicative & Estimated Prospective Fair Market Value	Rs. 5,17,00,000/-
C)	Total Expected Realizable/ Fetch Value	Rs. 4,39,45,000/-
d)	Total Expected Distress/ Forced Sale Value	Rs. 3,87,75,000/-
e)	Valuation for the purpose of Insurance	Rs. 2,25,00,000/-

3.	ENCLOSURES	
a.	Part A	Valuation Report as per SBI format
b.	Part B - Annexure-I	Area description of the Property
C.	Part C - Annexure-II	Valuation Assessment of the Property
d.	Part D - Annexure-III	Summary of the Valuation report
e.	Annexure - IV	Circle Rate Screenshot -Page No. 23
f.	Annexure - V	Summary of Building Calculation Page No. 24
g.	Annexure - VI	Google Map Location Page No. 25
h.	Annexure - VII	Photographs Page No. 26,27,28,29,30,31,32,33,34
i.	Annexure - VIII	Valuer's Remarks- Page No. 35-36
j.	Annexure - IX	Survey Summary Sheet – Page No. 37
k.	Annexure - X	Copy of relevant papers from the property documents referred in the Valuation



R.K ASSOCIATES IMPORTANT NOTES:

DEFECT LIABILITY PERIOD - In case of any query/ issue or escalation you may please contact Incident Manager by writing at valuers @rkassociates.org. We try our level best to ensure maximum accuracy in the Calculations done, Rates adopted and various other data points & information mentioned in the report but still can't rule out typing, human errors, assessment or any other mistakes. In case you find any mistake, variation, discrepancy or inaccuracy in any data point of the report, please help us by bringing all such points into our notice in writing at valuers @rkassociates.org within 30 days of the report delivery, to get these rectified timely, failing which R.K Associates won't be held responsible for any inaccuracy in any manner. Also if we will not hear back anything from you within 30 days, we will assume that report is correct in all respect and no further claim of any sort will be entertained thereafter. We would welcome and appreciate your feedback & suggestions in order to improve our services.

Our **DATA RETENTION POLICY** is of <u>ONE YEAR</u>. After this period we remove all the concerned records related to the assignment from our repository. No clarification or query can be answered after this period due to unavailability of the data.

<u>COPYRIGHT FORMAT</u> - This report is prepared on the copyright format of R.K Associates to serve our clients in the best possible way. Legally no one can copy or distribute this format without prior approval from R.K Associates. It is meant only for the organization as mentioned on the cover page of this report. Distribution or use of this format other than R.K Associates will be seen as unlawful act and necessary legal action can be taken against the defaulters.

IF REPORT IS USED FOR BANK/ FIS

NOTE: As per IBA Guidelines in case the valuation report submitted by the valuer is not in order, the banks / FIs shall bring the same to the notice of the valuer within 15 days of submission for rectification and resubmission. In case no such communication is received, it shall be presumed that the valuation report has been accepted.

At our end we have not verified the authenticity of any documents provided to us. Bank is advised to verify the genuineness of the property documents before taking any credit decision.



CIRCLE RATE – ANNEXURE IV

	पंजीयन एवं मुद्रांक विभाग, अजमेर Registration & Stamps Department, Ajmer ईपंजीयन : पंजीयन व मूल्यांकन की एकीकृत ऑनलाईन प्रणाली							
<u>अन्य जिला चुनें</u>	अन्य जिला चुनें DLC Rates							
	Di	strict Name :- ALWAR						
	SR	O Name :- NEEMRANA	Zone Na	me :- Nir	urana			
		Area :- Urban	Colony	Name :-	- All			
		Back	Con	vert To PDI	-			
SRO Name	Zone	Colony	Type Of Land	Exterior	Interior	Unit	Plot Wise Rate	Previous DLC
NEEMRANA	Nimrana	Anantraj Ashray	Residential	9000	-	Sq Mtr	Select	Select
			Commercial	18000	-	Sq Mtr		Select
		Anurag Homes	Residential	9000	-	Sq Mtr	Select	Select
			Commercial	18000	-	Sq Mtr		Select
		Ashiyana Aangan Neemrana	Residential	24530	-	Sq. Yd.	Select	Select
		EPIP-NEEMRANA	Residential	9000	-	Sq Mtr	Select	Select
			Commercial	18000	-	Sq Mtr		Select
			Industrial	4500	-	Sq Mtr		Select
		Ganpati Plaza/ GH 1	Residential	9000	-	Sq Mtr	Select	Select
			Commercial	18000	-	Sq Mtr		Select
		GHILOTH	Residential	7200	-	Sq Mtr	Select	Select
			Commercial	14400	-	Sq Mtr		Select
			Industrial	3600	-	Sq Mtr		Select
		Green Akad/ Ashadeep	Residential	14070	-	Sq. Yd.	Select	Select
			Commercial	29030	-	Sq. Yd.		Select




				IL/STRUCTURES VALUATION- M/S. SCI	HON ULTRAW	ARES PRIVATE LIMITED	(NEEMRANA PLA	(NT)		
6.No.	Block Name	Floor wise Height(mtrs)	Year of construction	Type of Construction	Structure condition	Usability	Area (in sq. mtr.)	Area (in sq. ft.)	Rates Adopted (per sq. ft.)	Current Depreciated Market Value
1	Basement	12.75	2014	RCC load bearing structure on beam column and 9" brick walls	Good	Hall Used as Store	421.06	4532.25	₹ 1,000	₹ 45,32,250
2	Ground Floor	12.25	2014	RCC load bearing structure on beam column and 9" brick walls	Good	Office, Reception, Admin Area	421.06	4532.25	₹ 1,250	₹ 56,65,313
3	First Floor	11	2014	RCC load bearing structure on beam column and 9" brick walls	Good	Vacant Space(Only Superstructure. Not finished from inside)	421.06	4532.25	₹ 850	₹ 38,52,413
4	Ground Floor-Tin shed	25.87	2014	Plain Tin shed roof mounted on iron pillars, trusses frame structure resting on brick wall	Good	Production area	1272.04	13692.14	₹ 1,050	₹ 1,43,76,747
5	Security Room	9	2014	RCC load bearing structure on beam column and 9" brick walls	Good	Security	9.29	100.00	₹ 900	₹ 90,000
6	Pannel Room	9	2014	RCC load bearing structure on beam column and 9" brick walls	Good	Pannel	9.29	100.00	₹ 900	₹ 90,000
7	Transformer Room	9	2014	RCC load bearing structure on beam column and 9" brick walls	Good	Transformer	9.29	100.00	₹ 900	₹ 90,000
8	Circuit Room	9	2014	RCC load bearing structure on beam column and 9" brick walls	Good	Circuit	9.29	100.00	₹ 900	₹ 90,000
Total						2572.38	27688.89		₹ 2,87,86,722	

Summary of Building Calculation– ANNEXURE V

2. Appropriate Plinth Area (per sq. ft.) is taken as per the age, type of structure & condition of the buildings during the site survey.




GOOGLE MAP LOCATION- ANNEXURE VI







PHOTOGRAPHS OF THE PROPERTY – ANNEXURE VI
































































VALUER'S REMARKS - ANNEXURE IX

a)	This Valuation report is prepared based on the copies of the documents/ information which interested organization or customer could provide to us out of the standard checklist of documents sought from them and further based on our assumptions and limiting conditions. All such information provided to us has been relied upon in good faith and we have assumed that it is true and correct. Verification or cross checking of the documents provided to us from the originals has not been done at our end.
b)	Legal aspects for eg. investigation of title, ownership rights, lien, charge, mortgage, lease, verification of documents, etc. have to be taken care by legal expert/ Advocate and same are not done at our end. It is assumed that the concerned Lender/ Financial Institution has asked for the valuation of that property for which the legal verification has been already taken and cleared by the competent Advocate before requesting for the Valuation report.
c)	Analysis and conclusions adopted in the report are limited to the reported assumptions, conditions and information came to our knowledge during the course of the work.
d)	Value varies with the Purpose/ Date/ Condition prevailing in the market. We recommend not to refer the indicative & estimated prospective Value of the asset given in this report if any of these points are different from the one mentioned aforesaid in the Report. We also recommend that the indicative estimated Value in the Valuation Report holds good only up to the period of 3 months from the date of Valuation.
e)	This report is having limited scope as per its fields & format to provide only the general basic idea of the value of the property prevailing in the market based on the documents/ data/ information provided by the client. The suggested indicative prospective estimated value should be considered only if transaction is happened as free market transaction.
f)	This Valuation report is prepared based on the facts of the property on the date of the survey. It is a well-known fact that the market value of any asset varies with time & socio-economic conditions prevailing in the country. In future property Market may go down, property conditions may change or may go worse, Property reputation may differ, Property vicinity conditions may go down or become worse, Property market may change due to impact of Govt. policies or effect of World economy, Usability prospects of the property may change, etc. Hence before financing, Banker/ FI should take into consideration all such future risk and should loan conservatively to keep the advanced money safe in case of the downward trend of the property value.
g)	Valuation of the same asset/ property can fetch different values in different situations. For eg. Valuation of a running/ operational shop/ hotel/ factory will fetch better value and in case of closed shop/ hotel/ factory it will have considerable lower value. Similarly an asset sold directly by an owner in the market will fetch better value and if the same asset/ property is sold by any financer due to encumbrance on it will fetch lower value. Hence before financing, Banker/ FI should take into consideration all such future risks and should loan conservatively to keep the advanced money safe in case of any such situation.
h)	Getting cizra map or coordination with revenue officers for site identification is not done at our end.
i)	Valuation is done for the property identified to us by the owner/ owner representative. At our end we have just cross verified the identification of the property with reference to the documents produced for perusal. Method by which identification of the property is carried out is also mentioned in the report clearly. Responsibility of identifying the correct property to the Valuer/ its authorized surveyor is solely of the client/ owner for which Valuation has to be carried out. It is requested from the Bank to cross check from their own records/ information if this is the same property for which Valuation has to be carried out to ensure that owner has not misled the Valuer company or misrepresented the property due to any vested interest.
j) k)	In India more than 70% of the geographical area is lying under rural/ remote/ non municipal/ unplanned area where the subject property is surrounded by vacant lands having no physical demarcation or having any display of property survey or municipal number / name plate on the property clearly. Even in old locations of towns, small cities & districts where property number is either not assigned or not displayed on the properties clearly and also due to the presence of multiple/ parallel departments due to which ownership/ rights/ illegal possession/ encroachment issues are rampant across India and due to these limitations at many occasions it becomes tough to identify the property with 100% surety from the available documents, information & site whereabouts and thus chances of error, misrepresentation by the borrower and margin of chances of error always persists in such cases. To avoid any such chances of error it is advised to the Bank to engage municipal/ revenue department officials to get the confirmation of the property to ensure that the property shown to Valuer/ Banker is the same as for which documents are provided.
к)	Township then approvals, maps of the complete group housing society/ township is out of scope of this report and this report will be made for the specific unit based on the assumption that complete Group Housing Society/ Integrated Township must be approved in all respect



l)	Due to fragmented & frequent change in building/ urban planning laws/ guidelines from time to time, different laws/ guidelines between regions/ states and no strict enforceability of Building Bye-Laws in India specially in non-metro and scale b & c cities & Industrial areas, property owners many times extend or make changes in the covered area/ layout from the approved/ applicable limits. There are also situations where properties are decades old when there was no formal Building Bye-Laws applicable when the construction must have been done. Due to such discrete/ unplanned development in many regions sometimes it becomes tough to determine the exact lawful situation on ground for the Valuer. In case nothing specific is noted on the covered built-up area considered in the Valuation Report, the covered area present on the site as per site survey will be considered in the Valuation.
m)	Valuation is a subjective field and opinion may differ from consultant to consultant. To check the right opinion, it is important to evaluate the methodology adopted and various data point/ information/ factors/ assumption considered by the consultant which became the basis for the Valuation report before reaching to any conclusion.
n)	Value analysis of any asset cannot be regarded as an exact science and the conclusions arrived at in many cases will, of necessity, be subjective and dependent on the exercise of individual judgment. Given the same set of facts and using the same assumptions, expert opinions may differ due to the number of separate judgment decisions, which have to be made. Therefore, there can be no standard formula to establish an indisputable exchange ratio. In the event of a transaction, the actual transaction value achieved may be higher or lower than our indicative analysis of value depending upon the circumstances of the transaction. The knowledge, negotiability and motivations of the buyers and sellers and the applicability of a discount or premium for control will also affect actual price achieved. Accordingly, our indicative analysis of value will not necessarily be the price at which any agreement proceeds. The final transaction price is something on which the parties themselves have to agree. However our Valuation analysis can definitely help the stakeholders to make them informed and wise decision about the Value of the asset and can help in facilitating the arm's length transaction.
0)	This report is prepared on the RKA V-L3 (Medium) Valuation format as per the client requirement and scope of work. This report is having limited scope as per its fields & format to provide only the general estimated & indicative basic idea of the value of the property prevailing in the market based on the information provided by the client. No detailed analysis, audit or verification has been carried out of the subject property.
p)	This is just an opinion report and doesn't hold any binding on anyone. It is requested from the concerned Client/ Bank/ Financial Institution which is using this report for mortgaging the property that they should consider all the different associated relevant & related factors & risks before taking any business decision based on the content of this report.
q)	All Pages of the report including annexures are signed and stamped from our office. In case any paper in the report is without stamp & signature then this should not be considered a valid paper issued from this office.
r)	Defect Liability Period is <u>30 DAYS</u> . We request the concerned authorized reader of this report to check the contents, data and calculations in the report within this period and intimate us in writing if any corrections are required or in case of any other concern with the contents or opinion mentioned in the report. Corrections only related to typographical, calculation, spelling mistakes will be entertained within the defect liability period. No request for any illegitimate value revision, date change or any other change will be entertained other than the one mentioned above.
s)	R.K Associates encourages its customers to give feedback or inform concerns over its services through proper channel at valuers@rkassociates.org in writing within 30 days of report delivery. After this period no concern/ complaint/ proceedings in connection with the Valuation Services can be entertained due to possible change in situation and condition of the property.
t)	Our Data retention policy is of <u>ONE YEAR</u> . After this period we remove all the concerned records related to the assignment from our repository. No clarification or query can be answered after this period due to unavailability of the data.
u)	This Valuation report is governed by our (1) Internal Policies, Processes & Standard Operating Procedures, (2) R.K Associates Quality Policy, (3) Valuation & Survey Best Practices Guidelines formulated by management of R.K Associates, (4) Information input given to us by the customer and (4) Information/ Data/ Facts given to us by our field/ office technical team. Management of R.K Associates never gives acceptance to any unethical or unprofessional practice which may affect fair, correct & impartial assessment and which is against any prevailing law. In case of any indication of any negligence, default, incorrect, misleading, misrepresentation or distortion of facts in the report then it is the responsibility of the user of this report to immediately or at least within the defect liability period bring all such act into notice of R.K Associates management so that corrective measures can be taken instantly.
V)	R.K Associates never releases any report doing alterations or modifications by pen. In case any information/ figure of this report is found altered with pen then this report will automatically become null & void.