	The second second		1.700 14	110 11 141				
	File No.	RKA/DN	CR//			NEIN SEIN	FORCING Y	FOUR BUSINESS
Da	te of Receiving	7/9b)		- 1	AS	500	TATES
File	Receiver Name	Doopa	ic Ja	hi				
			-		120 101 11 50 E	71-557-61	449-4	01-514
	DECEMBER	ementellen		AV/-14	slon 5.0) vision: 30(01) 20	-	eventest	Tibleven
	Items	Assign		Assigned to Date	To be completed by date	Submitted On date	Grade	HOD Engg. Signature
File R	leceived By	Ocepak		NA	NA NA			
Surve	ey	Deepar		19/2)	20/9/21			
Prepa	ration							
	A - Very Good, I	B - Satisfac	tory, C - A	verage D -	Poor F - Evtre	maly Poor		
o rea	unprepared due son	prope repre:	rly done, sentative p	perly done, Deligible Photo photo not to	graphs not cl aken, □ Owner	n is not clearly early taken, downer repre	y done, □ I □ Selfie/ esentative s	Measurement is no
o rea		prope repres	erly done, sentative p loogle Map inor defect eyor. Repo	perly done, Photo photo not ta not taken, i cts in the set preparer	☐ Identification graphs not cl aken, ☐ Owner ☐ Survey sumn	n is not clearly early taken, of owner repre- nary sheet no approved for issing informa	y done, D N Selfie/ esentative s t filled preparatio tion on his	Measurement is no Owner or owner signature not taken
o rea	se File is returne e preparer - HOD comment &	prope repres	erly done, sentative p loogle Map inor defect eyor. Repo	perly done, Photo photo not ta not taken, f cts in the rt preparer s in the surv	☐ Identification graphs not cleaken, ☐ Owner ☐ Survey summer survey hence to collect the mixey. Survey has	n is not clearly early taken, of owner repre- nary sheet no approved for issing informa	y done, D N Selfie/ esentative s t filled preparatio tion on his	Measurement is no Owner or owne signature not taken
o rea	se File is returne e preparer - HOD comment &	prope repres	erly done, sentative p loogle Map inor defect eyor. Repo	perly done, Photo photo not ta not taken, f cts in the rt preparer s in the surv	☐ Identification graphs not cl aken, ☐ Owner ☐ Survey summ survey hence to collect the mi	n is not clearly early taken, of owner repre- nary sheet no approved for issing informa	y done, D N Selfie/ esentative s t filled preparatio tion on his	Measurement is no Owner or owne signature not taken
In car by th Engo Sign	se File is returne e preparer - HOD comment & ature	rates prope repres Go ad Surve Ma Order or	erly done, sentative pogle Map inor defective por Repo	perly done, Photo photo not ta not taken, f ets in the sint preparer s in the sun CENIER	☐ Identification graphs not cleaken, ☐ Owner ☐ Survey summer ☐ Survey hence to collect the mixey. Survey has	n is not clearly early taken, or owner repre- mary sheet not approved for issing information to be done a cost estimation cost estimation.	y done, D N Selfie/ Selfie/ esentative st filled preparation on his orgain.	Measurement is no Owner or owne signature not taken
In caby the Engo	se File is returne e preparer - HOD g. comment & ature Proposal/ Work Ref. No.	proper repres	is not properly done, sentative pogle Map inor defect eyor. Report ajor defects	perly done, Photo photo not ta not taken, i cts in the sint preparer s in the surv CENIER attion Report	□ Identification graphs not cl aken, □ Owner □ Survey summ survey hence to collect the m vey. Survey has □ Construction cates, □ TEV R □ PSU	is not clearly early taken, of owner representation of the content	y done,	Measurement is no Owner or owne signature not taken on with warning to own.
In car by th Engo Sign 1.	se File is returne e preparer - HOD comment & ature Proposal/ Work Ref. No. Type of Service	rates prope repres Go ad	inor defection of the land	perly done, Photo photo not taken, ots in the set preparer s in the sun clanification Report r CE Certification pany	□ Identification graphs not cl aken, □ Owner □ Survey summ survey hence to collect the mi vey. Survey has □ Construction cates, □ TEV R □ PSU □ Private clien Bank L-	approved for issing information cost estimate eport, □ LIE □ NBFC □ t □ Direct	y done,	Measurement is no Owner or owne signature not taken on with warning to own.
In carby the Engg Sign.	se File is returne e preparer - HOD comment & ature Proposal/ Work Ref. No. Type of Service Type of custome Bank/ FI/ Organ	rates prope repres Go ed	inor defection of the land	perly done, Photo photo not ta not taken, i cts in the rt preparer s in the sun CENIER ation Report r CE Certific	□ Identification graphs not cl aken, □ Owner □ Survey summ survey hence to collect the m vey. Survey has □ Paralles □ Private clien □ Paralles	approved for issing information cost estimate eport, □ LIE □ NBFC □ t □ Direct	y done, Selfie/ Selfie/ esentative s t filled preparatio tion on his or gain. te, Cost Corpora client through	Measurement is no Owner or owne signature not taken on with warning to own.
In carby the Engg Sign. 1. 2. 3.	se File is returne e preparer - HOD comment & ature Proposal/ Work Ref. No. Type of Service Type of custome Bank/ FI/ Organ Name & Addres	rates prope repres Go ad Surve Ma Order or er dization as Officer/	inor defection of the land	perly done, Photo photo not taken, cts in the sint preparer s in the sun CENIER Attion Report CE Certific pany Attintal	□ Identification graphs not cl aken, □ Owner □ Survey summ survey hence to collect the mi vey. Survey has □ PSU □ Private clien □ PSU □ Contact □	approved for issing information cost estimate eport, □ LIE □ NBFC □ LIC □ Direct	done, D of the control of the contro	Measurement is no Owner or owne signature not taken on with warning to own.
In carby th Engg Sign. 1. 2. 3.	se File is returne e preparer - HOD comment & ature Proposal/ Work Ref. No. Type of Service Type of custome Bank/ FI/ Organ Name & Addres Case Allotment	rates prope repres Go ad Surve Ma Order or er dization as Officer/	inor defects and Defects Anni	perly done, Photo photo not taken, cts in the sint preparer s in the sun CENIER Ation Report r CE Certific pany Name	□ Identification graphs not cl aken, □ Owner □ Survey summ survey hence to collect the m vey. Survey has □ PSU □ Private clien □ PSU □ Contact □ PSU □ Private clien □ PSU □ Private clien	approved for issing information cost estimate eport, □ LIE □ NBFC □ HOUSE UNITED TO THE UNITED TO TH	done, Did done, Selfie/ Selfie/ Selfie/ Sesentative set filled preparation on his selfie done on his selfie	Measurement is no Owner or owne signature not taken on with warning to own. vetting certificate ate ugh Bank
In carby the Engo Sign. 1. 2. 3.	se File is returne e preparer - HOD comment & ature Proposal/ Work Ref. No. Type of Service Type of custome Bank/ FI/ Organ Name & Addres Case Allotment Fees paying pair	rates prope repres Go ad Surve Ma Order or er dization as Officer/	inor defects Valua Other Comp	perly done, Photo photo not taken, cts in the sint preparer s in the sun CENIER ation Report r CE Certific pany Name Pathak	□ Identification graphs not cl aken, □ Owner □ Survey summ survey hence to collect the m vey. Survey has □ PSU □ Private clien □ PSU □ Contact □ PSU □ Private clien □ PSU □ Private clien	approved for issing information cost estimate eport, □ LIE □ NBFC	done, Did done, Selfie/ Selfie/ Selfie/ Sesentative st filled preparation on his selfie done in his selfie	Measurement is no Owner or owner signature not taken on with warning to own. The wetting certificate attempts and Branch
In carby the Enge Sign. 1. 2. 3.	se File is returne e preparer - HOD comment & ature Proposal/ Work Ref. No. Type of Service Type of custome Bank/ FI/ Organ Name & Addres Case Allotment Fees paying pai	rates prope repres Go ad Surve Ma Order or er dization as Officer/	inor defects and other Comp The N Amour	ets in the survey of the surve	Identification graphs not claken, Survey summer survey hence to collect the mixey. Survey has surv	approved for issing information cost estimate eport, □ LIE □ NBFC	done, Did done, Selfie/ Selfie/ Selfie/ Sesentative st filled preparation on his selfie done in his selfie	wetting certificate signal ld Email ld South G. ddn G count/ customer

Page 1 of 15

- di		Total Control	CASE DETA	LS	STED AT 12	
1.	Type of Property	Reside				
2.	Purpose of Valuation/ Assignment	□ Value assessment of the asset for creating new collateral mortgage □ Periodic Re-Valuation for Bank, □ Distress sale for NPA A/c., □ For DRT Recovery purpose, □ Capital Gains Wealth Tax purpose □ Partition purpose, □ General Value Assessment □ Any other:				
3.	Owner/ Applicant Details	s , Name Contact Number Email Id				r Email Id
		(hando Singh	19 mohan Negi	955719	99998	
4.	Account Name	_				
5.	Property Address	Enclaye D. Du	e imaya k	i Lare lathan	Mo.06	1 H-No. 2/6, EK19 Organa pariwadoon
6.	Who will coordinate on	-	Name			Contact Number
	site for the site survey	Jitendag Singh Negi 9557199998				99998
7.	Preferred time of survey	Date	100 2019	Children and the second	Time	
8.	Documents Received (Any one ownership document and approved site plan/ map is must)	☐ Reg ☐ Cor 2. Map: 3. Utility receip 4. Any O	☐ Cizra Map, ☐ A Bills: ☐ Electric t, ☐ House Tax de	elinquishme Allotment Approved M ity Bill & pa emand & pa CLU,	ent Deed, E Letter, Fap, Site syment reco	☐ Transfer Deed, Possession Letter Plan eipt, ☐ Water Bill & payment
9.	Documents received from	BANK				
10.	Special Instructions if any:					
11.	I agree to pay the amount m on Valuer firm to distort any vested interest and to benefit Customer Signature;	facts and w	ould not try to influ	ence any me	ember or off	I agree that I'll not put pressure ficial of the firm in the ill spirit or lly.

File No. RKA/DNCR/ 1.VIS(2031-33)-PL449-401-514

FILE RECEIVER CASE COLLECTION PROCESS COMPLIANCE CHECKLIST (To be filled by Surveyor)

-	To be filled by Su	(مان المان	
S.NO.	COMPLIANCE CHECKLIST	STATUS	APPROVER SIGNATURE/ REMARKS IN CASE OF ANY (X)
1.	Is Case collection Form properly filled by Receiver?	6	
2.	Is purpose of the assignment understood clearly by the receiver?	9	
3.	Has receiver checked if this is a new case or existing case of the Bank?	D	
4.	Has receiver fixed the fees with the manager/ client and sent quotation properly or have taken approval of the work over email?	100	
5.	Has receiver taken proper Work Order/ Email/ CESA form formality?	0	
6.	In case of private case or for fresh case 50% advance is received?	A	
7.	Is document checklist email sent to the customer?	9	
8.	Has the received documents is having 'documents provided by stamp'?		

IMPORTANT INSTRUCTIONS TO SURVEYOR

1.	Please fill the above compliance checklist before moving for the survey.
2.	Please do not do the survey if you do not have proper documents.
3.	For Vacant Plot/ Land - Cizra Map/ Master/ Zonal/ Site Plan is must to identify the Plot. For Agriculture or converted land from agriculture - Mutation documents, CLU is must.
4.	Firstly please first study the documents of the property which needs to get surveyed.
5.	Mark the Owner/ Area/ Boundaries mentioned in the ownership documents with bold florescent marker pen before moving for the survey. During site survey if any difference is found in the above fields from the ownership documents then please contact the owner immediately to know the reason for the difference.
6.	Confirm ongoing property rates in the subject location through public domain, property sites and contact dealers to show you the available properties in that area during your survey.
7.	Identify the Property clearly by matching the boundaries and area mentioned in the property papers.
8.	Do sample physical or google measurements of the property.
9.	PHOTOGRAPH INSTRUCTIONS: a. Take owner/ representative photograph along with the property. b. Take your selfie along with the property and the owner/ representative. c. Take full scale photo of the property with gate. d. Take photo of the property along with abutting road, towards left, right and center. e. Take multiple photos of inside-out of the property. f. Take nearby photographs of the Property. g. Take a short video to cover property and neighborhood.
10.	Take Google Map location.
11.	Check main road name & width and approach road width and distance of property from main road.
12.	Check Jurisdiction Municipal Limits & Ward Name.
13.	Fill each column of survey form diligently in detail and tick the appropriate option clearly.
14.	Check any defects or negativity in the property and comment in detail on survey form.
15.	Do extensive market rate enquiries and confirm for any recent past transactions.
16.	In case customer appears to be providing misleading information to you or trying to influence you by money or cash then immediately report to the Management & Bank.

LTANGE TO

GRADE	BURVEY GRADING MATRIX
A	In case all the points below are done properly, timely with full care and diligence: 1. Survey started with proper work order and knowing the source of payment. 2. Survey done with proper documents. 3. Done complete homework and studied the documents properly with highlighting the main points before moving for the survey. 4. Chosen correct survey form as per the property type. 5. All fields of Survey form are properly filled. 6. All site special observations and negative and positive factors are clearly mentioned. 7. Self & client signatures taken on survey form. 8. Property rates information properly taken, mentioned and verified. 9. Site rough sketch plan made. 10. Proper photographs taken. 11. Selfie with property taken. 12. Selfie and owner photograph with
В	points are covered.
С	In case of more than 3 minor mistakes and any 1 major mistake in any of the above points and if any points are completely missing except Point 1, 2, 3, 4,6,0,45, that are in any of the above points and if any points
D	In case of 1 major mistake or missing of any 1 point out of 4.2.
E	In case of more than 1 major mistakes or missing of more than 1 point out of 1, 2, 3, 4, 6, 8, 10, 11, 12.

Note (Survey Grading Matrix):

- For special assignments like LIE, Stock Valuation, etc. where till date survey format is not specified or released, in such cases point wise site observation report has to be submitted by the Surveyor duly signing it properly. Without signed Site Observation report, Point 4 will be considered as not done and will fall under Category E.
- 2. Similar Grading Matrix is issued for Case Collection & Report Preparation as well.

Note (Overall Grading Matrix):

 In case client reports any careless mistake in the report for which revision has to be done in the report then in that case Grading Matrix may be revised and Grade E will be awarded.

S.NO.	(To be submitted by Surveyor with each Survey) COMPLIANCE CHECKLIST POINTS					
S.NO.		SURVEY PROCESS COMPLIANCE CHECKLIST (To be submitted by Surveyor with each Survey)				
	an inter of legitle of 1 office	STATUS				
1.	Did you take proper property documents to carry out the survey?	4				
2.	Have you properly studied & highlighted Owner/ Area/ Boundaries in the property documents with bold florescent before moving for the survey?	B				
3.	Did you check prominent landmark nearby the subject property and mentioned in the survey form?	9				
4.	Did you identified the Property clearly by matching the boundaries and area mentioned in the property papers?					
5.	Did you check if property is merged with any other property or it is an independent property?	4				
6.	Did you do sample physical or google measurements of the property in case of property more than 2500 sq.mtr?	4				
7.	Did you check for any building violations in the property?	W				
8.	Did you check municipal limits/ jurisdiction/ ward?	4				
9.	Did you take Google Map location and shared it to Maps whatsapp group?	.DI				
10.	Did you check Main road name & width and its distance from the subject property?					
11.	Did you check approach Lane width on which property is located?	01				
12.	Have you taken property full scale photograph with gate?	D				
13.	Have you taken owner/ representative photograph with the property?	01				
14.	Have you taken your selfie with the property along with owner/ representative?	87				
15.	Have you taken photograph of the property along with abutting road and towards left and right of the property?					
16.	Have you taken multiple photographs of the property from inside-out?	1				
17.	Did you check nearby development and whereabouts and commented on survey form?	4				
18.	Did you check any defects or negativity in the property in terms of location, legality, disputes, marketability, salability, etc. and commented on survey form in detail?	9				
19.	Have you filled all the columns of survey form including survey summary sheet properly?	12				
20.	Did you draw site key plan (location map)?	197				
21.	Did you draw rough site sketch plan?	-				
22.	Have you taken self-attested documents from owner/ representative and stamped "documents provided by stamp"?	-				
23.	Did you check any defects or negativity in the property in terms of location, legality, disputes, marketability, salability, etc. and commented on survey form in detail?	4				
24.	Have you confirmed any recent past transactions during market enquiries and enquired property rates locally very rigorously?	47				
25.	Did you take signatures of the owner/ representative on undertaking and survey summary sheet?	山				
26.	Did you signed the undertaking?	w				

For File No.	VIS/2021-222-PL419-40-514
Surveyor Name	Deepak Jahi
Signature	Dochi
Date	20/9/21

GENERAL SURVEY FORM (FOR PROPERTIES OTHER THAN FLATS) (Version 5.0) Pale of implementation 3.02.20 in Last Revision 04.01.2018 Latest Revision 31.10.2020

File No. RKA/DNCR/...../.

		GENERAL DETAILS	
1.	Name of the Surveyor	Deepat Joshi	
2.	Property shown by	Owner, Representative, I locked, survey could not be done	No one was available, Property is from inside Contact No.
		Therebia fringh Maga	95571 99998
3.	Survey Type	☐ Full survey (inside-out with mo ☐ Half Survey (Measurements fo ☐ Only photographs taken (No r	rom outside & photographs)
4.	Reason for Half survey or only photographs taken	☐ Property was locked, ☐ Poproperty, ☐ NPA property so cou	ossessee didn't allow to inspect the uldn't be surveyed completely
5.	How Property is Identified	name plate displayed on the powner representative, □ Enquire □ Identification of the property done	could not be done, Survey was not
6.	Type of Property	Apartment, ☐ Residential Building, ☐ Commercial Office, Floor, ☐ Shopping Mall, ☐ Hotel	nt, ☐ Residential House, ☐ Low Rise ilder Floor, ☐ Commercial Land & ☐ Commercial Shop, ☐ Commercial el, ☐ Industrial, ☐ Institutional, Residential Plot, ☐ Vacant Industrial
7.	Property Measurement	Self-measured, Sample m	easurement only, No measurement
8.	Reason for no measurement	☐ Property was locked, ☐ Own ☐ NPA property so didn't enter	ing so measurement not required her/ possessee didn't allow it, if the property, □ Very Large Property, easure the entire area □ Any other
9.	Purpose of Valuation	Periodic Re-Valuation for Ba	set for creating new collateral mortgage ink, Distress sale for NPA A/c., Capital Gains Wealth Tax purpose al Value Assessment
10.	Type of Loan	Loan, Loan against Property	ake Over Loan, □ Home Improvemen , □ Construction Loan, □ Educationa t Loan, □ Term Loan, □ CC Limi .imit, □ Industrial Loan, □ NA
11.	Loan Amount	NA	

Page 6 of 15

10	d Comment	OWNERS		11 9	900H2127	.127-100000000000000000000000000000000000	SECTION FLORID
1.	Legal Owner Name/s	Chandria		THE RESERVE AND ADDRESS OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED I	mi		DESCRIPTION OF STREET
2.	Property Purchaser Name				U		
3.	Property Address under Valuation	thino. 283/2, Lane No. 6, H. No. 2/6, Etg Endar					
4.	Present Residence Address of	14419	Lauthan	position	Goud	fartungon	MAN
	the Owner/ Purchaser	-			u		
5.	Property constitution	Free Hol	d, 🗆 Lease	Hold			
		L(0)0/411(0	ON DETA	IIS			
1.	Adjoining Properties	East		West	N	orth So	uth
	(Match it with papers with the help of compass or Sun direction and also confirm it with nearby people)	Plot of M Rapput	1	se of Rathore	Prop	. 1	t mgo
2.	Property Facing		t Facing, □			cing. □ 8outh Fac	
3.	Landmark	New 1	MRILL	Hhanp	IN R	sanch, D. Du	n
4.	Ward Name/ No.	NA	11010	Directory.	21.2	50,107, 0 15	
5.	Zone Name	NA					
6.	Main Road Name & Width	Nan		Wid	ith Soft	Distance from	
7.	Approach Road Name & Width	Ring Road	a Cha	-	Road	18 ft 60 d	
8.	Location consideration of the Society	☐ Within Ma	ain city, □ irea, □ Hig	Within Goo	od Urban ality	developed Area, Tery Good, □ Goo	☐ Within d,
9.	Special Location consideration	☐ Park Fac	ing, 🗆 Po	ol Facing, i	☐ Road	Facing, Entran	ce North-
	of the property	East Facing,	☐ Sunligh	t facing			
10.	Characteristics of the locality	☐ Urban developed, ☐ Urban developing, ☐ Semi Urban, ☐ Rural, ☐ Backward, ☐ Industrial, ☐ Institutional					
11.	Category of Society/ locality	☐ High End, ☐ Normal, ☐ Affordable Group Housing, ☐ EWS, ☐ HIG, ☐ MIG, ☐ LIG					
12.	Utilities/ Facilities in the locality		use, 🗆 Wa	alk Trails, [nming Pool, □ Gy lay zone, □ 100	% Power
13.	Proximity to civic amenities	School	Hospital	Market	Metro	Railway Station	Airport
		144	124	214	-	_	_
14.	Any new development in surrounding area		No				

Page 7 of 15

15.	Jurisdiction limits	Nagar Nigam,	Nagar Panchayat, Gr	am Panchayat, Nagar
		Palika Parishad, A	rea not within any munici	pal limits
16.	Jurisdiction Development	□ DDA, □ GDA, □ I	NOIDA, 🗆 GNIDA, 🗆 YE	IDA, □ HUDA, □KMDA,
	Authority Name		er Development Authority	
	7	L		
17.	Municipal Company		development authority li	
17.	Municipal Corporation Name	□ NDMC, □ SDMC,	, 🗆 EDMC, 🗆 Ghaziaba	ad Municipal Corporation,
		☐ Gurgaon Municipa	Corporation, Faridab	ad Municipal Corporation,
		☐ Kolkata Municipal	Corporation, La Dehrado	un Municipal Corporation,
		☐ Area not within	any municipal limits.	☐ Any other Municipal
		Corporation/ Municipa		
		Corporations marriage	anty.	
		PHYSICAL DET	AILS	
1.	Land Area	As per Title deed		As per site survey
		376 S9M	376 SAM	61, X.99
2.	Any conversion to the land use	No		
3.	Land Type	Solid, Rocky	. Marsh Land, Re	eclaimed Land, Water
		logged, Land lock		
	Ot (N-1		1300.00	
4.	Shape of the Land		ingular, 🗆 Trapezium, 🗆	Triangular, Trapezoid,
		☐ Irregular, ☐ NA		
5.	Level of Land	Un road level, □	Below road level, Abo	ove road level, NA
6.	Frontage to depth ratio	Normal frontage,	☐ Less frontage, ☐ Lar	ge frontage, □ NA
7.	Are Boundaries matched	4	☐ No relevant papers ndaries not mentioned in	available to match the available documents
8.	Is Independent access available	Clear independ	ent access is available	, Access available in
	to the property	sharing of other ad	lioining property. No	clear access is available,
_		☐ Access is closed		
9.	Is property clearly demarcated with permanent boundaries?	Yes, No, O	nly with Temporary boun	daries
10.	Is the property merged or colluded with any other property	No		
11.	" [- [[]] [] [] [] [] [] [] []	UD Owner, □ Vaca	nt, 🗆 Lessee, 🗆 Under	Construction, Couldn't
	time of survey	be Surveyed, □ I sealed	Property was locked, E	☐ Bank sealed, ☐ Cour
12.	Current activity carried out in the	이 네 [14]이는 생활 아이를 잃었다면 하는 때문에	: [1] : [1]	l purpose, Godown
	property	☐ Office, ☐ Industr	rial, 🗆 Vacant, 🗀 Locked	d, Any other use:
1.	Construction Status	G/ CONSTRUCTION		100 T 100 M 10 T
4.7	Constitution Status	Built-up proper	ty in use, Under const	truction, No construction


A COL		
2.	Covered Built-up Area	Covered Area, Floor Area, Super Area, Carpet Area
1	Marketon and the second of the	As per Title deed
	(Tick one on the basis of which valuation is to be calculated)	GF-119-13 SgM GF- 1500 Sg
3.		, 50 5- 60
3.	Total Number of Floors in the Building	9+1 FF - 550 S9
4.	Floor on which property is situated	GF only (as FF is not approved)
5.	Type of Unit/ Number of Rooms/ Cabins/ Cubicles	
6.	Building Type	RCC Framed Structure, Load bearing Pillar Beam column,
		☐ Ordinary brick wall structure, ☐ Iron trusses & Pillars, ☐ Scrap abandoned structure
7.	Roof	a. Make: ☐ RBC, ☐ RCC, ☐ GI Shed, ☐ Tin Shed, ☐ Stone
		b. Height: 10f4
	1	c. Finish: Simple plaster, POP Punning, POP False
		Ceiling, □ Coved roof, □ No plaster
8.	Flooring	☐ Vitrified tiles, ☐ Ceramic Tiles, ☐ Simple marble, ☐ Marble
		chips, ☐ Mosaic, ☐ Granite, ☐ Italian Marble, ☐ Kota stone,
		☐ Wooden, ☐ PCC, ☐ Imported Marble, ☐ Pavers, ☐ Chequered
		Tiles, ☐ Brick Tiles, ☐ No Flooring, ☐ Under construction, ☐ Any
9.	Appearance/ Condition of the	other type: Internal - □ Excellent, □ Very Good, □ Good, □ Ordinary,
	Building	□ Average, □ Poor □ Under construction, □ No Survey
	-	External - Excellent, Very Good, Good, Ordinary,
		□ Average, □ Poor □ Under construction
10.	Maintenance of the Building	☐ Very Good, ☐ Average, ☐ Poor, ☐ Under construction
11.	Interior decoration	☐ Excellent, ☐ Very Good, ☐ Good, ☐ Simple, ☐ Ordinary,
1		☐ Average, ☐ Below average, ☐ Under construction, ☐ No Survey
12.	Interior Finishing	Simple plastered walls, Brick walls without plaster,
		□ Designer textured walls, □ POP punning, □ Coved roof,
		☐ Under construction, ☐ No Survey
13.	Exterior Finishing	Simple plastered walls, Brick walls without plaster,
		☐ Architecturally designed or elevated, ☐ Brick tile Cladding,
		☐ Structural glazing, ☐ Aluminum composite panel cladding,
14	Vitabas	☐ Glass façade, ☐ Domb, ☐ Porch, ☐ Under construction
14.	Kitchen	☐ Simple with no cupboard, ☐ Ordinary with cupboard, ☐ Normal Modular with chimney, ☐ High end Modular with chimney, ☐ Under
		construction, No Survey
15.	Class of Electrical fittings	□ External, □ Hiternal
12/2/67		☐ Ordinary fixtures & fittings, ☐ Fancy lights, ☐ Chandeliers,
		☐ Concealed lightning, ☐ Under construction, ☐ No Survey
16.	Class of Sanitary/ Plumbing &	□ External, ☑ Internal
	water supply fittings	☐ Excellent, ☐ Very Good, ☐ Good, ☐ Simple, ☐ Average,
		☐ Below average, ☐ Under construction, ☐ No Survey
17.	Water arrangements	☐ Jet pump, ☐ Submersible, ☐ Jal board supply
18.	Fixed Wooden Work	☐ Excellent, ☐ Very Good, ☐ Good, ☐ Simple, ☐ Ordinary,
		☐ Average, ☐ Below Average, ☐ No wooden work, ☐ No survey
19.	Age of Building/ Recent	2002
200	Improvements done	
20.	Maintenance of the Building \	✓ Very Good, ☐ Average, ☐ Poor

21.	Any defects in the building	☐ Maintenance issues ☐ Fini	abina isang Ela		
	No	 □ Maintenance issues, □ Finishing issues, □ Seepage issues, □ Water supply issues, □ Electricity issues, □ Structural issues, □ Visible cracks in the building 			
22.	Any violation done in the property 10	☐ Construction done without approved Map, ☐ Extra covered.	t Map, Construction not as per		
23.	Boundary Wall (Only for individual property)	adjacent property, ☐ Encroach	led adjacent area illegally		
	property	Running Mtr. Height	Width Finish		
24.	Lift/ elevators	F3.B			
	No	☐ Passenger/ ☐ Commercial Make:			
25	17.5	wake.	Capacity:		
25.	Power backup	☐ Inverter, ☐ DG Set			
		Make:	Capacity:		
26.	Garden/ Landscaping	☐ Yes, ☐ No, ☐ Beautiful, ☐	2-1		
27.	Parking facilities	Available within the property			
			☐ On stilt		
		 Not available within the property 	- Acute parking		
28.	Special Comments/ Observations, if any		problem		
	MARKETABII	LITY/ SELABILITY/ UTLITY D			
1.	Any issues in marketability of the	☐ Yes, ☐ No	HALLS		
	property?		Location, ☐ Surrounding, ☐ Legal e, ☐ Any Other:		
2.	How is Demand & Supply condition	Demand PTVery Good T G	ood, ☐ Average, ☐ Low, ☐ Poor		
	in the Market of such properties?	-7	ood, Average, Low, Poor		
3.	Is property easily sellable &	Supply			
	marketable?	Comments:			
4.	How is the current utility of the property?	☐ ExcellentL Very Good, ☐ Good, ☐ Average, ☐ Low, ☐ Poor			
5.	At what True rate Owner bought this Property?	Year of purchase	1000		
-		Purchase Price	1-1-10		
6.	Present expected Sale Value of the overall property?	r dichase Price			

BLANK PAGE FOR PROVIDING ANY ADDITIONAL DETAILS/ INFORMATION

Graind Floor: 3-Bediloom
3-Washroom
1-Kitchen
1-Diquing
1-Dining

First Floor! 3-Room 1-totchen 1-washnum



FF	(AVEILE	ble for Sale or	Transaction already	happened in past)	
.No	Particulars	Subject Property	Comparable 1	Comparable 2	Comparable 3
1.	Name (source of information)	NA	Kapil Halia	Man Mohan Neg:	
2.	Contact No.	NA	8410636300	9568333761	
3.	Type of source of information (Seller/ Property dealer/ nearby people)	NA	Dealer	Dealer	
4.	Rates/ Price informed (in Rs. with unit)	. NA	2600-3000	30000 Squrd	
5.	Rates Type (Sale/ Buy)	NA	sale	Sale	
6.	Shape of the Property (Square, Rectangular, Irregular)		Rectangular	Rectargular	
7.	Area/ Size of the Property		300 Sq 44d	3505940	
8.	Legal Status (clear, negative, weak)/ No. of owners		Clean	Clean	
9.	Location/ surrounding/ neighborhood comparison with the subject property (Similar, Lower, Better, Highly Better than the subject Property)	Base Case	Smilar	Smilar	
10.	Distance from the subject Property	0	500M	300M	
11.	Other factors (Corner, 2 side open, North-East facing, Park facing, Legal/ Financial encumbrance, etc.)		South	Nanth	
12.	Approach road width		&oft	201-	
13.	Level of Land (Below/ On/ Above road level)		Above	About	
14.	Frontage to depth ratio (Normal, Less, Large)		Normal	Normal	
15.	Present Use		Residential	Residential	
16.	Any other details/ Discussion held	NA	Had a word Nathan pur, 28000 /594	, Etta Enchu	
17.	Present expected Sale Value of the overall property?	_	•		Page 13 of 15

· Secretario de la constitución de la constitución

UNDERTAKING BY THE CUSTOMER

I confirm that I have made the inspection of the subject property to the surveyor of R.K Associates, which is correct property in question for which the documents have been provided/ submitted by me. I further confirm that I am aware of all the information related to the subject property and I have provided all its information to the surveyor true to the best of my knowledge. I understand that any false or manipulative information provided by me will be considered as cheating with the professional organization since it will lead to incorrect valuation report and I'd be solely responsible for this unlawful act and will bear the charges for the changes/modifications which have to undergo due to the false information. I also undertake that I have not given any cash or in kind to any member of R.K Associates to influence the Value of the Property or favor any individual or organization and the same is not accepted or asked by the member of R.K Associates. Any such act will lead to cancellation of the material prepared by R.K Associates with forfeiting of the fees and i'll be completely responsible for its repercussions and legal actions taken for it.

IMPORTANT: We have not authorized any of our person/ Surveyor to take Cash or kind from the customers in any situation. In case Surveyor or any member of R.K Associates asks for any money or kind from you then kindly please inform on number +91-9958632707, 0120-4110117. Our Valuation process is very stringent and have multiple check points to ensure correct & error free reports to keep the lending agency risk free. In case Surveyor claims that he would be able to arbitrary effect the Valuation figures unfairly or as per your requirement & need, then he is making a false claim to you and we request you to complaint such act immediately on the number provided above.

Name	Letcher Ejl
Relationship with owner	Son
Signature	Tel-Si
Mobile No.	955719998
Date	d.

UNDERTAKING BY THE SURVEYOR

I confirm that I have carried out the Survey of the property properly as per the fair professional best practices and Valuation & Survey policy guidelines issued by R.K Associates. I have not taken any cash or kind from the customer nor have I come into any kind of influence of the customer / bank for arbitrary providing the Property Valuation as per one's need. I further state that I have not given any assurances to the customer nor given any wrong or false information or statement. In case at any point of time it is found that I have done any kind of fraudulent activity in this case and misled the company then I understand its legal consequences and appropriate penal action which company can take against me. Also in regard to it any monetary or reputation loss will be recovered from me by the company.

For File No.	V14(2021-92)-PL449-401-514
Surveyor Name	Decept Joshi
Signature	Nesh
Date	20/9/21

UNDERTAKING BY THE PREPARER

I confirm that this Valuation Report is prepared as per the fair professional best practices and Valuation & Survey Policy Guidelines issued by the organization. I also confirm that without any personal interest, partiality or prejudice, I have worked on this Valuation assignment. Rates adopted for the asset is based on various facts, information collected from the site came to my knowledge during the course of the assignment and I have taken all sincere efforts to review, cross check & confirm this data/ information from all different angles using my prudent approach without any biasedness or pressure. I have prepared the report based on true facts & information as per best of my knowledge & case facts. I understand that any false information provided by me will lead to the incorrect valuation report and I'd be solely responsible for it and will bear the losses which will be put on the Company in form of monetary or reputation loss by its client or statutory bodies.

I also undertake that I did not come into any influence by the customer, Bank representative (officer or agent), colleagues, coworkers or any other person to arbitrary change the Valuation figures or facts unethically or illegitimately which may put the public money at risk which is in the form of Bank deposits.

In case at any point of time in future, if I am found guilty of illegitimately distorting the facts in the Valuation or any other professional services which company offers in the market on being influenced by the customer or Bank representative (officer or agent) or for whatsoever reason then I'd solely responsible of any such act and I understand that the Company can take appropriate legal action against me which may include suspension from the current roles & responsibilities or termination from the employment with immediate effect.

I also undertake that I have not taken any cash, favor or in kind from the customer for favoring any individual or organization by unfair means.

I also undertake that I'll not prepare any report on incomplete Survey form which is not properly filled as per the Company guidelines and in case I am preparing it which is creating an incorrect report then I'd be responsible for its consequences.

For File No.	
Preparer Name	
Signature	
Date	



Enclosure: 6

SURVEY SUMMARY SHEET (10) BE ENGLOSED WITH VALUATION REPORTS

(Version 1.0) | Date of implementation: 10.04.2017

Every Valuation report at R.K Associates is prepared based on the thorough survey of the property carried out by our Engineering Surveyor. This Survey Summary Sheet is for the information of Banker/ concerned interested organization. Detailed Survey Form can also be made available to the interested organization in case it is required to cross check what information our surveyor has given in site inspection report based on which Valuation report is prepared.

1.	File No.	VISI2021-22)-PL449-401-514				
2.	Name of the Surveyor	Deepar Joshi				
3.	Borrower Name					
4.	Name of the Owner	Chandela Hotan Sirah Weghi				
5.	Property Address which has to be valued	Hayra Hadram por 10-pur				
6.	Property shown & identified by at spot	Owner, DRepresentative, I could not be done from inside Name	□ No one was available,	☐ Property is locked, survey Contact No.		
7.	How Property is Identified by the Surveyor	☐ From schedule of the properties mentioned in the deed, ☐ From name plate displayed on the property, ☐ Identified by the owner/ owner representative, ☐ Enquired from nearby people, ☐ Identification of the property could not be done, ☐ Survey was not done				
8.	Are Boundaries matched	Yes, No, No relevant papers available to match the boundaries, Boundaries not mentioned in available documents				
9.	Survey Type	Full survey (inside-out with measurements & photographs) Half Survey (Measurements from outside & photographs) Only photographs taken (No measurements)				
10.	Reason for Half survey or only photographs taken	☐ Property was locked, ☐ Possessee didn't allow to inspect the property, ☐ NPA property so couldn't be surveyed completely				
11.	Type of Property	☐ Flat in Multistoried Apartment, ☐ Residential House, ☐ Low Rise Apartment, ☐ Residential Builder Floor, ☐ Commercial Land & Building, ☐ Commercial Office, ☐ Commercial Shop, ☐ Commercial Floor, ☐ Shopping Mall, ☐ Hotel, ☐ Industrial, ☐ Institutional, ☐ School Building, ☐ Vacant Residential Plot, ☐ Vacant Industrial Plot, ☐ Agricultural Land				
12.	Property Measurement	Self-measured, ☐ Sample r	_ □ Self-measured, □ Sample measurement, □ No measurement			
13.	Reason for no measurement	☐ It's a flat in multi storey building so measurement not required ☐ Property was locked, ☐ Owner/ possessee didn't allow it, ☐ NPA property so didn't enter the property, ☐ Very Large Property, practically not possible to measure the area within limited time ☐ Any other Reason:				
14.	Land Area of the Property	As per Title deed	As per Map	As per site survey		
		376 544	376504	HD2 dFE		
15.	Covered Built-up Area	As per Title deed	As per Map	As per site survey		
16.	Property possessed by at the time of survey	☐ Owner, ☐ Vacant, ☐ Less☐ Property was locked, ☐ Bar		on, Couldn't be Surveyed,		
17.	Any negative observation of the					

	property during survey	No
18.	Is Independent access available to the property	Clear independent access is available, Access available in sharing of other adjoining property, No clear access is available, Access is closed due to dispute
19.	Is property clearly demarcated with permanent boundaries?	☐ Yes, ☐ No, ☐ Only with Temporary boundaries
20.	Is the property merged or colluded with any other property	No
21.	Local Information References on property rates	Please refer attached sheet named 'Property rate Information Details.'

Endorsement:

1. Signature of the Person who was present from the owner side to identify the property:

Undertaking: I have shown the correct property and provided the correct information about the property to the surveyor of R.K Associates to the best of my knowledge for which Valuation has to be prepared. In case I have shown wrong property or misled the valuer company in any way then I'll be solely responsible for this unlawful act.

a.	Name of the	Person:	Studen	5
b.	Relation:	Pm		

c. Signature: Jucillarith

d. Date:

In case not signed then mention the reason for it:

No one was available,
Property is locked,
Owner/
representative refused to sign it,
Any other reason:

2. Surveyor Signature who did site inspection:

Undertaking: I have inspected the property and cross verified the property details at site to the extent of a. Matching boundaries of the property, b. Sample measurement of its area, c. Physical condition, d. Property rates as per local information with what is mentioned in the property documents provided to me by the Bank/ interested organization. I have not come under influence of anyone during site inspection and have only recorded the true and factual details in the survey form which I come across during the site survey. I understand that giving any manipulative information in the survey form will lead to incorrect Valuation report which is an unlawful act and i'll be solely responsible for doing it.

a. Name of the Surveyor: Depar Joshi

c. Date: