the state of the s	
File No.	RKA/DNCR//
Date of Receiving	
File Receiver Name	Shrujash. Shetty



## <u>CASE COLLECTION FORM</u> (Version:5.0) Date of implementation, 9.02.2011 | Last Revision: 30.01.2020/ Letest (Revision: 31.5020/)

	items	Assigned		Assigned to Date	To l compl by d	eted	Subm On	nitted date	Grade		OD Engg. lignature
File Rec	ceived By	Shreyash Shetty.		NA ,	N	4					
Survey		Shetty. Diperh. Bedr	nutha				1				
Prepara	ation										
	A - Very Good, E	3 - Satisfactor	y, C - A	verage, D -	Poor, E	- Extre	mely F	oor			
	turned to HOD inprepared due on	rates is properly represer	not prop done, ntative p	erly done,	☐ Ident graphs aken, ☐	ification not cle Owner	is not early owne	clearly aken, er repre	oone, □ □ Selfie sentative	/ Ow	rket survey for urement is not ner or owner ture not taken,
by the	e File is returne preparer - HOD comment & cure	Surveyo	r. Repoi	ts in the of the sun	to collec	t the mi	ssing i	nforma	ion on his	on wi	th warning to
				्रहार <u>ू</u>	VIED E	VIIIS.					
	Proposal/ Work Ref. No.			2021-2				di Elementi			
2.	Type of Service		Valua □ Other	etion Repor r CE Certifi	t, □ Cor cates, □	nstruction	Report,	☐ LIE			ng certificate
3.	Type of custom	<u></u>	☑ Bank □ Com		☐ PSU		nt [		☐ Corpo		Bank .
4.	Bank/ FI/ Organ	And the second second	SB	SI, SAI	N-II,	Mum	bài.				
5.	Case Allotment			Name		Conta	ct Nu	nber		Em	ail Id
5.	Fees paying pa		San	jean Jos	hì				team 4	.15	859 @sbi.
		CITY LAND	Sanjean Joshi 7738069			w. 1					
6.	Case Type			Case for Fre	Fresh Account					unt/ customer	
7.	Fees Details		Amou	nt of Fees	Adva	ance Ar	nount	if any	Fee	s will	be paid by
			6000	+6155		-		✓ Bank □ Cus		□ Customer	
8.	Billing Details			Billed To	Party N	arty Name				GSTI	1

		CASEIDETAIL	S					
1.	Type of Property	Residencial Flat.	B. L. B. L. B. B. C.					
2.	Purpose of Valuation/ Assignment	□ Value assessment of the asset for creating new collateral mortgage □ Periodic Re-Valuation for Bank, □ Distress sale for NPA A/c., □ For DRT Recovery purpose, □ Capital Gains Wealth Tax purpose □ Partition purpose, □ General Value Assessment □ Any other:						
3.	Owner/ Applicant Details	Name	Contact	Number	Email Id			
		Stempor International limited		-	-			
4.	Account Name	M/S Stemkor Inter	national	limited				
5.	Property Address	Flat No. 201, 2nd F	love. Pi	issaile	DI Pride			
		M/S Stemkor Inter Flat No. 201, 2nd F Plot No. 67, T.P. Mumbai - 400050	S. IV , A	Imeida P	ock, Bandra west			
6.	Who will coordinate on	Name		C	ontact Number			
	site for the site survey	Hemanis		98200	30933			
7.	Preferred time of survey	Date 05/03/21		Time (	2.30 pm			
8.	Documents Received (Any one ownership document and approved site plan/ map is must)	<ol> <li>Ownership Documents         □ Registered Will, □ Registered Wills: □ Electricity        □ Electricity</li></ol>	elinquishmer I Allotment L pproved Ma ty Bill & pay emand & pay ☐ CLU, ☐ T	nt Deed, □ T Letter, □ Pos p, □ Site Pla /ment receipt yment receipt	ransfer Deed, session Letter an t,   Water Bill & payment			
9.	Documents received from	Bank						
10.	Special Instructions if any:		et seet e					
11	on Valuer firm to distort ar	mentioned above for the prepara ny facts and would not try to influ fit any individual or organization	ience any me	ember or offici	al of the firm in the ill spirit or			

	File No. RKA/DNCR//		
			NUANCE/CHECK ST
	FILE RECEIVER CASE COLLECTION PROC		HUANGEGHEGRADI
	(To be filled by Sur		
S.NO.	COMPLIANCE CHECKLIST	STATUS	APPROVER SIGNATURE/
			REMARKS IN CASE OF ANY (X)
1.	Is Case collection Form properly filled by Receiver?	V	
A VEHICLE COM			
2.	Is purpose of the assignment understood clearly by the receiver?		
3.	Has receiver checked if this is a new case or existing case of the Bank?		
4.	Has receiver fixed the fees with the manager/ client and sent quotation properly or have taken approval of the work over email?		
5.	Has receiver taken proper Work Order/ Email/ CESA form formality?	V	
6.	In case of private case or for fresh case 50% advance is received?		
7.	Is document checklist email sent to the customer?	. 0	
8.	Has the received documents is having 'documents provided by stamp'?		
	IMPORTANT INSTRUCTION		
1.	Please fill the above compliance checklist before move Please do not do the survey if you do not have prope	r document	suivey.
3.	For Vacant Plot/ Land — Cizra Map/ Master/ Zon Agriculture or converted land from agriculture — Muta	al/ Site Pla	an is must to identify the Plot. For
4.	Firstly please first study the documents of the proper	v which ne	eds to get surveyed.
5.	Mark the Owner/ Area/ Boundaries mentioned in marker pen before moving for the survey. During above fields from the ownership documents the know the reason for the difference.	the owners	ship documents with bold florescent if any difference is found in the
6.	Confirm ongoing property rates in the subject local contact dealers to show you the available properties	tion throug	h public domain, property sites and during your survey.
7.	Identify the Property clearly by matching the bo papers.	undaries a	nd area mentioned in the property
8.	Do sample physical or google measurements of	the propert	y.
9.	PHOTOGRAPH INSTRUCTIONS:		
	a. Take owner/ representative photograph along with	the proper	ty.
	b. Take your selfie along with the property and the o	wner/ repre	sentative.
	c. Take full scale photo of the property with gate.		
	d. Take photo of the property along with abutting roa		left, right and center.
	e. Take multiple photos of inside-out of the property.		
	f. Take nearby photographs of the Property.	rhaad	
40	g. Take a short video to cover property and neighbo	111000.	
10.		width and d	istance of property from main road
11.		widhi aliu u	istance of property from main road.
12.		ail and tick	the appropriate entire clearly

Check any defects or negativity in the property and comment in detail on survey form.

In case customer appears to be providing misleading information to you or trying to influence you by

Do extensive market rate enquiries and confirm for any recent past transactions.

money or cash then immediately report to the Management & Bank.

14.

15.

ARREST	SURVEY GRADING MATRIX
GRADE	PARAMETERS/ CRITERIA
Α	In case all the points below are done properly, timely with full care and diligence:
	<ol> <li>Survey started with proper work order and knowing the source of payment.</li> <li>Survey done with proper documents.</li> <li>Done complete homework and studied the documents properly with highlighting the main points before moving for the survey.</li> <li>Chosen correct survey form as per the property type.</li> <li>All fields of Survey form are properly filled.</li> <li>All site special observations and negative and positive factors are clearly mentioned.</li> <li>Self &amp; client signatures taken on survey form.</li> <li>Property rates information properly taken, mentioned and verified.</li> <li>Site rough sketch plan made.</li> <li>Proper photographs taken.</li> </ol>
	11. Selfie with property taken.
В	12. Selfie and owner photograph with property taken.
В	In case of 3 minor mistakes in any of the above points except Point 1, 2, 3, 4, 6, 8, 10, 11, 12 but all the points are covered.
С	In case of more than 3 minor mistakes and any 1 major mistake in any of the above points and if any points are completely missing except Point 1, 2, 3, 4, 6, 8, 10, 11, 12.
D	In case of 1 major mistake or missing of any 1 point out of 1, 2, 3, 4, 6, 8, 10, 11, 12.
E	In case of more than 1 major mistakes or missing of more than 1 point out of 1, 2, 3, 4, 6, 8, 10, 11, 12.

#### Note (Survey Grading Matrix):

- For special assignments like LIE, Stock Valuation, etc. where till date survey format is not specified or released, in such cases point wise site observation report has to be submitted by the Surveyor duly signing it properly. Without signed Site Observation report, Point 4 will be considered as not done and will fall under Category E.
- 2. Similar Grading Matrix is issued for Case Collection & Report Preparation as well.

#### Note (Overall Grading Matrix):

1. In case client reports any careless mistake in the report for which revision has to be done in the report then in that case Grading Matrix may be revised and Grade E will be awarded.

	SURVEY PROCESS COMPLIANCE CHECKLIST	
	(To be submitted by Surveyor with each Survey)	
NO.	COMPLIANCE CHECKLIST POINTS	STATUS
	Did you take proper property documents to carry out the survey?	V
2.	Have you properly studied & highlighted Owner/ Area/ Boundaries in the property documents with bold florescent before moving for the survey?	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
3.	Did you check prominent landmark nearby the subject property and mentioned in the survey form?	
4.	Did you identified the Property clearly by matching the boundaries and area mentioned in the property papers?	
5.	Did you check if property is merged with any other property or it is an independent property?	
6.	Did you do sample physical or google measurements of the property in case of property more than 2500 sq.mtr?	
7.	Did you check for any building violations in the property?	
8.	Did you check municipal limits/ jurisdiction/ ward?	
9.	Did you take Google Map location and shared it to Maps whatsapp group?	
10.	Did you check Main road name & width and its distance from the subject property?	D
11.	Did you check approach Lane width on which property is located?	V
12.	Have you taken property full scale photograph with gate?	V
	Have you taken owner/ representative photograph with the property?	
13.	Have you taken your selfie with the property along with owner/ representative?	
14. 15.	Have you taken photograph of the property along with abutting road and towards left and right of the property?	
16.	Have you taken multiple photographs of the property from inside-out?	
17.	to be a should and commented on survey	
18.	Did you check any defects or negativity in the property in terms of location, legality, disputes, marketability, salability, etc. and commented on survey form in detail?	V
19	f and including survey summary silect	
20		
21	D: Long draw rough site sketch plan?	
22	. Have you taken self-attested documents from owner/ representative and stamped	
23	Did you check any defects or negativity in the property in terms of location, legality,	
24	Have you confirmed any recent past transactions during market enquiries and	
2	5. Did you take signatures of the owner/ representative on undertaking and survey summary sheet?	
2	6. Did you signed the undertaking?	

For File No.	VIS (2021-22)-PL520-450 -11
Surveyor Name	Dipuh Bedmitha
Signature	Deseduithe.
Date	05/03/22

# GENERAL SURVEY FORM (FOR PROPERTIES OTHER THAN FLATS)

(Version 5:0)

Date of implementation: 9.02.2011 | Last Revision: 04.01.2018 | Latest Revision: 31.10.2020

File No. RKA/DNCR//.	Date:	05/03	122	Time:	12.30	pm	

			<u>GENERAL DETAILS</u>							
	1.	Name of the Surveyor	Dipesh Bedmutha							
	2.	Property shown by	☐ Owner, ☐ Representative, ☐ N	o one was available, D Property is						
		To L	locked, survey could not be done from inside Tenant / Lesse							
		Tenant (Flat was on Rent)	Name	Contact No.						
		CETAT Was III (1811)	Hemani. S	98200 309 33						
	3.	Survey Type	☐ Full survey (inside-out with mea							
		Sample Measurents &	☐ Half Survey (Measurements from outside & photographs)							
		only how photos of hall & Kit	Only photographs taken (No me	asurements)						
	4.		☐ Property was locked, ☐ Poss	essee didn't allow to inspect the						
		photographs taken	property,   NPA property so could	n't be surveyed completely						
	5.	How Property is Identified	☐ From schedule of the propertie	s mentioned in the deed, From						
		alter that a	name plate displayed on the pro	perty, V Identified by the owner/						
		Constitution And Continue Constitution	owner representative, Figured	from nearby people,						
		A Service		uld not be done, ☐ Survey was not						
		T. C.	done							
	6.	Type of Property	☐ Flat in Multistoried Apartment, ☐ Residential House, ☐ Low Ris Apartment, ☐ Residential Builder Floor, ☐ Commercial Land							
			Building, □ Commercial Office, □ Commercial Shop, □ Commercial							
			Floor, □ Shopping Mall, □ Hotel, □ Industrial, □ Institutional,							
			☐ School Building, ☐ Vacant Residential Plot, ☐ Vacant Industrial							
			Plot, ☐ Agricultural Land							
	7.	Property Measurement		surement only,   No measurement						
	8.	Reason for no measurement	☐ It's a flat in multi storey building							
		The Tenant did not allow	☐ Property was locked, ☐ Owner/	possessee didn't allow it,						
,		to take photographs &	☐ NPA property so didn't enter th	e property, □ Very Large Property,						
		to take photographs & measurement of Rooms.	practically not possible to meas	ure the entire area   Any other						
Meyw	event	Photos of only Hull, passage	Reason:							
		& Kitchen was allowed.								
	9.	Purpose of Valuation		for creating new collateral mortgage						
		CHINAL SECTION	Periodic Re-Valuation for Bank							
			For DRT Recovery purpose, ☐ Capital Gains Wealth Tax purpose							
			☐ Partition purpose, ☐ General V	and a first Electrophysical and replaced to the contract of the contract of						
	10.	Type of Loan		e Over Loan,  Home Improvement						
		Business Loan	Loan, ☐ Loan against Property, ☐ Construction Loan, ☐ Educational							
				oan, ☐ Term Loan, ☐ CC Limit						
	44	Loop Amount	enhancement,   Cash Credit Lim	ii, 🗆 iiidustriai Loan, 🚜 NA						
	11.	Loan Amount								
	1-57	Market Statement Co. Market Statement								

		OWNERSHIP DETAILS					
1.	Legal Owner Name/s	MIS Stemkor International Private Limited.					
2.	Property Purchaser Name	M/S Stempor International Prixate Limited					
3.	Property Address under						
	Valuation	Flat No. 201 2nd Floor, Prinacle 'D' Pride, Plot No. 67, T. P.S. IV, Almeida Park, Bardra West Mumbai - 400050					
4.	Present Residence Address of	Mumsul - 400050					
	the Owner/ Purchaser						
5.	Property constitution	☐ Free Hold, ☐ Lease Hold					
	VIII state and the second	Runeja Classic. Manisha Bullding.					
		LOCATION DETAILS					
1.	Adjoining Properties	East West North South					
	(Match it with papers with the help	Building Building Shiva Passeye compaind, compained, Apartments lifts,					
	of compass or Sun direction and	Building Building Shiva Passeye compound, compound, compound, Apartments lifts,					
2.	also confirm it with nearby people)	- cturcase					
2.	Property Facing	☐ East Facing, ☐ North Facing, ☐ West Facing, ☐ South Facing,					
	W — E	☐ North-East Facing, ☐ South-West Facing, ☐ South-East Facing,					
	Entry	□ North-West Facing					
3.	Landmark	Aza Shopping Moul.					
4.	Ward Name/ No.	Bandry - F					
5.	Zone Name						
6.	Main Road Name & Width	Name Width Distance from property					
	Corner local.	Couranak Moery. Aprox 25 ft. 70 m					
7.	Approach Road Name & Width	3rd wad - Aprix & to 20 ft.					
8.	Location consideration of the	☐ Within Main city, ☐ Within Good Urban developed Area, ☐ Within					
	Society	developing area, ☐ Highly posh locality, ☐ Very Good, ☐ Good,					
		□ Ordinary, □ In interiors, □ Remote area, □ Backward, □ Average,					
		□ Poor					
9.	Special Location consideration	☐ Park Facing, ☐ Pool Facing, ☐ Road Facing, ☐ Entrance North-					
	of the property	East Facing, Sunlight facing Building Road Jaung-					
10.	Characteristics of the locality	Urban developed, □ Urban developing, □ Semi Urban, □ Rural,					
		□ Backward, □ Industrial, □ Institutional					
11.	Category of Society/ locality	High End, Normal, Affordable Group Housing, EWS, HIG,					
12	. Utilities/ Facilities in the locality	☐ MIG, ☐ LIG  ☐ Lifts, ☐ Garden, ☐ Landscaping, ☐ Swimming Pool, ☐ Gym,					
1,2	. January Lamines III the locality	☐ Club House, ☐ Walk Trails, ☐ Kids play zone, ☐ 100% Power					
		Backup					
13	. Proximity to civic amenities	School Hospital Market Metro Railway Station Airport					
		240m 270m 230m - 1.3 km, 11 km					
14		Repair work of entire Building Bandra Mumbal Foling on currently. Phy Intl					
	surrounding area						
		Page 7 of 15 Arport					

AF I	India disas and a							
15.	Jurisdiction limits	□ Nagar Nigam, □ Nagar Panchayat, □ Gram Panchayat, □ Nagar						
	DNIC	Palika Parishad, ☐ Area not within any municipal limits						
16.	Jurisdiction Development	□ DDA, □ GDA, □ NOIDA, □ GNIDA, □ YEIDA, □ HUDA, □KMDA,						
	rationty Name	☐ MDDA, ☐ Any other Development Authority:						
		☐ Area not within any development authority limits						
17.	Mussiainalo	□ NDMC, □ SDMC, □ EDMC, □ Ghaziabad Municipal Corporation,						
		☐ Gurgaon Municipal Corporation, ☐ Faridabad Municipal Corporation						
		☐ Kolkata Municipal Corporation, ☐ Dehradun Municipal Corporation						
		☐ Area not within any municipal limits, ☐ Any other Municipal						
		Corporation/ Municipality:						
		PHYSICAL DETAILS						
1.	Land Area	As per Title deed						
		Company of the least of the lea						
2.	Any conversion to the land use							
		NA.						
3.	Land Type	Solid,  Rocky,  Marsh Land,  Reclaimed Land,  Water						
	ASSESSMENT CONSTRUCTION	logged, □ Land locked						
4.	Shape of the Land	☐ Square, ☐ Rectangular, ☐ Trapezium, ☐ Triangular, ☐ Trapezoid,						
	Flat Survey.	□ Irregular, ☑ NA						
5.	Level of Land	☐ On road level, ☐ Below road level, ☐ Above road level, ☐ NA						
6.	Frontage to depth ratio	☑ Normal frontage, ☐ Less frontage, ☐ Large frontage, ☐ NA						
7.	Are Boundaries matched	☐ Yes, ☐ No, ☑ No relevant papers available to match the						
		boundaries,   Boundaries not mentioned in available documents						
8.	Is Independent access available to the property	Clear independent access is available,   Access available in						
		sharing of other adjoining property,   No clear access is available,						
9.	Is property clearly demarcated	☐ Access is closed due to dispute						
	with permanent boundaries?	✓ Yes, □ No, □ Only with Temporary boundaries						
10	<ul> <li>Is the property merged or colluded with any other property</li> </ul>	Na						
11		, — Louising Dider Construction. — Collida						
	time of survey	be Surveyed, ☐ Property was locked, ☐ Bank sealed, ☐ Court sealed						
12								
	property	☐ Office, ☐ Industrial, ☐ Vacant, ☐ Locked, ☐ Any other use:						
Malacia								
1.	Construction Status	G/CONSTRUCTIONAUTILITY/DETAILS						
	Sonsil delion Status	Built-up property in use, □ Under construction, □ No construction						

/								
2.	Cover	ed Built-up Area	☐ Covered Area, ☐	Floor Area, 🗆 Super Are	ea, Carpet Area			
			As per Title deed	As per Map	As per site survey			
		one on the basis of which tion is to be calculated)	Coupet Area!		571.08 ft2			
3.		Number of Floors in the	1350 Sq. Ft	1 1 1-1 25	210075			
J.	Build		& Bateme	nt + Or + & F	The len and			
4.	Floor	r on which property is situated	2nd Flow		not allow to the			
5.	1	e of Unit/ Number of Rooms/ ins/ Cubicles	2 BHK.		hooms.			
6.	No. of the last	ding Type	RCC Framed St	ructure,   Load bearing	ng Pillar Beam column,			
0.	Built	ung Type	Ordinary brick w	all structure.   Iron trus	sses & Pillars,   Scrap			
			shandaned structure					
	-		aballubried structure	RCC D GI Shed.	☐ Tin Shed, ☐ Stone			
7.	Roo	of	Patla	у 1,00°, п ст спост,				
			h Height: Q 2	45 ft ,				
			b. rieight. 613	95 TL	Punning, POP False			
			c. Finish: \square Sim	iple plaster, W ror i	diffing, D			
			Ceiling, Li Cove	ed roof,  No plaster	mple marble,   Marble			
8.	Flo	poring	I I Mangio [	Granite Mitalian Mart	ile. Li Kota storie,			
			chips, $\square$ Mosaic, $\square$	C  Imported Marble.	☐ Pavers, ☐ Chequered			
	•		U Wooden, LI PC	.c, □ Imported Marsis,	der construction,  Any			
_	Α.	ppearance/ Condition of the	Internal - D Exc	ellent, D Very Good,	☐ Good, ☐ Ordinary,			
9		uilding	other type:  Internal - □ Excellent, □ Very Good, □ Good, □ Ordinary, □ Average, □ Poor □ Under construction, □ No Survey					
		ulluling	External - Description Repair with going a					
			□ Average □ Por	or Under construction	Repair work going or			
-	0 1	Naintenance of the Building	☐ Very Good I/I	verage, $\square$ Pool, $\square$ One	iei construction			
			D Excellent M	Very Good \( \Pi \) Good.	☐ Simple, ☐ Ordinary,			
	11.	nterior decoration	☐ Average. ☐ Be	low average, 🛘 Under co	onstruction, LINO Survey			
	10 1	nterior Finishing	Cimple planters	d walls   Rrick walls WI	thout plaster, .			
	12.	Illerior i misimig	☐ Designer textur	ed walls, POP punnin	g, ☐ Coved roof,			
	1 1		□ Under construct	ion,   No Survey				
	12	Exterior Finishing	Simple plas	tered walls,   Brick	walls without plaster,			
	13.	Exterior Fillianing	□ Architecturally	designed or elevated	Brick tile Cladding,			
	1		☐ Structural glazi	ng,   Aluminum compos	site panel cladding,			
			☐ Glass façade,	□ Domb, □ Porch, □ U	with cupboard,  Normal			
	14.	Kitchen	☐ Simple with no	cupboard, Li Ordinary	ar with chimney,  Under			
	LF.		construction, $\square$ N					
		- I CHI	Z External Z In	ternal				
	15.	Class of Electrical fittings	Ordinary fixtu	ures & fittings,  Fand	cy lights,   Chandeliers,			
			Concealed light	ntning,   Under construc	ction,   No Survey			
-	10	Class of Sanitary/ Plumbing &	□ External □ Ir	ternal				
	16.	water supply fittings	□ Excellent □ \	Very Good, ☐ Good, ☐ S	Simple, Li Average,			
			☐ Below averag	e, Under construction,	d supply			
	17.	Water arrangements	☐ Jet pump, ☐	Submersible, Jal boar	□ Simple □ Ordinary			
	18.	Fixed Wooden Work	☐ Excellent, ☑	Very Good, 🗆 Good	, ☐ Simple, ☐ Ordinary,			
			☐ Average, ☐ E	Below Average, ☐ No Wo	oden work,  No survey			
	19.	Age of Building/ Recent	Aprox 15 y	early, here	on work of Building			
		Improvements done	71707 0		pair work going on			
	20.	Maintenance of the Building	☐ Very Good, L	Average, Poor Ke	Proceeding of			

/21.	Any defects in the building	☐ Maintenance issues, ☐ Finishing issues, ☐ Seepage issues,			
	Repair works going on	☐ Water supply issues, ☐ Electricity issues, ☐ Structural issues,			
	Repair works going on in building from outside	☐ Visible cracks in the building			
22.	Any violation done in the property	☐ Construction done without Map, ☐ Construction not as per			
			without sanctioned Map, ☐ Joined		
	νο.	adjacent property, ☐ Encroache			
23.	Boundary Wall (Only for individual	☐ Yes, ☐ No, ☐ Common bour			
	property)	Running Mtr. Height	Width Finish		
0.4					
24.	Lift/ elevators	☐ Passenger/ ☐ Commercial			
	UPK.	Make: Schindler	Capacity: 476 kg, 7 people		
25.	Power backup	☐ Inverter, ☐ DG Set			
	No.	Make:	Capacity:		
26.	Garden/ Landscaping	☐ Yes, ☐ No, ☐ Beautiful, ☐ C			
27.	Parking facilities	Available within the property			
		☐ On stilt			
		☐ Not available within the ☐ On road, ☐ Acute parking			
28.	Special Comments/ Observations,	property problem			
20.	if any	Measurements of Room	of Room (Two rooms).		
		ions, i) the Tenant did not allow to take photos & Measurements of Room (Two rooms).  2) It is a 3 BHK flat converted into 2 BHK Flat.			
7/3/00/17/3					
		ATY/SEVABILITY/JUTETTY/DI	TAILS		
1.	Any issues in marketability of the	Yes, No			
	property?	Reason in case of No:  Location, Surrounding, Legal			
		aspects, ☐ Demand, ☐ Shape, ☐ Any Other:			
2.	How is Demand & Supply condition	Demand ☐ Very Good, ☐ Go	od, □ Average, □ Low, □ Poor		
	in the Market of such properties?	Supply	od, □ Average, □ Low, □ Poor		
3.	Is property easily sellable &	☑ Yes, □ No			
	marketable?	Comments: Grood locality.			
4.	How is the current utility of the	☐ Excellent, ☐ Very Good, ☐ (	Good, ☐ Average, ☐ Low, ☐ Poor		
-	property?  At what True rate Owner bought	Year of purchase	2016, 30th July.		
5.	this Property?	Purchase Price	2018, 3012 JULY		
		Turonase i noc			
6.	Present expected Sale Value of the				
	overall property?				

## **\*\*\*BLANK PAGE FOR PROVIDING ANY ADDITIONAL DETAILS INFORMATION**

Sample measurement: (2BHK Flat). Height = 8.345ft

Hall:  $-22.12 \text{ ft } \times 15.905 \text{ ft} = 351.7 \text{ ft}^2$ Passage:  $-25.045 \times 4.23 \text{ ft} = 105.91 \text{ ft}^2$ Kitchen:  $-12.41 \text{ ft} \times 9.37 \text{ ft} = 113.47 \text{ ft}^2$ 


(NOTE):-

3BHK converted to 2BHK,

NOTE :-

- 1) It is a 3BHK Flat converted to 28HK.
- 2) The Tenant did not allow to take photos & measurements of Two sooms.

  Only photos & measurements of Hall, Kitchen & passage taken.
- 3) Repair work of Building going on.
- 4) No selfie with Tenant on he did not allow.



	PROPERTY MARKET COMPARABLE RATE INFORMATION DETAILS  (Available for Sale or Transaction already happened in past)				
S.No	Particulars	Subject Property	Comparable 1	Comparable 2	Comparable 3
1.	Name (source of information)	NA	Suni	Sanjary	Tushez
2.	Contact No.	NA	9892278864	9820239162	9869247927
3.	Type of source of information (Seller/ Property dealer/ nearby people)	NA	Property dealer	Proporty dealer	Property dealer
4. ′	Rates/ Price informed (in Rs. with unit)	NA	1) 5.5 (r) nego 2) 6.5 (r) ciable	502	Aprox 6 Or
5.	Rates Type (Sale/ Buy)	NA	Buy.	Buy.	Buy.
6.	Shape of the Property (Square, Rectangular, Irregular)	STATE OF THE STATE			-
7.	Area/ Size of the Property		1) 940 sq. ft corpet	it 1000 fth	Aprox 1 200 Ftl corpet
8.	Legal Status (clear, negative, weak)/ No. of owners		Clear	Clear	clear
9.	Location/ surrounding/ neighborhood comparison with the subject property (Similar, Lower, Better, Highly Better, than the subject Property)	Base Case	surrounding Similar	Surrounding similar	Surrounding. 4 similar
10.	Distance from the subject Property	0	300 m	around sev	in radius of 300 to 400 m
11.	Other factors (Corner, 2 side open, North-East facing, Park facing, Legal/ Financial encumbrance, etc.)	United	ARONIN KIYAKE DI	ACTURE.	
12.	Approach road width	and our the first	Same	Same	Same
13.	Level of Land (Below/ On/ Above road level)		Same	Same	same
14.	Frontage to depth ratio (Normal, Less, Large)		Same	Same	Same
15.	Present Use	a some or extra	Residencial.	Residencial	Residencial.
16.	Any other details/ Discussion held	NA	Both Flots are unfurnished. only blooming is available.	Flat is  Vinfurnished,  one more flat  near survey  site at For	Flat is almeida park which is in swrounding
17.	Present expected Sale Value of the overall property?		Rate includes price of parking.	of area of	to survey site.
				Built up.	Page 13 of 15

### UNDERTAKING BY THE CUSTOMER

correct property in question for which the documents have been provided/ submitted by me. I further confirm that I am aware of all the information related to the subject property and I have provided all its information to the surveyor true to the best of my knowledge. I understand that any false or manipulative information provided by me will be considered as cheating with the professional organization since it will lead to incorrect valuation report and I'd be solely responsible for this unlawful act and will bear the charges for the changes/ modifications which have to undergo due to the false information. I also undertake that I have not given any cash or in kind to any member of R.K Associates to influence the Value of the Property or favor any individual or organization and the same is not accepted or asked by the member of R.K Associates. Any such act will lead to cancellation of the material prepared by R.K Associates with forfeiting of the fees and i'll be completely responsible for its repercussions and legal actions taken for it.

IMPORTANT: We have not authorized any of our person/ Surveyor to take Cash or kind from the customers in any situation. In case Surveyor or any member of R.K Associates asks for any money or kind from you then kindly please inform on number +91-9958632707, 0120-4110117. Our Valuation process is very stringent and have multiple check points to ensure correct & error free reports to keep the lending agency risk free. In case Surveyor claims that he would be able to arbitrary effect the Valuation figures unfairly or as per your requirement & need, then he is making a false claim to you and we request you to complaint such act immediately on the number provided above.

Name	Memani · S
Relationship with owner	Rental/Lesse. (on Rent)
Signature	
Mobile No.	9820030933
Date	05/03/22

## UNDERTAKING BY THE SURVEYOR

I confirm that I have carried out the Survey of the property properly as per the fair professional best practices and Valuation & Survey policy guidelines issued by R.K Associates. I have not taken any cash or kind from the customer nor have I come into any kind of influence of the customer / bank for arbitrary providing the Property Valuation as per one's need. I further state that I have not given any assurances to the customer nor given any wrong or false information or statement. In case at any point of time it is found that I have done any kind of fraudulent activity in this case and misled the company then I understand its legal consequences and appropriate penal action which company can take against me. Also in regard to it any monetary or reputation loss will be recovered from me by the company.

For File No.	VIS (2021-22)-PLS 520-450-1172
Surveyor Name	Dipesh Bedmutha
Signature	DiBedmitha.
Date	05/03/22

Page 14 of 15

## UNDERTAKING BY THE PREPARER

I confirm that this Valuation Report is prepared as per the fair professional best practices and Valuation & Survey Policy Guidelines issued by the organization. I also confirm that without any personal interest, partiality or prejudice, I have worked on this Valuation assignment. Rates adopted for the asset is based on various facts, information collected from the site came to my knowledge during the course of the assignment and I have taken all sincere efforts to review, cross check & confirm this datal information from all different angles using my prudent approach without any biasedness or pressure. I have prepared the report based on true facts & information as per best of my knowledge & case facts. I understand that any false information provided by me will lead to the incorrect valuation report and I'd be solely responsible for it and will bear the losses which will be put on the Company in form of monetary or reputation loss by its client or statutory bodies.

I also undertake that I did not come into any influence by the customer, Bank representative (officer or agent), colleagues, coworkers or any other person to arbitrary change the Valuation figures or facts unethically or illegitimately which may put the public money at risk which is in the form of Bank deposits.

In case at any point of time in future, if I am found guilty of illegitimately distorting the facts in the Valuation or any other professional services which company offers in the market on being influenced by the customer or Bank representative (officer or agent) or for whatsoever reason then I'd solely responsible of any such act and I understand that the Company can take appropriate legal action against me which may include suspension from the current roles & responsibilities or termination from the employment with immediate effect.

I also undertake that I have not taken any cash, favor or in kind from the customer for favoring any individual or organization by unfair means.

I also undertake that I'll not prepare any report on incomplete Survey form which is not properly filled as per the Company guidelines and in case I am preparing it which is creating an incorrect report then I'd be responsible for its consequences.

For File No.		
Preparer Name		
Signature		
Date		

Enclosure: 6

#### <u>SURVEY SUMMARY SHEET</u> (FIO BEEINGLOSED WITH VALUATION REPORT)

(Version 1.0) | Date of implementation: 10.04.2017

Every Valuation report at R.K Associates is prepared based on the thorough survey of the property carried out by our Engineering Surveyor. This Survey Summary Sheet is for the information of Banker/ concerned interested organization. Detailed Survey Form can also be made available to the Interested organization in case it is required to cross check what information our surveyor has given in site inspection report based on which Valuation report is prepared.

- 1	File No.	100(2021-22) = P	1520-450-117	2
1.	124-12-12-12-12-12-12-12-12-12-12-12-12-12-	VISCAULITY I		
2.	Name of the Surveyor	Dipeth Bedmitha		
3.	Borrower Name	MIS Stempor International Private United.  MIS Stempor International Private United.  Flat No. 201, 2nd Floor, Pinnacle DI Pride, Plot. No 67,  T.P.S. IV, Almuda Park, Bandra West, Mumbai - 400050  T.P.S. IV, Almuda Park, Bandra West, Mumbai - 400050		
4.	Name of the Owner	MIS Stempor Linto	Thatloral process	Prido Plot- No 67,
5.	Property Address which has to be	Flat No. 201, 2nd Floor, Fland West, Mumbai - 400050		
	valued	Downer Penresentative	☐ No one was available, ☐	Property is locked, survey
6.	Property shown & identified by at	Owner, Representative, No one was available, Property is locked, survey could not be done from inside Contact No.		
	spot			
		10.	98200	30933
		Hemani S	1 to the e	lood Of From name plate
7.	How Property is Identified by the	From schedule of the pr	Identified by the owner/	owner representative,
	Surveyor	displayed on the property,	e,   Identification of the pr	onerty could not be done,
		Enquired from nearby peop	e, 🗆 Identification of the pr	
		☐ Survey was not done	- Helle to	match the boundaries.
.8.	Are Boundaries matched	☐ Yes, ☐. No, ☑ No re	elevant papers available to	, match the boundary
		☐ Boundaries not mentione	d in available documents	
9.	Survey Type 0 -1 1.c	☐ Full survey (inside-out wit	h measurements & photogra	ipns)
	alexament & Photos	Half Survey (Measurements from outside & photographs)		
	of Hall, Kitchen 4 100 150/2			
10.	Reason for Half survey or only	☐ Property was locked, ☐ Possessee didn't allow to inspect the property, ☐ NPA		
10.	photographs taken	property so couldn't be surveyed completely		
11.	Type of Property	☐ Flat in Multistoried Apartment, ☐ Residential House, ☐ Low Rise Apartment, ☐ Residential Builder Floor, ☐ Commercial Land & Building, ☐ Commercial Office, ☐		
11.	Flat	Residential Builder Floor,	Commercial Land & Building	g, $\square$ Commercial Office, $\square$
	Figi	Commercial Shop,   Comm	nercial Floor, 🗆 Shopping M	all, ☐ Hotel, ☐ Industrial,
		☐ Institutional, ☐ School B	uilding, 🗆 Vacant Residentia	al Plot,   Vacant Industrial
		Plot, Agricultural Land		
12	Property Measurement	☐ Self-measured, ☐ Sampl	e measurement, 🗆 No meas	urement
12.	Reason for no measurement	☐ It's a flat in multi storey	ouilding so measurement not	required
13.	Reason for no measurement	☐ Property was locked, ☑	Owner/ possessee didn't a	llow it, □ NPA property so
		didn't enter the property	☐ Very Large Property,	practically not possible to
		measure the area within lim	ited time 🗆 Any other Reason	on:
				A site suprov
14.	Land Area of the Property	As per Title deed	As per Map	As per site survey
15.	Covered Built-up Area	As per Title deed	As per Map	As per site survey
		Area: 1350 ft 2		571.08 Ft
16.	Property possessed by at the time of	Owner, Vacant, L	essee, Under Constructio	n, □ Couldn't be Surveyed,
	survey		Bank sealed,  Court sealed	
17.	Any negative observation of the	No, only depair	work going on	of Building
		currently.		1

The Fenant did not allow to take photos & Measurements of Two rooms. Only photos & Measurements of Hall, Kitchen & parage taken.

	The second secon	
1	property during survey	Tenant did not allow to take selfie with him.
18.	Is Independent access available to the property	Clear independent access is available,  Access available in sharing of other adjoining property,  No clear access is available,  Access is closed due to dispute
19.	Is property clearly demarcated with permanent boundaries?	✓ Yes, ☐ No, ☐ Only with Temporary boundaries
20.	Is the property merged or colluded with any other property	No .
21.	Local Information References on property rates	Please refer attached sheet named 'Property rate Information Details.'

#### **Endorsement:**

# 1. Signature of the Person who was present from the owner side to identify the property:

Undertaking: I have shown the correct property and provided the correct information about the property to the surveyor of R.K Associates to the best of my knowledge for which Valuation has to be prepared. In case I have shown wrong property or misled the valuer company in any way then I'll be solely responsible for this unlawful act.

a.	Name of the Person: Memouni & S	
b.	Name of the Person: Memouni . S  Relation: Tenant/Leuse (on Rent).  Signature: Date: 05/03/22	
c.	Signature:	
d.	Date: 05/03/2\	
In c	ase not signed then mention the reason for it: $\Box$ No one was available, $\Box$ Properesentative refused to sign it. $\Box$ Any other reason:	erty is locked, 🗆 Owner/

## 2. Surveyor Signature who did site inspection:

Undertaking: I have inspected the property and cross verified the property details at site to the extent of a. Matching boundaries of the property, b. Sample measurement of its area, c. Physical condition, d. Property rates as per local information with what is mentioned in the property documents provided to me by the Bank/interested organization. I have not come under influence of anyone during site inspection and have only recorded the true and factual details in the survey form which I come across during the site survey. I understand that giving any manipulative information in the survey form will lead to incorrect Valuation report which is an unlawful act and I'll be solely responsible for doing it.

a. Name of the Surveyor: Dipesh Bedmutha
b. Signature: DiBedmutha
c. Date: : 05/03/22