

Dehradun Branch Office:

39/3, 1st Floor, Subhash Road Dehradun, REPORT FORMAT: V-L10 (P&M) | Version: 8.0u2010 and (248001)

Ph: 7017919244, 9958632707

File No.: VIS(2021-22)-PL619-537-674

Dated: 11.11.2021

VALUATION REPORT

OF

INDUSTRIAL PLANT & MACHINERY

SITUATED AT

NEAR BUDDHI MATA MANDIR, LAKSAR ROAD, KANKHAL, HARIDWAR UTTARAKHAND

OWNER/S

M/S. EVOLUTION AUTOTECH

A/C: M/S. EVOLUTION AUTOTECH

- Corporate Valuers
- Business/ Enterprise/ Equity Valuations

REPORT PREPARED FOR

- Lender's Independed SINNIA BLOAL BANK, CIRCLE SASTRA BRANCH, HARIDWAR
- Techno Economic Viability Consultants (TEV)

portant - In case of any query/ issue or escalation you may please contact Incident Manager

- Agency for Specialized Account ந்டுந்தோரை (ASES) org. We will appreciate your feedback in order to improve our services.
- Project TechNo TianAsiperdBAtGuidelines please provide your feedback on the report within 15 days of its submission after which report will be considered to be correct.
- Chartered Engineers
- Industry/Trade Rehabilitation Consultants
- NPA Management

CORPORATE OFFICE:

D-39, 2nd floor, Sector 2, Noida-201301

Ph - +91-0120-4110117, 4324647, +91 - 9958632707 E-mail - valuers@rkassociates.org

 Panel Valuer & Techno Economic Consultants for PSU FILE NO.: VIS(2021-22)-PL619-537-674

Other Offices at: Mumbai | Kolkata | Bengaluru | Ahmedabad | Lucknow | Shahjahanpur | Satellite & Shared Office: Moradabad | Meerut | Agra



PART A PLANT & MACHINERY VALUATION PROCEDURE

Name & Address of Branch	Punjab National Bank, Circle Sastra Branch, Haridwar.
Name of Customer (s)/ Borrower Unit	M/s. Evolution Autotech

S.NO.	CONTENTS	DESCRIPTION
1.	INTRODUCTION	
a.	Name of Property Owner	M/s. Evolution Autotech
	Address & Phone Number of the Owner	Near Buddhi Mata Mandir, Laksar Road, Kankhal, Haridwar Uttarakhand
b.	Purpose of the Valuation	For Distress Sale of mortgaged assets under NPA a/c
C.	Date of Inspection of the Property	3 November 2021
d.	Date of Valuation Report	11 November 2021
e.	Name of the Developer of the Property	Owners themselves
	Type of Developer	Property built by owner's themselves

2.	TECHNICAL DESCRIPTION OF THE PI	LANT/ MACHINERY			
a.	Nature of Plant & Machinery	Electric Rikshaw Manufacturing Plant			
b.	Size of the Plant	Small scale Plant			
C.	Type of the Plant	Semi Automatic			
d.	Year of Installation/ Commissioning/ COD (Commercial Operation Date)	2018 as per old valuation report			
e.	Production Capacity	Not Known to us since plant was	un-operational		
f.	Capacity at which Plant was running at the time of Survey	Not Working since Feb. 2019			
g.	Number of Production Lines	1			
h.	Condition of Machines	Average.			
i.	Status of the Plant	Not in operation.			
j.	Products Manufactured in this Plant	Electric Rikshaw			
k.	Recent maintenance carried out on	NA since factory was closed since	e 2019		
I.	Recent upgradation, improvements if done any	No			
m.	Total Gross Block & Net Block of	Gross Block	Net Block		
	Assets	As on 31/1	0/2021		
		Not Known to us.	Not Known to us.		
n.	Any other Details if any	NA			
1.	LOCATION/ ADDRESS WHERE PLANT	T/ MACHINES ARE FOUND TO B	E INSTALLED		
	All the plant and machinery as per the lis	st provided to us is considered to b	oe installed inside the factor		
	which is located Near Buddhi Mata Mand	dir, Laksar Road, Kankhal, Haridwa	ar Uttarakhand.		
2.	SURVEY DETAILS				
	Plant has been surveyed by our Engineering Team on dated 03/11/2021.				

FILE NO.: VIS(2021-22)-PL619-537-674

Page 2 of 17






Page 3 of 17

11.	Site inspection was done	in the presence of Bank's Representative Mr. T.S. Negi who were available			
	from the Bank to furnish a	ny detail about the Plant & Machinery.			
III.	Our team examined & ver	rified the machines and utilities from the list of machines by the Bank. All the			
	major machinery & equipr	ment has been verified. Some of the items were missing at site at the time of			
	site survey. So we have n	ot considered those machines for the purpose of valuation.			
IV.	Photographs have also been taken of many of the Machines and its accessories present at site.				
V.	170				
٧.	All the details have been cross checked as per the old valuation provided to us by the bank and what				
	was observed at the site.	is already through visual absorption only. No technical/ mechanical/			
VI.		es is checked through visual observation only. No technical/ mechanical/			
		en carried out to ascertain the condition and efficiency of machines.			
VII.	Site Survey has been car	ried out on the basis of the physical existence of the assets rather than their			
	technical expediency.				
VIII.	As per the overall site	visit summary, machines appeared to be in average condition but the			
	maintenance is needed.				
3.	MANUFACTURING PRO	CESS			
	NA				
4.	TECHNOLOGY TYPE/ G	ENERATION USED AND TECHNOLOGICAL COLLABORATIONS IF ANY			
-	NA NA				
5.	RAW MATERIALS REQU	IIRED & AVAII ARII ITY			
Э.	Type of Raw Material:	Steel, Mirror, Tires etc.			
	Availability:	As per requirement.			
•					
6.	AVAILABILITY & STATU Power/ Electricity	Yes			
	Water	Yes			
	Road/ Transport	Yes			
7.	COMMENT ON AVAILAB				
	Availability:	Appears to be easily & adequately available.			
	Number of Labours	No one since plant was non-operational.			
	working in the Factory				
8.		AL PROSPECTS OF SUCH PLANTS/ MACHINERY			
0.	Individual machine sale o				
	Reason: The subject Industry is not operational and machines required maintenance as per visual				
	observation. Since the machines present at the site are general purpose machines and can be easily				
		ries so we believe these machines will fetch maximum value in ale as per			
	piecemeal basis.				
9.	100	NT & MACHINERY IN THE MARKET			
Э.	The property of the property o	as per general information available in public domain			
	, appeare to be initiative to	as per general information available in public domain.			



10.	VALUATION PROEDURE
a.	Basic Methodology: For arriving at fair market value of P&M & other fixed assets our engineering
	team has rationally applied the mixture of 'sales comparison approach (market approach)' and the
	'cost approach (depreciated replacement cost)'. The fair market value of Plant & Machinery on the
	date of valuation is its cost of reproduction & commissioning on that date less the depreciation & other
	deterioration deductions (Technological, Economic, Functional obsolescence) or additions for good
	maintenance from the date of commissioning of the machinery to the date of its valuation.
b.	P&M Asset Valuation is done keeping in mind various factors like technology used, machines
	availability, its condition, average age, maintenance & service and parts replacement availability of the
	machines and more importantly demand in the market.
C.	Main Machinery of this Plant are CNC Machine, Hydraulic Shearing, Bending & Punching machines
	while secondary machines are welding machines, motors, lifting jack etc.
d.	The main data point for the Valuation of Plant & Machinery is the list of machines which is provided by
	the bank having asset name and quantity.
e.	Replacement cost has been taken based on the independent market research in secondary market
	from public domain or machinery dealers.
f.	On the Depreciated Replacement Cost (DRC) deduction for obsolescence/ deterioration or addition for
	good maintenance has been taken to arrive at the estimated Prospective Fair Market Value of the
	machines.
g.	Underlying assumption for the evaluation of this Plant & Machinery is that it can be sold individually
	in market since demand of used & second hand machinery of this type is available in the market.
11.	CONSOLIDATED PLANT & MACHINERY VALUATION
	The cost of equipment considered from P&M List doesn't includes Pre-operative, Finance, and IDC
	Charges etc.





	PLANT & MACHINERY VALUATIONS						
S. No.	Description	Qty.	Unit	Rate		Fair Market Value in Rs.	
1	CNC Machine, Make HAAS, Model VF-1D, Serial No. 39042, MFG Year 2004	1	Nos.	1,300,000	₹	1,300,000.00	
2	Hydraulic Shearing Machine, Make-iPan, Mode: IP HVR 415, MFG Year 2017- 18	1	Nos.	280,000	₹	280,000.00	
3	Hydraulic Bending Machine, Make : iPan, Model IP PBR 815, MFG Year 2017-18	1	Nos.	300,000	₹	300,000.00	
4	Hydraulic Punching Machine, Make Rajesh Machines Inida LLP	1	Nos.	250,000	₹	250,000.00	
5	Compressor, Make Comptech	1	Nos.	15,000	₹	15,000.00	
6	Hand Cutter	1	Nos.	1,500	₹	1,500.00	
7	Hand Punching Machine	1	Nos.	2,000	₹	2,000.00	
8	SS Welding Machine	2	Nos.	3,500	₹	7,000.00	
9	Split Air Conditioner	2	Nos.	7,000	₹	14,000.00	
10	Lifting Jack	1	Nos.	1,000	₹	1,000.00	
11	Electrical Panel	1	Nos.	1,500	₹	1,500.00	
12	Electric Rickshaw frame	6	Nos.	17,000	₹	102,000.00	
	Electric Rickshaw	2	Nos.	55,000	₹	110,000.00	
13	Scooter Eterno	1	Nos.	5,000	₹	5,000.00	
14	Electric Rickshaw Alloy Wheel	53	Nos.	750	₹	39,750.00	
15	Electric Rickshaw Tyre	20	Nos.	500	₹	10,000.00	
16	Electric Rickshaw Wind Screen	5	Nos.	3,500	₹	17,500.00	
17	Office Table with 1 High Nick Chair and 02 Low Nick Chair	1	Nos.	5,000	₹	5,000.00	
18	Display Board	1	Nos.	1,500	₹	1,500.00	
19	Inventor with 2 Batteries	1	Nos.	12,000	₹	12,000.00	
20	Fire Extinguisher	5	Nos.	1,000	₹	5,000.00	
21	MS Rack	1	Nos.	1,500		1,500.00	
22	Gas Welding Tank/ Cylinder	2	Nos.	1,200		2,400.00	
23	Study Chair	9	Nos.	450	₹	4,050.00	
24	Miscellaneous (SS pipe, MS Pipe & Strip, Aluminum Frame, Screw & E-rickshaw, Etc.)	1	LS	150,000	₹	150,000.00	
	TOTAL				₹	2,637,700.00	
						104	



PART C CONSOLIDATED VALUATION ASSESSMENT OF PLANT & MACHINERY

S.No.	Particulars	Purchase Value	Prospective Fair Market Value	
1.	Plant & Machinery Value	NA	Rs.26,37,700/-	
2.	Additional Premium if any			
	Details/ Justification			
3.	Deductions charged if any			
	Details/ Justification			
4.	Total Prospective Fair		Rs.26,37,700/-	
	Market Value#			
5.	Rounded Off		Rs.26,40,000/-	
6.	Expected Realizable Value [^]	1000000	Rs.22,44,000/-	
	(@ ~15% less)		NS.22,44,000/-	
7.	Expected Forced Distress		D- 40 80 000/	
	Sale Value* ((@ ~25% less)		Rs.19,80,000/-	

8.	Concluding Comments &	i. We have done the valuation of the machines as per the list
	Disclosures if any	present in the old valuation report provided to us by the bank
		and whatever the machines available at site.
		ii. The valuation is done on market comparable approach. We
		have got the comparable of the machines from the second hand
		market portal.
		iii. No technical verification has been done we have given the value
		only as per physical appearance.
		iv. This Valuation report is prepared based on the copies of the
		documents/ information which interested organization or
		customer could provide to us out of the standard checklist of
		documents sought from them and further based on our
		assumptions and limiting conditions. All such information
		provided to us has been relied upon in good faith and we have
		assumed that it is true and correct.
		v. Legal aspects for e.g. investigation of title, ownership rights,
		lien, charge, mortgage, lease, verification of documents from
		originals, etc. has to be taken care by legal experts/ Advocates.
		vi. This report only contains opinion based on technical & market
		information which came to knowledge during course of the
		assignment. It doesn't contain any recommendations.
		vii. This valuation assessment doesn't cover any Value addition or
		Enterprise/ Company Valuation factors of the Project/ Industry
		which may have additional premium or discounting impact on
		the overall Project/ Industry Value due to various other financial
		conditions of the Project.
		viii. This report is prepared following our Standard Operating
		Procedures & Best Practices, Limitations, Conditions, Remarks,
		Important Notes, Valuation TOR.



PART D

SUMMARY OF THE VALUATION REPORT

S.NO.	CONTENTS	DESCRIPTION		
1.	GENERAL DETAILS			
a.	Report prepared for	Bank		
b.	Name & Address of Organization	Punjab National Bank, Circle Sa	stra Branch, Haridwar	
C.	Name of Borrower unit	M/s. Evolution Autotech		
d.	Name of Property Owner	M/s. Evolution Autotech		
e.	Address & Phone Number of the owner	Near Buddhi Mata Mandir, Laks Uttarakhand	ar Road, Kankhal, Haridwar	
f.	Address at which Plant & Machinery located	Near Buddhi Mata Mandir, Lak Uttarakhand		
g.	Type of the Property	Manufacturing machines lying a	t site	
h.	Nature of Industry	Manufacturing Machines		
i.	Type of Loan	NPA A/C		
j.	Type of Valuation	Plant & Machinery Valuation		
k.	Report Type	Plain Asset Valuation		
1.	Date of Inspection of the Property	3 November 2021		
m.	Date of Valuation Report	11 November 2021		
n.	Bank person name, contact number & designation assisted for Survey	Mr. T.S. Negi (2+91-98978771	69)	
0.	Purpose of the Valuation	Distress Sale for NPA a/c		
p.	Scope of the Assessment	Non Binding Opinion on Ge Assessment of the Plant & Ma as-is-where basis.		
q.	Out-of-Scope of the Assessment Information provided/ available for	 i. Verification of authenticity of documents from original or cross checking from any Govt. deptt. is not done a our end. ii. Legal aspects & rights of the Plant & Machinery ar out-of-scope of this report. iii. Inventorization of P&M is out of scope of work. iv. Componentization of Plant & Machinery is out of scope of this report. v. Identification of the P&M is only limited to cross verification of major machines & production lines. vi. Technical/ mechanical/ operational testing of the machines is out-of-scope of the report. vii. Comment/ determination on technological aspect is out of scope of this report. viii. Any kind of machine/ process design is out of scope of the report. 		
r.	Information provided/ available for assessment	Total 02 documents requested. Detailed Fixed Asset Register/ Inventory Sheet Documents Provided Total 01 documents provided. Machine list having mach		



		E	PC contract agreements	3	Old \	/aluatior	report
S.	Identification of the property	\boxtimes	Cross checked from mentioned in the Invoite the bank.				NAME OF TAXABLE PARTY O
		\boxtimes	Identified by the Bank r	epre	sentative		
	☐ Identified from the available Invoices						
		☐ Identification of the machines could not be done proper				ne properly	
			Due to large number of production lines & mac			-	B1 1877
			Physical inspection of the machines could not be done				

2. BRIEF DESCRIPTION OF THE ASSET UNDER VALUATION

a.



Snapshot of the Asset/ Property Under Valuation

Page **8** of **17**





This valuation report is prepared for plant & machinery pertaining to M/s. Evolution Autotech plant situated at Near Buddhi Mata Mandir, Laksar Road, Kankhal, Haridwar Uttarakhand.

As per the old valuation report provided during site survey M/s. Evolution Autotech was established in 2018 and from 2019 it has been shut down. Currently the plant is non-operational and machines needs some maintenance for proper operation.

3.	VALUATION SUMMARY		
a.	Gross Block	Not provided to us.	
b.	Total Prospective Fair Market Value	Rs.26,40,000/-	
C.	Total Expected Realizable/ Fetch Value	Rs.22,44,000/-	
d.	Total Expected Distress/ Forced Sale Value	Rs.19,80,000/-	

4.	ENCLOSURES	
a.	Part B	Valuation Report as per Punjab National Bank Format
b.	Part C	Consolidated Valuation Assessment of Plant &
		Machinery
C.	Annexure-1	Google Map Location
d.	Annexure-2	Detailed Plant & Machinery calculation
e.	Annexure-3	Photographs of Plant & Machinery
f.	Annexure-4	Survey Summary Sheet - Pages
g.	Annexure-5	Copy of relevant papers from the property documents referred in the Valuation – Pages x






R.K ASSOCIATES IMPORTANT NOTES:

- 1. <u>DEFECT LIABILITY PERIOD</u> In case of any query/ issue or escalation you may please contact Incident Manager by writing at valuers@rkassociates.org. We try our level best to ensure maximum accuracy in the Calculations done, Rates adopted and various other data points & information mentioned in the report but still can't rule out typing, human errors or any other mistakes. In case you find any mistake, variation, discrepancy or inaccuracy in any data point of the report, please help us by bringing all such points into our notice in writing at <u>valuers@rkassociates.org</u> within 30 days of the report delivery, to get these rectified timely, failing which R.K Associates won't be held responsible for any inaccuracy in any manner. Also if we will not hear back anything from you within 30 days, we will assume that report is correct in all respect and no further claim of any sort will be entertained thereafter. We would welcome and appreciate your feedback & suggestions in order to improve our services.
- Our DATA RETENTION POLICY is of <u>ONE YEAR</u>. After this period we remove all the concerned records related to the
 assignment from our repository. No clarification or query can be answered after this period due to unavailability of the
 data
- 3. <u>COPYRIGHT FORMAT</u> This report is prepared on the copyright format of R.K Associates to serve our clients in the best possible way. Legally no one can copy or distribute this format without prior approval from R.K Associates. It is meant only for the organization as mentioned on the cover page of this report. Distribution or use of this format other than R.K Associates will be seen as unlawful act and necessary legal action can be taken against the defaulters.

IF REPORT IS USED FOR BANK/ FIS

NOTE: As per IBA Guidelines in case the valuation report submitted by the valuer is not in order, the banks / FIs shall bring the same to the notice of the valuer within 15 days of submission for rectification and resubmission. In case no such communication is received, it shall be presumed that the valuation report has been accepted.


At our end we have not verified the authenticity of any documents provided to us. Bank is advised to verify the genuineness of the property documents before taking any credit decision.





GOOGLE MAP LOCATION- ANNEXURE I





FILE NO.: VIS(2021-22)-PL619-537-674



Page 2 of 17

PHOTOGRAHS - ANNEXURE II





FILE NO.: VIS(2021-22)-PL619-537-674

M/S. EVOLUTION AUTOTECH








FILE NO.: VIS(2021-22)-PL619-537-674







FILE NO.: VIS(2021-22)-PL619-537-674

Page 19 of 17









VALUER'S REMARKS - ANNEXURE III

i.	This Valuation report is prepared based on the copies of the documents/ information which interested organization or customer could provide to us out of the standard checklist of documents sought from them and further based on our assumptions and limiting conditions. All such information provided to us has been relied upon in good faith and we have assumed that it is true and correct. Verification or cross checking of the documents provided to us from the originals has not been done at our end.
ii.	Legal aspects for e.g. investigation of title, ownership rights, lien, charge, mortgage, lease, verification of documents, etc. have to be taken care by legal expert/ Advocate and same are not done at our end. It is assumed that the concerned Lender/ Financial Institution has asked for the valuation of that property for which the legal verification has been already taken and cleared by the competent Advocate before requesting for the Valuation report.
iii.	Analysis and conclusions adopted in the report are limited to the reported assumptions, conditions and information came to our knowledge during the course of the work.
iv.	Value varies with the Purpose/ Date/ Condition prevailing in the market. We recommend not to refer the indicative & estimated prospective Value of the asset given in this report if any of these points are different from the one mentioned aforesaid in the Report. We also recommend that the indicative estimated Value in the Valuation Report holds good only up to the period of 3 months from the date of Valuation.
V.	This report is having limited scope as per its fields & format to provide only the general basic idea of the value of the property prevailing in the market based on the documents/ data/ information provided by the client. The suggested indicative prospective estimated value should be considered only if transaction is happened as free market transaction.
vi.	This Valuation report is prepared based on the facts of the property on the date of the survey. It is a well-known fact that the market value of any asset varies with time & socio-economic conditions prevailing in the country. In future property Market may go down, property conditions may change or may go worse, Property reputation may differ, Property vicinity conditions may go down or become worse, Property market may change due to impact of Govt. policies or effect of World economy, Usability prospects of the property may change, etc. Hence before financing, Banker/ FI should take into consideration all such future risk and should loan conservatively to keep the advanced money safe in case of the downward trend of the property value.
vii.	Valuation of the same asset/ property can fetch different values in different situations. For egg. Valuation of a running/ operational shop/ hotel/ factory will fetch better value and in case of closed shop/ hotel/ factory it will have considerable lower value. Similarly an asset sold directly by an owner in the market will fetch better value and if the same asset/ property is sold by any financer due to encumbrance on it will fetch lower value. Hence before financing, Banker/ FI should take into consideration all such future risks and should loan conservatively to keep the advanced money safe in case of any such situation.
viii	Getting cizra map or coordination with revenue officers for site identification is not done at our end.
	Valuation is done for the property identified to us by the owner/ owner representative. At our end we have just cross verified the identification of the property with reference to the documents produced for perusal. Method by which identification of the property is carried out is also mentioned in the report clearly. Responsibility of identifying the correct property to the Valuer/ its authorized surveyor is solely of the client/ owner for which Valuation has to be carried out. It is requested from the Bank to cross check from their own records/ information if this is the same property for which Valuation has to be carried out to ensure that owner has not misled the Valuer company or misrepresented the property due to any vested interest.
x.	In India more than 70% of the geographical area is lying under rural/ remote/ non municipal/ unplanned area where the subject property is surrounded by vacant lands having no physical demarcation or having any display of property survey or municipal number / name plate on the property clearly. Even in old locations of towns, small cities & districts where property number is either not assigned or not displayed on the properties clearly and also due to the presence of multiple/ parallel departments due to which ownership/ rights/ illegal possession/ encroachment issues are rampant across India and due to these limitations at many occasions it becomes tough to identify the property with 100% surety from the available documents, information & site whereabouts and thus chances of error, misrepresentation by the borrower and margin of chances of error always persists in such cases. To avoid any such chances of error it is advised to the Bank to engage municipal/ revenue department officials to get the confirmation of the property to ensure that the property shown to Valuer/ Banker is the same as for which documents are provided.
xi.	If this Valuation Report is prepared for the Flat/ dwelling unit situated in a Group Housing Society or Integrated Township then approvals, maps of the complete group housing society/ township is out of scope of this report and this report will be made for the specific unit based on the assumption that complete Group Housing Society/ Integrated Township must be approved in all respect
xii.	Due to fragmented & frequent change in building/ urban planning laws/ guidelines from time to time, different laws/

FILE NO.: VIS(2021-22)-PL619-537-674

Page 16 of 17

M/S. EVOLUTION AUTOTECH



Page 17 of 17

	guidelines between regions/ states and no strict enforceability of Building Bye-Laws in India specially in non-metro and scale b & c cities & Industrial areas, property owners many times extend or make changes in the covered area/ layout from the approved/ applicable limits. There are also situations where properties are decades old when there was no formal Building Bye-Laws applicable when the construction must have been done. Due to such discrete/ unplanned development in many regions sometimes it becomes tough to determine the exact lawful situation on ground for the Valuer. In case nothing specific is noted on the covered built-up area considered in the Valuation Report, the covered area present on the site as per site survey will be considered in the Valuation. Valuation is a subjective field and opinion may differ from consultant to consultant. To check the right opinion, it is
xiii.	important to evaluate the methodology adopted and various data point/ information/ factors/ assumption considered by the consultant which became the basis for the Valuation report before reaching to any conclusion.
xiv.	Value analysis of any asset cannot be regarded as an exact science and the conclusions arrived at in many cases will, of necessity, be subjective and dependent on the exercise of individual judgment. Given the same set of facts and using the same assumptions, expert opinions may differ due to the number of separate judgment decisions, which have to be made. Therefore, there can be no standard formula to establish an indisputable exchange ratio. In the event of a transaction, the actual transaction value achieved may be higher or lower than our indicative analysis of value depending upon the circumstances of the transaction. The knowledge, negotiability and motivations of the buyers and sellers and the applicability of a discount or premium for control will also affect actual price achieved. Accordingly, our indicative analysis of value will not necessarily be the price at which any agreement proceeds. The final transaction price is something on which the parties themselves have to agree. However our Valuation analysis can definitely help the stakeholders to make them informed and wise decision about the Value of the asset and can help in facilitating the arm's length transaction.
xv.	This report is prepared on the RKA V-L10 (Medium P&M) Valuation format as per the client requirement and scope of work. This report is having limited scope as per its fields & format to provide only the general estimated & indicative basic idea of the value of the property prevailing in the market based on the information provided by the client. No detailed analysis, audit or verification has been carried out of the subject property.
xvi.	In case of Valuation of Plant & Machinery or equipment, condition of machines is evaluated by visual observation only. No technical/ mechanical testing of any kind has been carried out at our end to ascertain the condition and efficiency of the machines. Valuation of Plant & Machinery is done on the basis of physical existence of the assets rather than their technical expediency.
xvii.	This is just an opinion report and doesn't hold any binding on anyone. It is requested from the concerned Client/ Bank/ Financial Institution which is using this report for mortgaging the property that they should consider all the different associated relevant & related factors & risks before taking any business decision based on the content of this report.
xviii.	All Pages of the report including annexures are signed and stamped from our office. In case any paper in the report is without stamp & signature then this should not be considered a valid paper issued from this office.
xix.	Defect Liability Period is <u>30 DAYS</u> . We request the concerned authorized reader of this report to check the contents, data and calculations in the report within this period and intimate us in writing if any corrections are required or in case of any other concern with the contents or opinion mentioned in the report. Corrections only related to typographical, calculation, spelling mistakes will be entertained within the defect liability period. No request for any illegitimate value revision, date change or any other change will be entertained other than the one mentioned above.
XX.	R.K Associates encourages its customers to give feedback or inform concerns over its services through proper channel at valuers@rkassociates.org in writing within 30 days of report delivery. After this period no concern/complaint/proceedings in connection with the Valuation Services can be entertained due to possible change in situation and condition of the property.
xxi.	Our Data retention policy is of <u>ONE YEAR</u> . After this period we remove all the concerned records related to the assignment from our repository. No clarification or query can be answered after this period due to unavailability of the data.
xxii.	This Valuation report is governed by our (1) Internal Policies, Processes & Standard Operating Procedures, (2) R.K Associates Quality Policy, (3) Valuation & Survey Best Practices Guidelines formulated by management of R.K Associates, (4) Information input given to us by the customer and (4) Information/ Data/ Facts given to us by our field/ office technical team. Management of R.K Associates never gives acceptance to any unethical or unprofessional practice which may affect fair, correct & impartial assessment and which is against any prevailing law. In case of any indication of any negligence, default, incorrect, misleading, misrepresentation or distortion of facts in the report then it is the responsibility of the user of this report to immediately or at least within the defect liability period bring all such act into notice of R.K Associates management so that corrective measures can be taken instantly.
xxiii.	R.K Associates never releases any report doing alterations or modifications by pen. In case any information/ figure of this report is found altered with pen then this report will automatically become null & void.
	out und the PA