VIS	12021-	23-	1264 -	-016-	055
* . ·	Del 1 Per la Contra	- particular	the second second second second second		

File No. RKA/DNER/..../MVMB4/ Date of Receiving 06/05/2021



File Receiver Name Abhishek . Shanbhag

CASE COLLECTION FORM

(Version 5.0) Date of implementation: 9.02.2011 | Last Revision: 30.01.2020 | Latest Revision: 31.10.2020

Items	Assigned To	Assigned to Date	To be completed by date	Submitted On date	Grade	HOD Engg. Signature
File Received By	Abhishek Shanbhag	NA	NA			
Survey	Abhishek Shanbhag					
Preparation						

A - Very Good, B - Satisfactory, C - Average, D - Poor, E - Extremely Poor

Engg. unprepared due to reason	 Survey not done properly. I Survey Form not properly filled. Market survey for rates is not properly done. Identification is not clearly done. Measurement is not properly done. I Photographs not clearly taken. Selfie/ Owner or owner representative photo not taken. Owner/ owner representative signature not taken. Google Map not taken. Survey summary sheet not filled
-----------------------------------	--

In case File is returned by the preparer - HOD Engg. comment &	Minor defects in the survey hence approved for preparation with warning to Surveyor. Report preparer to chieft the missing information on his own.
Signature	Major defects in the survey Survey has to be done again.

5		SIEVES.	L DETAILS	21.122-	1.1.1	A HOLE AND
1.	Proposal/ Work Order or Ref. No.	VIS (2021-22) - PL-64 - 216 - 054				
2.	Type of Service	Valuation Report	✓ Valuation Report. □ Construction cost estimate. □ Cost vetting certification □ Other CE Certificates. □ TEV Report. □ LIE			ting certificate
3.	Type of customer	Company	 PSU Private cliei 	nt 🗌 Direc	Corporate t client through	Bank
4.	Bank/ FI/ Organization Name & Address	Union Bank Mumbai	Union Bank of India, Hanuman Road, Mumbai			e Barle,
5.	in the Alternal	Name Contact Numbe		act Number	Email Id	
	Fees paying party Details	-			-	
ò.	Case Type	Z Case for Fres	h Account	🗆 Case	for exiting account/ customer	
	Fees Details	Amount of Fees	Amount of Fees Advance Amount if an		Fees will be paid by	
8	1000 00111	30,50046157	7,20	0	🗆 Bank	VZ Custome
	Billing Details	Billed To Pa	arty Name		GST	IN

	241	SUBSER	CASE DETA	ILS	(20 ⁻⁰).00	State of the second second	
1.	Type of Property	La	ind & Bui				
2.	Purpose of Valuation/ Assignment	Perio	 Value assessment of the asset for creating new collateral mortgage Periodic Re-Valuation for Bank, Distress sale for NPA A/c., For DRT Recovery purpose, Capital Gains Wealth Tax purpose Partition purpose, General Value Assessment Any other: 				
3.	Owner/ Applicant Details		Name	Conta	ct Number	Email Id	
			jendra·V. a.h.		73030	ho.svvsuraj@ yahoo.com	
4.	Account Name		v Polytex				
5.	Property Address	Survey	Survey No 118/1/2+1issa-2, Village Dadra, UT- Dadra Nagar Haveli				
6. Who will coordinate on		Name			Contact Number		
	site for the site survey	01/07/2021			937	5838388	
7.	Preferred time of survey	Date	Mr K.D. Ani	il Kumar	Time	10:30 am	
8.	Documents Received (Any one ownership document and approved site plan/ map is must)	 Ownership Documents: □ Sale Deed, □ Power of Attorney, □ Registered Will, □ Relinquishment Deed, □ Transfer Deed, □ Conveyance Deed, □ Allotment Letter, □ Possession Letter Map: □ Cizra Map, □ Approved Map, □ Site Plan Utility Bills: 12 Electricity Bill & payment receipt, □ Water Bill & payment receipt, □ House Tax demand & payment receipt Any Other document: □ CLU, 12 TIR Report, 12 Agreement to Sale, □ Old Valuation Report No documents provided: □ 					
).	Documents received from	Customer (Mr. Dharmendra- 9022325759)				9022325959)	
10.	Special Instructions if any:						
1.	I agree to pay the amount me on Valuer firm to distort any i vested interest and to benefit Custor Signature:	fants and V	vould not try to influe.	nce any me	nper or onic	agree that I'll not put pressure ial of the firm in the ill spirit of	

File No. RKA/DHCR/ /VIS(2021-22)-PL64-816-054

S.NO.	COMPLIANCE CHECKLIST	STATUS	APPROVER SIGNATURE/ REMARKS IN CASE OF ANY (X)
1.	Is Case collection Form properly filled by Receiver?	VE	
2.	Is purpose of the assignment understood clearly by the receiver?	P	
3.	Has receiver checked if this is a new case or existing case of the Bank?	Ø	
4.	Has receiver fixed the fees with the manager/ client and sent quotation properly or have taken approval of the work over email?	Ø	
5	Has receiver taken proper Work Order/ Email/ CESA form formality?	R	
6.	In case of private case or for fresh case 50% advance is received?	U	
7.	is document checklist email sent to the customer?	V	
8.	Has the received documents is having 'documents provided by stamp'?		

IMPORTANT INSTRUCTIONS TO SURVEYOR

1.	Please fill the above compliance checklist before moving for the survey.
2.	Please do not do the survey if you do not have proper documents.
3.	For Vacant Plot/ Land – Gizra Map/ Master/ Zonal/ Site Plan is must to identify the Plot. For Agriculture or converted land from agriculture – Mutation documents, CLU is must.
4.	Firstly please first study the documents of the property which needs to get surveyed.
5.	Mark the Owner/ Area/ Boundaries mentioned in the ownership documents with bold florescent marker pen before moving for the survey. During site survey if any difference is found in the above fields from the ownership documents then please contact the owner immediately to know the reason for the difference.
6.	Confirm ongoing property rates in the subject location through public domain, property sites and contact dealers to show you the available properties in that area during your survey.
7	Identify the Property clearly by matching the boundaries and area mentioned in the property papers.
8.	Do sample physical or google measurements of the property.
9.	PHOTOGRAPH INSTRUCTIONS: a. Take owner/ representative photograph along with the property. b. Take your self e along with the property and the owner/ representative. c. Take full scale photo of the property with gate. d. Take photo of the property along with abutting road, towards left, right and center. e. Take multiple photos of inside-out of the property. f. Take nearby photographs of the Property. g. Take a short video to cover property and neighborhood.
10.	The second stand location
11.	at a serie read name & width and approach road width and distance of property from main road.
12	Check Jurisdiction Municipal Limits & Ward Name.
13.	A A A A A A A A A A A A A A A A A A A
14.	Fill each column of survey form diligency of the property and comment in detail on survey form. Check any defects or negativity in the property and comment in detail on survey form.
15	Check any detects of negativity in the providing for any recent past transactions. Do extensive market rate enquiries and confirm for any recent past transactions.
16.	Do extensive market rate enquines In case customer appears to be providing misleading information to you or trying to influence you be money or cash then immediately report to the Management & Bank.

RADE	SURVEY GRADING MATRIX PARAMETERS/ CRITERIA
A	in case all the points below are done properly, timely with full care and diligence.
	 Survey started with proper work order and knowing the source of payment. Survey done with proper documents. Done complete homework and studied the documents properly with highlighting the main points before moving for the survey. Chosen correct survey form as per the property type. All fields of Survey form are properly filled. All site special observations and negative and positive factors are clearly mentioned. Self & client signatures taken on survey form. Property rates information properly taken, mentioned and verified. Proper photographs taken. Self e with property taken. Self e and owner photograph with property taken.
3	In case of 3 minor mistakes in any of the above points except Point 1, 2, 3, 4, 6, 8, 10, 11, 12 but all the points are covered.
C	in case of more than 3 minor mistakes and any 1 major mistake in any of the above points and if any points are completely missing except Point 1, 2, 3, 4, 6, 8, 10, 11, 12
D	in case of 1 major mistake or missing of any 1 point out of 1, 2, 3, 4, 6, 8, ro, 11, 12
=	In case of more than 1 major mistakes or missing of more than 1 point out of 1, 2, 3, 4, 6, 8, 10, 11, 12

Note (Survey Grading Matrix):

- For special assignments like LIE. Stock Valuation, etc. where till date survey format is not specified or released, in such cases point wise site observation report has to be submitted by the Surveyor duly signing it properly. A thout signed 3 te Observation report. Point 4 will be considered as not done and will fail under Category E.
- 2. Similar Grading Matrix is issued for Case Collection & Report Preparation as well

Note (Overall Grading Matrix):

 In case client reports any careless mistake in the report for which revision has to be done in the report then in that case Grading Motivities, be revised and Grade E will be availed.

SURVEY PROCESS COMPLIANCE CHECKLIST

(To be submitted by Surveyor with each Survey)

S.NO.	COMPLIANCE CHECKLIST POINTS	STATUS			
1.	Did you take proper property documents to carry out the survey?				
2.	Have you properly studied & highlighted Owner/ Area/ Boundaries in the property	JE JE			
Ζ.	documents with bold florescent before moving for the survey?				
3.	Did you check prominent landmark nearby the subject property and mentioned in the survey form?				
4.	Did you identified the Property clearly by matching the boundaries and area mentioned in the property papers?	J.S.			
5.	Did you check if property is merged with any other property or it is an independent property?	J.			
6.	Did you do sample physical or google measurements of the property in case of property more than 2500 sq.mtr?	æ			
7.	Did you check for any building violations in the property?	I			
8.	Did you check municipal limits/ jurisdiction/ ward?	A			
9.	Did you take Google Map location and shared it to Maps whatsapp group?	N			
10.	Did you check Main road name & width and its distance from the subject property?	R			
11.	Did you check approach Lane width on which property is located?	R			
12.	Have you taken property full scale photograph with gate?	Ø			
13.	Have you taken owner/ representative photograph with the property?	JE .			
14.	Have you taken your selfie with the property along with owner/ representative?	N			
15.	Have you taken photograph of the property along with abutting road and towards left and right of the property?	Ø			
16.	Have you taken multiple photographs of the property from inside-out?	R			
17.	form?	R			
18.	Did you check any defects or negativity in the property in terms of location, legality, disputes, marketability, salability, etc. and commented on survey form in detail?	UB.			
19.	Have you filled all the columns of survey form including survey summary sheet properly?	P			
20.	Did you draw site key plan (location map)?				
21.	Did you draw rough site sketch plan?				
22.	Have you taken self-attested documents from owner/ representative and stamped "documents provided by stamp"?				
23.	Did you check any defects or negativity in the property in terms of location, legality, disputes marketability, salability, etc. and commented on survey form in detail?				
24.	Have you confirmed any recent past transactions during market enquiries and	-LB			
25.	Did you take signatures of the owner/ representative on undertaking and survey summary sheet?	R			
26.	Did you signed the undertaking?	LB.			

For File No.	VIS (2021-22)-PL64 -Q16-054
Surveyor Name	Abhisher shanbhag
Signature	Standreg.
Date	0107/21

	(FOR F	ENERAL SURVEY FORM PROPERTIES OTHER THAN FLATS) (Version 5.0) 011 Last Revision: 04.01.2018 Latest Revision: 31.10.2020				
F	ILE NO. RKA/DNCR//MUM	Date: 01 07/21 Time: 10: 30 am				
The second		GENERAL DETAILS				
1.	Name of the Surveyor	Abhishek-Shanbhag				
2.	Property shown by	Owner, Representative, No one was available, Property is locked, survey could not be done from inside Name Contact No.				
		Mr. K. O. Anil Kumar 9375838388				
3.	Survey Type	 Full survey (inside-out with measurements & photographs) Half Survey (Measurements from outside & photographs) Only photographs taken (No measurements) 				
4.	Reason for Half survey or only photographs taken NA	Property was locked, Possessee didn't allow to inspect the property, NPA property so couldn't be surveyed completely —				
5.	How Property is Identified	 From schedule of the properties mentioned in the deed, From name plate displayed on the property, Identified by the owner/ owner representative, Enquired from nearby people, Identification of the property could not be done, Survey was not done 				
6.	Type of Property	 □ Flat in Multistoried Apartment, □ Residential House, □ Low Rise Apartment, □ Residential Builder Floor, □ Commercial Land & Building, □ Commercial Office, □ Commercial Shop, □ Commercial Floor, □ Shopping Mall, □ Hotel, ☑ Industrial, □ Institutional, □ School Building, □ Vacant Residential Plot, □ Vacant Industrial Plot, □ Apricultural Land 				
7.	Property Measurement	Seif-measured, Sample measurement only, D No measurement				
8.	Reason for no measurement	 It's a flat in multi storey building so measurement not required Property was locked, Owner/ possessee didn't allow it, NPA property so didn't enter the property, Very Large Property, practically not possible to measure the entire area Any other Reason: Output 				
9.	Purpose of Valuation	 Value assessment of the asset for creating new collateral mortgage Periodic Re-Valuation for Bank, Distress sale for NPA A/c., For DRT Recovery purpose, 				
10.	Type of Loan	 ☐ Housing Loan, ☐ Housing Take Over Loan, ☐ Home Improvement Loan, ☐ Loan against Property, ☐ Construction Loan, ☐ Educationat Loan, ☐ Car Loan, ☐ Project Loan, ☐ Term Loan, ☐ CC Lime enhancement, ☐ Cash Credit Limit, ☑ Industrial Loan, ☐ NA 				
11.	Loan Amount					



N E		OWNERSHIP DETAILS
1.	Legal Owner Name/s	Mr. Rajendra. V. Shah
2.	Property Purchaser Name	Mr. Rojendra. V. shah
3.	Property Address under Valuation	Survey No. # 118/1/2 Hissa-1, Village Dadra, UT- Dadre Nagar Haveli
4.	Present Residence Address of the Owner/ Purchaser	601, Anisha, Subhash Road, Vile Parle CE), Mumbai - 400057
5.	Property constitution	Free Hold, 🗆 Lease Hold

-	The Party States and States and	LOCA	TION D	TAILS	COR/ CO		WELLINGS
1.	Adjoining Properties	Eas	st	North	- Ful	Alexante .	South
	(Match it with papers with the help of compass or Sun direction and also confirm it with nearby people)	Industri Estate Roo		Reliance Colosed fr 13-14 grs	Da	ainage !!	Petrola Co.
2.	Property Facing		acing, 🗆 East Facir	North Facing, ig, □ South-V	□ West /est Faci	Facing, [] Sou ng, [] South-E - Giujarat	ast Facing,
3.	Landmark (Entrance)	NT.	Dadra	checkp	nst		
4.	Ward Name/ No.	-	Jaar	- chi si p			
5.	Zone Name	-					
6.	Main Road Name & Width	N	lame	W	idth	Distance f	rom property
		Vapi-Si	ivasa	Rd		500 m	1.00
7.	Approach Road Name & Width			Estate	Road		
	Society	 Ordinar Poor 	y, 🗇 In i	nteriors, 🗌 Re	mote are	Very Good, 🗆 a, 🗆 Backward	d, 🗆 Average
9.	Special Location consideration of the property	144 Aber 3		Pool Facing, light facing	Road	Facing, 🗆 En	trance North-
10.	Characteristics of the locality	□ Urban developed, □ Urban developing, ☑ Semi Urban, □ Rural, □ Backward, □ Industrial, □ Institutional					
11.	Category of Society/ locality	□ High End, ☑ Normal, □ Affordable Group Housing, □ EWS, □ HIG, □ MIG, □ LIG					
12.	Utilities/ Facilities in the locality	 ✓ Lifts, □ Garden, □ Landscaping, □ Swimming Pool, □ Gym, □ Club House, □ Walk Trails, □ Kids play zone, 1⁄2 100% Power Backup 					
13.	Proximity to civic amenities	School	Hospit	al Market	Metro	Railway Stat	ion Airport
		I KM	3 Km	1 Km	-	8 Km	130 Km
14.	Any new development in surrounding area	Indust	trial	Area		and the stand	1.20 1.00

Page 7 of 15



15.	Jurisdiction limits	□ Nagar Nigam, □ Nagar Panchayat, ☑ Gram Panchayat, □ Nagar Palika Parishad, □ Area not within any municipal limits
16.	Jurisdiction Development Authority Name	DDA, GDA, NOIDA, GNIDA, YEIDA, HUDA, KMDA, MDDA, Any other Development Authority: Dadya Nagar Area not within any development authority limits
17.	Municipal Corporation Name	 NDMC, □ SDMC, □ EDMC, □ Ghaziabad Municipal Corporation, □ Gurgaon Municipal Corporation, □ Faridabad Municipal Corporation, □ Kolkata Municipal Corporation, □ Dehradun Municipal Corporation, □ Area not within any municipal limits, √ Any other Municipal Corporation, □ Corporation/ Municipality: Dodro Nagar Haveu

22		PHYSICAL DETAIL	the second s	AND REAL PROPERTY.		
1.	Land Area	As per Title deed	As per Map	As persite servey		
	Idal Amalgamated ->	11,900 sq.mtr	< • NA	Land area - 2 + 7900m2		
2.	Any conversion to the land use	Non- Agricult From Agricu	ural land (cluval land)	TIR) (Agreement)		
3.	Land Type	Solid, Z Rocky, D Marsh Land, D Reclaimed Land, D Water				
4.	Shape of the Land	logged, □ Land locked □ Square, □ Rectangular, □ Trapezium, □ Triangular, □ Trapezoid, √ Irregular, □ NA				
5.	Level of Land	VZ On road level. 🗆 Belo	w road level, 🗌 Abov	ve road level, 🗆 NA		
6.	Frontage to depth ratio	Normal frontage, 🗆 Less frontage, 🗆 Large frontage, 🗆 NA				
7.	Are Boundaries matched	Yes, INO, No. No relevant papers available to match the boundaries, Downdaries not mentioned in available documents				
8.	Is Independent access available to the property	Clear independent a sharing of other adjoinin C Access is closed due t	g property, 🗆 No cl	 Access available in ear access is available 		
9.	Is property clearly demarcated with permanent boundaries?	Yes, 🗆 No, 🗔 Only with Temporary boundaries				
10.	Is the property merged or colluded with any other property	Survey No. 118/1/2, Missa No-1, Village Dadra, UT-Dadra Nagar Haveli				
11.	Property possessed by at the time of survey	✓ Owner, □ Vacant, □ Lessee, □ Under Construction, □ Couldn't be Surveyed, □ Property was locked, □ Bank sealed, □ Court sealed				
12.	Current activity carried out in the property	Residential purpose Office, Industrial,				

B	UILDING/ CONSTRUCTION/ UTLITY DETAILS
1. Construction Status	Built-up property in use, Under construction, No construction

Page 8 of 15

GF - Ground Aloor, FF - First ADOr

1

2.	Covered Built-up Area	Covered Area, P F	loor Area, 🗆 Super A	vrea, 🗆 Carpet Area		
4		As per Title deed	As per Map	As per site survey		
	(Tick one on the basis of which valuation is to be calculated)	GF- 1311.84 m2 FF-1160.69 m2	-	sample measurement		
3.	Total Number of Floors in the Building		dustrial typ			
4.	Floor on which property is situated	-				
5.	Type of Unit/ Number of Rooms/ Cabins/ Cubicles	-				
6.	Building Type	Ordinary brick wall abandoned structure	structure, 🗆 Iron tru	ing Pillar Beam column, isses & Pillars, □ Scrap		
7.	Roof	Patla	ZRCC, □ GI Shed,	□ Tin Shed, □ Stone		
		c. Finish: Simpl Ceiling, Coved	e plaster, POP F roof, No plaster	Punning, 🗆 POP False		
8.	Flooring	chips, □ Mosaic, □ C □ Wooden, □ PCC, Tiles, □ Brick Tiles,	Granite, Italian Marb Imported Marble, I No Flooring, Un	□ Pavers, □ Chequered der construction, □ Any		
9.	Appearance/ Condition of the Building	Internal - Excell Average, Poor External - Excell Average, Poor	□ Under construction, lent, v Very Good, □ Under construction	Good, Ordinary,		
10.	Maintenance of the Building	Very Good, Average, Poor, Under construction				
11.		Average, Below	ry Good, 🗆 Good, average, 🗆 Under co	□ Simple, □ Ordinary, onstruction, □ No Survey		
12.	Interior Finishing	Under construction	walls, 2 POP punning No Survey	g, Z Coved roof, ily office		
13.	Exterior Finishing	 Simple plactere Architecturally di Structural glazing, Glass façade, III 	ed walls, Brick esigned or elevated, Aluminum compos Domb, Porch, Ur	walls without plaster, Brick tile Cladding, ite panel cladding, ider construction		
14.	Kitchen	Modular with chimner construction, D No S	y, □ High end Modul: Survey	with cupboard, 🗆 Normal ar with chimney, 🗆 Under		
15.	External - plant	Concealed lightni	s & fittings, 🗆 Fanc ng, 🗆 Under construc	iy lights, □ Chandeliers tion, □ No Survey		
16.	Class of Sanitary/ Plumbing & water supply fittings	🗆 Below average, D	/ Good, □ Good, □ S] Under construction,	No Survey		
17	Water arrangements		mersible, Jal board	Simple, Ordinary		
18	A state day Morek	🗆 Average, 🗆 Belo	w Average, 🗹 No woo	oden work, 🗆 No survey		
19	Age of Building/ Recent Improvements done		2	irrecent improvem		
20	- A state of the Building	Very Good, 🗆 Av	verage, LI Poor			


Page 9 of 15



21.	Any defects in the building	 □ Maintenance issues, □ Finishing issues, □ Seepage issues, □ Water supply issues, □ Electricity issues, □ Structural issues, □ Visible cracks in the building Non € 					
22.	Any violation done in the property	□ Construction done without Map, □ Construction not as p approved Map, □ Extra covered without sanctioned Map, □ Joint adjacent property, □ Encroached adjacent area illegally Non C					
23.	Boundary Wall (Only for individual	Ves, D No, D	Common bou	ndary wall of a com	plex		
	property)	Running Mtr.	Height	Width	Finish		
		+	-	-	-		
24.	Lift/ elevators	Passenger/ Commercial (Industrial)					
		Make: Lo cal		Capacity: 2	Т		
25.	Power backup	D Inverter, D					
		Make: Sudh	i'r commin	r (commins) Capacity: 100 KVA			
26.	Garden/ Landscaping	🗆 Yes, 🗆 No, 🗆	Beautiful, 🗆 C	ordinary			
27.	and the second se	Available with	n the property	On Ground, D On stilt] In Basement,		
		Not availab property	le within the	On road, problem	Acute parking		
28.	Special Comments/ Observations, if any	property			are)		

1.	Any issues in marketability of the	□ Yes Z No		
	property?	Reason aspects, i	in case of No: 12 Location, 12 Surrounding, 12 Lega Demand, Shape, Any Other:	
2.	How is Demand & Supply condition	Demand	🗆 Very Good, 🗹 Good, 🗆 Average, 🗆 Low, 🗆 Poor	
2.	in the Market of such properties?	Supply	🗌 Very Good, 🖉 Good, 🗆 Average, 🗆 Low, 🗆 Poor	
3.	Is property easily sellable &	Yes, 🗆 No		
	marketable?		party agrees upon their cielling price	
4.	How is the current utility of the property?		nt, 🗹 Very Good, 🗆 Good, 🗆 Average, 🗆 Low, 🗆 Poor	
5.	At what True rate Owner bought	Year of pu	irchase 1993-94	
	this Property? .	Purchase	Price (Dharmendra Si'r)	
6.	Present expected Sale Value of the overall property?			





* According to Grove, NA (Non-Agricultural) land rate is B2000 to Rs 4,0001- (per sq. mtr) in and around property area.

- * Broker
-) Navendra Trivedi 9824101174
- 2) Viral shah 9824110877 104 min, 124-15Kmax,
- Brethelan stah 1924148357 The brokes)
- * In Dadra, CLU is only available for 55%. But of 100%. of land i.e for acres land, only 55 acres can be used as CLU. (As per Grovt). Any Small land cannot be taken as CLU.
 - Navoli Area & Oadra area prices same (land votes).

Page 11 of 15



DRAW SITE KEY PLAN & SKETCH PLAN

Page 12 of 15



l

No	Particulars	Subject Property	Transaction already Comparable 1	Comparable 2	Comparable 3
l.	Name (source of information)	NA	Viral shah	Narrendra T	-
to the	Contact No.	NA	9824110877	982-4101174	-
3.	Type of source of information (Seller/ Property dealer/ nearby people)	NA	Property/ Land dealer	property dealer/ industrialist	-
4.	Rates/ Price informed (in Rs. with unit)	(per m2)	Min- IOIC Max - 12toist	int-IGK	-
5.	Rates Type (Sale/ Buy)	NA	Buy	Buy	-
6.	Shape of the Property (Square, Rectangular, Irregular)		-	-	-
7.	Area/ Size of the Property		As per required	As per read	-
8.	Legal Status (clear, negative, weak)/ No. of owners		clear	dear	-
9.	Location/ surrounding/ neighborhood comparison with the subject property (Similar, Lower, Better, Highly Better than the subject Property)	Base Case	Same B nearby locality	same & near by locality	-
10.	Distance from the subject Property	0	100-200 Mtrs.	200-300 Mt28	-
11.	Other factors (Corner, 2 side open, North-East facing, Park facing, Legal/ Financial encumbrance, etc.)		-	-	-
12.	Approach road width			-	~
13.	Level of Land (Below/ On/ Above road level)		same road level	same road level	-
14.	Frontage to depth ratio (Normal, Less, Large)		Large	Large	-
15.	Present Use		-	-	-
16.	Any other details/ Discussion held	NA		_	-
7.	Present expected Sale Value of the overall	Minimu	m - 10K { 12Kto 15K }	7.2000 - Grov	t rate

Market Rote

UNDERTAKING BY THE CUSTOMER

I confirm that I have made the inspection of the subject property to the surveyor of R.K Associates, which is correct property in question for which the documents have been provided/ submitted by me. I further confirm that I am aware of all the information related to the subject property and I have provided all its information to the surveyor true to the best of my knowledge. I understand that any false or manipulative information provided by me will be considered as cheating with the professional organization since it will lead to incorrect valuation report and I'd be solely responsible for this unlawful act and will bear the charges for the changes/ modifications which have to undergo due to the false information. I also undertake that I have not given any cash or in kind to any member of R.K Associates to influence the Value of the Property or favor any individual or organization and the same is not accepted or asked by the member of R.K Associates. Any such act will lead to cancellation of the material prepared by R.K Associates with forfeiting of the fees and i'll be completely responsible for its repercussions and legal actions taken for It.

IMPORTANT: We have not authorized any of our person/ Surveyor to take Cash or kind from the customers in any situation. In case Surveyor or any member of R.K Associates asks for any money or kind from you then kindly please inform on number +91-9958632707, 0120-4110117. Our Valuation process is very stringent and have multiple check points to ensure correct & error free reports to keep the lending agency risk free. In case Surveyor claims that he would be able to arbitrary effect the Valuation figures unfairly or as per your requirement & need, then he is making a false claim to you and we request you to complaint such act immediately on the number provided above.

Name	Mr. K.D. Anil Kumar
Relationship with owner	Accountant
Signature	M.
Mobile No.	9375838388
Date	01/07/21

UNDERTAKING BY THE SURVEYOR

I confirm that I have carried out the Survey of the property property as per the fair professional best practices and Valuation & Survey policy guidelines issued by R.K Associates. I have not taken any cash or kind from the customer nor have I come into any kind of influence of the customer / bank for arbitrary providing the Property Valuation as per one's need. I further state that I have not given any assurances to the customer nor given any wrong or false information or statement. In case at any point of time it is found that I have done any kind of fraudulent activity in this case and misled the company then I understand its legal consequences and appropriate penal action which company can take against me. Also in regard to it any monetary or reputation loss will be recovered from me by the company.

For File No.	VIS (2021-22)-PL64-916-054
Surveyor Name	Abhisher Shanbhag
Signature	(Contrast
Date	01 07/21

UNDERTAKING BY THE PREPARER

I confirm that this Valuation Report is prepared as per the fair professional best practices and Valuation & Survey Policy Guidelines issued by the organization. I also confirm that without any personal interest, partiality or prejudice, I have worked on this Valuation assignment. Rates adopted for the asset is based on various facts, information collected from the site came to my knowledge during the course of the assignment and I have taken all sincere efforts to review, cross check & confirm this data/ information from all different angles using my prudent approach without any biasedness or pressure. I have prepared the report based on true facts & information as per best of my knowledge & case facts. I understand that any false information provided by me will lead to the incorrect valuation report and I'd be solely responsible for it and will bear the losses which will be put on the Company in form of monetary or reputation loss by its client or statutory bodies.

I also undertake that I did not come into any influence by the customer, Bank representative (officer or agent), colleagues, coworkers or any other person to arbitrary change the Valuation figures or facts unethically or illegitimately which may put the public money at risk which is in the form of Bank deposits.

In case at any point of time in future, if I am found guilty of illegitimately distorting the facts in the Valuation or any other professional services which company offers in the market on being influenced by the customer or Bank representative (officer or agent) or for whatsoever reason then I'd solely responsible of any such act and I understand that the Company can take appropriate legal action against me which may include suspension from the current roles & responsibilities or termination from the employment with immediate effect.

I also undertake that I have not taken any cash, favor or in kind from the customer for favoring any individual or organization by unfair means.

I also undertake that I'll not prepare any report on incomplete Survey form which is not properly filled as per the Company guidelines and in case I am preparing it which is creating an incorrect report then I'd be responsible for its consequences.

For File No.	
Preparer Name	
Signature	
Date	

Page 15 of 15

Enclosure: 6



SURVEY SUMMARY SHEET (TO BE ENCLOSED WITH VALUATION REPORT)

(Version 1.0) | Date of implementation: 10.04.2017

Every Valuation report at R.K Associates is prepared based on the thorough survey of the property carried out by our Engineering Surveyor. This Survey Summary Sheet is for the information of Banker/ concerned interested organization. Detailed Survey Form can also be made available to the interested organization in case it is required to cross check what information our surveyor has given in site inspection report based on which Valuation report is prepared.

1.	File No.	VIS (2021-22) - PL64 -Q16-054		
2.	Name of the Surveyor	Abhishek-shanbhaq		
3.	Borrower Name	Mr. Kajendra V. Shah		
4.	Name of the Owner	Mr. Rajendra Vishah		
5.	Property Address which has to be valued	Dadra & Nagar Haveli		
6.	Property shown & identified by at spot	Owner, Representative, No one was available, Property is locked, surve could not be done from inside		
		Name		Contact No.
		Jigar Patel	846	50439059
7.	How Property is Identified by the Surveyor	 □ From schedule of the properties mentioned in the deed, □ From name plate displayed on the property, ☑ identified by the owner/ owner representative, □ Enquired from nearby people, □ Identification of the property could not be done, □ Survey was not done 		
8.	Are Boundaries matched	 Yes, No, No, No relevant papers available to match the boundaries, Boundaries not mentioned in available documents 		
9.	Survey Type	 Full survey (inside-out with measurements & photographs) Half Survey (Measurements from outside & photographs) Only photographs taken (No measurements) 		
10.	Reason for Half survey or only photographs taken	Property was locked. Possessee didn't allow to inspect the property, NPA property so couldn't be surveyed completely		
11.	Type of Property	Elat in Multiotoried Apartment, Residential House, Low Rise Apartment, Residential Builder Floer, Commercial Land & Building, Commercial Office, Commercial Shop, Commercial Floor, Shopping Mall, Hotel, Industrial, Institutional, School Building, Vacant Residential Plot, Vacant Industrial Plot, Agricultural Land		
12.	Property Measurement	Self-measured, Sample measurement, No measurement		
13.	Reason for no measurement	□ It's a flat in multi storey building so measurement not required □ Property was locked, □ Owner/ possessee didn't allow it, □ NPA property so didn't enter the property, □ Very Large Property, practically not possible to measure the area within limited time □ Any other Reason:		
	Land Area of the Property	As per Title deed	As per Map	As per site survey
14.	(m^2) 7,900 + 4000 \rightarrow	11,900 sq. mtr	-	-
15	Covered Built-up Area	As per Title deed (m^2)	As per Map	As per site survey
15.		1311-84+1160.69	-	Sample
16.	Property possessed by at the time of survey	Owner, Vacant, Lessee, Under Construction, Couldn't be Surveyed, Property was locked, Bank sealed, Court sealed		
17.	Any negative observation of the	-		

	property during survey	-
18.	Is Independent access available to the property	✓ Clear independent access is available, □ Access available in sharing of other adjoining property, □ No clear access is available, □ Access is closed due to dispute
19.	Is property clearly demarcated with permanent boundaries?	Yes, 🗆 No, 🗆 Only with Temporary boundaries
20.	is the property merged or colluded yes .	
21.	Local Information References on property rates	Please refer attached sheet named 'Property rate Information Details."

Endorsement:

Signature of the Person who was present from the owner side to identify the property:

Undertaking: I have shown the correct property and provided the correct information about the property to the surveyor of R.K Associates to the best of my knowledge for which Valuation has to be prepared. In case I have shown wrong property or misled the valuer company in any way then I'll be solely responsible for this unlawful act.

- a. Name of the Person: Mr. K.D. Anil Kumar
- b. Relation: Accoyctant
- c. Signature:
- d. Date: 01/07/21

In case not signed then mention the reason for it: 🗆 No one was available, 🗆 Property is locked, 🗔 Owner/ representative refused to sign it, 🗌 Any other reason

2. Surveyor Signature who did site inspection:

Undertaking: I have inspected the property and cross vended the property details at site to the extent of a Matching boundaries of the property, b. Sample manusement of its area, c. Physical condition, d. Property rates as per local information with what is minitiared in the property documents provided to me by the Bank/ interested organization. I have not come under influence of anothe during site inspection and have only recorded the true and factual details in the survey form which I come across during the site survey. I understand that giving any manipulative information in the winery form will lead to incorrect Valuation report which is an unlawful act and i'll be solely responsible for doing it.

- a. Name of the Surveyor: Abhisher Shanbhag b. Signature: Sanbhag
- c. Date: 01/07/21