File No.	RKA/DNCR/				
Date of Receiving					



File Receiver Name Abhrshek Shan bhag.

CASE COLLECTION FORM

(Version 5.0)

Date of implementation: 9.02.2011 | Last Revision: 30.01.2020 | Latest Revision: 31.10.2020

Items	Assigned To	Assigned to Date	To be completed by date	Submitted On date	Grade	HOD Engg. Signature
File Received By	Abhishek Shanbhag.	NA	NA			
Survey	Shreyash Shetty	15/11/21.				
Preparation	J					

A - Very Good, B - Satisfactory, C - Average, D - Poor, E - Extremely Poor

representative photo not taken, Owner/ owner representative signature not take Google Map not taken, Survey summary sheet not filled	File Returned to HOD Engg. unprepared due to reason	□ Survey not done properly, □ Survey Form not properly filled, □ Market survey for rates is not properly done, □ Identification is not clearly done, □ Measurement is not properly done, □ Photographs not clearly taken, □ Selfie/ Owner or owner representative photo not taken, □ Owner/ owner representative signature not taken, □ Survey summary sheet not filled
--	---	---

In case File is returned by the preparer - HOD Engg. comment &	☐ Minor defects in the survey hence approved for preparation with warning to Surveyor. Report preparer to collect the missing information on his own.
Signature	□ Major defects in the survey. Survey has to be done again.

	and the second	GENER	AL DETAILS			and the second second	
1.	Proposal/ Work Order or Ref. No.	PLGSI-QI	56.				
2.	Type of Service		Valuation Report, Construction cost estimate, Cost vetting certificate Other CE Certificates, TEV Report, LIE				
3.	Type of customer	Bank	Company Private client Di		Corporate		
		Company			Direct client through Bank		
4.	Bank/ FI/ Organization Name & Address	PNB,LCB, Co Wing, Coffe					
5.	Case Allotment Officer/	Name Contact Number		act Number	Email Id		
	Fees paying party Details	Mr. Surest Salar	Saban 9819598184		60090210@pnb. co.in		
6.	Case Type	Case for Fresh Account		Case	for exiting acco	ount/ customer	
7.	Fees Details	Amount of Fees	es Advance Amount if an		Fees wil	I be paid by	
		5,000 + 6 ST		_	Bank	Customer	
8.	Billing Details	1210	Billed To Party Name		GSTIN		

		PNBLCB.			
		CASE DET	AILS		
1.	Type of Property	Residential Flat			
2.	Purpose of Valuation/ Assignment	 Value assessment of the asset for creating new collateral mortgage Periodic Re-Valuation for Bank, Distress sale for NPA A/c., For DRT Recovery purpose, Capital Gains Wealth Tax purpose Partition purpose, General Value Assessment Any other: 			
3.	Owner/Applicant Details Please Find Below	Name	Contac	ct Number	Email Id
4.	Account Name	Flat No- 401, Rajnigo	7/c Baji	math Mela	ram.
5.	Property Address	Flat No- 401, Rajnigo Talimki Road, Santi	actual CHIS	.Ltd.,Savası st, Mumbaj.	uct Colony,
6.	Who will coordinate on site for the site survey	Name Mr. Nikunj Koth	ari.	Contact Number 9821351973	
7.	Preferred time of survey	Date 15/11/2	021./	Time 3:	oopm.
8.	Documents Received (Any one ownership document and approved site plan/ map is must)	 Ownership Documen Registered Will, Conveyance Deed, Map: Cizra Map, Utility Bills: Electric receipt, House Tax Any Other document Old Valuation Repo No documents provide 	ts: Sale De Relinquishme Allotment I Approved Ma icity Bill & pay demand & pay t CLU, 1	nt Deed,	sfer Deed, ssion Letter Water Bill & paymer
9.	Documents received from	Banker.			
10.	Special Instructions if any:				
	I agree to pay the amount m	entioned above for the prepar		tion Report. I agree	

Series and

File No. RKA/DNCR/ ______ PL651 - Q 156

	FILE RECEIVER CASE COLLECTION PROCESS COMPLIANCE CHECKLIST (To be filled by Surveyor)					
S.NO.	COMPLIANCE CHECKLIST	STATUS	APPROVER SIGNATURE/ REMARKS IN CASE OF ANY (X)			
1.	Is Case collection Form property filled by Receiver?	2				
2.	Is purpose of the assignment understood clearly by the receiver?	Z				
3.	Has receiver checked if this is a new case or existing case of the Bank?	VE				
4.	Has receiver fixed the fees with the manager/ client and sent quotation properly or have taken approval of the work over email?	8				
5.	Has receiver taken proper Work Order/ Email/ CESA form formality?	V				
6.	In case of private case or for fresh case 50% advance is received?					
7.	Is document checklist email sent to the customer?					
8.	Has the received documents is having 'documents provided by stamp'?					

IMPORTANT INSTRUCTIONS TO SURVEYOR

1.	Please fill the above compliance checklist before moving for the survey.
2.	Please do not do the survey if you do not have proper documents.
3.	For Vacant Plot/ Land - Cizra Map/ Master/ Zonal/ Site Plan is must to identify the Plot. For Agriculture or converted land from agriculture - Mutation documents, CLU is must.
4.	Firstly please first study the documents of the property which needs to get surveyed.
5.	Mark the Owner/ Area/ Boundaries mentioned in the ownership documents with bold florescent marker pen before moving for the survey. During site survey if any difference is found in the above fields from the ownership documents then please contact the owner immediately to know the reason for the difference.
6.	Confirm ongoing property rates in the subject location through public domain, property sites and contact dealers to show you the available properties in that area during your survey.
7.	Identify the Property clearly by matching the boundaries and area mentioned in the property papers.
8.	Do sample physical or google measurements of the property.
9.	 PHOTOGRAPH INSTRUCTIONS: a. Take owner/ representative photograph along with the property. b. Take your selfie along with the property and the owner/ representative. c. Take full scale photo of the property with gate. d. Take photo of the property along with abutting road, towards left, right and center. e. Take multiple photos of inside-out of the property. f. Take nearby photographs of the Property. g. Take a short video to cover property and neighborhood.
10.	Take Google Map location.
11.	Check main road name & width and approach road width and distance of property from main road.
12.	Check Jurisdiction Municipal Limits & Ward Name.
13.	Fill each column of survey form diligently in detail and tick the appropriate option clearly.
14.	Check any defects or negativity in the property and comment in detail on survey form.
15.	Do extensive market rate enquiries and confirm for any recent past transactions.
16.	In case customer appears to be providing misleading information to you or trying to influence you by money or cash then immediately report to the Management & Bank.

	Contraction of the second s
	SURVEY GRADING MATRIX
GRADE	
A	In case all the points below are done properly, timely with full care and diligence:
	1. Survey started with proper work order and knowing the source of payment.
	2. Survey done with proper documents
	 Done complete homework and studied the documents properly with highlighting the main points before moving for the survey.
	Chosen correct survey form as per the property type
	5. All fields of Survey form are properly filled
	All site special observations and negative and positive factors are clearly must be and the special observations.
	7. Sen a chern signatures taken on survey form
	Property rates information property taken, mentioned and verified
	9. Site rough sketch plan made.
	10. Proper photographs taken.
	11. Selfie with property taken.
	12. Selfie and owner photograph with property taken
	points are covered.
	In case of more than 3 minor mistakes and any 1 major mistake in any of the above points and if any points are completely missing except Point 1, 2, 3, 4, 6, 8, 10, 11, 12.
U	In case of 1 major mistake or missing of any 1 point out of 1 2 3 4 6 8 10 11 10
E	In case of more than 1 major mistakes or missing of more than 1 point out of 1, 2, 3, 4, 6, 8, 10, 11, 12,
	g

Note (Survey Grading Matrix):

- For special assignments like LIE, Stock Valuation, etc. where till date survey format is not specified or released, in such cases point wise site observation report has to be submitted by the Surveyor duly signing it properly. Without signed Site Observation report, Point 4 will be considered as not done and will fall under Category E.
- 2. Similar Grading Matrix is issued for Case Collection & Report Preparation as well.

Note (Overall Grading Matrix):

 In case client reports any careless mistake in the report for which revision has to be done in the report then in that case Grading Matrix may be revised and Grade E will be awarded.

1	SURVEY PROCESS COMPLIANCE CHECKLIST	
S.NO.	(To be submitted by Surveyor with each Survey)	1
1.	COMPEIANCE CHECKLIST POINTS	STATUS
2.	Did you take proper property documents to carry out the survey?	N
10.58	Have you properly studied & highlighted Owner/ Area/ Boundaries in the property documents with bold florescent before moving for the survey?	
3.	Did you check prominent landmark nearby the subject property and mentioned in the survey form?	0
4.	Did you identified the Property clearly by matching the boundaries and area mentioned in the property papers?	V
5.	Did you check if property is merged with any other property or it is an independent property?	V
6.	Did you do sample physical or google measurements of the property in case of property more than 2500 sq.mtr?	V
7.	Did you check for any building violations in the property?	V
8.	Did you check municipal limits/ jurisdiction/ ward?	V
9.	Did you take Google Map location and shared it to Maps whatsapp group?	
10.	Did you check Main road name & width and its distance from the subject property?	N.
11.	Did you check approach Lane width on which property is located?	
12.	Have you taken property full scale photograph with gate?	
13.	Have you taken owner/ representative photograph with the property?	2
14.	Have you taken your selfie with the property along with owner/ representative?	R
15.	Have you taken photograph of the property along with abutting road and towards left and right of the property?	8
16.	Have you taken multiple photographs of the property from inside-out?	A
17.	Did you check nearby development and whereabouts and commented on survey form?	2
18.	Did you check any defects or negativity in the property in terms of location, legality, disputes, marketablility, salability, etc. and commented on survey form in detail?	V
19.	Have you filled all the columns of survey form including survey summary sheet properly?	Ø
20.	Did you draw site key plan (location map)?	V
21.	Did you draw rough site sketch plan?	V
22.	Have you taken self-attested documents from owner/ representative and stamped "documents provided by stamp"?	
23.	Did you check any defects or negativity in the property in terms of location, legality, disputes, marketability, salability, etc. and commented on survey form in detail?	8
24.	Have you confirmed any recent past transactions during market enquiries and enquired property rates locally very rigorously?	Ø
25.	Did you take signatures of the owner/ representative on undertaking and survey summary sheet?	V
26.	Did you signed the undertaking?	d

For File No.	PL651-Q156
Surveyor Name	Shreyach Shetty.
Signature	13.45
Date	15/11/2021.

	(FOR	ENERAL SURVEY FORM PROPERTIES OTHER THAN FLATS (Version 5.0) 2011 Last Revision: 04.01.2018 La			
	File No. RKA/DNCR/	Date: 15/11/2021	Time: 6:00pm.		
	and the second second	GENERAL DETAILS			
1.	Name of the Surveyor	Shreyash Shetty.			
2.	Property shown by	□ Owner, ☑ Representative, □ N locked, survey could not be done fi			
		Name	Contact No.		
3.	Survey Type	Mr. Nikunj Kothari Full survey (inside-out with mea Half Survey (Measurements from Only photographs taken (No me	m outside & photographs)		
4.	Reason for Half survey or only photographs taken N · A ·	Property was locked, Possessee didn't allow to inspect the property, NPA property so couldn't be surveyed completely			
5.	How Property is Identified	From schedule of the propertie name plate displayed on the pro owner representative, Enquired	es mentioned in the deed, From operty, Identified by the owner/		
6.	Type of Property Flat in a 7 Storey Building.	□ Flat in Multistoried Apartment, □ Apartment, □ Residential Builde Building, □ Commercial Office, □ Floor, □ Shopping Mall, □ Hotel, □	□ Residential House, □ Low Rise r Floor, □ Commercial Land & Commercial Shop, □ Commercial □ Industrial, □ Institutional, sidential Plot, □ Vacant Industrial		
7.	Property Measurement	Self-measured, Sample meas	surement only, No measurement		
8.	Reason for no measurement	 It's a flat in multi storey building a Property was locked, Owner/ NPA property so didn't enter the 	so measurement not required		
9.	Purpose of Valuation	 Value assessment of the asset for Periodic Re-Valuation for Bank, For DRT Recovery purpose, Partition purpose, General Valuation 	Distress sale for NPA A/c., Capital Gains Wealth Tax purpose		
10.	Type of Loan Business Loan	□ Housing Loan, □ Housing Take Loan, □ Loan against Property, □ Loan, □ Car Loan, □Project Loan enhancement, □ Cash Credit Limit,	Construction Loan, Educational an, Term Loan, CC Limit		
11.	Loan Amount				

		OWNERSHIP DETAILS
Π.	Legal Owner Name/s	Reter Pg. No. 2.
2.	Property Purchaser Name	Refer Pg. No. 2.
3.	Property Address under Valuation	Flat No 401, Rajangandha (HS Ltd., Saraswet Colony) Talinki Ruad, Sanlascruz West, Mumbai.
4.	Present Residence Address of the Owner/ Purchaser	
5.	Property constitution	Free Hold, Lease Hold

		LOCAT	TION DETA	ILS	and in the second second		
1.	Adjoining Properties	East	T 1	West			outh
	(Match it with papers with the help	LiFt .	Bui	Idina	Stair	o Othe	Buildry
	of compass or Sun direction and	211	Con	poor of 8	Flat	Navas Buelo	iting
	also confirm it with nearby people)	/	OT	w Blog.	· · ···	No 402 Build	ound.
2.	Property Facing	East Fa	and the second se		in the second se	cing, 🗆 South Fa	
		□ North-E	ast Facing, [□ South-W	est Facino	, 🗆 South-East F	acing.
			/est Facing		5-295-41-0-0-18-0-9 8		
3.	Landmark						
4.	Ward Name/ No.	k Rojnigan	the (HS,	Jack R.	Tones B.	ilding Arya Sar	neij Mondi
	ward warner No.			21. 		•	V
5.	Zone Name	-					
6.	Main Road Name & Width	Na	ame	Wi	idth	Distance from	n property
		Linking	Rood .	-		300-400	m.
7.	Approach Road Name & Width		: Road			,	
8.	Location consideration of the				od Urban	developed Area	, Within
	Society	developing area, Highly posh locality, Very Good, Good,					
		□ Ordinary, □ In interiors, □ Remote area, □ Backward, □ Average,					
		Columary	, un inter		mote area	a, 🗆 backwaru, L	- Average,
		D Poor			00		
9.	Special Location consideration	D Park Fa	acing, 🗆 Po	ol Facing,	Road	Facing, Entra	nce North-
	of the property N A	East Facin	g, 🗆 Sunligt	nt facing			
10.	Characteristics of the locality			1	alaping	🗆 Semi Urban, 🗆	Dural
10.	Characteristics of the locality	L Orban d	eveloped, V	Urban dev	eloping,	_ Semi orban, _	i Kurai,
		Backwar	d, 🗆 Industr	ial, 🗆 Instit	tutional		
11.	Category of Society/ locality	I High En	d Norma		able Grou	p Housing, 🗆 EV	/S. □ HIG
						p needen gi	
12.	Utilities/ Facilities in the locality			Landscapin	g. 🗆 Swi	mming Pool, 🗆 G	iym,
		1 JULY 2010 STATE			1	lay zone, 🗆 10	
		Backup					
13.	Proximity to civic amenities	School	Hospital	Market	Metro	Railway Station	Airport
		160m	650m	800m	WTP.	900m.	2.8 hn
14.	Any new development in			1	- and -		
	surrounding area	-					

15.	Jurisdiction limits	 Nagar Nigam, Nagar Panchayat, Gram Panchayat, Na, Palika Parishad, Area not within any municipal limits
16.	Jurisdiction Development Authority Name M. M R. D. A-	 DDA, GDA, NOIDA, GNIDA, YEIDA, HUDA, KMDA, MDDA, Any other Development Authority: Area not within any development authority limits
17.	Municipal Corporation Name $B \cdot M - C$	 NDMC, SDMC, BEDMC, Ghaziabad Municipal Corporation, Gurgaon Municipal Corporation, Faridabad Municipal Corporation, Kolkata Municipal Corporation, Dehradun Municipal Corporation, Area not within any municipal limits, Any other Municipal Corporation/ Municipality:

1. 2. 3.	Land Area Any conversion to the land use Land Type	As per Title deed	As per Map	As per site survey			
			3				
6782							
3.	Land Type	-					
3.	Land Type						
		Solid, C Rocky, C logged, C Land locked	Marsh Land, 🗆 Re	claimed Land, 🗆 Water			
4.	Shape of the Land	□ Square, □ Rectangul	ar, 🗆 Trapezium, 🗆 🕯	Triangular, 🗆 Trapezoid			
5.	Level of Land	On road level, 🗆 Belo	w road level, Abov	/e road level, 🗆 NA			
6.	Frontage to depth ratio	Va Normal frontage, D L	Normal frontage, Less frontage, Large frontage, NA				
7.	Are Boundaries matched	☐ Yes, ☑ No, ☐ No relevant papers available to match the boundaries, ☐ Boundaries not mentioned in available documents					
8.	Is Independent access available to the property	 Clear independent access is available, Access available in sharing of other adjoining property, No clear access is available, Access is closed due to dispute 					
9.	Is property clearly demarcated with permanent boundaries?	Yes, 🗆 No, 🗆 Only w	ith Temporary bound	aries			
10.	Is the property merged or colluded with any other property	No, not marged o	. Collected.				
11.	Property possessed by at the time of survey	 Owner, Vacant, Vacant, be Surveyed, Proper sealed 	rty was locked, 🗆	Bank sealed, Court			
12.	Current activity carried out in the property	Residential purpose					

	BUILI	DING/ CONSTRUCTION/ UTLITY DETAILS
1.	Construction Status	Built-up property in use, Under construction, No construction


	Covered Built-up Area	Covered Area, Floor Area, Super Area, Carpet Area
. [As per Title deed As per Map As per site survey
2	(Tick one on the basis of which	Flat No. 402 Carpet -
-	valuation is to be calculated)	1275 Sq. Ft. 1151.694 Sq. Ft.
3.	Total Number of Floors in the Building	G+7 Floors.
4.	Floor on which property is situated	4th Floor.
5.	Type of Unit/ Number of Rooms/ Cabins/ Cubicles	
6.	Building Type	Servent Avarter, Passage & Balconigs. RCC Framed Structure, D Load bearing Pillar Beam column,
		□ Ordinary brick wall structure, □ Iron trusses & Pillars, □ Scrap
		abandoned structure
7.	Roof	a. Make: □ RBC, □ RCC, □ GI Shed, □ Tin Shed, □ Stone Patla
		b. Height: 8.685
		c. Finish: Simple plaster, POP Punning, POP False
		Ceiling, Coved roof, No plaster
8.	Flooring	Vitrified tiles, V Ceramic Tiles, V Simple marble, D Marble
		chips, 🗆 Mosaic, 🗆 Granite, 🗆 Italian Marble, 🗆 Kota stone,
		□ Wooden, □ PCC, □ Imported Marble, □ Pavers, □ Chequered
		Tiles, Brick Tiles, No Flooring, Under construction, Any
		other type:
9.	Appearance/ Condition of the	Internal - VZ Excellent, D Very Good, D Good, Ordinary,
	Building	Average, Poor Under construction, No Survey
		External - Excellent, Very Good, Good, Ordinary,
		Average, Poor Under construction
10.	Maintenance of the Building	Very Good, Average, Poor, Under construction
11.	Interior decoration	Excellent, Very Good, Good, Simple, Ordinary,
		Average, Below average, Under construction, No Survey
12.	Interior Finishing	Simple plastered walls, Brick walls without plaster,
		Designer textured walls, POP punning, Coved roof,
		Under construction, No Survey
13.	Exterior Finishing	Simple plastered walls, Brick walls without plaster
		Architecturally designed or elevated, Brick tile Cladding
		Structural glazing, Aluminum composite panel cladding,
		□ Glass façade, □ Domb, □ Porch, □ Under construction
14.	Kitchen	□ Simple with no cupboard, ☑ Ordinary with cupboard, □ Norma
		Modular with chimney, High end Modular with chimney, Unde
		construction, No Survey
15.	Class of Electrical fittings	External, Internal
		☑ Ordinary fixtures & fittings, ☑ Fancy lights, □ Chandeliers
		Concealed lightning, Under construction, No Survey
16.	Class of Sanitary/ Plumbing &	VExternal, Internal
	water supply fittings	Excellent, S Very Good, Good, Simple, Average,
47	10/min	Below average, Under construction, No Survey
17.	Water arrangements	□ Jet pump, □ Submersible, □ Jal board supply
18.	Fixed Wooden Work	Excellent, Very Good, Good, Simple, Ordinary
		□ Average, □ Below Average, □ No wooden work, □ No survey
19.	Age of Building/ Recent Improvements done	35 +Years
20.	Maintenance of the Building	Very Good, Average, Poor

Res Street

21.	Any defects in the building	 Maintenance issues, I minishing issues, Seepage issues, Water supply issues, Electricity issues, Structural issues, Visible cracks in the building 				
22.	Any violation done in the property	□ Construction done without Map, □ Construction not as per approved Map, □ Extra covered without sanctioned Map, □ Joined adjacent property, □ Encroached adjacent area illegally				
23.	Boundary Wall (Only for individual			dary wall of a com		
	property)	Running Mtr.	Height	Width	Finish	
	N.1	1/1				
24.	Lift/ elevators	Passenger/ Commercial				
	2 Lifts.	Make: OT 1		Capacity: 5 P 3 G O	erson	
25.	Power backup	□ Inverter, □ DG Set				
	A No-	Make:	-	Capacity:		
26.	Garden/ Landscaping	Yes, No, C	Beautiful, D O	rdinary		
27.	Parking facilities	Available with			In Basement,	
		Not availab property	le within the	On road, problem	Acute parking	
28.	Special Comments/ Observations, if any					

	MARKETABI	LITY/ SEL	ABILITY/ UTLITY DE	TAILS	
1.	Any issues in marketability of the	□ Yes, No Reason in case of No: □ Location, □ Surrounding, □ Legal aspects, □ Demand, □ Shape, □ Any Other:			
	property?				
2.	2. How is Demand & Supply condition		U Very Good, V Good	d, 🗆 Average, 🗆 Low, 🗀 Poor	
	in the Market of such properties?	Supply	U Very Good, V Good	d, Average, Low, Poor	
3.	Is property easily sellable &	VYes, D No			
	marketable?	Comment	S:		
4.	How is the current utility of the property?	Excelle	ent, 🗆 Very Good, 🗆 Go	ood, 🗆 Average, 🗀 Low, 🗆 Poor	
5.	At what True rate Owner bought	Year of pu	urchase	1985 .	
	this Property?	Purchase	Price	1 1 83	
6.	Present expected Sale Value of the overall property?				

DRAW SITE KEY PLAN & SKETCH PLAN



1	(Availa	able for Sale c	OMPARABLE RATE IN or Transaction already	happened in past)	IL O
No	Particulars	Subject Property	Comparable 1	Comparable 2	Comparable 3
1.	Name (source of information)	NA	Mukesh.	Maverick Realty.	Arrit Gohil.
2.	Contact No.	NA	9004390005		
3.	Type of source of information (Seller/ Property dealer/ nearby people)	NA	Deal ex-	Dealor	Dealer.
4.	Rates/ Price informed (in Rs. with unit)	NA	45,000-50,000 besg. F+ Carpet.	42,000-50,000 persy 1+ laipit.	40,000-68.00. persq. H 6-per
5.	Rates Type (Sale/ Buy)	NA	Sche	Boy	Buy .
6.	Shape of the Property (Square, Rectangular, Irregular)		Tregular	Irregular	Ingular.
7.	Area/ Size of the Property		1200-1300	3BHH	30HK
В.	Legal Status (clear, negative, weak)/ No. of owners		clear	(tear	Gear
9.	Location/ surrounding/ neighborhood comparison with the subject property (Similar, Lower, Better, Highly Better than the subject Property)	Base Case	Similar	Similar	Similar
10.	Distance from the subject Property	0	в	Ikm	800m.
11.	Other factors (Corner, 2 side open, North-East facing, Park facing, Legal/ Financial encumbrance, etc.)		Similar	Similar	Similar
12.	Approach road width		Similar	Similar	Similar.
13.	Level of Land (Below/ On/ Above road level)		A 'Scame	1.0	11
14.	Frontage to depth ratio (Normal, Less, Large)		Same	Same	Same
15.	Present Use		Rented.	Voccont	Vacant.
16.	Any other details/ Discussion held	NA	him rates and i around Referk	44-40k is easily sellable.	RELOKTOLISK
P	Present expected Sale Value of the overall property?		S S SC.	-	

UNDERTAKING BY THE CUSTOMER

I confirm that I have made the inspection of the subject property to the surveyor of R.K Associates, which is correct property in question for which the documents have been provided/ submitted by me. I further confirm that I am aware of all the information related to the subject property and I have provided all its information to the surveyor true to the best of my knowledge. I understand that any false or manipulative information provided by me will be considered as cheating with the professional organization since it will lead to incorrect valuation report and I'd be solely responsible for this unlawful act and will bear the charges for the changes/ modifications which have to undergo due to the false information. I also undertake that I have not given any cash or in kind to any member of R.K Associates to influence the Value of the Property or favor any individual or organization and the same is not accepted or asked by the member of R.K Associates. Any such act will lead to cancellation of the material prepared by R.K Associates with forfeiting of the fees and i'll be completely responsible for its reports by R.K Associates with forfeiting of the fees and i'll be completely responsible for its reports and legal actions taken for it.

IMPORTANT: We have not authorized any of our person/ Surveyor to take Cash or kind from the customers in any situation. In case Surveyor or any member of R.K Associates asks for any money or kind from you then kindly please inform on number +91-9958632707, 0120-4110117. Our Valuation process is very stringent and have multiple check points to ensure correct & error free reports to keep the lending agency risk free. In case Surveyor claims that he would be able to arbitrary effect the Valuation figures unfairly or as per your requirement & need, then he is making a false claim to you and we request you to complaint such act immediately on the number provided above.

Name	Mikumi Kolhan
Relationship with owner	Representative
Signature	Hikmikahar
Mobile No.	09821351973
Date	15/11/21

UNDERTAKING BY THE SURVEYOR

I confirm that I have carried out the Survey of the property properly as per the fair professional best practices and Valuation & Survey policy guidelines issued by R.K Associates. I have not taken any cash or kind from the customer nor have I come into any kind of influence of the customer / bank for arbitrary providing the Property Valuation as per one's need. I further state that I have not given any assurances to the customer nor given any wrong or false information or statement. In case at any point of time it is found that I have done any kind of fraudulent activity in this case and misled the company then I understand its legal consequences and appropriate penal action which company can take against me. Also in regard to it any monetary or reputation loss will be recovered from me by the company.

For File No.	PL651-Q156.
Surveyor Name	Sheyash Shetty
Signature	Fileh >
Date	15/01/2021.



Enclosure: 6

SURVEY SUMMARY SHEET (TO BE ENCLOSED WITH VALUATION REPORT)

(Version 1.0) | Date of implementation: 10.04.2017

Every Valuation report at R.K Associates is prepared based on the thorough survey of the property carried out by our Engineering Surveyor. This Survey Summary Sheet is for the information of Banker/ concerned interested organization. Detailed Survey Form can also be made available to the interested organization in case it is required to cross check what information our surveyor has given in site inspection report based on which Valuation report is prepared.

1.	File No.	PL601-Q156 .				
2.	Name of the Surveyor	Shreyash Shetty				
3.	Borrower Name			1		
4.	Name of the Owner	Shri. Melaran Baijnath, Sml. Rukmonidevi Melaram, Shri. Bhopendrokumar Melaram & Shri. Vinadkimer Melaram Fat No. 401,4th Floor, Regingandra CHS Lid., Scrasurer Colony,				
5.	Property Address which has to be valued	Fat No. Wai, 4th Floor, 1 Talimki Road, Santa	Reginigandha CHS I	Lid., Sarasukit Colony,		
6.	Property shown & identified by at spot	Owner, Representative, could not be done from inside	No one was ávailable	e, \Box Property is locked, survey		
		Name		Contact No.		
		Mr. Nikuni Ketha	. 9821	351973->		
7.	How Property is Identified by the	From schedule of the pro	perties mentioned in t	he deed, From name plate		
	Surveyor	displayed on the property, Enquired from nearby people Survey was not done	Identified by the owner, \Box Identification of the	ner/ owner representative, Variation of the done, the property could not be done,		
8.	Are Boundaries matched	Yes, V No, No rel Boundaries not mentioned		e to match the boundaries,		
9.	Survey Type	 Full survey (inside-out with measurements & photographs) Half Survey (Measurements from outside & photographs) Only photographs taken (No measurements) 				
10.	Reason for Half survey or only photographs taken N.A.	□ Property was locked, □ Possessee didn't allow to inspect the property, □ NPA property so couldn't be surveyed completely				
11.	Type of Property Flat in a 7-Storey Building.	 □ Flat in Multistoried Apartment, □ Residential House, □ Low Rise Apartment, □ Residential Builder Floor, □ Commercial Land & Building, □ Commercial Office, □ Commercial Shop, □ Commercial Floor, □ Shopping Mall, □ Hotel, □ Industrial, □ Institutional, □ School Building, □ Vacant Residential Plot, □ Vacant Industrial Plot, □ Agricultural Land 				
12.	Property Measurement	Self-measured, Sample	measurement, 🗆 No m	neasurement		
13.	Reason for no measurement	It's a flat in multi storey by Property was locked,	uilding so measurement Owner/ possessee didn Very Large Proper	not required 't allow it, INPA property so ty, practically not possible to		
14.	Land Area of the Property	As per Title deed	As per Map	As per site survey		
				As per site survey		
15.	Covered Built-up Area	As per Title deed	As per Map			
16.	Property possessed by at the time of survey	□ Owner, □ Vacant, ☑ Les □ Property was locked, □ B	see, Under Construction Under Construction	ttion, Couldn't be Sorveyed,		
	Any negative observation of the		and the second sec			

	property during survey	/
18.	Is Independent access available to the property	Clear independent access is available, Access available in sharing of other adjoining property, No clear access is available, Access is closed due to dispute
19.	Is property clearly demarcated with permanent boundaries?	Yes, D No, D Only with Temporary boundaries
20.	Is the property merged or colluded with any other property	No, not marged.
21.	Local Information References on property rates	Please refer attached sheet named 'Property rate Information Details.'

Endorsement:

1. Signature of the Person who was present from the owner side to identify the property:

Undertaking: I have shown the correct property and provided the correct information about the property to the surveyor of R.K Associates to the best of my knowledge for which Valuation has to be prepared. In case I have shown wrong property or misled the valuer company in any way then I'll be solely responsible for this unlawful act.

- d. Date:

a. Name of the Person: Mikuni Kulhan b. Relation: Representative c. Signature: Hikuni Kulhan 1Stul-

In case not signed then mention the reason for it:
No one was available,
Property is locked,
Owner/ representative refused to sign it,
Any other reason:

Surveyor Signature who did site inspection:

Undertaking: I have inspected the property and cross verified the property details at site to the extent of a. Matching boundaries of the property, b. Sample measurement of its area, c. Physical condition, d. Property rates as per local information with what is mentioned in the property documents provided to me by the Bank/ interested organization. I have not come under influence of anyone during site inspection and have only recorded the true and factual details in the survey form which I come across during the site survey. I understand that giving any manipulative information in the survey form will lead to incorrect Valuation report which is an unlawful act and I'll be solely responsible for doing it.

a. Name of the Surveyor: Shrepsh. Shetty. b. Signature: Rest. . c. Date: 15/11/2021.

M.Bedl - 10.59×14.625 \$ 154.8789.				
Dining Aren - 10.525 × 10.60 111.000.				
MBedz-12.685 X12.01152.347.				
Kiden - 7.94 ×10.77 - 85.51.				
Staff Ruarter - 7.925 × 13.125 - 104.016.				
Bussage - 20.39×3.77 76.87. ht=8685	SPt-			
Han -14.67 x.18.33 - 268.90.				
M.Bed 3 - 4.81x 3.725 + 10.59×11.925 - 144.203.				
Balcony - 4.22 x12.6551 - 53.404.				
1151.694.				