INDUSTRIAL PLANT SURVEY FORM

(FOR INDUSTRIAL PROPERTIES ONLY)

(Version 2.0) | Date of implementation: 9.02.2011 | Date of Revision: 04.01.2018, 15.08.2019

File No. RKA/DNCR/ /	Date: 15 66 2021	Time: 9:28 AM

		GENERAL DETAILS	
1.	Name of the Surveyor	Suresh Mandavka	d
2.	Property shown by		any Representative. I) No one was survey could not be done from inside
		Name	Contact No.
		yash goyal	9521233243.
3	Survey Type	random measurements & photo sample random measurements photographs taken (No measure	
4	Reason for Half survey or only photographs taken	property. NPA property so ow	ossessee didn't allow to inspect the ner was hostile and survey couldn't be tion property, Very Large 'regular
5.	How Property is Identified	name plate displayed on the pro	perty Promined in the deed. From perty Prominer owner owner owner owner nearby people, I identification of the survey was not done
6.	Type of Industry	Small Manufacturing Unit, C Scale Industrial Plant, C Very La	Medium Scale Industrial Unit, Vicarge arge Scale Industrial Plant
7.	Property Measurement		sasurement only, © No measurement
8.	Reason for no measurement		☐ Owner/ possessee didn't allow it, ☐
		NPA property so didn't enter t	the property. No Very Large Property, are the entire area - Any other Reason.
9.	Purpose of Valuation	☐ Periodic Re-Valuation for Ban	et for creating collateral mortgage A. C. Distress sale for NPA Aic. 11 Days 11 Not avenifeld.

Page 5 of 14

		☐ For DRT Recovery purpose, ☐ For Insolvency purpose, ☐ Capital Gains Wealth Tax purpose, ☐ Partition purpose, ☐ General Value Assessment, ☐ For company merger & amalgamation purpose, ☐ For any other purpose:
10.	Type of Loan	☐ Project Loan, ☐ Term Loan, ☐ CC Limit enhancement, ☐ Cash Credit Limit, ☐ Industrial Loan, ☐ Business Loan, ☐ NA
11.	Loan Amount	

	THE PERSON NAMED IN COLUMN	OWNERSHIP DETAILS
1.	Name of the Industry	Emune pharmaceuticulo kith.
2.	Legal Owner Name/s	Refor Document
3.	Property Purchaser Name	
4.	Plant Address under Valuation	plor P-2, Reynandhi in Fotedh yark High
5.	Present Residence Address of the Owner/ Director	Refer Documents.
6.	Property constitution	☐ Free Hold, ** Cease Hold

		LOCATION	DETAILS		-
1.	Adjoining Properties	East	West	North	South
	(Match it with papers with the help of compass or Sun direction and also confirm it with nearby people)	20.0m wide led	- C	wide red	602 b-1
2.	Property Facing	North-East Facing. North-East Facing. South-West Facing. South-East Facing. North-West Facing.			
3.	Landmark	Mear SP	13 - 5 In	-2547-	
4.	Ward Name/ No.				
5.	Zone Name	Industried			
6.	Main Road Name & Width	Hingewedi Keser po om o khe gri Hingewedi Resertsen gel Ao		nce from property	
7.	Approach Road Name & Width	Hinje	would Ruse	rsin gel	Ao mwil
8.	Are proper road facilities available?	√Yes, □ No			
9.	Type of Approach Road	☐ Brick khadanja	n, Mud surfacing	, □ Broken poth	ncrete paver block, oled metalled road, row approach road

W	The state of the s	The second second		7,100	2010 DEC 2024	THE RESERVE OF THE PARTY OF	HA BRITTHE SPECIAL PROPERTY.
10.	Location characteristics	maintained Main city, Within urb Within urb Institutional	d Industrial a Within of the pan developments area,	ity suburbing zone, area, Out of m	thin un-not s, Within Within Within to	al area, Within tified Industrial are in urban develope urban undevelope commercial area, mits, no civic in interiors, Within	ea, DWithin ed Area, Ded area, DWithin frastructure
		500000000000000000000000000000000000000				- Carl Hebro	n Pural II
11.	Classification of the Locality	Urban o	developed,	□ Urban d	eveloping	. 🗆 Semi Urban,	□ Rural, □
		Backward	. 🗆 Industria	l, 🗆 Institu	tional		
	Location consideration					en, □ On >30' w	ide road. □
12.	Eucation Consideration	Near to Me North-Eas within the Location v	etro station, t Facing, locality,	□ Near to I Ordinary lo Normal Lo y, □ Poor	Market, Discation with ocation will location will	Near to Highway, hin locality, □ Goot thin the locality, within the locality,	Entrance od Location Average
13.	Is Plant part of notified	VZ Yes, □	No				
	Industrial Area? If yes then name of Industrial area/ estate & governing authority managing it.						
14.	Proximity to civic amenities	School	Hospital	Market	Metro	Railway Station	
		1 km	1 km	1 km	buses	Crokm	28/km
15.	Any new development in surrounding area	wetwo roug Din busters.					
16.	Jurisdiction limits			100		Gram Panchaya inicipal limits	t, 🗆 Nagar
17.	Jurisdiction Development Authority Name		MIDC				
		☐ Area no	t within any	developm	ent author	rity limits	
18.	Municipality/ Municipal Corporation Name	Name:	pimp	ri chi	inchw	nd Munici	pul

Í		☐ Area not within any municipal limits
19.	Surrounding land uses and adjoining/ nearby establishment details	Italustrial, and commercial.
0.	Is the location proper for the subject industry?	yes.
1	Is it a standalone Industry in this area? is it a belt for the subject nature of Industry?	MA. All thos.
2.	In case Industry gets closed then does the land can be used for any other purpose?	Depends.

	PLANT DETAILS				
S.No.	PARTICULARS	DESCRIPTION			
1.	Brief History & Description of the Plant	API Facility injectable, Denelope pharmacenticulo products. terblets. copsules.			
2.	Nature of Industry	pharma centiculo.			
3.	Plant Inception Date	15/06/2021			
4.	Commercial Operational Date				
5.	No. of Production Lines				
6.	Date of Inception of each Production Line	15/06/2021			
7.	Total Block Value of the Machines (As on Year ending 31st March)	Refer FAR			
8.	Industry benchmark cost for setting up these Plants (for eg. Per MW or Per MT)				
9,	Establishment Type	Tundigenous, □ EPC Contractor, □ Local Contractor			
10.	Plant Type	□ Manual, □ Semi-Automatic, □ Fully Automatic, □ Conventional, □ Non-Conventional, □ Computerized Controlled			

11.	Plant & Machinery Purchase Type	VFirst Hand, □ Second Hand
12.	Plant & Machinery Make	□ Domestic branded, □ Domestic local made, □ Onsite fabrication □ Imported machines, □ Mfx (Domestic + Foreign)
13.	Plant Overall Condition	□ Newly Commissioned, \□ Excellent, □ Very Good, □ Good, □ Average, □ Poor, □ Completely scrap
14.	Plant Status	Naintenance, □ Completely shutdown
15.	If Plant is not operational then period since it is not operational & reason for not being in operation	MA
16.	If Plant is not operational then does it require any money for refurbishing to restart the Plant?	alt
17.	Total money spent in last one year on maintenance of machines	Details not available
18.	Any major failure, fault, breakdown in last 3 years?	40-
19.	Any Technology collaboration of the Plant	petails not available
20.	Average Plant Capacity Utilization rate in last one month. Attach Production chart of last one week.	Refer maril (Mash Goyal)
21.	Name & Function of each block in the plant - Use Separate Sheet If Required	
22.	Main machines used in the Plant - Use Separate Sheet If Required	Yes-
23.	Estimated net weight of the large machines and of total machines present at site - Use Separate Sheet If Required	refer FAR
24.	Estimated Economic Life of the Plant/ Machines	As por FAR
25.	Age of the Plant/ Remaining	1

	100	
20.	Record of Last Maintenance Done (Attach Copy Of Maintenance Log Book If Possible)	Details not available
27.	Production Capacity In Quantity & Weight For Different Products/ Units	Refer mail. (Youth Gayor)
28.	Description Of Products Manufactured	Tellpressements trablets, capsules; sor
29.	Brand Name under which Products are sold in the Market	Emana
30.	Raw Material Used & Sources Of Primary Raw Material Used	
31.	No. & Type of Furnace	4 to. A Boilor
32	No./ Type/ Height of Chimney/ Exhaust	Q 30.00 m/s.
33.	Is Plant using obsolete technology or currently used technology in the market? Please comment.	yes.
34.	Whether STP is installed (Mention Type & Capacity)	Yes
35.	Whether ETP is installed (Mention Type & Capacity)	yes.
36.	Fire Fighting System	Yes.
37.	No. of Resources Working In the Plant (Managerial, Skilled, Unskilled)	
38.	Is the adequate skilled labour available in this area for the subject Industry?	yes.
39.	Power Supply arrangements in the Plant (Sanctioned Load Kw and Units consumed in last 3 months)	
40.	Auxiliary power arrangements type in the plant (Type & Capacity)	വൗട്ട് Sets, □ Captive Power Plant

41.	HVAC System In the Plant	Yes
42.	Cooling System In the Plant	Yes
43.	Water Arrangements/ Source of water	☐ Jet pump, & Submersible, ☐ Jal board supply, ☐ Reservoir, ☐ Any other:
44.	Major issues noticed in the Industry which can create issues in operations	No.

ATTACHMENTS:

S. No.	PARTICULARS	DESCRIPTION
1.	Inventory Sheet of P&M from Fixed Asset Register (Machine Name/ Machine Type/ Capacity/ Model No./ Machine Make/ Capitalization Date/ Capitalization Value/ Current Book Value/ Machine Status (working/ not working)	
2.	Flow chart / Block diagram from raw material to finished product	
3.	Plant Layout	
4.	Factories registration	
5.	Labor license	
6	Fire NOC	
7.	Copy of last paid Electricity Bill	
8.	NOC from Pollution Control Board	
9	Environment Clearance (if applicable)	
10.	Petroleum Product Storage license (if applicable)	
31.	Explosive Product Storage license (if applicable)	
12.	Export Import Code (If applicable)	
13.	Any other approval or NOC as per industry	
14	Daily Performance Report	
15.	Production data of last one week	
16	Plant maintenance log	

CASE NO.

UNDERTAKING BY THE CUSTOMER

I confirm that the property is inspected in front of me and I have provided all the information true related to the property to the best of my knowledge. I understand that any false or manipulative information provided by me will be considered as cheating with the professional organization since it will lead to incorrect valuation report and Ed be solely responsible for this unlawful act and will bear the charges for the changes/ modifications which have to undergo due to the false information. I also undertake that I haven't given any cash or in kind to any member of R.K. Associates to influence the Value of the Property or favor any individual or organization and the same is not accepted or asked by the member of R.K. Associates. Any such act will lead to cancellation of the material prepared by R.K. Associates with forteiting of the fees and i'll be completely responsible for its repercussions and legal actions taken for it.

IMPORTANT: We have not authorized any of our Surveyor to take Cash or kind from the customers in any situation. In case Surveyor or any member of R.K. Associates asks for any money or kind from you then kindly please inform on number +91-9999597597. Our Valuation process is very stringent and have multiple check points to ensure correct & error free reports to keep the lending agency risk free. In case Surveyor claims that he would be able to arbitrary effect the Valuation figures unfairly or as per your requirement & need then he is making a Talse claim to you and we request you to complaint such act immediately on the number provided above.

Name: Yady Goya

Signature: Yung Mobile No.: 9521233243

Date: 15th Tune 2021

UNDERTAKING BY THE SURVEYOR

I confirm that I have carried out the Survey of the property properly as per the fair professional best practices and Valuation & Survey policy guidelines issued by the organization. I have not taken any cash or kind from the customer or given the customer any wrong or false information or have made any false claims for arbitrary providing the Property Valuation as per one's need or requirement by distorting the facts. In case at any point of time it is found that I have done any kind of fraudulent activity in this case and misled the company then I understand its legal consequences and appropriate penal action which company can take against me. Also in regard to it any monetary or reputation loss will be recovered from me by the company.

Surveyor Name: Sureth mandarber
Signature: 15/06/2021

Page 13 of 14



Enclosure: 6

SURVEY SUMMARY SHEET

(TO BE ENCLOSED WITH VALUATION REPORT)

(Version 1.0) | Date of implementation: 10.04.2017

Every Valuation report at B.K. Amorates is prepared hased on the thirough survey of the property carried out by our Engineering Surveyor. This Survey Summary Sheet is for the Information of Banker/ concerned interested organization. Detailed Survey Form can also be made available to the interested organization in case it is required to cross check what information our surveyor has given in site inspection report based on which Valuation report is prepared.

	File No.			
2.	Name of the Surveyor	sure sh mandarkar		
3.	Borrower Name			
4	Name of the Owner	Dimin Ganetta Inforter		
5.	Property Address which has to be valued	Emcune, P-2, Rigiv-Ganelli Intorted		
6.	Property shown & identified by at	Owner, Depresentative, could not be done from inside	No one was available.	
	spot	Name		Contact No.
			95217	400d Forom name plate
7.	How Property is Identified by the Surveyor	From schedule of the properties mentioned in the deed, From name plate displayed on the property. Endentified by the owner/ owner representative, Enquired from nearby people, I identification of the property could not be done. Survey was not done.		
8.	Are Boundaries matched	☐ Yes, ☐ No. O No relevant papers available to match the ocumbation		
9.	Survey Type	Half Survey (Measurements from outside & photographs) wat plut of		
10.	Reason for Half survey or only photographs taken	Property was locked. Decisessee didn't allow to inspect the property.		
11.	Type of Property	property so coulant to be solve to the control of		
		Plot. L. Agriculturar Cario	a massirement No me	asurement
12.	Property Measurement	Self-measured, Desample measurement, On No measurement It's a flat in multi-storey building so measurement not required		
13.	Reason for no measurement		Owner/ possessee didn't	practically not possible to
		As per Title deed	As per Map	As per site survey
14.	Land Area of the Property		Description of the second	As per site survey
15	Covered Built-up Area	As per Title deed	As per Map	we have seen all
23.			T Under Construct	ion. Couldn't be Surveye
	THE RESERVE OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TRANSPORT OF THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TW			
16.	Property possessed by at the time of survey	☐ Property was locked, ☐ §	Bank sealed, Court seale	ed

1	property during survey	
18.	Is independent access available to the property	Clear independent access is available. ☐ Access available in sharing of other adjoining property. ☐ No clear access is available. ☐ Access is closed due to dispute
19.	is property clearly demarcated with permanent boundaries?	Yes, □ No, □ Only with Temporary boundaries
20.	is the property merged or colluded with any other property	to Cormation Details *
21.	Local Information References on property rates	Please refer attached sheet named 'Property rate Information Details' Report details mul.

Endorsement:

Signature of the Person who was present from the owner side to identify the property:

Undertaking: I have shown the correct property and provided the correct information about the property to the surveyor of R.K Associates to the best of my knowledge for which Valuation has to be prepared. In case I have shown wrong property or misled the valuer company in any way then I'll be solely responsible for this unlawful act

		0-140
a. Name of the Person:	Yash	appen

b. Relation:

c. Signature:

In case not signed then mention the reason for it:

No one was available,

Property is locked,

Owner/ representative refused to sign it,

Any other reason:

2. Surveyor Signature who did site inspection:

Undertaking: I have inspected the property and cross verified the property details at site to the extent of a. Matching boundaries of the property, b. Sample measurement of its area, c. Physical condition, d. Property rates as per local information with what is mentioned in the property documents provided to me by the Bank/ interested organization. I have not come under influence of anyone during site inspection and have only recorded the true and factual details in the survey form which I come across during the site survey. I understand that giving any manipulative information in the survey form will lead to incorrect Valuation report which is an unlawful act and i'll be solely responsible for doing it.

a Name of the Surveyor: Sureth, Mandovker	
c Date: 15/06/2021 In the received	intermulian
> the area with the most Hygience is servey from out the outside	aven