File No.	RKA/DNCR//
Date of Receiving	08/12/21
	1



File Receiver Name ONWY AND Subhash Chandra.

# CASE COLLECTION FORM (Version 5.0) of implementation: 9.02.2011 | Last Revision: 30.01.2020 | Latest Revision: 31.10.2020

	Items	Assign	ed To	Assigned	To be	Submitted On date	Grade	HOD Engg. Signature
				to Date	completed by date	Officiale		
File	Received By	Subhas	sh·c	NA	NA			
Surv	ey	Shreyas	44					
		Dipest						
Prep	aration							
	A - Very Good, B	B - Satisfaci	tory, C - A	Average, D -	Poor, E - Ext	remely Poor		for
	Returned to HOD . unprepared due	☐ Sur rates i proper	rvey not of s not proof of the state of the	done proper perly done, , D Photo photo not ta	ly, □ Survey □ Identification graphs not on tken, □ Owno	Form not propon is not clearly	☐ Selfie. esentative	☐ Market survey for Measurement is not // Owner or owner signature not taken,
by th	se File is returned e preparer - HOD J. comment & ature	Survey	yor. Repo	ort preparer t	o collect the n	approved for nissing informa	(ION ON MS	on with warning to own.
20146466924	and the second of the second o			CENEDA	L DETAILS			
1.	Proposal/ Work C	order or	1/19	2 ( 2021	-22)-PI	701-6	08-8	29
	Ref. No.		VIC	, ( 2021				
2	Type of Service		∕ Valua	ation Report,	☐ Constructi	on cost estima	te, □ Cost	vetting certificate
0	Turns of quotomor		☐ Other ☐ Bank		ates, □ TEV F □ PSU	Report,   LIE  NBFC	☐ Corpora	ate
3.	Type of customer		Com	All and the second second	☐ Private clie		client thro	
4.	Bank/ FI/ Organiz Name & Address	ation	SBI	CAG B	ranch, A	lew Dell	11	
5.			Name Contact Number Email Id					
0.	Case Allotment O	fficer/		Name	Conta	ot italinoo.		Ziridii id
J.	Case Allotment O Fees paying party		Shikh	a Maam	<b>9864</b>	340385	CO. 1	cagdel@sbi.
6.					<b>9864</b>	340385	CO. 1	cagdel@sbi.
	Fees paying party		□ Ca	a Maam	<b>9864</b>	340385 Case fo	co. 10 or exiting a	cagdel@sbi.
6.	Fees paying party  Case Type	Details	Amoun	o Maam	T 864  Account  Advance An	340385 Case fo	Co i por exiting a  Fees  Bank	Cagdel @ Sbi.

A		CASE DETAILS						
	Type of Property	Commercial Land & 8	Suilding	1 + RE	esidencial			
2.	Purpose of Valuation/ Assignment	□ Value assessment of the asset for creating new collateral mortgage □ Periodic Re-Valuation for Bank, □ Distress sale for NPA A/c., □ For DRT Recovery purpose, □ Capital Gains Wealth Tax purpose □ Partition purpose, □ General Value Assessment □ Any other:						
3.	Owner/ Applicant Details	Name Mahanayar Telephone Nigam Limited,	Contact	t Number	Email Id			
4.	Account Name	Mahanagar Teleph	one	Nigam	Limited .			
5.	Property Address	Crimbala Hill Telephone Hill, Mumbai - 40002	Exchar 6.					
6.	Who will coordinate on	Name		Contact Number				
	site for the site survey	Gravas Ji'		9757152021				
7.	Preferred time of survey	Date 23/02/22			1 + 30 pm			
8.	Documents Received (Any one ownership document and approved site plan/ map is must)	<ol> <li>Ownership Documents: ☐ Registered Will, ☐ Relin ☐ Conveyance Deed, ☐ Al</li> <li>Map: ☐ Cizra Map, ☐ App</li> <li>Utility Bills: ☐ Electricity I receipt, ☐ House Tax dema</li> <li>Any Other document: ☐ ☐ Old Valuation Report</li> <li>No documents provided:</li> </ol>	quishmer Illotment L roved Ma Bill & pay and & pay CLU,   The Total Tota	nt Deed, ☐ Tr etter, ☐ Poss p, ☐ Site Plar ment receipt, ment receipt	ansfer Deed, session Letter n □ Water Bill & payment Property Tax bill.			
9.	Documents received from	MTNL- Chetan J	i.					
10.	Special Instructions if any:	MTNL- Chetan J Land + Building including Residencial)						
11.	Valuer firm to distort any	nentioned above for the preparation of facts and would not try to influence it any individual or organization by a	e any mer	nper or official	gree that I'll not put pressure of the firm in the ill spirit or			

1	File No. RKA/DNCR//						
	FILE RECEIVER CASE COLLECTION PROCESS COMPLIANCE CHECKLIST  (To be filled by Surveyor)						
S.NO.	COMPLIANCE CHECKLIST	STATUS	APPROVER SIGNATURE/ REMARKS IN CASE OF ANY (X)				
1.	Is Case collection Form properly filled by Receiver?	Ø					
2.	Is purpose of the assignment understood clearly by the receiver?	J					
3.	Has receiver checked if this is a new case or existing case of the Bank?	A					
4.	Has receiver fixed the fees with the manager/ client and sent quotation properly or have taken approval of the work over email?	<i>y</i>					
5.	Has receiver taken proper Work Order/ Email/ CESA form formality?	J					
6.	In case of private case or for fresh case 50% advance is received?						
7.	Is document checklist email sent to the customer?						
8.	Has the received documents is having 'documents						

### IMPORTANT INSTRUCTIONS TO SURVEYOR

provided by stamp'?

1.	Please fill the above compliance checklist before moving for the survey.
2.	Please do not do the survey if you do not have proper documents.
3.	For Vacant Plot/ Land - Cizra Map/ Master/ Zonal/ Site Plan is must to identify the Plot. For
	Agriculture or converted land from agriculture – Mutation documents, CLU is must.
4.	Firstly please first study the documents of the property which needs to get surveyed.
5.	Mark the Owner/ Area/ Boundaries mentioned in the ownership documents with bold florescent
	marker pen before moving for the survey. During site survey if any difference is found in the
	above fields from the ownership documents then please contact the owner immediately to
	know the reason for the difference.
6.	Confirm ongoing property rates in the subject location through public domain, property sites and
	contact dealers to show you the available properties in that area during your survey.
7.	Identify the Property clearly by matching the boundaries and area mentioned in the property
	papers.
8.	Do sample physical or google measurements of the property.
9.	PHOTOGRAPH INSTRUCTIONS:
	a. Take owner/ representative photograph along with the property.
	b. Take your selfie along with the property and the owner/ representative.
	c. Take full scale photo of the property with gate.
	d. Take photo of the property along with abutting road, towards left, right and center.
	e. Take multiple photos of inside-out of the property.
	f. Take nearby photographs of the Property.
	g. Take a short video to cover property and neighborhood.
10.	Take Google Man location.
11.	Check main road name & width and approach road width and distance of property from main road.
12.	Check Jurisdiction Municipal Limits & Ward Name.
13.	Fill each column of survey form diligently in detail and tick the appropriate option clearly.
14.	Check any defects or negativity in the property and comment in detail on survey form.
15.	Do extensive market rate enquiries and confirm for any recent past transactions.
16.	In case customer appears to be providing misleading information to you or trying to influence you by
	money or cash then immediately report to the Management & Bank.

	SURVEY GRADING MATRIX
$\mathcal{L}$	PARAMETERS/ CRITERIA
	In case all the points below are done properly, timely with full care and diligence:
	<ol> <li>Survey started with proper work order and knowing the source of payment.</li> <li>Survey done with proper documents.</li> <li>Done complete homework and studied the documents properly with highlighting the main points before moving for the survey.</li> <li>Chosen correct survey form as per the property type.</li> <li>All fields of Survey form are properly filled.</li> <li>All site special observations and negative and positive factors are clearly mentioned.</li> <li>Self &amp; client signatures taken on survey form.</li> <li>Property rates information properly taken, mentioned and verified.</li> <li>Site rough sketch plan made.</li> <li>Proper photographs taken.</li> <li>Selfie with property taken.</li> <li>Selfie and owner photograph with property taken.</li> </ol>
В	In case of 3 minor mistakes in any of the above points except Point 1, 2, 3, 4, 6, 8, 10, 11, 12 but all the
С	In case of more than 3 minor mistakes and any 1 major mistake in any of the above points and if any points are completely missing except Point 1, 2, 3, 4, 6, 8, 10, 11, 12.
D	In case of 1 major micrake or missing of any 1 point out of 1 2 3 4 6 8 10, 11, 12.
E-	In case of more than 1 major mistakes or missing of more than 1 point out of 1, 2, 3, 4, 6, 8, 10, 11, 12.

Note (Survey Grading Matrix):

- 1. For special assignments like LIE, Stock Valuation, etc. where till date survey format is not specified or released, in such cases point wise site observation report has to be submitted by the Surveyor duly signing it properly. Without signed Site Observation report, Point 4 will be considered as not done and will fall under Category E.
- 2. Similar Grading Matrix is issued for Case Collection & Report Preparation as well.

Note (Overall Grading Matrix):

1. In case client reports any careless mistake in the report for which revision has to be done in the report then in that case Grading Matrix may be revised and Grade E will be awarded.

	SURVEY PROCESS COMPLIANCE CHECKLIST	
/	(To be submitted by Surveyor with each Survey)	
10.	COMPLIANCE CHECKLIST POINTS	STATUS
1.	Did you take proper property documents to carry out the survey?	V
2.	Have you properly studied & highlighted Owner/ Area/ Boundaries in the property documents with bold florescent before moving for the survey?	J
3.	Did you check prominent landmark nearby the subject property and mentioned in the survey form?	Ø
4.	Did you identified the Property clearly by matching the boundaries and area mentioned in the property papers?	. 🗆
5.	Did you check if property is merged with any other property or it is an independent property?	
6.	Did you do sample physical or google measurements of the property in case of property more than 2500 sq.mtr?	<i>y</i>
7.	Did you check for any building violations in the property?	
8.	Did you check municipal limits/ jurisdiction/ ward?	
9.	Did you take Google Map location and shared it to Maps whatsapp group?	
10.	Did you check Main road name & width and its distance from the subject property?	
11.	Did you check approach Lane width on which property is located?	
12.	Have you taken property full scale photograph with gate?	V
13.	Have you taken owner/ representative photograph with the property?	
14.	Have you taken your selfie with the property along with owner/ representative?	
15.	Have you taken photograph of the property along with abutting road and towards left and right of the property?	
16.	Have you taken multiple photographs of the property from inside-out?	V
17.	Did you check nearby development and whereabouts and commented on survey form?	D
18.	Did you check any defects or negativity in the property in terms of location, legality, disputes, marketability, salability, etc. and commented on survey form in detail?	
19.	Have you filled all the columns of survey form including survey summary sheet properly?	
20.	Did you draw site key plan (location map)?	
21.	Did you draw rough site sketch plan?	
22.	Have you taken self-attested documents from owner/ representative and stamped "documents provided by stamp"?	
23.	Did you check any defects or negativity in the property in terms of location, legality, disputes, marketability, salability, etc. and commented on survey form in detail?	Z
24.	Have you confirmed any recent past transactions during market enquiries and enquired property rates locally very rigorously?	<b>P</b>
25.	Did you take signatures of the owner/ representative on undertaking and survey summary sheet?	Ø
26.	Did you signed the undertaking?	1
20.	Did you signed the undertaining.	

For File No.	VIS (2021-22) -PL 701-608-8
Surveyor Name	Shreyash & Dipelh
Signature	ziBedmitha.
Date	23/02/22

GENERAL SURVEY FORM
(FOR PROPERTIES OTHER THAN FLATS)
(Version 5.0)
Date of implementation: 9.02.2011 | Last Revision: 04.01.2018 | Latest Revision: 31.10.2020

	the state of			T	
File No. RKA/DNCR//.	Date:	23/02	122	Time:	1.30 pm

		GENERAL DETAILS	
1.	Name of the Surveyor	e. 18011	
2.	Property shown by	Downer D Representative DN	lo one was available, □ Property is
		locked, survey could not be done fr	rom inside
		Name	Contact No.
		Commit	0752152021.
3.	Survey Type	Gavas Ti. Full survey (inside-out with mea	surements & photographs) .
		Half Survey (Measurements from	n outside & photographs)
	Very large Property	☐ Only photographs taken (No me	
4.	Reason for Half survey or only	☐ Property was locked. ☐ Poss	essee didn't allow to inspect the
	photographs taken	property, □ NPA property so could	n't be surveyed completely
5.	How Property is Identified	From schedule of the propertie	s mentioned in the deed, From
		name plate displayed on the proj	perty, Identified by the owner/
		owner representative,  Enquired	from nearby people,
		☐ Identification of the property cou	lld not be done, $\square$ Survey was not
		done	
6.	Type of Property	☐ Flat in Multistoried Apartment, ☐	☐ Residential House, ☐ Low Rise
	(Commercial land & Building) +	Apartment,   Residential Builder	Floor, Commercial Land &
	& Building) +	Building, ☐ Commercial Office, ☐	Commercial Shop,   Commercial
	Residencial ( in Same	Floor,   Shopping Mall,   Hotel,	] Industrial, □ Institutional,
	building as commercial	☐ School Building, ☐ Vacant Res	sidential Plot, 🗆 Vacant Industrial
	building ) + Substation	Plot, □ Agricultural Land	
7.	Property Measurement Building	☐ Self-measured, ☐ Sample meas	urement only, $\square$ No measurement
8.	Reason for no measurement	☐ It's a flat in multi storey building s	
	NA.	☐ Property was locked, ☐ Owner/ p	
		☐ NPA property so didn't enter the	property, Very Large Property,
		practically not possible to measure	re the entire area   Any other
		Reason:	
9.	Purpose of Valuation	☐ Value assessment of the asset fo	
		Periodic Re-Valuation for Bank, [	
		☐ For DRT Recovery purpose, ☐ C	
		□ Partition purpose, □ General Val	1544 P. 18 18 18 18 18 18 18 18 18 18 18 18 18
10.	Type of Loan	☐ Housing Loan, ☐ Housing Take (	
		Loan, ☐ Loan against Property, ☐ 0	
		Loan, ☐ Car Loan, ☐ Project Loa	
		enhancement,   Cash Credit Limit,	☐ Industrial Loan, ☑ NA
11.	Loan Amount		

Page 6 of 15

5.	Property Purchaser Name Property Address under Valuation	OWNERSHIP DETAILS  Mahanagar Telephone Nigam Limited.  Mahanagar Telephone Nigam Limited.  Cumbala Hill Telephone Exchange, Pedder Road,  Cumbala Hill Mumbai - 400026
4.	Present Residence Address of the Owner/ Purchaser	- (ambala Hill, Mumba; - 400026
5.	Property constitution	☑ Free Hold, ☐ Lease Hold

Contract of the Contract of th	<u>LOCATION DETAILS</u>							
1.	Adjoining Properties	SE & 'East		West		orth		outh
	(Match it with papers with the help	Ambaria House	e Pedo	der Road	Pedde	r Road,	Kenili	Joth
	of compass or Sun direction and	+ Antilia	Ash	a Mahal	Kalla:	to cut	Blog.	
	also confirm it with nearby people)	BEST Officers	Blace	9.	naipa.	ida.	J	
2.	Property Facing	Amban's House  Antilia,  BEST Officers  Bast Facing, [	North	Facing, □ \	West Fac	ing, $\square$ Sc	outh Fac	cing,
		☐ North-East Fa		1.71				
		North-West Fa						
3.								
	Landmark	Antilia, Ped BMC - D	der	Road, M	TNL	Blog.		
4.	Ward Name/ No.	RMC-D	Ward			U		
5.	Zone Name							
6.	Main Road Name & Width	Name		Widt	h	Distance	e from	property
		Pedder Road				(	)~~	
7.	Approach Road Name & Width	Pedder Ro	cd.					
8.	Location consideration of the	Pedder Ro Within Main o	ity,	Within Good	Urban o	developed	Area,	☐ Within
	Society	developing area,						
		□ Ordinary, □	•					
			iii iiitoiie	oro, 🗀 rtome	io alou,			
		□ Poor						
9.	Special Location consideration	☐ Park Facing,	☐ Pool	I Facing,	Road Fa	acing, $\square$	Entrand	ce North-
	of the property	East Facing,   S	Sunlight	facing				
10.	Characteristics of the locality	Urban develor	oed, □ l	Urban develo	ping, 🗆	Semi Urb	an, 🗆 F	Rural,
	\	□ Backward, □ I	ndustria	al □ Institutio	onal			
11.	Category of Society/ locality	☐ High End, ☐ N	Normal,	☐ Affordable	e Group	Housing,	□ EWS	s, □ HIG,
		☐ MIG, ☐ LIG	-					
12.	Utilities/ Facilities in the locality	∠ Lifts, ☐ Garde						
		☐ Club House,	□ wall	k Trails, □	Kids pla	y zone,	<u> </u> 100°	% Power
40	Drawinsitute sivie amenities	Backup School Hos	spital	Market N	Metro	Railway S	tation	Airport
13.	Proximity to civic amenities	1						
		350m 50		450m =	•		m.	22km
14.	Any new development in	Construction vicinit	5 9	oing on	10	near	rby	
	surrounding area	vicinit	y .		8 Z 81 Z			

			그는 사람들이 되었다면 하는데			
		risdiction limits	□ Nagar Nigam, □ Nagar Panchayat, □ Gram Panchayat, □ Nagar			
		BMC	Palika Parishad, □ Area not within any municipal limits			
	5.	Jurisdiction Development	□ DDA, □ GDA, □ NOIDA, □ GNIDA, □ YEIDA, □ HUDA, □KMDA,			
	/	Authority Name	☐ MDDA, ☐ Any other Development Authority:			
1		BM C	☐ Area not within any development authority limits			
-	17.	Municipal Corporation Name	□ NDMC, □ SDMC, □ EDMC, □ Ghaziabad Municipal Corporation,			
		0	☐ Gurgaon Municipal Corporation, ☐ Faridabad Municipal Corporation,			
		BMC	☐ Kolkata Municipal Corporation, ☐ Dehradun Municipal Corporation,			
			☐ Area not within any municipal limits, ☐ Any other Municipal			
			Corporation/ Municipality:			
	A Vernica A Nava Andrea		DUVOICALIDETAILS			
	1.	Land Area	PHYSICAL DETAILS  As per Title deed			
		Land / Wod	4270.85 sq.m 4270095 -			
	2.	Any conversion to the land use	Not known to us.			
	3.	Land Type	Solid, ☐ Rocky, ☐ Marsh Land, ☐ Reclaimed Land, ☐ Water			
			logged. ☐ Land locked			
	4.	Shape of the Land	☐ Square, ☐ Rectangular, ☐ Trapezium, ☐ Triangular, ☐ Trapezoid,			
1			☑ Irregular, □ NA			
	5.	Level of Land	✓ On road level, ☐ Below road level, ☐ Above road level, ☐ NA			
	6.	Frontage to depth ratio	☐ Normal frontage, ☐ Less frontage, ☐ Large frontage, ☐ NA			
	7.	Are Boundaries matched	☐ Yes, ☐ No, ☐ No relevant papers available to match the			
			boundaries,  Boundaries not mentioned in available documents			
	8.	Is Independent access available	Clear independent access is available,   Access available in			
		to the property	sharing of other adjoining property,   No clear access is available,			
			☐ Access is closed due to dispute			
	9.	Is property clearly demarcated with permanent boundaries?	✓ Yes, □ No, □ Only with Temporary boundaries			
	10.	Is the property merged or colluded with any other property	No, not merged.			
11. Property possessed by at the time of survey  □ Owner, □ Vacant, □ Lessee, □ Under Co be Surveyed, □ Property was locked, □ B sealed		Property possessed by at the	Owner,  Vacant,  Lessee,  Under Construction,  Couldn't be Surveyed,  Property was locked,  Bank sealed,  Court			
12. Current activity carried out in the property ☐ Residential purpose, ☐ Commercial pu			☐ Residential purpose, ☐ Commercial purpose, ☐ Section, ☐ Office, ☐ Industrial, ☐ Vacant, ☐ Locked, ☐ Any other use:			
		BUILDING	G/CONSTRUCTION/UTLITY DETAILS			
	1.	Construction Status	Built-up property in use, ☐ Under construction, ☐ No construction			
			Page 8 of 15			

Page 8 of 15

	overed Built-up Area	☐ Covered Area, ☐	Floor Area,  Super Are	ea.  Carpet Area
		As per Title deed	As per Map	As per site survey
1	(Tick one on the basis of which			
	valuation is to be calculated)		15276.48 sqim	The state of the s
3.	Total Number of Floors in the	6 + 6	LI Floor 1	Sub Station (
	Building	Basement + U	+ 14 Floors) +	Dullani
4.	Floor on which property is situated	Basement+G-	+ la Floors) +	Sub Station ( Cont
5.	Type of Unit/ Number of Rooms/ Cabins/ Cubicles	1/ //	"	
6.	Building Type	RCC Framed Str	ructure, 🗆 Load bearing	Pillar Beam column,
		☐ Ordinary brick wa	Il structure, □ Iron truss	ses & Pillars,   Scrap
		shandaned structure		
7.	Roof	a. Make: RBC,	RCC, GI Shed, C	☐ Tin Shed, ☐ Stone
		Datia		
		b. Height: Diff	went on each	flor ·
		c. Finish: Simp	le plaster, POP Pu	nning, POP False
8.	Flooring	Vitrified tiles	Ceramic Tiles, Simp	ole marble,   Marble
0.	Different types of flooring on different	Line Manaia	Cranito   Italian Marble	. L Nota stylie,
	Different US	DIMenden DDCC	☐ Imported Marble. ☐	Pavers, La Chicquoisa
	tracking on allean	Tiles, ☐ Brick Tiles,	☐ No Flooring, ☐ Unde	er construction, $\square$ Any
	410087.	- Ale - u to un o t		the state of the s
9.	Appearance/ Condition of the	Internal -   Excel	lent, □ Very Good, □	No Survey
	Building	☐ Average, ☐ Poor	☐ Under construction, ☐	Cood Ordinary
		External -   Exce	llent, □ Very Good, □	Good, L Ordinary,
	64 0.31	☐ Average, ☐ Poor	☐ Under construction * erage, ☑ Poor, ☐ Under	construction
. 10.	Maintenance of the Building	Very Good, Ave	ry Good, Good, G	Simple. Ordinary,
11.	Interior decoration	☐ Average, ☐ Below	average, □ Under cons	truction, 🗆 140 Curvey
12.	Interior Finishing	Simple plastered v	valls, Brick walls witho	Coved roof.
		Designer textured	walls, POP punning,	3 00 (04 )
		☐ Under construction	,   NO Survey	alls without plaster
13.	Exterior Finishing	Simple plastere	ed walls, □ Brick w esigned or elevated, □	Brick tile Cladding.
		Structural glazing.	☐ Aluminum composite	panel cladding,
		Glass facade,	Domb, 🗆 Porch, 🗀 Under	construction
14.	Kitchen	☐ Simple with no cu	pboard,   Ordinary with	cupboard,   Normal
14.	Tation	Modular with chimne	y, 🗆 High end Modular w	vith chimney, □ Under
		construction,   No S		
15.	Class of Electrical fittings	External, Intern	al	abta 🗆 Chandalia
		Ordinary fixtures	& fittings,   Fancy li	gnis, □ Chandellers, □
Comment of		External, Intern	ig, ☐ Under construction	, L. IVO Guivey
16.	Class of Sanitary/ Plumbing &	✓ Excellent ☐ Very	Good, Good, Simp	le,  Average.
	water supply fittings	☐ Below average. ☐	Under construction, □ N	lo Survey
17	Water arrangements	☐ Jet pump, ☐ Subr	nersible, 🗌 Jal board sup	pply
17.	Fixed Wooden Work	☐ Excellent, ☐ Ve	ry Good, 🗆 Good, 🗆	Simple, Ordinary,
10.	TIACU WOODGII WOIN	□ Average, □ Below Average, □ No wooden work, □ No survey		
19.	Age of Building/ Recent	Control of the Contro		ou Construction.
10.	Improvements done	Approx - 18 /	ears-	и
20.	Maintenance of the Building	.□ Very Good, ☑ Ave	erage, 🗸 Poor	

Page 9 of 15

		ny defects in the building Maintenance issues, Finishing issues, Seepage issues,				page issues,
					icity issues, 🗆 Stru	
	1		☐ Visible crack	s in the building		
	12.	Any violation done in the property	☐ Construction	done without	Map, □ Construc	ction not as per
1		No	approved Map,	☐ Extra covered	without sanctioned	d Map, □ Joined
1		1. 4	adjacent property,   Encroached adjacent area illegally			gally
-	23.	Boundary Wall (Only for individual			dary wall of a comp	plex Finish
		property)	Running Mtr.	Height	Width	FINISH
			/-	/-		
-	24.	Lift/ elevators	Passenger/	Commercial		- 1/ //
		4 Lifts.	Make: Olymp		Capacity: 176	8 kg, 26 person.
	25.	Power backup	☐ Inverter, ☑	G Set	- 4	
			Make:		Capacity: -	
	26.	Garden/ Landscaping	☐ Yes. No.	□ Beautiful, □ Or	dinary	
	27.		Available within the property		☐ On Stilt	
				able within the	blom	Acute parking
	28.	Special Comments/ Observations, if any	Behind house)	Antillia.	(Mukesh	Ambani's
	25/200A (PAC)	MARKETARI		TY UTLTY DE	TAILS	
	_1	Any issues in marketability of the	D Vac DAla			
	1.	property?	Reason in ca	ise of No: La	ocation, Surrou	unding, Legal
		property	aspects, Der	mand, □ Shape, [	☐ Any Other:	
	0	How is Demand & Supply condition	Demand □ V	/ery Good, 🗹 Goo	od, □ Average, □ I	Low,  Poor
	2.	in the Market of such properties?	Supply  U	/ery Good, Goo	od, □ Average, □ I	Low, 🗆 Poor
	3.	Is property easily sellable &	✓ Yes, □ No			
		marketable?	Comments:	Behind And	tillia (Muk	esh Ambanis
			House)			
	4.	How is the current utility of the property?	☐ Excellent, ☐	] Very Good, □ G	ood, Average, D	☐ Low, ☐ Poor
	5.	At what True rate Owner bought	Year of purcha			
		this Property?	Purchase Price			
	6.	Present expected Sale Value of the overall property?				

#### BLANK PAGE FOR PROVIDING ANY ADDITIONAL DETAILS/ INFORMATION

MTNL Survey !-

1) Land & Building .:- Two Buildings are There.

Building 1: Basement + (by + 14)
[This includes commercial of Residencial]

Building 2: - Gitl (Substation Building).

\*) Building 1: & Basement + (G1+14)

Floor 3, 4, 6, 7, 9 -> Griven on Rent.


Floor 10: - Refugee floor

Floor 11 to 14 -> Residencial.

\*) Building 1:- Croound floor to 9th commercial use.

10th Floor -> Refugee floor.

11th to 14 Moor - Residencial.



/	Particulars	Subject Property	Transaction already Comparable 1	Comparable 2	Comparable 3
1	Name (source of information)	NA	Jagdeep	Prem	# Vikrom
	Contact No.	NA	9821134651	9892424566	982157533
	Type of source of information (Seller/ Property dealer/ nearby	NA	Property	Property dealer	property dealer 3.5 lath
•	people) Rates/ Price informed (in Rs. with unit)	NA	13 (2	Lower side:- 1-1.25 lakh Higher end:- 2.5 to 3 lakh.	( Rent).
	Rates Type (Sale/ Buy)	NA	Buy	3 lakt. Rent.	Rent.
	Shape of the Property (Square, Rectangular,		-	-	1100 Sq.Ft
	Irregular) Area/ Size of the Property		2100 Sq. Ft corpet	Soo to 900 sq. ft carpet	
	Legal Status (clear, negative, weak)/ No. of		clear -	Clear	dcar ·
	owners  Location/ surrounding/ neighborhood comparison with the subject property (Similar, Lower, Better, Highly Better than the	Base Case	Swrounding	Near MTNL Building.	Pedder Road.
0.	subject Property  Distance from the subject Property	0	Around 500 m	New MTNL Building.	fo prom
1.	Other factors (Corner, 2 side open, North-East facing, Park facing, Legal/ Financial encumbrance, etc.)		-		
2.	Approach road width		pedden road.	Pedder Joad	Pedder Road
3.	Level of Land (Below/ On/ Above road level)				
1.	Frontage to depth ratio (Normal, Less, Large)		_	2011	Commercial
j.	Present Use		Residencial. (Purchase)	Residencial (Rent)	shop
	Any other details/ Discussion held	NA	Average building Flat on 8th Floor. 3 Car parkings but charges are additional.	Avg. Building Semi-Furnish Flat on Rent is Around I to 1.25 lakh. Orund Building	Pedden Road Fox Purchas Price is 7 C
•	Present expected Sale Value of the overall property?		Partial see  View from  Flat.	& Furnished	for Rent printing is 3.5 lakes. Page 13 of 15

#### UNDERTAKING BY THE CUSTOMER

I confirm that I have made the inspection of the subject property to the surveyor of R.K Associates, which is correct property in question for which the documents have been provided/ submitted by me. I further confirm that I am aware of all the information related to the subject property and I have provided all its information to the surveyor true to the best of my knowledge. I understand that any false or manipulative information provided by me will be considered as cheating with the professional organization since it will lead to incorrect valuation report and I'd be solely responsible for this unlawful act and will bear the charges for the changes/ modifications which have to undergo due to the false information. I also undertake that I have not given any cash or in kind to any member of R.K Associates to influence the Value of the Property or favor any individual or organization and the same is not accepted or asked by the member of R.K Associates. Any such act will lead to cancellation of the material prepared by R.K Associates with forfeiting of the fees and i'll be completely responsible for its repercussions and legal actions taken for it.

IMPORTANT: We have not authorized any of our person/ Surveyor to take Cash or kind from the customers in any situation. In case Surveyor or any member of R.K Associates asks for any money or kind from you then kindly please inform on number +91-9958632707, 0120-4110117. Our Valuation process is very stringent and have multiple check points to ensure correct & error free reports to keep the lending agency risk free, In case Surveyor claims that he would be able to arbitrary effect the Valuation figures unfairly or as per your requirement & need, then he is making a false claim to you and we request you to complaint such act immediately on the number provided above.

Name	Rakesh kumah
Relationship with owner	Employee
Signature	- NIA1104 MY 102/22
Mobile No.	9869434850
Date	23 02 22

## UNDERTAKING BY THE SURVEYOR

I confirm that I have carried out the Survey of the property properly as per the fair professional best practices and Valuation & Survey policy guidelines issued by R.K Associates. I have not taken any cash or kind from the customer nor have I come into any kind of influence of the customer / bank for arbitrary providing the Property Valuation as per one's need. I further state that I have not given any assurances to the customer nor given any wrong or false information or statement. In case at any point of time it is found that I have done any kind of fraudulent activity in this case and misled the company then I understand its legal consequences and appropriate penal action which company can take against me. Also in regard to it any monetary or reputation loss will be recovered from me by the company.

	2) 01 7-1 6-0 829
For File No.	VIS (2021-22)-PL 701-608-829
Surveyor Name	Shreyash Shetty & Dipesh.
Signature	Deboduntha.
Date	23/02/2022.

Page 14 of 15



### UNDERTAKING BY THE PREPARER

Survey Policy Guidelines issued by the organization. I also confirm that without any personal interest, partiality or prejudice, I have worked on this Valuation assignment. Rates adopted for the asset is based on various facts, information collected from the site came to my knowledge during the course of the assignment and I have taken all sincere efforts to review, cross check & confirm this data/ information from all different angles using my prudent approach without any biasedness or pressure. I have prepared the report based on true facts & information as per best of my knowledge & case facts. I understand that any false information provided by me will lead to the incorrect valuation report and I'd be solely responsible for it and will bear the losses which will be put on the Company in form of monetary or reputation loss by its client or statutory bodies.

I also undertake that I did not come into any influence by the customer, Bank representative (officer or agent), colleagues, coworkers or any other person to arbitrary change the Valuation figures or facts unethically or illegitimately which may put the public money at risk which is in the form of Bank deposits.

In case at any point of time in future, if I am found guilty of illegitimately distorting the facts in the Valuation or any other professional services which company offers in the market on being influenced by the customer or Bank representative (officer or agent) or for whatsoever reason then I'd solely responsible of any such act and I understand that the Company can take appropriate legal action against me which may include suspension from the current roles & responsibilities or termination from the employment with immediate effect.

I also undertake that I have not taken any cash, favor or in kind from the customer for favoring any individual or organization by unfair means.

I also undertake that I'll not prepare any report on incomplete Survey form which is not properly filled as per the Company guidelines and in case I am preparing it which is creating an incorrect report then I'd be responsible for its consequences.

For File No.	ALL THE	
Preparer Name		1
Signature		
Date		

Enclosure: 6

## SURVEY SUMMARY SHEET (TO BE ENCLOSED WITH VALUATION REPORT)

(Version 1.0) | Date of implementation: 10.04.2017

Every Valuation report at R.K Associates is prepared based on the thorough survey of the property carried out by our Engineering Surveyor. This Survey Summary Sheet is for the information of Banker/ concerned interested organization. Detailed Survey Form can also be made available to the interested organization in case it is required to cross check what information our surveyor has given in site inspection report based on which Valuation report is prepared.

2. Name of the Surveyor  3. Borrower Name  4. Name of the Owner  5. Property Address which has to be valued  6. Property shown & identified by at spot  7. How Property is Identified by the Surveyor  8. Are Boundaries matched  9. Survey Type  10. Reason for Half survey or only photographs taken  11. Type of Property  12. Property Measurement  13. Reason for no measurement  14. Land Area of the Property  15. Covered Built-up Area  16. Name of the Surveyor  17. How Property is Identified by the Survey (Representative, Impact the property is locked, surveyor (Identified by the owner) owner representative displayed on the property, Identified by the owner/ owner representative Enquired from nearby people, Identification of the property could not be despited by the owner/ owner representative Enquired from nearby people, Identification of the property could not be despited by the owner/ owner representative Enquired from nearby people, Identification of the property could not be despited by the owner/ owner representative displayed on the property, Identification of the property could not be despited by the owner/ owner representative displayed on the property, Identification of the property could not be despited by the owner/ owner representative displayed on the property, Identification of the property could not be despited by the owner/ owner representative displayed on the property was not done  12. Property Measurement   Property was locked, Possessee didn't allow to inspect the property, I property was locked, Possesses didn't allow to inspect the property, I property was locked, Possesses didn't allow to inspect the property of possessed didn't allow to inspect the property was locked, Possesses didn't allow to inspect the property was locked, Possesses didn't allow to inspect the property was locked, Possesses didn't allow to property was locked, Possesses didn't allow it, Pos	1.	File No.	VIS (2021-22)-P	L701-	608 - 820	1	
3.   Borrower Name			Chrenath & Div	resh		CONTROL LINES	1
Name of the Owner			Mahanasar Telephi		Nigan	1 4mites	
Survey Type				one Nig	am limit	ed las doo	di
Survey Type	12210	Property Address which has to be	Cumbala Itill Telef	chai - 4	achange, P	codoll 1	ked survey
Survey Type   Survey (Inside-out with measurements & photographs)   Property was not done   Property (Inside-out with measurements & photographs)   Property was not done   Property was not done   Property (Inside-out with measurements & photographs)   Property was not done   Property (Inside-out with measurements & photographs)   Property was not done   Property (Inside-out with measurements & photographs)   Property was not done   Property (Inside-out with measurements & photographs)   Property was not done   Property (Inside-out with measurements & photographs)   Property was not done   Property was not done   Property (Inside-out with measurements & photographs)   Property was not done   Property (Inside-out with measurements & photographs)   Property was not done   Property   Property was not done   Property   Propert	_		Owner, Representative	, ☐ No one w	vas available, □	Property is loc	Keu, survey
Name   Contact No.	6.		could not be done from inside				
Surveyor   Surveyor   Survey from nearby people,   Identification of the property could not be definition   Survey was not done   Yes,   No,   No relevant papers available to match the boundar   Boundaries not mentioned in available documents   Full survey (Measurements & photographs)   Half Survey (Measurements from outside & photographs)   Only photographs taken (No measurements   Property was locked,   Possessee didn't allow to inspect the property or property so couldn't be surveyed completely   Yeny   Carge   Property   Property was locked,   Property was locked,   Commercial Land & Building,   Commercial Shop,   Commercial Floor,   Shopping Mall,   Hotel,   Industrial House,   Low Rise Apartment   Residential Builder Floor,   Commercial Floor,   Shopping Mall,   Hotel,   Industrial Land   Self-measured,   Sample measurement,   No measurement   Self-measured,   Sample measurement not required   Property was locked,   Owper/ possessee didn't allow it,   NPA property was locked,   Owper/ possessee didn't allow it,   NPA property was locked,   Owper/ possessee didn't allow it,   NPA property was locked,   Owper/ possessee didn't allow it,   NPA property was locked,   Owper/ possessee didn't allow it,   NPA property was locked,   Owper/ possessee didn't allow it,   NPA property was locked,   Owper/ possessee didn't allow it,   NPA property was locked,   Owper/ possessee didn't allow it,   NPA property was locked,   Owper/ possessee didn't allow it,   NPA property was locked,   Owper/ possessee didn't allow it,   NPA property was locked,   Owper/ possessee didn't allow it,   NPA property was locked,   Owper/ possessee didn't allow it,   NPA property was locked,   Owper/ possessee didn't allow it,   NPA property was locked,   Owper/ possessee didn't allow it,   NPA property was locked,   Owper/ possessee didn't allow it,   NPA property was locked,   Owper/ posses		spot	The second secon			Contact No.	OF LOT STORY
Surveyor   Surveyor   Surveyor   Candidate   Commercial Survey			1		97571	52021	- plata
Are Boundaries matched	7.		Enquired from nearby peopl	e, 🗆 Identific	cation of the pro	perty could n	ot be done,
Boundaries not mentioned in available abculletts   Survey Type			□ Ves □ No. □ No re	levant paper	rs available to	match the	boulluaries,
Survey Type	8.	Are Boundaries matched	I da device not montioned	in available	documents		
Half Survey (Measurements from outside & photographs)   Only photographs taken (No measurements)   Property was locked, Possessee didn't allow to inspect the property, property so couldn't be surveyed completely			Boundaries not mentioned	h measureme	ents & photograp	phs)	
Property was locked,   Possessee didn't allow to inspect the property so couldn't be surveyed completely   Ory   Orge   Property	9.	Survey Type	Half Survey (Measuremer	its from outsi	ge & priotograpi		orty
Self-measured, Sample measurement   Self-measure building so measurement not required   NPA property was locked, Owner/ possessee didn't allow it, NPA property   Owner/ possessee didn't allow it, NPA property   New Large Property, practically not possible measure the area within limited time Any other Reason:    As per Title deed		photographs taken	property so couldn't be surved  ☐ Flat in Multistoried Apart Residential Builder Floor,  Commercial Shop, ☐ Comm  ☐ Institutional, ☐ School B	ment,  Resi	dential House, [ Land & Building,	☐ Low Rise Ap  ☐ Commerciall, ☐ Hotel, [	artment, $\square$ al Office, $\square$ $\square$ Industrial
13. Reason for no measurement  □ It's a flat in multi storey building so measurement not required □ Property was locked, □ Owner/ possessee didn't allow it, □ NPA property was locked, □ Owner/ possessee didn't allow it, □ NPA property didn't enter the property, □ Very Large Property, practically not possibly measure the area within limited time □ Any other Reason:  14. Land Area of the Property  As per Title deed  As per Map  As per site survey  As per Title deed  As per Map  As per site survey  As per Title deed  As per Map  As per site survey  As per Title deed  As per Map  As per site survey  As per Title deed  As per Map  As per site survey  As per Sample Measure the Asper Dunder Construction, □ Couldn't be Survey			Plot, Agricultural Land		· □ No moasi	rement	
13. Reason for no measurement  □ It's a flat in multi storey building so measurement not required □ Property was locked, □ Owner/ possessee didn't allow it, □ NPA property was locked, □ Owner/ possessee didn't allow it, □ NPA property didn't enter the property, □ Very Large Property, practically not possibly measure the area within limited time □ Any other Reason:  14. Land Area of the Property  As per Title deed  As per Map  As per site survey  As per Title deed  As per Map  As per site survey  As per Title deed  As per Map  As per site survey  As per Title deed  As per Map  As per site survey  As per Title deed  As per Map  As per site survey  As per Sample Measure the Asper Dunder Construction, □ Couldn't be Survey		n	☐ Self-measured, ☐ Sample	e measureme	nt, 🗆 No meast	no muiro d	
Property was locked,   Owner/ possessee durit and the didn't enter the property,   Very Large Property, practically not possible didn't enter the property,   Very Large Property, practically not possible didn't enter the property,   Very Large Property, practically not possible didn't enter the property,   Very Large Property, practically not possible didn't enter the property,   Very Large Property, practically not possible didn't enter the property,   Very Large Property, practically not possible didn't enter the property,   Very Large Property, practically not possible didn't enter the property,   Very Large Property, practically not possible didn't enter the property,   Very Large Property, practically not possible didn't enter the property,   Very Large Property, practically not possible didn't enter the property,   Very Large Property, practically not possible didn't enter the property,   Very Large Property, practically not possible didn't enter the property,   Very Large Property, practically not possible didn't enter the property,   Very Large Property, practically not possible didn't enter the property,   Very Large Property, practically not possible didn't enter the property,   Very Large Property, practically not possible didn't enter the property,   Very Large Property, practically not possible didn't enter the property   Very Large Property, practically not possible didn't enter the property   Very Large Property, practically not possible didn't enter the property   Very Large Property, practically not possible didn't enter the property   Very Large Property, practically not possible didn't enter the property   Very Large Property, practically not possible didn't enter the property   Very Large Property, practically not possible didn't enter the property   Very Large Property	12.						property so
As per Title deed  As per Map  As per site surver  4270.85 Sq.m 4270.95 Sq.m  As per Map  As per Map  As per site surver  As per Map  As per Site surver  As per Map  As per Site surver  As per Map  As per Map  As per Map  As per Map  As per Site surver  As per Map  As per Map  As per Map  As per Site surver  As per Map  As per Site surver  As per Map  As per Map  As per Site surver  As per Map  As per Map  As per Site surver  As per Map  As per Site surver  As per Map  As per Map  As per Map  As per Site surver  As per Map  As per Site surver  As per Map  As per Map  As per Map	13.	Reason for no measurement	☐ Property was locked, ☐	Owner/ poss	rge Property, F	practically not	possible to
14. Land Area of the Property  4270.85 Sq.   As per Title deed  As per Map  A							e survey
As per Title deed  As per Map  As per site surve  As per Title deed  As per Map  As per site surve  Sample Meal  Torsee □ Under Construction, □ Couldn't be Surve	14	Land Area of the Property					
15. Covered Built-up Area  As per Interdect  15.276.48 Sq. m Sample Med  Under Construction,  Couldn't be Surv	14.		4270.85 Sq.m	Acne	er Map	As per si	te survey
15. Covered Built-up 71. Couldn't be Survive Construction, □ Couldn't be Survive Coul		Greered Ruilt-up Area	As per Title deed	1C 0 7.1	1. 0. So -0	Sample	Measurer
. I CA O mor I I Val dill. La cosses,	15.		- Vacant. ☑ Le	essee, Unc	der Construction	ı, □ Couldn't	be Surveyed
Property Was locked, 25	16.		Property Was locked,	A 100 CO.		cakase	issul
17. Any negative observation of the Maintainance is sue, Rakage 18		Any pogative observation of the	Maintai	nance 1	2200/	d	1

	- Supray	at other
	operty during survey	Access available in sharing of other
	Is Independent access available to	Clear independent access is available,  Access available in sharing of other adjoining property,  No clear access is available,  Access is closed due to dispute
1	Laproperty	adjoining property, □ No. □ Only with Temporary boundaries
	haranerty clearly demarcated with	V res, 🗆 mo, 🗆
19.	anont houndaries:	
10	Is the property merged or conduct	NO Laformation Details."
1 20.	with any other property	Please refer attached sheet named 'Property rate Information Details.'
1	Local Information References on	Please reich diese
21.	property rates	

# 1. Signature of the Person who was present from the owner side to identify the property:

Undertaking: I have shown the correct property and provided the correct information about the property to the surveyor of R.K Associates to the best of my knowledge for which Valuation has to be prepared. In case I have shown wrong property or misled the valuer company in any way then I'll be solely responsible for this unlawful act.

unia	IWIGI dec.	a. Losh	Kamar
а.	Name of the Person:	E-allied.	
b.	Name of the Person: Relation: Signature: Date:	Employ	
c.	Signature: ZWZ	100119 22	THE RESERVE
4	Date:	23	

In case not signed then mention the reason for it: 

No one was available, 

Property is locked, 

Owner/ representative refused to sign it,  $\square$  Any other reason:


# 2. Surveyor Signature who did site inspection:


Undertaking: I have inspected the property and cross verified the property details at site to the extent of a. Matching boundaries of the property, b. Sample measurement of its area, c. Physical condition, d. Property rates as per local information with what is mentioned in the property documents provided to me by the Bank/ interested organization. I have not come under influence of anyone during site inspection and have only recorded the true and factual details in the survey form which I come across during the site survey. I understand that giving any manipulative information in the survey form will lead to incorrect Valuation report which is an unlawful act and i'll be solely responsible for doing it.


a. Name of the Surveyor: Strugash of Dipesh
b. Signature: Disedmiths
c. Date:

c. Date:

23/02/22







Scanned with CamScanner

A) 12th Floor: - MTNL Flats. (6 Flats) Height = 9.220. I confirm that Survey Police

\*) 13th Floor: - MTNL Flats (6Flats)

Height = 9, 22 ft

\*) luth Floor: - 2 Flats of Ig

IQ = 5 bedroom + Kitchen + Store room

Hught = 7. 225 ft