File No.	RKA/DNCR//
Date of Receiving	
File Receiver Name	Abhishek. Shanbhag,



# CASE COLLECTION FORM (Version 5.0) Date of implementation: 9.02.2011. Last Revision: 30.01.2020 | Latest Revision: 31.10.2020

	tems	Assig	ned To	Assigned to Date	To be completed	Submitted On date	Grade	HOD Engg. Signature
File Rece	eived By	Alhish	et bhas	NA	by date NA			
Survey		Abhish	ek.sf		Tana sa			
Preparati	ion							
Α-	Very Good, E	B - Satisfac	ctory. C - A	Average D.	Poor, E - Extre	moly Doss		
Engg. unp to reason	rned to HOD prepared due	prope	rly done, sentative p	Derly done, I Derly done, I De	☐ Identification raphs not cle	is not clearly of arly taken, owner represe	done, □ Selfie entative :	☐ Market survey for Measurement is now / Owner or owner signature not taken,
case ri	le is returned		nor defect	ts in the su	rvey hence ar	proved for pr	reparatio	n with warning to
Engg. con Signature		□ Maj	or defects	in the survey	. Survey has to	be done agair	n on his (	own.
Engg. con Bignature 1. Prop Ref.	nment &	□ Maj	or defects	in the survey	. Survey has to	be done agair	n on his (	own.
ingg. con Signature  1. Prop Ref.  2. Type	posal/ Work O No. e of Service	□ Maj	or defects  VIS	in the survey  GENERAL  (2021 -	DETAILS  Construction of	be done again F 88 - 68 7	n on his on.	etting certificate
Engg. con Signature  1. Prop Ref. 2. Type	oosal/ Work O	□ Maj	VIS  □ Valuatio □ Other O	GENERAL  2021 -  On Report,  CE Certificate	DETAILS  Construction of St.   TEV Reports	be done againg the second of t	n on his on.  1. — 8 7  □ Cost v  □ BBJ Co  Corporate	etting certificate
1. Prop Ref. 2. Type 4. Bank	oosal/ Work O No. e of Service	□ Maj	or defects  VIS  □ Valuatio □ Other O □ Bank □ Compar	GENERAL  C2021 -  on Report,  CE Certificate  ny	DETAILS  Construction of St. TEV Reports  Private client	tost estimate, Dort, DIE J	on his on his on.  - 87  Cost v  BBI Co  Corporate  nt throug	etting certificate  LLP purp  th Bank
1. Prop Ref. 2. Type 3. Type 4. Bank Name 5. Case	oosal/ Work O No. e of Service of customer	□ Maj	VIS  Valuation Other Compar  Vand Unit n  Vandar	GENERAL  C2021-  on Report, CE Certificate  ny Cana Uta  in 1112/ ame	Construction of the Private client  Contact N	be done again  be done again  be done again  be the first of the first	Cost v BBJ Cost through	etting certificate  LFF purp  th Bank  C , Bandry, ku  mail Id Comptex
1. Prop Ref. 2. Type 3. Type 4. Bank Name 5. Case Fees	oosal/ Work O No. e of Service e of customer IRP d/ FI/ Organiza e & Address e Allotment Off paying party I	□ Maj	VIS  Valuation Other Compar  Vand Unit n  Vandar  (RP)	GENERAL  C2021-  on Report, CE Certificate  ny Cana Uta  in 1112/ ame	Construction of St.   Construction of St.   TEV Reports   Contact N   Contact	tost estimate, I ort,  Direct clie  Ont,  Direct clie  Ont,  Cort  Cort,    Cort,   Cort,   Cort,   Cort,   Cort,   Cort,   Cort,   Cort,	Cost v BBJ Cost v BBJ Cost v Corporate nt throug	etting certificate  out, Iff purp  th Bank  c, Bandry, ku  mail Id Comptex  ultula  400
1. Property Ref. 2. Type 3. Type 4. Bank Name 5. Case Fees 6. Case	oosal/ Work O No. e of Service e of customer IRP d/ FI/ Organiza e & Address e Allotment Off paying party I	rder or	VIS  Valuation Other Compar  Vand Unit n  Vandar  (RP)	GENERAL  C20 21 -  On Report, CE Certificate  On A TION  On A TION  TO TION	Construction of St.   Construction of St.   TEV Reports   Contact N   Contact	tost estimate, Dort, DIFE Direct clie	Cost v BBJ Co Corporate Int through  Fr. Yaghi  Ogmating according	etting certificate  LFF purp  th Bank  C , Bandry, ku  mail Id Comptex
1. Property Ref. 2. Type 3. Type 4. Bank Name 5. Case Fees 6. Case	oosal/ Work O No. e of Service e of customer IRP d/ FI/ Organiza e & Address e Allotment Off paying party I	Index or Ind	VIS  Valuation Other Compar  Vand Vandar  (RP)  Case	GENERAL  C2021-  on Report,  CE Certificate  ny  on a trace  in the survey  C2021-  on Report,  CE Certificate  ny  on a trace  for Fresh Address Addr	Construction of St.   Construction of St.   TEV Report   Contact No.   C	ting information be done again	Cost v BBJ Co Corporate Int through  Fr. Yaghi  Ogmating according	etting certificate  out Iff property  the Bank  C. Bandry, ku  mail Id Comptex  where 400  ount/ customer

Page 1 of 15

NAME OF THE PERSON		CASE D	And Manager and Andrews
1.	Type of Property	office units + W	C's in Commercial Buil
2.	Purpose of Valuation/ Assignment  ISBT Lase,  IRP purpose.	☐ Value assessment of the asset for ☐ Periodic Re-Valuation for Bank, ☐ ☐ For DRT Recovery purposes ☐ Go	creating new collateral mortgage Distress sale for NPA A/c., spital Gains Wealth Tax purpose
3.	Owner/ Applicant Details		act Number Email Id  wit: - cirp. Yag huleda 1  21587702 gmail can
4.	Account Name	Reghuleela Builders Put.	ltd.
5.	Property Address	One BKC building, BK	
6.	Who will coordinate on site for the site survey	Name	Contact Number
7		Rehul Agormal	7021587702
7.	Preferred time of survey	Date 22/03/2 24/03/2	P.Time P. Time
8.	Documents Received (Any one ownership document and approved site plan/ map is must)	4. Any Other document: ☐ CLU, ☐ T	nt Deed, ☐ Transfer Deed, Letter, ☐ Possession Letter IP, ☐ Site Plan Iment receipt, ☐ Water Bill & payment Iment receipt
9.	Documents received from	Company and the second	A September 1
10.	Special Instructions if any:		
11.	on Valuer firm to distort any f	ntioned above for the preparation of Valuatio acts and would not try to influence any mem any individual or organization by any means ill	ber or official of the firm in the ill spirit or

	File No. RKA/DNCR//		
	FILE RECEIVER CASE COLLECTION PROC	ESS COM	PLIANCE CHECKLIST
S.NO.	(To be filled by Su	NO COL	<b>在数据的图片,这种图片的图片</b>
		STATUS	THE THE PART OF TH
1.	Is Case collection Form properly filled by Receiver?	21-10 Th	REMARKS IN CASE OF ANY (X
2.	Is purpose of the assignment understood clearly by	D	
	T	V	Mark Live et
3.	Has receiver checked if this is a new case or existing case of the Bank?	9	
4.	Has receiver fixed the fees with the manager/ client and sent quotation properly or have taken approval of the work over email?	A	
5.	Has receiver taken proper Work Order/ Email/ CESA form formality?		
6.	In case of private case or for fresh case 50% advance is received?		
7.	Is document checklist email sent to the customer?		
8.	Has the received documents is having 'documents provided by stamp'?		

#### IMPORTANT INSTRUCTIONS TO SURVEYOR

г		<b>以</b> 自然的运动的运动或者的现在分词
	1.	Please fill the above compliance checklist before moving for the survey.
L	2.	Please do not do the survey if you do not have proper documents
	3.	For Vacant Plot/ Land - Cizra Map/ Master/ Zonal/ Site Plan is must to identify the Plot. For Agriculture or converted land from agriculture.
١		Agriculture or converted land from agriculture – Mutation documents, CLU is must.
Γ	4.	Firstly please first study the documents of the mutation documents, CLU is must.
r	5.	Firstly please first study the documents of the property which needs to get surveyed.  Mark the Owner/ Area/ Roundaries mention for the property which needs to get surveyed.
ı	•	Mark the Owner/ Area/ Boundaries mentioned the ownership documents with bold florescent
ı		
		and the desired with the owner simple documents then please contact the owner immediately the
H	6.	mion are reason for the difference.
l	0.	Confirm ongoing property rates in the subject location through public domain, property sites and
H	7	1 SOLITOR GODIES TO SHOW YOU THE AVAILABLE DIVIDENTED IN THAT STORY ALTERNATION AND ALTERNATIO
	7.	identify the Property clearly by matching the boundaries and area mentioned in the property
H	-	papers.
L	8.	Do sample physical or google measurements of the property.
	9.	PHOTOGRAPH INSTRUCTIONS:
		a. Take owner/ representative photograph along with the property.
		b. Take your selfie along with the property and the owner/ representative
		c. Take full scale photo of the property with gate.
		d. Take photo of the property along with abutting road, towards left, right and center.
		e. Take multiple photos of inside-out of the property.
		f. Take nearby photographs of the Property.
		g. Take a short video to cover property and neighborhood.
	10.	Take Google Map location.
	11.	Check main road name & width and approach road width and distance of property from main road.
	12.	Check Jurisdiction Municipal Limits & Ward Name.
	13.	Fill each column of survey form diligently in detail and tick the appropriate option clearly.
	14.	Check any defects or negativity in the property and comment in detail on survey form.
	15.	Do extensive market rate enquiries and confirm for any recent past transactions.
	16.	In case customer appears to be providing misleading information to
	10.	In case customer appears to be providing misleading information to you or trying to influence you by money or cash then immediately report to the Management & Bank.
_		money or easit their infinediately report to the Management & Bank.

RADE	
A	In case all the points below are done properly, timely with full care and diligence:  1. Survey started with proper work order and knowing the source of payment.  2. Survey done with proper documents.  3. Done complete homework and studied the documents properly with highlighting the main points before moving for the survey.  4. Chosen correct survey form as per the property type.  5. All fields of Survey form are properly filled.  6. All site special observations and negative and positive factors are clearly mentioned.  7. Self & client signatures taken on survey form.  8. Property rates information properly taken, mentioned and verified.  9. Site rough sketch plan made.  10. Proper photographs taken.  11. Selfie with property taken.
В	12. Selfie and owner photograph with property teles-
	In case of 3 minor mistakes in any of the above points except Point 1, 2, 3, 4, 6, 8, 10, 11, 12 but all the points are covered.
C	In case of more than 3 minor mistakes and any 1 major mistake in any of the above points and if any point are completely missing except Point 1, 2, 3, 4, 6, 8, 10, 11, 12.
D	In case of 1 major mistake or missing of any 1 point out of 1, 2, 3, 4, 6, 8, 10, 11, 12.  In case of more than 1 major mistake a project of 1, 2, 3, 4, 6, 8, 10, 11, 12.
E	In case of more than 1 major mistakes or missing of more than 1 point out of 1, 2, 3, 4, 6, 8, 10, 11, 12.

# Note (Survey Grading Matrix):

- For special assignments like LIE, Stock Valuation, etc. where till date survey format is not specified or released, in such cases point wise site observation report has to be submitted by the Surveyor duly signing it properly. Without signed Site Observation report, Point 4 will be considered as not done and will fall under Category E.
- 2. Similar Grading Matrix is issued for Case Collection & Report Preparation as well.

### Note (Overall Grading Matrix):

 In case client reports any careless mistake in the report for which revision has to be done in the report then in that case Grading Matrix may be revised and Grade E will be awarded.

	SURVEY PROCESS COMPLIANCE CHECKLIST	
S.NO.	10 De supmitted by Surveyor with and to	
1.	THE CHECKLIST POINTS	STATUS
2.	Did you take proper property documents to carry out the survey?	
3.	documents with bold florescent before moving for the current?	A
	form?	W.
4.	Did you identified the Property clearly by matching the boundaries and area mentioned in the property papers?	J
5.	Did you check if property is merged with any other property or it is an independent property?	D
6.	Did you do sample physical or google measurements of the property in case of property more than 2500 sq.mtr?	, 🗆
7.	Did you check for any building violations in the property?	V V
8.	Did you check municipal limits/ jurisdiction/ ward?	
9.	Did you take Google Map location and shared it to Maps whatsapp group?	
10.	Did you check Main road name & width and its distance from the subject property?	
11.	bid you check approach Lane width on which property is located?	
12.	Have you taken property full scale photograph with gate?	
13.	Have you taken owner/ representative photograph with the property?	V
14.	have you taken your selfie with the property along with owner/ representative?	
15.	right of the property?	
16.	Have you taken multiple photographs of the property from inside-out?	
17.	form?	9
18.	Did you check any defects or negativity in the property in terms of location, legality, disputes, marketability, salability, etc. and commented on survey form in detail?	W
19.	properly?	W
20.	Did you draw site key plan (location map)?	
21.	Did you draw rough site sketch plan?	
22.	Have you taken self-attested documents from owner/ representative and stamped "documents provided by ctamp"?	
23.	Did you check any defects or negativity in the property in terms of location, legality, disputes, marketability, salability, etc. and commented on survey form in detail?	Ø
24.	enquired property rates locally very rigorously?	A
25.	Did you take signatures of the owner/ representative on undertaking and survey summary sheet?	D
26.	Did you signed the undertaking?	,

For File No.	VIS (2021-22)-PL788-687-875
Surveyor Name	Abhishek. S 4 Dipenh. B
Signature	DiBulyn.
Date	22/03/22 + 24/03/22

GENERAL SURVEY FORM
(FOR PROPERTIES OTHER THAN FLATS)
(Version 5.0)
Date of implementation: 9.02.2011 | Last Revision: 04.01.2018 | Latest Revision: 31.10.2020

	. 0	
File No. RKA/DNCR//	22/03/22 4 Date: 24/03/22	Time:

	語語的影響的原理的影響的遊	GENERAL DETAILS
1.	Name of the Surveyor	Abhishek.s + Dipuh.B
2.	Property shown by	☐ Owner, ☐ Representative, ☐ No one was available, ☐ Property is locked, survey could not be done from inside
1135		Name Contact No.
		Rahul Agarwal 7021587702
3.	Survey Type	Full survey (inside-out with measurements & photographs)  □ Half Survey (Measurements from outside & photographs)
	Committee Commit	☐ Only photographs taken (No measurements)
4.	Reason for Half survey or only photographs taken $N$	☐ Property was locked, ☐ Possessee didn't allow to inspect the property, ☐ NPA property so couldn't be surveyed completely
5.	How Property is Identified	☐ From schedule of the properties mentioned in the deed, ☐ From name plate displayed on the property, ☐ Identified by the owner/owner representative, ☐ Enquired from nearby people, ☐ Identification of the property could not be done, ☐ Survey was not done
6. M	Type of Property Ultiple Office units	☐ Flat in Multistoried Apartment, ☐ Residential House, ☐ Low Rise Apartment, ☐ Residential Builder Floor, ☐ Commercial Land &
	in one BKC Building.	Building, ☐ Commercial Office, ☐ Commercial Shop, ☐ Commercial Floor, ☐ Shopping Mall, ☐ Hotel, ☐ Industrial, ☐ Institutional, ☐ School Building, ☐ Vacant Residential Plot, ☐ Vacant Industrial Plot, ☐ Agricultural Land
7.	Property Measurement	Self-measured,  Sample measurement only,  No measurement
8.	Reason for no measurement	☐ It's a flat in multi storey building so measurement not required ☐ Property was locked, ☐ Owner/ possessee didn't allow it, ☐ NPA property so didn't enter the property, ☐ Very Large Property, practically not possible to measure the entire area ☐ Any other Reason:
9.	Purpose of Valuation  IBBI case .  IRP purpose .	<ul> <li>□ Value assessment of the asset for creating new collateral mortgage</li> <li>□ Periodic Re-Valuation for Bank, □ Distress sale for NPA A/c.,</li> <li>□ For DRT Recovery purpose, □ Capital Gains Wealth Tax purpose</li> <li>□ Partition purpose, □ General Value Assessment</li> </ul>
10.	Type of Loan	☐ Housing Loan, ☐ Housing Take Over Loan, ☐ Home Improvement Loan, ☐ Loan against Property, ☐ Construction Loan, ☐ Educational Loan, ☐ Car Loan, ☐ Project Loan, ☐ Term Loan, ☐ CC Limit enhancement, ☐ Cash Credit Limit, ☐ Industrial Loan, ☐ NA
11.	Loan Amount	

	<b>的现在分词形式的基础的是对对对对对对对对对对对对对对对对对对对对对对对对对对对对对对对对对对对</b>	OWNERSHIP DETAILS
1.	Legal Owner Name/s	Raghuleela Builders Put. Ltd.
2.	Property Purchaser Name	in distance barrans
3.	Property Address under Valuation	one BKC building, BKC, Bandra, East,
4.	Present Residence Address of the Owner/ Purchaser	
5.	Property constitution	✓ Free Hold, □ Lease Hold

	<u>LOCATION DETAILS</u>								
1.	Adjoining Properties	East	To F		West		North		South
	(Match it with papers with the help	Sharad P	awar	lati	kard/	M	A Gricket	Lati	ka rd/Ave
	of compass or Sun direction and	Indrov 1	bucket	Ave	nue 300	0	Tround	320	Rd 9
	also confirm it with nearby people)	Academ.	4.					India	an oil pet
2.	Property Facing, A E						Facing, 🗆 So	outh Fa	acing, '
		□ North-Ea	ast Facin	g, Z	South-V	Vest Faci	ng,   South	East F	Facing,
	WIS	□ North-W							
3.	Landmark Entry				Total Design				
4.	Ward Name/ No.	BKC			**	The same of the sa			
5.	Zone Name		1						
6.	Main Road Name & Width	Na	me	2 TH		Vidth	Distanc	e from	property
0.	Wall Road Walle & Width								
7.	Approach Road Name & Width	Latika To	men	me	3 rd	גמוקה	4)ft.		Market I
		F -	Anin oibe		Alithin G	ood Lirba	n developed	Area	□ Within
8.	Location consideration of the								
	Society	developing	area, □	High	ly posh lo	ocality, L	Very Good,	□ G0	oa,
		□ Ordinary,	☐ In ir	nterio	ors, 🗆 Re	emote are	a,   Backwa	ard, $\square$	Average,
		□ Poor							
0	Special Location consideration		cina 🗆	Poo	Facing	Road	Facing,	Entran	ce North-
9.								Linuar	CE NOTHI-
	of the property	East Facing					ding.		
10.	Characteristics of the locality	Urban de	eveloped,	. 🗆 (	Jrban de	veloping,	☐ Semi Urba	an, 🗆	Rural,
	A CONTRACTOR OF THE PARTY OF TH	□ Backward	I, 🗆 Indu	stria	I, 🗆 Insti	tutional			
44	Cotonon of Conjuty Insplity	D High End	I □ Norr	mal	□ Afford	able Grou	p Housing, [	] E\M	
11.	Category of Society/ locality	□ MIG, □ L		riai,	LI Alloid	able Oroc	ip riousing, c		5, 🗆 1110,
12.	Utilities/ Facilities in the locality			La	ndscapir	ıg, □ Swi	mming Pool,	√ Gy	m,
70							lay zone, J		
	products.	Backup							
13.	Proximity to civic amenities	School	Hospita	al	Market	Metro	Railway St	ation	Airport
		50m	2.3	Km	103 km		3.2 8	in	11 Km
14.	Any new development in surrounding area	Tucha							

15.		☐ Nagar Nigam, ☐ N	agar Panchayat, 🗆 Gra	m Panchayat, □ Naga
	BMC	Palika Parishad, □ Are	a not within any municipa	al limits
16.	. Jurisdiction Development □ DDA, □ GDA, □ NOIDA, □ GN			DA, □ HUDA, □KMDA
	Authority Name	☐ MDDA, ☐ Any other	Development Authority:	
	BMC	☐ Area not within any o	development authority lim	nits
17.	Municipal Corporation Name	□ NDMC, □ SDMC, □	□ EDMC, □ Ghaziabad	Municipal Corporation
	BMC		Corporation,   Faridabac	
	DIVIC		orporation,   Dehradun	
			ny municipal limits,	
		Corporation/ Municipality		
To Make Park	Manual Programme			nie – sude Townstonius II. St. Ook in Participal
1.	Land Area	As per Title deed	As per Map	As per site survey
	Land Area	As per fille deed	As per map	7.0 per ente entre y
2.	Any conversion to the lead was			
2.	Any conversion to the land use	-		
3.	Land Type	Solid, Rocky,	] Marsh Land, ☐ Recla	aimed Land,   Water
		logged,   Land locked		
4.	Shape of the Land	☐ Square, ☐ Rectange	ular, 🗆 Trapezium, 🗅 Tr	iangular,   Trapezoid,
		☐ Irregular, ☑ NA		
5.	Level of Land	☐ On road level, ☐ Bel	low road level, Above	road level, □ NA
6.	Frontage to depth ratio	☐ Normal frontage, ☐	Less frontage, 🗸 Large f	rontage,   NA
7.	Are Boundaries matched	✓ Yes, □ No, □ N	No relevant papers av	ailable to match the
MEN'		boundaries,   Boundar	ies not mentioned in ava	ilable documents
8.	Is Independent access available	Clear independent	access is available,	Access available in
	to the property	sharing of other adjoini	ng property,   No clea	r access is available,
		☐ Access is closed due	to dispute	
9.	Is property clearly demarcated with permanent boundaries?	✓ Yes, ☐ No, ☐ Only v	vith Temporary boundarie	es
10.	Is the property merged or	No.		
	colluded with any other property		/ /	,
11.	Property possessed by at the time of survey	Owner, Vacant, De Surveyed, Prope	Lessee, Under Con	struction, Couldn't
		sealed		
12.	Current activity carried out in the property	☐ Residential purpose ☐ Office, ☐ Industrial, ☐	e, ☑ Commercial pu ☑ Vacant, ☐ Locked, ☐ /	rpose,  Godown,  Any other use:
		CONSTRUCTION/ UT	LITY DETAILS	
1.	Construction Status		use,  Under construction	on, □ No construction

F 2.	Covered Built-up Area	☐ Covered Area, ☐ Floor Area, ☐ Super Area, ☐ Carpet Area
1 2.		As per Title deed
	(Tick one on the basis of which valuation is to be calculated)	As per attached downerth -
3.	Total Number of Floors in the Building	As per attached downers.
4.	Floor on which property is situated	4, 5, 6, 7, 8, 9, 10, 11, 12, 13, 14, 15, 16, 20, B3, Strage, Ground.
5.	Type of Unit/ Number of Rooms/ Cabins/ Cubicles	
6.	Building Type	☐ RCC Framed Structure, ☐ Load bearing Pillar Beam column, ☐ Ordinary brick wall structure, ☐ Iron trusses & Pillars, ☐ Scrap abandoned structure
7.	Different on different flows	a. Make:  RBC,  RCC,  GI Shed,  Tin Shed,  Stone Patla  b. Height:  Attached  C. Finish:  Simple plaster,  POP Punning,  POP False
	William d / 100/	Coiling A Coved roof No plaster
8.	different on different floors.	☐ Vitrified tiles, ☐ Ceramic Tiles, ☐ Simple marble, ☐ Marble chips, ☐ Mosaic, ☐ Granite, ☐ Italian Marble, ☐ Kota stone, ☐ Wooden, ☐ PCC, ☐ Imported Marble, ☐ Pavers, ☐ Chequered Tiles, ☐ Brick Tiles, ☐ No Flooring, ☐ Under construction, ☐ Any other type:
9.	Appearance/ Condition of the Building	Internal - ☐ Excellent, ☐ Very Good, ☐ Good, ☐ Ordinary, ☐ Average, ☐ Poor ☐ Under construction, ☐ No Survey  External - ☐ Excellent, ☐ Very Good, ☐ Good, ☐ Ordinary,
		☐ Average. ☐ Poor, ☐ Under construction
10.	Maintenance of the Building	✓ Very Good, ☐ Average, ☐ Poor, ☐ Under construction
11.	Interior decoration	<ul> <li>□ Excellent,</li> <li>□ Very Good,</li> <li>□ Good,</li> <li>□ Simple,</li> <li>□ Ordinary,</li> <li>□ Average,</li> <li>□ Below average,</li> <li>□ Under construction,</li> <li>□ No Survey</li> </ul>
12.	Interior Finishing	<ul> <li>✓ Simple plastered walls, □ Brick walls without plaster,</li> <li>□ Designer textured walls, □ POP punning, □ Coved roof,</li> <li>□ Under construction, □ No Survey</li> </ul>
13.	Exterior Finishing	Simple plastered walls, □ Brick walls without plaster, □ Architecturally designed or elevated, □ Brick tile Cladding, □ Structural glazing, □ Aluminum composite panel cladding, □ Glass façade, □ Domb, □ Porch, □ Under construction
14.	Kitchen —	☐ Simple with no cupboard, ☐ Ordinary with cupboard, ☐ Normal Modular with chimney, ☐ High end Modular with chimney, ☐ Under construction, ☐ No Survey
15.	The state of the state of the	
16.	water supply fittings	☑ External,☑ Internal □ Excellent, □ Very Good, ☑ Good, □ Simple, □ Average, □ Below average,☑ Under construction, □ No Survey
17.	Water arrangements	☐ Jet pump, ☐ Submersible, ☑ Jal board supply
18.		<ul> <li>□ Excellent,</li> <li>□ Very Good,</li> <li>□ Good,</li> <li>□ Simple,</li> <li>□ Ordinary,</li> <li>□ Average,</li> <li>□ Below Average,</li> <li>□ No wooden work,</li> <li>□ No survey</li> </ul>
19.	Age of Building/ Recent	J. J. House House
	Improvements done	
20.	STATE OF CONTROL OF STATE OF S	Very Good, ☐ Average, ☐ Poor

	Ta defeate ! H. I. H. H.					
21.	Any defects in the building	☐ Maintenance issues, ☐ Finishing issues, ☐ Seepage issues,				
	No.	☐ Water supply issues, ☐ Elec	ectricity issues,   Structural issues,			
		☐ Visible cracks in the building				
22.	Any violation done in the property	☐ Construction done without	Map ☐ Constru	uction not as p		
	No					
	100.	approved Map, □ Extra covered without sanctioned Map, □ adjacent property, □ Encroached adjacent area illegally				
23.	Boundary Wall (Only for individual	The second secon	And the second of the second o			
	property)	☐ Yes, ☐ No, ☐ Common bour Running Mtr. Height	Width	Finish		
	2110 10	Kulling Witt. Height	- Width	-		
24.	Lift elevators Total 20:- 18 operational (8+8+2+2) Bl Power backup	☑ Passenger/ ☐ Commercial	10/13/			
	Total 20:- 10 operational	Make:	Capacity:	H. Line		
25.	Bayes backup	C wing.				
25.	Fower backup		Capacity			
		Make:	Capacity:			
26.	Garden/ Landscaping	Yes, No, Beautiful, O	rdinary			
27.	Parking facilities	Available within the property	On Ground,	☐ In Basemen		
		1	☑ On stilt			
		☐ Not available within the ☐ On road, ☐ Acute parking				
3	A CALLEY		The state of the s			
28.	Special Comments/ Observations, if any	Abst units a	ru under	construction		
		Box - There year out of the				
		Market Market No.	The state of the s	1 1 1		
		THE PARTY OF THE PARTY I	CONTRACTOR OF THE PARTY OF THE	- Andrews and the Company of the Company of		
	CONTROL BY THE CONTROL BUTCH CONTROL BY THE CONTROL	LITY/ SELABILITY/ UTLITY DE	TALS	出版的		
. 1.	Any issues in marketability of the	☐ Yes, V No.	The state of			
	property?	Reason in case of No:   Lo		inding, $\square$ Lega		
	13.415 1 45 - 14.51	aspects,  Demand,  Shape,  Shape,	☐ Any Other:			
				ny .		
2.	How is Demand & Supply condition	Demand ☐ Very Good, ☐ Goo				
	in the Market of such properties?	Supply	d, 🗆 Average, 🗆 l	ow,  Poor		
3.	Is property easily sellable &	✓ Yes, □ No 1				
	marketable?	Comments:				
		PACTURE TO A STATE OF THE PACTURE OF				
			Marit and the			
4.	How is the current utility of the			☐ Excellent, ☐ Very Good, ☐ Good, ☐ Average, ☐ Low, ☐ Poor		
1.		under construction (units)/. Vactant or low				
	property?	SHOWL CONSTIGUISTS	T STATE /	lactant or le		
5.	At what True rate Owner bought	Year of purchase	- 1.	lactant or le		
5.		Year of purchase Purchase Price	-	lactant or le		
	At what True rate Owner bought this Property?	Year of purchase	-	lactant or lo		
<ul><li>5.</li><li>6.</li></ul>	At what True rate Owner bought this Property?  Present expected Sale Value of the	Year of purchase	-			
	At what True rate Owner bought this Property?	Year of purchase	-	lactant or lo		

```
SAMPLE MEASUREMENTS:-
1) Unit No. 1415 :- Height = 10.885 Ft (8.03×13.70)+(32-9×40)
2) unit no 1613-14: 26-29x 33:79,
                                    height - 11.33
3) voit NO. 1615 :- No keys.
4) Unit 1309-10:- 26.14 ×33.73, height -11.33
5) unit 1211-12 i- 26.07 ×33.68, height - 11.33
d) unit 1213:- 41.03 x 33.73
                                    height - 11.33
7) Unit No. 1015: - unit not found. ( keys also not present)
8) Unit no: 908-09:-26.28 x
                                     height-11.35
                   (15.92+ 16.95)
9) voit No. 812; - (24.53+ 15.14) x 34.05
                                                  Height = 11.33
10) Unit No: 605-606; - Reight = 10.93
 11) Unit No 607 :- Height = 9.14
 12) Unit No. 1114 :- (40.955 x 31.22) Height = 11.23 Ft.
 (3) Unit No. 405: (16.31 x 13.415) Height = 12.24 ft
 14) voit No: 404: (67.16) X (60.31+22.11), Height = 12.28
                        (26.32 x 33.60)
 16) Unit No. 2001: - + (45.03 x 29.89) + (31.04 x 57.65) +

(29.32 x 14.23) | Height = 11.16 (8.11 x 48.61) +

(34.91 x 4.86) + (34.55 x 9.37)
  17) Unit 407 & 408: - (Merged) Photos not allowed.
                Height = 10.2 ft.
                   Mea = (57.01 + 52.56) x (61.6) x [36.59+10.98]
                                                    + [(57.22+
                                                         46.66
                            2930.3 + 3182.2
                             6112.5 Sq. Ft.
```

## BLANK PAGE FOR PROVIDING ANY ADDITIONAL DETAILS/ INFORMATION

NOTE ) ;

- 1) Few units were un-identified.
  - 2) Keys of some units were not present.
- 3) Some units are on rent, so survey was not possible. It will done only on saturday's or Sunday's.
- 4) · Some unit were under construction ie, no flooring, only walls constructed, no electrical fitings etc.
- 5) Mr. Rahul Agarwal (RP team)
  Said, he will arrange the keys
  of units & also identify the
  remaininging units for survey next
  time ie, during PAM survey.
- 6) The Ground Floor, B3 unit (as per excel sheet) storage vnit (as per excel sheet) are yet to be surveyed. It will done next time during pfm survey.


7) Ground & unit No. 407 & 408 Sowey done

18) Lobby (B4C) :- Height = 22.9 Pt.

Area = (69.63) x (64.92 + 79.14)

= 10,030.8 Ft?

Page 11 of 15



Page 12 of 15

Vo!	Particulars	Subject	Transaction already	Comparable 2	Comparable 3
理		Property	Comparable 1	Comparable 2	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	Name (source of information)	NA	Vishel	Samir	Ati'
	Contact No.	NA	98 20056180	9167839555	
	Type of source of information (Seller/ Property dealer/ nearby people)	NA	Property dealer	Profesty	Property dealer
	Rates/ Price informed (in Rs. with unit)	NA	50k to 55k persq.ft builtup	45 K to 55K Per Sq.ft builty	on carpet
	Rates Type (Sale/ Buy)	NA	Bry.	Buy.	Buy,
i.	Shape of the Property (Square, Rectangular, Irregular)		-	-	
7.	Area/ Size of the Property		4000 - \$5000 sq. ft	4000-5000 59-Fr	4000-5000 Sq. Ft
В.	Legal Status (clear, negative, weak)/ No. of owners		clear	Clear	Clear
9.	Location/ surrounding/ neighborhood comparison with the subject property (Similar, Lower, Better, Highly Better than the	Base Case	Same building. (one BKC)	same building.	bwiding.
10.	Distance from the subject Property	0	0	0	0
11.	2 side open, North-East facing, Park facing, Legal/ Financial	THE FUE	- THE STATE OF THE		
12.	encumbrance, etc.) Approach road width		Saml	Some	same
13.	Level of Land (Below/ On/ Above road level)		same	Same	Same
14.	Frontage to depth ratio (Normal, Less, Large)		some	Same	Same
15.	- Illes		Communcial	communuial.	Commercial
16.	Any other details/ Discussion held	NA	of office, facing of office, floor location, etc. the	off office is unfurnished ie, no flooring, electrical connect etc, then rate	or semi-fun
17	Present expected Sale Value of the overall property?		from 50 k to  55 k/sg.ft	per sq.ft. builty	

# **UNDERTAKING BY THE CUSTOMER**

I confirm that I have made the inspection of the subject property to the surveyor of R.K Associates, which is correct property in question for which the documents have been provided/ submitted by me. I further confirm that I am aware of all the information related to the subject property and I have provided all its information to the surveyor true to the best of my knowledge. I understand that any false or manipulative information provided by me will be considered as cheating with the professional organization since it will lead to incorrect valuation report and I'd be solely responsible for this unlawful act and will bear the charges for the changes/modifications which have to undergo due to the false information. I also undertake that I have not given any cash or in kind to any member of R.K Associates to influence the Value of the Property or favor any individual or organization and the same is not accepted or asked by the member of R.K Associates. Any such act will lead to cancellation of the material prepared by R.K Associates with forfeiting of the fees and i'll be completely responsible for its repercussions and legal actions taken for it.

IMPORTANT: We have not authorized any of our person/ Surveyor to take Cash or kind from the customers in any situation. In case Surveyor or any member of R.K Associates asks for any money or kind from you then kindly please inform on number +91-9958632707, 0120-4110117. Our Valuation process is very stringent and have multiple check points to ensure correct & error free reports to keep the lending agency risk free. In case Surveyor claims that he would be able to arbitrary effect the Valuation figures unfairly or as per your requirement & need, then he is making a false claim to you and we request you to complaint such act immediately on the number provided above.

Name	Restrict Agreement label Aglan
Relationship with owner	Employee Rf Team
Signature	8
Mobile No.	7021587702
Date	22/03/22 4 24/03/22

# UNDERTAKING BY THE SURVEYOR

I confirm that I have carried out the Survey of the property properly as per the fair professional best practices and Valuation & Survey policy guidelines issued by R.K Associates. I have not taken any cash or kind from the customer nor have I come into any kind of influence of the customer / bank for arbitrary providing the Property Valuation as per one's need. I further state that I have not given any assurances to the customer nor given any wrong or false information or statement. In case at any point of time it is found that I have done any kind of fraudulent activity in this case and misled the company then I understand its legal consequences and appropriate penal action which company can take against me. Also in regard to it any monetary or reputation loss will be recovered from me by the company.

For File No.	VIS (2021-22) -PL788-687 - 875
Surveyor Name	Abhishek. S & Dipush B
Signature	gto.
Date	22/03/22 4 24/03/22

Page 14 of 15

# UNDERTAKING BY THE PREPARER

I confirm that this Valuation Report is prepared as per the fair professional best practices and Valuation & Survey Policy Guidelines issued by the organization. I also confirm that without any personal interest, partiality or prejudice, I have worked on this Valuation assignment. Rates adopted for the asset is based on various facts, information collected from the site came to my knowledge during the course of the assignment and I have taken all sincere efforts to review, cross check & confirm this data/ information from all different angles using my prudent approach without any biasedness or pressure. I have prepared the report based on true facts & information as per best of my knowledge & case facts. I understand that any false information provided by me will lead to the incorrect valuation report and I'd be solely responsible for it and will bear the losses which will be put on the Company in form of monetary or reputation loss by its client or statutory bodies.

I also undertake that I did not come into any influence by the customer, Bank representative (officer or agent), colleagues, coworkers or any other person to arbitrary change the Valuation figures or facts unethically or illegitimately which may put the public money at risk which is in the form of Bank deposits.

In case at any point of time in future, if I am found guilty of illegitimately distorting the facts in the Valuation or any other professional services which company offers in the market on being influenced by the customer or Bank representative (officer or agent) or for whatsoever reason then I'd solely responsible of any such act and I understand that the Company can take appropriate legal action against me which may include suspension from the current roles & responsibilities or termination from the employment with immediate effect.

I also undertake that I have not taken any cash, favor or in kind from the customer for favoring any individual or organization by unfair means.

I also undertake that I'll not prepare any report on incomplete Survey form which is not properly filled as per the Company guidelines and in case I am preparing it which is creating an incorrect report then I'd be responsible for its consequences.

For File No.	A RESIDENCE PROSE
Preparer Name	
Signature	
Date	The second secon



Enclosure: 6

# SURVEY SUMMARY SHEET (TO BE ENCLOSED WITH VALUATION REPORT)

(Version 1.0) | Date of implementation: 10.04.2017

Every Valuation report at R.K Associates is prepared based on the thorough survey of the property carried out by our Engineering Surveyor. This Survey Summary Sheet is for the information of Banker/ concerned interested organization. Detailed Survey Form can also be made available to the interested organization in case it is required to cross check what information our surveyor has given in site inspection report based on which Valuation report is prepared.

1.	File No.	VIS (2021-22) -PL	T00 - 601 0		
2.	Name of the Surveyor	ANTICAN	AAAL 1 IS		
3.	Borrower Name	Rashuleela Buildon	Put-Ltd		
4.	Name of the Owner	Rashulele Buildurs	Put . Ita	In Complex, Muni	
5.	Property Address which has to be valued	Rashuleda Builders Rashuleda Builders Rashuleda Builders BAC Wing, Onl U00051	No one was available, [	☐ Property is locked, survey	
6.	Property shown & identified by at spot	Name Rahad Aggrad (R)	team) 70219	Contact No.	
7.	How Property is Identified by the Surveyor	displayed on the property, of Enquired from nearby people,	Row Approve (R) + 158 + 70  From schedule of the properties mentioned in the deed, From name plate displayed on the property, Identified by the owner/ owner representative, Enquired from nearby people, Identification of the property could not be done, Survey was not done  Yes, No, No relevant papers available to match the boundaries,		
8.	Are Boundaries matched	- to the montioned ii	available de-		
9.	Survey Type	Boundaries not mentoned with measurements & photographs)  □ Full survey (inside-out with measurements & photographs)  □ Half Survey (Measurements from outside & photographs)  □ Only photographs taken (No measurements)  □ Property was locked, □ Possessee didn't allow to inspect the property, □ NPA property so couldn't be surveyed completely  □ Flat in Multistoried Apartment, □ Residential House, □ Low Rise Apartment, □ Residential Builder Floor, □ Commercial Land & Building, □ Commercial Office, □ Commercial Shop, □ Commercial Floor, □ Shopping Mall, □ Hotel, □ Industrial, □ Institutional, □ School Building, □ Vacant Residential Plot, □ Vacant Industrial			
10.	Reason for Half survey or only photographs taken				
11.	Type of Property  Multiple units in  Building				
		Plot, ☐ Agricultural Land  Self-measured, ☐ Sample m	neasurement,   No meas	urement	
12.	Property Measurement				
13.	Reason for no measurement	☐ It's a flat in multi storey building so measurement not required ☐ It's a flat in multi storey building so measurement not required ☐ Property was locked, ☐ Owner/ possessee didn't allow it, ☐ NPA property so didn't enter the property, ☐ Very Large Property, practically not possible to measure the area within limited time ☐ Any other Reason:			
		As per Title deed	As per Map	As per site survey	
14.	Land Area of the Property			As per site survey	
15.	Covered Built-up Area	As per Title deed  AS POT downsen	As per Map ts attached		
16.	Property possessed by at the time of survey	AS PUZ downer, Owner, Vacant, Vacant, Vacant, Vacant, Vacant, Vacant, Vacant, Vacant, Vacant	Under Construction	n, □ Couldn't be Surveyeu,	
17	Any negative observation of the			1	

1.	Clear Inc	dependent access: - As per data recorded during survey.
1.	property during survey	0 30000
18.	Is Independent access available to the property (for building).	Clear independent access is available, ☐ Access available in sharing of other adjoining property, ☐ No clear access is available, ☐ Access is closed due to dispute
19.	Is property clearly demarcated with permanent boundaries?	✓ Yes, ☐ No, ☐ Only with Temporary boundaries
20.	Is the property merged or colluded with any other property	Multiple office units or different flows.
21.	Local Information References on property rates	Please refer attached sheet named 'Property rate Information Details.'

#### **Endorsement:**

# 1. Signature of the Person who was present from the owner side to identify the property:

Undertaking: I have shown the correct property and provided the correct information about the property to the surveyor of R.K Associates to the best of my knowledge for which Valuation has to be prepared. In case I have shown wrong property or misled the valuer company in any way then I'll be solely responsible for this unlawful act.


		100
a.	Name of the Person: Rahu Relation: Employee	of Agarwal
b.	Relation: Employee	RP Team
	Cianaturo	
d.	Date: 22/03/22 &	24/03/22

In case not signed then mention the reason for it:  $\square$  No one was available,  $\square$  Property is locked,  $\square$  Owner/representative refused to sign it,  $\square$  Any other reason:

### 2. Surveyor Signature who did site inspection:

Undertaking: I have inspected the property and cross verified the property details at site to the extent of a. Matching boundaries of the property, b. Sample measurement of its area, c. Physical condition, d. Property rates as per local information with what is mentioned in the property documents provided to me by the Bank/interested organization. I have not come under influence of anyone during site inspection and have only recorded the true and factual details in the survey form which I come across during the site survey. I understand that giving any manipulative information in the survey form will lead to incorrect Valuation report which is an unlawful act and i'll be solely responsible for doing it.

a.	Name of th	e Surveyor:	Abhishek.S	4 Dipush	B
b.	Signature:	Dus			
c.	Date:	22/03/2	2 & 24/0	3/22	



	broucher		Csq.ft)	
office unit	Height 9	idependent	Sample	
no.	1 / 1 / 1	3 Ccess	Meagurement	
1415	10.85	Yes.	\$ (1643-8	30)
(404)	12.28	Yes	5535	
\$ 405	12.24	705	401219mel.	
812	11.33	409	1351	
9 1115	11.23	yes.	1279.	
1213	11-33	Yes	1384	
• 奉 200	11-16	under construct	3 4441	
1112-13	10.98	Yes	ar 884000	
1115-E	-	RAGIC!		
1211-12	11.33	Yes	878	
1309-10	11.33	Jes -	882	
1418-E		£1 == 2 m		
1216-E	o Zeha			
1613-14	11.33	Jes -	\$ 889	
1619-E			- 12177	
1509-E	1 -1-102	PE = 1001/	1811 1 1 day	
605-6	10.93	Yes	- 121	
V712-E	era Hood	(3 34	11 to old ?	
804-E 908-9	L -	S.	pad may	
908-9	11.35	Yes	864	
· Grand			1	
			3	

	4,5,20, Grad, B3, Storage			
17	office )	Height 1	independent/	Sample
3	unit	(+t)	access	masurement
	-4077	re'ed . 110.26	7. 2 anthies	2000
	- 4081	KALL WAR	separate but inside	Sq. St.
	607	29.914 VIII	yel Yesissis	1/10 3800 3
	519	Not identif	A CONTRACTOR OF THE PARTY OF TH	
			Not identified.	The state of
	1615 B3	No Keys	. Jes many	5109 % 514 AP 11 (
3	·storage	Complete Complete	- 6/6	00/A 18/1/5
	a .		2/3	316
	0 0 0 0 0		3/3	7491(8)
	1 12 12 12 12	ralified	THE RESERVE THE PROPERTY OF TH	
	1000	distriction	10-10-913 cm	a 2/91 (1st
	(2 : http://	1 / 1 / 1 / 60	11 601 12	· 18/ (3
		. 1/4		
		4,11	. C (86.17 Y)	(3.3)
		A STATE OF THE STA	1) pro-11/2-1/2	
	V ( 1 )			
<b>3</b> ,				
3-	)			
7				
The state of the s			Coonned	with CamScanner

