

REPORT FORMAT: V-L1 (Basic) | Version: 6.0_2018

FILE NO. VIS(2021-22)-PL937-814-1039

DATED: 05/02/2022

VALUATION REPORT

OF

RESIDENTIAL FLAT

SITUATED AT

APPARTMENT NO. CGC-183, 18TH FLOOR, TOWER C, DLF CAPITAL GREENS, 15 SHIVAJI MARG, MOTI NAGAR, NEW DELHI 110015

OWNER/S

MR. BHUMICA DUA W/O MR. LUXMAN DASS DUS

&

Corporate Valuers

MR. LUXMAN DASS DUA S/O MR. LAL CHAND DUA

- Business/ Enterprise/ Equity Valuations
- Lender's Independent Engineers (LIE)

REPORT PREPARED FOR

- Techno Economic Viability Consultants (1EV)

 TAX LAW
- Agency for Specialized Account Monitoring (ASM)
- Project Techno-Finduico Atanitoria case of any query/ Issue/ concern or escalation you may please contact Incident Manager @ valuers@rkassociates.org. We will appreciate your feedback in order to improve our service.
- Chartered Engineers
 - NOTE: As per IBA Guidelines please provide your feedback on the report within 15 days of its submission after which
- Industry/Trade Rehabilitation Consultants
 report will be considered to be correct.
- NPA Management

CORPORATE OFFICE:


D-39, 2nd floor, Sector 2, Noida-201301 Ph - +91-0120-4110117, 4324647, +91 - 9958632707

E-mail - valuers@rkassociates.org | Website: www.rkassociates.org

 Panel Valuer & Techno Economic Consultants for PSU Banks



ASSET/ PROPERTY UNDER VALUATION



SITUATED AT

APPARTMENT NO. CGC-183, 18TH FLOOR, TOWER C, DLF CAPITAL GREENS, 15
SHIVAJI MARG, MOTI NAGAR, NEW DELHI 110015





| | REPORT OF THE PROPERTY OF THE | G | SENERAL DETAILS | 3 | | |
|------------|---|--|--|---|---|--|
| 1. | Report prepared for | Indivi | idual customer | | | |
| 2. | Name & Address of Organization | NA | | | | |
| 3. | Name of Customer | | Bhumica Dua W/o Mr al Chand Duaa | . Luxman Dass Dua & Mr. | Luxman Dass Dua S/o | |
| 4. | Credit Analyst | NA | | | | |
| 5. | Type of Loan | NA | | | | |
| 6. | Report Format | V-L1 | V-L1 (Basic) Version: 6.0_2018 | | | |
| 7. | Date of Valuation | 5 Feb | 5 February 2022 | | | |
| 8. | Date of Survey | 3 Feb | oruary 2022 | | | |
| 9. | Date of Valuation for Capital Gains | 7 Jan | uary 2021 | | | |
| 10. | Type of the Property | Resid | dential Apartment in m | nultistoried building | | |
| 11. | Type of Valuation | Resid | dential Flat Value | | | |
| 12. | Report Type | Plain | Asset Valuation | | | |
| 13. | Surveyed in presence of | Owne | er's representative | Mr. Narendra Dua (+91-9 | 9818513154) | |
| 14. | Purpose of Valuation | For T | he Purpose Of Austra | alian Capital Gains Tax Lav | W | |
| 15. 16. | Scope of the Report Out-of-Scope of the Report | Prope | erty identified by Prop | General Prospective Value erty owner or through its re icity of documents from or | epresentative | |
| | | b. L. c. l. b. d. d. d. d. f. M. g. L. | Legal aspects of the podentification of the propoundaries at site if moderating cizra map dentification is not dorweasurement is only light deasurement of the propoundaries of t | s not done at our end. roperty are out-of-scope of roperty is only limited to o entioned in the provided do or coordination with re- ne at our end. imited upto sample random roperty as a whole is not do n of the property is out of so | cross verification from its ocuments. venue officers for site in measurement. one at our end. | |
| 17. | Documents provided for perusal | | uments Requested | Documents Provided | Documents Reference No. | |
| | | То | otal 02 documents requested. | Total 01 documents provided. | 01 | |
| | | Prop | erty Title document | Sale Deed | Dated: 24/09/2020 | |
| | | | Approved Map | NA | | |
| 18. | Identification of the property | | | oundaries of the property r | | |
| | | | | e displayed on the property | | |
| | | | | r/ owner representative | | |
| | | | Enquired from local re | | | |
| | | | | operty could not be done p | roperly | |
| | | | Survey was not done | | | |
| 19. | Enclosures | 1 | 100 to | s per RKA Format Annex | ure-1 | |
| | | Contract of | R.K Associates Impo | | | |
| | | | Valuer's Remark - Pa | | | |
| | | IV. | | rice trend references of the | | |
| | | | | on public domain - Page N | O.X | |
| | | | Google Map – Page | | | |
| | | | Photographs - Page | | | |
| | | | Copy of Circle Rate | | | |
| | | | Survey Summary Sh | | | |
| | | IX. | Copy of relevant pap Valuation – Pages 0 | pers from the property docu 1 | iments referred in the | |







VALUATION REPORT AS PER RKA FORMAT – ANNEXURE 1

| 1. | Customer Details | | | | | | |
|---|---|---|---|--|--------------------|---------------|------------------------|
| i. | Name | Mr. Bhumica Du | | Mr. Luxman Dass Dua | & Mr. Luxi | man Dass D | ua S/o Lal Chand Dua |
| ii. | Application No. | NA | | | G IIII. EGA | Hall Baco B | da o/o Lai Ollalia Dua |
| 2. | | | - | Property Details | 1652 | | |
| i. | Address | Appartment No. | CGC | 183, 18 TH FLOOR, D | LE Canita | d Greens 1 | 5 Shiyaii Mara Moti |
| | 7.144.000 | Nagar, New Del | hi 110 | 015 | Li Capito | di Oreens, | 15 Stilvaji Marg, Moti |
| ii. | Nearby Landmark | | | Itself a land mark | | | |
| iii. | Google Map | Enclosed with th | | | | | |
| | 3 | | Coordinates or URL: 28°39'54.1"N 77°09'02.9"E | | | | |
| iv. | Independent access to | | Clear independent access is available | | | | |
| | the property | | oledi ilideperidenti decessi le dvalidatio | | | | |
| V. | Type of ownership | Joint ownership | 5 | | | | |
| vi. | Constitution of the | Free Hold | | | | | |
| | Property | | | | | | |
| vii. | Is the property merged | No, its an indepe | endent | singly bounded propert | у | | |
| | or colluded with any | | | | | | |
| | other property | | | | | | |
| 3. | Document Details | Status | | Name of Approving | Auth. | A | pproval No. |
| i. | Layout Plan | No information | on | | | | NA |
| | | provided | | | | | |
| ii. | Building plan | No information | on | | | | NA |
| ••• | | provided | | | | | |
| iii. | Construction Permission | No information | on | | | | NA |
| | Land Danimanta | provided | | Cala Dand | | 10 | |
| iv. | Legal Documents | Available | | Sale Deed | | NA | na |
| 4. | | | ysicai | Details of the Prope | | | 111 |
| i. | Adjoining Properties | North | | South Corridor/ CGC -184 | | ast 3 -181 | West |
| ii. | Are Boundaries matched | Open Yes | | Corridor/ CGC - 164 | CGI | 5-101 | Open/ CGC-182 |
| iii. | Plot demarcation | Yes | | | | | |
| iv. | Approved land Use | Residential as p | er zoni | na regulation | | | |
| V. | Type of Property | · · | | - | | | |
| v. vi. | Note: The subject property | Residential Apartment in multistoried building | | | | | |
| VII. | | | | | | | |
| VIII. | | | round- | | | | |
| | Total no. of floors of the | y was a Flat 3 Basements+G | Fround- | | | | |
| | Total no. of floors of the property | 3 Basements+G | Fround- | | | | |
| viii. | Total no. of floors of the property Floor on which the | | Fround- | | | | |
| | Total no. of floors of the property Floor on which the property is located | 3 Basements+G 18 th Floor | | | the subjec | t property wa | as approx. 4 years old |
| viii. | Total no. of floors of the property Floor on which the | 3 Basements+G 18 th Floor | | -26 Floors. | he subjec | t property wa | as approx. 4 years old |
| viii. | Total no. of floors of the property Floor on which the property is located Approx. age of the | 3 Basements+G 18 th Floor As per the informin 2021. | mation | -26 Floors. | | t property wa | as approx. 4 years old |
| viii. ix. | Total no. of floors of the property Floor on which the property is located Approx. age of the property Residual age of the property | 3 Basements+G 18 th Floor As per the informin 2021. Approx. 55-60 y | mation ears su | -26 Floors. provided by the owner t | | t property wa | as approx. 4 years old |
| viii. ix. | Total no. of floors of the property Floor on which the property is located Approx. age of the property Residual age of the property Type of structure | 3 Basements+G 18 th Floor As per the inforr in 2021. Approx. 55-60 y | mation ears su | -26 Floors. provided by the owner t | | t property wa | as approx. 4 years old |
| viii. ix. x. | Total no. of floors of the property Floor on which the property is located Approx. age of the property Residual age of the property Type of structure Condition of the | 3 Basements+G 18 th Floor As per the informin 2021. Approx. 55-60 y | mation ears su | -26 Floors. provided by the owner t | | t property wa | as approx. 4 years old |
| viii. ix. x. xi. xii. | Total no. of floors of the property Floor on which the property is located Approx. age of the property Residual age of the property Type of structure | 3 Basements+G 18 th Floor As per the informin 2021. Approx. 55-60 y RCC framed stru Good | mation ears su ucture | provided by the owner tubject to timely maintena | ance | t property wa | as approx. 4 years old |
| viii. ix. x. | Total no. of floors of the property Floor on which the property is located Approx. age of the property Residual age of the property Type of structure Condition of the Structure | 3 Basements+G 18 th Floor As per the inform in 2021. Approx. 55-60 y RCC framed strugged Good Tenure | mation ears su ucture | provided by the owner to the provided by the owner to the | Details | | as approx. 4 years old |
| viii. ix. x. xi. xii. | Total no. of floors of the property Floor on which the property is located Approx. age of the property Residual age of the property Type of structure Condition of the Structure Property presently posses | 3 Basements+G 18 th Floor As per the inform in 2021. Approx. 55-60 y RCC framed strugged Good Tenure | mation ears su ucture | provided by the owner tubject to timely maintena | Details | | as approx. 4 years old |
| viii. ix. x. xi. xii. | Total no. of floors of the property Floor on which the property is located Approx. age of the property Residual age of the property Type of structure Condition of the Structure Property presently posses by | 3 Basements+G 18 th Floor As per the inform in 2021. Approx. 55-60 y RCC framed structure Good Tenure seed/ occupied | mation ears su ucture l/ Occ | provided by the owner to the provided by the owner to the | Details | | as approx. 4 years old |
| viii. ix. x. xi. xii. | Total no. of floors of the property Floor on which the property is located Approx. age of the property Residual age of the property Type of structure Condition of the Structure Property presently posses by Status of Tenure | 3 Basements+G 18 th Floor As per the informin 2021. Approx. 55-60 y RCC framed structure Good Tenure ssed/ occupied | mation ears su ucture Owner | provided by the owner to the provided by the owner to the | Details ite survey | | as approx. 4 years old |
| viii. ix. x. xi. xii. | Total no. of floors of the property Floor on which the property is located Approx. age of the property Residual age of the property Type of structure Condition of the Structure Property presently posses by Status of Tenure No. of years of occupancy | 3 Basements+G 18 th Floor As per the informin 2021. Approx. 55-60 y RCC framed structure Good Tenure sed/ occupied | mation rears su ucture Owner NA 02 year | provided by the owner to the provided by the owner to the | Details ite survey | | as approx. 4 years old |
| viii. ix. x. xi. xii. ii. iii. iv. | Total no. of floors of the property Floor on which the property is located Approx. age of the property Residual age of the property Type of structure Condition of the Structure Property presently posses by Status of Tenure No. of years of occupancy Relationship of tenant or | 3 Basements+G 18 th Floor As per the informin 2021. Approx. 55-60 y RCC framed structure Good Tenure sed/ occupied | mation ears su ucture Owner | provided by the owner to the provided by the owner to the | Details ite survey | | as approx. 4 years old |
| viii. ix. x. xi. xii. | Total no. of floors of the property Floor on which the property is located Approx. age of the property Residual age of the property Type of structure Condition of the Structure Property presently posses by Status of Tenure No. of years of occupancy | 3 Basements+G 18 th Floor As per the informin 2021. Approx. 55-60 y RCC framed structure Good Tenure sed/ occupied | mation rears su ucture Owner NA 02 year | provided by the owner to the provided by the owner to the | Details ite survey | | as approx. 4 years old |



| 7. | Violation in the property | | | |
|----|------------------------------|-----------------------------------|--|--|
| | a. Violation if any observed | b. Nature and extent of violation | c. Any other negativity, defect or drawback in the property | |
| | NA | NA | No | |

| 8. | AREA DETAILS OF THE PROPERTY* | | | | |
|-----|-------------------------------|---|---------------------------------------|--|--|
| i. | | Land area (as per documents/ site survey, whichever is less) t considered since this is a Built-up Dwelling Unit Valuation) | | | |
| | Area as per documents | Area as per site survey | Area considered for Valuation | | |
| | NA | NA | NA | | |
| * | Area adopted on the basis of | NA | | | |
| | Remarks & Observations | NA | | | |
| ii. | | Built Up Unit Value (As per IS 3861-1 | 1966) | | |
| | Area as per documents | Area as per site survey | Area considered for Valuation | | |
| | 146.71sq. mtr (1579 sq. ft.) | Not Measureable at site | 146.71sq. mtr (1579 sq. ft.) | | |
| | Area adopted on the basis of | Property documents only since site | e measurement couldn't be carried out | | |
| | Remarks & Observations | NA | | | |

^{*}Please see note in concluding comments.

| 9. | VALUATION ASSESSMENT | | | | | |
|-------|--|---|----------------------------|------------|------------------------------|-------------------------|
| A. | | ASSES | SMENT FACTORS | | | |
| i. | Valuation Type | Built-up unit value (sold-purchased as a seperate dwelling unit/ comparable Residential flat Value | | | | flat Value |
| ii. | Scope of the Valuation | Non binding opinion on the assessment of Plain Asset Valuation of the proper identified to us by the owner or through his representative. | | | | |
| iii. | Property Use factor | Curre | | Highest & | Best Use | |
| iv. | Legality Aspect Factor (Refer clauses i & j of Point-10) | Residential Residential Positive as per documents produced to us. | | | gentiai | |
| ٧. | Land Physical factors | Shape | Size | L | _evel | Frontage to depth ratio |
| | | Not Applicable | Not Applicable | Not A | Applicable | Not Applicable |
| Vİ. | Property location category factor | City Categorization | Locality Categorization | | ty location sification | Floor Level |
| | | Metro City | Good | | ary location the locality | NA |
| | | Urban | Within good urban | | NA | |
| | | | developed area | | NA | |
| | | Property Facing | South Facing | | | |
| vii. | New Development in surrounding area | NA | NA | | | |
| viii. | Property overall usability Factor | NA | | | | |
| ix. | Comment on Property Salability Outlook | NA | | | | |
| Χ. | Comment on Demand & Supply in the Market | NA | | | | |
| xi. | Sale transaction method assumed | NA | | | | |
| xii. | Best Sale procedure to realize maximum Value | NA | | | | |
| xiii. | Methodology/ Basis of | Govt. Guideline Va | | | | ssociales Value |
| | Valuation | Market Value: Reve | erse calculation method | d as per p | present Marke | er Rates (g) |



| | | • This valuation report is prepared for Australian Capital Gains Tax Law as per the |
|------|--|---|
| | | requirement of the client. |
| | | As per Australian Capital Gains Tax Law it will be assumed that the concerned |
| | | owner acquired this asset on the day when he became Australian resident which was 7 th January, 2021 as per information provided by the client. |
| | | • So, accordingly as per Australian Capital Gains Tax Law, the valuation has to be |
| | | prepared for value of the property was on 7th January, 2021. |
| | | • For Calculation of the Value prevailing in the year- 2021, we have adopted reverse |
| | | Calculation Method based on the Market rates prevailing as on date and assume |
| | | that market may have grown based on the below percentages as per demand of the market in these previous years. |
| | | Housing/ Property Price/ Cost Inflation Index method is also referred to ascertain |
| | | the value prevailed in Jan., 2021. |
| | | • In Jan., 2021 market was not normal due to covid-19 restrictions and not many |
| | | sale-purchase was taking place at that point of time. |
| | | Therefore for the purpose of this valuation instead of ascertaining the valuation in that particular period we have wideped the period from Jan. 2021 till Oct. 2021. |
| | | that particular period, we have widened the period from Jan., 2021 till Oct., 2021 when the market started coming to normalcy. |
| | | Presently the market rates are around Rs.12,000/- to Rs.13,000 per sq.ft. |
| | | • As per various market trends Housing/ Property Price and reports published by |
| | | several institutions, there is negligible price difference in last one year. In few |
| | | specific cases it can be considered maximum of 5% price difference in last 1 year. |
| | | This property falls in the developing area of Moti Nagar New Delhi. The subject area of Moti Nagar is in New Delhi and this area is considered to be a |
| | | good residential area. |
| | | • The green line of metro has been expanded to Shiva ji Park and was operational |
| | | since year 2020. |
| | | • As per the variation in the property market since 2021 we are of the opinion that in |
| | | the subject location of Shiva Ji marg, property rates have been almost same based on the development & demand in that year. |
| | | As per significant local enquiries in the market from the old inhabitants and |
| | | experienced property dealers, we came to know that the prices in year 2021 must |
| | | have been around Rs.12,000/- to Rs.13,000/- per sq. ft. (On super area) in the |
| | | locality of DLF Capital Greens, Shivaji Nagar. • Hence taking into consideration the facts of record we are of the opinion that the |
| | | residential flat prices are around Rs.12,000/- to Rs.13,000/- per sq. ft. (On super |
| | | area). |
| | | • Based on the locality we are of the opinion to take Rs.12,500 per sq. ft. (On super |
| | | area). |
| xiv. | References on prevailing market Rate/ Price trend of | 1. Name: Mr. Arpan Contact No.: +91-9871348522 |
| | the property and Details of | Nature of reference: Habitants of the subject locality |
| | the sources from where the | Size of the Property: 1579 sq.ft (Super area) |
| | information is gathered (from | Location: DLF Greens, Shivaji Marg, Moti Nagar |
| | property search sites & local information) | Rates/ Price informed: Around Rs.12,000/- to Rs.12,500/- per sq. ft. (On |
| | | super area) |
| | | Any other details/ Discussion held: As per discussion with consultant we came to know that the rates are depend upon the size, view, |
| | | approach road and floor on which unit is available but |
| | | rates with lies in prescribed range of Rs.12,000/- to |
| | | Rs.13,000/- per sq. ft. on super area. |







| B. | | VALUATION CAL | | |
|------------------|--|---|---|--|
| a. | | GUIDELINE/ CIRC | LE VALUE | |
| i. | Land Value (Not considered since this is a built-up unit valuation) | Total Land Area considered as per documents/ site survey (whichever is less) | Prevailing Rates Range | Rates adopted (considering all characteristics assessment factors of the property) |
| | | NA | NA | NA |
| | Total Land Value (a) | | NA | |
| | Total Land Value (a) | | NA | |
| | | | Built-Up unit value | |
| | Comptunction Dominaciated | Structure Type | Construction category | Age Factor |
| ii. | Construction Depreciated Replacement Value | RCC framed structure | Good | 2-5 years old construction |
| 11. | Replacement value | Rate range | Rate adopted | Super Area |
| | | | | 1579 sq.ft./146.71 sq.mt |
| | Total Construction Depreciated | | NA | |
| | Replacement Value (b) | | NA | |
| iii. | TOTAL GUIDELINE/ CIRCLE | | NA | |
| | RATE VALUE: (a+b) | | NA | |
| | | | | |
| b. | PROS | PECTIVE MINIMUM FA | AIR MARKET VALUE | |
| | | (AS ON 01.04. | 2001) | |
| | | Total Land Area | Prevailing Rates | Rate adopted |
| | Land Value (Not considered since this is a built-up unit valuation) | considered as per | Range | (considering all characteristics |
| i. | | documents/ site | | assessment factors of the |
| | | survey (whichever is less) | | property) |
| | | NA | NA | NA |
| | Total Land Value (a) | | NA | |
| | Total Land Value (a) | | NA | |
| | | | Built-Up unit value | |
| | | Structure Type Construction category | | Age Factor |
| ii. | Construction Depreciated | RCC framed structure | Class B construction (Good) | 2-5 years old constructio |
| | Replacement Value | Rate range | Rate adopted | Super Area |
| | | Rs.12,000/- to | Rs.12,000/- per sq. ft. | 146.71 sq. mtr (1579 sq. |
| | | Rs.13,000/- per sq. ft. | (On super area) | ft.) |
| | Total Construction Depreciated | Rs.13,000/- per sq. ft. (On super area) | (On super area) | ft.) |
| | Total Construction Depreciated | Rs.13,000/- per sq. ft. (On super area) | (On super area) 79 sq. ft. x Rs.12,500/- per | ft.) |
| III. | Replacement Value Value (b) Add extra for Architectural aesthet improvements (c) | Rs.13,000/- per sq. ft. (On super area) | (On super area) | ft.) |
| iii. | Replacement Value Value (b) Add extra for Architectural aesthet improvements (c) (add lump sum cost) Add extra for fittings & fixtures (d) (doors, windows, wood work, cupboards, module of the control | Rs.13,000/- per sq. ft. (On super area) 15 | (On super area) 79 sq. ft. x Rs.12,500/- per Rs.1,97,37,500/- | ft.) |
| | Replacement Value Value (b) Add extra for Architectural aesthet improvements (c) (add lump sum cost) Add extra for fittings & fixtures (d) (doors, windows, wood work, cupboards, modufittings) Add extra for services (e) | Rs.13,000/- per sq. ft. (On super area) 15 ic developments, ular kitchen, electrical/ sanitary | (On super area) 79 sq. ft. x Rs.12,500/- per Rs.1,97,37,500/- NA | ft.) |
| iv. | Replacement Value Value (b) Add extra for Architectural aesthet improvements (c) (add lump sum cost) Add extra for fittings & fixtures (d) (doors, windows, wood work, cupboards, modufittings) Add extra for services (e) (water, electricity, sewerage, main gate, bound | Rs.13,000/- per sq. ft. (On super area) 15 ic developments, ular kitchen, electrical/ sanitary | (On super area) 79 sq. ft. x Rs.12,500/- per Rs.1,97,37,500/- NA NA NA NA NA NA Rs.1,97,37,500/- est | ft.) |
| iv. v. vi. | Replacement Value Value (b) Add extra for Architectural aesthet improvements (c) (add lump sum cost) Add extra for fittings & fixtures (d) (doors, windows, wood work, cupboards, modulittings) Add extra for services (e) (water, electricity, sewerage, main gate, bound | Rs.13,000/- per sq. ft. (On super area) 15 ic developments, ular kitchen, electrical/ sanitary | (On super area) 79 sq. ft. x Rs.12,500/- per Rs.1,97,37,500/- NA NA NA NA He) Rs.1,97,37,500/- estithe year 2021 | sq. ft. |
| iv. | Replacement Value Value (b) Add extra for Architectural aesthet improvements (c) (add lump sum cost) Add extra for fittings & fixtures (d) (doors, windows, wood work, cupboards, modufittings) Add extra for services (e) (water, electricity, sewerage, main gate, bound | Rs.13,000/- per sq. ft. (On super area) 15 ic developments, ular kitchen, electrical/ sanitary | (On super area) 79 sq. ft. x Rs.12,500/- per Rs.1,97,37,500/- NA NA NA NA NA NA Rs.1,97,37,500/- est | sq. ft. |
| iv. v. vi. | Replacement Value Value (b) Add extra for Architectural aesthet improvements (c) (add lump sum cost) Add extra for fittings & fixtures (d) (doors, windows, wood work, cupboards, modufittings) Add extra for services (e) (water, electricity, sewerage, main gate, bound T Additional Premium if any | Rs.13,000/- per sq. ft. (On super area) 15 ic developments, ular kitchen, electrical/ sanitary | (On super area) 79 sq. ft. x Rs.12,500/- per Rs.1,97,37,500/- NA NA NA NA He) Rs.1,97,37,500/- estithe year 2021 NA | sq. ft. |





| | the year 2021 | | | | |
|-------|--|---|--|--|--|
| x. | | Round Off | year 2021 | | |
| xi. | EXPECTED REALIZA | BLE VALUE [^] (@ ~15% less) | NA | | |
| xii. | EXPECTED FORCED/ DISTRI | ESS SALE VALUE* (@ ~25% less) | NA | | |
| xiii. | | THE INSURANCE PURPOSÉ | NA | | |
| xiv. | Justification for more than 20% difference in Market & Circle Rate | NA | | | |
| XV. | Concluding comments if any | Based on the facts of the our best to take realistic a previous years to reach tyear 2021. However, we arrived historical Valuatio that period. In case the axis prepared finds any mathe report then he is well authentic reasoning so the report in case the reasoning. Valuation of the asset is documents & facts provided. The covered area of the given by the owner. Any kind of unpaid statuted dues on the asset has not dues on the asset has not Registration charges, Brown purchase of this property Value. As per the scope of the Assumptions, Remarks below, R.K Associate (Enclosure: 1) & other | case and the available information we have tried assumptions about the growth of the market in the he realistic assessment of the Value prevailed in a do not claim or take any responsibility for the n due to the limited data/ information available of athorised reader of the report for whom this report aterial deficiencies in the assumptions adopted in come to contradict it based of some evidence & that appropriate corrections can be made in the anglis worthwhile to be accepted. In done on the basis of as- is — where — is basis as the day the owner representative. It is property has been taken from the undertaking force, utilities, lease, interest or any other pecuniary to been factored in the Valuation. The series of asset transaction like Stamp Duty, obserage, Bank interest etc. pertaining to the sale/of are not considered while assessing the Market the assignment, Value assessment is subject to a limiting Conditions mentioned in Point '7' Important Notes and Valuer's Remarks the report. Without these enclosures/ documents to id. | | |








| 10. | ASSUMPTIONS REMARKS LIMITING CONDITIONS | | | |
|------|---|--|--|--|
| i. | Qualification in TIR/Mitigation Suggested, if any: Cannot comment since copy of TIR is not provided to us. | | | |
| ii. | Is property SARFAESI compliant: Yes | | | |
| iii. | Whether property belongs to social infrastructure like hospital, school, old age home etc.: No | | | |
| iv. | Whether entire piece of land on which the unit is set up / property is situated has been mortgaged or to be mortgaged: NA | | | |
| V. | Details of last two transactions in the locality/area to be provided, if available: Information couldn't be found. | | | |
| vi. | Any other aspect which has relevance on the value or marketability of the property: Property located in developing area | | | |

- a. Information of the average market rates is taken based on the verbal market survey in the subject area from the local people, property agents, recent deals, demand-supply, internet postings which has been relied upon. No written record is generally available for such market information and only the verbal information has to be relied upon.
- Forced, compulsion, constraint, obligatory sales transactions data doesn't forms part of the Fair Market Valuation exercise.
- c. Sale transaction method of the asset is assumed as free market transaction while assessing Prospective Fair Market Value of the asset.
- d. This Valuation report is prepared based on the facts of the property on the date of the survey. However in future property Market may go down, property conditions may change or may go worse, Property reputation may differ, Property vicinity conditions may go down or become worse, Property market may change due to impact of Govt. policies or effect of World economy, Usability prospects of the property may change, etc. Hence before financing, Banker/ FI should take into consideration all such future risk and should loan conservatively to keep the advanced money safe in case of the downward trend of the property value.
- e. Valuation of the same asset/ property can fetch different values in different situations. For eg. Valuation of a running/ operational shop/ hotel/ factory will fetch better value and in case of closed shop/ hotel/ factory it will have considerable lower value. Similarly an asset sold directly by an owner in the market will fetch better value and if the same asset/ property is sold by any financer due to encumbrance on it will fetch lower value. Hence before financing, Banker/ Fl should take into consideration all such future risks and should loan conservatively to keep the advanced money safe in case of any such situation.
- f. This report is prepared based on the copies of the documents/ information which interested organization or customer could provide to us out of the standard checklist of documents sought from them and further based on our assumptions and limiting conditions. All such information provided to us has been relied upon and we have assumed that it is true and correct. Verification or cross checking of the documents provided to us from the originals has not been done at our end. If at any time in future it's found or came to our knowledge that misrepresentation of facts or incomplete or distorted information has been provided to us then this report will automatically become null & void.
- g. Getting cizra map or coordination with revenue officers for site identification is not done at our end.
- h. All area measurements are on approximate basis. Verification of the area measurement of the property is done only based on sample random checking and not based on full scale measurement. Area of the large land parcels of more than 2500 sq.mtr or of uneven shape, is taken as per property documents which has been relied upon.
- i. Legal aspects for eg. ownership rights, lien, charge, mortgage, etc. are not considered in this report. It is assumed and taken into account that the concerned Bank/ Financial Institution has first got the legal verification cleared by the competent Advocate before requesting for the Valuation report. In case Valuation is obtained before taking legal scrutiny or opinion then it is expected from the Bank to inform back the Valuer timely about such change of rights on the property as soon as it comes into the notice of the Bank/ Financer which may affect their charge on the mortgage asset so that accordingly Valuation modification can be done only for that portion for which the Bank has complete charge/ rights.
- j. Investigation of title of the property and its legal right is beyond the scope of this report. If this property is offered as collateral security, then concerned financial institution is requested to verify & satisfy themselves on the ownership & legality of the property shown in this valuation report with respect to the latest legal opinion.
- K. Valuation is done for the property identified to us by the owner/ owner representative. Responsibility of identifying the correct property to the Valuer/ its authorized surveyor is solely of the client/ owner for which Valuation has to be carried out. At our end we can just cross verify the identification of the property with reference to the documents produced for perusal. Method by which identification of the property is carried out is also mentioned in the report clearly. It is requested from the Bank to cross check from their own records/ information if this is the same property for which Valuation has to be carried out to ensure that owner has not misled the Valuer company or misrepresented the property due to any vested interest.



- In India more than 70% of the geographical area is lying under rural/ remote/ non municipal/ unplanned area where the subject property is surrounded by vacant lands having no physical demarcation or having any display of property survey or municipal number / name plate on the property clearly. Even in old locations of towns, small cities & districts where property number is either not assigned or not displayed on the properties clearly and also due to the presence of multiple/ parallel departments due to which ownership/ rights/ illegal possession/ encroachment issues are rampant across India and due to these limitations at many occasions it becomes tough to identify the property with 100% surety from the available documents, information & site whereabouts and thus chances of error, misrepresentation by the borrower and margin of chances of error always persists in such cases. To avoid any such chances of error it is advised to the Bank to engage municipal/ revenue department officials to get the confirmation of the property to ensure that the property shown to Valuer/ Banker is the same as for which documents are provided.
- m. If this Valuation Report is prepared for the Flat/ dwelling unit situated in a Group Housing Society or Integrated Township then it is assumed that the Banker or the concerned organization has satisfied themselves with the approval of the Group Housing Society/ particular floor & building before allotting the Valuation case to the Valuer company.
- n. Due to fragmented & frequent change in building/ urban planning laws/ guidelines from time to time, different laws/ guidelines between regions/ states and no strict enforceability of Building Bye-Laws in India specially in non-metro and scale b & c cities & Industrial areas, property owners many times extend or make changes in the covered area/ layout from the approved/ applicable limits. There are also situations where properties are decades old when there was no formal Building Bye-Laws applicable when the construction must have been done. Due to such discrete/ unplanned development in many regions sometimes it becomes tough to determine the exact lawful situation on ground for the Valuer. In case nothing specific is noted on the covered built-up area considered in the Valuation Report, the covered area present on the site as per site survey will be considered in the Valuation.
- o. In case of Valuation of Plant & Machinery or equipment, condition of machines is evaluated by visual observation only. No technical/ mechanical testing of any kind has been carried out at our end to ascertain the condition and efficiency of the machines. Valuation of Plant & Machinery is done on the basis of physical existence of the assets rather than their technical expediency.
- p. Secondary/ Tertiary costs related to asset transaction like Stamp Duty, Registration charges, Brokerage, Bank interest, etc. pertaining to the sale/ purchase of this property are not considered while assessing the Market Value.
- q. Any kind of unpaid statutory, utilities, lease, interest or any other pecuniary dues on the asset has not been factored in the Valuation.
- r. Valuation is a subjective field and opinion may differ from consultant to consultant. To check the right opinion, it is important to evaluate the methodology adopted and various data point/ information/ factors/ assumption considered by the consultant which became the basis for the Valuation report before reaching to any conclusion.
- s. At the outset, it is to be noted that Value analysis of any asset cannot be regarded as an exact science and the conclusions arrived at in many cases will, of necessity, be subjective and dependent on the exercise of individual judgment. Given the same set of facts and using the same assumptions, expert opinions may differ due to the number of separate judgment decisions, which have to be made. Therefore, there can be no standard formulae to establish an indisputable exchange ratio. In the event of a transaction, the actual transaction value achieved may be higher or lower than our indicative analysis of value depending upon the circumstances of the transaction. The knowledge, negotiability and motivations of the buyers and sellers and the applicability of a discount or premium for control will also affect actual price achieved. Accordingly, our indicative analysis of value will not necessarily be the price at which any agreement proceeds. The final transaction price is something on which the parties themselves have to agree. However our Valuation analysis can definitely help the stakeholders to make them informed and wise decision about the Value of the asset and can help in facilitating the arm's length transaction.









| 11. | 建设设施的 | DECLARATION | | | | | |
|-----|---|---|--|--|--|--|--|
| | i. The property was inspected by our a | uthorized surveyor on 3 February | 2022 by name Er. Sachin Pandey in | | | | |
| | presence of the owner's representative. | | | | | | |
| | | The undersigned does not have any direct/indirect interest in the above property. | | | | | |
| | iii. The information furnished herein is true and correct to the best of our knowledge. | | | | | | |
| | iv. This valuation report is carried out by our Engineering team on the request from Mrs. Bhumica Dua W/o Mr. | | | | | | |
| | Luxman Dass Dua & Mr. Luxman D | | | | | | |
| 12. | Name & Address of Valuer | Wealth Tax Registration No. | Signature of the authorized person | | | | |
| | company | | | | | | |
| | M/s R.K. Associates Valuers & | 2303/ 1988 | | | | | |
| | Techno Engineering Consultants Pvt. | | | | | | |
| | Ltd. G-183, Preet Vihar, Delhi-110092 | | | | | | |
| 13. | Enclosed Documents | I. Valuer's Remark - Page No. | | | | | |
| | | | d references of the similar related properties | | | | |
| | | available on public domain - | - Page No.x | | | | |
| | | III. Google Map – Page No.13 | | | | | |
| | | IV. Photographs – Pages No.xx | | | | | |
| | | V. Copy of Circle Rate – Pages | | | | | |
| | | VI. Survey Summary Sheet – Pa | | | | | |
| | | | n the property documents referred in the | | | | |
| | Total Number of Donos in the | Valuation – Pages No.15 | | | | | |
| 14. | Total Number of Pages in the Report with Enclosures | 15 | | | | | |
| 15. | Engineering Team worked on the report | SURVEYED BY: Er. Sachin Pand | ey | | | | |
| | | PREPARED BY: Eng. Aditya | | | | | |
| | | | ssociates Values | | | | |
| | | REVIEWED BY: HOD Valuations | Techno En | | | | |
| | | | 13/ | | | | |



R.K ASSOCIATES IMPORTANT NOTES:

- 1. <u>DEFECT LIABILITY PERIOD</u> In case of any query/ issue or escalation you may please contact Incident Manager by writing at valuers@rkassociates.org. We ensure 100% accuracy in the Calculations done, Rates adopted and various other data points & information mentioned in the report but still can't rule out typing, human errors or any other mistakes. In case you find any mistake, variation, discrepancy or inaccuracy in any data point of the report, please help us by bringing all such points into our notice in writing at <u>valuers@rkassociates.org</u> within 30 days of the report delivery, to get these rectified timely, failing which R.K Associates won't be held responsible for any inaccuracy in any manner. Also if we will not hear back anything from you within 30 days, we will assume that report is correct in all respect and no further claim of any sort will be entertained thereafter. We would welcome and appreciate your feedback & suggestions in order to improve our services.
 - 2. <u>COPYRIGHT FORMAT</u> This report is prepared on the copyright format of R.K Associates to serve our clients in the best possible way. Legally no one can copy or distribute this format without prior approval from R.K Associates. It is meant only for the organization as mentioned on the cover page of this report. Distribution or use of this format other than R.K Associates will be seen as unlawful act and necessary legal action can be taken against the defaulters.

IF REPORT IS USED FOR BANK/ FIS

NOTE: As per IBA Guidelines in case the valuation report submitted by the valuer is not in order, the banks / FIs shall bring the same to the notice of the valuer within 15 days of submission for rectification and resubmission. In case no such communication is received, it shall be presumed that the valuation report has been accepted.

At our end we have not verified the authenticity of any documents provided to us. Bank is advised to verify the genuineness of the property documents before taking any credit decision.





ENCLOSURE: 1 – VALUER'S REMARKS

| 1 | Fair Market Value# suggested by the competent Valuer is that prospective estimated amount of the subject |
|-----|---|
| 1. | Fair Market Value* suggested by the competent Valuer is that prospective estimated amount of the subject asset/ property in his expert & prudent opinion without any prejudice after he has carefully & exhaustively evaluated all the facts & information related to the subject asset at which the subject asset/ property should be exchanged between a willing buyer and willing seller at an arm's length transaction after proper marketing. |
| | wherein the parties, each acted knowledgeably, prudently and without any compulsion on the date of the Valuation. |
| 2. | Realizable Value^ is the minimum prospective value of the property which it may be able to realize at the time of actual property transaction factoring in potential prospects of deep negotiations carried out between the buyer & seller for ultimately finalizing the transaction. Realizable value may be 10-20% less of the Fair Market Value depending on the various salability prospects of the subject property. |
| 3. | Forced/ Distress Sale Value* is the value when the property has to be sold due to any compulsion or constraint like financial encumbrances, dispute, as a part of a recovery process, any defect in the property, having unclear title or any such sort of condition or situation. In this type of sale minimum disposable value is assessed which varies from 20-35% less from the Fair Market Value based on the nature, size & salability prospects of the property. In this type of sale negotiation power of the buyer is always more than the seller and eagerness of selling the property is more than buying it. Therefore the Forced/ Distress Sale Value always fetches less value. |
| 4. | Best rates are rationally adopted based on the facts of the case came to our knowledge during the course of the assignment considering many factors like nature of the property, size, location, approach, market situation and trends. |
| 5. | Construction rates are adopted based on present replacement cost of construction and calculating applicable depreciation & deterioration factor as per its existing condition, specifications based on the visual observation of the structure. No structural, physical tests have been carried out in respect of it. |
| 6. | This Valuation report is prepared based on the facts of the property on the date of the survey. However in future property Market may go down, property conditions may change or may go worse, Property reputation may differ, Property vicinity conditions may go down or become worse, Property market may change due to impact of Govt. policies or effect of World economy, Usability prospects of the property may change, etc. Hence before financing, Banker/ FI should take into consideration all such future risk and should loan conservatively to keep the advanced money safe in case of the downward trend of the property value. |
| 7. | Valuation of the same asset/ property can fetch different values in different situations. For eg. Valuation of a running/ operational shop/ hotel/ factory will fetch better value and in case of closed shop/ hotel/ factory it will have considerable lower value. Similarly an asset sold directly by an owner in the market will fetch better value and if the same asset/ property is sold by any financer due to encumbrance on it will fetch lower value. Hence before financing, Banker/ FI should take into consideration all such future risk and should loan conservatively to keep the advanced money safe in case of any such situation. |
| 8. | No employee or member of R.K Associates has any direct/ indirect interest in the property. |
| 9. | Sale transaction method of the asset is assumed as free market transaction while assessing Fair Prospective Market Value of the asset. |
| 10. | Area measurements considered in the Valuation Report pertaining to Land & Building is adopted from relevant approved documents or actual site measurement whichever is less. All area measurements are on approximate basis only. |
| 11. | This report is having limited scope as per its fields to provide only the general basic idea of the value of the property prevailing in the market based on the documents/ data/ information provided by the client. The suggested value should be considered only if transaction is happened as free market transaction. |
| 12. | The condition assessment and the estimation of residual economic life of the structure is based on the visual observations and appearance found during the site survey. We have not carried out any structural design or stability study; nor carried out any physical tests to assess structural integrity & strength. |
| 13. | This report is prepared based on the copies of the documents/ information which interested organization or customer could provide to us out of the standard checklist of documents sought from them and further based on our assumptions and limiting conditions. All such information provided to us has been relied upon and we have assumed that it is true and correct. Verification or cross checking of the documents provided to us from the originals has not been done at our end. If at any time in future it's found or came to our knowledge that misrepresentation of facts or incomplete or distorted information has been provided to us then this report will automatically become null & void. |
| 14. | Investigation of title of the property and its legal right is beyond the scope of this report. If this property is offered as collateral security, then concerned financial institution is requested to verify & satisfy themselves on the |



| | ownership & legality of the property shown in this valuation report with respect to the latest legal opinion. |
|-----|---|
| 15. | Value varies with the Purpose/ Date/ Condition of the market. This report should not to be referred if any of these points are different from the one mentioned aforesaid in the Report. The Value indicated in the Valuation Report holds good only upto the period of 3 months from the date of Valuation. |
| 16. | Analysis and conclusions adopted in the report are limited to the reported assumptions, conditions and information came to our knowledge during the course of the work. |
| 17. | This report is prepared on the RKA V-L3 (Medium) Valuation format as per the client requirement, charges paid and the time allotted. This report is having limited scope as per its fields to provide only the general estimated basic idea of the value of the property prevailing in the market based on the information provided by the client. The Valuation assessed in this Valuation Report should hold good only if transaction is happened as per free market transaction. No detailed analysis or verification of the information is carried upon pertaining to the value of the subject property. No claim for any extra information will be entertained whatsoever be the reason. For any extra work over and above the fields mentioned in the report will have an extra cost which has to be borne by the customer. |
| 18. | This is just an opinion report and doesn't hold any binding on anyone. It is requested from the concerned Client/Bank/ Financial Institution which is using this report for mortgaging the property that they should consider all the different associated relevant & related factors also before taking any business decision based on the content of this report. |
| 19. | All Pages of the report including annexures are signed and stamped from our office. In case any paper in the report is without stamp & signature then this should not be considered a valid paper issued from this office. |
| 20. | Defect Liability Period is <u>30 DAYS</u> . We request the concerned authorized reader of this report to check the contents, data and calculations in the report within this period and intimate us in writing if any corrections are required or in case of any other concern with the contents or opinion mentioned in the report. Corrections only related to typographical, calculation, spelling mistakes will be entertained within the defect liability period. No request for any illegitimate value revision, date change or any other change will be entertained other than the one mentioned above. |
| 21. | R.K Associates encourages its customers to give feedback or inform concerns over its services through proper channel at valuers@rkassociates.org in writing within 30 days of report delivery. After this period no concern/complaint/proceedings in connection with the Valuation Services can be entertained due to possible change in situation and condition of the property. |
| 22. | Our Data retention policy is of <u>ONE YEAR</u> . After this period we remove all the concerned records related to the assignment from our repository. No clarification or query can be answered after this period due to unavailability of the data. |
| 23. | This Valuation report is governed by our (1) Internal Policies, Processes & Standard Operating Procedures, (2) R.K Associates Quality Policy, (3) Valuation & Survey Best Practices Guidelines formulated by management of R.K Associates, (4) Information input given to us by the customer and (4) Information/ Data/ Facts given to us by our field/ office technical team. Management of R.K Associates never gives acceptance to any unethical or unprofessional practice which may affect fair, correct & impartial assessment and which is against any prevailing law. In case of any indication of any negligence, default, incorrect, misleading, misrepresentation or distortion of facts in the report then it is the responsibility of the user of this report to immediately or atleast within the defect liability period bring all such act into notice of R.K Associates management so that corrective measures can be taken instantly. |
| 24. | R.K Associates never releases any report doing alterations or modifications from pen. In case any information/ figure of this report is found altered with pen then this report will automatically become null & void. |
| 25. | If this report is prepared for the matter under litigation in any Indian court, no official or employee of R.K Associates will be under any obligation to give in person appearance in the court as a testimony. For any explanation or clarification, only written reply can be submitted on payment of charges by the plaintiff or respondent which will be 10% of the original fees charged where minimum charges will be Rs.2500/ |








Page 14 of 14

ENCLOSURE: 2 - GOOGLE MAP LOCATION







Enclosure: 6

SURVEY SUMMARY SHEET (TO BE ENCLOSED WITH VALUATION REPORT)

(Version 1.0) | Date of implementation: 10.04.2017

Every Valuation report at R.K Associates is prepared based on the thorough survey of the property carried out by our Engineering Surveyor. This Survey Summary Sheet is for the information of Banker/ concerned interested organization. Detailed Survey Form can also be made available to the interested organization in case it is required to cross check what information our surveyor has given in site inspection report based on which Valuation report is prepared.

| 1. | File No. | | | |
|-----|--|--|--------------------|--------------------------------|
| 2. | Name of the Surveyor | Couls Pardon | | |
| 3. | Borrower Name | Nest Bhunica Ova & Cakshman Dua | | |
| 4. | Name of the Owner | | | |
| 5. | Property Address which has to be valued | Clost No. Cal - 183 Tower & Diftapited | | |
| 6. | Property shown & transfeed by at spot | could not be done from inside | | le, Property is locked, survéy |
| | Brother. | Name | | Contact No. |
| - | | Mr Masendry D | U9 98 | 18 (131 61 |
| 7. | How Property is Identified by the Surveyor | ☐ From schedule of the properties mentioned in the deed, ☐ From name plate displayed on the property ☐ identified by the owner/ owner representative. ☐ Enquired from nearby people, ☐ Identification of the property could not be done, ☐ Survey was not done. | | |
| 8. | Are Boundaries matched | Yes. No. No relevant papers available to match the boundaries, Boundaries not mentioned in available documents | | |
| 9. | Survey Type | Full survey (inside-out with measurements & photographs) Half Survey (Measurements from outside & photographs) Only photographs taken (No measurements) | | |
| 10. | Reason for Half survey or only photographs token | ☐ Property was locked, ☐ Possessee didn't allow to inspect the property, ☐ NPA property so couldn't be surveyed completely | | |
| 11. | Type of Property | Residential Builder Floor, Commercial Land & Building, Commercial Shop, Commercial Floor, Shopping Mall, Hotel, Industrial, Institutional, School Building, Vacant Residential Plot, Vacant Industrial | | |
| 12. | Property Measurement | Piot, Agricultural Land | | |
| 13. | Reason for no measurement | ☐ Self-measured, ☐ Sample measurement, ☐ No measurement ☐ it's a flat in multi storey building so measurement not required ☐ traperty was locked, ☐ Owner/ possessee didn't allow it, ☐ NPA property so didn't enter the property, ☐ Very Large Property, practically not possible to measure the area within limited time ☐ Any other Reason: | | |
| 14. | Land Area of the Progresty | As per Title deed | As per Map | As per site survey |
| | | 01576 Sq ft | X | 1 × |
| 15. | Covered Built and American | 1576 Sq ft | As per Map | As per site survey |
| | C |) Y _ | X | To per site survey |
| 16. | Property passes and any of the time of survey | Converty was locked, Bank sealed, Court sealed | | |
| 17. | Any negative observation of the | was above up to Bank Ser | neo, 🗀 court seale | ed sociales Value |

| | property during survey | No. | |
|-----|--|---|--|
| 18. | Is independent access available to the property | Clear independent access is available, ☐ Access available in sharing of other adjusting property, ☐ No clear access is available, ☐ Access is closed due to dispute | |
| 19. | Is property clearly demarcated with permanent boundaries? | View, □ No, □ Only with Temporary boundaries | |
| 20. | Is the property manger or colluded with any other property | No. | |
| 21. | Local Information decrences on property rates | Please refer attached sheet named 'Property rate Information Details.' | |

Endorsement:

1. Signature of the corson who was present from the owner side to identify the property:

Undertaking I have shown the correct property and provided the correct information about the property to the surveyor of R.K. Associates to the best of my knowledge for which Valuation has to be prepared, in case I have shown correct property or misted the valuer company in any way then I'll be solely responsible for this unlawful act.

a. Name of the foreign: Name of

- b. Relations
- c. Signature:
- d. Date

In case not it used then mention the ceason for it:

No one was available,
Property is locked,
Owner/
representative reloced to sign it,
Any other reason:

2. Surveyor Standblird who did site inspection:

Undertaking I have inspected the properly and cross verified the property details at site to the extent of a. Matching freedom of the property. It Samula measurement of its area, c. Physical condition, d. Property rates as not local information with what is manifolded in the property documents provided to me by the Bank/Interested organization. I have not caree under influence of anyone during site inspection and have only recorded the true and factual details in the survey form which I come across during the site survey. I understand that sloved any manipulative information in the survey form will lead to incorrect Valuation report which is accorded to a retail of the solely responsible for doing it.

a. Name of the seyon:

b. Signatur

c. Date

Salvelouder 03/orhors

