File No.	RKA/DNCR//.
Date of Receiving	20 04 22
File Receiver Name	Abhishelc.s

RNP Scaffholdings

CASE COLLECTION FORM

(Version 5.0) Date of implementation: 9.02.2011 Last Revision: 30.01.2020 | Latest Revision: 31.10.2020


Items	Assigned To	Assigned to Date	To be completed by date	Submitted On date	Grade	HOD Engg. Signature
File Received By	Abhishek S-	NA	NA			
Survey	Abhishek S					
Preparation						

A - Very Good, B - Satisfactory, C - Average, D - Poor, E - Extremely Poor

File Returned to HOD Engg. unprepared due to reason	□ Survey not done properly, □ Survey Form not properly filled, □ Market survey for rates is not properly done, □ Identification is not clearly done, □ Measurement is not properly done, □ Photographs not clearly taken, □ Selfie/ Owner or owner representative photo not taken, □ Owner/ owner representative signature not taken, □ Google Map not taken, □ Survey summary sheet not filled
---	---

by the preparer - HOD	☐ Minor defects in the survey hence approved for preparation with warning to Surveyor. Report preparer to collect the missing information on his own.
Engg. comment & Signature	□ Major defects in the survey. Survey has to be done again.

		GENER	AL DETAILS			Provide the second second
1. Proposal/ Work Order or						
	Ref. No.	VIS (2022-23)	- PL033 -	019 - 039		
2.	Type of Service		Valuation Report, Construction cost estimate, Cost vetting certificate Other CE Certificates, TEV Report, LIE			etting certificate
3.	Type of customer			CI NBFC		
		Company				
4.	Bank/ FI/ Organization	PNB MCC Branch, Maker Tower 'f' wing, 7th floor, Cuffe				or, cuffe
	Name & Address	Parade, Mumbai - 400005				
5.	Case Allotment Officer/	Name Contact Number		act Number	Email Id	
	Fees paying party Details	Mr. Jash	9422	296792	c1pc.6294	@gmail.com
6.	Case Type	Case for Free	Case for Fresh Account		for exiting acc	count/ customer
7.	Fees Details	Amount of Fees Advance		nount if any	Fees w	ill be paid by
		7500 + GIST	00 + GIST 50%		🗆 Bank	Customer
8.	Billing Details	Billed To Party Name		GST	IN	



Customer Signature:

File No. RKA/DNCR/...../

THE PARTY	EILE RECEIVER CASE COLLECTION PROC		
学校にでく	FILE RECEIVER CASE COLLECTION PROC	ESS COM	PLIANGE CHECKLIST
CNO	(To be filled by Su	veyor)	
S.NO.	COMPLIANCE CHECKLIST	STATUS	APPROVER SIGNATURE/
			REMARKS IN CASE OF ANY (X)
1.	Is Case collection Form properly filled by Receiver?	R	
2.	Is purpose of the assignment understood clearly by	X	
	the receiver?	~	
3.	Has receiver checked if this is a new case or	I	
	existing case of the Bank?		
4.	Has receiver fixed the fees with the manager/ client	J	
	and sent quotation properly or have taken approval		
	of the work over email?		
5.	Has receiver taken proper Work Order/ Email/	Z	
	CESA form formality?		
6.	In case of private case or for fresh case 50%	A	
	advance is received?		
7.	Is document checklist email sent to the customer?		
8.	Has the received documents is having 'documents		
	provided by stamp'?		

IMPORTANT INSTRUCTIONS TO SURVEYOR

1.	Please fill the above compliance checklist before moving for the survey.
2.	Please do not do the survey if you do not have proper documents.
3.	For Vacant Plot/ Land – Cizra Map/ Master/ Zonal/ Site Plan is must to identify the Plot. For Agriculture or converted land from agriculture – Mutation documents, CLU is must.
4.	Firstly please first study the documents of the property which needs to get surveyed.
5.	Mark the Owner/ Area/ Boundaries mentioned in the ownership documents with bold florescent marker pen before moving for the survey. During site survey if any difference is found in the above fields from the ownership documents then please contact the owner immediately to know the reason for the difference.
6.	Confirm ongoing property rates in the subject location through public domain, property sites and contact dealers to show you the available properties in that area during your survey.
7.	Identify the Property clearly by matching the boundaries and area mentioned in the property napers.
8.	Do sample physical or google measurements of the property.
9.	 PHOTOGRAPH INSTRUCTIONS: a. Take owner/ representative photograph along with the property. b. Take your selfie along with the property and the owner/ representative. c. Take full scale photo of the property with gate. d. Take photo of the property along with abutting road, towards left, right and center. e. Take multiple photos of inside-out of the property. f. Take nearby photographs of the Property. g. Take a short video to cover property and neighborhood.
10.	Take Google Map location. Check main road name & width and approach road width and distance of property from main road.
11.	and the light and humining him to 8 Ward Name
12.	The ask asking of survey form diligently in detail and tick the appropriate option clearly.
13.	Check any defects or negativity in the property and comment in detail on survey form.
14.	De autonoino markot rato onquirios and confirm for any recent past transactions.
16.	In case customer appears to be providing misleading information to you or trying to influence you by money or cash then immediately report to the Management & Bank.

and Loan	SURVEY GRADING MATRIX	
GRADE	PARAMETERS/ CRITERIA	
A	In case all the points below are done properly, timely with full care and diligence:	
	 Survey started with proper work order and knowing the source of payment. Survey done with proper documents. Done complete homework and studied the documents properly with highlighting the main points before moving for the survey. Chosen correct survey form as per the property type All fields of Survey form are properly filled. All site special observations and negative and positive factors are clearly mentioned. Self & client signatures taken on survey form. Property rates information properly taken, mentioned and verified. Site rough sketch plan made. Proper photographs taken. Selfie with property taken. Selfie and owner photograph with property taken. 	
В	In case of 3 minor mistakes in any of the above points except Point 1, 2, 3, 4, 6, 8, 10, 11, 12 but all the points are covered.	
С	In case of more than 3 minor mistakes and any 1 major mistake in any of the above points and if any point are completely missing except Point 1, 2, 3, 4, 6, 8, 10, 11, 12.	
D	In case of 1 major mistake or missing of any 1 point out of 1, 2, 3, 4, 6, 8, 10, 11, 12.	
E	In case of more than 1 major mistakes or missing of more than 1 point out of 1, 2, 3, 4, 6, 8, 10, 11, 12.	

Note (Survey Grading Matrix):

- 1. For special assignments like LIE, Stock Valuation, etc. where till date survey format is not specified or released, in such cases point wise site observation report has to be submitted by the Surveyor duly signing it properly. Without signed Site Observation report, Point 4 will be considered as not done and will fall under Category E.
- 2. Similar Grading Matrix is issued for Case Collection & Report Preparation as well.

Note (Overall Grading Matrix):

1. In case client reports any careless mistake in the report for which revision has to be done in the report then in that case Grading Matrix may be revised and Grade E will be awarded.



SURVEY PROCESS COMPLIANCE CHECKLIST

(To be submitted by Surveyor with each Survey)

	(To be submitted by Surveyor with each Survey)	
S.NO.	COMPLIANCE CHECKLIST POINTS	STATUS
1.	Did you take proper property documents to carry out the survey?	V
2.	Have you properly studied & highlighted Owner/ Area/ Boundaries in the property documents with bold florescent before moving for the survey?	A
3.	Did you check prominent landmark nearby the subject property and mentioned in the survey	J
4.	form? Did you identified the Property clearly by matching the boundaries and area mentioned in	A
5.	the property papers? Did you check if property is merged with any other property or it is an independent	
6.	property? Did you do sample physical or google measurements of the property in case of property	
	more than 2500 sq.mtr?	J
7.	Did you check for any building violations in the property?	A
8.	Did you check municipal limits/ jurisdiction/ ward?	Æ
9.	Did you take Google Map location and shared it to Maps whatsapp group?	J
10.	Did you take Google Map location and shared it to map Did you check Main road name & width and its distance from the subject property?	P
11.	Did you check approach Lane width on which property is located?	E
12.	Have you taken property full scale photograph with gate?	J
13.	Have you taken property run scale processory Have you taken owner/ representative photograph with the property?	I
14.	Have you taken owner/ representative processing with owner/ representative? Have you taken your selfie with the property along with owner/ representative? Have you taken photograph of the property along with abutting road and towards left and	
15.	Have you taken photograph of the property doing that a c	
	right of the property?	UT
16. 17.	right of the property? Have you taken multiple photographs of the property from inside-out? Did you check nearby development and whereabouts and commented on survey	
17.	form? Did you check any defects or negativity in the property in terms of location, legality,	A
19.	Did you check any defects or negativity in the property in terms disputes, marketability, salability, etc. and commented on survey form in detail? Have you filled all the columns of survey form including survey summary sheet	
10.		
20.	Did you draw site key plan (location map).	
21.	Did you draw site key particular of the set	
22.	Have you taken self-attested documents "documents provided by stamp"?	J
23.	Did you check any defects or negativity in the property in terms of the defect of the	R
24.	Have you confirmed any recent pater and enquired property rates locally very rigorously? Did you take signatures of the owner/ representative on undertaking and survey	V
25.	many sheet?	P
26.	Did you signed the undertaking?	

For File No.	12033-019-039	
Surveyor Name	Abhishek.S	
Signature	Banbhag	
Date	10 5 22	



at in

GENERAL SURVEY FORM (FOR PROPERTIES OTHER THAN FLATS)

(Version 5.0) Date of implementation: 9.02.2011 | Last Revision: 04.01.2018 | Latest Revision: 31.10.2020

-	File No. RKA/DNCR//	Date: 1005 22 Time:	June 10 prover 12
		GENERAL DETAILS	1.5 m. 2016.2 m
	Name of the Surveyor	Abhishek.S	
	Property shown by	□ Owner, V Representative, □ No one was available. □ F	Property i
		locked, survey could not be done from inside	
		Name Contact No.	
		Sandip Gaural 7722052313	
3.	Survey Type	Full survey (inside-out with measurements & photographs	5)
		□ Half Survey (Measurements from outside & photographs)	
		□ Only photographs taken (No measurements)	anaot the
4.	Reason for Half survey or only	□ Property was locked, □ Possessee didn't allow to in	spect un
	photographs taken NA	property, NPA property so couldn't be surveyed completel	y
5.	How Property is Identified	From schedule of the properties mentioned in the deed	
		name plate displayed on the property, I Identified by th	ie owner
		owner representative, Enquired from nearby people, Identification of the property could not be done, Surve	v was no
		done	1
-	Transformativ	□ Flat in Multistoried Apartment, □ Residential House, □	Low Ris
6.	Type of Property	Apartment, Residential Builder Floor, Commercial	Land a
		Building, Commercial Office, Commercial Shop, Co	ommercia
		Floor, C Shopping Mall, C Hotel, C Industrial, C Institutiona	al,
		🗆 School Building, 🗆 Vacant Residential Plot, 🗆 Vacant	Industria
		Plot, Agricultural Land	
7.	Property Measurement	□ Self-measured, Sample measurement only, □ No mea	suremen
8.	Reason for no measurement	 It's a flat in multi storey building so measurement not requination Property was locked, Owner/ possessee didn't allow it, 	neu
		□ NPA property so didn't enter the property. □ Very Large	Property
		practically not possible to measure the entire area	
		Reason:	
		Treason.	
9.	Purpose of Valuation	Value assessment of the asset for creating new collateral	
	credit limit	□ Periodic Re-Valuation for Bank, □ Distress sale for NPA A	
	enhancement	□ For DRT Recovery purpose, □ Capital Gains Wealth Tax	purpose
		Partition purpose, General Value Assessment	
10.	Type of Loan	□ Housing Loan, □ Housing Take Over Loan, □ Home Imp	
		Loan, □ Loan against Property, □ Construction Loan, □ Ed Loan, □ Car Loan, □Project Loan, □ Term Loan, □	
		Loan, L Car Loan, LProject Loan, L Term Loan, L	
		aphancement Cash Credit Limit Industrial Loan CINA	OO LIIII
11.	Loan Amount	enhancement, Cash Credit Limit, Industrial Loan, NA	

Page 6 of 15



		OWNERSHIP DETAILS
1.	Legal Owner Name/s	Ramesh N. Patil
2.	Property Purchaser Name	-4
3.	Property Address under Valuation	Pg. 2
4.	Present Residence Address of the Owner/ Purchaser	
5.	Property constitution	Free Hold, Lease Hold

				9			
1.	Adjoining Properties	East	V	lest	N	lorth	South
	(Match it with papers with the help	Gut no.	Dar	n F	Gut	N 0 -	Gut no- 76
	of compass or Sun direction and	78	wate	-+ +	92,	91	76
	also confirm it with nearby people)	70	Na	٩			
2.	Property Facing N	East Facing,	🗌 North F	acing, [□ West Fa	cing, Sc	outh Facing,
	W_E	North-East Facing, South-West Facing, South-East Facing,					
	6	□ North-West F	acina				
-	S			1	1 1		
3.	Landmark Entry	Darshan Mau	Valley_	1 Mar	nashak	h	
4.	Ward Name/ No.						
5.	Zone Name / Village	a Vars	oli	14/		Distance	from proporti
6.	Main Road Name & Width	Name		VV	idth	Distance	e from property
	Mumbai	- Pune Exp	ressway	1	-	500-6	500 M
7.	Approach Road Name & Width	Approach	head,	CNO,	name)		
8.	Location consideration of the	□ Within Main city, ✓ Within Good Urban developed Area, □ Within					
	Society	developing area, 🗆 Highly posh locality, 🖾 Very Good, 🖾 Good,					
		□ Ordinary, □ In interiors, □ Remote area, □ Backward, □ Average,					
		Poor			- Dead I	acing []	Entrance North-
9.	Special Location consideration	201	/		2 Road F	∙acing, ⊔	Entrance North-
	of the property	East Facing,	Sunlight fa	cing			
10.	Characteristics of the locality	Urban develo	oped, 🗆 Ur	ban dev	eloping, 🗆	Semi Urba	an, 🗆 Rural,
		🗆 Backward, 🗆	Industrial.	🗆 Instit	utional		
11.	Category of Society/ locality		Normal, []	Afforda	able Group	Housing, L	∃ EWS, □ HIG.
		☐ MIG, ☐ LIG		decenin	a Swir	ming Pool	Gym
12.	Utilities/ Facilities in the locality	Litts, Gard	Ien, Lan	Trails	Kids pl	av zone i	□ 100% Power
		Backup	U vvaik	riano, v		., 20110, 1	
13.	Proximity to civic amenities		ospital N	arket	Metro	Railway St	ation Airport
13.	FTOXITING to only difference			uka		3.7 Kn	0 64 Km
4.4	Any new development in	300 m 1.	DICM 1.	INM		Lu JL	
14.		300 1.1 Infrastr	uture	(Te	mple &	bldg) p	Jy str Airp
	surrounding area						

Page 7 of 15



15.	Jurisdiction limits	🗆 Nagar Nigam, 🗆 Nagar Panchayat, 🗆 Gram Panchayat, 🗆 Nagar		
	Varsoli Gram Panchayat	Palika Parishad, Area not within any municipal limits		
16.	Jurisdiction Development	DDA, GDA, NOIDA, GNIDA, YEIDA, HUDA, KMDA.		
	Authority Name Lonavola Maria apol	□ MDDA, □ Any other Development Authority:		
	Nagarpalika	Area not within any development authority limits		
17.	Municipal Corporation Name	□ NDMC, □ SDMC, □ EDMC, □ Ghaziabad Municipal Corporation,		
	Lonavale	Gurgaon Municipal Corporation, Faridabad Municipal Corporation,		
	Nagarpalika	□ Kolkata Municipal Corporation, □ Dehradun Municipal Corporation,		
		🗆 Area not within any municipal limits, 🗆 Any other Municipal		
		Corporation/ Municipality:		

10 10		PHYSICAL DETAIL	Englishes, Spheresenergy and an and a second s	
1.	Land Area	As per Title deed	As per Map	As per site survey
	<i>2</i>	1 hectare		
2.	Any conversion to the land use	Agricultural	(x .)	
3.	Land Type	□ Solid, □ Rocky, □ Marsh Land, □ Reclaimed Land, □ Water logged, □ Land locked		
4.	Shape of the Land	🛛 Irregular, 🗆 NA		riangular, 🗆 Trapezoid
5.	Level of Land	On road level, 🗆 Bela		
6.	Frontage to depth ratio	🗆 Normal frontage,	ess frontage, 🗆 Large	e frontage, 🗆 NA
7.	Are Boundaries matched	Yes, INO, INO relevant papers available to match the boundaries, IBoundaries not mentioned in available documents		
8.	Is Independent access available to the property	Clear independent access is available, Access available in sharing of other adjoining property, No clear access is available, Access is closed due to dispute		
9.	Is property clearly demarcated with permanent boundaries?	Yes, 🗆 No, 🗆 Only v	with Temporary bounda	aries
10.	Is the property merged or colluded with any other property	NO.		
11.	Property possessed by at the time of survey	✓ Owner, ✓ Vacant, □ Lessee, □ Under Construction, □ Couldn't be Surveyed, □ Property was locked, □ Bank sealed, □ Court sealed		
12.	Current activity carried out in the property	 ☑ Residential purpos □ Office, □ Industrial, 		purpose, □ Godown □ Any other use:

E[U] 41	NIG/ CONSTRUCTION/UTLITY DETAILS
1. Construction Status	Built-up property in use, Under construction, No construction



2.	Covered Built-up Area	Covered Area, 🗆 Floor Area, 🗆 Super Area, 🗆 Carpet Area		
2.		As per Title deed As per Map As per site survey		
	(Tick one on the basis of which			
	valuation is to be calculated) BU A-	7557.41 m - sample meggyrement.		
3.	Total Number of Floors in the	Par 11		
	Building	Gtl		
4.	Floor on which property is situated	Bungalow		
5.	Type of Unit/ Number of Rooms/ Cabins/ Cubicles	-		
6.	Building Type	RCC Framed Structure, D Load bearing Pillar Beam column.		
		□ Ordinary brick wall structure, □ Iron trusses & Pillars, □ Scrap		
		abandoned structure		
7.	Roof	a. Make: □ RBC, □ RCC, □ GI Shed, □ Tin Shed, □ Stone Patla		
		b. Height: 27.44 St		
		c. Finish: Simple plaster, D POP Punning, D POP False		
		Ceiling Coved roof No plaster		
8.	Flooring	 □ Vitrified tiles, □ Ceramic Tiles, □ Simple marble, □ Marble chips, □ Mosaic, □ Granite, □ Italian Marble, □ Kota stone, □ Wooden, □ PCC, □ Imported Marble, □ Pavers, □ Chequered Tiles, □ Brick Tiles, □ No Flooring, □ Under construction, □ Any 		
0	Appearance/ Condition of the	Internal - Excellent, Very Good, Good, Ordinary.		
9.	Building	Average Poor Under construction, No Survey		
	Duilding	External - Excellent, Very Good, Good, Ordinary,		
		Average, Poor Under construction		
10.	Maintenance of the Building	Very Good, Average, Poor, Under construction		
11.	Interior decoration	□ Excellent, □ Very Good, □ Good, □ Simple, □ Ordinary, □ Average, □ Below average, □ Under construction, □ No Survey		
12.	Interior Finishing	☐ Simple plastered walls, □ Brick walls without plaster, □ Designer textured walls, □ POP punning, □ Coved roof, □ Under construction, □ No Survey		
13.	Exterior Finishing	 Simple plastered walls, □ Brick walls without plaster, □ Architecturally designed or elevated, □ Brick tile Cladding, □ Structural glazing, □ Aluminum composite panel cladding, □ Class facade □ Domb □ Porch, □ Under construction 		
14.	Kitchen	☐ Glass laçade, ☐ Benne, ☐ Ordinary with cupboard, ☐ Normal ☐ Simple with no cupboard, ☑ Ordinary with cupboard, ☐ Normal Modular with chimney, ☐ High end Modular with chimney, ☐ Under construction, ☐ No Survey		
15.	Class of Electrical fittings	☐ External, ☐ Internal		
		Concealed lightning, Under construction, No Survey		
16.	Class of Sanitary/ Plumbing &	□ External, □ Internal □ Excellent, □ Very Good, □ Good, □ Simple, □ Average,		
	water supply fittings	Below average Under construction, U No Survey		
17	. Water arrangements	Laterman Chemorsible Chalboard Supply of Z water su		
18	and the second se	Excellent, Very Good, Good, Simple, Ordinary,		
10	•	□ Average, □ Below Average, □ No wooden work, □ No survey		
19		7-8 yrs. None (4yrs ago to		
	Improvements done	Very Good, Average, Poor		
20	. Maintenance of the Building	Page 9 of 15		

,

Page 9 of 15



21.	Any defects in the building	□ Maintenance issues, □ Finishing issues, □ See	epage issues,
21.	7	□ Water supply issues, □ Electricity issues, □ Str	
		□ Visible cracks in the building Leakage	problem
22.	Any violation done in the property	🗌 Construction done without Map, 🗆 Constru	ction not as per
	NO	approved Map, Extra covered without sanctione adjacent property, Encroached adjacent area ille	d Map, 🗋 Joined gally
23.	Boundary Wall (Only for individual	□ Yes, □ No, □ Common boundary wall of a com	plex
20.	property)	Running Mtr. Height Width	Emisi
		- 4it to loing	rocks (ceme
24.	Lift/ elevators	Passenger/ Commercial NA	
£ 1.		Make: Capacity:	
25.	Power backup	□ Inverter, 12 DG Set	
20.		Make: KOEL Capacity: -	
26.	Garden/ Landscaping	Yes, D No, Beautiful, D Ordinary	
20.	Parking facilities	Available within the property On Ground,	
			Acute parking
28.	Special Comments/ Observations, If any	Boundary wall ranges from 4th height. At one side BW is under Common BW for adjoining property	to 12-1t r construction
		Common BW for adjoining property	f.

1. 1.	Any issues in marketability of the property?	Yes, VO	000	
1.		Reason in case of No: Location, Surrounding, L aspects, Demand, Shape, Any Other:	ega	
	How is Demand & Supply condition	Demand Very Good, Good, Average, Low, Poor		
2.	in the Market of such properties?	Supply Very Good, Good, Average, Low, Poor		
3.	Is property easily sellable & marketable?	Z Yes, D No		
э.		Comments: The property is under green ZOR. My Excellent Very Good, Good, Average, Low, Po	or	
4.	How is the current utility of the			
-	property? At what True rate Owner bought	Year of purchase 1999		
5.	this Property?	Purchase Price		
6.	Present expected Sale Value of the overall property?	-		

BLANK PAGE FOR PROVIDING ANY ADDITIONAL DETAILS/ INFORMATION

Height - 27.44 St Dining Aba - 31.58×10.94 Hall - 27.32 × 31.18 Kitchen - 13.71×8.71

- all in the

PROPERTY MARKET COMPARABLE RATE INFORMATION DETAILS

A REAL			or Transaction alread	v happened in past)	And the for the stand of the stand
S.No	Particulars	Subject Property	Comparable 1	Comparable 2	Comparable 3
1.	Name (source of information)	NA	Sarpanch	Deepak	
2.	Contact No.	NA	9623150341	9881793211	
3.	Type of source of information (Seller/ Property dealer/ nearby people)	NA	Ex sarpanch	Lo cal broker	
4.	Rates/ Price informed (in Rs. with unit)	NA	3L - 3.5L per guntha	3L - 5L per guntha	
5.	Rates Type (Sale/ Buy)	NA	Buy	per guntha Buy	•
6.	Shape of the Property (Square, Rectangular, Irregular)		-	-	
7	Area/ Size of the Property		1-2 acre	1-2 acre	
8.	Legal Status (clear, negative, weak)/ No. of owners		Uear	deav	
9.	Location/ surrounding/ neighborhood comparison with the subject property (Similar, Lower, Better, Highly Better than the subject Property)	Base Case	same Location	same Location	
10.	Distance from the subject Property	0	Jeon radius	500 M radius	
11.	Other factors (Corner, 2 side open, North-East facing, Park facing, Legal/ Financial encumbrance, etc.)		-	-	
12.	Approach road width		-	-	
13.	Level of Land (Below/ On/ Above road level)		-		
14.	Frontage to depth ratio (Normal, Less, Large)		_	-	
5.	Present Use		Green zone rates an	area plot re given about.	
6.	Any other details/ Discussion held	NA			
1	Present expected Sale Value of the overall property?	j			e 13 of 15

UNDERTAKING BY THE CUSTOMER

Context that I have made the inspection of the sublect property to the surveyor of R.P. Accordance, which is context theorem in question for which the documents have been provided/ submitted by no. I further confirmation is all that dware of all the information related to the subject property and I have provided all its information to the surveyor true to the best of my knewledge. Lunderstand that any false or manipulative information provided by the wall be considered as chesting with the professional organization since it will lead to incorrect valuation (exclusion and Td be soleh) responsible for this unlawful act and will bear the charges for the obarges) incuffications which have to undergo due to the false information. Laiso undertake that I have not given all cush or in kind to any member of R.K. Associates to influence the Value of the Property or favor any individual to all calculation and the same is not accepted or asked by the member of R.K. Associates. Any such act will lead to calcellation of the material prepared by R.K. Associates with forfeiting of the fees and the some factor costories to the material prepared by R.K. Associates with forfeiting of the fees and the completely costories for the material prepared by R.K. Associates with forfeiting of the fees and the be completely costories to the material prepared by R.K. Associates with forfeiting of the fees and the completely costories for its repercussions and legal actions taken for it.

MAXIMANT: We have not authorized any of our person/ Surveyor to take Gash or kind from the customers in any situation. In case Surveyor or any member of R.K Associates asks for any money or kind from you then kindly please inform on number +91-9958632707, 0120-4110117. Our Valuation process is very stringent and have multiple check points to ensure correct & error free reports to keep the lending agency risk free. In case Surveyor claims that he would be able to arbitrary effect the Valuation figures unfairly or as par your requirement & need, then he is making a false claim to you and we request you to complaint output soft ast immediately on the number provided above.

Name	Sandip Gravrau
Relationship with owner	office staff
Signature	FURDED.
Mobile No.	7722052313
Date	10/05/22

UNDERTAKING BY THE SURVEYOR

I confirm that I have carried out the Survey of the property properly as per the fair professional best practices and Valuation & Survey policy guidelines issued by R.K Associates. I have not taken any cash or kind from the customer nor have I come into any kind of influence of the customer / bank for arbitrary providing the Property Valuation as per one's need. I further state that I have not given any assurances to the customer nor given any wrong or false information or statement. In case at any point of time it is found that I have done any kind of fraudulent activity in this case and misled the company then I understand its legal consequences and appropriate penal action which company can take against me. Also in regard to it any monetary or reputation loss will be recovered from me by the company.

For File No.		
Surveyor Name	Abhishelc.S	
Signature		
Date	10 05 22	

UNDERTAKING BY THE PREPARER

I confirm that this Valuation Report is prepared as per the fair professional best practices and Valuation & Survey Policy Guidelines issued by the organization. I also confirm that without any personal interest, partiality or prejudice, I have worked on this Valuation assignment. Rates adopted for the asset is based on various facts, information collected from the site came to my knowledge during the course of the assignment and I have taken all sincere efforts to review, cross check & confirm this data/ information from all different angles using my prudent approach without any biasedness or pressure. I have prepared the report based on true facts & information as per best of my knowledge & case facts. I understand that any false information provided by me will lead to the incorrect valuation report and I'd be solely responsible for it and will bear the losses which will be put on the Company in form of monetary or reputation loss by its client or statutory bodies.

I also undertake that I did not come into any influence by the customer, Bank representative (officer or agent), colleagues, coworkers or any other person to arbitrary change the Valuation figures or facts unethically or illegitimately which may put the public money at risk which is in the form of Bank deposits.

In case at any point of time in future, if I am found guilty of illegitimately distorting the facts in the Valuation or any other professional services which company offers in the market on being influenced by the customer or Bank representative (officer or agent) or for whatsoever reason then I'd solely responsible of any such act and I understand that the Company can take appropriate legal action against me which may include suspension from the current roles & responsibilities or termination from the employment with immediate effect.

I also undertake that I have not taken any cash, favor or in kind from the customer for favoring any individual or organization by unfair means.

I also undertake that I'll not prepare any report on incomplete Survey form which is not properly filled as per the Company guidelines and in case I am preparing it which is creating an incorrect report then I'd be responsible for its consequences.

For File No.	
Preparer Name	
Signature	
Bate	

SURVEY SUMMARY SHEET (TO BE ENCLOSED WITH VALUATION REPORT)

(Version 1.0) | Date of implementation: 10.04.2017

Every Valuation report at R.K Associates is prepared based on the thorough survey of the property carried out by our Engineering Surveyor. This Survey Summary Sheet is for the information of Banker/ concerned interested organization. Detailed Survey Form can also be made available to the interested organization in case it is required to cross check what information our surveyor has given in site inspection report based on which Valuation report is prepared.

1.	File No.	VIS (2022-23)-PL033-019-034			
2.	Name of the Surveyor	Abhishek-S Ramesh-N. Patil			
3.	Borrower Name	Ramesh N. Patil			
4.	Name of the Owner	Ramesh N. Patil			
5.	Property Address which has to be valued	Gut no. 77, Varsoli, Maharashtra-L	Ramesh N. Patil Ramesh N. Patil Gut no. 77, Varsoli, Lonavela, Tail-Maval, Dist-Pun Maharashtra-410401		
6.	Property shown & identified by at	□ Owner, □ Representative, □ No one was available, □ Property is locked, survey			
	spot	could not be done from inside		Contact No.	
		Name		1722-052213	
		Sandip Gaur	av in antioned	in the deed, \Box From name plate	
7.	How Property is Identified by the	From schedule of the prop	erties mentioned	owner/ owner representative, C	
	Surveyor	displayed on the property,	Identified by the	owner/ owner representative,	
		Enquired from nearby people,	Identification o	f the property could not be done	
		Survey was not done		a de la constante de la constan	
8.	Are Boundaries matched	Yes, 🗆 No, 🗆 No relev	ant papers avail	able to match the boundaries	
0.	Pire of the second second	Boundaries not mentioned in	available docume	nts	
0	Survey Type	Full survey (inside-out with measurements & photographs)			
9.	Survey Type	□ Half Survey (Measurements from outside & photographs)			
		Only photographs taken (No measurements)			
		Property was locked, Possessee didn't allow to inspect the property, NPA			
10.	Reason for Half survey or only	property so couldn't be surveyed	completely		
	photoBrophistoric	Elat in Multistoried Apartmen	t, E Residential H	louse, 🗆 Low Rise Apartment, 🗆	
11.	Type of Property	Residential Builder Floor, 🗆 Commercial Land & Building, 🗆 Commercial Office, 🗔			
		Commercial Shop, Commercial Floor, Shopping Mall, Hotel, Industrial,			
		□ Institutjonal, □ School Building, □ Vacant Residential Plot, □ Vacant Industrial			
		Plot, Agricultural Land Self-measured, Sample measurement, No measurement			
12.	Property Measurement	It's a flat in multi storey build			
13.	Reason for no measurement	□ It's a flat in multi storey build	ng so measureme	in't allow it. NPA property so	
		□ Property was locked, □ Owner/ possessee didn't allow it, □ NPA property so didn't enter the property, □ Very Large Property, practically not possible to			
		measure the area within limited	time 🗌 Any other	Reason:	
		measure the area mention and			
14.	Land Area of the Property	As per Title deed	As per Map	As per site survey	
14.		1 hectare		-	
15	Covered Built-up Area	As per Title deed	As per Map	As per site survey	
15.	Dura	2 557,41/02	-	sample measurem	
16.	Property possessed by at the time of	Owner Vacant, LI Lessee,	Under Constru	action, 🗌 Couldn't be Surveyed,	
10.	survey	Property was locked, Bank s	ealed, 🗌 Court se	aled	
17.	Any negative observation of the	NO			
71.	any negative observation of the				



_	property during survey	
18.	Is Independent access available to the property	Clear independent access is available, adjoining property, No clear access is available, Access is closed due to dispute
19.	Is property clearly demarcated with permanent boundaries?	Yes, 🗆 No, 🗆 Only with Temporary boundaries
20.	Is the property merged or colluded with any other property	No ·
21.	Local Information References on property rates	Please refer attached sheet named 'Property rate Information Details.'

Endorsement:

Signature of the Person who was present from the owner side to identify the property:

Undertaking: I have shown the correct property and provided the correct information about the property to the surveyor of R.K Associates to the best of my knowledge for which Valuation has to be prepared. In case I have shown wrong property or misled the valuer company in any way then I'll be solely responsible for this unlawful act.

- a. Name of the Person: Sandip. Gaurau b. Relation: office staff
- b. Relation: Office Staff c. Signature:

In case not signed then mention the reason for it: \Box No one was available, \Box Property is locked, \Box Owner/ representative refused to sign it, 🗌 Any other reason:

2. Surveyor Signature who did site inspection:

Undertaking: I have inspected the property and cross verified the property details at site to the extent of a. Matching boundaries of the property, b. Sample measurement of its area, c. Physical condition, d. Property rates as per local information with what is mentioned in the property documents provided to me by the Bank/ interested organization. I have not come under influence of anyone during site inspection and have only recorded the true and factual details in the survey form which I come across during the site survey. I understand that giving any manipulative information in the survey form will lead to incorrect Valuation report which is an unlawful act and i'll be solely responsible for doing it.

- a. Name of the Surveyor: Abhisheks
- b. Signature: Ranbhas
- 10/05/22 c. Date: