MIS	Ruby tugh purity	Sylfem
File No.	RKA/DNCR/	TASSOCIATES
Date of Receiving	a0/5/2	開発器A330C1A1C3 Supres a trivial transformal Conscious System
File Receiver Name	Deopre	VIS(202-23)-P1096-081-134
	CASE COLLEC	TION FORM

(Version 5.0)

Date of implementation: 9.02.2011 | Last Revision: 30.01.2020 | Latest Revision: 31.10.2020

Items	Assigned To	Assigned to Date	To be completed by date	Submitted On date	Grade	HOD Engg Signature
File Received By	Deepar	NA	NA			
Survey	Deepar	20/5/22	20/5/22			
Preparation						
A - Very Good, I	B - Satisfactory, C	- Average, D -	Poor, E - Extre	mely Poor		
File Returned to HOD Engg. unprepared due to reason	rates is not properly don representative	roperly done, le, D Photo e photo not ta	☐ Identification graphs not cle	is not clearly early taken, owner repres	done, □ N □ Selfie/ sentative si	Market survey for fleasurement is not Owner or owner ignature not taken,
In case File is returne by the preparer - HOD			survey hence a			n with warning to

Engg. comment & Signature

		GENER	AL DETAILS	STATE OF THE PARTY OF THE PARTY.
1.	Proposal/ Work Order or Ref. No.			
2.	Type of Service		t, Construction cost estima cates, TEV Report, LIE	te. Cost vetting certificate
3.	Type of customer	Bank Company	☐ PSU ☐ NBFC ☐ Private client ☐ Direc	☐ Corporate t client through Bank
4.	Bank/ Fl/ Organization Name & Address	SBID SME	Branch Ranipw	
5.	Case Allotment Officer/ Fees paying party Details	Sheetanshy Jo	Contact Number Shi 9837776317	Sheedhahu-Joshi
6.	Case Type	Case for Fres	sh Account	Shi: Co-in or exiting account/ customer
7.	Fees Details	Amount of Fees 5000 HR1	Advance Amount if any ROCETURE	Fees will be paid by Bank Customer
8.	Billing Details	Billed To P	arty Name	GSTIN

☐ Major defects in the survey. Survey has to be done again.

	Type of Property	CASE DETAILS
		Residential Land & Builder
2.	Purpose of Valuation/ Assignment	☐ Value assessment of the asset for creating new collateral mortgage ☐ Periodic Re-Valuation for Bank, ☐ Distress sale for NPA A/c., ☐ For DRT Recovery purpose, ☐ Capital Gains Wealth Tax purpose ☐ Partition purpose, ☐ General Value Assessment ☐ Any other:
3.	Owner/ Applicant Details	Name Contact Number Email Id Ginja Stantar 895862 1298
4.	Account Name	HIS AND LINE DIEL LALL
5.	Property Address	th. No 1705/2, Vill-Salemper Hondard 2. Hardwas
6.	Who will coordinate on site for the site survey	Name Contact Number
7.	Preferred time of survey	Olivi 9 Chanton. D. Pato 8958621298 Date 28/1022 Time
8.	Documents Received (Any one ownership document and approved site plan/ map is must)	1. Ownership Documents: ☐ Sale Deed, ☐ Power of Attorney, ☐ Registered Will, ☐ Relinquishment Deed, ☐ Transfer Deed, ☐ Conveyance Deed, ☐ Allotment Letter, ☐ Possession Letter 2. Map: ☐ Cizra Map, ☐ Approved Map, ☐ Site Plan 3. Utility Bills: ☐ Electricity Bill & payment receipt, ☐ Water Bill & payment receipt, ☐ House Tax demand & payment receipt 4. Any Other document: ☐ CLU, ☐ TIR Report, ☐ Agreement to Sale, ☐ Old Valuation Report 5. No documents provided: ☐
9.	Documents received from	Banc
10.	Special Instructions if any:	
11.	on Valuer firm to distort any	pentioned above for the preparation of Valuation Report. I agree that I'll not put pressure facts and would not try to influence any member or official of the firm in the ill spirit or any individual or organization by any means illegitimately.

File No. RKA/DNCR/ / 1/1/(2022-23)-PL096-081-134

	FILE RECEIVER CASE COLLECTION PROCESS COMPLIANCE CHECKLIST (To be filled by Surveyor)					
S.NO.	COMPLIANCE CHECKLIST	STATUS	APPROVER SIGNATURE/ REMARKS IN CASE OF ANY (X)			
1.	Is Case collection Form properly filled by Receiver?	w				
2.	Is purpose of the assignment understood clearly by the receiver?	-27				
3.	Has receiver checked if this is a new case or existing case of the Bank?	Do				
4.	Has receiver fixed the fees with the manager/ client and sent quotation properly or have taken approval of the work over email?	P				
5.	Has receiver taken proper Work Order/ Email/ CESA form formality?	4				
6.	In case of private case or for fresh case 50% advance is received?	9				
7.	Is document checklist email sent to the customer?	4				
8.	Has the received documents is having 'documents provided by stamp'?	4				

IMPORTANT INSTRUCTIONS TO SURVEYOR

1.	Please fill the above compliance checklist before moving for the survey.
2.	Please do not do the survey if you do not have proper documents.
3.	For Vacant Plot/ Land - Cizra Map/ Master/ Zonal/ Site Plan is must to identify the Plot. For Agriculture or converted land from agriculture - Mutation documents, CLU is must.
4.	Firstly please first study the documents of the property which needs to get surveyed.
5	Mark the Owner/ Area/ Boundaries mentioned in the ownership documents with bold florescent marker pen before moving for the survey. During site survey if any difference is found in the above fields from the ownership documents then please contact the owner immediately to know the reason for the difference.
6.	Confirm ongoing property rates in the subject location through public domain, property sites and contact dealers to show you the available properties in that area during your survey.
7.	Identify the Property clearly by matching the boundaries and area mentioned in the property papers.
8.	Do sample physical or google measurements of the property.
9,	PHOTOGRAPH INSTRUCTIONS: a. Take owner/ representative photograph along with the property. b. Take your selfie along with the property and the owner/ representative. c. Take full scale photo of the property with gate. d. Take photo of the property along with abutting road, towards left, right and center. e. Take multiple photos of inside-out of the property. f. Take nearby photographs of the Property. g. Take a short video to cover property and neighborhood.
10.	Take Google Map location.
11.	Check main road name & width and approach road width and distance of property from main road.
12.	Uneck Jurisdiction Municipal Limits & Ward Name
13.	Fill each column of survey form diligently in detail and tick the appropriate antice along
14	where dry defects of negativity in the property and comment in detail as a second
15.	DU EXITIEST THE INTERIOR AND CONTINUE FOR ANY FOCUNT ASSAULT
16.	In case customer appears to be providing misleading information to you or trying to influence you by money or cash then immediately report to the Management & Bank.

GRADE	SURVEY GRADING MATRIX
A	An case all the points below are done properly, timely with full care and diligence. 1. Survey started with appropriate timely with full care and diligence.
	Survey started with proper work order and knowing the source of payment. Done complete.
	before moving for the survey. Chosen correct survey form as per the property type.
	b. All site special observations properly filled.
	to Fruitality rathe inflammatica
	9. Site rough shatch area properly taken, mentioned and verified.
	10. Proper photographs takes
	11. Selfie with property taken. 12. Selfie and owner photographs.
B	12. Selfie and owner photograph with property taken. In case of 3 minor mistakes in any of the above points except Point 1, 2, 3, 4, 6, 8, 10, 11, 12 but all the
	points are covered. Point are above points except Point 1, 2, 3, 4, 6, 8, 10, 11, 12 but all the
C	10 Case of more than 3 minus minus minus
D	are completely missing except Point 1, 2, 3, 4, 6, 8, 10, 11, 12.
-	
	In case of more than 1 major mistakes or missing of more than 1 point out of 1, 2, 3, 4, 6, 8, 10, 11, 12.

Note (Survey Grading Matrix):

- 1. For special assignments like LIE, Stock Valuation, etc. where till date survey format is not specified or released, in such cases point wise site observation report has to be submitted by the Surveyor duly signing it properly. Without signed Site Observation report, Point 4 will be considered as not done and will fall under Category E.
- 2. Similar Grading Matrix is issued for Case Collection & Report Preparation as well.

Note (Overall Grading Matrix):

1. In case client reports any careless mistake in the report for which revision has to be done in the report then in that case Grading Matrix may be revised and Grade E will be awarded.

	SURVEY PROCESS COMPLIANCE CHECKLIST	
	(To be submitted by Surveyor with each Survey)	
S.NO.	COMPLIANCE CHECKLIST POINTS	STATU
1	Did you take proper property documents to carry out the survey?	u
2	Have you properly studied & highlighted Owner/ Area/ Boundaries in the properly documents with bold florescent before moving for the survey?	y ·
3.	Did you check prominent landmark nearby the subject property and mentioned in the survey form?	1
4	Did you identified the Property clearly by matching the boundaries and area mentioned in the property papers?	
5.	Did you check if property is merged with any other property or it is an independent property?	
6.	Did you do sample physical or google measurements of the property in case of property more than 2500 sq.mtr?	2
7.	Did you check for any building violations in the property?	1
8.	Did you check municipal limits/ jurisdiction/ ward?	NANGON N
9.	Did you take Google Map location and shared it to Maps whatsapp group?	
10.	Did you check Main road name & width and its distance from the subject property?	2
11.	Did you check approach Lane width on which property is located?	
12.	Have you taken property full scale photograph with gate?	
13.	Have you taken owner/ representative photograph with the property?	-0
14.	Have you taken your selfie with the property along with owner/ representative?	1
15.	Have you taken photograph of the property along with abutting road and towards left and right of the property?	
16.	Have you taken multiple photographs of the property from inside-out?	6
17	Did you check nearby development and whereabouts and commented on survey form?	7
18.	Did you check any defects or negativity in the property in terms of location, legality, disputes marketability, salability, etc. and commented on survey form in detail?	
19.	Have you filled all the columns of survey form including survey summary sneet properly?	8
20.	Did you draw site key plan (location map)?	
21.	Did you draw rough site sketch plan?	-
22.	Have you taken self-attested documents from owner/ representative and stamped	7
23.	Did you check any defects or negativity in the property in terms of location, legality,	
24.	Have you confirmed any recent past transactions during market enquiries and	
25.	Did you take signatures of the owner/ representative on undertaking and survey summary sheet?	1
26.	Did you signed the undertaking?	1

For File No.	VIS(2022-23)-PL096-081-134
Surveyor Name	Deepale
Signature	Dahi
Date	- 20 S 22

GENERAL SURVEY FORM (FOR PROPERTIES OTHER THAN FLATS)

(Version 5.0)

Date of implementation: 9.02.2011 | Last Revision: 04.01.2018 | Latest Revision: 31.10.2020

File No. RKA/DNCR/.../ Date: 20 5 22 Time:

	Name of the Surveyor	GENERAL DETAILS					
		Deepak					
2.	Property shown by	Owner, Representative, N	o one was available. Property is				
		locked, survey could not be done from					
		Name	Contact No.				
		Cimia Mantas. D. Pott					
3.	Survey Type	Fix survey (inside-out with measurements & photographs)					
		☐ Half Survey (Measurements from					
		Only photographs taken (No measurements)					
4.	Reason for Half survey or only	☐ Property was locked, ☐ Poss					
	photographs taken	property, NPA property so couldr					
5	How Property is Identified		mentioned in the deed, D From				
		name plate displayed on the proj	perty. Transfer by the owner				
		owner representative, Enquired f	rom nearby people,				
		☐ Identification of the property cou	ld not be done, Survey was not				
		done					
6.	Type of Property	☐ Flat in Multistoried Apartment, ☐					
		Apartment, Residential Builder					
		Building, Commercial Office,					
		Floor, Shopping Mall, Hotel, Industrial, Institutional,					
		☐ School Building, ☐ Vacant Residential Plot, ☐ Vacant Industrial					
-	Descript Management	Plot, ☐ Agricultural Land Self-measured, ☐ Sample meas	unment only [] No many translation				
7.	Property Measurement Reason for no measurement	☐ It's a flat in multi storey building s					
8.	Reason for no measurement	☐ Property was locked. ☐ Owner/					
		☐ NPA property so didn't enter the					
		practically not possible to measu	re the entire area . Any other				
		Reason:					
	Purpose of Valuation	☐ Value assessment of the asset for	or creating new collateral mortgage				
		Periodic Re-Valuation for Bank, I					
		☐ For DRT Recovery purpose, ☐ C					
		☐ Partition purpose, ☐ General Val					
35	Type of Loan	Housing Loan, D Housing Take	Over Loan, Home Improvement				
		Loan. D Loan against Property, D					
		Loan, Car Loan, Project Loan	an, Term Loan, CC Limit				
		enhancement Cash Credit Limit.	☐ Industrial Loan. ☐ NA				
1	Lean Amount						


10	KIND OF THE REAL PROPERTY.	OWNERSHIP DETAILS
	Legal Owner Name/s	Hr. Cinita Mankan. D. Patel
2.	Property Purchaser Name	Hilly Over
3.	Property Address under Valuation	ROOKER, Dist Houses
4.	Present Residence Address of the Owner/ Purchaser	KOUNSE) Dist Tradeway
5.	Property constitution	☐ Free Hold, ☐ Lease Hold

	LOCATION DETAILS North South							
1	Adjoining Properties	East		West		North		1
	(Match it with papers with the help	Others		BHALL	ROS	A	to	pd
	of compass or Sun direction and	Amp		000	20	Pt 1	20	4
	also confirm it with nearby people)	prof		Pig		1		g/ pinn
2.	Property Facing	☐ East Fa	cing LD-No	rth Facing	□ West F	acing, So	utn ra	Ciriy.
		□ North-E	ast Facing,	☐ South-	West Facir	g. South-	East F	acing.
		□ North-W	□ North-West Facing					
3.	Landmark	Vear	Salom	DUT (have		3980	
4.	Ward Name/ No.	NA	100					
5.	Zone Name	MA			1000			
6.	Main Road Name & Width	Na	ime	1	Width	Distance		property
		Salom	DIN RO	90	looft	1 3	50M	200
7.	Approach Road Name & Width	1/11/20	P Dan	T 201	+ /200	10		
8.	Location consideration of the					developed		
	Society	developing	area, 🗆 Hi	ghly posh	locality.	Very Good	1600	d.
		☐ Ordinary	☐ In inte	riors, 🗆 R	emote are	a, 🗆 Backwa	rd, 🗆	Average.
		□ Poor						
	- Use associated		cina 🗆 Po	ol Facing	☐ Road	Facing, D 8	Entranc	e North-
9.	Special Location consideration							
	of the property	East Facing						
10.	Characteristics of the locality	☐ Urban de	eveloped,	Urban de	veloping	Semi Urba	n, L F	dural,
		□ Backward	i, 🗆 Industr	ial, 🗆 Inst	itutional			
-	Category of Society/ locality	☐ High End	I. D. Norma	. Afford	lable Grou	p Housing, [EWS	. HIG.
110	Category or occasi,	MIG. DI						
12.	Utilities/ Facilities in the locality					mming Pool,		
		☐ Club House, ☐ Walk Trails, ☐ Kids play zone, ☐ 100% Power						
		Backup	112-1	34-2-1	Make	Delham Ct	Non I	Almand
13.	Proximity to civic amenities	School	Hospital	Market	Metro	Railway Sta	SHOTI	Airport
		500M	1/am	SIM	-	-	100	5
14	Any new development in		No					
	surrounding area		100	,				

	Jurisdiction limits	□ Nagar Nigam, □ Nagar Panchayat, □ Gram Panchayat, □ Naga				
4		Palika Parishad, ☐ Area not within any municipal limits				
	Jurisdiction Development	□ DDA, □ GDA, □ NOIDA, □ GNIDA, □ YEIDA, □ HUDA, □KMDA				
P	Authority Name	□ MDDA, □ Any other Development Authority: WPDA				
		☐ Area not within any development authority limits				
	Municipal Corporation Name	□ NDMC, □ SDMC, □ EDMC, □ Ghaziabad Municipal Corporation				
		☐ Gurgaon Municipal Corporation, ☐ Faridabad Municipal Corporation				
		☐ Kolkata Municipal Corporation, ☐ Dehradun Municipal Corporation.☐ Area not within any municipal limits, ☐ Any other Municipal				
		Corporation/ Municipality:				
		Corporation withicipality.				
	Land Area	PHYSICAL DETAILS				
	Land Area	As per Title deed As per Map As per site survey				
		1800 5917				
	Any conversion to the land use	20'X 90'				
	Land Type	Profit Dealer Dealer Dealers Land Dealers Land Dealers				
		Solid, Rocky, Marsh Land, Reclaimed Land, Water logged, Land locked				
	Shape of the Land	☐ Square, ☐ Rectangular, ☐ Trapezium, ☐ Triangular, ☐ Trapezoid,				
		☐ Irregular, ☐ NA				
5.	Level of Land	☐ On road level, ☐ Below road level, ☐ Above road level, ☐ NA				
3.	Frontage to depth ratio	Normal frontage, ☐ Less frontage, ☐ Large frontage, ☐ NA				
	Are Boundaries matched	Yes, No, No relevant papers available to match the				
		boundaries, Boundaries not mentioned in available documents				
3.	Is Independent access available					
	to the property	sharing of other adjoining property, No clear access is available,				
		☐ Access is closed due to dispute				
9.	Is property clearly demarcated	Yes, □ No, □ Only with Temporary boundaries				
10.	with permanent boundaries? Is the property merged or					
	colluded with any other propert					
		Owner, U Vacant, Lessee, Under Construction, Couldn't				
	time of survey	be Surveyed. ☐ Property was locked, ☐ Bank sealed, ☐ Court sealed				
12	Current activity carried out in the Residential purpose, Commercial purpose,					
	property	☐ Office, ☐ Industrial, ☐ Vacant, ☐ Locked, ☐ Any other use:				
	CONTRACTOR OF STREET					
	BUILDI	NG/ CONSTRUCTION/ UTLITY DETAILS				

Crick one on the basis of which valuation is to be calculated As per Title deed As per Map As per site survey valuation is to be calculated Both	1	Covered Built-up Area	Too				
valuation is to be calculated)	1		Covered Area, Floor Area, Super Area, Carpet Area				
Total Number of Floors in the Building Cover on which property is situated Bight		(Tick one on the basis of which valuation is to be calculated)		As per Map			
Section Suliding	3.	Total Number of Floors in the			1000 397+		
Type of Unit/ Number of Rooms/		Building	44				
Type of Unit/ Number of Rooms/ Carbins/ Cubicles Cabins/ Cubicles	4.	Floor on which property is situated	Roth				
RCC Framed Structure, Load bearing Pillar Beam column	5.	Type of Unit/ Number of Rooms/					
Roof Grante Condition Condition Roof Ro	6.		40000M	211-40	us' i		
Age of Building Average Below average Under construction No Survey		L	RCC Framed Stru	cture, Load bearing	g Pillar Beam column		
Age of Building Average Below average Under construction No Survey			Ordinary brick wall	structure, Iron trus	ses & Pillars, Scrap		
a. Make: RBC_ RCC, Gl Shed, Tin Shed, Stone Patls b. Height: Simple plaster, POP Punning, POP False Ceiling, Coved roof, No plaster	7	Roof					
B. Height: Simple plaster. POP Punning. POP False Ceiling. Coved roof. No plaster. POP Punning. POP False Ceiling. Coved roof. No plaster. POP Punning. POP False Ceiling. Coved roof. No plaster. Marble. Marble. Marble. Marble. Marble. Marble. Marble. Marble. Marble. Pop.		1,001		RCC, G GI Shed, I	☐ Tin Shed, ☐ Stone		
c. Finish: Simple plaster, POP Punning, POP False Ceiling, Coved roof, No plaster Semple marble, Coved roof, No plaster Coved roof, No plaste							
Received the service of the servic			D. Height: 10 /				
Vitrified titles, Ceramic Titles, Simple marble, Marble chips, Mosaic, Granite, Italian Marble, Rota stone, Wooden, PCC, Imported Marble, Pavers, Chequered Tiles, Brick Tiles, No Flooring, Under construction, Any other type.					nning, POP False		
Virtiled tiles, Ceramic Tiles Simple marble, Marble chips, Mosaic, Granite, Italian Marble, Kota stone. Wooden, PCC, Imported Marble, Rovers, Chequered Tiles, Brick Tiles, No Flooring, Under construction, Any other type; Internal Excellent, Very Good, Good, Ordinary, Average, Poor Under construction, No Survey External Excellent, Very Good, Good, Ordinary, Average, Poor Under construction No Survey External Excellent, Very Good, Good, Ordinary, Average, Poor Under construction Ordinary, Average, Poor Under construction Ordinary, Average, Below average, Under construction, No Survey Simple plastered walls, Brick walls without plaster, Designer textured walls, POP punning, Coved roof, Under construction, No Survey Simple plastered walls, Brick walls without plaster, Designer textured walls, Brick tile Cladding, Structural glazing, Aluminum composite panel cladding, Glass façade, Domb, Porch, Under construction No Survey Destarral, High end Modular with chimney, Under construction, No Survey Destarral, Internal Destarral, Destarral, Internal Des	8	Flooring					
Wooden, PCC, Imported Marble, Pavers, Chequered Tiles, Brick Tiles, No Flooring, Under construction, Any other type:		, looning	☐ Vitrified tiles, ☐ C	eramic Tiles, Simp	ole marble, Marble		
Tilles,							
Suilding							
Appearance/ Condition of the Building			other type:				
Building Average, Poor Under construction, No Survey External Excellent, Very Good, Good, Ordinary, Average, Poor Under construction Ordinary, Average, Poor, Under construction Interior decoration Excellent, Very Good, Good, Simple, Ordinary, Average, Below average, Under construction, No Survey I2. Interior Finishing Simple plastered walls, Brick walls without plaster, Designer textured walls, POP punning, Coved roof, Under construction, No Survey I3. Exterior Finishing Simple plastered walls, Brick walls without plaster, Architecturally designed or elevated, Brick tile Cladding, Structural glazing, Aluminum composite panel cladding, Structural glazing, Aluminum composite panel cladding, Simple with no cupboard, Ordinary with cupboard, Normal Modular with chimney, High end Modular with chimney, Under construction, No Survey I5. Class of Electrical fittings External, Internal Ordinary fixtures & fittings, Fancy lights, Chandellers, Concealed lightning, Under construction, No Survey I6. Class of Sanitary/ Plumbing & External, Internal Excellent, Very Good, Good, Simple, Average, Below average, Under construction, No Survey I7. Water arrangements Jet pump, Submersible, Jet board supply Excellent, Very Good, Good, Simple, Ordinary, Average, Below Average, No wooden work, No survey I9. Age of Building/ Recent Improvements done	9.	Appearance/ Condition of the	Control of the Contro	nt, Very Good,	Good. Ordinary		
External - Excellent, Very Good, Good, Ordinary, Average, Poor Under construction		Building					
Average, Poor Under construction							
Interior decoration							
Average, Below average, Under construction, No Survey	10.	Maintenance of the Building	☐ Very Good, ☐ Avera	ige, 🗆 Poor, 🗆 Under	construction		
12. Interior Finishing	11.	Interior decoration					
Designer textured walls, DPOP punning, Coved roof, Under construction, No Survey 13. Exterior Finishing Simple plastered walls, Brick walls without plaster, Architecturally designed or elevated, Brick tile Cladding, Structural glazing, Aluminum composite panel cladding, Glass façade, Domb, Porch, Under construction Simple with no cupboard, Ordinary with cupboard, Normal Modular with chimney, High end Modular with chimney, Under construction, No Survey 15. Class of Electrical fittings External, Internal Ordinary fixtures & fittings, Fancy lights, Chandellers, Concealed lightning, Under construction, No Survey 16. Class of Sanitary/ Plumbing & External, Internal Excellent, Very Good, Good, Simple, Average, Below average, Under construction, No Survey 17. Water arrangements Jet pump, Submersible, Alaboard supply 18. Fixed Wooden Work Excellent, Very Good, Good, Simple, Ordinary, Average, Below Average, No wooden work, No survey 19. Age of Building/ Recent Royal Below Average, No wooden work, No survey 19. Age of Building/ Recent Royal Below Average, No wooden work, No survey 19. Age of Building/ Recent Royal Below Average, No wooden work, No survey 19. Age of Building/ Recent Royal Below Average, No wooden work, No survey 19. Age of Building/ Recent Royal Below Average, No wooden work, No survey 19. Age of Building/ Recent Royal Below Average, No wooden work, No survey 19. Age of Building/ Recent Royal Below Average, No wooden work Royal Below Average							
Under construction,	12.	Interior Finishing					
Simple plastered walls, Brick walls without plaster. Architecturally designed or elevated, Brick tile Cladding, Structural glazing, Aluminum composite panel cladding, Glass façade, Domb, Porch, Under construction	1			The state of the s	J Coved roof,		
Architecturally designed or elevated,			The second secon				
Structural glazing, Aluminum composite panel cladding, Glass façade, Domb, Porch, Under construction	13.	Exterior Finishing					
Glass façade, Domb, Porch, Under construction 14. Kitchen Simple with no cupboard, Ordinary with cupboard, Normal Modular with chimney, High end Modular with chimney, Under construction, No Survey No Survey			Architecturally desi	gned or elevated,	Brick tile Cladding,		
Simple with no cupboard,							
Modular with chimney, High end Modular with chimney, Under construction, No Survey	4.4	Vitchen					
Class of Electrical fittings	14.	Kitchen	Modular with chimney	High end Modular v	ith chimney Under		
Class of Electrical fittings					nti criminey, 🗆 Onder		
Ordinary fixtures & fittings, ☐ Fancy lights, ☐ Chandeliers, ☐ Concealed lightning, ☐ Under construction, ☐ No Survey 16. Class of Sanitary/ Plumbing & ☐ External, ☐ Jaternal ☐ water supply fittings ☐ Excellent, ☐ Very Good, ☐ Good, ☐ Simple, ☐ Average, ☐ Below average, ☐ Under construction, ☐ No Survey 17. Water arrangements ☐ Jet pump, ☐ Submersible, ☐ Jail board supply 18. Fixed Wooden Work ☐ Excellent, ☐ Very Good, ☐ Good, ☐ Simple, ☐ Ordinary, ☐ Average, ☐ Below Average, ☐ No wooden work, ☐ No survey 19. Age of Building/ Recent ☐ Improvements done	15	Class of Electrical fittings					
Class of Sanitary/ Plumbing &	10.			fittings. Fancy liv	ohts. Chandeliers		
16. Class of Sanitary/ Plumbing & □ External, □ Internal □ Excellent, □ Very Good, □ Good, □ Simple, □ Average, □ Below average, □ Under construction, □ No Survey 17. Water arrangements □ Jet pump, □ Submersible, □ dal board supply 18. Fixed Wooden Work □ Excellent, □ Very Good, □ Good, □ Simple, □ Ordinary, □ Average, □ Below Average, □ No wooden work, □ No survey 19. Age of Building/ Recent □ Market □ Plant Pla			☐ Concealed lightning.	☐ Under construction	☐ No Survey		
Below average, □ Under construction, □ No Survey	16.	Class of Sanitary/ Plumbing &					
17 Water arrangements ☐ Jet pump, ☐ Submersible, ☐ dal board supply 18 Fixed Wooden Work ☐ Excellent, ☐ Very Good, ☐ Good, ☐ Simple, ☐ Ordinary. ☐ Average, ☐ Below Average, ☐ No wooden work, ☐ No survey 19 Age of Building/ Recent ☐ Description of the pump, ☐ Submersible, ☐ dal board supply ☐ Ordinary. ☐ Average, ☐ Below Average, ☐ No wooden work, ☐ No survey 19 Age of Building/ Recent ☐ Description of the pump, ☐ Submersible, ☐ dal board supply ☐ Ordinary. ☐ Average, ☐ Below Average, ☐ No wooden work, ☐ No survey 19 Age of Building/ Recent ☐ Description of the pump, ☐ Submersible, ☐ dal board supply ☐ Ordinary. ☐ Average, ☐ Below Average, ☐ No wooden work, ☐ No survey 19 Age of Building/ Recent ☐ Description of the pump, ☐ Submersible, ☐ dal board supply ☐ Ordinary. ☐ Average, ☐ Below Average, ☐ No wooden work, ☐ No survey 19 Age of Building/ Recent ☐ Description of the pump ☐ Description ☐ D		water supply fittings	☐ Excellent, ☐ Very Go	ood, Good, Simpl	e, Average,		
18. Fixed Wooden Work ☐ Excellent. ☐ Very Good, ☐ Good, ☐ Simple, ☐ Ordinary. ☐ Average, ☐ Below Average, ☐ No wooden work, ☐ No survey 19. Age of Building/ Recent Improvements done ☐ 2017— ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐			☐ Below average, ☐ U	nder construction, N	lo Survey		
Average, ☐ Below Average, ☐ No wooden work, ☐ No survey 19. Age of Building/ Recent Improvements done	17.	Water arrangements					
19. Age of Building/ Recent 2017	18.	Fixed Wooden Work	☐ Excellent, ☐ Very	Good, Good,	Simple, Ordinary,		
Improvements done			☐ Average, ☐ Below A	verage, No wooden	work, No survey		
	19.		7017				
40 I Waintellance of the building Li very Good Lanverage, Li Poor	20.	Maintenance of the Building	☐ Very GoodL□ Average	ge, 🗆 Poor			

B	Any defects in the building	☐ Maintenance issues, ☐ Finishing issues, ☐ Seepage issues,☐ Water supply issues, ☐ Electricity issues, ☐ Structural issues,☐ Visible cracks in the building				
22	Any violation done in the property ND	☐ Construction done without approved Map, ☐ Extra covered adjacent property, ☐ Encroache	d without sanctioned Ma	ip. L. Joines		
23.	Boundary Wall (Only for individual	☐ Yes, ☐ No, ☐ Common bout	ndary wall of a complex			
	property) No	Running Mtr. Height	Width	Finish		
24.	Lift/ elevators					
	200 000000	☐ Passenger/ ☐ Commercial Make:	Capacity:			
25.	Power backup	☐ Inverter, ☐ DG Set		100000000000000000000000000000000000000		
		Make:	Capacity:			
26.	Garden/ Landscaping	☐ Yes. ☐ No. ☐ Beautiful, ☐ C	ordinary			
27.	Parking facilities	☐ Available within the property	☐ On Ground, ☐ In Basema			
	Special Comments/ Observations,	☐ Not available within the property	☐ On road, ☐ Acc problem	ute parking		
	if any MARKETARI	LITY/ SELABILITY/ UTLITY DI	ETAILS			
1.	Any issues in marketability of the property?	Reason in case of No: Location, Surrounding, Legal aspects, Demand, Shape, Any Other:				
2.	How is Demand & Supply condition	Demand Very Good & Good, Average, Low, Poor				
1	in the Market of such properties?		od, Average, Low,			
3.	Is property easily sellable &	☐Yes, ☐ No		TO STATE OF		
	marketable?	Comments:				
4.	How is the current utility of the property?	☐ Excellent, ☐ Very GoodL☐+		w, 🗆 Poor		
4.	property?	☐ Excellent, ☐ Very Good! ☐ (w, 🗆 Poor		
			300d, Average, DLo 3015 5 Lakh	w, 🗆 Poor		



Page 12 of 15

	PROPERTY I	MARKET COM	PARABLE RATE IN	FORMATION DETAIL	LS
S.No	Particulars	Subject	Transaction already h Comparable 1	Comparable 2	Comparable 3
1	Name (source of information)	Property	Roshe Roshe Dry	P lista Chow	9
2	Contact No.	NA		9997444400	1
3.	Type of source of information (Sellari Property dealer nearby	NA	9412074363		
4	People) Rates/ Price informed	NA	Dealer	Deals	
	(in Rs. with unit)	NA	1800-2000/	1500 - 1800 S941	
5.	Rates Type (Sale/Buy)	NA	Sali	Sel	
6	Shape of the Property (Square, Rectangular, Irregular)		Rectargular		
7.	Area/ Size of the Property		1800 SIH	Rectargular 250059 PL	
8.	Legal Status (clear, negative, weak)/ No. of owners		clear	Clean	
9.	Location/ surrounding/ neighborhood comparison with the subject property (Similar, Lower, Better, Highly Better than the subject Property)	Base Case	Smilar	Graffar	
10.	Distance from the subject Property	0	300M	IM	
11.	Other factors (Corner, 2 side open, North-East facing, Park facing, Legal/ Financial encumbrance, etc.)		NOAH	Suth	
12.	Approach road width		goft	20A	
13.	Level of Land (Below/ On/ Above road level)		mand	on load	
14.	Frontage to depth ratio (Normal, Less, Large)		Klosmal		
15	Present Use		Residential	Residential	
16.	Any other details/ Discussion held	NA	Had gwod		hat at
			Jalem pur	Mehdood is	abbrax
			100-001		11.
17	Present expected Sale Value of the overall property?		-		

UNDERTAKING BY THE CUSTOMER

I confirm that I have made the inspection of the subject property to the surveyor of R.K Associates, which is correct property in question for which the documents have been provided/ submitted by me. I further confirm that I am aware of all the information related to the subject property and I have provided all its information to the surveyor true to the best of my knowledge. I understand that any false or manipulative information provided by me will be considered as cheating with the professional organization since it will lead to incorrect valuation report and I'd be solely responsible for this unlawful act and will bear the charges for the changes/modifications which have to undergo due to the false information. I also undertake that I have not given any cash or in kind to any member of R.K Associates to influence the Value of the Property or favor any individual or organization and the same is not accepted or asked by the member of R.K Associates. Any such act will lead to cancellation of the material prepared by R.K Associates with forfeiting of the fees and I'll be completely responsible for its repercussions and legal actions taken for it.

IMPORTANT: We have not authorized any of our person/ Surveyor to take Cash or kind from the customers in any situation. In case Surveyor or any member of R.K Associates asks for any money or kind from you then kindly please inform on number +91-9958632707, 0120-4110117. Our Valuation process is very stringent and have multiple check points to ensure correct & error free reports to keep the lending agency risk free. In case Surveyor claims that he would be able to arbitrary effect the Valuation figures unfairly or as per your requirement & need, then he is making a false claim to you and we request you to complaint such act immediately on the number provided above.

Name	Coirige Shandow D Partel
Relationship with owner	Snot
Signature	Pos Petch
Mobile No.	8958621298
Date	20/5/22

UNDERTAKING BY THE SURVEYOR

I confirm that I have carried out the Survey of the property property as per the fair professional best practices and Valuation & Survey policy guidelines issued by R.K. Associates. I have not taken any cash or kind from the customer nor have I come into any kind of influence of the customer / bank for arbitrary providing the Property Valuation as per one's need. I further state that I have not given any assurances to the customer nor given any wrong or false information or statement. In case at any point of time it is found that I have done any kind of fraudulent activity in this case and misled the company then I understand its legal consequences and appropriate penal action which company can take against me. Also in regard to it any monetary or reputation loss will be recovered from me by the company.

For File No.			
Surveyor Name	Davas	-1.	
Signature	Dooper	Hill	
Date	20/07	130VI	100