VALUATION REPORT FOR CHOLAMANDALAM INVESTMENT AND FINANCE CO.LTD.

STANDARD VALUATION REPORT Valuation is as per permissible area as per prevailing by e laws

	f No. : - AG/ CHIFCL/12/-2021/S	S							
A	GENERAL DETAILS								
1	APPLICATION NO.	X0HEEDL0000156	3721 & YO	UED	UE000040000				
			X0HEEDL00001563721 & X0HEDHE00001306266 DEL 2						
2	Name of the Coat								
	. Name of the Customer(s) Name of document holder	Mr. Vinod Kumar	Jain						
	rame of document holder	Mr. Abhishek Jain			Per	son met at	site: - Not		
3.	Property Address	A - 51 -			Inst	ected	2116 MOI		
	- Forty Fluid Coss	Property No. 995/229, New No IX /2292, Gali No.11 & 12, Kailash Nagar, Gandhi Nagar, Shahdara ,New Delhi - 110031. Legal Address of the property: (Postal) – if different :- House No-IX/2292, Gali No- 11 & 12, Kailash Nagar, Gandhi Nagar, Delhi On Inspection:- House No-IX/2292, Gali No- 11 & 12, Kailash Nagar, Gandhi Nagar, Delhi							
	Customan	Address of the Electricity Bill:- NA							
1	Customer name in Electricity E Landmark	Bill NA		_	K. no NA				
_	Firing date	Near Jain Mandir			IVA IVA				
	Loan Application Number/	22/12/2021							
٠.	MIS No.	By mail							
2.	Ward No/ Municipal land No Vicinity	House No-IX/2292 Residential							
_	Гуре	Middle Class							
4. F	Proximity to Civic Amenities	Nearest Railwa	av Station		0.17				
		Nearest Bus S	ay Station	:-	3 Km				
		Nearest Hospit	ω		900 M				
. (Condition of approach road	Average	aı	:-	2 Km				
i. F	Plot demarked at site	Yes							
. P	Property identified through	1.	marasti -	/ B #					
P	ROPERTY DETAILS	Name board / Site de	amarcation	/ Ne	ıgnbor's Enqui	У			
. [ype of Property	Not Inspected		_					
91	ype of Usage of entire property	Not Inspected							
A	ccommodation Detail	Not Inspected							
	dditional Amenities	NA							
S	UBJECT PROPERTY DETAILS			_					
	ype of Premises	Residential							
0	ccupied by	Not Inspected							
_		relative, state relationship with the applicant: NA							
-		Is property rented: NA							
	Boundary details								
-	As per document	East	Wes	st	North		South		

E STRUCTUR	As per site AL DETAILS	Gali		Gali	Part of Po	rtion Others				
1. Type of Strue	cture				- urt of Fo	ortion Other Prope				
2. No. of Floors	RCC & Load bearing wall									
3. No. of Wings		G+3	G+3							
4. No. of flats of	2 Aach flaar	1								
5. No. of lifts in	ooch win-	NA								
6. Age of the Pr	each wing	NA								
7. Estimated Fu	turo Life	25 year								
Quality of Co		35year								
	nstruction									
A Exteriors										
1. Beam & Colu	RCC & Load bearing wall									
2. Appearance of	f Building	Average								
3. Maintenance	of the Building	Average								
4. Common Area	as Remarks	Reception	1.	NA						
		Staircase		Yes						
				res						
		O/h water tank	:	Yes						
B Interior		Sanitation:- conn	ected	d to public sev	/er					
5. Flooring		Sanitation:- connected to public sewer								
6. Finishing		Not Inspected								
		Not Inspected								
7. Roofing and te 8. No. Of lifts	rracing	Not Inspected								
		NA								
Construction as sanctioned plan	าร	Sanction plan is not available								
F UNIT DETAILS										
1. Situated on floo	r No	Not Inspected	Not Inspected							
Internal Compo	sition	Not Inspected	Not Inspected							
3. Flooring		Not Inspected								
4. Quality of fitting	S	Not Inspected								
5. Woodwork										
VALUATION		Not Inspected								
Plot Area (sq. yo	1/	400								
Total Built up ar	22 (permissible	100 sq yd								
area)	ed (herringstbl6	2430 sq ft								
Total Constructe	d area	2220 - 4								
or Number		3320 sq ft								
rmissible area	Basement	Ground Floor		First Floor	Second Floor	Thind FI				
		810 sq ft		810 sq ft	810 sq ft	Third Floor				
nstructed Area		900 sq ft		932 sq ft		4				
Current Governn Rates		NA		002 34 IL	948 sq ft	540 sq ft				
Current Market Rate		Rs.1,30,000/- to Rs.1,40,000/- per sq yd								
Recommended F	13. 1,35,000/- per si	Rs.1,35,000/- per sq yd								
Basis for Recomm	Based on enquiries made from reliable market sources									
Final Valuation		100 and 10 Paris 10 P								
		100 sq yd @ Rs.1,3	5,000	0/- per sq yd	= Rs.1,35,	00.000/-				
	2430 sq ft @ Rs.600 TOTAL MKT VALUE)/- no	r sq ft	= Rs. 14,	58,000/-					
	- D- 4 40 FD									
	LOTIMATED VALUE OF ENTIRE PROPERTY.									
	13.1,49,30,000/- (Approx)									
Valuation		(Rs. ONE CRORE FORTY NINE LAC FIFTY THOUSAND ONLY)								
i) Not Inspected										
	Rs.1,49,50,000/- (Ap	prox)							
ii) Rented Resider	tial									

	iii) Vacant Residential							
-	iv) Rental Commercial							
L	Insurance value/ construction cost (compulsory)	Rs. 1	4,58,000/-					
	Brief description of property	Prope 100 se	erty is built g yd, the ac	up with grou tual covered	ınd, first, secon I area is 3320 se	d & third floor on a plot are g ft & permissible area is 20.		
	H Remarks	Subje	the road in	front of hou	se is about 20'.	permissible area is 20		
	Other Remarks-if applicable	E- W	ioia, thus v	om outside as instructed by n & approximation.				
		Repor		erties Patwa	Required/Not Required			
	Property Ownership as per papers	Electri	city bill/nan	Yes/No				
	Type of document provided- Sale deed/GPA/ANY Other	materi	ing as per s ancy level	%				
	The state of Alvi Other				70			
	Property Owners I:	Surrou	nding deve	4000/				
	Property Ownership as per papers	Freeho	ld/leaseho	100%				
		Proper	ty dealer de					
		Buildin	g Height &	Building ht-				
	Sito Dimonata Di Li	East	14/0.04	1.1	Floor Ht-			
		2.432	West	<u>North</u>	South			
		Deviation	n in terms	of 9/ n==				
	This property as per demolition list of MCD from 2001 to 2021	No	terms	vi %age	(Low /Medium/High)			
	Distrose Value (750)							
Î	Moline -	Rs.1,12,18,500/- 83.6 sq m @ Rs.56,640/- per sq m = Rs.47,35,104/- 188 sq m @ Rs.8220/- per sq m = Rs.15.45,360/-						
	Circle rate							
	Declaration	TOTAL \	OTAL VALUE AS DED CIDAL = 5					
-	eby declare that:				MAIL =	Rs.62,80,464/-		

1. We have deputed my representative Mr. Satyam Singh to inspect the property. My representative has personally inspected the property on 23/12/2021

2. I have no direct or indirect interest in the property valued.

3. The information furnished in the report is true and correct to the best of my knowledge and belief.

4. The ownership papers/sale deeds may please be verified at your end to ascertain the right title & area

5. The fair market value indicated in the report is an opinion of the value prevailing on the date of the said report and is based on market feedback on values of similar properties. The client is free to obtain other independent opinions on the same. The fair, market value of such properties/localities may increase or decrease, depending on the future market conditions and scenarios. This report does not certify or confirm any ownership or title of the property that has been

6. Structural stability certificate from the owner should be taken.

7. Ownership, area and occupant's status may please be verified at your end.

8. The value considered in the report has not incorporated the effect on property values due to scrapping currency denomination, which will only be reflected in time to come. The value is based on information prior to this effect


Verifier's Name & Signature (Satyam Singh)

(AUTHORIZED SIGNATORY) Date: - 23/11/2021


Place: - Delhi


ANIL KUMAR


Digitally signed by ANIL KUMAR DN: cn=ANIL KUMAR, c=IN, st=Delhi, o=Personal, serialNumber=76f4c52f20398051b 008478f5828fb8ce5a598517f95137 871b9dab90d4d33ed Date: 2021.12.28 14:16:37 +05'30'



Latitude and Longitude :- 28.662685 & 77.261052







SITE DRAWING DIMENSION WITH BOUNDARIES	
THE STATES	