1P RES = ABA 38203290 - Collaboration of the series of the

IMMOVABLE PROPERTY (COMMERCIAL PREMISES)

OWNED BY MR. RAHUL KISHNAKUMAR KANODIA



SITUATED AT

UNIT NO.4, ON THE GROUND FLOOR IN THE BUILDING KNOWN AS "GUPTA BHAVAN" PREMISES CO-OP.SOC.LIMITED, PLOT NO. 64/B, IRON MARKET, 32/38, AHMEDABAD STREET, SANT TUKARAM ROAD, CARNAC BUNDER, MASJID BUNDER (EAST), MUMBAI

BY

A. V. SHETTY & ASSOCIATES

CHARTERED ENGINEERS & GOVT. REGISTERED VALUERS

PANEL VALUERS AND TECHNICAL APPRAISERS FOR BANKS, FINANCIAL INSTITUTIONS & INCOME TAX DEPT.

IBBI REGISTERED VALUERS UNDER THE INSOLVENCY AND BANKRUPTCY CODE 2016

a.v.shetty & associates

103, NAVIN ASHA, FIRST FLOOR, 126-A, DADASAHEB PHALKE ROAD, DADAR (E), MUMBAI - 400 014. E-MAIL ADDRESS: rtnaks@gmail.com 51178

Date: 18.05.2019

ANNEXURE - P


Ref. No. AVSA/OBC/26189A/2019

PROFORMA FOR VALUATION REPORT IN RESPECT OF IMMOVABLE PROPERTY

(Applicable in Borrowal accounts where aggregate credit limits are above 10.00 Lac OR anticipated value of immovable property to be mortgaged / charged is above 20.00 Lac)

Chapter: Introduction

S. No.	Content	Comments of Valuer
1.1	Name of Valuer	A. V. Shetty & Associates
1.2	Date of Valuation	17.05.2019
1.3	Purpose of Valuation	To assess the 'Fair Market Value' of the said property for the purpose of availing Bank Credit facilities from Oriental Bank of Commerce, Nariman Point Branch, Mumbai.
1.4	Name of Property Owner/s (Proposed purchasers)	Mr.Rahul Kishnakumar Kanodia
1.5	Name of Bank as applicable	Oriental Bank of Commerce, Nariman Point Branch, Mumbai.
1.6	Name of Developer/Transferors of the Property	



Physical	Characteristics	of the	Property
rnysical	Characteristics	or me	Lioberth

2.1		Unit No.4, on the Ground Floor In The Building Known As "Gupta Bhavan" Premises Co-Op.Soc.Limited, Plot No. 64/B, Iron Market, 32/38, Ahmedabad Street,Sant Tukaram Road, Carnac Bunder, Masjid Bunder (East), Mumbai
2.2	Municipal Ward No.	- L. Floor, "Granta Bhayan"
2.3	I OSIAL GUGLOSS OF CT. L. L.	Unit No.4, on the Ground Floor "Gupta Bhavan" Premises Co-Op.Soc.Limited, Plot No. 64/B, Iron Market, 32/38, Ahmedabad Street, Sant Tukaram Road, Carnac Bunder, Masjid Bunder (East), Mumbai
2.4	Area of the plot/land (supported by a	Records not available
	nlan)	Records not available
2.5	Layout plan of the layout in which the	A STATE OF THE STA
	property is located	32/38, Ahmedabad Street, Sant Tukaram Road,
2.6	Details of Roads abutting the asset	Carnac Bunder, Masjid Bunder (East), Mumbai
	C the egget under	Co-ordinate: 18°57'3.99"N & 72°50'22.26"E
2.7	Demarcation of the asset under valuation on a neighbourhood layout	
2.8	map Description of Adjoining properties	On or towards East: Unit Prakash On or towards West: Unit Gandhi & Co. On or Towards North: Units On or towards South: Ahmedabad street Road
	Survey no. if any	up M M
2.9	out to have	The state of the s
2.10	Details of the building/buildings and other improvements in terms of area, height, no. of floors, plinth area floor wise, year of construction, year of making alterations/additional constructions with details, full details of specifications to be appended along with building plans and elevations	Premises is provided with vitrified tiles flooring, Wooden frame door and safety gate & Aluminium frame glazed windows The Building is about 25-30 years old
	Plinth area, Carpet area and saleabl	e Unit No.4, on the Ground Floor 635sqf.Saleable
2.1	area to be mentioned separately an clarified	

Town Planning Parameters

3.1	Master plan provisions related to the property in terms of land use	Records not available
3.2	Planning area/zone	Records not available
3.3	Development controls	-
3.4	Zoning regulations	Records no available
3.5	FAR/FSI permitted and consumed	Permissible F.S.I – 1.33
3.6	Ground coverage	
3.7	Transferability of development rights if any, building bye-law provisions as applicable to the property viz. setbacks, height restrictions, etc.	N.A.
3.8	Comment on surrounding land uses and adjoining properties in terms of usage	Mixed area

3.9	Comment on unauthorized constructions if any	
3.10	Comment on demolition proceedings if any	-
3.11	Comment on compounding /regularisation proceedings	
3.12	Comment on whether OC has been issued or not	
3.13	Any other aspect	Nil



hetty & Associates

Legal Aspects of the Property

4.	Description of legal aspects to include:	450C/10 dt 1 4 2019 in
4.1	Ownership documents,	Society Maintenance Bill No.4506/19 dt.1.4.2019 in the Name of Mr.Rahul Kishanakumar Kanodia, for the month of April to June 2019 @ ₹ 23843/-
4.2	Names of Owner/s	Mr.Rahul Kishnakumar Kanodia
4.3	Title verification,	Record not available
4.4	Details of leases if any,	N.A
4.5	Ordinary status of freehold or leasehold including restrictions on transfer,	Free hold Land
4.6	Agreements of easements if any,	
4.7	Notification for acquisition if any,	
4.8	Notification for road widening if any,	
4.9	Heritage restrictions if any,	Society Maintenance Bill No.4506/19 dt.1.4.2019 in
4.10	All legal documents, receipts related to electricity, water tax, property tax and any other building taxes to be verified and copies as applicable to be enclosed with the report,	Society Maintenance Bill No.4336775 the Name of Mr.Rahul Kishanakumar Kanodia, for the month of April to June 2019 @ ₹ 23843/- Electricity Bill: BEST - Consumer No.329-441-002*9 Bill No.905329441002 dt.01.04.2019, in the Name of Mr.Kishanakumar Kanodia, for the month of May 2019, @ ₹ 4170/-
4.11	Comment on transferability of the property ownership,	'I-blo
4.12	Comment on existing mortgages / charges / encumbrances on the	Records not available
4.13	Comment on whether the owners of the property have issued any guarantee (personal or corporate)	77.17.
4.14	Duilding plan sanction, illega	
4.1	A ser other aspect.	



Retty Ass

Economic Aspects of the Property

5.1	Reasonable letting value	A.
5.2	Details of monthly rents payable	
5.3	Details of monthly rents being received, if any, including status of tenancy rights	N.A. (Owner occupied)
5.4	Taxes and other outgoings	
5.5	Property insurance	Society maintenance
5.6	Monthly maintenance charges	Society maintenance Charges is inclusive of all taxes other charges.
5.7	Security charges, etc.	
5.8	Any other aspect	

Socio-cultural Aspects of the Property

6.	Descriptive account of the location of the property in terms of the social structure of the area, population, social stratification, regional origin, age groups, economic levels, location of slums/squatter settlements nearby, etc.	



Functional and Utilitarian Aspects of the property

Description of the functionality and utility of the asset in terms of:	Commercial premises on Ground floor
Space allocation,	Commercial premises on Ground floor
Storage spaces,	As above
Utility of spaces provided within the building,	As above
Car parking facilities	
Balconies	
Any other aspect	
	utility of the asset in terms of: Space allocation, Storage spaces, Utility of spaces provided within the building, Car parking facilities Balconies

Infrastructure Availability

A) Description of aqua infrastructu	
Water supply	As per regulations of MCGM
	As per regulations of MCGM
	As per regulations of MCGM
Storm water drainage,	fractructure facilities viz.
B) Description of other physical in	
Solid waste management	As per regulations of MCGM
Electricity	Electricity Bill: BEST - Consumer No.329-441-002*9 Bill No.905329441002 dt.01.04.2019, in the Name of Mr.Kishanakumar Kanodia, for the month of May 2019 ② ₹ 4170/-
Roads and public transportation connectivity	Well connected by road & all types transport services available
Availability of other public utilities nearby	All public utility services available within 1km radius
C) Social infrastructure in terms of	
Schools	
Medical facilities	Available within 1km radius
Recreation facilities in terms of parks and open spaces	
	Water supply Sewerage/sanitation Storm water drainage, B) Description of other physical In Solid waste management Electricity Roads and public transportation connectivity Availability of other public utilities nearby C) Social infrastructure in terms of Schools Medical facilities Recreation facilities in terms of

Marketability of the Property

9.	Analysis of the market for the property in terms of	
9.1	Locational attributes	Well connected by road & all types transport services available
9.2	Scarcity	Balanced
9.3	Demand and supply of the kind of subject property	Balanced
9.4	Comparable sale prices in the locality.	Sale Instances of similar properties in the vicinity not available.

Engineering and Technology Aspects of the Property

10.	Description of engineering and tech	nology aspects to include
10.1	Type of construction,	RCC framed Gr. + 5 upper floors Brick / CC Block masonry wall building having adequate floor height. Premises is provided with vitrified tiles flooring, Wooden frame door and safety gate & Aluminium frame glazed windows
10.2	Materials and technology used,	Good
10.3	Specifications,	
10.4	Maintenance issues,	No.
10.5	Age of the building	The Building is about 25-30 years old
10.6	Total life of the building,	Estimated residual life : about 20 years
10.7	Extent of deterioration,	with proper maintenance. Not observed
10.8	Structural safety	Structurally sound
10.9	Protection against natural disasters viz. earthquakes,	As per Architectural Design
10.10	Visible damage in the building if any,	No visible damage
10.11	Common facilities viz. lift, water pump, lights, security systems, etc.,	1 No. Lift
10.12	System of air-conditioning,	
10.13	Provision for fire fighting,	As per provisions of MCGM
	Copies of plans and elevations of the	building to be included - Not made available

Declaration

I hereby declare that: 14.

- a) The information provided is true and correct to the best of my knowledge and belief.
- b) The analysis and conclusions are limited by the reported assumptions and conditions.
- c) I have no direct or indirect interest in the asset valued.
- d) I/my authorized representative /Associates have inspected the subject property on 17.05.2019
- e) I am a 'Valuer' as per the existing provisions in Category I-233 and fulfil the education, experience and other criteria laid out therein.
- f) I abide by the code of conduct as provided at the time of empanelment.
- g) I/We confirm that the norms / procedures of valuation as prescribed by the 'Institute of Valuers' have been strictly complied with.

shetty & associates

B.E. (CIVII) (Hons.) F.I.E., F.I.V.,
D ENGINEERS & GOVT. REGISTERED VALUES
RS AND TECHNICAL APPRAISERSV FORS,
CIAL INSTITUTIONS & INCOME TAY DEST

Name and address of the Valuer

Name of Valuer Association of which I am a bona fide member in good standing The IOV Regd. Valuers Foundation Membership No. IOVRVF/VM/L&B/4666 & Registered with IBBI Regn. No. IBBI/RV/02/2019/11075

Signature of the Valuer

Date 18.05.2019

Tel. No. 022-24115420/ 24115442

Mobile no: 9821010756.....

E-Mail: rtnaks@gmail.com

15.		■ Layout plan of the area in which the asset is located	Nil
	es:	■ Building plan	Nil
	sur	■ Floor plan	Nil
	Enclosur	■ Photographs of the property being valued	Attached
		■ Any other relevant document/extracts	Google map attached

A. V. Shetty & Associates

11.1	Use of environment friendly building materials, Green building techniques if any,	N.A
.2	Provision for rain water harvesting,	
1.3	Use of solar heating and line	N.A.
	Use of solar heating and lighting systems, etc., Presence of environmental pollution in the vicinity of the property in terms of industries, heavy traffic, etc.	

Architectural and Aesthetic Quality of the Property

12.	Descriptive account				
	Descriptive account on whether the building is modern, old fashioned, etc., plain looking or with decorative elements, heritage value if applicable, presence of landscape elements, etc.	Standard Commercial Building			
13. Val	notice and the state of the sta				

13. Valuation

The "Fair Market Value" of the said property has thus been assessed based on local enquires using "Market Value" method & taking into account the factors mentioned as above and briefly listed below:

- A) Extent and Survey Number.
- B) Location, accessibility, distance from the centre of the town.
- C) Developments infrastructural facilities etc.
- D)Market value of land as estimated by local enquiries
- E) Building type of construction, age, future life, depreciation.
- F) Dues/Outgoings Records not available

The "Fair Market Value" of the said property has been worked out as under:

635sqf.

₹ 27,500/sqf.

= ₹ 1,74,62,500/**-**₹ 1,74,75,000/-

(Above rate takes into consideration value added on account of Loft Coverage & improvement)

Therefore, to the best of our knowledge and belief, the "Fair Market Value" of the said property is ₹ 1,74,75,000/- (Rupees one crore seventy four lakhs & seventy five thousand only) and the "Realisable Value" of the said property is ₹ 1,57,25,000/- (Rupees one crore fifty seven lakhs & twenty five thousand only) and the "Forced Sale Value" of the said property is ₹ 1,39,75,000/- (Rupees one crore thirty nine lakhs & seventy five thousand only) and the "Insurable Value" (Reinstatement value of the structure) of the said property is ₹ 7,50,000/- (Rupees seven lakhs & fifty thousand only) as on the date of visit (17.05.2019) and the same may be considered to be true and fair.

avstreuty & associates B.E. (CIVII) (Hons.) F.I.E., F.I.V.,
CS. RYERED ENGINEERS & GOVT. REGISTERED VALUES PAIT LY LUERS AND TECHNICAL APPRAISERSY FOR BANKS, FINAL CIAL INSTITUTIONS & INCOME TAX DEPT.

IEST REGISTERED VALUERS UNDER THE INSCLYENCY AND BANKRUPTCY CODE 2018

COHA, FIRST FLOOR, 126-A, DADASAHEE PHALKE POAD, DADAR (EAST), MUNBAL - (10 01 1: 21:15420 - 24115442, 24168955 F. A. 15-27-1102 4 Elli/IL: rtnaks@nm; 1