PL323-247-457. RKA/DNCR/...../... File No. Sep 5th, 2022 Date of Receiving Abhishek. Shanbleg

File Receiver Name

CASE COLLECTION FORM (Version 5.0)

	Date of Imple	amemani	IIII NOTAYA	資高機 調点 シレブ 母 レノ	CVIDIOITA	VI III	175.7				
	Items	Assig	ned To	Assigned to Date	com	o be pleted date	1000	ubmitte On date			HOD Engg. Signature
File	Received By	Ashis	shele. shele	NA	1	NA ————					
Sur	vey	Shre	y ash etty	14/9/202	2						
Pre	paration		J								
	A - Very Good, B	- Satisfa	ctory, C -	Average, D	- Poor, l	E - Extr	eme	ly Poor			
Eng	Returned to HOD g. unprepared due ason	rates proper	is not pro erly done esentative	perly done, Photo	☐ Iden graphs aken, ☐	tificatio not cl Owne	n is learly r/ ov	not cleai y taken vner rep	rly done, □ , □ Selfi resentative] Me e/ (Market survey fo easurement is no Owner or owne nature not taken
by th	ase File is returned ne preparer - HOD g. comment & nature	Surve	eyor. Repo	cts in the sort preparer to	to collec	t the mi	issin	g inform	ation on hi	tion s ow	with warning to vn.
		NA BUILD		GENERA	VED EI	ALS					建於關聯黨與政府
1.	Proposal/ Work Or Ref. No.	der or	5	DL 32	23-	24	7	-45	7.		
2.	Type of Service			tion Report, CE Certific						st ve	etting certificate
3.	Type of customer		☐ Bank	any	☐ Priva	te clien	t	☐ Direc	☐ Corpo	oug	h Bank
4.	Bank/ FI/ Organiza Name & Address	tion	PNB M Sir P.	M. Road	, Fort	or,	unit	ai-4	ank of	Ind	lia Bldg,
5.	Case Allotment Off	icer/		Name		Contac	t Nu	ımber		Er	nail ld
	Fees paying party	Details	MY. S	andeep	7	5887	72	554	mce 813	3 @	pnb. co. in
6.	Case Type		Ca	se for Frest	n Accou	nt		Case	for exiting	acco	ount/ customer
7.	Fees Details		Amoun	t of Fees	Advan	ce Am	ount	if any	Fees	wil	l be paid by
			15,000+	-6,5 T	8,	85	B o		Ban	K	Customer
8.	Billing Details		Е	Billed To Pa					G	ITS	V

	with the second second second second	CASE DETAILS
1.	Type of Property	office unit
2.	Purpose of Valuation/ Assignment	Value assessment of the asset for creating new collateral mortgage ☐ Periodic Re-Valuation for Bank, ☐ Distress sale for NPA A/c., ☐ For DRT Recovery purpose, ☐ Capital Gains Wealth Tax purpose ☐ Partition purpose, ☐ General Value Assessment ☐ Any other:
3.	Owner/ Applicant Details	Name Contact Number Email Id MS. Trincas Agencies & Commerce Put-Ltd.
4.	Account Name	
5.	Property Address	Alpha Alternatives Hololings Put. Ltd. Senapati Bapat Marg, Dadar West, Mumboi-400013. Parking Spaces - 62,63,64,81,82. Name Contact Number
6.	site for the site survey	Name Contact Number Sophie - (Khyati). (9987282945) Khyati:
7.	Preferred time of survey	Date 14/09/2022 Time 4-30pm.
8.	Documents Received (Any one ownership document and approved site plan/ map is must)	 Ownership Documents: Sale Deed, Power of Attorney,
9.	Documents received from	Banker (Mr. Sandeep - 7588772554)
10.	Special Instructions if any:	
11.	on Valuer firm to distort any	entioned above for the preparation of Valuation Report. I agree that I'll not put pressu facts and would not try to influence any member or official of the firm in the ill spirit any individual or organization by any means illegitimately.

Alpha Alternatives Investment Pvt. Ltd., 34th Floor, Sonshine Tower, Dadar West, Mumbai-400013.

FILE RECEIVER CASE COLLECTION PROCESS COMPLIANCE CHECKLIST (To be filled by Surveyor)

S.NO.	COMPLIANCE CHECKLIST	STATUS	APPROVER SIGNATURE/ REMARKS IN CASE OF ANY (X)
1.	Is Case collection Form properly filled by Receiver?	No.	OF AIRT (A)
2.	Is purpose of the assignment understood clearly by the receiver?		
3.	Has receiver checked if this is a new case or existing case of the Bank?	D	
4.	Has receiver fixed the fees with the manager/ client and sent quotation properly or have taken approval of the work over email?		
5.	Has receiver taken proper Work Order/ Email/ CESA form formality?		
6.	In case of private case or for fresh case 50% advance is received?		
7.	Is document checklist email sent to the customer?		
8.	Has the received documents is having 'documents provided by stamp'?		

IMPORTANT INSTRUCTIONS TO SURVEYOR

-	
1.	Please fill the above compliance checklist before moving for the survey.
2.	Please do not do the survey if you do not have proper documents.
3.	For Vacant Plot/ Land - Cizra Map/ Master/ Zonal/ Site Plan is must to identify the Plot. For Agriculture or converted land from agriculture - Mutation documents, CLU is must.
4.	Firstly please first study the documents of the property which needs to get surveyed.
5.	Mark the Owner/ Area/ Boundaries mentioned in the ownership documents with bold florescent
	marker pen before moving for the survey. During site survey if any difference is found in the
	above fields from the ownership documents then please contact the owner immediately to
	know the reason for the difference.
6.	Confirm ongoing property rates in the subject location through public domain, property sites and
	contact dealers to show you the available properties in that area during your survey.
7.	Identify the Property clearly by matching the boundaries and area mentioned in the property
	papers.
8.	Do sample physical or google measurements of the property.
9.	PHOTOGRAPH INSTRUCTIONS:
	a. Take owner/ representative photograph along with the property.
	b. Take your selfie along with the property and the owner/ representative.
	c. Take full scale photo of the property with gate.
	d. Take photo of the property along with abutting road, towards left, right and center.
	e. Take multiple photos of inside-out of the property.
	f. Take nearby photographs of the Property.
	g. Take a short video to cover property and neighborhood.
10.	Take Google Map location.
11.	Check main road name & width and approach road width and distance of property from main road.
12.	Check Jurisdiction Municipal Limits & Ward Name.
13.	Fill each column of survey form diligently in detail and tick the appropriate option clearly.
14.	Check any defects or negativity in the property and comment in detail on survey form.
15.	Do extensive market rate enquiries and confirm for any recent past transactions.
16.	In case customer appears to be providing misleading information to you or trying to influence you by

money or cash then immediately report to the Management & Bank.

	SURVEY GRADING MATRIX				
SRADE	PARAMETERS/ CRITERIA				
A	In case all the points below are done properly, timely with full care and diligence:				
	 Survey started with proper work order and knowing the source of payment. Survey done with proper documents. Done complete homework and studied the documents properly with highlighting the main points before moving for the survey. Chosen correct survey form as per the property type. All fields of Survey form are properly filled. All site special observations and negative and positive factors are clearly mentioned. Self & client signatures taken on survey form. Property rates information properly taken, mentioned and verified. Site rough sketch plan made. Proper photographs taken. Selfie with property taken. Selfie and owner photograph with property taken. 				
В	In case of 3 minor mistakes in any of the above points except Point 1, 2, 3, 4, 6, 8, 10, 11, 12 but all the				
	points are covered.				
C	In case of more than 3 minor mistakes and any 1 major mistake in any of the above points and if any points				
	are completely missing except Point 1, 2, 3, 4, 6, 8, 10, 11, 12.				
D	In case of 1 major mistake or missing of any 1 point out of 1, 2, 3, 4, 6, 8, 10, 11, 12.				
E	n case of more than 1 major mistakes or missing of more than 1 point out of 1, 2, 3, 4, 6, 8, 10, 11, 12.				

Note (Survey Grading Matrix):

- For special assignments like LIE, Stock Valuation, etc. where till date survey format is not specified or released, in such cases point wise site observation report has to be submitted by the Surveyor duly signing it properly. Without signed Site Observation report, Point 4 will be considered as not done and will fall under Category E.
- 2. Similar Grading Matrix is issued for Case Collection & Report Preparation as well.

Note (Overall Grading Matrix):

1. In case client reports any careless mistake in the report for which revision has to be done in the report then in that case Grading Matrix may be revised and Grade E will be awarded.

	SURVEY PROCESS COMPLIANCE CHECKLIST	
	(To be submitted by Surveyor with each Survey)	1 位 22 温 / 通 / 通
S.NO.	COMPLIANCE CHECKLIST POINTS	STATUS
1.	Did you take proper property documents to carry out the survey?	U C
2.	Have you properly studied & highlighted Owner/ Area/ Boundaries in the property	
	documents with bold florescent before moving for the survey?	
3.	Did you check prominent landmark nearby the subject property and mentioned in the survey form?	
4.	Did you identified the Property clearly by matching the boundaries and area mentioned in the property papers?	
5.	Did you check if property is merged with any other property or it is an independent property?	No.
6.	Did you do sample physical or google measurements of the property in case of property more than 2500 sq.mtr?	Z
7.	Did you check for any building violations in the property?	W
8.	Did you check municipal limits/ jurisdiction/ ward?	
9.	Did you take Google Map location and shared it to Maps whatsapp group?	W
10.	Did you check Main road name & width and its distance from the subject property?	10
11.	Did you check approach Lane width on which property is located?	V
12.	Have you taken property full scale photograph with gate?	
13.	Have you taken owner/ representative photograph with the property?	
14.	Have you taken your selfie with the property along with owner/ representative?	W
15.	Have you taken photograph of the property along with abutting road and towards left and right of the property?	
16.	Have you taken multiple photographs of the property from inside-out?	
17.	Did you check nearby development and whereabouts and commented on survey form?	
18.	Did you check any defects or negativity in the property in terms of location, legalid disputes, marketability, salability, etc. and commented on survey form in detail?	ty,
19.	Have you filled all the columns of survey form including survey summary she properly?	eet 🗷
20.	Did you draw site key plan (location map)?	
21.	Did you draw rough site sketch plan?	
22.	Have you taken self-attested documents from owner/ representative and stamp "documents provided by stamp"?	oed [
23.	Did you check any defects or negativity in the property in terms of location, legal disputes, marketability, salability, etc. and commented on survey form in detail?	ity,
24.	Have you confirmed any recent past transactions during market enquiries enquired property rates locally very rigorously?	and
25.	Did you take signatures of the owner/ representative on undertaking and sur summary sheet?	vey
26.	Did you signed the undertaking?	

For File No.	PL323-267-457
Surveyor Name	Shreyash Shetty.
Signature	Fachs.
Date	14/09/2022

GENERAL SURVEY FORM

(FOR PROPERTIES OTHER THAN FLATS)
(Version 5.0)

Date of implementation: 9.02.2011 | Last Revision: 04.01.2018 | Latest Revision: 31.10.2020

D1 157						
PL323-247-457						
File No. RKA/DNCR//	Date:	14 09	22	Time:	4:30b	m

Taling of the		GENERAL DETAILS		
1.	Name of the Surveyor	Shreyash Shetty.		
2.	Property shown by	☐ Owner, ☐ Representative, ☐ N	o one was available, Property is	
		locked, survey could not be done fr	The second of th	
		Name	Contact No.	
		Sophie.	Khyati-9987282965.	
3.	Survey Type	✓ Full survey (inside-out with measurements & photographs)☐ Half Survey (Measurements from outside & photographs)		
		☐ Only photographs taken (No me	easurements)	
4.	Reason for Half survey or only	☐ Property was locked, ☐ Poss	sessee didn't allow to inspect the	
	photographs taken N.A.	property, NPA property so could		
5.	How Property is Identified	From schedule of the properties	es mentioned in the deed, . From	
		name plate displayed on the pro	operty, Identified by the owner/	
		owner representative, Enquired		
		☐ Identification of the property co	uld not be done, \square Survey was not	
		done		
6.	Type of Property		\square Residential House, \square Low Rise	
			er Floor, \square Commercial Land &	
			Commercial Shop, Commercial	
		Floor, □ Shopping Mall, □ Hotel,		
			esidential Plot, Vacant Industrial	
		Plot Agricultural Land		
7.	Property Measurement		asurement only, No measurement	
8.	Reason for no measurement	☐ It's a flat in multi storey building ☐ Property was locked, ☐ Owner		
		The same and the s	ne property, Very Large Property	
	N.A.			
	10.		sure the entire area Any othe	
		Reason:		
9.	Purpose of Valuation	. Value assessment of the asset	t for creating new collateral mortgage	
		☐ Periodic Re-Valuation for Bank	North and the state of the stat	
	New trest		Capital Gains Wealth Tax purpose	
	(04)-	☐ Partition purpose, ☐ General \		
10.	Type of Loan		te Over Loan, ☐ Home Improvemen	
	Business		☐ Construction Loan, ☐ Educations	
	loan		Loan, Term Loan, CC Lim	
	C	enhancement, Cash Credit Lim		
11.	Loan Amount	- January Country Coun	m, is madorial coun, is two	

		OWNERSHIP DETAILS		
1.	Legal Owner Name/s	MIS. Tringas Agencies & Commerce P. H. 1td.		
2.	Property Purchaser Name	M/S. Trincas Agencies & Commerce Put. Ltd.		
3.	Property Address under	P. N Dr.		
	Valuation	Pg. No.z. Refer.		
4.	Present Residence Address of			
	the Owner/ Purchaser			
5.	Property constitution	Free Hold, ☐ Lease Hold		
A Sec Office	· · · · · · · · · · · · · · · · · · ·	LOCATION DETAILS		
1.	Adjoining Properties	East West North South		
1.	(Match it with papers with the help			
	of compass or Sun direction and	Open tosky, Eddy action Open to		
	also confirm it with nearby people)	Open to sky, Lobby & Lifts, Open to Lobby & Elift Railway Track Other Building, Sky. Railway Stati		
2.	Property Facing ST	☐ East Facing, ☐ North Facing, ☐ West Facing, ☐ South Facing,		
	1	☐ North-East Facing, ☐ South-West Facing, ☐ South-East Facing,		
		☐ North-West Facing		
3.	Landmark Entry	Pard Rly stn, Sunshine Tower.		
4.	Ward Name/ No.			
5.	Zone Name			
6.	Main Road Name & Width	Name Width Distance from property		
		Senapati Bapat Marg - Slane cach 50m. Internal Road of For Sunshine Tower. Within Main situal Within Good Urban developed Area (Within		
7.	Approach Road Name & Width	Internal Road of For Sunshine Tower.		
8.	Location consideration of the	☐ Within Main city, ☑ Within Good Urban developed Area, ☐ With		
	Society	developing area, ☐ Highly posh locality, ☐ Very Good, ☐ Good,		
		☐ Ordinary, ☐ In interiors, ☐ Remote area, ☐ Backward, ☐ Averag		
		☐ Ordinary, ☐ In interiors, ☐ Remote area, ☐ Backward, ☐ Avera		
		□ Poor		
9.	Special Location consideration	☐ Park Facing, ☐ Pool Facing, ☑ Road Facing, ☐ Entrance Nort		
9.	Special Location consideration of the property	☐ Park Facing, ☐ Pool Facing, ☑ Road Facing, ☐ Entrance Nort		
9.		□ Poor □ Park Facing, □ Pool Facing, ☑ Road Facing, □ Entrance Nort East Facing, □ Sunlight facing ☐ Floor, Good View ☑ Urban developed, □ Urban developing, □ Semi Urban, □ Rural,		
***************************************	of the property	□ Park Facing, □ Pool Facing, ☑ Road Facing, □ Entrance Nort East Facing, □ Sunlight facing Top Floor, Good View		
10.	of the property Characteristics of the locality	□ Park Facing, □ Pool Facing, ☑ Road Facing, □ Entrance Nort East Facing, □ Sunlight facing ☐ Floor, Cood View ☑ Urban developed, □ Urban developing, □ Semi Urban, □ Rural, □ Backward, □ Industrial, □ Institutional		
***************************************	of the property	□ Park Facing, □ Pool Facing, ☑ Road Facing, □ Entrance Nort East Facing, □ Sunlight facing ☐ Floor, Cood View ☑ Urban developed, □ Urban developing, □ Semi Urban, □ Rural, □ Backward, □ Industrial, □ Institutional ☑ High End, □ Normal, □ Affordable Group Housing, □ EWS, □ High End, □ H		
10.	of the property Characteristics of the locality Category of Society/ locality	□ Park Facing, □ Pool Facing, ☑ Road Facing, □ Entrance Nort East Facing, □ Sunlight facing ☐ Floor, Good View ☑ Urban developed, □ Urban developing, □ Semi Urban, □ Rural, □ Backward, □ Industrial, □ Institutional ☑ High End, □ Normal, □ Affordable Group Housing, □ EWS, □ Hi □ MIG, □ LIG		
10.	of the property Characteristics of the locality	□ Park Facing, □ Pool Facing, ☑ Road Facing, □ Entrance Nort East Facing, □ Sunlight facing ☐ Floor, Cood View ☑ Urban developed, □ Urban developing, □ Semi Urban, □ Rural, □ Backward, □ Industrial, □ Institutional ☑ High End, □ Normal, □ Affordable Group Housing, □ EWS, □ Hi □ MiG, □ LIG ☑ Lifts, □ Garden, □ Landscaping, □ Swimming Pool, □ Øym,		
10.	of the property Characteristics of the locality Category of Society/ locality	□ Park Facing, □ Pool Facing, ☑ Road Facing, □ Entrance Nort East Facing, □ Sunlight facing ☐ Floor, road View ☑ Urban developed, □ Urban developing, □ Semi Urban, □ Rural, □ Backward, □ Industrial, □ Institutional ☑ High End, □ Normal, □ Affordable Group Housing, □ EWS, □ HI □ MIG, □ LIG ☑ Lifts, □ Garden, □ Landscaping, □ Swimming Pool, □ Øym, □ Club House, □ Walk Trails, □ Kids play zone, ☑ 100% Pow		
10.	of the property Characteristics of the locality Category of Society/ locality	□ Park Facing, □ Pool Facing, ☑ Road Facing, □ Entrance Nort East Facing, □ Sunlight facing ☐ Floor, Cood View ☑ Urban developed, □ Urban developing, □ Semi Urban, □ Rural, □ Backward, □ Industrial, □ Institutional ☑ High End, □ Normal, □ Affordable Group Housing, □ EWS, □ Hi □ MiG, □ LIG ☑ Lifts, □ Garden, □ Landscaping, □ Swimming Pool, □ Øym,		
10. 11.	of the property Characteristics of the locality Category of Society/ locality Utilities/ Facilities in the locality	□ Park Facing, □ Pool Facing, ☑ Road Facing, □ Entrance Nort East Facing, □ Sunlight facing ☐ Floor. Cool View □ Urban developed, □ Urban developing, □ Semi Urban, □ Rural, □ Backward, □ Industrial, □ Institutional □ High End, □ Normal, □ Affordable Group Housing, □ EWS, □ HI □ MIG, □ LIG □ Lifts, □ Garden, □ Landscaping, □ Swimming Pool, □ Øym, □ Club House, □ Walk Trails, □ Kids play zone, □ 100% Pow Backup School Hospital Market Metro Railway Station Airpo		
10. 11.	of the property Characteristics of the locality Category of Society/ locality Utilities/ Facilities in the locality	□ Park Facing, □ Pool Facing, ☑ Road Facing, □ Entrance Nort East Facing, □ Sunlight facing ☐ Floor, Food View ☑ Urban developed, □ Urban developing, □ Semi Urban, □ Rural, □ Backward, □ Industrial, □ Institutional ☑ High End, □ Normal, □ Affordable Group Housing, □ EWS, □ HI □ MIG, □ LIG ☑ Lifts, □ Garden, □ Landscaping, □ Swimming Pool, □ Øym, □ Club House, □ Walk Trails, □ Kids play zone, ☑ 100% Pow Backup School Hospital Market Metro Railway Station Airport		

17.	Jurisdiction limits Jurisdiction Development Authority Name M. M. R. D. A Municipal Corporation Name BMC.	 Nagar Nigam, □ Nagar Panchayat, □ Gram Panchayat, □ Nagar Palika Parishad, □ Area not within any municipal limits □ DDA, □ GDA, □ NOIDA, □ GNIDA, □ YEIDA, □ HUDA, □ KMDA, □ MDDA, □ Any other Development Authority: □ Area not within any development authority limits □ NDMC, □ SDMC, □ EDMC, □ Ghaziabad Municipal Corporation, □ Gurgaon Municipal Corporation, □ Faridabad Municipal Corporation, □ Kolkata Municipal Corporation, □ Dehradun Municipal Corporation, □ Area not within any municipal limits, □ Any other Municipal Corporation/ Municipality: 				
Dec Service	The same of the sa	PHYSICAL DETAILS				
1.	Land Area	As per Title deed				
2.	Any conversion to the land use	Not known tous.				
	Lond Time					
3.	Land Type	Solid, Rocky, Marsh Land, Reclaimed Land, Water				
		logged, □ Land locked				
4.	Shape of the Land	☐ Square, Rectangular, ☐ Trapezium, ☐ Triangular, ☐ Trapezoid,				
		□ Irregular, □ NA				
5.	Level of Land	☐ On road level, ☐ Below road level, ☑ Above road level, ☐ NA				
6.	Frontage to depth ratio	☐ Normal frontage, ☐ Less frontage, ☐ Large frontage, ☐ NA				
7.	Are Boundaries matched	☐ Yes, ☐ No. ☐ No relevant papers available to match the				
		boundaries, Doundaries not mentioned in available documents				
8.	Is Independent access available	Clear independent access is available, Access available in				
	to the property	sharing of other adjoining property, \square No clear access is available,				
		☐ Access is closed due to dispute				
9.	Is property clearly demarcated with permanent boundaries?	✓ Yes, □ No, □ Only with Temporary boundaries				
10.	Is the property merged or colluded with any other property	No, not marged.				
11.	Property possessed by at the	☐ Owner, ☐ Vacant, ☐ Lessee, ☐ Under Construction, ☐ Couldn't				
	time of survey	be Surveyed, ☐ Property was locked, ☐ Bank sealed, ☐ Court				
12.	Current activity carried out in the	sealed Residential purpose V Commercial purpose D Godown				
12.	property	☐ Residential purpose, ☐ Commercial purpose, ☐ Godown, ☐ Office, ☐ Industrial, ☐ Vacant, ☐ Locked, ☐ Any other use:				
1.	Construction Status	CONSTRUCTION UTLITY DETAILS				
		₩ Built-up property in use, □ Under construction, □ No construction				

	Covered Built-up Area				
		☐ Covered Area, ☐ Floor Area, ☐ Super Area, ☐ Carpet Area			
	(Tick one on the basis of which	As per The deed	As per Map	As per site survey	
	valuation is to be calculated)	Carpet =	, is per map	Built up =	
F 3.	Total Number of Floors in the	366059. Ft.		4375.44.2g. Ft.	
0.	Building	G+Pi, Pz, F	3, Pu, P5, 6-	to Flance	
4.	Floor on which property is situated	34th Flo			
5.	Type of Unit/ Number of Rooms/ Cabins/ Cubicles	10 Cabins, 1 Confer	ena Room, 1 Pan	try, was brooms,	
6.	Building Type	Storage Area (U)	oicles & X Desks	ar Dillar Boom column	
270.50				ng Pillar Beam column,	
		☐ Ordinary brick wall structure, ☐ Iron trusses & Pillars, ☐ Scra			
7.	Roof	abandoned structure	POC F CI Shed	□ Tip Shod □ Stone	
1.	Rooi	a. Make: \square RBC, \square	∠ RCC, ⊔ GI Shed,	☐ Tin Shed, ☐ Stone	
		b. Height: 978	C+.		
		c. Finish: Simp	le plaster, POP I	Punning, POP False	
		Coiling Coved	roof. No plaster		
8.	Flooring	Vitrified tiles	Ceramic Tiles. Si	mple marble, Marble	
		chips, Mosaic,	Granite, VItalian Mark	□ Pavers, □ Chequered	
		□ Wooden, □ PCC,	☐ Imported Marble,	nder construction, Any	
		athertune:			
9.	Appearance/ Condition of the	other type:	ent. Very Good,	☐ Good, ☐ Ordinary,	
9.	Building	□ Average □ Poor I	☐ Under construction,	☐ No Survey	
	Building	External VI Excel	lent □ Very Good.	☐ Good, ☐ Ordinary,	
		□ Average □ Poor [☐ Under construction		
10	Maintenance of the Building	Very Good. Ave	rage, Poor, Und	er construction	
10.		N Excellent □ Ve	ry Good □ Good.	☐ Simple, ☐ Ordinary,	
11.	Interior decoration	☐ Average ☐ Below	average, Under co	onstruction, No Survey	
10	Interior Finishing	Simple plastered w	valls. Drick walls wi	thout plaster,	
12.	Interior Finishing	☐ Designer textured	walls, POP punning	g, ☐ Coved roof,	
		☐ Upder construction			
	5 to its Finishing	Simple plastere	d walls. Brick	walls without plaster,	
13.	Exterior Finishing	☐ Architecturally de	esigned or elevated,	☐ Brick tile Cladding,	
		☐ Structural glazing.	☐ Aluminum compos	site panel cladding,	
		☐ Glass facade. ☐ ☐	omb. \square Poreh, \square Ur	nder construction	
14.	Kitchen	☐ Simple with no cu	pboard, Ordinary	with cupboard, U Normal	
1-7.		Modular with chimney	/, 🗆 High end Modula	ar with chimney, \square Under	
		construction, ☐ No S	urvey		
15.	Class of Electrical fittings	External, Intern	al		
		Ordinary fixtures	& fittings, \to Fanc	y lights, Chandeliers,	
		☐ Concealed lightnin	g, Under construct	ion, No Survey	
16.	Class of Sanitary/ Plumbing &	External, Intern	al		
	water supply fittings	☑ Excellent, ☐ Very	Good, ☐ Good, ☐ S	imple, □ Average,	
	le .	☐ Below average, ☐	Under construction,	☐ No Survey	
17.	Water arrangements	☐ Jet pump, ☐ Subn	nersible, 🗌 Jal board	supply	
18.	Fixed Wooden Work	Excellent, Ve	ry Good, \square Good,	☐ Simple, ☐ Ordinary	
	Account of the Section Control of the Section	☐ Average, ☐ Below	Average, 🗆 No woo	den work, No survey	
19.	Age of Building/ Recent		211300		
1000007	Improvements done	10-12	Years.		
20.	Maintenance of the Building	Very Good, □ Ave	erage, Poor		

	Any defects in the building	☐ Mainter		
		☐ Maintenance issues, ☐ Finishing issues, ☐ Seepage issues, ☐ Water supply issues. ☐		
1		Electricity issues, Structural issues,		
/ 22.	Any violation done in the property	This bille cracks in the building		
4	and property	☐ Construction done without	Map, Construc	ction not as per
		approved Map, \square Extra covered	without sanctione	d Map, Joined
23.	Boundary Wall (Only for individual	adjacent property, Encroached adjacent area illegally		
20.	property)	Yes, □ No, □ Common boundary wall of a complex		
		Running Mtr. Height	Width	Finish
24.	Lift/ elevators	✓ Passenger/ ☐ Commercial		
	5 Lifts.	Make: OTIS	Capacity: 16	Persons.
25.	Power backup	☐ Inverter, ☑ DG Set		
		Make:	Capacity:	
26.	Garden/ Landscaping	☐ Yes, ☑ No, ☐ Beautiful, ☐ Ordinary		
27.	Parking facilities	Available within the property	☐ On Ground,	☐ In Basement,
		Podium Parking PI-PS.	☐ On stilt	A auto porting
		☐ Not available within the	☐ On road, ☐ problem	Acute parking
28.	Special Comments/ Observations,	property	problem	
20.	If any			
	MARKETABI	LITY SELABILITY UTLITY DE	TAILS ::	
1.	Any issues in marketability of the	☐ Yes, ☑ No		
	property?	Reason in case of No: Lo	cation, Surrou	unding, Legal
		aspects, Demand, Shape,		
2.	How is Demand & Supply condition	Demand Very Good, ☐ Goo		
	in the Market of such properties?	Supply ☐ Very Good, ☑ Good	d, \square Average, \square	Low, Poor
3.	Is property easily sellable &	✓ Yes, □ No		
	marketable?	Comments:		
4.	How is the current utility of the property?	Excellent, Very Good, Go	ood, 🗆 Average, L	」Low, ∐ Poor
5.	At what True rate Owner bought	Year of purchase	2017) .
	this Property?	Purchase Price		
6.	Present expected Sale Value of the	-(0)		
	overall property?	15CR-16C	K .	
- 1	5050 ASSA 1885			

10	Particulars (AVaila	Subject	IPARABLE RATE IN Transaction already I Comparable 1	nappened in past) Comparable 2	Comparable 3
40		Property	- comparable 1	Comparable 2	Comparable 5
Ī.	Name (source of information)	NA	Sun Realtors.	Ayez Ansari.	Padmavati .
	Contact No.	NA	9768909775	9809807575	
	Type of source of information (Seller/ Property dealer/ nearby people)	NA	Dealer	Doder.	Doaler.
	Rates/ Price informed (in Rs. with unit)	NA	40k to 45 K/ 3q. Ft - Carpet	42-48 K/sq.	T Gok tousk
	Rates Type (Sale/ Buy)	NA	Buy.	Boy.	Buy.
	Shape of the Property (Square, Rectangular, Irregular)		Rectangular.	Rectangle.	Roctangle.
	Area/ Size of the Property		Similar.	Similar	Similar
	Legal Status (clear, negative, weak)/ No. of owners		Clear.	Clear.	Clear.
*	Location/ surrounding/ neighborhood comparison with the subject property (Similar, Lower, Better, Highly Better than the subject Property)	Base Case	Same	Saml	Same
0.	Distance from the subject Property	0	.0	0	0
1.	Other factors (Corner, 2 side open, North-East facing, Park facing, Legal/ Financial encumbrance, etc.)		Same.	Saml	Same
2.	Approach road width	м	5 Scome	Same	Same
3.	Level of Land (Below/ On/ Above road level)		Abover	Above	Above
١.	Frontage to depth ratio (Normal, Less, Large)		1083	(035	1239
5.	Present Use		Vacant.	Vacant	Vacant
5.	Any other details/ Discussion held	NA	Rates are around 40-46 on Carpet	Hear Ft and	Carp
	Present expected Sale Value of the overall		Asyougo high	above 48k.	es govera litt

UNDERTAKING BY THE CUSTOMER

correct property in question for which the documents have been provided/ submitted by me. I further confirm that I am aware of all the information related to the subject property and I have provided all its information to the surveyor true to the best of my knowledge. I understand that any false or manipulative information provided by me will be considered as cheating with the professional organization since it will lead to incorrect valuation report and I'd be solely responsible for this unlawful act and will bear the charges for the changes/ modifications which have to undergo due to the false information. I also undertake that I have not given any cash or in kind to any member of R.K Associates to influence the Value of the Property or favor any individual or organization and the same is not accepted or asked by the member of R.K Associates. Any such act will lead to cancellation of the material prepared by R.K Associates with forfeiting of the fees and i'll be completely responsible for its repercussions and legal actions taken for it.

IMPORTANT: We have not authorized any of our person/ Surveyor to take Cash or kind from the customers in any situation. In case Surveyor or any member of R.K Associates asks for any money or kind from you then kindly please inform on number +91-9958632707, 0120-4110117. Our Valuation process is very stringent and have multiple check points to ensure correct & error free reports to keep the lending agency risk free. In case Surveyor claims that he would be able to arbitrary effect the Valuation figures unfairly or as per your requirement & need, then he is making a false claim to you and we request you to complaint such act immediately on the number provided above.

Name
Relationship with owner
Signature

Mobile No.

Date

14/09/2022

UNDERTAKING BY THE SURVEYOR

I confirm that I have carried out the Survey of the property properly as per the fair professional best practices and Valuation & Survey policy guidelines issued by R.K Associates. I have not taken any cash or kind from the customer nor have I come into any kind of influence of the customer I bank for arbitrary providing the Property Valuation as per one's need. I further state that I have not given any assurances to the customer nor given any wrong or false information or statement. In case at any point of time it is found that I have done any kind of fraudulent activity in this case and misled the company then I understand its legal consequences and appropriate penal action which company can take against me. Also in regard to it any monetary or reputation loss will be recovered from me by the company.

For File No.	PL323-247-457
Surveyor Name	Smegash Shetty.
Signature	Tacks:
Date	12/09/2022.

Enclosure: 6

(TO BE ENCLOSED WITH VALUATION REPORT)

ASSOLIATES

(Version 1.0) | Date of implementation: 10.04.2017

Every Valuation report at R.K Associates is prepared based on the thorough survey of the property carried out by our Engineering Surveyor. This Survey Summary Sheet is for the information of Banker/ concerned interested organization. Detailed Survey Form can also be made available to the interested organization in case it is required to cross check what information our surveyor has given in site inspection report based on which Valuation report is prepared.

1.	File No.	01000-01	n 167	
2.	Name of the Surveyor	SI 523-24		
3.	Borrower Name	Shreyosh Shy		04
4.	Name of the Owner	MIS. VIvincas Agencies & Commerce Rut. Utd.		
5.	Property Address which has to be valued	34th Floor, Sunshine Tower, Senapati Bapat Marg,		
6.	Property shown & identified by at	Vadaw West, Mombai - 400 013 - Owner, Representative, □ No one was available, □ Property is locked, survey		
	spot	could not be done from inside		
		Name		Contact No.
		Sophie.	Kh	yati-9987282945
7.	How Property is Identified by the	☐ From schedule of the properties mentioned in the deed, ☐ From name plate		
	Surveyor	displayed on the property, ldentified by the owner/ owner representative,		
		Enquired from nearby peop	ole, \square Identification of	the property could not be done,
		☐ Survey was not done		
8.	Are Boundaries matched	☐ Yes, ☐ No, ☐ No r	elevant papers availa	ble to match the boundaries,
		Boundaries not mentione	ed in available documer	nts
9.	Survey Type	Full survey (inside-out with measurements & photographs)		
٥.		☐ Half Survey (Measureme	nts from outside & pho	tographs)
		☐ Only photographs taken	(No measurements)	
10.	Reason for Half survey or only	☐ Property was locked, ☐ Possessee didn't allow to inspect the property, ☐ NPA		
10.	photographs taken N.A.	property so couldn't be surveyed completely		
11.	Type of Property	☐ Flat in Multistoried Apartment, ☐ Residential House, ☐ Low Rise Apartment, ☐		
		Residential Builder Floor, Commercial Land & Building, Commercial Office,		
		Commercial Shop, Comm	nercial Floor, 🗆 Shopp	oing Mall, 🗆 Hotel, 🗀 Industrial,
		☐ Institutional, ☐ School Building, ☐ Vacant Residential Plot, ☐ Vacant Industrial		
		Plot, Agricultural Land		
12.	Property Measurement	Self-measured, 🗆 Sampl	e measurement, 🗀 No	measurement
13.	Reason for no measurement	☐ It's a flat in multi storey building so measurement not required		
		☐ Property was locked, ☐	Owner/ possessee di	dn't allow it, \(\sum \text{ NPA property so} \)
	N.A.			erty, practically not possible to
	10.11	measure the area within lim	ited time L. Any other	Reason:
14.	Land Area of the Property	As per Title deed	As per Map	As per site survey
2.71				
15.	Covered Built-up Area	As per Title deed	As per Map	As per site survey
23.		Carpet - 3660 89. Ft.	/	BiH-ub- 4375 44
16.	Property possessed by at the time of	☐ Owner, ☐ Vacant, ☑ Le	ssee, Under Constr	uction, Couldn't be Surveyed,
	survey	☐ Property was locked, ☐ B		
17.	Any negative observation of the			

	during survey	
100	and the property clearly demarcated with	☐ Clear independent access is available, ☐ Access available in sharing of other adjoining property, ☐ No clear access is available, ☐ Access is closed due to dispute Yes, ☐ No, ☐ Only with Temporary boundaries
F 20.	is the property merged or colluded with any other property	No, not marged.
21.	Local Information References on property rates	Please refer attached sheet named 'Property rate Information Details.'

Endorsement:

1. Signature of the Person who was present from the owner side to identify the property:

Undertaking: I have shown the correct property and provided the correct information about the property to the surveyor of R.K Associates to the best of my knowledge for which Valuation has to be prepared. In case I have shown wrong property or misled the valuer company in any way then I'll be solely responsible for this unlawful act.

- Name of the Person:
- Relation:
- Signature: Date: 14/04/2022.

In case not signed then mention the reason for it:

No one was available,

Property is locked,

Owner/ representative refused to sign it,
Any other reason:

2. Surveyor Signature who did site inspection:

Undertaking: I have inspected the property and cross verified the property details at site to the extent of a. Matching boundaries of the property, b. Sample measurement of its area, c. Physical condition, d. Property rates as per local information with what is mentioned in the property documents provided to me by the Bank/ interested organization. I have not come under influence of anyone during site inspection and have only recorded the true and factual details in the survey form which I come across during the site survey. ! understand that giving any manipulative information in the survey form will lead to incorrect Valuation report which is an unlawful act and i'll be solely responsible for doing it.

Name of the Surveyor: Shreyach Shetty
Signature: Foshs.
Date: 214/09/2022.

Signature: b.