| - File N | •. RKA/DNCR/ | 5(22-23 | - PL38 | S-Q090 REINT | ORCING Y | OUR BUSINESS | |
|-------------------|--------------------------------------|--|---------------------|-----------------|-----------------------|-----------------------------------|--|
| Date of Receivin | 19 13/10/5 | 22 | A S S O C I A T E S | | | | |
| File Receiver Nam | e Shreypst | Shetty | | | | | |
| Items | plementation: 9.02.20 Assigned To | (Vers 011 Last Rev Assigned to Date | To be completed | AN ALCONTRACT | evision: 31. Grade | 10.2020 HOD Engg. Signature | |
| File Received By | Shneyash Shetty | NA | NA | | | | |
| Survey | Shreyash Shreyash Shreyash | 13/10/22 | 6 | | | | |
| | | | | * | | | |

A - Very Good, B - Satisfactory, C - Average, D - Poor, E - Extremely Poor

| File Returned to HOD Engg. unprepared due to reason | □ Survey not done properly, □ Survey Form not properly filled, □ Market survey for rates is not properly done, □ Identification is not clearly done, □ Measurement is not properly done, □ Photographs not clearly taken, □ Selfie/ Owner or owner representative photo not taken, □ Owner/ owner representative signature not taken, |
|---|---|
| , 'Y | □ Google Map not taken, □ Survey summary sheet not filled |

| In case File is returned | □ Minor defects in the survey hence approved for preparation with warning to |
|--------------------------|--|
| by the preparer - HOD | Surveyor. Report preparer to collect the missing information on his own. |
| Engg. comment & | |
| Signature | □ Major defects in the survey. Survey has to be done again. |
| | 1 20 March 2 |

| No. | | GENER. | AL DETAILS | | and the second second | State of the second | |
|----------|---|-----------------------------|--|----------------------|-------------------------------|-----------------------|--|
| 1. | Proposal/ Work Order or Ref. No. | VIS(2 | z-23) - P | 1385 | -Q090. | - | |
| | Rel. No. | | | | | | |
| 2. | Type of Service | | ✓ Valuation Report, □ Construction cost estimate, □ Cost vetting certificate □ Other CE Certificates, □ TEV Report, □ LIE | | | | |
| 3. | Type of customer | Bank | D PSU | NBFC | Corporate | | |
| | | Company | □ Private client | Direc | t client throug | h Bank | |
| 4. | Bank/ FI/ Organization | SBT, Diamone | Branch, BI | DB, BI | KC, Ban | dra East, | |
| | Name & Address | Mumbain | | | | | |
| 5. | Name & Address Case Allotment Officer/ | Mumbain | Contact | Number | Er | nail Id | |
| 5. | | | 01 991 777 | | | | |
| 5. 6. | Case Allotment Officer/ | Name Mr. Am Am | ol 996 777 | 6684. | amtsso.c | | |
| | Case Allotment Officer/ Fees paying party Details | Name Mr. Am Am Kamble | ol 996 777 | 166 84. Na Case f | amtsso · C or exiting acco | 9276 Q. Sbi. co.in | |
| 6. | Case Allotment Officer/ Fees paying party Details Case Type | Name Mr. Am Am Kamble | ol 996 777 sh Account Advance Amou | A Case f | amtsso · C or exiting acco | 36: co.in | |

| | | H.K. Jewels. | |
|-----|--|---|---|
| | | CASE DETAILS | A THE CONTRACTOR OF THE |
| 1. | Type of Property | Residential Flat. | |
| 2. | Purpose of Valuation/ Assignment | Periodic Re-Valuation for Ban For DRT Recovery purpose, [Partition purpose, [General Any other: | |
| 3. | Owner/ Applicant Details | Name (Mr. Ghanshgam Dhai | zjibhai Dholakia. |
| 4. | Account Name | Mls. H. K. Jewels F | Put. Ltd. |
| 5. | Property Address | Flot No. 503, 5th Fli BKG MMRDA Area, | VT. Ltd. Dor, B-Wing, Insignia Building, Kalinga, Santacruz East, Mumbai Contact Number |
| 6. | Who will coordinate on site for the site survey | Name Mr. Umesh . | Contact Number 40005 97662 26615 |
| 7. | Preferred time of survey | Date 13/10/22 | Time 41:00pm. |
| 8. | Documents Received (Any one ownership document and approved site plan/ map is must) | Ownership Documents: S Registered Will, Relinqu Conveyance Deed, Allot Map: Cizra Map, Approv dillity Bills: Electricity Bill receipt, House Tax demand | ale Deed, □ Power of Attorney, ishment Deed, □ Transfer Deed, ment Letter, □ Possession Letter red Map, □ Site Plan & payment receipt, □ Water Bill & payment |
| 9. | Documents received from | Client - Mr. Kun | al - H.K. Jewel - @ 982099667, |
| 10. | Special Instructions if any: | | |
| 11. | on Valuer firm to distort any | | Valuation Report. I agree that I'll not put pressure ny member or official of the firm in the ill spirit or means illegitimately. |

| | FILE RECEIVER CASE COLLECTION PROCESS COMPLIANCE CHECKLIST (To be filled by Surveyor) | | | | | |
|-------|---|--------|---|--|--|--|
| S.NO. | COMPLIANCE CHECKLIST | STATUS | APPROVER SIGNATURE/ REMARKS IN CASE OF ANY (X) | | | |
| 1. | Is Case collection Form properly filled by Receiver? | V | | | | |
| 2. | Is purpose of the assignment understood clearly by the receiver? | V | r - | | | |
| 3. | Has receiver checked if this is a new case or existing case of the Bank? | V | | | | |
| 4. | Has receiver fixed the fees with the manager/ client and sent quotation properly or have taken approval of the work over email? | × | | | | |
| 5. | Has receiver taken proper Work Order/ Email/ CESA form formality? | × | | | | |
| 6. | In case of private case or for fresh case 50% advance is received? | VE | / | | | |
| 7. | Is document checklist email sent to the customer? | V | | | | |
| 8. | Has the received documents is having 'documents provided by stamp'? | | | | | |

IMPORTANT INSTRUCTIONS TO SURVEYOR

| 1. | Please fill the above compliance checklist before moving for the survey. |
|-----|--|
| 2. | Please do not do the survey if you do not have proper documents. |
| 3. | For Vacant Plot/ Land - Cizra Map/ Master/ Zonal/ Site Plan is must to identify the Plot. For |
| | Agriculture or converted land from agriculture – Mutation documents, CLU is must. |
| 4. | Firstly please first study the documents of the property which needs to get surveyed. |
| 5. | Mark the Owner/ Area/ Boundaries mentioned in the ownership documents with bold florescent |
| | marker pen before moving for the survey. During site survey if any difference is found in the |
| | above fields from the ownership documents then please contact the owner immediately to |
| | know the reason for the difference. |
| 6. | Confirm ongoing property rates in the subject location through public domain, property sites and |
| | contact dealers to show you the available properties in that area during your survey. |
| 7. | Identify the Property clearly by matching the boundaries and area mentioned in the property |
| _ | papers. |
| 8. | Do sample physical or google measurements of the property. |
| 9. | PHOTOGRAPH INSTRUCTIONS: |
| | a. Take owner/ representative photograph along with the property. |
| | b. Take your selfie along with the property and the owner/ representative. |
| | c. Take full scale photo of the property with gate. |
| | d. Take photo of the property along with abutting road, towards left, right and center. |
| | e. Take multiple photos of inside-out of the property. |
| | f. Take nearby photographs of the Property. |
| | g. Take a short video to cover property and neighborhood. |
| 10. | Take Google Map location. |
| 11. | Check main road name & width and approach road width and distance of property from main road. |
| 12. | Check Jurisdiction Municipal Limits & Ward Name. |
| 13. | Fill each column of survey form diligently in detail and tick the appropriate option clearly. |
| 14. | Check any defects or negativity in the property and comment in detail on survey form. |
| 15. | Do extensive market rate enquiries and confirm for any recent past transactions. |
| 16. | In case customer appears to be providing misleading information to you or trying to influence you by |
| - | money or cash then immediately report to the Management & Bank. |
| | |

| | SURVEY PROCESS COMPLIANCE CHECKLIST | 3 |
|-------|---|--------|
| | (To be submitted by Surveyor with each Survey) | |
| S.NO. | COMPLIANCE CHECKLIST POINTS | STATUS |
| 1. | Did you take proper property documents to carry out the survey? | Y) |
| 2. | Have you properly studied & highlighted Owner/ Area/ Boundaries in the property | V |
| | documents with bold florescent before moving for the survey? | / |
| 3. | Did you check prominent landmark nearby the subject property and mentioned in the survey form? | V |
| 4. | Did you identified the Property clearly by matching the boundaries and area mentioned in the property papers? | × |
| 5. | Did you check if property is merged with any other property or it is an independent property? | V |
| 6. | Did you do sample physical or google measurements of the property in case of property more than 2500 sq.mtr? | V |
| 7. | Did you check for any building violations in the property? | V |
| 8. | Did you check municipal limits/ jurisdiction/ ward? | V/ |
| 9. | Did you take Google Map location and shared it to Maps whatsapp group? | ×/ |
| 10. | Did you check Main road name & width and its distance from the subject property? | V/ |
| 11. | Did you check approach Lane width on which property is located? | V |
| 12. | Have you taken property full scale photograph with gate? | V |
| 13. | Have you taken owner/ representative photograph with the property? | V/ |
| 14. | Have you taken your selfie with the property along with owner/ representative? | V/ |
| 15. | Have you taken photograph of the property along with abutting road and towards left and right of the property? | |
| 16. | Have you taken multiple photographs of the property from inside-out? | V |
| 17. | Did you check nearby development and whereabouts and commented on survey form? | / |
| 18. | Did you check any defects or negativity in the property in terms of location, legality, | |
| | disputes, marketability, salability, etc. and commented on survey form in detail? | |
| 19. | Have you filled all the columns of survey form including survey summary sheet properly? | |
| 20. | Did you draw site key plan (location map)? | ·□ |
| 21. | Did you draw rough site sketch plan? | |
| 22. | Have you taken self-attested documents from owner/ representative and stamped "documents provided by stamp"? | |
| 23. | Did you check any defects or negativity in the property in terms of location, legality, disputes, marketability, salability, etc. and commented on survey form in detail? | |
| 24. | Have you confirmed any recent past transactions during market enquiries and enquired property rates locally very rigorously? | |
| 25. | Did you take signatures of the owner/ representative on undertaking and survey summary sheet? | |
| 26. | Did you signed the undertaking? | Ø |

| For File No. | PL 385 - Q090- |
|---------------|------------------|
| Surveyor Name | Shreyash Shetty. |
| Signature | Frash:S: |
| Date | 13/10/22. |

| | GENERAL SURVEY FORM (FOR PROPERTIES OTHER THAN FLATS) (Version 5.0) Date of implementation: 9.02.2011 Last Revision: 04.01.2018 Latest Revision: 31.10.2020 | | | | | |
|-----|--|--|--|--|--|--|
| | PL385-Q090- File No. RKA/DNCR// | Date: 13/10/22. Time: 6:00pm | | | | |
| 219 | | GENERAL DETAILS | | | | |
| 1. | Name of the Surveyor | | | | | |
| 2. | Property shown by | Shneyash Shitty. Owner, Representative, No one was available, Property is | | | | |
| | | locked, survey could not be done from inside | | | | |
| | | Name Contact No. | | | | |
| | | M. MIL -1 9766 2266 15 | | | | |
| 3. | Survey Type | Full survey (inside-out with measurements & photographs) | | | | |
| | | □ Half Survey (Measurements from outside & photographs) | | | | |
| | | □ Only photographs taken (No measurements) | | | | |
| 4. | Reason for Half survey or only | □ Property was locked, □ Possessee didn't allow to inspect the | | | | |
| | photographs taken N.A. | property, NPA property so couldn't be surveyed completely | | | | |
| 5. | How Property is Identified | □ From schedule of the properties mentioned in the deed, ↓□ From | | | | |
| | | name plate displayed on the property, V Identified by the owner/ | | | | |
| 2 | | owner representative, Enquired from nearby people, | | | | |
| | | □ Identification of the property could not be done, □ Survey was not | | | | |
| | | done | | | | |
| 6. | Type of Property | V Flat in Multistoried Apartment, Residential House, Low Rise | | | | |
| | | Apartment, Residential Builder Floor, Commercial Land & | | | | |
| | | Building, Commercial Office, Commercial Shop, Commercial | | | | |
| | | Floor, Shopping Mall, Hotel, Industrial, Institutional, | | | | |
| | | □ School Building, □ Vacant Residential Plot, □ Vacant Industrial Plot, □ Agricultural Land | | | | |
| 7. | Property Measurement | | | | | |
| 8. | Reason for no measurement | Self-measured, Sample measurement only, No measurement | | | | |
| | | It's a flat in multi storey building so measurement not required Property was locked, Owner/ possessee didn't allow it, | | | | |
| | | □ NPA property so didn't enter the property, □ Very Large Property, | | | | |
| | N.A. | | | | | |
| | | practically not possible to measure the entire area Any other Reason: | | | | |
| | | Reason | | | | |
| 9. | Purpose of Valuation | Value assessment of the asset for creating new collateral mortgage | | | | |
| | | □ Periodic Re-Valuation for Bank, □ Distress sale for NPA A/c., | | | | |
| | | □ For DRT Recovery purpose, □ Capital Gains Wealth Tax purpose | | | | |
| | | □ Partition purpose, □ General Value Assessment | | | | |
| 10. | Type of Loan | □ Housing Loan, □ Housing Take Over Loan, □ Home Improvement | | | | |
| | 1.200. | Loan, Loan against Property, Construction Loan, Educational | | | | |
| | Business Loan. | Loan, 🗆 Car Loan, 🗆 Project Loan, 🗆 Term Loan, 🗆 CC Limit | | | | |
| | | enhancement, 🗆 Cash Credit Limit, 🗆 Industrial Loan, 🗆 NA | | | | |
| 11. | Loan Amount | | | | | |
| | | | | | | |

| 1 | Legal Owner Name/s | OWNERSHIP DETAILS |
|----|---|------------------------------------|
| 2. | Property Purchaser Name | Mr. Ghanshyam Dhanjibhai Pholakia. |
| 3. | Property Address under Valuation | Same as above. Refer Pg. No. 2. |
| 4. | Present Residence Address of the Owner/ Purchaser | 7 |
| 5. | Property constitution | Free Hold, Lease Hold |

| | | LOCATIO | DN DETA | ILS | | | | |
|-----|---|-----------------------------------|---------------|---------------|------------------|-----------|-----------|-----------|
| 1. | Adjoining Properties | East | | West | N | orth | S | outh |
| | (Match it with papers with the help of compass or Sun direction and also confirm it with nearby people) | Other Bi Swartik Ind Estate | is loting C-1 | Wing. | Possa | ge & 1 | Mas | rid. |
| 2. | Property Facing | | ng, 🗆 Nort | h Facing, 🗆 | West Fa | cing, 🗆 S | outh Fac | ing, |
| | | D North-East | t Facing, [| South-We | est Facing | , 🗆 South | n-East Fa | icing, |
| | | North-Wes | st Facing | | | | | |
| 3. | Landmark | Insignia | Britdin | o. Rum | er Kin | a Kali | ing. | |
| 4. | Ward Name/ No. | | | g, ong | 6 (0) | Juco | 1.51 | |
| 5. | Zone Name | | | | | | | |
| 6. | Main Road Name & Width | Nam | e | (3Lan | dth e - 1 Way | Distan | ce from | property |
| | | Santacru | z - (1 | | | | | 1 |
| 7. | Approach Road Name & Width | Santacri | 12 - G | hembu | r Link | Road | • | |
| 8. | Location consideration of the | U Within Ma | | | | | | Within |
| | Society | developing an | rea, 🗆 Hig | hly posh lo | cality, 🗆 \ | /ery Good | Goo | d, |
| | | 💟 Ordinary, | □ In inter | iors. 🗆 Rei | mote area | Back | ward. 🗆 | Average |
| | | | | | | | | Julia |
| | | Poor | | | | | | |
| 9. | Special Location consideration | D Park Faci | ng, 🗆 Po | ol Facing, | Road | Facing, 🗆 | Entran | ce North- |
| | of the property | East Facing, | 🗆 Sunligh | t facing | | / | | |
| 10. | Characteristics of the locality | 🗆 Urban dev | eloped, V | Urban dev | eloping, | Semi Ur | ban, 🗆 I | Rural, |
| | | Backward, | Industri | al, 🗆 Instit | utional | | | |
| 11. | Category of Society/ locality | High End, | Normal | Afforda | bla Crow | Housing | | |
| | sategory of oboletyr locality | | | | ble Group | Housing | , | |
| 12. | Utilities/ Facilities in the locality | Lifts, 🗆 Ga | | andscapin | g, 🗆 Swin | nming Poo | ol, 🗆 Gyi | n, |
| | | Club Hous | se, 🗆 Wa | ilk Trails, [| Kids pl | ay zone, | 100 | % Power |
| 13. | Provimity to sivia amonitian | Backup | | | | - | 21.11 | |
| 13. | Proximity to civic amenities | | Hospital | Market | Metro | Railway | Station | Airport |
| 14 | Any now development is | 290m | 850m | 650m | WIP. | 1-4k | im. | 2.1km |
| 14. | Any new development in | | | | | | | |
| | surrounding area | (| | | | | | |

| 15. | Jurisdiction limits | 🗆 Nagar Nigam, 🗆 Nagar Panchayat, 🗆 Gram Panchayat, 🗆 Naga | |
|-----|----------------------------|---|--|
| | BMC. | Palika Parishad, Area not within any municipal limits | |
| 16. | Jurisdiction Development | □ DDA, □ GDA, □ NOIDA, □ GNIDA, □ YEIDA, □ HUDA, □KMDA, | |
| | Authority Name | MDDA, Any other Development Authority: | |
| | M.M.R.D.A. | □ Area not within any development authority limits | |
| 17. | Municipal Corporation Name | □ NDMC, □ SDMC, □ EDMC, □ Ghaziabad Municipal Corporation, | |
| | | □ Gurgaon Municipal Corporation, □ Faridabad Municipal Corporation, | |
| | BMC. | □ Kolkata Municipal Corporation, □ Dehradun Municipal Corporation, | |
| | | □ Area not within any municipal limits, □ Any other Municipal | |
| | | Corporation/ Municipality: | |

| 162 | PHYSICAL DETAILS | | | | |
|-----|--|--|--|-------------------------|--|
| 1. | Land Area | As per Title deed | As per Map | As per site survey | |
| | | | | | |
| 2. | Any conversion to the land use | Not known + | o wus | 1 | |
| 3. | Land Type | Solid, CRocky, Colored | Solid, CROCKY, Marsh Land, Reclaimed Land, Water logged, Land locked | | |
| 4. | Shape of the Land | □ Square, □ Rectangu ☑ Irregular, □ NA | lar, 🗆 Trapezium, 🗆 T | riangular, 🗆 Trapezoid, | |
| 5. | Level of Land | 🗆 On road level, 🗆 Bel | ow road level, Above | e road level, | |
| 6. | Frontage to depth ratio | 🗆 Normal frontage, 🗸 L | □ Normal frontage, V Less frontage, □ Large frontage, □ NA | | |
| 7. | Are Boundaries matched | □ Yes, □ No, □ No relevant papers available to match the boundaries, □ Boundaries not mentioned in available documents | | | |
| 8. | Is Independent access available to the property | Clear independent access is available, Access available in sharing of other adjoining property, No clear access is available, Access is closed due to dispute | | | |
| 9. | Is property clearly demarcated with permanent boundaries? | Yes, No, Only with Temporary boundaries | | | |
| 10. | Is the property merged or colluded with any other property | No, not merged. | | | |
| 11. | Property possessed by at the time of survey | □ Owner, ✓ Vacant, □ Lessee, □ Under Construction, □ Couldn't be Surveyed, □ Property was locked, □ Bank sealed, □ Court sealed | | | |
| 12 | Current activity carried out in the property | Residential purpos | | | |

| | BUILDING/ CONSTRUCTION/ UTLITY DETAILS | | |
|----|--|---|--|
| 1. | Construction Status | □ Built-up property in use, V Under construction, □ No construction | |

| - A | | | | |
|-----|--|--|--|--|
| 12. | Covered Built-up Area | Covered Area, Floor Area, Super Area, Carpet Area | | |
| | (Tick one on the basis of which | As per Title deed As per Map As per site survey | | |
| | valuation is to be calculated) | Carpet-121.20 Carpet. So. mitrs - 1377.45759.Ft | | |
| 3. | Total Number of Floors in the | 3 Basements + Lower GF+ Upper GF+13+ Podium | | |
| | Building | | | |
| 4. | Floor on which property is situated | Floor + 2nd to 13 Floors. | | |
| | | 5th Floor. | | |
| 5. | Type of Unit/ Number of Rooms/ Cabins/ Cubicles | 4 Bedrom, Hall; Kitchen, Store Room, Washroom | | |
| 6. | Building Type | RCC Framed Structure, Load bearing Pillar Beam column, | | |
| | | □ Ordinary brick wall structure, □ Iron trusses & Pillars, □ Scrap | | |
| | | abandoned structure | | |
| 7. | Roof | a. Make: RBC, RCC, GI Shed, Tin Shed, Stone Patla | | |
| | | b. Height: 8.9 Ft. | | |
| | | c. Finish: Simple plaster, POP Punning, V POP False | | |
| | | Øeiling, □ Coved roof, □ No plaster | | |
| 8. | Flooring | VI Vitrified tiles, Ceramic Tiles, Simple marble, Marble | | |
| | | chips, Mosaic, Granite, Italian Marble, Kota stone, | | |
| | | □ Wooden, □ PCC, □ Imported Marble, □ Pavers, □ Chequered | | |
| | | Tiles, Brick Tiles, No Flooring, Under construction, Any | | |
| | | other type: | | |
| 9. | Appearance/ Condition of the | Internal - Excellent, Very Good, Good, Ordinary, | | |
| | Building | □ Average, □ Poor □ Under construction, □ No Survey | | |
| | | External - Excellent, Dery Good, Good, Ordinary, | | |
| | | Average, Poor Under construction | | |
| 10. | Maintenance of the Building | Very Good, Average, Poor, Under construction | | |
| 11. | Interior decoration | □ Excellent, □ Very Good, □ Good, ∨ Simple, ∨ Ordinary, □ Average, □ Below average, ∨ Under construction, □ No Survey | | |
| 12. | Interior Finishing | Simple plastered walls, Brick walls without plaster, | | |
| | | □ Designer textured walls, □ POP punning, □ Coved roof, | | |
| | | v Under construction, □ No Survey | | |
| 13. | Exterior Finishing | Simple plastered walls, Brick walls without plaster, | | |
| | | □ Architecturally designed or elevated, □ Brick tile Cladding, | | |
| | | □ Structural glazing, □ Aluminum composite panel cladding. | | |
| | | □ Glass façade, □ Domb, □ Porch, □ Under construction | | |
| 14. | Kitchen | □ Simple with no cupboard, □ Ordinary with cupboard, □ Normal | | |
| | | Modular with chimney, High end Modular with chimney, Under | | |
| | | construction, No Survey | | |
| 15. | Class of Electrical fittings | External, Internal | | |
| | | □ Ordinary fixtures & fittings, □ Fancy lights, □ Chandeliers, | | |
| 10 | | Concealed lightning Under construction, INo Survey | | |
| 16. | Class of Sanitary/ Plumbing & water supply fittings | External, Internal | | |
| | water supply nutrigs | □ Excellent, □ Very Good, □ Good, ☑ Simple, □ Average, □ Below average, ☑ Under construction, □ No Survey | | |
| 17. | Water arrangements | ☐ Jet pump, ☐ Submersible, ☐ Jal board supply | | |
| 18. | Water arrangements Fixed Wooden Work | □ Excellent, □ Very Good, ☑ Good, □ Simple, □ Ordinary, | | |
| 10. | | □ Average, □ Below Average, □ No wooden work, □ No survey | | |
| 19. | Age of Building/ Recent | | | |
| | Improvements done | 14 par. | | |
| 20. | Maintenance of the Building | Very Good, 🗆 Average, 🗆 Poor | | |
| | | | | |

| 21. | Any defects in the building | Maintenance issues, Finishing issues, Seepage issues, | | | |
|---------------------|------------------------------------|---|--------------------------------------|--|--|
| | | □ Water supply issues, □ Elect | tricity issues, 🗆 Structural issues, | | |
| | | □ Visible cracks in the building | | | |
| 22. | Any violation done in the property | □ Construction done without | Map, Construction not as per | | |
| | | approved Map, 🗆 Extra covered | d without sanctioned Map, | | |
| | | adjacent property, Encroache | ed adjacent area illegally | | |
| 23. | Boundary Wall (Only for individual | Yes, 🗆 No, 🗆 Common bour | ndary wall of a complex | | |
| | property) | Running Mtr. Height | Width Finish | | |
| | | | | | |
| 24. Lift/ elevators | Lift/ elevators | Passenger/ Commercial | | | |
| | 26Fts. | Make: KONE | Capacity: 13 Person. | | |
| 25. | Power backup | □ Inverter, ☑ DG Set | | | |
| | | Make: | Capacity: | | |
| 26. | Garden/ Landscaping | □ Yes, V No, □ Beautiful, □ C | ordinary | | |
| 27. | Parking facilities | Available within the property | On Ground, In Basement, | | |
| | | Podium. | On stilt | | |
| | | Not available within the | On road, Acute parking | | |
| | | property | problem | | |
| 28. | Special Comments/ Observations, | | | | |
| | if any | | | | |
| | | | | | |
| | | | | | |

| | MARKETABILITY/ SELABILITY/ UTLITY DETAILS | | | |
|----|---|--|--|--|
| 1. | Any issues in marketability of the | Yes, □ No | | |
| | property? | Reason in case of No: Location, Surrounding, Legal | | |
| | | aspects, Demand, Shape, Any Other: | | |
| - | | | | |
| 2. | How is Demand & Supply condition | Demand Uvery Good, Good, Average, Low, Poor | | |
| | in the Market of such properties? | Supply Very Good, Good, Average, Low, Poor | | |
| 3. | Is property easily sellable & marketable? | VZ Yes, 🗆 No | | |
| | | Comments: | | |
| | | | | |
| 4. | How is the current utility of the property? | □ Excellent, □ Very Good, √ Good, □ Average, □ Low, □ Poor | | |
| 5. | At what True rate Owner bought | Year of purchase 2017. | | |
| | this Property? | Purchase Price | | |
| 6. | Present expected Sale Value of the overall property? | G CR | | |

BLANK PAGE FOR PROVIDING ANY ADDITIONAL DETAILS/ INFORMATION

3 Master Bedroom. 1 Bedroom. 1 Hall & Kitchen. 1 Washroom. 1 Store Room.

 $34 \cdot 21 \times 16 \cdot 7 = 571 \cdot 307$ $12 \cdot 26 \times 28 \cdot 66 = .351 \cdot 37 \cdot$ $19 \cdot 435 \times 23 \cdot 40 = 454 \cdot 78$ $\overline{1377} \cdot 457$

| S.No | Particulars | ble for Sale of Subject | MPARABLE RATE IN Transaction already | happened in past) | and the second second |
|------|--|----------------------------|---|-----------------------------------|--|
| | | Property | Comparable 1 | Comparable 2 | Comparable 3 |
| 1. | Name (source of information) | NA | Mr. Jay | Survise Estat | e Paras |
| 2. | Contact No. | NA | 9820773190 | 9702909488 | |
| 3. | Type of source of information (Seller/ Property dealer/ nearby people) | NA | Douler. | Dealer. | 88799 89196. Dealer |
| 4. | Rates/ Price informed (in Rs. with unit) | NA | 35,000 - 45,000 per sq. Ft. | 38,000 tous,00 persq.ft on per | = 35,00 to |
| 5. | Rates Type (Sale/ Buy) | NA | Safe. | persquift oper Sale. | Couplet Sale |
| 6. | Shape of the Property (Square, Rectangular, Irregular) | | Irregular. | Irregular. | Ingolar |
| 7. | Area/ Size of the Property | | 1340 Sq. ft Carpet Clear. | 13 ho sq. ft. Carpet. | (340 90 Et 1 1340 90 Et |
| 8. | Legal Status (clear, negative, weak)/ No. of owners | | clear. | Clear. | Clear |
| 9. | Location/ surrounding/ neighborhood comparison with the subject property (Similar, Lower, Better, Highly Better than the subject Property) | Base Case | Same. | Same | Same |
| 10. | Distance from the subject Property | 0 | 0 | 0 | 0 |
| 11. | Other factors (Comer, 2 side open, North-East facing, Park facing, Legal/ Financial encumbrance, etc.) | | Same. | Same | Same |
| 12. | Approach road width | | Same. | Same. | Similat |
| 13. | Level of Land (Below/ On/ Above road level) | | 3 Above. | Above. | Aore. |
| 14. | Frontage to depth ratio (Normal, Less, Large) | | Less | Less | Less |
| 15. | Present Use | | Vacant. | Vacant. | Vacant |
| 16. | Any other details/ Discussion held | NĂ | According to him rates are around Rs. 35,000 to 40,000 / 29. Ft. On Compet. | 0.000 | a According 3000000000000000000000000000000000000 |
| 17. | Present expected Sale Value of the overall property? | | GCR. | F C | mper |

UNDERTAKING BY THE CUSTOMER

I confirm that I have made the inspection of the subject property to the surveyor of R.K Associates, which is correct property in question for which the documents have been provided/ submitted by me. I further confirm that I am aware of all the information related to the subject property and I have provided all its information to the surveyor true to the best of my knowledge. I understand that any false or manipulative information provided by me will be considered as cheating with the professional organization since it will lead to incorrect valuation report and I'd be solely responsible for this unlawful act and will bear the charges for the changes/ modifications which have to undergo due to the false information. I also undertake that I have not given any cash or in kind to any member of R.K Associates to influence the Value of the Property or favor any individual or organization and the same is not accepted or asked by the member of R.K Associates. Any such act will lead to cancellation of the material prepared by R.K Associates with forfeiting of the fees and i'll be completely responsible for its repercussions and legal actions taken for it.

IMPORTANT: We have not authorized any of our person/ Surveyor to take Cash or kind from the customers in any situation. In case Surveyor or any member of R.K Associates asks for any money or kind from you then kindly please inform on number +91-9958632707, 0120-4110117. Our Valuation process is very stringent and have multiple check points to ensure correct & error free reports to keep the lending agency risk free. In case Surveyor claims that he would be able to arbitrary effect the Valuation figures unfairly or as per your requirement & need, then he is making a false claim to you and we request you to complaint such act immediately on the number provided above.

| Name | Umesh Sarliya |
|-------------------------|---------------|
| Relationship with owner | Employe |
| Signature | Quest |
| Mobile No. | 9766226615 |
| Date | 13/10/22. |

UNDERTAKING BY THE SURVEYOR

I confirm that I have carried out the Survey of the property properly as per the fair professional best practices and Valuation & Survey policy guidelines issued by R.K Associates. I have not taken any cash or kind from the customer nor have I come into any kind of influence of the customer I bank for arbitrary providing the Property Valuation as per one's need. I further state that I have not given any assurances to the customer nor given any wrong or false information or statement. In case at any point of time it is found that I have done any kind of fraudulent activity in this case and misled the company then I understand its legal consequences and appropriate penal action which company can take against me. Also in regard to it any monetary or reputation loss will be recovered from me by the company.

| For File No. | #PL385-Q090- |
|---------------|------------------|
| Surveyor Name | |
| <u>.</u> | Shreyash Shetty. |
| Signature | Brash S- |
| Date | |
| | 13/10/22 |



Enclosure: 6

SURVEY SUMMARY SHEET (TO BE ENCLOSED WITH VALUATION REPORT)

(Version 1.0) | Date of implementation: 10.04.2017

Every Valuation report at R.K Associates is prepared based on the thorough survey of the property carried out by our Engineering Surveyor. This Survey Summary Sheet is for the information of Banker/ concerned interested organization. Detailed Survey Form can also be made available to the interested organization in case it is required to cross check what information our surveyor has given in site inspection report based on which Valuation report is prepared.

| | 1 | 2.0.1. | | | |
|------|---|---|--|------------------------------|--|
| 1. | File No. | PL385-Q000 " | 90 ~ | | |
| 2. | Name of the Surveyor | Streyash Shetty. | | | |
| 3. | Borrower Name | | anjibhai Phol | akia. | |
| 4. | Name of the Owner | Mr. Chanshyam Dhan | ji bhai. Dholak | va. | |
| 5. | Property Address which has to be valued | Flat 503, 5th Floor, B-6 | Ning Insignia B | wilding, BKC, MMRDA | |
| 6. | Property shown & identified by at | Area, Kaling Santacruz E | | | |
| 0. | spot | □ Owner, ☑ Representative, □ N could not be done from inside | to one was available, L | - Froperty is locked, survey | |
| | spor | Name | | Contact No. | |
| | | | 07.000 | | |
| 7. | How Property is Identified by the | Mr. Umesh. | 976622 | 26615. | |
| 7. | Surveyor | | | | |
| | Surveyor | displayed on the property, V Ide | | · | |
| | | Enquired from nearby people, | Identification of the p | roperty could not be done, | |
| | | □ Survey was not done | | | |
| 8. | Are Boundaries matched | 🗆 Yes, 🗆 No, 🗆 No relevan | | o match the boundaries, | |
| | | Boundaries not mentioned in av | | | |
| 9. | Survey Type | VZ Full survey (inside-out with mea | 10 A A A A A A A A A A A A A A A A A A A | | |
| | | Half Survey (Measurements fro | om outside & photogra | phs) | |
| | | Only photographs taken (No me | easurements) | | |
| 10. | Reason for Half survey or only | Property was locked, Posses | □ Property was locked, □ Possessee didn't allow to inspect the property, □ NPA | | |
| | photographs taken N-A. | property so couldn't be surveyed c | completely | 1874 82 27 1980 - | |
| 11. | Type of Property | Flat in Multistoried Apartment, | , 🗆 Residential House, | □ Low Rise Apartment, □ | |
| | | Residential Builder Floor, 🗆 Comm | mercial Land & Buildin | g, 🗆 Commercial Office, 🗔 | |
| | | Commercial Shop, 🗌 Commercial | I Floor, Shopping N | Aall, 🗆 Hotel, 🗆 Industrial, | |
| | | 🗆 Institutional, 🗆 School Building | | | |
| | | Plot | | | |
| 12. | Property Measurement | V Self-measured, Sample mea | surement, 🗆 No meas | surement | |
| 13. | Reason for no measurement | L It's a flat in multi storey buildin | | | |
| | | Property was locked, Owne | | | |
| | | didn't enter the property, 🗆 V | | | |
| | N.A. | measure the area within limited ti | | | |
| 14. | Land Area of the Property | | | | |
| 14. | Land Area of the Property | As per Title deed | As per Map | As per site survey | |
| 15. | Covered Built-up Area | | <u></u> | | |
| 1.3, | A | As per Title deed | As per Map | As per site survey | |
| 16. | Property possessed by at the time of | - 121.20 sq. mt. | | 1377.457 sq.Ft. | |
| | survey | Owner, Vacant, Lessee, Property was locked D Bank or | | h, 🗀 Couldn't be Surveyed, | |
| 17. | Any negative observation of the | Property was locked, D Bank se | ealed, LI Court sealed | | |
| | And the second | | | | |

| | property during survey | |
|-----|--|---|
| 18. | Is Independent access available to the property | Clear independent access is available, adjoining property, No clear access is available, Access is closed due to dispute |
| 19. | Is property clearly demarcated with permanent boundaries? | Yes, 🗆 No, 🗆 Only with Temporary boundaries |
| 20. | Is the property merged or colluded with any other property | Nor not marged. |
| 21. | Local Information References on property rates | Please refer attached sheet named 'Property rate Information Details.' |

Endorsement:

1. Signature of the Person who was present from the owner side to identify the property:

Undertaking: I have shown the correct property and provided the correct information about the property to the surveyor of R.K Associates to the best of my knowledge for which Valuation has to be prepared. In case I have shown wrong property or misled the valuer company in any way then I'll be solely responsible for this unlawful act.

- а.
- b.
- c.
- d.
- Name of the Person: Umesh Sarligg Relation: Employe. Signature: Omes Date: 13/10/22.

In case not signed then mention the reason for it: 🗌 No one was available, 🗌 Property is locked, 🗋 Owner/ representative refused to sign it,
Any other reason:

2. Surveyor Signature who did site inspection:

Undertaking: I have inspected the property and cross verified the property details at site to the extent of a. Matching boundaries of the property, b. Sample measurement of its area, c. Physical condition, d. Property rates as per local information with what is mentioned in the property documents provided to me by the Bank/ interested organization. I have not come under influence of anyone during site inspection and have only recorded the true and factual details in the survey form which I come across during the site survey. I understand that giving any manipulative information in the survey form will lead to incorrect Valuation report which is an unlawful act and i'll be solely responsible for doing it.

a.

Signature: b.

с.

Name of the Surveyor: Shreyash Shetty. Signature: Thesh.S. Date: 13/10/22.