


Structural Damages in the Building At various Location
























Facade - Falling Stone & Damages to
Glazing in the Building
At various Location
Cleaning & Restoration of Stone

































MEP Damages in the Building At various Location














































Public Area Damages in the Building At various Location






















































External Area Damages in the Building At various Location



Room Damages in the Building At various Location





