

VIS(2022-23)-PL445-257 → 670 to 673 (Hali Bering, Chaitanyapur, Bunderpur & Gernkhal)



REINFORCING YOUR BUSINESS
ASSOCIATES

M/S Haldia Water Services
Pvt. Ltd., 4 plants at
different locations.

File No.	RKA/DNCR/...../.....
Date of Receiving	

**CASE COLLECTION FORMAT
(INDUSTRIAL PLANT SURVEY FORM)**

(Version 2.1) | Date of implementation: 9.02.2011 | Date of Revision: 04.01.2018, 30.01.2020

Items	Assigned To	Assigned to Date	To be completed by date	Submitted On date	Grade	HOD Engg. Signature
File Received By	Praveen	NA	NA			NA
Survey	Arun Kumar Raj					
Preparation						

A - Very Good, B - Satisfactory, C - Average, D - Poor, E - Extremely Poor

File Returned to HOD Engg. unprepared due to reason	☐ Proper documents not received, ☐ Survey not done properly, ☐ Survey Form not properly filled, ☐ Market survey for rates is not properly done, ☐ Identification is not clearly done, ☐ Measurement is not properly done, ☐ Photographs not clearly taken, ☐ Selfie/ Owner or owner representative photo not taken, ☐ Owner/ owner representative signature not taken, ☐ Google Map not taken, ☐ Survey summary sheet not filled

In case File is returned by the preparer - HOD Engg. comment & Signature

☐ Minor defects in the survey hence approved for preparation with warning to Surveyor. Report preparer to collect the missing information on his own.

☐ Major defects in the survey. Survey has to be done again.

GENERAL DETAILS

1.	Proposal or Ref. No.			
2.	Type of Service	☒ Valuation Report		
3.	Type of customer	☐ Bank	☐ PSU	☐ NBFC
		☐ Company	☒ Private client	☐ Direct client through Bank
4.	Bank/ FI/ Organization/ Name & Address	Haldia Water Services Pvt. Ltd.		
5.	Case Allotment Officer/ Fees paying party Details	Name Sandip Chakraborty	Contact Number 9647292227	Email Id Purchase@haldiaservices.com
6.	Case Type	☒ Case for Fresh Account		☒ Case for existing account/ customer
7.	Fees Details	Amount of Fees Rs 75000 + GST	Advance Amount if any 35% paid	Payment will be paid by ☐ Bank ☒ Customer
8.	Billing Details	Billed To Party Name		GSTIN

CASE DETAILS

1.	Name of the Industry/ Account	M/S Haldia Water Services pvt. Ltd.		
2.	Type of Property	☒ Small Manufacturing Unit, ☐ Medium Scale Industrial Unit, ☐ Large Scale Industrial Plant, ☐ Very Large Scale Industrial Plant		
3.	Owner/ Applicant Details	Name	Contact Number	Email Id
4.	Account Name	HDA (HDA gave all plants to HWSPL on lease)		
5.	Plant Address	M/S Haldia Water Services pvt. Ltd.		
6.	Who will coordinate on site for the site survey	Name	Contact Number	
7.	Preferred time of survey	Date	Time	
8.	Documents Received (Any one ownership document and approved site plan/ map is must)	5 plants in 5 different location. Respective address mentioned below.		
9.	Special Instructions if any:	Sourin Sengupta → 9069367805 Sandeep Chaurabarty → 9647292227		
10.	I agree to pay the amount mentioned above for the preparation of Valuation Report. I agree that I'll not put pressure on Valuer firm to distort any facts and would not try to influence any member or official of the firm in the ill spirit or vested interest and to benefit any individual or organization by any means illegitimately.	Date: 26/12/22 to 28/12/22		

1. Ownership Documents: ☐ Sale Deed, ☐ Power of Attorney, ☐ Will Relinquishment Deed, ☐ Transfer Deed, ☐ Conveyance Deed, ☐ Allotment Letter, ☐ Possession Letter, ☐ Agreement to Sell, ☐ Mortgage Deed, ☐ Indenture of Mortgage

2. Map: ☐ Cizra Map, ☐ Sanctioned Map, ☐ Site Plan

3. Project Approval Documents: ☐ Factory Registration, ☐ Memorandum of Understanding with the State Govt., ☐ Industrial Entrepreneurs Memorandum, ☐ Environment Clearance, ☐ Fire NOC

4. Any Other document: ☐ TIR Report, ☐ Old Valuation Report, ☐ Plant & Machinery Inventory Sheet, ☐ Fixed Asset Register, ☐ Building Area Statement, ☐ CLU Document, ☐ Detailed Project Report, ☐ Invoices of the Major Equipment's, ☐ Daily Performance Report, ☐ TEV Report, ☐ LIE Report, ☐ Production data of last one week, ☐ Plant maintenance log, ☐ Copy of last paid Electricity Bill, ☐ Copy of municipal tax receipt

5. No documents provided: ☐

6. Any other: ☒ Stock excel sheet and company (HWSPL) sealed Hard copy of stock sheet

7. Customer Signature:

All 5 plants are owned by HDA. The plants are given on lease for operation & maintenance. The lease was given on 2019 for 15 yrs as informed by Tapan Trepathe (company official)

① Basuderpur Plant address (Pumping station)

Basuderpur pumping station, Vill. → Basuderpur,
P.O. → Kharjanchak, Dist. → Purba Medinipur, Pin- 721602
West Bengal, Landmark → Anashganga complex.

② Chaitanyapur plant address (Pumping station)

Vill. & P.O. → Chaitanyapur, P.S. → Sutahata, Pin- 721645
Dist. → Purba Medinipur, (W.B.), Landmark → PHE
Pump House.

③ Hatibesia Plant Address (Pumping station)

Village → Chack Tarawa (Padmapukur), P.O. → Haldia Township,
P.S. → Haldia, Dist. → Purba Medinipur, Pin → 721657
(W.B.).

④ Geonkhali New WTP address

Vill. → Gopalchak, P.O. → Rajaniganje, P.S. → Mahishadal,
Dist. → Purba Medinipur, Pin → 721603 (W.B.)

⑤ Geonkhali Old WTP address

Vill. → Suklalpur, P.O. → Geonkhali, Purba Medinipur (W.B.)
Pin → 721603

IMPORTANT INSTRUCTIONS

*FILE PREPARER TO START PREPARING THE FILES ONLY AFTER ENSURING THE STATUS OF ALL THE BELOW POINTS IS COMPLETED. FOR ANY EXCEPTION PLEASE BRING IT INTO NOTICE OF SENIOR GENERAL MANAGER (OPERATIONS), OTHERWISE PENAL ACTION WILL BE TAKEN AGAINST THE FILE PREPARER.

1.	Please do not accept the case if you do not have proper documents.
2.	Understand the nature of Industry before moving for survey
3.	Study the Plant Inventory sheet or FAR properly before moving for survey
4.	Firstly please take & study the current applicable ownership documents of the property which needs to get surveyed.
5.	Mark the Owner/ Area/ Boundaries mentioned in the ownership documents with bold florescent marker pen before moving for the survey. During site survey if any difference is found in the above fields from the ownership documents then please contact the owner immediately to know the reason for the difference.
6.	Identify the Property clearly by matching the boundaries and area mentioned in the property papers.
7.	Check whether Building Measurement Area is given in the Map or if they have any Building Area sheet or if self-measurement has to be carried out before moving for survey.
8.	Take Google Map location.
9.	Take one photograph of the property along with abutting road.
10.	Take nearby photographs of the Property.
11.	Check Jurisdiction Municipal Limits & Ward Name.
12.	Fill the details in the Survey form and tick the appropriate option clearly.
13.	In case customer is found providing misleading information to you or trying to influence you by money or cash then immediately report to the Management & Bank.

S.No.	CHECKLIST	STATUS
1.	IS PURPOSE OF THE ASSIGNMENT UNDERSTOOD CLEARLY	☒
2.	IS WORK ORDER/ EMAIL/ CESA FORM FORMALITY COMPLETED	☒
3.	FOR PRIVATE CASE OR FOR FRESH CASE 50% ADVANCE IS RECEIVED	☒
4.	IS DOCUMENT CHECKLIST PROVIDED TO THE CUSTOMER	☒

S.NO.	CHECKLIST	STATUS
1.	Check nearby prominent landmark	☒
2.	DO CLEAR IDENTIFICATION OF THE PROPERTY	☒
3.	Match the boundaries of the property and its directions with the help of compass or sun direction	☐
4.	Do sample measurement	☐
5.	CHECK IF ANY BUILDING VIOLATIONS DONE	☐
6.	Click multiple proper photographs of the property from inside-out	☐
7.	Take selfie with the available representative	☐

Not in scope of work

only stock photos taken

8.	Send Google Map location at maps@rkassociates.org	☒
9.	Check municipal jurisdiction	☒
10.	Check Main road name & width and its distance from the subject property	☒
11.	Check Lane width on which property is located	Not in scope ☐
12.	Check any defects or negativity in the property	Not in scope ☐
13.	CONFIRM PROPERTY RATES LOCALLY	u ☐
14.	CHECK NEARBY DEVELOPMENT	u ☐

SPECIAL INSTRUCTIONS:

1. During Survey please follow the blocks mentioned in the plant layout and clearly mention the details of each block. Use separate sheet wherever space is not adequate in the form.
2. During survey please keep P&M inventory sheet in hand and cross check the machines from the list.
3. Mention type, height & area of shed of each block clearly.
4. Take photographs of the machines including its machine plate.
5. In case machine is not in running condition then test the condition of the machine by moving its lever, pulley and check oil condition.

SURVEY GRADING MATRIX	
GRADE	PARAMETERS/ CRITERIA
A	In case all the points below are done properly, timely with full care and diligence: 1. Survey started with proper work order and knowing the source of payment. 2. Survey done with proper documents. 3. Done complete homework and studied the documents properly with highlighting the main points before moving for the survey. 4. Chosen correct survey form as per the property type. 5. All fields of Survey form are properly filled. 6. All site special observations and negative and positive factors are clearly mentioned. 7. Self & client signatures taken on survey form. 8. Property rates information properly taken, mentioned and verified. 9. Site rough sketch plan made. 10. Proper photographs taken. 11. Selfie with property taken. 12. Selfie and owner photograph with property taken.
B	In case of 3 minor mistakes in any of the above points except Point 1, 2, 3, 4, 6, 8, 10, 11, 12 but all the points are covered.
C	In case of more than 3 minor mistakes and any 1 major mistake in any of the above points and if any points are completely missing except Point 1, 2, 3, 4, 6, 8, 10, 11, 12.
D	In case of 1 major mistake or missing of any 1 point out of 1, 2, 3, 4, 6, 8, 10, 11, 12.
E	In case of more than 1 major mistakes or missing of more than 1 point out of 1, 2, 3, 4, 6, 8, 10, 11, 12.

Note (Survey Grading Matrix):

1. For special assignments like LIE, Stock Valuation, etc. where till date survey format is not specified or released, in such cases point wise site observation report has to be submitted by the Surveyor duly signing it properly. Without signed Site Observation report, Point 4 will be considered as not done and will fall under Category E.
2. Similar Grading Matrix is issued for Case Collection & Report Preparation as well

Note (Overall Grading Matrix):

1. In case client reports any careless mistake in the report for which revision has to be done in the report then in that case Grading Matrix may be revised and Grade E will be awarded.

Stocks of HWS PL lying in old WP has been checked, based on the list shared from their end. I shared the same on VIS.

INDUSTRIAL PLANT SURVEY FORM

(FOR INDUSTRIAL PROPERTIES ONLY)

(Version 2.0) | Date of implementation: 9.02.2011 | Date of Revision: 04.01.2018, 15.06.2019

File No. RKA/DNCR/...../.....

Date:

Time:

GENERAL DETAILS

1.	Name of the Surveyor	Anishan Roy / Rajat Kr. Choudhary	
2.	Property shown by	☐ Owner/ Director, ☒ Company Representative, ☐ No one was available, ☐ Property is locked, survey could not be done from inside	
		Name	Contact No.
		Sorik Samanta	9064367805
		Sandeep Chakraborty	9647292227
3.	Survey Type	☐ Full survey (inside-out with approximate measurements & photographs), ☐ Full survey (inside-out with approximate sample random measurements & photographs), ☐ Half Survey (Approximate sample random measurements from outside & photographs), ☐ Only photographs taken (No measurements)	
4.	Reason for Half survey or only photographs taken	☐ Property was locked, ☐ Possessee didn't allow to inspect the property, ☐ NPA property so owner was hostile and survey couldn't be carried out, ☐ Under construction property, ☐ Very Large irregular Property, practically not possible to measure the entire area, ☐ Any other reason:	
5.	How Property is Identified	☐ From schedule of the properties mentioned in the deed, ☐ From name plate displayed on the property, ☒ Identified by the owner/ owner representative, ☐ Enquired from nearby people, ☐ Identification of the property could not be done, ☐ Survey was not done	
6.	Type of Industry	☐ Small Manufacturing Unit, ☐ Medium Scale Industrial Unit, ☐ Large Scale Industrial Plant, ☐ Very Large Scale Industrial Plant	
7.	Property Measurement	☐ Self-measured, ☐ Sample measurement only, ☒ No measurement	
8.	Reason for no measurement	☐ Property was locked/ sealed, ☐ Owner/ possessee didn't allow it, ☐ NPA property so didn't enter the property, ☐ Very Large Property, practically not possible to measure the entire area ☐ Any other Reason:	
9.	Purpose of Valuation	☐ Value assessment of the asset for creating collateral mortgage, ☐ Periodic Re-Valuation for Bank, ☐ Distress sale for NPA A/c.	

Valuation of stock

The stocks lying in Basudanpur, Hatibera, Chaitanyapur belongs to HDA. Some stocks lying in old WP of geonkhali belongs to HWS PL. Plz ask bill/ receipt of the same from them. However stocks lying in New WP belongs to HDA. ~~Some of the PL~~

* Please note:-

- 1) HWSPL has shared two stock list to us:-
 - one is ^{shared} via mail on 14 Dec, 2022, this list (HDA list)
 HWSPL has got from HDA. According to HWSPL
 officials this list is 60% correct. They believe the
 actual quantity of stocks is not shared in the list
 upto total extent, only 60% is given. This list has
 been shared prior to site visit.

- The another list ^{was} shared on 26 Dec, 2022 via
 mail and hard copy, during our site visit. This list
~~was~~ is ~~slightly~~ updated, as officials from HWSPL
 has made this list. According to the verbal discussion
 with their official, we came to know this.

- we have cross checked Geonkhali OWTP & NWTP
 stores from the updated list, prepared from HWSPL's end.
 Geonkhali OWTP has 2 stores & 1 store yard. Geonkhali
 NWTP has only 1 store. ^{the stock yard at OWTP has been}
 checked via HWSPL list. ^{However, officials}
^{unable to detect anything}

- we have cross checked Chaturapur stores & yards from
 both HDA list & HWSPL list. store 3 & 4 has been
 cross checked via HWSPL list, store 2 has been cross
 checked via HDA list & 2 store yard has been cross
 checked by HDA list. ^{Due to shade fear, and dense vegetation}
^{majority of store yard & store 1}
^{unable to access}

- Based on cross checking done via HWSPL list & HDA
 list, the store yard cross checked via HDA list &
 store 1 & 2 via HWSPL list.

- Hatibedia unit has been cross checked ^{via} HWSPL list. Only store items were verified. ~~No items were present~~ one or two scrap and rust pipes were present in a yard. ^{RO In our view}, there was not yard at all.

- we have to face snake fear in chaitanyapur & in Geonkhali. Basuderpur,
- The majority of stocks lying in @ Basuderpur, chaitanyapur, Geonkhali & Hatibedia are scraps. The condition of the stocks are not good.
- For chaitanyapur store 1 & store 2, also store yard due to dense vegetation and snake prone area, we are unable to reach some places & verify the stocks. ^{from} from company side clicked pictures for majority of store & storeyard.
- For Basuderpur store yard majority of pictures were clicked by company hired labour due to dense vegetation & snake prone area we are unable to reach many places & verify the stocks by ^{our} own.

* The person hired from company are local people and there regular labour. So they knew the condition of the stores & storeyard very well. During our inspection, we even got snake skin lying at chaitanyapur store yard. And we also found carbore acid at many places, ~~for~~ it works as a snake ~~repellent~~ repellent.

*** Based on the previous observations, we are
unable to cross check each individual here
mentioned in both HDA list & HOSPL list.

		☐ For DRT Recovery purpose, ☐ For Insolvency purpose, ☐ Capital Gains Wealth Tax purpose, ☐ Partition purpose, ☐ General Value Assessment, ☐ For company merger & amalgamation purpose, ☐ For any other purpose:
10.	Type of Loan	☐ Project Loan, ☐ Term Loan, ☐ CC Limit enhancement, ☐ Cash Credit Limit, ☐ Industrial Loan, ☐ Business Loan, ☐ NA
11.	Loan Amount	

OWNERSHIP DETAILS

1.	Name of the Industry	Same as Pg. 2
2.	Legal Owner Name/s	u
3.	Property Purchaser Name	u
4.	Plant Address under Valuation	u
5.	Present Residence Address of the Owner/ Director	
6.	Property constitution	☐ Free Hold, ☒ Lease Hold (for operation & Maintenance)

LOCATION DETAILS

1.	Adjoining Properties	East	West	North	South
	(Match it with papers with the help of compass or Sun direction and also confirm it with nearby people)	This is a stock survey of 5 plants located in 5 different location.			
2.	Property Facing	☐ East Facing, ☐ North Facing, ☐ West Facing, ☐ South Facing, ☐ North-East Facing, ☐ South-West Facing, ☐ South-East Facing, ☐ North-West Facing			
	Different for different properties. As its a stock survey so didn't took details.				
3.	Landmark				
4.	Ward Name/ No.				
5.	Zone Name				
6.	Main Road Name & Width	Name	Width	Distance from property	
7.	Approach Road Name & Width				
8.	Are proper road facilities available?	☒ Yes, ☐ No			
9.	Type of Approach Road	☐ Bituminous, ☐ Metalled, ☐ Cement concrete, ☐ Concrete paver block, ☐ Brick khadanja, ☐ Mud surfacing, ☐ Broken potholed metalled road, ☐ No proper approach road available, ☐ Very narrow approach road towards the property			
	Not in scope of work.				

At So, we have mentioned only address. Page 6 of 17

10.	Location characteristics	☐ Within well-developed notified Industrial area, ☐ Within averagely maintained Industrial area, ☐ Within un-notified Industrial area, ☐ Within Main city, ☐ Within city suburbs, ☐ Within urban developed Area, ☐ Within urban developing zone, ☐ Within urban undeveloped area, ☐ Within urban remote area, ☐ Within commercial area, ☐ Within Institutional area, ☐ Out of municipal limits, no civic infrastructure available, ☒ Within rural village area, ☐ In interiors, ☐ Within Backward area, ☐ Within Remote area					
11.	Classification of the Locality	☐ Urban developed, ☐ Urban developing, ☐ Semi Urban, ☒ Rural, ☐ Backward, ☐ Industrial, ☐ Institutional					
12.	Location consideration	☐ Corner Plot, ☐ 2 side open, ☐ 3 side open, ☐ On >30' wide road, ☐ Near to Metro station, ☐ Near to Market, ☐ Near to Highway, ☐ Entrance North-East Facing, ☐ Ordinary location within locality, ☐ Good Location within the locality, ☐ Normal Location within the locality, ☐ Average Location within locality, ☐ Poor location within the locality, ☐ Property towards end of the locality, ☐ Any other					
13.	Is Plant part of notified Industrial Area? If yes then name of Industrial area/ estate & governing authority managing it.	☐ Yes, ☒ No Stock Valuation					
14.	Proximity to civic amenities	School	Hospital	Market	Metro	Railway Station	Airport
15.	Any new development in surrounding area	→					
16.	Jurisdiction limits	☐ Nagar Nigam, ☐ Nagar Panchayat, ☒ Gram Panchayat, ☐ Nagar Palika Parishad, ☐ Area not within any municipal limits					
17.	Jurisdiction Development Authority Name	Name: <u>HDA (Haldia Development Authority)</u> ☐ Area not within any development authority limits					
18.	Municipality/ Municipal Corporation Name	Name: <u>Haldia Municipality</u>					

→ Chaitanyapur & Beemkhali → Gram panchayat
→ Basudev pur & Hataberia → Haldia Municipality

		☐ Area not within any municipal limits
19.	Surrounding land uses and adjoining/ nearby establishment details	Different for different plants
20.	Is the location proper for the subject industry?	yes
21.	Is it a standalone Industry in this area? is it a belt for the subject nature of Industry?	yes
22.	In case Industry gets closed then does the land can be used for any other purpose?	Yes

PHYSICAL DETAILS				
1.	Land Area	As per Title deed	As per Map	As per site survey
		Not in	scope of work.	
		Area as per mortgage deed: Not in scope		
2.	Any conversion to the land use	u		
3.	Land Type Not in scope	☐ Solid, ☐ Rocky, ☐ Marsh Land, ☐ Reclaimed Land, ☐ Water logged		
4.	Shape of the Land y	☐ Square, ☐ Rectangular, ☐ Trapezium, ☐ Triangular, ☐ Trapezoid, ☐ Irregular, ☐ NA		
5.	Level of Land ✓	☐ On road level, ☐ Below road level, ☐ Above road level, ☐ NA		
6.	Frontage to depth ratio ✓	☐ Normal frontage, ☐ Less frontage, ☐ Large frontage, ☐ NA		
7.	Are Boundaries matched u	☐ Yes, ☐ No, ☐ No relevant papers available to match the boundaries, ☐ Boundaries not mentioned in available documents, ☐ Very large land parcel forming multiple lands so not possible to match it with papers		
8.	Is Independent access available to the property u	☐ Clear independent access is available, ☐ Access is available in sharing of other adjoining property, ☐ No clear access is available, ☐ Access is closed due to dispute, ☐ Land locked		
9.	Is property clearly demarcated with permanent boundaries? u	☐ Yes, ☐ No, ☐ Only partially, ☐ Only with Temporary boundaries,		
10.	Is the property merged or colluded with any other property u	Can't comment		
11.	Is complete property mortgaged with the Bank under valuation or only portion of it? u	u		
12.	Property possessed by at the time of survey 6	☐ Owner, ☐ Vacant, ☐ Lessee, ☐ Under Construction, ☐ Couldn't be Surveyed, ☐ Property was locked, ☐ Bank sealed, ☐ Court sealed		
13.	Current activity carried out in the property	☐ Industrial, ☐ Vacant, ☐ Locked, ☐ Sealed ☐ Any other use:		

Not in scope of work.

BUILDING/ CONSTRUCTION/ UTILITY DETAILS

1.	Construction Status	☐ Built-up property in use, ☐ Under construction, ☐ No construction		
2.	Covered Built-up Area	As per Title deed	As per Map	As per site survey
	RCC			
	Shed			
3.	Building Type	☐ RCC Framed Structure, ☐ Load bearing Pillar Beam column, ☐ Ordinary brick wall structure, ☐ Shed mounted on Iron trusses & Pillars, ☐ Scrap abandoned structure		
4.	Appearance/ Condition of the Building	Internal - ☐ Excellent, ☐ Very Good, ☐ Good, ☐ Ordinary, ☐ Average, ☐ Poor ☐ Under construction, ☐ No Survey External - ☐ Excellent, ☐ Very Good, ☐ Good, ☐ Ordinary, ☐ Average, ☐ Poor ☐ Under construction		
5.	Maintenance of the Building	☐ Very Good, ☐ Average, ☐ Poor, ☐ Under construction		
6.	Age of Building/ Recent Improvements done			
7.	Maintenance of the Building	☐ Very Good, ☐ Average, ☐ Poor		
8.	Any defects in the building	☐ Maintenance issues, ☐ Finishing issues, ☐ Seepage issues, ☐ Water supply issues, ☐ Electricity issues, ☐ Structural issues, ☐ Visible cracks in the building		
9.	Any violation done in the property	☐ Construction done without Map, ☐ Construction not as per approved Map, ☐ Extra covered without sanctioned Map, ☐ Joined adjacent property, ☐ Encroached adjacent area illegally		
10.	Boundary Wall (Only for individual property)	☐ Yes, ☐ No, ☐ Common boundary wall of a complex		
		Running Mtr.	Height	Width
				Finish
11.	Garden/ Landscaping	☐ Yes, ☐ No, ☐ Beautiful, ☐ Ordinary		
12.	Parking facilities	☐ Available within the property	☐ On Ground, ☐ In Basement, ☐ On stilt	
		☐ Not available within the property	☐ On road, ☐ Acute parking problem	
13.	Special Comments if any			

NOTE: Use table below to mention the individual building/ shed/ blocks details. Mentioned Type of construction (RCC/ Corrugated GI Shed Mounted on Brick Wall or Iron Pillars & Trusses/ Corrugated Colored GI Shed/ Simple GI Shed/ Simple Tin Shed), Height & Area of each block in the table below.

PLANT DETAILS

S.No.	PARTICULARS	DESCRIPTION
1.	Brief History & Description of the Plant	HWSPL started in the year 2019. HDA gave them for O&M. The lease is for 15 yrs.
2.	Nature of Industry	water Purifying plant (Treatment)
3.	Plant Inception Date	Given on lease by HDA.
4.	Commercial Operational Date	4
5.	No. of Production Lines	Prod. line → 2 (old, WTP & New WTP) Distribution line → 3 (Chaitanyapur, Basoderpur & Hatibena)
6.	Date of Inception of each Production Line	Given on lease by HDA for 15 yrs.
7.	Total Block Value of the Machines (As on Year ending 31 st March)	—
8.	Industry benchmark cost for setting up these Plants (for eg. Per MW or Per MT)	—
9.	Establishment Type	☐ Indigenous, ☐ EPC Contractor, ☐ Local Contractor Not in Scope
10.	Plant Type	☐ Manual, ☒ Semi-Automatic, ☐ Fully Automatic, ☐ Conventional, ☐ Non-Conventional, ☐ Computerized Controlled
11.	Plant & Machinery Purchase Type	☐ First Hand, ☐ Second Hand Not in Scope
12.	Plant & Machinery Make	☐ Domestic branded, ☐ Domestic local made, ☐ Onsite fabrication A credit comment Imported machines, ☐ Mix (Domestic + Foreign)
13.	Plant Overall Condition	☐ Newly Commissioned, ☐ Excellent, ☐ Very Good, ☒ Good, ☐ Average, ☐ Poor, ☐ Completely scrap
14.	Plant Status	☒ In Operation, ☐ Not Running, ☐ Partially running, ☐ Stopped For Maintenance, ☐ Completely shutdown
15.	If Plant is not operational then period since it is not operational & reason for not being in operation	—

	If Plant is not operational then does it require any money for refurbishing to restart the Plant?	—
17.	Total money spent in last one year on maintenance of machines	Not in scope
18.	Any major failure, fault, breakdown in last 3 years?	u
19.	Any Technology collaboration of the Plant	u
20.	Average Plant Capacity Utilization rate in last one month. <i>Attach Production chart of last one week.</i>	For 2 W+P's → (50 Million Gallon/day) 90%
21.	Name & Function of each block in the plant - Use Separate Sheet If Required	—
22.	Main machines used in the Plant - Use Separate Sheet If Required	—
23.	Estimated net weight of the large machines and of total machines present at site - Use Separate Sheet If Required	Not in scope
24.	Estimated Economic Life of the Plant/ Machines	u
25.	Age of the Plant/ Remaining Life of Machines	u
26.	Record of Last Maintenance Done (<i>Attach Copy Of Maintenance Log Book If Possible</i>)	—
27.	Production Capacity In Quantity & Weight For Different Products/ Units	50 Million Gallon/ Day (Treats water)
28.	Description Of Products Manufactured	water treat ment plant.
29.	Brand Name under which Products are sold in the Market	—
30.	Raw Material Used & Sources Of Primary Raw Material Used	—

31.	No. & Type of Furnace	-
32.	No./ Type/ Height of Chimney/ Exhaust	-
33.	Is Plant using obsolete technology or currently used technology in the market? Please comment.	-
34.	Whether STP is installed (Mention Type & Capacity)	-
35.	Whether ETP is installed (Mention Type & Capacity)	-
36.	Fire Fighting System	-
37.	No. of Resources Working In the Plant (Managerial, Skilled, Unskilled)	45 (approx), company payroll. Not in scope
38.	Is the adequate skilled labour available in this area for the subject Industry?	Yes
39.	Power Supply arrangements in the Plant (Sanctioned Load Kw and Units consumed in last 3 months)	WBSEDCL, THKFA AT
40.	Auxiliary power arrangements type in the plant (Type & Capacity)	☒ DG Sets, ☐ Captive Power Plant one DG set in chaitanyapur
41.	HVAC System In the Plant	-
42.	Cooling System In the Plant	-
43.	Water Arrangements/ Source of water	☐ Jet pump, ☐ Submersible, ☐ Jal board supply, ☐ Reservoir, ☐ Any other: AT River water.
44.	Major issues noticed in the Industry which can create issues in operations	-

AT

G → 33 kVA (Geonkhali)

B → 11 kVA (Basudor per)

Ch → ~~750~~ 11 kVA (Chaitanyapur)

Hatibara → 11 kVA

ATTACHMENTS:

S.No.	PARTICULARS	DESCRIPTION
1.	Inventory Sheet of P&M from Fixed Asset Register (Machine Name/ Machine Type/ Capacity/ Model No./ Machine Make/ Capitalization Date/ Capitalization Value/ Current Book Value/ Machine Status (working/ not working))	
2.	Flow chart / Block diagram from raw material to finished product	
3.	Plant Layout	
4.	Factories registration	
5.	Labor license	
6.	Fire NOC	
7.	Copy of last paid Electricity Bill	
8.	NOC from Pollution Control Board	
9.	Environment Clearance (if applicable)	
10.	Petroleum Product Storage license (if applicable)	
11.	Explosive Product Storage license (if applicable)	
12.	Export/ Import Code (if applicable)	
13.	Any other approval or NOC as per industry	
14.	Daily Performance Report	
15.	Production data of last one week	
16.	Plant maintenance log	

LAND RATES INFORMATION DETAILS

Gather information on the basis of the factors like Area location, Property location, Floor level, Block, Position, Frontage, Width of lane/ road in front of the property, Nearby development

1.	Demand & Supply condition in the Market for such properties	☐ Very Good, ☐ Good, ☐ Average, ☐ Low	
2.	At what True rate Owner bought this Property	Year of purchase	
		Purchase Price	
3.	Minimum Rate in the locality		
4.	Maximum Rate in the locality		
5.	Local Information gathered during Site survey (Minimum 2 enquiries are must):		
	1. Name:		
	Contact No.		
	Sale Purchase Rate		
	Rental Rate		
	Comments		
	2. Name:		
	Contact No.		
	Sale Purchase Rate		
	Rental Rate		
	Comments		
	3. Name:		
	Contact No.		
	Sale Purchase Rate		
	Rental Rate		
	Comments		

Surveyor Name:

Signature:

Date:

CASE NO.

UNDERTAKING BY THE CUSTOMER

I confirm that the property is inspected in front of me and I have provided all the information true related to the property to the best of my knowledge. I understand that any false or manipulative information provided by me will be considered as cheating with the professional organization since it will lead to incorrect valuation report and I'd be solely responsible for this unlawful act and will bear the charges for the changes/ modifications which have to undergo due to the false information. I also undertake that I haven't given any cash or in kind to any member of R.K Associates to influence the Value of the Property or favor any individual or organization and the same is not accepted or asked by the member of R.K Associates. Any such act will lead to cancellation of the material prepared by R.K Associates with forfeiting of the fees and I'll be completely responsible for its repercussions and legal actions taken for it.

IMPORTANT: We have not authorized any of our Surveyor to take Cash or kind from the customers in any situation. In case Surveyor or any member of R.K Associates asks for any money or kind from you then kindly please inform on number +91-9999597597. Our Valuation process is very stringent and have multiple check points to ensure correct & error free reports to keep the lending agency risk free. In case Surveyor claims that he would be able to arbitrary effect the Valuation figures unfairly or as per your requirement & need then he is making a false claim to you and we request you to complaint such act immediately on the number provided above.

Name:

Signature:

Mobile No.:

Date:

UNDERTAKING BY THE SURVEYOR

I confirm that I have carried out the Survey of the property properly as per the fair professional best practices and Valuation & Survey policy guidelines issued by the organization. I have not taken any cash or kind from the customer or given the customer any wrong or false information or have made any false claims for arbitrary providing the Property Valuation as per one's need or requirement by distorting the facts. In case at any point of time it is found that I have done any kind of fraudulent activity in this case and misled the company then I understand its legal consequences and appropriate penal action which company can take against me. Also in regard to it any monetary or reputation loss will be recovered from me by the company.

Surveyor Name:

Signature:

Date:

Hirpan Ray

28/11/22

CASE NO.

UNDERTAKING BY THE PREPARER

I confirm that this Valuation Report is prepared as per the fair professional best practices and Valuation & Survey Policy Guidelines issued by the organization. I also confirm that without any personal interest, partiality or prejudice I have worked on the Valuation work of this case. Rates adopted for the asset is based on various facts, information collected from the site came to my knowledge during the course of the assignment and I have taken all sincere efforts to review & confirm this data/ information from all different angles using my prudent approach without any biasedness or pressure. I have prepared the report based on true facts & information as per best of my knowledge & case facts. I understand that any false information provided by me will lead to the incorrect valuation report and I'd be solely responsible for it and will bear the losses which will be put on the Company in form of monetary or reputation loss by its client or statutory bodies.

I also undertake that I did not come into any influence by the customer, Bank representative (officer or agent), colleagues, coworkers or any other person to arbitrary change the Valuation figures or facts unethically or illegitimately which may put the public money at risk which is in the form of Bank deposits.

In case at any point of time in future I am found guilty of illegitimately distorting the facts in the Valuation or any other professional services which company offers in the market on being influenced by the customer or Bank representative (officer or agent) or for whatsoever may be the reason then I'd solely responsible of any such act and I understand that the Company shall take appropriate legal action against me which may include suspension from the current roles & responsibilities or termination from the employment with immediate effect.

I also undertake that I have not taken any cash, favor or in kind from the customer for favoring any individual or organization by unfair means.

I also undertake that I'll not prepare any report on incomplete Survey form which is not properly filled as per the Company guidelines and in case I am preparing it which is creating an incorrect report then I'd be responsible for its consequences.

Preparer Name:

Signature:

Date:

SURVEY SUMMARY SHEET

(TO BE ENCLOSED WITH VALUATION REPORT)

(Version 1.0) | Date of implementation: 10.04.2017

Every Valuation report at R.K Associates is prepared based on the thorough survey of the property carried out by our Engineering Surveyor. This Survey Summary Sheet is for the information of Banker/ concerned interested organization. Detailed Survey Form can also be made available to the interested organization in case it is required to cross check what information our surveyor has given in site inspection report based on which Valuation report is prepared.

1.	File No.			
2.	Name of the Surveyor	Anurban / Rajat		
3.	Borrower Name	Mr. Haldin water services not comment		
4.	Name of the Owner	H.D. cannot comment		
5.	Property Address which has to be valued	Given on Pg. 2		
6.	Property shown & identified by at spot	☐ Owner, ☐ Representative, ☐ No one was available, ☐ Property is locked, survey could not be done from inside		
		Name	Contact No.	
		Mr. Sourin Samanta	90643 678 05	
7.	How Property is Identified by the Surveyor	☐ From schedule of the properties mentioned in the deed, ☐ From name plate displayed on the property, ☐ Identified by the owner/ owner representative, ☐ Enquired from nearby people, ☐ Identification of the property could not be done, ☐ Survey was not done		
8.	Are Boundaries matched	☐ Yes, ☐ No, ☐ No relevant papers available to match the boundaries, ☐ Boundaries not mentioned in available documents		
9.	Survey Type	☐ Full survey (inside-out with measurements & photographs) ☐ Half Survey (Measurements from outside & photographs) ☐ Only photographs taken (No measurements)		
10.	Reason for Half survey or only photographs taken	☐ Property was locked, ☐ Possessee didn't allow to inspect the property, ☐ NPA property so couldn't be surveyed completely		
11.	Type of Property	☐ Flat in Multistoried Apartment, ☐ Residential House, ☐ Low Rise Apartment, ☐ Residential Builder Floor, ☐ Commercial Land & Building, ☐ Commercial Office, ☐ Commercial Shop, ☐ Commercial Floor, ☐ Shopping Mall, ☐ Hotel, ☐ Industrial, ☐ Institutional, ☐ School Building, ☐ Vacant Residential Plot, ☐ Vacant Industrial Plot, ☐ Agricultural Land		
12.	Property Measurement	☐ Self-measured, ☐ Sample measurement, ☐ No measurement		
13.	Reason for no measurement	☐ It's a flat in multi storey building so measurement not required ☐ Property was locked, ☐ Owner/ possessee didn't allow it, ☐ NPA property so didn't enter the property, ☐ Very Large Property, practically not possible to measure the area within limited time ☐ Any other Reason:		
14.	Land Area of the Property	As per Title deed	As per Map	As per site survey
15.	Covered Built-up Area	As per Title deed	As per Map	As per site survey
16.	Property possessed by at the time of survey	☐ Owner, ☐ Vacant, ☐ Lessee, ☐ Under Construction, ☐ Couldn't be Surveyed, ☐ Property was locked, ☐ Bank sealed, ☐ Court sealed		
17.	Any negative observation of the			

	property during survey	
18.	Is Independent access available to the property	☒ Clear independent access is available, ☐ Access available in sharing of other adjoining property, ☐ No clear access is available, ☐ Access is closed due to dispute
19.	Is property clearly demarcated with permanent boundaries?	☐ Yes, ☐ No, ☐ Only with Temporary boundaries <i>Access comment</i>
20.	Is the property merged or colluded with any other property	u
21.	Local Information References on property rates	Please refer attached sheet named 'Property rate Information Details.'

Endorsement:

1. Signature of the Person who was present from the owner side to identify the property:

Undertaking: I have shown the correct property and provided the correct information about the property to the surveyor of R.K Associates to the best of my knowledge for which Valuation has to be prepared. In case I have shown wrong property or misled the valuer company in any way then I'll be solely responsible for this unlawful act.

- Name of the Person:
- Relation:
- Signature:
- Date:

In case not signed then mention the reason for it: ☐ No one was available, ☐ Property is locked, ☐ Owner/representative refused to sign it, ☐ Any other reason:

2. Surveyor Signature who did site inspection:

Undertaking: I have inspected the property and cross verified the property details at site to the extent of a. Matching boundaries of the property, b. Sample measurement of its area, c. Physical condition, d. Property rates as per local information with what is mentioned in the property documents provided to me by the Bank/interested organization. I have not come under influence of anyone during site inspection and have only recorded the true and factual details in the survey form which I come across during the site survey. I understand that giving any manipulative information in the survey form will lead to incorrect Valuation report which is an unlawful act and I'll be solely responsible for doing it.

- Name of the Surveyor:
- Signature:
- Date:

Anishan/ Rajat
26/12/2022 to 28/12/2022