

File No.	RKA/DNCR//
Date of Receiving	22/02/23
File Receiver Name	shahid



CASE COLLECTION FORM (Version 5.0) Date of implementation: 9.02.2011 | Last Revision: 30.01.2020 | Latest Revision: 31.10.2020

Items	Assigned To	Assigned to Date	To be completed by date	Submitted On date	Grade	HOD Engg. Signature
File Received By	shahid	NA	NA			
Survey	Abhishek Shanbhag					
Preparation						

A - Very Good, B - Satisfactory, C - Average, D - Poor, E - Extremely Poor

File Returned to HOD	□ Survey not done properly, □ Survey Form not properly filled, □ Market survey for		
Engg. unprepared due rates is not properly done, Identification is not clearly done, Measuremen			
to reason	properly done, Photographs not clearly taken, Selfie/ Owner or owner		
	representative photo not taken, Owner/ owner representative signature not taken,		
	□ Google Map not taken, □ Survey summary sheet not filled		

	□ Minor defects in the survey hence approved for preparation with warning to
by the preparer - HOD	Surveyor. Report preparer to collect the missing information on his own.
Engg. comment &	
Signature	Major defects in the survey. Survey has to be done again.

		GENER	AL DETAILS			
1.	Proposal/ Work Order or		0	2		
	Ref. No.	VIS (2022-23) - PL 66	8 - 559 -	- 933	
2.	Type of Service		✓ Valuation Report, □ Construction cost estimate, □ Cost vetting certificate □ Other CE Certificates, □ TEV Report, □ LIE			tting certificate
3.	Type of customer	Bank			Corporate	
		Company	Private clie	ent 🗆 Direc	ct client through	
4.	Bank/ FI/ Organization	SBI SME, S	Sector 18	Noida		
	Name & Address			/		
5.	Case Allotment Officer/	Name	Contact Number		Email Id	
	Fees paying party Details	🖀 shilpi Suman	945	6593976	shilpi.sun co.in	nan @ sbi.
6.	Case Type	Case for Fres	h Account	Case	for exiting acco	ount/ customer
7.	Fees Details	Amount of Fees	Advance An	nount if any	Fees wil	be paid by
		As per bank fec structure	e + GIST	-	Bank	
8.	Billing Details	Billed To Pa	Billed To Party Name			N

and the second second

.

			CASE DETAIL	9		
1.	Type of Property	R	esidential		8 bunga	low
2.	Purpose of Valuation/ Assignment	Periodic For DR	Re-Valuation for TRecovery purpose purpose, □ Gen	Bank, □ E se, □ Cap)istress sale f ital Gains We	
3.	Owner/ Applicant Details		Name	Contac	t Number	Email Id
			a Aggarwal sh Aggarwal	0.010	066665	Saggarwal @ Vtipl.com
4.	Account Name	Visua	l Technol	ogies (i) lut L	td ·
5.	Property Address	Lot Bea no. 102 Taluka	ring no og , Hissa no. - Mulshi, I	, first 1+3,1/ District-	- Court & , Village - Pune	Street, Sarvey - Dasave,
6.	Who will coordinate on		Name			ontact Number
	site for the site survey	A	imod Kuma	17	9833	8159006
7.	Preferred time of survey	Date	09/03/23		Time	
8.	Documents Received (Any one ownership document and approved site plan/map is must) Plan, Map, Development Permission letter, TIR, lease deed, Possession letter, ovr	□ Reg □ Con 2. Map: □ 3. Utility receipt, 4. Any Ot □ Old	□ House Tax de	linquishme Allotment proved Ma y Bill & pa mand & pa] CLU, □	nt Deed, T Letter, Pos ap, Site Pla yment receipt yment receipt	ransfer Deed, sesssion Letter an t, □ Water Bill & payment t
9.	Documents received from	Bank	er / clien	t		
10.	Special Instructions if any:		_			
11.	I agree to pay the amount m on Valuer firm to distort any vested interest and to benefit	facts and wo	ould not try to influe	nce any me	ember or officia	agree that I'll not put pressure al of the firm in the ill spirit or
	Customer Signature:					

File No. RKA/DNCR/....../

FILE RECEIVER CASE COLLECTION PROCESS COMPLIANCE CHECKLIST (To be filled by Surveyor) COMPLIANCE CHECKLIST APPROVER SIGNATURE/ S.NO. STATUS REMARKS IN CASE OF ANY (X) Is Case collection Form properly filled by Receiver? 1. D Is purpose of the assignment understood clearly by 2. D the receiver? Has receiver checked if this is a new case or 3. D existing case of the Bank? Has receiver fixed the fees with the manager/ client 4. A and sent quotation properly or have taken approval of the work over email? Has receiver taken proper Work Order/ Email/ 5. D CESA form formality? In case of private case or for fresh case 50% 6. advance is received? Is document checklist email sent to the customer? 7. A Has the received documents is having 'documents 8. provided by stamp'?

IMPORTANT INSTRUCTIONS TO SURVEYOR

1.	Please fill the above compliance checklist before moving for the survey.
2.	Please do not do the survey if you do not have proper documents.
3.	For Vacant Plot/ Land - Cizra Map/ Master/ Zonal/ Site Plan is must to identify the Plot. For
	Agriculture or converted land from agriculture – Mutation documents, CLU is must.
4.	Firstly please first study the documents of the property which needs to get surveyed.
5.	Mark the Owner/ Area/ Boundaries mentioned in the ownership documents with bold florescent
	marker pen before moving for the survey. During site survey if any difference is found in the
	above fields from the ownership documents then please contact the owner immediately to
	know the reason for the difference.
6.	Confirm ongoing property rates in the subject location through public domain, property sites and
	contact dealers to show you the available properties in that area during your survey.
7.	Identify the Property clearly by matching the boundaries and area mentioned in the property
	papers.
8.	Do sample physical or google measurements of the property.
9.	PHOTOGRAPH INSTRUCTIONS:
(*12538). 	a. Take owner/ representative photograph along with the property.
	b. Take your selfie along with the property and the owner/ representative.
	c. Take full scale photo of the property with gate.
	 d. Take photo of the property along with abutting road, towards left, right and center.
	e. Take multiple photos of inside-out of the property.
	f Take nearby photographs of the Property.
	g. Take a short video to cover property and neighborhood.
10.	Taka Caagla Man location
11.	Check main road name & width and approach road width and distance of property from main road.
12.	Check Jurisdiction Municipal Limits & Ward Name.
13.	Fill each column of survey form diligently in detail and tick the appropriate option clearly.
14.	Check any defects or negativity in the property and comment in detail on survey form.
15.	Do extensive market rate enquiries and confirm for any recent past transactions.
16.	In sease sustamer appears to be providing misleading information to you or trying to influence you by
0.4602-024	money or cash then immediately report to the Management & Bank.

	SURVEY PROCESS COMPLIANCE CHECKLIST	
	(To be submitted by Surveyor with each Survey)	
S.NO.	COMPLIANCE CHECKLIST POINTS	STATUS
1.	Did you take proper property documents to carry out the survey?	UZ
2.	Have you properly studied & highlighted Owner/ Area/ Boundaries in the property	I
2.	documents with bold florescent before moving for the survey?	Le l
3.	Did you check prominent landmark nearby the subject property and mentioned in the survey	I
0.	form?	01
4.	Did you identified the Property clearly by matching the boundaries and area mentioned in	æ
	the property papers?	-
5.	Did you check if property is merged with any other property or it is an independent	U
	property?	
6.	Did you do sample physical or google measurements of the property in case of property	UT .
	more than 2500 sq.mtr?	
7.	Did you check for any building violations in the property?	Æ
8.	Did you check municipal limits/ jurisdiction/ ward?	D
9.	Did you take Google Map location and shared it to Maps whatsapp group?	LE .
10.	Did you check Main road name & width and its distance from the subject property?	Æ
11.	Did you check approach Lane width on which property is located?	U
12.	Have you taken property full scale photograph with gate?	æ
13.	Have you taken owner/ representative photograph with the property?	Ð
14.	Have you taken your selfie with the property along with owner/ representative?	Æ
15.	Have you taken photograph of the property along with abutting road and towards left and	U
	right of the property?	
16.	Have you taken multiple photographs of the property from inside-out?	I
17.	Did you check nearby development and whereabouts and commented on survey	E
	form?	
18.	Did you check any defects or negativity in the property in terms of location, legality,	J
	disputes, marketability, salability, etc. and commented on survey form in detail?	
19.	Have you filled all the columns of survey form including survey summary sheet	æ
	properly?	
20.	Did you draw site key plan (location map)?	
21.	Did you draw rough site sketch plan? Have you taken self-attested documents from owner/ representative and stamped	
22.	"documents provided by stamp"?	
- 22	Did you check any defects or negativity in the property in terms of location, legality,	Æ
23.	disputes, marketability, salability, etc. and commented on survey form in detail?	1.000.000.000
24.	Have you confirmed any recent past transactions during market enquiries and	U
24.	enquired property rates locally very rigorously?	
25.	Did you take signatures of the owner/ representative on undertaking and survey	UP .
20.	summary sheet?	
26.	Did you signed the undertaking?	Æ

For File No.	1668-559-933
Surveyor Name	Abhishek S
Signature	æ
Date	09/03/23



GENERAL SURVEY FORM (FOR PROPERTIES OTHER THAN FLATS) (Version 5.0) Date of implementation: 9.02.2011 | Last Revision: 04.01.2018 | Latest Revision: 31.10.2020

L	File No. RKA/DNCR//	Date: 09 03 23	Time:	
		GENERAL DETAILS		
1.	Name of the Surveyor	<u>GENERAL DETAILS</u> Abhishek · S		
2.	Property shown by	Owner,√ Representative, □ N locked, survey could not be done fr Name Amod Kumay		
3.	Survey Type	☐ Full survey (inside-out with mea ☐ Half Survey (Measurements fror ☐ Only photographs taken (No me	surements & photographs) m outside & photographs)	
1.	Reason for Half survey or only photographs taken	□ Property was locked, □ Poss property, □ NPA property so could	sessee didn't allow to inspect th	
5.	How Property is Identified	 □ From schedule of the properties mentioned in the deed, □ From schedule of the properties mentioned in the deed, □ From schedule of the property, □ Identified by the owner owner representative, □ Enquired from nearby people, □ Identification of the property could not be done, □ Survey was not done 		
3.	Type of Property Bungalow Residential land	 □ Flat in Multistoried Apartment, Apartment, □ Residential Builde Building, □ Commercial Office, □ Floor, □ Shopping Mall, □ Hotel, □ School Building, □ Vacant Re Plot, □ Agricultural Land 	er Floor,	
7.	Property Measurement	Self-measured, Sample mea	surement only, No measurement	
3.	Reason for no measurement	 It's a flat in multi storey building Property was locked, Owner/ NPA property so didn't enter the practically not possible to meas Reason: 	so measurement not required possessee didn't allow it, e property, v Very Large Proper	
).	Purpose of Valuation	 Value assessment of the asset Periodic Re-Valuation for Bank, For DRT Recovery purpose, Partition purpose, General Valuation 	□ Distress sale for NPA A/c., Capital Gains Wealth Tax purpos	
10.	Type of Loan Business loan	 □ Housing Loan, □ Housing Take Loan, □ Loan against Property, □ Loan, □ Car Loan, □Project Lo enhancement, □ Cash Credit Limit 	e Over Loan, □ Home Improveme Construction Loan, □ Education oan, □ Term Loan, □ CC Lir	
1.	Loan Amount			



	Legal Owner Name/s	OWNERSHIP			
1.	Property Purchaser Name	Mrs. Rita	Aggarwal	1Mr. Satish	Agggrwal
2.	Property Address under	-4-			-0
3.	Valuation	P 9.	2		
4.	Present Residence Address of	C-156, MAL	PONT Encla	ve, GT Kar	roal Road.
	the Owner/ Purchaser	Delhi-33	(- L	avaga 1
5.	Property constitution	□ Free Hold, Ø	Lease Hold	999 985-	Corporation
		LOCATION			Ud]
1.	Adjoining Properties	LOCATION D East	No. of Concession, Name of Street, or other	North	South
1.	(Match it with papers with the help		West	North	
		Vacant	Plot no-	open to	First
	of compass or Sun direction and	bungalow.	9	sky, hill	coust
	also confirm it with nearby people)	NO plot no-	,	open to sky, hill view	street
2.	Property Facing N		North Facing,	West Facing,	
	W-E			st Facing, South	
	IS	□ North-West Fac			20011 00
3.	Landmark	First C			
4.	Ward Name/ No.	First C		1	1.
5.	Zone Name	Survey r	10- 102, Hi	ssa. 1+31	(/[
		Village-	- Dasave	, Taluka-	-Mulshi
6.	Main Road Name & Width	Name Width Distance from property			
		Dasave R	oad -	- 3	oo mtr
7.	Approach Road Name & Width	123			
539359		First Court Street Within Main city, Within Good Urban developed Area, Within			
8.	Location consideration of the	Within Main ci	ty, 🗋 Within Goo	a orban actorpo	d Area, 🗆 Within
59359	Society		124.002	ality, 🗆 Very Good	
59359		developing area,	☐ Highly posh loc		, Good,
59359	Society within Lavasa	developing area,	☐ Highly posh loc	ality, 🗆 Very Good	, Good,
59359	Society within Lavasa aity. On hillghat	developing area, l Ordinary, Ir Poor	☐ Highly posh loc n interiors, ☐ Rem	ality, 🗆 Very Good	,\⊡ Good, ward, □ Average,
8.	Society within Lavasa aity. On hill Ighat section Special Location consideration	developing area, l Ordinary, D Ir Poor Park Facing, I	☐ Highly posh loc n interiors, ☐ Rem ☐ Pool Facing, ⊻	ality, □ Very Good note area, □ Backv	,\⊡ Good, ward, □ Average,
8. 9.	Society Within Lavasa aity. On hill Ighat section Special Location consideration of the property	developing area, l Ordinary, Ir Poor Park Facing, I East Facing, S	☐ Highly posh loc n interiors, ☐ Rem ☐ Pool Facing, ⊻ unlight facing	ality, □ Very Good note area, □ Backv ☑ Road Facing, □	,
8.	Society within Lavasa aity. On hill Ighat section Special Location consideration	developing area, l Ordinary, Ir Poor Park Facing, I East Facing, S	☐ Highly posh loc n interiors, ☐ Rem ☐ Pool Facing, ⊻ unlight facing	ality, □ Very Good note area, □ Backv	,
8. 9.	Society Within Lavasa aity. On hill Ighat section Special Location consideration of the property	developing area, l Ordinary, Ir Poor Park Facing, I East Facing, S	☐ Highly posh loc n interiors, ☐ Rem ☐ Pool Facing, unlight facing ed, ☐ Urban deve	ality, □ Very Good note area, □ Backv Road Facing, □ eloping, √ Semi Ur	,
8. 9. 10.	Society Within Lavasa aity. On hill Ighat section Special Location consideration of the property Characteristics of the locality	developing area, I Ordinary, Ir Poor Park Facing, I East Facing, I Urban develop Backward, Ir	☐ Highly posh loc n interiors, ☐ Rem ☐ Pool Facing, ☑ unlight facing ed, ☐ Urban deve ndustrial, ☐ Institu	ality, □ Very Good note area, □ Backv Road Facing, □ eloping, √ Semi Ur	,
8. 9.	Society Within Lavasa aity. On hill Ighat section Special Location consideration of the property	developing area, I Ordinary, Ir Poor Park Facing, I East Facing, I Urban develop Backward, Ir	☐ Highly posh loc n interiors, ☐ Rem ☐ Pool Facing, ☑ unlight facing ed, ☐ Urban deve ndustrial, ☐ Institu	ality, □ Very Good note area, □ Backv Road Facing, □ eloping, ☑ Semi Ur utional	,
8.9.10.11.	Society Within Lavasa aity. On hill Ighat section Special Location consideration of the property Characteristics of the locality Category of Society/ locality	developing area, I Ordinary, Ir Poor Park Facing, I East Facing, I Urban develop Backward, Ir High End, IG	☐ Highly posh loc n interiors, ☐ Rem ☐ Pool Facing, unlight facing ed, ☐ Urban deve ndustrial, ☐ Institu	ality, □ Very Good note area, □ Backv Road Facing, □ eloping, ☑ Semi Ur utional	,
8. 9. 10.	Society Within Lavasa aity. On hill Ighat section Special Location consideration of the property Characteristics of the locality	developing area, I Ordinary, Ir Poor Park Facing, I East Facing, IS Urban develop Backward, Ir High End, IR MIG, ILG Lifts, IG Garden	☐ Highly posh loc n interiors, ☐ Rem ☐ Pool Facing, ☑ unlight facing ed, ☐ Urban deve ndustrial, ☐ Institu ☑ ormal, ☐ Affordal	ality, Very Good note area, Backy Road Facing, C eloping, Semi Ur utional ble Group Housing g, Swimming Poo	,
8.9.10.11.	Society Within Lavasa aity. On hill Ighat section Special Location consideration of the property Characteristics of the locality Category of Society/ locality	developing area, I Ordinary, Ir Poor Park Facing, I East Facing, I Urban develop Backward, Ir High End, IR MIG, IIG Lifts, Garder Club House, I	☐ Highly posh loc n interiors, ☐ Rem ☐ Pool Facing, ☑ unlight facing ed, ☐ Urban deve ndustrial, ☐ Institu ☑ ormal, ☐ Affordal	ality, Very Good note area, Backy Road Facing, C eloping, Semi Ur utional ble Group Housing,	,
8. 9. 10. 11.	Society Within Lavasa Gity · On hill Ighat section Special Location consideration of the property Characteristics of the locality Category of Society/ locality Utilities/ Facilities in the locality	developing area, I Ordinary, Ir Poor Park Facing, I East Facing, S Urban develop Backward, Ir High End, IR MIG, LIG Lifts, Garder Club House, M Backup	☐ Highly posh loc n interiors, ☐ Rem ☐ Pool Facing, ☑ unlight facing ed, ☐ Urban deve ndustrial, ☐ Institu ☑ ormal, ☐ Affordal	ality, Very Good note area, Backy Road Facing, C eloping, Semi Ur utional ble Group Housing g, Swimming Poo	y Good, ward, □ Average, I Entrance North- ban, □ Rural, , □ EWS, □ HIG, ol, □ Gym, 100% Power
8.9.10.11.	Society Within Lavasa Gity · On hill Ighat section Special Location consideration of the property Characteristics of the locality Category of Society/ locality Utilities/ Facilities in the locality Proximity to civic amenities	developing area, I Ordinary, Ir Poor Park Facing, I East Facing, S Urban develop Backward, Ir High End, I MIG, LIG Lifts, Garder Club House, M Backup School Hos	☐ Highly posh loc n interiors, ☐ Rem ☐ Pool Facing, ☑ unlight facing ed, ☐ Urban deve ndustrial, ☐ Institu ormal, ☐ Affordal n, ☐ Landscaping ☑ Walk Trails, ☐ pital Market	ality, Very Good note area, Backy Road Facing, C eloping, Semi Ur utional ble Group Housing g, Swimming Poo Kids play zone, Metro Railway	y Good, ward, □ Average, I Entrance North- ban, □ Rural, , □ EWS, □ HIG, ol, □ Gym, 100% Power Station Airport
8. 9. 10. 11. 12.	Society Within Lavasa Gity · On hill Ighat section Special Location consideration of the property Characteristics of the locality Category of Society/ locality Utilities/ Facilities in the locality Proximity to civic amenities T: 7 for	developing area, 1 Ordinary, Ir Poor Park Facing, S Cast Facing, S Urban develop Backward, Ir High End, R MIG, LIG Lifts, Garder Club House, M Backup School Hos	☐ Highly posh loc ☐ Interiors, □ Rem ☐ Pool Facing, □ ☐ Pool Facing ☐ unlight facing ed, □ Urban deve ndustrial, □ Institution ormal, □ Affordal n, □ Landscaping ☑ Walk Trails, □ pital Market Image: Segment	ality, Very Good note area, Backy Road Facing, C eloping, Semi Ur utional ble Group Housing, G, Swimming Poo Kids play zone, Metro Railway	y Good, ward, □ Average, I Entrance North- ban, □ Rural, D EWS, □ HIG, DI, □ Gym, 100% Power Station Airport Km 62 Km
8. 9. 10. 11.	Society Within Lavasa Gity · On hill Ighat section Special Location consideration of the property Characteristics of the locality Category of Society/ locality Utilities/ Facilities in the locality Proximity to civic amenities	developing area, 1 Ordinary, Ir Poor Park Facing, S Cast Facing, S Urban develop Backward, Ir High End, R MIG, LIG Lifts, Garder Club House, M Backup School Hos	☐ Highly posh loc ☐ Interiors, □ Rem ☐ Pool Facing, □ ☐ Pool Facing ☐ unlight facing ed, □ Urban deve ndustrial, □ Institution ormal, □ Affordal n, □ Landscaping ☑ Walk Trails, □ pital Market Image: Segment	ality, Very Good note area, Backy Road Facing, C eloping, Semi Ur utional ble Group Housing g, Swimming Poo Kids play zone, Metro Railway	y Good, ward, □ Average, I Entrance North- ban, □ Rural, D EWS, □ HIG, DI, □ Gym, 100% Power Station Airport Km 62 Km



15.	Jurisdiction limits	🗆 Nagar Nigam, 🗆 Nagar Panchayat, 🗆 Gram Panchayat, 🗆 Nagar
1		Palika Parishad, Area not within any municipal limits
16.	Jurisdiction Development	DDA, GDA, NOIDA, GNIDA, YEIDA, HUDA, KMDA,
	Authority Name	□ MDDA, □ Any other Development Authority:
	Lavasa Corporation Utd	Area not within any development authority limits
17.	Municipal Corporation Name	□ NDMC, □ SDMC, □ EDMC, □ Ghaziabad Municipal Corporation,
	Pure MC	Gurgaon Municipal Corporation, Faridabad Municipal Corporation,
		Giller Kolkata Municipal Corporation, Dehradun Municipal Corporation,
		Area not within any municipal limits, Any other Municipal
		Corporation/ Municipality:


		PHYSICAL DETAIL	S	
1.	Land Area	As per Title deed	As per Map	As per site survey
	а -	2024 m2	-	
2.	Any conversion to the land use	Not Known		
3.	Land Type	Solid, □ Rocky, □ logged, □ Land locked		laimed Land, 🗆 Water
4.	Shape of the Land	□ Square, □ Rectangu ☑ Irregular, □ NA	ular, 🗆 Trapezium, 🗆 T	riangular, 🗆 Trapezoid
5.	Level of Land	On road level, Be	low road level, Above	e road level, 🗆 NA
6.	Frontage to depth ratio	□ Normal frontage, 1	Less frontage, 🗆 Large	frontage, 🗆 NA
7.	Are Boundaries matched	□ Yes, □ No, □ No relevant papers available to match the boundaries, □ Boundaries not mentioned in available documents		
8.	Is Independent access available to the property	· · · ·	ing property, 🗆 No cle	Access available in ear access is available.
9.	Is property clearly demarcated with permanent boundaries?	Yes, 🗆 No, 🗆 Only	with Temporary bounda	ries
10.	Is the property merged or colluded with any other property	NO		
11.	Property possessed by at the time of survey	✓ Owner, ✓ Vacant, □ Lessee, □ Under Construction, □ Couldn't be Surveyed, □ Property was locked, □ Bank sealed, □ Court sealed		
12.	Current activity carried out in the property	a second and a second state of the second	se,	purpose,

	BUILDING/ CONSTRUCTION/ UTLITY DETAILS				
1.	Construction Status	☐ Built-up property in use, □ Under construction, □ No construction			





/	Covered Built-up Area	Covered Area D EL
2.	00	Covered Area, C Floor Area, Super Area, Carpet Area
1	(Tick one on the basis of which	As per Title deed As per Map As per site survey
	valuation is to be calculated)	CA-3052 C2 CL 33515M2 Pg.11
-	Total Number of Floors in the	BUA- 4198 Sq. St BUA- CA- 3053 Sq. St 335.15 m ² Pg.11
3.	Building	(Git1) (Parking on ground)
4.	Floor on which property is situated	-
5.	Type of Unit/ Number of Rooms/ Cabins/ Cubicles	-
6.	Building Type	RCC Framed Structure, 🗆 Load bearing Pillar Beam column,
		□ Ordinary brick wall structure, □ Iron trusses & Pillars, □ Scrap
		abandoned structure
7.	Roof	a. Make: RBC, RCC, GI Shed, Tin Shed, Stone
		Patla
		c. Finish: Simple plaster, POP Punning, POP False
8.	Flooring	Ceiling, □ Coved roof, □ No plaster □ Vitrified tiles, □ Ceramic Tiles, ☑ Simple marble, □ Marble
1000		chips, □ Mosaic, □ Granite, □ Italian Marble, □ Kota stone,
		□ Wooden, □ PCC, □ Imported Marble, □ Pavers, □ Chequered
		Tiles, □ Brick Tiles, □ No Flooring, □ Under construction, □ Any
		other type:
9.	Appearance/ Condition of the	Internal - D Excellent, D Very Good, D Good, D Ordinary,
	Building	□ Average, □ Poor □ Under construction, □ No Survey
		External - Excellent, Very Good, Good, Ordinary,
		Average, Poor Under construction
10.	Maintenance of the Building	□ Very Good, ☑ Average, □ Poor, □ Under construction
11.	Interior decoration	Excellent, Very Good, Good, Simple, Ordinary,
		Average, Below average, Under construction, No Survey
12.	Interior Finishing	\square Simple plastered walls, \square Brick walls without plaster,
		□ Designer textured walls, □ POP punning, □ Coved roof,
		□ Under construction, □ No Survey
13.	Exterior Finishing	Simple plastered walls, Brick walls without plaster,
		□ Architecturally designed or elevated, □ Brick tile Cladding,
		□ Structural glazing, □ Aluminum composite panel cladding,
		Glass façade, Domb, Porch, Under construction
14.	Kitchen	□ Simple with no cupboard, □ Ordinary with cupboard, □ Normal
		Modular with chimney, □ High end Modular with chimney, □ Under construction, □ No Survey
15.	Class of Electrical fittings	External, Internal
15.		Ordinary fixtures & fittings, Fancy lights, Chandeliers,
		□ Concealed lightning, □ Under construction, □ No Survey
16.	Class of Sanitary/ Plumbing &	External, Internal
	water supply fittings	□ Excellent, □ Very Good, □ Good, ☑ Simple, □ Average,
		□ Below average, □ Under construction, □ No Survey
17.	Water arrangements	□ Jet pump, □ Submersible, □ Jal board supply
18.	Fixed Wooden Work	Excellent, Very Good, Good, Simple, Ordinary,
		□ Average, □ Below Average, □ No wooden work, □ No survey
19.	Age of Building/ Recent	10475 (2012) -
	Improvements done	10 yrs (2012) -
20.	Maintenance of the Building	□ Very Good, □ Average, □ Poor



1.	Any issues in marketability of the property?	□ Yes, v No		
			n case of No: ☑ Location, ☑ Surrounding, ☑ Lega ☑ Demand,☑ Shape, □ Any Other:	
2.	How is Demand & Supply condition in the Market of such properties?	Demand	🗆 Very Good, 🗹 Good, 🗆 Average, 🗆 Low, 🗆 Poor	
		Supply	🗆 Very Good, 🗹 Good, 🗆 Average, 🗆 Low, 🗆 Poor	
3.	3. Is property easily sellable & marketable?	VØYes, □ No		
		Comments	s:	
4.	How is the current utility of the property?		ent, □ Very Good, □ Good, □ Average, □ Low, □ Poor	
5.	At what True rate Owner bought this Property?	Year of pu	urchase 2012	
		Purchase	Price	
6.	Present expected Sale Value of the overall property?			

area. Hill view.



BLANK PAGE FOR PROVIDING ANY ADDITIONAL DETAILS/ INFORMATION * ist Fly Kitchen - 11.25 × 11.39-128 Hall - 42.02 × 16.23 - 682 St Flr - 16.05 St Sgift other area - 20.68× 10.01 · Stair area - 13.36× 6.38-85 Sq.St Balcony - 8.10× 16.02 -207 Height - 11-15 Sq.St * Girnd Flo · 1st Barrie Fly - 1017 Sq. St + 211 Sq. St · stair case - 85 sq. +1-Height - 8.93 ft . Grad For Fly - 1048 sq.ft open area - 14.62 × 13.32 - 195 · Balcony - 1st - 130 sq.ft Bedroom 1 - 16.91 × 17.50 - 296 grad - 130 sq. ft Bed 800m 2 - 18.56 × 16.25 - 301 WICI - 17.78×7.79-138 wlc 2 - 8.06×14.64 - 118

1048 ft2

1^{St} Fly: Open aseq - 14.45 × 4.48 - 65 WIC1 - # 5.90 × 4.35 - 26 WIC2 - 4.45 × 4.35 - 20 Bedroom Chouse Keeper) - 11.35 × 8.76 - 100 211

Page 11 of 15

No	Particulars	Subject Property	Transaction already h Comparable 1	Comparable 2	Comparable 3
	Name (source of information)	NA	Kunal		and the second second
2	Contact No.	NA			
3.	Type of source of information (Seller/ Property dealer/ nearby people)	NA	9657894911 Local		
4.	Rates/ Price informed (in Rs. with unit)	NA	5Cr-basevalue Max 6Cr	e	
5.	Rates Type (Sale/ Buy)	NA	Sale		
6.	Shape of the Property (Square, Rectangular, Irregular)		Irregular		
7.	Area/ Size of the Property		0.500 acre		
8.	Legal Status (clear, negative, weak)/ No. of owners		clear		
9.	Location/ surrounding/ neighborhood comparison with the subject property (Similar, Lower, Better, Highly Better than the subject Property)	Base Case	Same location		
10.	Distance from the subject Property	0	same location		
11	Other factors (Comer, 2 side open, North-East facing, Park facing, Legal/ Financial encumbrance, etc.)		-		
12	Approach road width				
13	. Level of Land (Below/ On/ Above road level)		on road level		
14	. Frontage to depth ratio (Normal, Less, Large)		Less		
15	Present Use		Vacant.		
16	. Any other details/ Discussion held	NA	Bungelow Used for 2-3 months a year for holiday pur	Pale.	
17	Present expected Sale Value of the overall property?			(~~	

UNDERTAKING BY THE CUSTOMER

I confirm that I have made the inspection of the subject property to the surveyor of R.K Associates, which is correct property in question for which the documents have been provided/ submitted by me. I further confirm that I am aware of all the information related to the subject property and I have provided all its information to the surveyor true to the best of my knowledge. I understand that any false or manipulative information provided by me will be considered as cheating with the professional organization since it will lead to incorrect valuation report and I'd be solely responsible for this unlawful act and will bear the charges for the changes/ modifications which have to undergo due to the false information. I also undertake that I have not given any cash or in kind to any member of R.K Associates to influence the Value of the Property or favor any individual or organization and the same is not accepted or asked by the member of R.K Associates. Any such act will lead to cancellation of the material prepared by R.K Associates with forfeiting of the fees and i'll be completely responsible for its repercussions and legal actions taken for it.

IMPORTANT: We have not authorized any of our person/ Surveyor to take Cash or kind from the customers in any situation. In case Surveyor or any member of R.K Associates asks for any money or kind from you then kindly please inform on number +91-9958632707, 0120-4110117. Our Valuation process is very stringent and have multiple check points to ensure correct & error free reports to keep the lending agency risk free. In case Surveyor claims that he would be able to arbitrary effect the Valuation figures unfairly or as per your requirement & need, then he is making a false claim to you and we request you to complaint such act immediately on the number provided above.

Name	Amod Kumar
Relationship with owner	Employee
Signature	Onne
Mobile No.	9833159006
Date	09 03/23

UNDERTAKING BY THE SURVEYOR

I confirm that I have carried out the Survey of the property properly as per the fair professional best practices and Valuation & Survey policy guidelines issued by R.K Associates. I have not taken any cash or kind from the customer nor have I come into any kind of influence of the customer / bank for arbitrary providing the Property Valuation as per one's need. I further state that I have not given any assurances to the customer nor given any wrong or false information or statement. In case at any point of time it is found that I have done any kind of fraudulent activity in this case and misled the company then I understand its legal consequences and appropriate penal action which company can take against me. Also in regard to it any monetary or reputation loss will be recovered from me by the company.

For File No.	PL668-559-933
Surveyor Name	Abhishek Shan bhag
Signature	R
Date	09 03 23



Enclosure: 6

SURVEY SUMMARY SHEET (TO BE ENCLOSED WITH VALUATION REPORT)

(Version 1.0) | Date of implementation: 10.04.2017

Every Valuation report at R.K Associates is prepared based on the thorough survey of the property carried out by our Engineering Surveyor. This Survey Summary Sheet is for the information of Banker/ concerned interested organization. Detailed Survey Form can also be made available to the interested organization in case it is required to cross check what information our surveyor has given in site inspection report based on which Valuation report is prepared.

1.	File No.	VIS(2022-23) - PL6	110 ,550 912	
2.	Name of the Surveyor	ALL'OR(-23)- FC6	68-337-133	
3.	Borrower Name	Abhishek Shanbhag Mrs. Rita Aggarwal / Mr Satish Aggarwal		
4.	Name of the Owner	Mrs. Kita Aggaru	Jar / Mr. Jatish	Hgggrwar
5.	Property Address which has to be valued	Plot no.08, First Court Road, Lavasa, Village- Dasque, Taluka-Mulshi, Dist-Pune		
6.	Property shown & identified by at spot	□ Owner, □ Representative, □ No one was available, □ Property is locked, surver could not be done from inside		
		Name		Contact No.
		1.000 M 100	- X 982	3159006
7.	How Property is Identified by the Surveyor	Amod Kumar 9833159006 From schedule of the properties mentioned in the deed, From name plate displayed on the property, Identified by the owner/ owner representative, I Enquired from nearby people, Identification of the property could not be done, Survey was not done		
8.	Are Boundaries matched	 Yes, □ No, □ No relevant papers available to match the boundaries, □ Boundaries not mentioned in available documents 		
9.	Survey Type	 Full survey (inside-out with measurements & photographs) Half Survey (Measurements from outside & photographs) Only photographs taken (No measurements) 		
10.	Reason for Half survey or only photographs taken NA	□ Property was locked, □ Possessee didn't allow to inspect the property, □ NPA property so couldn't be surveyed completely		
11.	Type of Property Residential land & bungalow	□ Flat in Multistoried Apartment, □ Residential House, □ Low Rise Apartment, □ Residential Builder Floor, □ Commercial Land & Building, □ Commercial Office, □ Commercial Shop, □ Commercial Floor, □ Shopping Mall, □ Hotel, □ Industrial, □ Institutional, □ School Building, □ Vacant Residential Plot, □ Vacant Industrial Plot, □ Agricultural Land		
12.	Property Measurement	Self-measured, Z Sample r	measurement, 🗆 No measu	irement
13.	Reason for no measurement	 It's a flat in multi storey building so measurement not required Property was locked, Owner/ possessee didn't allow it, NPA property so didn't enter the property, Very Large Property, practically not possible to measure the area within limited time Any other Reason: 		
14.	Land Area of the Property	As per Title deed	As per Map	As per site survey
		2024 M2	2024m2	
15.	Covered Built-up Area Sg-ft	As per Title deed	As per Map	As per site survey
	-BUA-4198 , CA	-3053 59.5t 1	3UA-335-15M2	sample
16.	Property possessed by at the time of survey	V Owner, V Vacant, D Less Property was locked, D Bar		. □ Couldn't be Surveyed
17.	Any negative observation of the	NO		

	property during survey	
18.	Is Independent access available to the property	Clear independent access is available, Access available in sharing of other
19.	Is property clearly demarcated with permanent boundaries?	adjoining property, No clear access is available, Access is closed due to dispute Yes, No, Only with Temporary boundaries
20.	Is the property merged or colluded with any other property	NO.
21.	Local Information References on property rates	Please refer attached sheet named 'Property rate Information Details.'

Endorsement:

1. Signature of the Person who was present from the owner side to identify the property:

Undertaking: I have shown the correct property and provided the correct information about the property to the surveyor of R.K Associates to the best of my knowledge for which Valuation has to be prepared. In case I have shown wrong property or misled the valuer company in any way then I'll be solely responsible for this unlawful act.

- a. Name of the Person: Ampd Kumar b. Relation: Employee c. Signature: d. Date: 09/03/23

In case not signed then mention the reason for it: \Box No one was available, \Box Property is locked, \Box Owner/ representative refused to sign it,
Any other reason:

2. Surveyor Signature who did site inspection:

Undertaking: I have inspected the property and cross verified the property details at site to the extent of a. Matching boundaries of the property, b. Sample measurement of its area, c. Physical condition, d. Property rates as per local information with what is mentioned in the property documents provided to me by the Bank/ interested organization. I have not come under influence of anyone during site inspection and have only recorded the true and factual details in the survey form which I come across during the site survey. I understand that giving any manipulative information in the survey form will lead to incorrect Valuation report which is an unlawful act and i'll be solely responsible for doing it.

- Name of the Surveyor: A bhishek Shanbhag a.
- b. Signature: c. Date: 09/03/23