File No.	RKA/DNCR//
Date of Receiving	06 03 2023
File Receiver Name	Abhicheks



CASE COLLECTION FORM (Version 5.0) Date of implementation: 9.02.2011 | Last Revision: 30.01.2020 | Latest Revision: 31.10.2020

ltems	Assigned To	Assigned to Date	To be completed by date	Submitted On date	Grade	HOD Engg. Signature
File Received By	Abhishele S	NA	NA			
Survey	Abhishef S.				_	
Preparation						

A - Very Good, B - Satisfactory, C - Average, D - Poor, E - Extremely Poor

Engg. unprepared due to reason	□ Survey not done properly, □ Survey Form not properly filled, □ Market survey for rates is not properly done, □ Identification is not clearly done, □ Measurement is not properly done, □ Photographs not clearly taken, □ Selfie/ Owner or owner representative photo not taken, □ Owner/ owner representative signature not taken, □ Google Map not taken, □ Survey summary sheet not filled
--------------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

In case File is returned		Minor	defects	in	the	survey	hence	approved	for	preparation	with	warning	to
by the preparer - HOD	Su	rveyor.	Report	orep	barer	to colle	ct the m	nissing info	rmat	tion on his ov	vn.		
Engg. comment &								020					
Signature		Maior o	defects in	the	e sur	vey. Su	vey has	s to be don	e ac	ain.			
orgnature	1.	Major C	lelects II	i u e	e sui	vey. ou	veyna	s to be don	c ag	ann.			

1312		GENER	AL DETAILS		1. 有限的 计时代	and the second
1.	Proposal/ Work Order or Ref. No.	VIS (2022-2	3)- PL 70	00 - 58	9	
2.	Type of Service	Valuation Report				tting certificate
3.	Type of customer	Bank	PSU Private clie	nt Dire	Corporate	Bank
4.	Bank/ FI/ Organization Name & Address	SBI SME,	Gorega	n (E) Mur	branch, nbai	
5.	Case Allotment Officer/	Name	Conta	act Number	En	nail Id
	Fees paying party Details	Anushq. s Rojeev · Prabi Case for Fres	7560	7582326	rajeeu p sbi-ce	rabhu @
6.	Case Type	Case for Fres	h Account	Case	for exiting acco	ount/ customer
7.	Fees Details	Amount of Fees	Advance Ar	nount if any	Fees wil	I be paid by
		35,000 + GIST	-	-	Bank	Customer
8.	Billing Details	Billed To Pa	arty Name		GSTI	N

Page 1 of 15

•

		CASE DETAILS	
1.	Type of Property	Residential + Commercia	
2.	Purpose of Valuation/ Assignment	 □ Value assessment of the asset for of □ Periodic Re-Valuation for Bank, □ I □ For DRT Recovery purpose, □ Cap 	Distress sale for NPA A/c., pital Gains Wealth Tax purpose
	e (r	□ Partition purpose, □ General Value Any other: Project Valuati	•
3.	Owner/Applicant Details Partners	Mr. Vikas Mi Kokane 088= 5000. Smite P. Dhoble Mr. Anil K. Thorat	29076445 saigroup. Kalyan @gmail.com
4.	Account Name	a: almaddle Der	velopeas
5.	Property Address	Road, Village- Mohane, 1	4433, Land survey no. 60/ -NRC, Titwale-Ambivli aluka-Kalyan, Dist-Thane Contact Number 421102
6.	Who will coordinate on site for the site survey	Name Sujit Butte	8652807945
7.	Preferred time of survey	Date 08 03 23	Time
8.	Documents Received (Any one ownership document and approved site plan/map is must) • Unsold inventory list • Sale deed cland) • OVR	 Ownership Documents: Sale D Registered Will, Relinquishme Conveyance Deed, Allotment Map: Cizra Map, Approved Ma Utility Bills: Electricity Bill & pa receipt, House Tax demand & pa Any Other document: CLU, Old Valuation Report No documents provided: G 	Letter, Possession Letter ap, Site Plan yment receipt, Water Bill & payment wment receipt
9.	Documents received from	Bank	
10.	Special Instructions if any:		
11.	LLL Contendiatort any	entioned above for the preparation of Valua facts and would not try to influence any me any individual or organization by any means	tion Report. I agree that I'll not put pressure ember or official of the firm in the ill spirit or s illegitimately.
	Customer Signature:		

File No. RKA/DNCR/...../

S.NO.	FILE RECEIVER CASE COLLECTION PROC (To be filled by Su COMPLIANCE CHECKLIST	rveyor)	
a series	and the second sec	STATUS	APPROVER SIGNATURE/ REMARKS IN CASE OF ANY (X
1.	Is Case collection Form properly filled by Receiver?	V	REMARKO IN CASE OF ANT (A
2.	Is purpose of the assignment understood clearly by the receiver?	N. N	
3.	Has receiver checked if this is a new case or existing case of the Bank?	Y	
4.	Has receiver fixed the fees with the manager/ client and sent quotation properly or have taken approval of the work over email?	U	
5.	Has receiver taken proper Work Order/ Email/ CESA form formality?		
6.	In case of private case or for fresh case 50% advance is received?		
7.	Is document checklist email sent to the customer?	U	
8.	Has the received documents is having 'documents provided by stamp'?		

IMPORTANT INSTRUCTIONS TO SURVEYOR

1.	Please fill the above compliance checklist before moving for the survey.
2.	Please do not do the survey if you do not have proper documents.
3.	For Vacant Plot/ Land – Cizra Map/ Master/ Zonal/ Site Plan is must to identify the Plot. For
	Agriculture or converted land from agriculture – Mutation documents, CLU is must.
4.	Firstly please first study the documents of the property which needs to get surveyed.
5.	Mark the Owner/ Area Boundaries mentioned in the ownership documents with bold florescent marker per before marine for the ownership documents with bold florescent
	marker pen before moving for the survey. During site survey if any difference is found in the
	above fields from the ownership documents then please contact the owner immediately to
	know the reason for the difference.
6.	Confirm ongoing property rates in the subject location through public domain, property sites and
	contact dealers to show you the available properties in that area during your survey.
7.	Identify the Property clearly by matching the boundaries and area mentioned in the property
	papers.
8.	Do sample physical or google measurements of the property.
9.	PHOTOGRAPH INSTRUCTIONS:
	a. Take owner/ representative photograph along with the property
	b. Take your selfie along with the property and the owner/ representative
	c. Take full scale photo of the property with gate.
	d. Take photo of the property along with abutting road, towards left, right and center
	e. Take multiple photos of inside-out of the property.
	f. Take nearby photographs of the Property.
	g. Take a short video to cover property and neighborhood.
10.	Take Google Map location.
11.	Check main road name & width and approach road width and distance of property from main road.
12.	oneck Juristiction Municipal Limits & Ward Name
13.	Fill each column of survey form diligently in detail and tick the appropriate and
14.	enconding defects of field livity in the property and commont in detail and
15.	Do extensive indiket rate enduiries and confirm for any recent next the
16.	In case customer appears to be providing misleading information to you or taking to internet
	money or cash then immediately report to the Management & Bank.
	, and an adjustment & Balik.

-	SURVEY GRADING MATRIX
GRADE	PAPAMETERO/ OPTER
. A	in case all the points below are done properly, timely with full care and diligence:
	 Survey started with proper work order and knowing the source of payment. Survey done with proper documents.
	 Done complete homework and studied the documents properly with highlighting the main points before moving for the survey.
	 Chosen correct survey form as per the property type. All fields of Survey form are properly filled.
	 All site special observations and negative and positive factors are clearly mentioned. Self & client signatures taken on survey form
	 Property rates information properly taken, mentioned and verified. Site rough sketch plan made.
	 Proper photographs taken. Selfie with property taken.
В	12. Selfie and owner photograph with property taken.
D	In case of 3 minor mistakes in any of the above points except Point 1, 2, 3, 4, 6, 8, 10, 11, 12 but all the points are covered.
С	In case of more than 3 minor mistakes and any 1 major mistake in any of the above points and if any points are completely missing except Point 1, 2, 3, 4, 6, 8, 10, 11, 12.
D	In case of 1 major mistake or missing of any 1 point out of 1, 2, 3, 4, 6, 8, 10, 11, 12.
E	In case of more than 1 major mistakes or missing of more than 1 point out of 1, 2, 3, 4, 6, 8, 10, 11, 12.

Note (Survey Grading Matrix):

- For special assignments like LIE, Stock Valuation, etc. where till date survey format is not specified or released, in such cases point wise site observation report has to be submitted by the Surveyor duly signing it properly. Without signed Site Observation report, Point 4 will be considered as not done and will fall under Category E.
- 2. Similar Grading Matrix is issued for Case Collection & Report Preparation as well.

Note (Overall Grading Matrix):

 In case client reports any careless mistake in the report for which revision has to be done in the report then in that case Grading Matrix may be revised and Grade E will be awarded.

GENERAL SURVEY FORM (FOR PROPERTIES OTHER THAN FLATS) (Version 5.0) Date of implementation: 9.02.2011 | Last Revision: 04.01.2018 | Latest Revision: 31.10.2020

Ĩ

	File No. RKA/DNCR//	Date: 08 03 23 Time:					
1.	Name of the Surveyor	GENERAL DETAILS					
2.		Achishele.s					
2.	Property shown by	[J] Owner, ☑ Representative, □ No one was available, □ Property					
		locked, survey could not be done from inside					
		Name Contact No.					
-		Sujit · Butte					
3.	Survey Type	□ Full survey (inside-out with measurements & photographs)					
		Half Survey (Measurements from outside & photographs)					
		□ Only photographs taken (No measurements)					
4.	Reason for Half survey or only	□ Property was locked, □ Possessee didn't allow to inspect the					
-	photographs taken NA	property, NPA property so couldn't be surveyed completely					
5.	How Property is Identified	□ From schedule of the properties mentioned in the deed, □ From					
		name plate displayed on the property. Identified by the owner/					
		owner representative, Enquired from nearby people,					
		□ Identification of the property could not be done, □ Survey was not					
6		done					
6.	Type of Property	□ Flat in Multistoried Apartment, □ Residential House, □ Low Rise					
	15 floods	Apartment, Residential Builder Floor, Commercial Land &					
	Residential	Building, Commercial Office, Commercial Shop, Commercial Shop, Commercial Shop,					
	Commercial Ish of	Floor, Shopping Mall, Hotel, Industrial, Institutional.					
	L8 B	School Building, Vacant Residential Plot, Vacant Industrial					
7.		Flot, L Agricultural Land					
1000	Property Measurement	□ Self-measured, Sample measurement only, □ No measurement					
8.	Reason for no measurement	in it's a hat in multi storey building so measurement not required					
		Property was locked, Owner/ possessee didn't allow it					
		□ NPA property so didn't enter the property, □ Very Large Property,					
	NA	practically not possible to measure the entire area Any other					
		Reason:					
Э.	Purpose of Valuation	□ Value assessment of the asset for creating new collateral mortgage					
	Project Valuation	□ Periodic Re-Valuation for Bank, □ Distress sale for NPA A/c.,					
		□ For DRT Recovery purpose, □ Capital Gains Wealth Tax purpose					
		□ Partition purpose, □ General Value Assessment					
0.	Type of Loan	□ Housing Loan. □ Housing Take Over Loss = 5.0					
	Business loan	□ Housing Loan, □ Housing Take Over Loan, □ Home Improvement					
		Loan, Loan against Property, Construction Loan, Educational Loan, Car Loan					
		Loan, Car Loan, Project Loan, Term Loan, CC Limit					
1.	Loan Amount	enhancement, Cash Credit Limit, Industrial Loan, NA					
		2					

Page 6 of 15



		OWNERSHIP DETAILS
1.	Legal Owner Name/s	<u>OWNERSHIP DETAILS</u>
2.	Property Purchaser Name	<u> </u>
3.	Property Address under Valuation	Pg-2 Pg-2
4.	Present Residence Address of the Owner/ Purchaser	-
5.	Property constitution	Free Hold, Lease Hold

	LOC/	TION DET	AILS	除你的任何 。	的 、在中世界的中世	学校。オマリ	物和自己的
Adjoining Properties		st	West		North	STRATE AND	South
	d .	T	Hwala	- M	ohan	ope	n
				K	heda		
				Bu	ilder		veloper
Property Facing	East F	acing, 🗆 No		West	Facing, C So	uth Fa	acing,
N-S	□ North-I	East Facing	□ South-	West Fac	ina. 🗆 South-E	East F	acing.
Landmark		-					
Latry							
	44-	Taluka	- Kaly	an,	Dist - TA	ani	e
Main Road Name & Width	N	ame		Width	Distance	from	property
Titwala	- Ambiu	li Roas	L	-	20	mt	8.
	-						9
Location consideration of the	U Within	Main city, [Within C	Good Urba	an developed A	Area,	Within
Society							
			5, P	is sump, _	, voly 0000, L	1 000	ju,
	C Ordina						
	Ordinary	v, 🗆 In inte	eriors, 🗌 R	emote are	ea, 🗌 Backwai	rd, 🗆	Average,
	Ordinary Poor	v, □ In inte	eriors, 🗌 R	emote are	ea, 🗌 Backwai	rd, 🗆	Average,
Special Location consideration	Poor						
Special Location consideration of the property	Poor Park Fa	acing, 🗆 Po	ool Facing		ea, ⊡ Backwar I Facing, ⊡ E		
of the property	□ Poor □ Park Fa East Facin	acing, 🗆 Po g, 🖬 Sunligi	ool Facing ht facing	Road	I Facing, 🗆 E	ntrand	ce North-
	□ Poor □ Park Fa East Facin	acing, 🗆 Po g, 🖬 Sunligi	ool Facing ht facing	Road		ntrand	ce North-
of the property	 Poor Park Fa East Facin Urban d 	acing, 🗆 Po g, 🖬 Sunligi	ool Facing ht facing] Urban de	. Road	I Facing, 🗆 E	ntrand	ce North-
of the property Characteristics of the locality	 Poor Park Facing Urban d Backwar 	acing, Po g, Sunligi eveloped, d, Industr	ool Facing ht facing] Urban de rial, □ Inst	, Road eveloping, itutional	I Facing, □ E	ntrano	ce North- Rural,
of the property	 Poor Park Fa East Facing Urban d Backwar High End 	acing, Po g, Sunlig eveloped, d, Industri d, Norma	ool Facing ht facing] Urban de rial, □ Inst	, Road eveloping, itutional	I Facing, 🗆 E	ntrano	ce North- Rural,
of the property Characteristics of the locality Category of Society/ locality	Poor Park Fa East Facing Urban d Backwar High Eng MIG, □	acing, Po g, Sunlig eveloped, d, Industr d, Norma LIG	ool Facing ht facing] Urban de rial, □ Inst I, □ Afforc	eveloping, itutional lable Grou	I Facing,	ntrand n, 🗆 F EWS	ce North- Rural,
of the property Characteristics of the locality Category of Society/ locality	Poor Park Facing Cast Facing Urban d Backwar High Eng MIG, Cast	acing, Po g, Sunligi eveloped, d, Industr d, Norma LIG Garden, I	ool Facing ht facing] Urban de rial, □ Inst I, □ Afforc Landscapi	eveloping, itutional lable Grou	I Facing, E E Semi Urbar Up Housing, D D D D D D D D D D D D D D D D D D D	ntrano n, 🗆 F EWS	ce North- Rural, , □ HIG,
of the property Characteristics of the locality Category of Society/ locality Utilities/ Facilities in the locality	Poor Park Facing Cast Facing Urban d Backwar High Eng MIG, Cast	acing, Po g, Sunligi eveloped, d, Industr d, Norma LIG Garden, I	ool Facing ht facing] Urban de rial, □ Inst I, □ Afforc Landscapi	eveloping, itutional lable Grou	I Facing,	ntrano n, 🗆 F EWS	ce North- Rural, , □ HIG,
of the property Characteristics of the locality Category of Society/ locality	Poor Park Facing Curban d Backwar High Eng MIG, D Club Ho	acing, Po g, Sunligi eveloped, d, Industr d, Norma LIG Garden, I	ool Facing ht facing] Urban de rial, □ Inst I, □ Afforc Landscapi	eveloping, itutional lable Grou	I Facing, E E Semi Urbar Up Housing, D D D D D D D D D D D D D D D D D D D	ntrano n, 🗆 F EWS	ce North- Rural, , □ HIG, n, % Power
of the property Characteristics of the locality Category of Society/ locality Utilities/ Facilities in the locality	Poor Park Fa East Facin Urban d Backwar High End MIG, D Club Ho Backup School	acing, Po g, Sunlig eveloped, d, Industr d, Norma LIG Garden, Wa Hospital	ool Facing ht facing] Urban de rial, □ Inst I, □ Afforc Landscapin alk Trails, 1 Market	eveloping, itutional lable Grou Metro	I Facing, □ E Semi Urbar Ip Housing, □ Imming Pool, [] Iplay zone, □ Railway Star	ntrano n,	ce North- Rural, , □ HIG, n, % Power Airport
of the property Characteristics of the locality Category of Society/ locality Utilities/ Facilities in the locality	Poor Park Fa East Facing Urban d Backwar High Eng High Eng MIG, Club Ho Backup School I·8 km	acing, Po g, Sunligi eveloped, d, Industr d, Norma LIG Garden, Wa	ool Facing ht facing] Urban de rial, □ Inst I, □ Afford Landscapin alk Trails, ' Market 4 00m	eveloping, itutional lable Grou	I Facing, □ E Semi Urbar up Housing, □ mming Pool, [] play zone, □	ntrand n,	ce North- Rural, , □ HIG, n, % Power
	(Match it with papers with the help of compass or Sun direction and also confirm it with nearby people) Property Facing N S Landmark Ward Name/ No. Zone Name Main Road Name & Width Tituda Approach Road Name & Width Location consideration of the	(Match it with papers with the help of compass or Sun direction and also confirm it with nearby people) Chaw Chaw Chaw Chaw Chaw Chaw Chaw Chaw	(Match it with papers with the help of compass or Sun direction and also confirm it with nearby people) Chawl T Property Facing □ East Facing, □ No N S □ North-East Facing, □ North-West Facing Landmark Fatry Nr: NRC Ward Name/ No. Image - Village - Zone Name Name Main Road Name & Width Name Location consideration of the □ Within Main city, □	(Match it with papers with the help of compass or Sun direction and also confirm it with nearby people) Chawl Titwala Property Facing Image: Chawl Titwala Ambiviti N S Image: Chawl Image: Chawl Ambiviti N S Image: Chawl Image: Chawl Image: Chawl Ambiviti Property Facing Image: Chawl Image: Chawl Image: Chawl Image: Chawl Ambiviti N Image: Chawl Image: Chawl Image: Chawl Image: Chawl Image: Chawl Image: Chawl Landmark Fatry Nr NRC Image: Chawl Image: Chawl	(Match it with papers with the help of compass or Sun direction and also confirm it with nearby people) Chawl Titwala - Ambi'uli Mu Property Facing Image: Chawl Image: Chawl Titwala - Ambi'uli Mu N S Image: Chawl Image: Chawl Image: Chawl Image: Chawl Property Facing Image: Chawl Image: Chawl Image: Chawl Image: Chawl Image: Chawl N S Image: Chawl Image: Chawl Image: Chawl Image: Chawl Image: Chawl Landmark Fatny Nr<	(Match it with papers with the help of compass or Sun direction and also confirm it with nearby people) Chawl Titwala - Ambivli Mohan Kheda Property Facing □ East Facing, □ North Facing, □ West Facing, □ So N - S □ North-East Facing, □ South-West	(Match it with papers with the help of compass or Sun direction and also confirm it with nearby people) Chawl Titwala - Ambivili Mohan open Property Facing [] [] East Facing, [] North Facing, [] West Facing, [] South Facing, [] N - S [] North-East Facing, [] South-West Facing, [] South-East Facing, [] Landmark Fatry Nr<


Page 7 of 15

15.	Jurisdiction limits	🗌 🗆 Nagar Nigam, 🗆 Nagar Panchayat, 🗆 Gram Panchayat, 🗆 Nagar
ļ	KDMC	Palika Parishad, Area not within any municipal limits
16.	Jurisdiction Development	□ DDA, □ GDA, □ NOIDA, □ GNIDA, □ YEIDA, □ HUDA, □KMDA,
	Authority Name	□ MDDA, □ Any other Development Authority:
	KDMC	□ Area not within any development authority limits
17.	Municipal Corporation Name	□ NDMC, □ SDMC, □ EDMC, □ Ghaziabad Municipal Corporation,
		□ Gurgaon Municipal Corporation, □ Faridabad Municipal Corporation,
	Kalyan- Dombiuli MC	🗆 Kolkata Minicipal Corporation, 🗆 Dehradun Municipal Corporation,
	Jombivili ric	🗆 Area not within any municipal limits, 🗆 Any other Municipal
		Corporation/ Municipality:

		PHYSICAL DETAIL	LS	
1.	Land Area	As per Title deed	As per Map	As per site survey
		2270 m2	-	2000 Ston the
2.	Any conversion to the land use	NA		2226m2
3.	Land Type	logged, 🗆 Land locked		aimed Land, 🗆 Water
4.	Shape of the Land	Irregular, 🗆 NA		iangular, 🛛 Trapezoid,
5.	Level of Land	🗆 On road level, 🗆 Bel	low road level, Above	road level, 🗆 NA
6.	Frontage to depth ratio	Normal frontage, Less frontage, Large frontage, NA		
7.	Are Bouldaries matched	□ Yes, □ No, □ No relevant papers available to match the boundaries, □ Boundaries not mentioned in available documents		
8.	Is Independent access available to the property		ng property, 🗆 No clea	Access available in ar access is available,
9.	Is property clearly demarcated with permanent boundaries?	Yes, 🗆 No, 🗆 Only v	with Temporary boundari	es
10.	Is the property merged or colluded with any other property	NO		
11.	Property possessed by at the time of survey	Owner, ✓ Vacant, □ Lessee, □ Under Construction, □ Couldn't be Surveyed, □ Property was locked, □ Bank sealed, □ Court sealed		
12.	Current activity carried out in the property	Residential purpos		

1 Spect	BUIL	DING/ CONSTRUCTION/ UTLITY DETAILS
1.	Construction Status	Built-up property in use, Under construction, No construction

2.	Covered Built-up Area	Coursed &		1
		Covered Area,	-loor Area, 🗆 Super	Area; Carpet Area
ŀ	(Tick one on the basis of which valuation is to be calculated)	As per Title deed	As per Map	As per site survey
. 3.	Total Number of Floors in the			Pg.11
	Building	Pg.11		
4.	Floor on which property is situated	Pg.11		
5.	Type of Unit/ Number of Rooms/ Cabins/ Cubicles	Pg.11		
6.	Building Type			
		The second secon		ring Pillar Beam column, usses & Pillars, □ Scrap
7		abandoned structure	/	
7.	Roof	a. Make: RBC, Patla	RCC, GI Shed	, 🗆 Tin Shed, 🗆 Stone
		b. Height: fg.	11	
		c Finish: Simple		Punning, 🗆 POP False
		Ceiling, Coved re		unning, El t et t unee
8.	Flooring			mple marble, 🗆 Marble
1		chips, Mosaic, Gr		
				□ Pavers, □ Chequered
1			No Flooring, 🗆 Un	der construction, 🗆 Any
9.	Appearance/ Condition of the	other type:	t Diver Cood	□ Good, □ Ordinary,
	Building			
	5	Average, Poor		
		Average, Poor	Inder construction	🗆 Good, 🗆 Ordinary,
10.	Maintenance of the Building	Very Good, Avera	ae. Poor Unde	er construction
11.				Simple, Ordinary,
		Average, Below av	verage, Under cor	astruction, No Survey
12.	Interior Finishing	Simple plastered wall	s, D Brick walls with	out plaster,
		Designer textured wa		
		□ Under construction, □	No Survey	
13.	Exterior Finishing	Simple plastered	walls, Brick	walls without plaster,
		□ Architecturally desig	gned or elevated, [□ Brick tile Cladding,
		□ Structural glazing, □	Aluminum composite	e panel cladding,
14.	Kitchen	□ Glass façade, □ Dom	ib, 🗆 Porch, 🗆 Unde	er construction
14.	Kichen	Modular with chimpoy	Dard, Crdinary wit	h cupboard, D Normal
		construction, No Surv	av end wodular	with chimney, Under
15.	Class of Electrical fittings	External,		
		Ordinary fixtures &	fittings. Fancy	lights C Chandeliers
		Concealed lightning, [Under construction	n, 🗆 No Survey
16.		External, Internal		
	water supply fittings	Excellent, D Very God	od, 🗆 Good, 🗆 Simp	ole, 🗆 Average,
17		🗆 Below average, 🗆 Un	der construction, 🗆 I	No Survey
17.	Water arrangements	□ Jet pump, □ Submersible, □ Jal board supply □ Excellent, □ Very Good, □ Good, □ Simple, □ Ordinary,		
18.	Fixed Wooden Work	L Excellent, Provide Very (Good, 🗆 Good, 🗆	Simple, Ordinary,
		Average, D Below Average	erage, 🗆 No wooder	n work, 🗆 No survey
19.	improvements done	year mid 202	3 unde	r construction 5% complete)
20.	Maintenance of the Building	ding Very Good, Average, Poor		




1111	MARKETABI	ITY/ SEL	ABILITY/ UTLITY DETAILS			
1.	property?		□ Yes, INo Reason in case of No: I Location, I Surrounding, □ Legal aspects, □ Demand, □ Shape, □ Any Other:			
2.	How is Demand & Supply condition	Demand	□ Very Good, Good, □ Average, □ Low, □ Poor			
	in the Market of such properties?	Supply	□ Very Good, 🗹 Good, □ Average, □ Low, □ Poor			
3.	Is property easily sellable & marketable?	Yes, [No			
		Comment	S:			
4.	How is the current utility of the property?	□ Excellent, □ Very Good, □ Good, □ Average, □ Low, □ Poor				
5.	At what True rate Owner bought	Year of pu	Irchase			
	this Property?	Purchase	Price			
6.	Present expected Sale Value of the overall property?					

BLANK PAGE FOR PROVIDING ANY ADDITIONAL DETAILS/INFORMATION

.

٠

$$IBHK (2^{NH} Fly) (52.Ft) I RK (2^{NH} Fly) (52.Ft) (1 RK (2^{NH} Fly) (52.Ft) (52.Ft)$$



THE REAL	Particul Avelle	olo loi Gale U	MPARABLE RATE IN r Transaction already h	annened in past)	
i.No		Subject Property	Comparable 1	Comparable 2	Comparable 3
1.	Name (source of information)	NA	Sales. office		and the state of the
2.	Contact No.	NA	983380769	7	
3.	Type of source of information (Seller/ Property dealer/ nearby people)	NA	Kisti. Patil		
4.	Rates/ Price informed (in Rs. with unit)	NA	Buy		
5.	Rates Type (Sale/ Buy)	NA	5200/52.77 BUA		
6.	Shape of the Property (Square, Rectangular, Irregular)		-		
7.	Area/ Size of the Property	BUA	- 475 to 700 Sq. ft		
8.	Legal Status (clear, negative, weak)/ No. of owners		clear		
9.	Location/ surrounding/ neighborhood comparison with the subject property (Similar, Lower, Better, Highly Better than the subject Property)	Base Case	Same bldg		
10.		0	-		
11.	Other factors (Corner, 2 side open, North-East facing, Park facing, Legal/ Financial encumbrance, etc.)		_		
12.	Approach road width		-		
13.	Level of Land (Below/ On/ Above road level)		Above		
14.	Frontage to depth ratio (Normal, Less, Large)		Normal		
15.	Present Use		Vacant		
16.	Any other details/ Discussion held	NA	office-Isklse shop-25k/sz-fl	st t	
17.	Present expected Sale Value of the overall property?	-			

Page 13 of 15

UNDERTAKING BY THE CUSTOMER

I confirm that I have made the inspection of the subject property to the surveyor of R.K Associates, which is correct property in question for which the documents have been provided/ submitted by me. I further confirm that I am aware of all the information related to the subject property and I have provided all its information to the surveyor true to the best of my knowledge. I understand that any false or manipulative information provided by me will be considered as cheating with the professional organization since it will lead to incorrect valuation report and I'd be solely responsible for this unlawful act and will bear the charges for the changes/ modifications which have to undergo due to the false information. I also undertake that I heve not given any cash or in kind to any member of R.K Associates to influence the Value of the Property or favor any individual or organization and the same is not accepted or asked by the member of R.K Associates. Any such act will lead to cancellation of the material prepared by R.K Associates with forfeiting of the fees and i'll be completely responsible for its repercussions and legal actions taken for it.

IMPORTANT: We have not authorized any of our person/ Surveyor to take Cash or kind from the customers in any situation. In case Surveyor or any member of R.K Associates asks for any money or kind from you then kindly please inform on number +91-9958632707, 0120-4110117. Our Valuation process is very stringent and have multiple check points to ensure correct & error free reports to keep the lending agency risk free. In case Surveyor claims that he would be able to arbitrary effect the Valuation figures unfairly or as per your requirement & need, then he is making a false claim to you and we request you to complaint such act immediately on the number provided above.

Name	Sujit Butte
Relationship with owner	Company employee
Signature	By
Mobile No.	8652807945
Date	08 03 23

UNDERTAKING BY THE SURVEYOR

I confirm that I have carried out the Survey of the property properly as per the fair professional best practices and Valuation & Survey policy guidelines issued by R.K Associates. I have not taken any cash or kind from the customer nor have I come into any kind of influence of the customer / bank for arbitrary providing the Property Valuation as per one's need. I further state that I have not given any assurances to the customer nor given any wrong or false information or statement. In case at any point of time it is found that I have done any kind of fraudulent activity in this case and misled the company then I understand its legal consequences and appropriate penal action which company can take against me. Also in regard to it any monetary or reputation loss will be recovered from me by the company.

For File No.	
Surveyor Name	Abhishet Shanbhag
Signature	æ
Date	08 03 23

Page 14 of 15

(Version 1.0) | Date of implementation: 10.04.2017

Every Valuation report at R.K Associates is prepared based on the thorough survey of the property carried out by our Engineering Surveyor. This Survey Summary Sheet is for the information of Banker/ concerned interested organization. Detailed Survey Form can also be made available to the interested organization. In case it is required to cross check what information our surveyor has given in site inspection report based on which Valuation report is prepared.

1.	File No.	VIS (2022-23) - PL700- 589			
2.	Name of the Surveyor	Abhishek-S			-
3.	Borrower Name Partners	An INFOR M. Kat	NO LIVER MIKETORE MASOW: SMITHI ONCO		
4.	Nameaftheowger	and My Anil· K? Thorat			7
5.	Property Address which has to be valued	Sai Icon, CTS n.	Sai Icon, CTS n. 4431 & 4433, Nr. Nr.		
6.	Property shown & identified by at spot	Ambiuli Koad, Villege- Mohane, Image: Ambiuli Koad, Survey Image: Owner, Image: Ambiult Koad, Image: Ambiuli Koad, Villege- Mohane, Image: Ambiuli Koad, Survey Image: Owner, Image: Ambiult Koad, Villege- Mohane, Image: Ambiuli Koad, Villege- Mohane, Image: Ambiuli Koad, Survey Image: Owner, Image: Ambiult Koad, Villege- Mohane, Image: Ambiult Koad, Villege- Mohane, Image: Ambiult Koad, Ima			
7.	How Property is Identified by the Surveyor	From schedule of the pudisplayed on the property, Enquired from nearby peop	ldentified by the le, [] Identification	of the property could not be done,	
8.	Are Boundaries matched	□ Yes, □ No, □ No r	elevant papers ava	ilable to match the boundaries, ents	
	×	Boundaries not mentione	d in available docum	nhotographs)	1
9.	Survey Type	 Full survey (inside-out with measurements & photographs) Half Survey (Measurements from outside & photographs) Only photographs taken (No measurements) 			
10.	Reason for Half survey or only photographs taken	□ Only photographs taken (no medicated din't allow to inspect the property, □ NPA □ Property was locked, □ Possessee didn't allow to inspect the property, □ NPA property so couldn't be surveyed completely			
11.		Residential Builder Floor, Commercial Shop, Comm Institutional, School B Plot, Agricultural Land	□ Flat in Multistoried Apartment, □ Residential House, □ Low Rise Apartment, □ □ Residential Builder Floor, □ Commercial Land & Building, □ Commercial Office, □ Commercial Shop, □ Commercial Floor, □ Shopping Mall, □ Hotel, □ Industrial, □ Institutional, □ School Building, □ Vacant Residential Plot, □ Vacant Industrial		
12.	Property Measurement	Self-measured, Sampl	e measurement, ⊔ I	No measurement	-
13.		□ It's a flat in multi storey building so measurement not required □ Property was locked, □ Owner/ possessee didn't allow it, □ NPA property so didn't enter the property, □ Very Large Property, practically not possible to measure the area within limited time □ Any other Reason: $2226 m^2$			
14.	Land Area of the Property	As per Title deed	As per Map	As per site survey	_
14.		2270m2	-	28883 16A	_
15.	Covered Built-up Area	As per Title deed	As per Map معلم	sample	
16.	Property possessed by at the time of survey	Owner, Vacant, D Le			
17.	i i stabe	None			

	property during survey	
18.	Is Independent access available to the p, operty	Clear independent access is available, Access available in sharing of other
19.	Is property clearly demarcated with	adjoining property, No clear access is available, Access is closed due to disp ute
20.	Is the property merged area in the	Yes, 🗆 No, 🗆 Only with Temporary boundaries
	with any other property	NO
21.	Local Information References on property rates	Please refer attached sheet named 'Property rate Information Details.'

Endorsement:

1. Signature of the Person who was present from the owner side to identify the property:

Undertaking: I have shown the correct property and provided the correct information about the property to the surveyor of R.K Associates to the best of my knowledge for which Valuation has to be prepared. In case I have shown wrong property or misled the valuer company in any way then I'll he solely responsible for this unlawful act.

- a. Name of the Person: Sujit Butte b. Relation: Company employee c. Signature: Gue
- d. Date: 08 03 23

In case not signed then mention the reason for it: 🗆 No one was available, 🗆 Property is locked, 🗆 Owner/ representative refused to sign it,
Any other reason:

2. Surveyor Signature who did site inspection:

Undertaking: I have inspected the property and cross verified the property details at site to the extent of a. Matching boundaries of the property, b. Sample measurement of its area, c. Physical condition, d. Property rates as per local information with what is mentioned in the property documents provided to me by the Bank/ interested organization. I have not come under influence of anyone during site inspection and have only recorded the true and factual details in the survey form which I come across during the site survey. I understand that giving any manipulative information in the survey form will lead to incorrect Valuation report which is an unlawful act and i'll be solely responsible for doing it.

- a. Name of the Surveyor: Abhishek S
- b. Signature:
- Date: 08 03 23 c.

S99	STST	твнк
<u>\$99</u>	72 7 4	твнк
455	ETST	твк
455	7757	твк
S99	TIST	твнк
S99	OTST	твнк
002	60ST	твнк
059	90ST	твнк
S69	SOST	твнк
059	170ST	твнк
059	7057	твнк
059	TOST	JBHK
S/7	1413	ТВК
S/7	1513	твк
060T	608	твнк
S66	508	твнк
S/t/	2010	OFFICE
370	5010	OFFICE
220	0104	OFFICE
250	60TO3	OFFICE
580	LS	dOHS
308	SS	dOHS
082	†∕S	dOHS