~	PL724-609-99
File No.	RKA/DNCR//
Date of Receiving	20/3/2023
File Receiver Name	Abhishek Shanbhag.



CASE COLLECTION FORM

(Version 5.0) Date of implementation: 9.02.2011 | Last Revision: 30.01.2020 | Latest Revision: 31.10.2020

Items	Assigned To	Assigned to Date	To be completed by date	Submitted On date	Grade	HOD Engg. Signature
File Received By	Abhshek Shambhag	NA	NA			
Survey	Shreyash Shetty.	20/3/23.				
Preparation	j	appe				

A - Very Good, B - Satisfactory, C - Average, D - Poor, E - Extremely Poor

File Returned to HOD Engg. unprepared due to reason	 □ Survey not done properly, □ Survey Form not properly filled, □ Market survey for rates is not properly done, □ Identification is not clearly done, □ Measurement is not properly done, □ Photographs not clearly taken, □ Selfie/ Owner or owner representative photo not taken, □ Owner/ owner representative signature not taken, □ Google Map not taken, □ Survey summary sheet not filled
---	---

In case File is returned by the preparer - HOD Engg. comment &	☐ Minor defects in the survey hence approved for preparation with warning to Surveyor. Report preparer to collect the missing information on his own.
Signature	□ Major defects in the survey. Survey has to be done again.

		GENER	AL DETAILS	41		
1.	Proposal/ Work Order or Ref. No.	PL724-	609-99	4.		
2.	Type of Service	Valuation Report			ate, 🗆 Cost ve	etting certificate
3.	Type of customer	Bank Company	PSU Private client	NBFC	Corporate t client throug	
4.	Bank/ FI/ Organization Name & Address	SBI, SME, C				
5.	Case Allotment Officer/ Fees paying party Details	Name Mr. Mshit		> 92947		nail ld nawct@shico.iu
6.	Case Type	Case for Fres	sh Account	□ Case f	or exiting acco	ount/ customer
7.	Fees Details	Amount of Fees 61000+655	Advance Am	ount if any		Le paid by
			-			

Page 1 of 15

		CASE DETAI	LS		
1.	Type of Property	Residential Flat			
2.	Purpose of Valuation/ Assignment	Value assessment of the Periodic Re-Valuation fo For DRT Recovery purpo Partition purpose, Ger Any other:	e asset for o or Bank, □ I ose, □ Cap	Distress sale fo bital Gains Wea	or NPA A/c.,
3.	Owner/ Applicant Details	Name Satyendra Sukhram		ct Number { Pawan K	Email Id aburam Vishnor
4.	Account Name	Mbl Shivam Pr	ime I	nfrastrur	ture Put. 14.
5.	Property Address	Mb Shivam Pri Flat No. 503, 5th Flo Soc. Etd., CTS No. 2	249/B, E	ling, Kamla Eksar, Bor	Enclave Co-op-Itsg ival West, off. Dr
6.	Who will coordinate on site for the site survey	Name			ntact Number
7.	Preferred time of survey	Mrs. Pawan S. Sahu Date 20/3/202			5:00pm
8.	Documents Received (Any one ownership document and approved site plan/ map is must)	 Ownership Documents: Registered Will, Redistered Will, Rediste	Sale De linquishmer Allotment L oproved Ma y Bill & pay mand & pay CLU,	eed, Power of ht Deed, Tra letter, Posse p, Site Plan ment receipt, ment receipt	of Attorney, insfer Deed, ession Letter Water Bill & payment
9.	Documents received from	Customer.			
10.	Special Instructions if any:				
11.	on valuer min to distort any f	entioned above for the preparatio facts and would not try to influen any individual or organization by a	nce any mem	ber or official of	e that I'll not put pressure f the firm in the ill spirit or

File No. RKA/DNCR/ 1. PL7@ 24-609-994.

	FILE RECEIVER CASE COLLECTION PROC (To be filled by Sui		PLIANCE CHECKLIST
S.NO.	COMPLIANCE CHECKLIST	STATUS	APPROVER SIGNATURE/ REMARKS IN CASE OF ANY (X)
1.	Is Case collection Form properly filled by Receiver?	V/	
2.	Is purpose of the assignment understood clearly by the receiver?	V	
3.	Has receiver checked if this is a new case or existing case of the Bank?	V	
4.	Has receiver fixed the fees with the manager/ client and sent quotation properly or have taken approval of the work over email?	Ø	/
5.	Has receiver taken proper Work Order/ Email/ CESA form formality?	V	
6.	In case of private case or for fresh case 50% advance is received?	V	/
7.	Is document checklist email sent to the customer?	V	
8.	Has the received documents is having 'documents provided by stamp'?		

IMPORTANT INSTRUCTIONS TO SURVEYOR

1.	Please fill the above compliance checklist before moving for the survey.
2.	Please do not do the survey if you do not have proper documents.
3.	For Vacant Plot/ Land - Cizra Map/ Master/ Zonal/ Site Plan is must to identify the Plot. For
	Agriculture or converted land from agriculture – Mutation documents, CLU is must.
4.	Firstly please first study the documents of the property which needs to get surveyed.
5.	Mark the Owner/ Area/ Boundaries mentioned in the ownership documents with bold florescent
	marker pen before moving for the survey. During site survey if any difference is found in the
	above fields from the ownership documents then please contact the owner immediately to
	know the reason for the difference.
6.	Confirm ongoing property rates in the subject location through public domain, property sites and
	contact dealers to show you the available properties in that area during your survey.
7.	Identify the Property clearly by matching the boundaries and area mentioned in the property
	papers.
8.	Do sample physical or google measurements of the property.
9.	PHOTOGRAPH INSTRUCTIONS:
	a. Take owner/ representative photograph along with the property.
	b. Take your selfie along with the property and the owner/ representative.
	c. Take full scale photo of the property with gate.
	d. Take photo of the property along with abutting road, towards left, right and center.
	e. Take multiple photos of inside-out of the property.
	f. Take nearby photographs of the Property.
	g. Take a short video to cover property and neighborhood.
10.	Take Google Map location.
11.	Check main road name & width and approach road width and distance of property from main road.
12.	Check Jurisdiction Municipal Limits & Ward Name.
13.	Fill each column of survey form diligently in detail and tick the appropriate option clearly.
14.	Check any defects or negativity in the property and comment in detail on survey form.
15.	Do extensive market rate enquiries and confirm for any recent past transactions.
16.	In case customer appears to be providing misleading information to you or trying to influence you by
	money or cash then immediately report to the Management & Bank.

Y	SURVEY PROCESS COMPLIANCE CHECKLIST	
1. N.	(To be submitted by Surveyor with each Survey)	W. Alla Conte
S.NO.	COMPLIANCE CHECKLIST POINTS	STATUS
1.	Did you take proper property documents to carry out the survey?	STATUS
2.	Have you properly studied & highlighted Owner/ Area/ Boundaries in the property documents with bold florescent before moving for the survey?	
3.	Did you check prominent landmark nearby the subject property and mentioned in the survey form?	U
4.	Did you identified the Property clearly by matching the boundaries and area mentioned in the property papers?	P
5.	Did you check if property is merged with any other property or it is an independent property?	2
6.	Did you do sample physical or google measurements of the property in case of property more than 2500 sq.mtr?	A
7.	Did you check for any building violations in the property?	E/
8.	Did you check municipal limits/ jurisdiction/ ward?	R
9.	Did you take Google Map location and shared it to Maps whatsapp group?	Ø
10.	Did you check Main road name & width and its distance from the subject property?	2
11.	Did you check approach Lane width on which property is located?	9
12.	Have you taken property full scale photograph with gate?	Ø
13.	Have you taken owner/ representative photograph with the property?	8
14.	Have you taken your selfie with the property along with owner/ representative?	P
15.	Have you taken photograph of the property along with abutting road and towards left and right of the property?	2
16.	Have you taken multiple photographs of the property from inside-out?	8
17.	Did you check nearby development and whereabouts and commented on survey form?	Ø
18.	Did you check any defects or negativity in the property in terms of location, legality, disputes marketability, salability, atc. and commented on survey form in details	2
19.	disputes, marketability, salability, etc. and commented on survey form in detail?	
	Have you filled all the columns of survey form including survey summary sheet properly?	
20.	Did you draw site key plan (location map)?	
21.	Did you draw rough site sketch plan?	
22.	Have you taken self-attested documents from owner/ representative and stamped "documents provided by stamp"?	-
23.	Did you check any defects or negativity in the property in terms of location, legality, disputes, marketability, salability, etc. and commented on survey form in detail?	V
24.	Have you confirmed any recent past transactions during market enquiries and enquired property rates locally very rigorously?	9
25.	Did you take signatures of the owner/ representative on undertaking and survey summary sheet?	Ý
26.	Did you signed the undertaking?	Y

For File No.	PL724-609-994
Surveyor Name	Shreyash Shetty.
Signature	Toutes
Date	20/3/2023.

PARTITION AND

Stall and

	GENERAL SURVEY FORM (FOR PROPERTIES OTHER THAN FLATS) (Version 5.0) Date of implementation: 9.02.2011 Last Revision: 04.01.2018 Latest Revision: 31.10.2020			
	File No. RKA/DNCR/	Date: 20/3/2023 Time: 2:00pm		
1 sec	Benchar and Stranger Stranger	GENERAL DETAILS		
1.	Name of the Surveyor	Shreyash. Shetty.		
2.	Property shown by	Owner, D Representative, No one was available, Property is		
		locked, survey could not be done from inside		
		Name Contact No.		
		Mrs. Paulan Sah. 99303 51220.		
3.	Survey Type	Mrs. Pawan - Sahu. 99303 51270. Full survey (inside-out with measurements & photographs)		
		□ Half Survey (Measurements from outside & photographs)		
		Only photographs taken (No measurements)		
4.	Reason for Half survey or only	□ Property was locked, □ Possessee didn't allow to inspect the		
	photographs taken N.A.	property, NPA property so couldn't be surveyed completely		
5.	How Property is Identified	From schedule of the properties mentioned in the deed, From		
		name plate displayed on the property, V Identified by the owner/		
		owner representative, D Enquired from nearby people,		
		□ Identification of the property could not be done, □ Survey was not		
6.	Tupo of Droport	done		
0.	Type of Property	Flat in Multistoried Apartment, Residential House, Low Rise		
		Apartment, C Residential Builder Floor, C Commercial Land &		
		Building, Commercial Office, Commercial Shop, Commercial		
	G+7 Blog.	Floor, Shopping Mall, Hotel, Industrial, Institutional,		
		□ School Building, □ Vacant Residential Plot, □ Vacant Industrial		
7.	Property Measurement	Plot, Agricultural Land		
8.	Reason for no measurement	Self-measured, Sample measurement only, No measurement		
Ξ.	inclusion for no measurement	□ It's a flat in multi storey building so measurement not required		
		□ Property was locked, □ Owner/ possessee didn't allow it,		
		□ NPA property so didn't enter the property, □ Very Large Property,		
		practically not possible to measure the entire area Any other		
	NA	Reason:		
9.	Purpose of Valuation			
		Value assessment of the asset for creating new collateral mortgage		
		□ Periodic Re-Valuation for Bank, □ Distress sale for NPA A/c.,		
		□ For DRT Recovery purpose, □ Capital Gains Wealth Tax purpose		
10	Type of Loan	Partition purpose, General Value Assessment		
_		□ Housing Loan, □ Housing Take Over Loan, □ Home Improvement		
	1 Jan.	Loan, Loan against Property, Construction Loan, Educational		
	Busineps Loan.	Loan, Car Loan, Project Loan, Term Loan, CC Limit		
11.	Loan Amount	enhancement, 🗆 Cash Credit Limit, 🗆 Industrial Loan, 🗆 NA		

115

		OWNERSHIP DETAILS
1.	Legal Owner Name/s	Refer Pg No-2.
2.	Property Purchaser Name	Refer Pg. No - 7.
3.	Property Address under Valuation	Refer Pg. No. 2.
4.	Present Residence Address of the Owner/ Purchaser	Flat No. 503 // Same Flat.
5.	Property constitution	Free Hold, Lease Hold

		LOCATION D	ETAILS				
1.	Adjoining Properties	East	West	N	lorth	S	South
	(Match it with papers with the help	FL+ND. 502 2	Building	Flat	Va 504, Bldg.	Buil	ding
	of compass or Sun direction and	Flat No. 5072 Approach	Cambourd.	Other	Rido	Comp	so and.
	also confirm it with nearby people)	Approach Road	compound.		J.J.	B-h	lina
2.	Property Facing	East Facing,	North Facing,	U West Fa	icing, 🗆 Sc	outh Fa	cing,
		North-East Facing, South-West Facing, South-East Facing,					
		□ North-West Fac	ing				
3.	Landmark	St. Racka Ca	lloon 19	Flee			
4.	Ward Name/ No.	St. Rocks Ca	sueger in a	- NSAT.			
5.	Zone Name						
6.	Main Road Name & Width	Name	W	lidth	Distance	e from	property
		Eksar Road	1 11 cm	e pach	10	0 -	150m
7.	Approach Road Name & Width	OFF. DNMh		100			-
8.	Location consideration of the	U Within Main city	, D Within Go	od Urban	developed	Area,	Within
	Society						
		developing area, □ Highly posh locality, □ Very Good, □ Good,					
		🗆 Ordinary, 🛛 In	interiors, 🗆 Re	emote area	, 🗆 Backw	ard, 🗆	Average,
		Poor					
9.	-						
1000	Special Location consideration	D Park Facing, D	Pool Facing,	Road I	acing, 🗆	Entran	ce North-
1000	Special Location consideration of the property	□ Park Facing, □ East Facing, □ Su		Road	acing, 🗆	Entran	ce North-
	of the property	East Facing, 🗆 Su	nlight facing				
10.			nlight facing				
	of the property	East Facing, 🗆 Su	nlight facing d, V Urban dev	veloping, [
	of the property	East Facing, Su Urban develope Backward, Inc	nlight facing d,√⊒ Urban dev lustrial, ⊡ Insti	veloping, E tutional] Semi Urb	an, 🗆 I	Rural,
10.	of the property Characteristics of the locality	East Facing,	nlight facing d,√⊒ Urban dev lustrial, ⊡ Insti	veloping, E tutional] Semi Urb	an, 🗆 I	Rural,
10.	of the property Characteristics of the locality	East Facing, Su Urban develope Backward, Inc High End, No	nlight facing d,√2 Urban de lustrial, □ Insti rmal, □ Afford	veloping, E tutional able Group] Semi Urb Housing, [an, □ f	Rural, 6, 🗆 HIG,
10. 11.	of the property Characteristics of the locality Category of Society/ locality	East Facing, Su Urban develope Backward, Inc High End, No MIG, LIG	nlight facing d,	veloping, □ tutional able Group ig, □ Swim] Semi Urb Housing, [ming Pool,	an, 🗆 f	Rural, 6, 🗆 HIG,
10. 11. 12.	of the property Characteristics of the locality Category of Society/ locality Utilities/ Facilities in the locality	East Facing, Su Urban develope Backward, Inc High End, No MIG, LIG Lifts, Garden, Club House, Backup	nlight facing d,	veloping, tutional able Group g, Swim Kids pla	Berni Urb Housing, I ming Pool, ay zone, I	an, 🗆 F 🗆 EWS 🗆 Gyr 🗆 1009	Rural, 6,
10. 11.	of the property Characteristics of the locality Category of Society/ locality	East Facing, Su Urban develope Backward, Inc High End, No MIG, LIG Lifts, Garden, Club House,	nlight facing d,	veloping, □ tutional able Group ig, □ Swim] Semi Urb Housing, [ming Pool,	an, 🗆 F 🗆 EWS 🗆 Gyr 🗆 1009	Rural, 6, 🗆 HIG, n,
10. 11. 12. 13.	of the property Characteristics of the locality Category of Society/ locality Utilities/ Facilities in the locality Proximity to civic amenities	East Facing, Su East Facing, Su East Facing, Su East Facing, Substituting East Facing, Substit,	nlight facing d,	veloping, tutional able Group ig, G Swim Kids pla Metro	Semi Urb Housing, I ming Pool, ay zone, I Railway St	an, 🗆 F EWS Gyr 1009	Rural, 6, □ HIG, n, % Power Airport
10. 11. 12.	of the property Characteristics of the locality Category of Society/ locality Utilities/ Facilities in the locality	East Facing, Su Urban develope Backward, Inc High End, No MIG, LIG Lifts, Garden, Club House, Backup	nlight facing d,	veloping, tutional able Group ig, G Swim Kids pla Metro	Semi Urb Housing, I ming Pool, ay zone, I Railway St	an, 🗆 F EWS Gyr 1009	Rural, 6, □ HIG, n, % Power Airport

Page 7 of 15

15.	Jurisdiction limits	🗆 Nagar Nigam, 🗆 Nagar Panchayat, 🗆 Gram Panchayat, 🗆 Nagi
	BMC.	Palika Parishad, Area not within any municipal limits
16.	Jurisdiction Development	□ DDA, □ GDA, □ NOIDA, □ GNIDA, □ YEIDA, □ HUDA, □KMDA,
	Authority Name	□ MDDA, □ Any other Development Authority:
	BMC.	□ Area not within any development authority limits
17.	Municipal Corporation Name	□ NDMC, □ SDMC, □ EDMC, □ Ghaziabad Municipal Corporation,
		Gurgaon Municipal Corporation, Gravidabad Municipal Corporation,
-	BMC.	□ Kolkata Municipal Corporation, □ Dehradun Municipal Corporation,
		□ Area not within any municipal limits, □ Any other Municipal
		Corporation/ Municipality:

		PHYSICAL DETAIL	<u>_S</u>			
1.	Land Area	As per Title deed	As per Map	As per site survey		
2.	Any conversion to the land use	Not known	to us.			
3.	Land Type		Solid, Rocky, Marsh Land, Reclaimed Land, Water logged, Land locked			
4.	Shape of the Land	□ Square, □ Rectange □ Irregular, □ NA	□ Square, □ Rectangular, □ Trapezium, □ Triangular, □ Trapezoid, □ Irregular, □ NA			
5.	Level of Land	On road level, 🗆 Be	low road level, Above	e road level, 🗆 NA		
6.	Frontage to depth ratio	Normal frontage, 🗆	Less frontage, 🗆 Large	frontage, 🗆 NA		
7.	Are Boundaries matched	□ Yes, □ No, □ No relevant papers available to match the boundaries, □ Boundaries not mentioned in available documents				
8.	Is Independent access available to the property	Clear independent access is available, Access available in sharing of other adjoining property, No clear access is available, Access is closed due to dispute				
9.	Is property clearly demarcated with permanent boundaries?	Yes, 🗆 No, 🗆 Only	with Temporary bounda	ries		
10.	Is the property merged or colluded with any other property	Not Mearged .				
11.	Property possessed by at the time of survey	✓ Owner, □ Vacant, □ Lessee, □ Under Construction, □ Couldn't be Surveyed, □ Property was locked, □ Bank sealed, □ Court sealed				
12.	Current activity carried out in the property		ose, □ Commercial □ Vacant, □ Locked, [purpose, □ Godown, □ Any other use:		


	BUILDING/ CONSTRUCTION/ UTLITY DETAILS		
1.	Construction Status	Built-up property in use, Under construction, No construction	

lag					
y2.	Covered Built-up Area	Covered Area, Floor Area, Super Area, Carpet Area			
		As per Title deed As per Map As per site survey			
	(Tick one on the basis of which valuation is to be calculated) (or pet-	- 55-29 sq. mtr Maintenance Bill Corpet-568.56 515 sq. Fl. Corpet-568.56			
3.	Total Number of Floors in the Building	Stilt +7 Floors.			
4.	Floor on which property is situated	5th Floor.			
5.	Type of Unit/ Number of Rooms/ Cabins/ Cubicles	2BHK OF 1Master Bedroom, Bedroom, Kitchen, Hall, Toilet			
6.	Building Type	RCC Framed Structure, Load bearing Pillar Beam col			
		□ Ordinary brick wall structure, □ Iron trusses & Pillars, □ Scrap			
		abandoned structure			
7.	Roof	a. Make: RBC, RCC, GI Shed, Tin Shed, Stone Patla			
		b. Height: 8.505			
		c. Finish: Simple plaster, D POP Punning, POP False			
		Ceiling, Coved roof, No plaster			
8.	Flooring	Vitrified tiles, 🗆 Ceramic Tiles, 🖓 Simple marble, 🗆 Marble			
		chips, 🗆 Mosaic, 🗆 Granite, 🗆 Italian Marble, 🗆 Kota stone,			
		□ Wooden, □ PCC, □ Imported Marble, □ Pavers, □ Chequered			
	7	Tiles, Brick Tiles, No Flooring, Under construction, Any			
		other type:			
9.	Appearance/ Condition of the	Internal - 🛛 Excellent, 🗆 Very Good, 🗆 Good, 🗆 Ordinary,			
	Building	□ Average, □ Poor □ Under construction, □ No Survey			
		External - C Excellent, V Very Good, C Good, C Ordinary,			
		□ Average, □ Poor □ Under construction			
10.	Maintenance of the Building	Very Good, Average, Poor, Under construction			
11.	Interior decoration	Excellent, Very Good, Good, Simple, Ordinary			
		□ Average, □ Below average, □ Under construction, □ No Survey			
12.	Interior Finishing	 Simple plastered walls, Brick walls without plaster, Designer textured walls, POP punning, Coved roof, 			
		□ Under construction, □ No Survey			
13.	Exterior Finishing	Simple plastered walls, D Brick walls without plaster			
		 Architecturally designed or elevated, Brick tile Cladding Structural glazing, Aluminum composite panel cladding, 			
		□ Glass façade, □ Domb, □ Porch, □ Under construction			
14.	Kitchen	□ Simple with no cupboard, ☑ Ordinary with cupboard, □ Norma			
14.	Kitchen	Modular with chimney, High end Modular with chimney, Under			
		construction, \Box No Survey			
15.	Class of Electrical fittings	External, Internal			
		Ordinary fixtures & fittings, Fancy lights, Chandeliers			
		Concealed lightning, Under construction, No Survey			
16.	Class of Sanitary/ Plumbing &	External, E Internal			
	water supply fittings	□ Excellent, Very Good, □ Good, □ Simple, □ Average,			
		□ Below average, □ Under construction, □ No Survey			
17.	Water arrangements	□ Jet pump, □ Submersible, □ Jal board supply			
18.	Fixed Wooden Work	Excellent, Very Good, Good, Simple, Ordinary			
		□ Average, □ Below Average, □ No wooden work, □ No survey			
19.	Age of Building/ Recent				
	Improvements done	8-9 Years.			
20.	Maintenance of the Building	Very Good, Average, Poor			
- 10 - 10 - 10 - 10 - 10 - 10 - 10 - 10		Page 9 of 15			

				ing inquies [] See	Dade issues	
21.	Any defects in the building	🗆 Maintenance issues, 🗆	Finish	ing issues, C out	page looses,	
		□ Water supply issues, □ Electricity issues, □ Structural issues,				
		Visible cracks in the buil	ilding			
22.	Any violation done in the property	□ Construction done wit	ithout	Map, 🗆 Construc	tion not as per	
		approved Map, Extra co	overed	without sanctioned	d Map, 🗌 Joined	
		adjacent property, Encro	oacheo	d adjacent area ille	gally	
23.	Boundary Wall (Only for individual	Yes, D No, D Common			blex	
20.	property)	Running Mtr. Height		Width	Finish	
24.	Lift/ elevators	Passenger/ Commerce	rcial			
		Make:		Capacity:		
25.	Power backup	□ Inverter, □ DG Set				
	No.	Make:		Capacity:		
26.	Garden/ Landscaping	Ves, D No, Beautiful,	l, 🗆 Or	dinary		
27.	Parking facilities	Available within the prop	perty	On Ground, [In Basement,	
	Parking Parking.			On stilt		
		Not available within	the	🗆 On road, 🗆	Acute parking	
		property		problem		
28.	Special Comments/ Observations, if any					

	MARKETABI	LITY/ SELABILITY/ UTLITY DETAILS
1.	Any issues in marketability of the property?	□ Yes, √2 No
		Reason in case of No: Location, Surrounding, Legal
		aspects, Demand, Shape, Any Other:
2.	How is Demand & Supply condition	Demand Uvery Good, Good, Average, Low, Poor
	in the Market of such properties?	Supply Very Good, Good, Average, Low, Poor
3.	Is property easily sellable & marketable?	VZ Yes, 🗆 No
		Comments:
4.	How is the current utility of the property?	Y Excellent, □ Very Good, □ Good, □ Average, □ Low, □ Poor
5.	At what True rate Owner bought this Property?	Year of purchase 2014
		Purchase Price
6.	Present expected Sale Value of the overall property?	21K-24K/sq. Rt - Carpet

DRAW SITE KEY PLAN & SKETCH PLAN



No	Particulars	Subject Property	Transaction already I Comparable 1	Comparable 2	Comparable 3
•	Name (source of information)	NA	Rising Property	Dev.	Vaibhar.
2.	Contact No.	NA	9619192021.	95948 88888	9773200832
3.	Type of source of information (Seller/ Property dealer/ nearby people)	NA	Dealer -	Dealer.	Deales
1.	Rates/ Price informed (in Rs. with unit)	NA	20,000 - 26,000/ sq.ft on Carpet	21K-23K/sq.Ft	21K-ak/ sqifte-lar
5.	Rates Type (Sale/ Buy)	NA	Sale	Sale	Sale.
5.	Shape of the Property (Square, Rectangular, Irregular)		Square	Rectangle	Rectangle
7.	Area/ Size of the Property		ZBHK	2BHK	2BIAK.
8.	Legal Status (<i>clear</i> , <i>negative</i> , <i>weak</i>)/ No. of owners		Clear	Clean	Ctear.
9.	Location/ surrounding/ neighborhood comparison with the subject property (Similar, Lower, Better, Highly Better than the subject Property)	Base Case	Same	Same	Same.
10.	Distance from the subject Property	0	Same	0	0
11.	Other factors (Corner, 2 side open, North-East facing, Park facing, Legal/ Financial encumbrance, etc.)		Same	Same	Same
12.	Approach road width		Same	Same	Same
13.	Level of Land (Below/ On/ Above road level)		Same	Same	Same.
14.	Frontage to depth ratio (Normal, Less, Large)		Normal	Normal	Normal
15.	Present Use		Vacant	Vacant	Vacant
16.	Any other details/ Discussion held	NA	Rotesare Zok-Z6k/saft on Carpetin this area'	Rotes are	Rates are 21k - 24k/ Sq. Fton Carpet.
17.	Present expected Sale Value of the overall property?	21-25	k/sq.ft on C	arpet	

UNDERTAKING BY THE CUSTOMER

I confirm that I have made the inspection of the subject property to the surveyor of R.K Associates, which is correct property in question for which the documents have been provided/ submitted by me. I further confirm that I am aware of all the information related to the subject property and I have provided all its information to the surveyor true to the best of my knowledge. I understand that any false or manipulative information provided by me will be considered as cheating with the professional organization since it will lead to incorrect valuation report and I'd be solely responsible for this unlawful act and will bear the charges for the changes/ modifications which have to undergo due to the false information. I also undertake that I have not given any cash or in kind to any member of R.K Associates to influence the Value of the Property or favor any individual or organization and the same is not accepted or asked by the member of R.K Associates. Any such act will lead to cancellation of the material prepared by R.K Associates with forfeiting of the fees and i'll be completely responsible for its repercussions and legal actions taken for it.

IMPORTANT: We have not authorized any of our person/ Surveyor to take Cash or kind from the customers in any situation. In case Surveyor or any member of R.K Associates asks for any money or kind from you then kindly please inform on number +91-9958632707, 0120-4110117. Our Valuation process is very stringent and have multiple check points to ensure correct & error free reports to keep the lending agency risk free. In case Surveyor claims that he would be able to arbitrary effect the Valuation figures unfairly or as per your requirement & need, then he is making a false claim to you and we request you to complaint such act immediately on the number provided above.

Name	D S O I
Relationship with owner	Pawan S. Salue
Signature	Bawan
Mobile No.	9930351270
Date	201322

UNDERTAKING BY THE SURVEYOR

I confirm that I have carried out the Survey of the property properly as per the fair professional best practices and Valuation & Survey policy guidelines issued by R.K Associates. I have not taken any cash or kind from the customer nor have I come into any kind of influence of the customer / bank for arbitrary providing the Property Valuation as per one's need. I further state that I have not given any assurances to the customer nor given any wrong or false information or statement. In case at any point of time it is found that I have done any kind of fraudulent activity in this case and misled the company then I understand its legal consequences and appropriate penal action which company can take against me. Also in regard to it any monetary or reputation loss will be recovered from me by the company.

For File No.	P1-724-609-994
Surveyor Name	Shreyesh Shetty.
Signature	Elis
Date	2018/2023.



Enclosure: 6

SURVEY SUMMARY SHEET (TO BE ENCLOSED WITH VALUATION REPORT)

(Version 1.0) | Date of implementation: 10.04.2017

Every Valuation report at R.K Associates is prepared based on the thorough survey of the property carried out by our Engineering Surveyor. This Survey Summary Sheet is for the information of Banker/ concerned interested organization. Detailed Survey Form can also be made available to the interested organization in case it is required to cross check what information our surveyor has given in site inspection report based on which Valuation report is prepared.

1.	File No.	PL724-609-9	194		
2.	Name of the Surveyor	Showing Shitte			
3.	Borrower Name	Mr. Satyendra Sukhram Sahu R Mrs. Pawan Kaluram Vish Mr. Satyendra Sukhram Sahu R Mrs. Pawan Kaluram Vishnoi. Flat No. 503, 5th Floor A - Wing, Kamla Enclave (o-of Hsg. So Read, NEKsar, Borival West, Mumbai - 400103			
4.	Name of the Owner	My Styledy Site of She P. M. P. V. I. Wan Nichan Vish			
5.	Property Address which has to be valued Ltd., of F. DN Mhatia	Flat No. 503, 5th Floor	A - Wing, Kamla	Enclave (o-of Hog.	
6.	Property shown & identified by at	Owner, C Representative, C	No one was available	Property is locked surve	
	spot	could not be done from inside	into one was available,	La rioperty is locked, surve	
		Name		Contact No.	
		Mrs. Pawan S- Sal	ne 99303		
7.	How Property is Identified by the	□ From schedule of the prop	erties mentioned in the	deed V From name nlat	
	Surveyor	displayed on the property,			
		Enquired from nearby people,		property could not be done	
0	A - B - I - I - I - I	Survey was not done			
8.	Are Boundaries matched	□ Yes, □ No, □ No rele		to match the boundaries	
		Boundaries not mentioned in available documents			
9.	Survey Type	Full survey (inside-out with measurements & photographs)			
		□ Half Survey (Measurements from outside & photographs)			
		Only photographs taken (No measurements)			
10.	Reason for Half survey or only	Property was locked, Po:	ssessee didn't allow to in	nspect the property, D NP	
	photographs taken N.A.	property so couldn't be surveyed completely			
11.	Type of Property	Flat in Multistoried Apartme	ent, 🗆 Residential House	e, 🗆 Low Rise Apartment, 🗆	
		Residential Builder Floor, 🗆 Co	ommercial Land & Buildin	ng, 🗆 Commercial Office, 🗆	
		Commercial Shop, Commer	cial Floor, Shopping I	Mall, 🗆 Hotel, 🗆 Industrial	
		□ Institutional, □ School Build			
	C . 2 RII				
12.	Property Measurement				
		Self-measured, 🗆 Sample n	the second s		
13,	Reason for no measurement	It's a flat in multi storey buil	-		
		□ Property was locked, □ O			
		didn't enter the property, [
	N A	measure the area within limite	d time 🗀 Any other Rea	son:	
14.	Land Area of the Property	As per Title deed	As per Map	As per site survey	
	,				
15.	Covered Built-up Area	As per Title deed	As per Map	As per site survey	
	Carpet	S5-29-59, mt. S V Owner, D Vacant, D Lesse		568.5654.Ft	
16.	Property possessed by at the time of	V Owner [] Vacant [] Lesse	e. 🗌 Under Constructio	on. Couldn't be Surveyed	
10.	survey	Property was locked, Ban	k sealed.	1	

	property during survey	7
18.	Is Independent access available to the property	Clear independent access is available, Access available in sharing of other adjoining property, No clear access is available, Access is closed due to dispute
19.	Is property clearly demarcated with permanent boundaries?	Yes, I No, Only with Temporary boundaries
20.	Is the property merged or colluded with any other property	Not Merged.
21.	Local Information References on property rates	Please refer attached sheet named 'Property rate Information Details.'

Endorsement:

Signature of the Person who was present from the owner side to identify the property:

Undertaking: I have shown the correct property and provided the correct information about the property to the surveyor of R.K Associates to the best of my knowledge for which Valuation has to be prepared. In case I have shown wrong property or misled the valuer company in any way then I'll be solely responsible for this unlawful act.

- Name of the Person: Pawar S. Salue Relation: wife Signature: Dawar a.
- b.
- C.
- d. Date:

In case not signed then mention the reason for it: 🗌 No one was available, 🗌 Property is locked, 🗋 Owner/ representative refused to sign it,
Any other reason:

2. Surveyor Signature who did site inspection:

Undertaking: I have inspected the property and cross verified the property details at site to the extent of a. Matching boundaries of the property, b. Sample measurement of its area, c. Physical condition, d. Property rates as per local information with what is mentioned in the property documents provided to me by the Bank/ interested organization. I have not come under influence of anyone during site inspection and have only recorded the true and factual details in the survey form which I come across during the site survey. I understand that giving any manipulative information in the survey form will lead to incorrect Valuation report which is an unlawful act and i'll be solely responsible for doing it.

Name of the Surveyor: Shreyash Shetty. Signature: Date: 20/3/2023. a.

2013/23

b.

c.

2