File No.	RKA/DNCR/:/
Date of Receiving	



CASE COLLECTION FORMAT (INDUSTRIAL PLANT SURVEY FORM)

(Version 2.1) | Date of implementation: 9.02.2011 | Date of Revision: 04.01.2018, 30.01.2020

Items	Assigned To	Assigned to Date	To be completed by date	Submitted On date	Grade	HOD Engg. Signature
File Received By	Sachin	NA	NA			NA
Survey A	n' than / E	thaneal /	Aart			
Preparation						

A - Very Good, B - Satisfactory, C - Average, D - Poor, E - Extremely Poor

File Returned to HOD	□ Proper documents not received, □ Survey not done properly, □
Engg. unprepared due to	Survey Form not properly filled. Market survey for rates is not
reason	properly done, I Identification is not clearly done, Measurement is
	not properly done, Photographs not clearly taken, Selfie/ Owner
	or owner representative photo not taken, U Owner/ owner
	representative signature not taken, Google Map not taken,
*	Survey summary sheet not filled

In case File is returned by the preparer - HOD Engg. comment & Signature	☐ Minor defects in the survey hence approved for preparation with warning to Surveyor. Report preparer to collect the missing information on his own.
	□ Major defects in the survey. Survey has to be done again.

		GENERAL D	ETAILS				
1.	Proposal or Ref. No.						
2.	Type of Service	Valuation Rep	Valuation Report				
3.	Type of customer	Bank					
4.	Bank/ FI/ Organization Name & Address	SBI	TFB, NO	Pumb			
5.	Case Allotment Officer/ Fees paying party Details	Name Ko Harilo	Name Contact Nun A-Hanilorisha 8452941		a. Loroi Koishna @		561.co
6.	Case Type	Case for Fr		•		ng account/ r	
1.	Fees Details	Amount of Fees	Advance An any		Paymer	nt will be paid by	
	als	FOK TAS-	P -		🗆 Bank	Customer	
8.	Billing Details	Billed To Party Na	ame		GSTIN	1	
		-			-		

Page 1 of 17

	Name of the Industry/	CASE DETAILS
	Account	MIS shalinor Paints Up.
	Type of Property	Small Manufacturing Unit, Medium Scale Industrial Unit Large Scale
		Industrial Plant, Very Large Scale Industrial Plant
	Owner/ Applicant Details	Name Contact Number Email Id
h.	Account Name	M/s shalenear Paints 4d.
5.	Plant Address	Gat No. → 121 B, 126, 127, 132, 133 B, 134 B, 141
	Miceubai	Agsa Road, Vill> Goude Duemala, Palerka - Igo
6.	Who will coordinate on site	O Name Contact Number O
	for the site survey Jago	anoth B. Biradar -> 9823249265 A
	0	>
7.	Preferred time of survey	Date Time -
1.	Fieldred and of Survey	Later 12folo1
		11/0/23
8.	Documents Received (Any	
	one ownership document and approved site plan/ map is must	Relinquishment Deed, Transfer Deed, Conveyance Deed, Mortgage
		Allotment Letter, □ Possession Letter, □ Agreement to Sell, □ Mortgage Deed, □ Indenture of Mortgage
		2. Map: Cizra Map, Sanctioned Map, Site Plan
		3. Project Approval Documents: Factory Registration, Memorandum of
		Understanding with the State Govt., □ Industrial Entrepreneurs Memorandum, □ Environment Clearance, □ Fire NOC
		4. Any Other document: TIR Report, Old Valuation Report, Plant &
		Machinery Inventory Sheet, Var Fixed Asset Register, D Building Area
		Statement, CLU Document, Detailed Project Report, Invoices of
		the Major Equipment's, □ Daily Performance Report, □ TEV Report, □ LIE Report, □ Production data of last one week, □ Plant maintenance log.
		Copy of last paid Electricity Bill, Copy of municipal tax receipt
		5. No documents provided: De provided (ayout.
		5 No documents provided pploned layout.
9	. Special Instructions if any	
9		
1	0 I agree to pay the amount	mentioned above for the preparation of Valuation Report. I agree that I'll not put pressure
10	on Valuer firm to distort an	y facts and would not try to influence any member or official of the firm in the ill spirit o
	vested interest and to bene	fit any individual or organization by any means illegitimately.
	Quatamore Cignostures	N/
	Customer Signature:	nerer
		1
NV	12 MORKL	/year (90-95%)
A	12,000.0	
		Nasheri, Pincodo > 422403 (19.4.) Page 2 of 17
ro	v Deit ->	Nashell, Pincodo - 42210,
5	e busi -	Page 2 of 17

IMPORTANT INSTRUCTIONS

*FILE PREPARER TO START PREPARING THE FILES ONLY AFTER ENSURING THE STATUS OF ALL THE BELOW POINTS IS COMPLETED. FOR ANY EXCEPTION PLEASE BRING IT INTO NOTICE OF SENIOR GENERAL MANAGER (OPERATIONS), OTHERWISE PENAL ACTION WILL BE TAKEN AGAINST THE FILE PREPARER.

1.

1.	Please do not apport the page if you do not have prepar documents					
	Please do not accept the case if you do not have proper documents.					
2.	Understand the nature of Industry before moving for survey					
3.	Study the Plant Inventory sheet or FAR properly before moving for survey					
4.	Firstly please take & study the current applicable ownership documents of the property which needs to get surveyed.					
5.	Mark the Owner/ Area/ Boundaries mentioned in the ownership documents with bold florescent marker pen before moving for the survey. During site survey if any difference is found in the above fields from the ownership documents then please contact the owner immediately to know the reason for the difference.					
6.	Identify the Property clearly by matching the boundaries and area mentioned in the property papers.					
7.	Check whether Building Measurement Area is given in the Map or if they have any Building Area sheet or if self-measurement has to be carried out before moving for survey.					
8.	Take Google Map location.					
9.	Take one photograph of the property along with abutting road.					
10	Take nearby photographs of the Property.					
11	. Check Jurisdiction Municipal Limits & Ward Name.					
12	. Fill the details in the Survey form and tick the appropriate option clearly.					
13	. In case customer is found providing misleading information to you or trying to influence you by money or cash then immediately report to the Management & Bank.					

S.No.	CHECKLIST	STATUS
1.	IS PURPOSE OF THE ASSIGNMENT UNDERSTOOD CLEARLY	GIAIOU
2.	IS WORK ORDER/ EMAIL/ CESA FORM FORMALITY COMPLETED	e e
3.	FOR PRIVATE CASE OR FOR FRESH CASE 50% ADVANCE IS RECEIVED	9
4.	IS DOCUMENT CHECKLIST PROVIDED TO THE CUSTOMER	T V

S.NO.	CHECKLIST	STATUS
1.	Check nearby prominent landmark	UNIOS
2.	DO CLEAR IDENTIFICATION OF THE PROPERTY	
3.	Match the boundaries of the property and its directions with the help of compass or sun direction	0
4.	Do sample measurement	10
5.	CHECK IF ANY BUILDING VIOLATIONS DONE	
6.	Click multiple proper photographs of the property from inside-out	
7.	Take selfie with the available representative	
8.	Send Google Map location at maps@rkassociates.org	
9.	Check municipal jurisdiction	
10.	Check Main road name & width and its distance from the subject property	J

Page 3 of 17

11.	Check Lane width on which property is located	ST -
12.	Check any defects or negativity in the property	
13.	CONFIRM PROPERTY RATES LOCALLY	
14.	CHECK NEARBY DEVELOPMENT	

SPECIAL INSTRUCTIONS:

- 1. During Survey please follow the blocks mentioned in the plant layout and clearly mention the details of each block. Use separate sheet wherever space is not adequate in the form.
- 2. During survey please keep P&M inventory sheet in hand and cross check the machines from the list.
- 3. Mention type, height & area of shed of each block clearly.
- 4. Take photographs of the machines including its machine plate.
- 5. In case machine is not in running condition then test the condition of the machine by moving its lever, pulley and check oil condition.

	SURVEY GRADING MATRIX
GRADE	PARAMETERS/ CRITERIA
A	In case all the points below are done properly, timely with full care and diligence:
	 Survey started with proper work order and knowing the source of payment. Survey done with proper documents. Done complete homework and studied the documents properly with highlighting the main points before moving for the survey. Chosen correct survey form as per the property type. All fields of Survey form are properly filled. All site special observations and negative and positive factors are clearly mentioned. Self & client signatures taken on survey form. Property rates information properly taken, mentioned and verified. Site rough sketch plan made. Proper photographs taken. Selfie with property taken.
В	12. Selfie and owner photograph with property taken. In case of 3 minor mistakes in any of the above points except Point 1, 2, 3, 4, 6, 8, 10, 11, 12 but all the points are covered.
С	In case of more than 3 minor mistakes and any 1 major mistake in any of the above points are any 1
D	
E	In case of 1 major mistake or missing of any 1 point out of 1, 2, 3, 4, 6, 6, 10, 11, 12. In case of more than 1 major mistakes or missing of more than 1 point out of 1, 2, 3, 4, 6, 8, 10, 11, 12.

Note (Survey Grading Matrix):

- 1. For special assignments like LIE, Stock Valuation, etc. where till date survey format is not specified or released, in such cases point wise site observation report has to be submitted by the Surveyor duly signing it properly. Without signed Site Observation report, Point 4 will be considered as not done and will fall under Category E.
- 2. Similar Grading Matrix is issued for Case Collection & Report Preparation as well.

Note (Overall Grading Matrix):

1. In case client reports any careless mistake in the report for which revision has to be done in the report then in that case Grading Matrix may be revised and Grade E will be awarded.

INDUSTRIAL PLANT SURVEY FORM (FOR INDUSTRIAL PROPERTIES ONLY) (Version, 2.0) | Date of implementation: 9.02.2011 | Date of Revision: 04.01.2018, 15.06.2019 いたいたいたいたいたいでは、1995年に Q037-192-27

File No. RKAUDNGR/......

Date: F 50/8 Time:

-	10.	9	φ	7.	5	'n	4	ယ္	2	-1
I nan Amnunt	. Type of Loan	Purpose of Valuation	Reason for no measurement	Property Measurement	Type of Industry	How Property is Identified	Reason for Half survey or only photographs taken	Survey Type	Property shown by	Name of the Surveyor
1	Project Loan, Term Loan, Credit Limit, Industrial Loan, Business Loan, NA	 □ Value assessment of the asset for creating collateral mortgage □ Periodic Re-Valuation for Bank, □ Distress sale for NPA A/c □ For DRT Recovery purpose, □ For Insolvency purpose, □ Capital Gains Wealth Tax purpose, □ Partition purpose, □ General Value Assessment, □ For company merger & amalgamation purpose, □ For any other purpose: 	NPA property was locked sectors, Very Large Property, Very Large Property, practically not possible to measure the entire area Any other Reason:	Self-measured Sample Ineasurement on Sesses didn't allow it,	Scale Industrial Plant, Uyery Large Scale Industrial Plant Scale Industrial Plant, Uyery Large Scale Industrial Plant	□ From schedule of the properties mentioped in the deed, ↓From name plate displayed on the property ∠r (dentified by the owner/owner representative, □ Enquired from nearby people, □ Identification of the property could not be done, □ Survey was not done property could not be done, □ Survey was not done	 Property was locked. Property, NA property so owner was hostile and survey couldn't be property, Under construction property, Very Large irregular carried out, Under construction property, Very Large irregular Property, practically not possible to measure the entire area. Any other reason: 	□ Full survey (inside-out with approximate measurements photographs), □ Full survey (inside-out with approximate sample random measurements & photographs), □ Half Survey (Approximate sample sample random measurements from outside & photographs), □ Only photographs taken (No measurements)	□ Owner/ Director, U Company Representative, □ No one wa available, □ Property is locked, survey could not be done from inside Name Contact No. Name Contact No.	Anistran / Dhawal / think
	□ Term Loan, □ CC Limit ennancement, □ ⊂astri Idustrial Loan, □ Business Loan, □ NA	ating collateral mortgage tress sale for NPA A/c., solvency purpose,	rty, □ Very Large Property, e entire area □ Any other	r/ possessee didn't allow it,	e Industrial Plant	titioped in the deed, € From dentified by the owner/ owner oeople, □ Identification of the is not done so industrial Unit. € Targe	nostile and survey couldn't be erty, Very Large irregular ure the entire area.	(inside-out with approximate measurements of Full survey (inside-out with approximate sample nents & photographs), □ Half Survey (Approximate easurements from outside & photographs), □ Only (No measurements)	oresentative, □ No one was could not be done from inside Contact No. のんっったいのである	tint

Page 5 of 17

i

1					Prove of Sectors
		OWNERSHIP DET	AILS		
1.	Name of the Industry	9	same as pe	9.2	
2.	Legal Owner Name/s		4	J	
3.	Property Purchaser Name		U		
4.	Plant Address under Valuation		Ч		
4. 5.	Present Residence Address of				
э.	the Owner/ Director		*		
6.	Property constitution	Free Hold, Lease	e Hold		
		East of East of Kord NH	West 8	North	South
1.	Adjoining Properties	East	al KS	0 01	1000
	(Match it with papers with the help	when I It	sou posed jus	Vege	asudenas
	of compass or Sun direction and	X 1000 F	ou los Jos	J	N.
	also confirm it with nearby people)	East Facing, D No	rth Facing Wes	t Facing,	South Facing,
2.	Property Facing	North-East Facing,	South-West Facir	ng, 🗆 Sout	h-East Facing, 🗆
		North-West Facing			
		Near	Cancernet	e Inde	ustry.
3.		Neces	Samemil		J
4			·		
5		Name	Width	Distan	ce from property
6	Main Road Name & Width	NH-3	120 At .		Adjoent
	Approach Road Name & Width		le as mai	in Rea	d'.
7		Ves, I No			
8	available?				
		Bituminous, 🗆 Me	talled, 🗆 Cement	concrete, [Concrete pave
9.		block. D Brick khad	lanja, 🗆 Mud su	rfacing, 🗆	Broken pothole
		metalled road, No	proper approach ro	oad availab	le, 🗆 Very narrov
		approach road toward			
). Location characteristics	Within well-develop	oed notified Indust	rial area, 🗆	Within averagel
10	J. LOCATION CHARACTERISTICS	maintained Industrial	area, 🗆 Within u	in-notified	Industrial area, [
		Within Main city, U	Within city suburbs	s, 🗆 Withir	n urban develope
		Area, Within urban			
1		area, Within urban			
		Within Institutional a			
		Within monoral c			

infrastructure available. Within rural village area,
In interiors,

🗆 Urban developed, 🗆 Urban developing, 🗆 Semi Urban, 🕞 Rural, 🗆

Within Backward area,

Within Remote area

Backward, 🗆 Industrial, 🗆 Institutional

Classification of the Locality

11.

1								
2. 1	Location consideration	□ Corner Plot, □ 2 side open, □ 3 side open, □ On >30' wide road						
		□ Near to Metro station, □ Near to Market, □ Near to Highway, □						
		Entrance North-East Facing, Ordinary location within locality,						
		Good Location within the locality, I Normal Location within the locality,						
		□ Average Location within locality, □ Poor location within the locality,						
		□ Property towards end of the locality, □ Any other						
12	In Digest next of notified							
13.	Is Plant part of notified Industrial Area? If yes then	□ Yes, 12 No						
	name of Industrial area/ estate							
	& governing authority managing it.							
14.	Proximity to civic amenities	School Hospital Market Metro Railway Station Airport						
	c	22Km 3Km Oska - 2OKm BOKe (Igalpuri)						
15.	Any new development in	- (Igapuri)						
	surrounding area	🗆 Nagar Nigam, 🗆 Nagar Panchayat, 🕞 Gram Panchayat, 🗆 Nagar						
16.	Jurisdiction limits	Palika Parishad, Area not within any municipal limits						
17.	Jurisdiction Development	Name: Goude Deeneda Groen panchaya						
	Authority Name							
	4	Area not within any development authority limits						
18.	Municipality/ Municipal Corporation Name	□ Area not within any development authority limits Name: Nasher Metropolitan fegenar De Authouty						
		Area not within any municipal limits						
19.	Surrounding land uses and adjoining/ nearby establishment details	Mixed (Residential of Ind.)						
20.	Is the location proper for the subject industry?	Xes						
21.	Is it a standalone Industry in this area? is it a belt for the subject nature of Industry?	Yes. Yes.						
22.	In case Industry gets closed then does the land can be used for any other purpose?~	yes.						

		PHYSICAL DETAI	LS	
1.	Land Area	As per Litle deed	As per Map	As per site survey
	As per approved heap	El approved 15.45 Acre.	•	15.2 Acre
	bitsosint.	Area as per mortgage	deed:	Google es
2.	Any conversion to the land use	Non agriculte	ual lan paul	d Receipt
3.	Land Type	Solid, C Rocky, C Ma	arsh Land, 🗆 Reclaimed	Land, Water logged
4.	Shape of the Land	□ Square, □ Rectangu □ Irregular, □ NA	lar, 🗆 Trapezium, 🗆 Ti	iangular, 🗆 Trapezoid,
12.1				

Page 7 of 17

□ On road level, \□ Below road level, □ Above road level, □ NA Level of Land □ Normal frontage, □ Less frontage, □ Large frontage, □ NA Frontage to depth ratio 6. □ Yes, □ No, □ No relevant papers available to match the boundaries, Are Boundaries matched 7. □ Boundaries not mentioned in available documents, □ Very large land parcel forming multiple lands so not possible to match it with papers Clear independent access is available,

Access is available in Is Independent access 8. sharing of other adjoining property, \Box No clear access is available, \Box available to the property Access is closed due to dispute,

Land locked Yes, I No, I Only partially, I Only with Temporary boundaries, Is property clearly demarcated 9. with permanent boundaries? NO Is the property merged or 10. colluded with any other property Mes Is complete property 11. mortgaged with the Bank under valuation or only portion Owner, 🗆 Vacant, 🗆 Lessee, 🗆 Under Construction, 🗆 Couldn't be of it? Property possessed by at the Surveyed,
Property was locked,
Bank sealed,
Court sealed 12. Industrial,
Vacant,
Locked,
Sealed
Any other use: time of survey Current activity carried out in 13. the property

ILE NI Dato

mino

		CONSTRUCTION/UTLITY DETAILS □ Built-up property in use, □ Under construction, □ No construction □ Built-up property in use, □ Under construction, □ No construction □ Built-up property in use, □ Under construction, □ No construction □ Built-up property in use, □ Under construction, □ No construction
	struction Status	As per Title deed As per Map As per site start
Cov	ered Built-up Area	As per the decu
_	RCC	As per Title deed As per Map As per site deed Separate sheet provided
1	Shed	V Dillor Beam column,
1	ilding Type	RCC Framed Structure, Load beauting that on Iron trusses & Pillars,
BU	Inding Type	Ordinary brick wall structure
		□ Scrap abandoned structure □ Internal - □ Excellent, □ Very Good, □ Good, □ Ordinary, □ □ Internal - □ Excellent, □ Very Good, □ No Survey □
-	ppearance/ Condition of the	Internal - Excellent, Very Good, No Survey
	Building	Internal - □ Excellent, □ Very Good, □ Average, □ Poor □ Under construction, □ No Survey External - □ Excellent, □ Very Good, □ Good, □ Ordinary, External - □ Excellent, □ Very Good, □ Good, □ Ordinary,
	ta mbantanya ata 🖬 k	
		Average, Poor Under construction
j.	Maintenance of the Building	Very Good, L Average, L 1
	Age of Building/ Recent	
6.	Improvements done	Alen plant 1991/1982 DE Good,
-	Maintenance of the Building	Very (1000, L'Average)
7.	Any defects in the building	□ Very Good, □ Average, □ Poor ♀ 𝔅𝔅𝔅𝔅𝔅𝔅𝔅 □ Naintenance issues, □ Finishing issues, □ Seepage issues, □ □ Maintenance issues, □ Finishing issues, □ Structural issues, □ Water supply issues, □ Electricity issues, □ Structural issues, □
8.	Any delects in the balland	Water supply issues, L License , 10
		Visible cracks in the building
	Any violation done in the	Visible cracks in the building Visible cracks in the building Construction not as per approved Construction done without Map, Construction not as per approved Map, Extra covered without sanctioned Map, Joined adjacent
9.		
	cannot commen	Map, Extra covered without property, Encroached adjacent area illegally
	Canton Cont	
1	0. Boundary Wall (Only for individual property)	Running Mtr. Height Stone Reabble M
	Individual property	No, Common because Width Finish Running Mtr. Height Width Finish N-78 KM 5.5.74 (Av.) 300 WM Stone Rebble M
		Voc No Beautiful, Ordinary
F.	11. Garden/ Landscaping	Sauciable within the property 4
	12. Parking facilities	Acute parking
		□ Not available within the □ On road, □ mail property problem
		property
	13. Special Comments if any	

NOTE: Use table below to mention the individual building/ shed/ blocks details. Mentioned Type of construction (RCC/ Corrugated GI Shed Mounted on Brick Wall or Iron Pillars & Trusses/ Corrugated Colored GI Shed/ Simple GI Shed/ Simple Tin Shed), Height & Area of each block in the table below.

	5	Vi	ē	7.	12	3	·0.	0	₽.	+6	6.	5	بعل	in	P.	- 100	
									low wateria			Macin plant		barred	Cypels Shed	Securation Cabin	N SHEET MAN
	z						x		(14.1)			9.41		C.F	F	e f	Slabs/ Floors
									た 80	212		19.8 H		204.	. 45	・廿二	wise height
									lag	lage		2018		4	U	1991	Year of construct ion
									c	OI shed, Fin	L.	G:IS and, 2 side built wall, y side shall wall, start for m		H IC	at shed, stie	Rec	Type of construction
Page									U	2 G	Christian Christian	u u stal Farm		U	4	Good	Structure condition
Page 10 of 17									「128」を	· # 43 4 9			19:547	1-13-14.	1 2 2 2 2 4 3 2 2 2 2 4 3 2 2 2 4 3 2 2 2 4 3 2 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	1412 11 11 11	Area in Sq.ft

		PLANT DETAILS
S.No.	PARTICULARS	DESCRIPTION
1.	Brief History & Description of the Plant	Setup in the year 1992.
		O for production of water base
		Setup in the year 1992 Of for production of water base Solvent based paints & Alkyd
2.	Nature of Industry	Manuefacturing
3.	Plant Inception Date	1000 14/02/1992
4.	Commercial Operational Date	16/03/1292
5.	No. of Production Lines	36 long nuxture
6.	Date of Inception of each Production Line	1992
7	. Total Block Value of the Machines (As on Year ending 31 st March)	<u></u>
8	3. Industry benchmark cost for setting up these Plants (for eg. Per MW or Per MT)	-
	9. Establishment Type	□ Indigenous, □ EPC Contractor, □ Local Contractor
	10. Plant Type	□ Manual, Semi-Automatic, □ Fully Automatic, □ Conventional, □ Non-Conventional, □ Computerized Controlled
	11. Plant & Machinery Purchase Type	First Hand, Second Hand
-	12. Plant & Machinery Make ~	□ Domestic branded, □ Domestic local made, □ Onsite fabrication □ Imported machines □ Mix (Domestic + Foreign)
	13. Plant Overall Condition	□ Newly Commissioned, □ Excellent, □ Very Good, □ Good, □ Average, □ Poor, □ Completely scrap
1	14. Plant Status	☐ In Operation, ☐ Not Running, ☐ Partially running, ☐ Stopped For Maintenance, ☐ Completely shutdown
1	 If Plant is not operational then period since it is not operational & reason for not being in operation 	

tł	Plant is not operational nen does it require any noney for refurbishing to estart the Plant?	
	Total money spent in last one year on maintenance of machines	36.94 lang (2022-23
	Any major failure, fault, breakdown in last 3 years?	NO
•	Any Technology collaboration of the Plant	
0.	Average Plant Capacity Utilization rate in last one month. Attach Production chart of last one week.	90-95°/0
21.	Name & Function of each block in the plant - Use Separate Sheet If Required	
22.	Main machines used in the Plant - Use Separate Sheet If Required	
23	Estimated net weight of the large machines and of total machines present at site - Use Separate Sheet If Required	
24	 Estimated Economic Life of the Plant/ Machines 	15-20 years (Appson,).
25	Life of Machines	from 1292 /2018.
26	Done (Attach Copy Of Maintenance Log Book If Possible)	
27	Production Capacity In Quantity & Weight For Different Products/ Units	12000 KL/Year
28.	Description Of Products Manufactured	water based, solvent based paints, Ackyd Recens.
29.	Brand Name under which Products are sold in the Market	Shalimar
30.	Raw Material Used & Sources Of Primary Raw Material Used	MPO > Meneral terpentence oil, " aylane, talc Powder, Emulsian.

1		
31.	No. & Type of Furnace	
32.	No./ Type/ Height of Chimney/ Exhaust	1 (30 m height)
33.	Is Plant using obsolete technology or currently used technology in the market? Please comment.	
34.	Whether STP is installed (Mention Type & Capacity)	Yes, 15 Ke/Day (capauly)
35.	Whether ETP is installed (Mention Type & Capacity)	Yes, ISKE/Day (4).
36.	Fire Fighting System	Yes.
37.	No. of Resources Working In the Plant (<i>Managerial,</i> <i>Skilled, Unskilled</i>)	120 (APP.),
38.	Is the adequate skilled labour available in this area for the subject Industry?	Yes.
39.	Power Supply arrangements in the Plant (Sanctioned Load Kw and Units consumed in last 3 months)	MSEDCL IIKVA
40.	Auxiliary power arrangements type in the plant (<i>Type & Capacity</i>)	12-DG Sets, □ Captive Power Plant ruly one, 320 KVA, Kjøles Kar Cenn
41.	HVAC System In the Plant	<
42.	Cooling System In the Plant	
43.	Water Arrangements/ Source of water	□ Jet pump, □ Submersible, □ Jal board supply, □ Reservoir. □ Any other: ↓ ● wetside from weel fame
44.	Major issues noticed in the Industry which can create issues in operations	

-

ATTACHMENTS:

/	PARTICULARS	DESCRIPTION
5.NO. 1.	Inventory Sheet of P&M from Fixed Asset Register (Machine Name/ Machine Type/ Capacity/ Model No./ Machine Make/ Capitalization Date/ Capitalization Value/ Current Book Value/ Machine Status (working/ not working)	
2.	Flow chart / Block diagram from raw material to finished product	
3.	Plant Layout	
4.	Factories registration	
5.	Labor license	
6.	Fire NOC	
7.	Copy of last paid Electricity Bill	
8.	NOC from Pollution Control Board	
9.	Environment Clearance (if applicable)	
10.	Petroleum Product Storage license (if applicable)	
11.	Explosive Product Storage license (if applicable)	
12.	Export/ Import Code (if	
13.	Any other approval or NOC as per industry	
14.	Daily Performance Report	
15.	Production data of last one week	
16.	Plant maintenance log	

LAND RATES INFORMATION DETAILS

Gather information on the basis of the factors like Area location, Property location, Floor level, Block, Position, Frontage, Width of lane/ road in front of the property, Nearby development

Demand & Supply condition in 1. □ Very Good, □ Good, □ Average, □ Low the Market for such properties 2. At what True rate Owner Year of bought this Property purchase **Purchase Price** 3. Minimum Rate in the locality 4. Maximum Rate in the locality Local Information gathered during Site survey (Minimum 2 enquiries are must): 5. Mr. Sonnath Bukne (Dealer) 1. Name: 8275587505 Contact No. RS 1.75 - 2.25 cr/ Acre (Industrial) Sale Purchase Rate Rental Rate Comments He has one plot very near to staliner points. The land is around 7 here and the asking price is 18 cr. Negotiate upto RISO takk to BS 1 cr. from asking Price (K) Shullow properties 7689708425 & 1.502 - 2.502/fere (Industria) 2. Name: Contact No. Sale Purchase Rate **Rental Rate** Comments Lond adjacent to NH-3 is bot allo very have. The densed is high i that area. The land rate could fetch avalue of RS1.5 - 2.500/Her Kedan lealty 3. Name: 9822788881 Contact No. Rs 1.502 - 2.25 or / Aere (Fudustrea) Sale Purchase Rate rate -ents Land adjacent to NH3, share fetch Value heitnen the range of BISON - 225 or Aere **Rental Rate** Comments

Surveyor Name: Anirban/ Phawal/ thus Signature: A Date: 1718/23 & at the bas another pot/ Industry for sale very hear to Page 15 of 17. Shell werpaints. The land is around 11 occe and the Date: 28 or or . (4. 40 land sq. ft.) Total covered area = 10f 059 Sq. ft. Total flee space -> 3.5 Fere

CASE NO.

UNDERTAKING BY THE CUSTOMER

confirm that the property is inspected in front of me and I have provided all the information true related to the property to the best of my knowledge. I understand that any false or manipulative information provided by me will be considered as cheating with the professional organization since it will lead to incorrect valuation report and I'd be solely responsible for this unlawful act and will bear the charges for the changes/ modifications which have to undergo due to the false information. I also undertake that I haven't given any cash or in kind to any member of R.K Associates to influence the Value of the Property or favor any individual or organization and the same is not accepted or asked by the member of R.K Associates. Any such act will lead to cancellation of the material prepared by R.K Associates with forfeiting of the fees and i'll be completely responsible for its repercussions and legal actions taken for it.

IMPORTANT: We have not authorized any of our Surveyor to take Cash or kind from the customers in any situation. In case Surveyor or any member of R.K Associates asks for any money or kind from you then kindly please inform on number +91-9999597597. Our Valuation process is very stringent and have multiple check points to ensure correct & error free reports to keep the lending agency risk free. In case Surveyor claims that he would be able to arbitrary effect the Valuation figures unfairly or as per your requirement & need then he is making a false claim to you and we request you to complaint such act immediately on the number provided above.

Biswaradh Biswarangen Chesh

9890685519

Name: Signature: Mobile No.: Date:

UNDERTAKING BY THE SURVEYOR

I confirm that I have carried out the Survey of the property properly as per the fair professional best practices and Valuation & Survey policy guidelines issued by the organization. I have not taken any cash or kind from the customer or given the customer any wrong or false information or have made any false claims for arbitrary providing the Property Valuation as per one's need or requirement by distorting the facts. In case at any point of time it is found that I have done any kind of fraudulent activity in this case and misled the company then I understand its legal consequences and appropriate penal action which company can take against me. Also in regard to it any monetary or reputation loss will be recovered from me by the company.

Surveyor Name: Signature: Date:

Anirban / Dhawaal) Anit Hol23

CASE NO.

UNDERTAKING BY THE PREPARER

I confirm that this Valuation Report is prepared as per the fair professional best practices and Valuation & Survey policy Guidelines issued by the organization. I also confirm that without any personal interest, partiality or prejudice I have worked on the Valuation work of this case. Rates adopted for the asset is based on various facts, information collected from the site came to my knowledge during the course of the assignment and I have taken all sincere efforts to review & confirm this data/ information from all different angles using my prudent approach without any biasedness or pressure. I have prepared the report based on true facts & information as per best of my knowledge & case facts. I understand that any false information provided by me will lead to the incorrect valuation report and I'd be solely responsible for it and will bear the losses which will be put on the Company in form of monetary or reputation loss by its client or statutory bodies.

I also undertake that I did not come into any influence by the customer, Bank representative (officer or agent), colleagues, coworkers or any other person to arbitrary change the Valuation figures or facts unethically or illegitimately which may put the public money at risk which is in the form of Bank deposits.

In case at any point of time in future I am found guilty of illegitimately distorting the facts in the Valuation or any other professional services which company offers in the market on being influenced by the customer or Bank representative (officer or agent) or for whatsoever may be the reason then I'd solely responsible of any such act and I understand that the Company shall take appropriate legal action against me which may include suspension from the current roles & responsibilities or termination from the employment with immediate effect.

I also undertake that I have not taken any cash, favor or in kind from the customer for favoring any individual or organization by unfair means.

I also undertake that I'll not prepare any report on incomplete Survey form which is not properly filled as per the Company guidelines and in case I am preparing it which is creating an incorrect report then I'd be responsible for its consequences.

Preparer Name: Signature: Date:



SURVEY SUMMARY SHEET (TO BE ENCLOSED WITH VALUATION REPORT)

ASSOCIATES

(Version 1.0) | Date of implementation: 10.04.2017

Every Valuation report at R.K Associates is prepared based on the thorough survey of the property carried out by our Engineering Surveyor. This Survey Summary Sheet is for the information of Banker/ concerned interested organization. Detailed Survey Form can also be made available to the interested organization in case it is required to cross check what information our surveyor has given in site inspection report based on which Valuation report is prepared.

1.	File No.		1				
2.	Name of the Surveyor	A. Jakan M.	awall Anes	_			
3.	Borrower Name	M/c chaling		1 det .			
4.	Name of the Owner	1915 Sharing	or partas	eyes			
5.	Property Address which has to be valued		3 pg-2				
6.	Property shown & identified by at spot	Owner Representative, No could not be done from inside	o one was available, 🗆 Pr	operty is locked, survey			
	5000	Name	Co	ntact No.			
	-	Selannath B. Birad.		49265			
7.	How Property is Identified by the Surveyor	☐ From schedule of the propertie displayed on the property. ☐ Ide Enquired from nearby people, ☐ I	es mentioned in the deen ntified by the owner/ ov dentification of the prop	d, From name plate vner representative, erty could not be done,			
8.	Are Boundaries matched	☐ Yes, ☑ No, ☐ No relevant	t papers available to r	match the boundaries,			
0,	Are boundaries matched	Boundaries not mentioned in available	ailable documents				
0	Survey Type	Full survey (inside-out with mea	surements & photograph	ns)			
9.	Survey Type	Half Survey (Measurements from outside & photographs)					
		Contractorraphs taken (No me	asurements)				
	a su tr	Property was locked, Posses	see didn't allow to inspe	ect the property, 🗆 NPA			
10.	No. 1997 March Lands Lands American Control (Control of Control of	account is couldn't be surveyed completely					
	photographs taken	Contraction Multictoried Apartment, Contraction Residential House, Contraction Residentia House, Contraction Residentia Hous					
11.	1. Type of Property Image: Flat in Multisofted Apartments Image: Commercial Commercial Commercial Land & Building, Image: Commercial Commercial Shop, Image: Commercial Floor, Image: Commercial Floor, Image: Commercial Shop, Image: Commercial Floor, Image: Commercial Flo						
12	Property Measurement	Self-measure Sample mea	surement, 🗆 No measu	rement			
12. 13.	Reason for no measurement	□ It's a flat in multi storey buildin □ Property was locked, □ Owned didn't enter the property, □ \ measure the area within limited to Approved plo	g so measurement not of er/ possessee didn't all /ery Large Property, p ime Any other Reaso	required ow it,			
	Land Area of the Property	As per Title deed	As per Map	As per site survey			
4.	61750 sq. mtr.	15.45 Aeu		15-2 A			
-	Covered Built-up Area	As per Title deed	As per Map	As per site survey			
5.	covered built op		<u> </u>				
5.	Property possessed by at the time of	 ☐ Owner, □ Vacant, □ Lessee, □ Property was locked, □ Bank s 	Under Constructio	n, 🗆 Couldn't be Surve			
	survey						

2	property during survey	
18.	Is Independent access available to the property	□ Clear independent access is available, □ Access available in sharing of othe adjoining property, □ No clear access is available, □ Access is closed due to dispute
19.	Is property clearly demarcated with permanent boundaries?	□ Yes, □ No, □ Only with Temporary boundaries
20.	Is the property merged or colluded with any other property	· · · · · · · · · · · · · · · · · · ·
21.	Local Information References on property rates	Please refer attached sheet named 'Property rate Information Details.'

Endorsement:

1. Signature of the Person who was present from the owner side to identify the property:

Undertaking: I have shown the correct property and provided the correct information about the property to the surveyor of R.K Associates to the best of my knowledge for which Valuation has to be prepared. In case I have shown wrong property or misled the valuer company in any way then I'll be solely responsible for this unlawful act. Biswasanjan Ghosh Employce

- a. Name of the Person:
- b. Relation:
- Signature: C.
- Date: d.

In case not signed then mention the reason for it: \Box No one was available, \Box Property is locked, \Box Owner/ representative refused to sign it,
Any other reason:

1\$ 8722

2. Surveyor Signature who did site inspection:

Undertaking: I have inspected the property and cross verified the property details at site to the extent of a. Matching boundaries of the property, b. Sample measurement of its area, c. Physical condition, d. Property rates as per local information with what is mentioned in the property documents provided to me by the Bank/ interested organization. I have not come under influence of anyone during site inspection and have only recorded the true and factual details in the survey form which I come across during the site survey. I understand that giving any manipulative information in the survey form will lead to incorrect Valuation report which is an unlawful act and i'll be solely responsible for doing it.

- Name of the Surveyor: a.
- b. Signature:
- c. Date:

Awirban 12/8/23.

2