

REPORT FORMAT: V-L2 (Large with P&M - SBI) | Version: 12.0_Nov.2022

CASE NO. VIS(2023-24)-PL223-Q037-193-276

Dated: 28.08.2023

FIXED ASSETS VALUATION REPORT

OF

NATURE OF ASSETS	LAND & BUILDING, PLANT & MACHINERY & OTHER MISCELLANEOUS FIXED ASSET
CATEGORY OF ASSETS	INDUSTRIAL
TYPE OF ASSETS	INDUSTRIAL PLANT

SITUATED AT

- M/S. SHALIMAR PAINTS LIMITED Corporate Valuers 19. CHINNA PULIYUR VILLAGE, GUMMIDIPUNDI TALUK, THIRUVALLUR DISTRICT, TAMIL NADU
- Business/ Enterprise/ Equity Valuations
- Lender's Independent Engineers (LIE)

REPORT PREPARED FOR

- Techno Economic Viability Consultants (TEV) ATE BANK OF INDIA, IFB BRANCH, MUMBAI
- Agency for Specialized Account Monitoring (ASM)
 - ry/ issue or escalation you may please contact Incident Manager
- We will appreciate your feedback in order to improve our services. Project Techno-Financial Advisors
- Chartered Engliseers As per IBA & Senk a Guidelines ple se provide your feedback on the report within 15 days of its submission report will be considered to be correct.
- Industry/Trade Patriakicitu iam (2001 Senvices & Valuer's Important Remarks are available at www.rkassociates.org for reference.
- NPA Management

Panel Valuer & Techno Economic Consultants for PSU

CORPORATE OFFICE:

D-39, 2nd floor, Sector 2, Noida-201301 Ph - +91-0120-4110117, 4324647, +91 - 9958632707 E-mail - valuers@rkassociates.org | Website: www.rkassociates.org



A product of R.K. Associates www.valuationintelligentsystem.com

VALUATION ASSESSMENT M/S. SHALIMAR PAINTS LIMITED



PART A

SNAPSHOT OF THE ASSET/ PROPERTY UNDER VALUATION







www.valuationintelligentsystem.com

VALUATION ASSESSMENT M/S. SHALIMAR PAINTS LIMITED



PART B

SBI FORMAT OF OPINION REPORT ON VALUATION

Name & Address of Branch	State Bank of India, IFB Branch, Mumbai	
Name of Customer (s)/ Borrower Unit	M/s. Shalimar Paints Limited	
Work Order No. & Date	Dated 1st August, 2023	

S.NO.	CONTENTS		DESCRIPTION				
1.	INTRODUCTION						
a.	Name of Property Owner	M/s. Shalimar Paints Limited (as per copy of documents provided to us)					
	Address & Phone Number of the Owner	Address: 1st Floor, Plot No. 28, Sector-32, Gurugram, Haryana					
b.	Purpose of the Valuation	For Periodic Re-valuation of the mortgaged property					
C.	Date of Inspection of the Property	22 August 2023					
	Property Shown By	Name	Relationship with Owner	Contact Number			
		Mr. Utkarsh Rastogi	Employee	+91- 86046 02440			
d.	Date of Valuation Report	28 August 2023					
e.	Name of the Developer of the Property	Owners themselves					
	Type of Developer	Property built by owne	er's themselves				

2. PHYSICAL CHARACTERISTICS OF THE PROPERTY

BRIEF DESCRIPTION OF THE PROPERTY UNDER VALUATION

This opinion on valuation report is prepared for the freehold property situated at Factory No. 19, Chinna Puliyur Village, Gummidipundi Taluk, Thiruvallur District, Tamil Nadu, having land area admeasuring 8.89 Acres / 35,977 sq.mtr. as per the Sale Deed provided to us. The survey numbers mentioned in the Deed is shown in the table below:

S. No.	Sale Deed No.	Survey Numbers	Area (in Acres)
1	6746	1/1A	3.49
2	6745	3/2	3.32
3	6745	3/1	1.5
4	6745	15/1A, 15/1B, 15/1C	0.58 (0.28 + 0.16 + 0.14)
	Tot	tal	8.89

The subject property comprises of the structures, details of which as per the measurement during the site survey is attached below:

Sr. No.	Particulars	Type of Structure	Area (in sq.ft.)	Height (in ft.)
1	Production Area	Tin Shed bounded on R.C.C Column	19,510	chno Engine 35
2	QC Area	Tin Shed bounded on R.C.C Column	1,584	35
3	RM Storage	Tin Shed bounded on R.C.C Column	26,320	85

FILE NO.: VIS(2023-24)-PL223-Q037-193-277





World's first fully digital Automated Platform for Integrating Valuation Life Cycle -A product of R.K. Associates www.valuationintelligentsystem.com

4	Utility Area	Tin Shed bounded on R.C.C Column	1,000	15
5	Barrel Shed	Tin Shed bounded on R.C.C Column	3,520	25
6	DP Godown	Tin Shed bounded on R.C.C Column	1,100	25
7	Hazardous waste	Tin Shed bounded on R.C.C Column	1,350	25
8	Non-Hazardous waste	Tin Shed bounded on R.C.C Column	1,350	25
9	LT Panel Room	R.C.C Framed structure	1,225	15
10	UPS Room	R.C.C Framed structure	1,050	15
11	MCC Panel	R.C.C Framed structure	800	15
12	Finished Goods Storage	Tin Shed bounded on R.C.C Column	16,200	45
13	New Shed (Under construction)	Tin Shed bounded on R.C.C Column	23,400	45
14	Packing material storage shed	R.C.C Framed structure	21,600	15
15	Production Area (Ground)	R.C.C Framed structure	20,075	18
16	Production Area (High)	Tin Shed bounded on R.C.C Column	1,600	45
17	Admin Block	R.C.C Framed structure	13,700	10
18	Weigh Bridge	R.C.C Framed structure	100	10
19	Guard Room	R.C.C Framed structure	150	10
20	Hard standing for solvent tank	R.C.C Hard standing	45,000	

The subject property is used for the manufacturing of Decorative and Industrial paints & located in the village Chinna Puliyur, Gummidipundi Taluk, Thiruvallur District, Tamil Nadu. All the basic and civic amenities are being set-up within the close proximity of the subject property.

This report only contains general assessment & opinion on the Guideline Value and the indicative, estimated Market Value of the property of which Bank/ customer asked us to conduct the Valuation for the property found on as-is-where basis as shown on the site by the Bank/ customer of which photographs is also attached with the report. No legal aspects in terms of ownership or any other legal aspect is taken into consideration. Even if any such information is mentioned in the report it is only referred from the information provided for which we do not assume any responsibility. Due care has been given while doing valuation assessment, but it doesn't contain any due-diligence or audit or verification of any kind other than the valuation computation of the property shown to us on site. Information/ data/ documents given to us by Bank/ client have been reliable to the property shown to us on site. Information of the property of any sort.

In case of discrepancy in the address/ property number mentioned in the property documents and the property shown to us at the site due to change in zoning or administrative level at the site or the client misled the valuer by providing the fabricated/ incorrect document or information, the valuation should be considered of the



REINFORCING YOUR BUSINESS ASSOCIATES

VALUERS & TECHNO ENGINEERING CONSULTANTS (P) LTD.

WALLATION CONTROL OF EXCELLENCE

1. RESPARCH CLEATER

World's first fully digital Automated Platform for Integrating Valuation Life Cycle -A product of R.K. Associates Integrating the Computation of the Computation of

	property shown to us at the site by the clier	nt of which the photogr	aphs are also at	tached. In case of any doubt,				
	best would be to contact the concerned au							
	property if the property depicted in the photographs in this report is same with the documents pledged.							
a.	Location attribute of the property							
i.	Nearby Landmark	Jindal Steels						
ii.	Postal Address of the Property	M/S. Shalimar Paint						
		No. 19, Chinna Puli	yur Village, Gun	nmidipundi Taluk, Thiruvallur				
		District, Tamil Nadu						
iii.	Type of Land	Solid Land/ on road	level					
ív.	Independent access/ approach to the property	Clear independent a	iccess is availab	le				
٧.	Google Map Location of the Property with	Enclosed with the R						
	a neighborhood layout map	Coordinates or URL	: 13°23'11.8"N 8	0°03'22.7"E				
vi.	Details of the roads abutting the property							
	(a) Main Road Name & Width	Sathyavedu Road		Approx. 60 ft. wide				
	(b) Front Road Name & width	Internal Road		Approx. 20 ft. wide				
	(c) Type of Approach Road	Bituminous Road						
	(d) Distance from the Main Road	- F						
vii.	Description of adjoining property	Rural area and most	of the nearby la	and is lying barron				
viii.	Plot No. / Survey No.	No. 19		,				
ix.	Zone/ Block							
Χ.	Sub registrar							
xi.	District	Thiruvallur						
xii.	Any other aspect							
AII.	7 my canon doposi	given in the copy of by the owner/ owner Getting cizra map of identification is a s	documents proving representative to coordination v	ound as per the information yided to us and/ or confirmed to us at site. with revenue officers for site and is not covered in this				
All.	7 my danor dopodi	given in the copy of by the owner/ owner Getting cizra map of identification is a s Valuation services.	documents proving representative to coordination version activity	vided to us and/ or confirmed to us at site. vith revenue officers for site and is not covered in this				
All.	7 my outlot dopost	given in the copy of by the owner/ owner Getting cizra map of identification is a s Valuation services.	representative to coordination veparate activity	vided to us and/ or confirmed to us at site. vith revenue officers for site and is not covered in this Documents				
All.	7 my danor dopode	given in the copy of by the owner/ owner Getting cizra map of identification is a signification services. Documents Requested	representative to coordination version activity Documents Provided	vided to us and/ or confirmed to us at site. vith revenue officers for site and is not covered in this				
All.	7 my outlook dopool	given in the copy of by the owner/ owner Getting cizra map of identification is a s Valuation services.	representative to coordination veparate activity	vided to us and/ or confirmed to us at site. vith revenue officers for site and is not covered in this Documents Reference No.				
All.	7 my danor dopode	given in the copy of by the owner/ owner Getting cizra map of identification is a signification services. Documents Requested Total 06	representative or coordination veparate activity Documents Provided Total 02	vided to us and/ or confirmed to us at site. vith revenue officers for site and is not covered in this Documents Reference No.				
All.		given in the copy of by the owner/ owner Getting cizra map of identification is a services. Documents Requested Total 06 documents	representative or coordination we parate activity Documents Provided Total 02 documents provided	vided to us and/ or confirmed to us at site. vith revenue officers for site and is not covered in this Documents Reference No.				
All.	(a) List of documents produced for	given in the copy of by the owner/ owner Getting cizra map of identification is a say Valuation services. Documents Requested Total 06 documents requested.	representative or coordination veparate activity Documents Provided Total 02 documents	vided to us and/ or confirmed to us at site. vith revenue officers for site and is not covered in this Documents Reference No.				
All.	(a) List of documents produced for perusal (Documents has been	given in the copy of by the owner/ owner Getting cizra map of identification is a signification services. Documents Requested Total 06 documents requested. Property Title document Approved Map	representative or coordination we parate activity Documents Provided Total 02 documents provided	vided to us and/ or confirmed to us at site. vith revenue officers for site and is not covered in this Documents Reference No.				
All.	(a) List of documents produced for perusal (Documents has been referred only for reference purpose as provided. Authenticity to be	given in the copy of by the owner/ owner Getting cizra map of identification is a second Valuation services. Documents Requested Total 06 documents requested. Property Title document	representative to representati	vided to us and/ or confirmed to us at site. vith revenue officers for site and is not covered in this Documents Reference No. Dated: 11.12.2009				
All.	(a) List of documents produced for perusal (Documents has been referred only for reference purpose	given in the copy of by the owner/ owner o	representative to representati	vided to us and/ or confirmed to us at site. vith revenue officers for site and is not covered in this Bocuments Reference No. Dated: 11.12.2009				
All.	(a) List of documents produced for perusal (Documents has been referred only for reference purpose as provided. Authenticity to be	given in the copy of by the owner/ owner Getting cizra map of identification is a second Valuation services. Documents Requested Total 06 documents requested. Property Title document Approved Map Change of Land Use	Documents Provided Total 02 documents provided Sale Deed	vided to us and/ or confirmed to us at site. vith revenue officers for site and is not covered in this Documents Reference No. Dated: 11.12.2009				
All.	(a) List of documents produced for perusal (Documents has been referred only for reference purpose as provided. Authenticity to be	given in the copy of by the owner/ owner Getting cizra map of identification is a sequested Total 06 documents requested. Property Title document Approved Map Change of Land Use Site Plan Last paid Electricity Bill Last paid Municipal Tax Receipt	Documents Provided Total 02 documents provided Sale Deed	vided to us and/ or confirmed to us at site. vith revenue officers for site and is not covered in this Documents Reference No. Dated: 11.12.2009				
All.	(a) List of documents produced for perusal (Documents has been referred only for reference purpose as provided. Authenticity to be	given in the copy of by the owner/ owner o	Documents Provided Total 02 documents provided Sale Deed Site Plan	vided to us and/ or confirmed to us at site. vith revenue officers for site and is not covered in this Documents Reference No. Dated: 11.12.2009				
All.	(a) List of documents produced for perusal (Documents has been referred only for reference purpose as provided. Authenticity to be	given in the copy of by the owner/ owner Getting cizra map of identification is a sequested Total 06 documents requested. Property Title document Approved Map Change of Land Use Site Plan Last paid Electricity Bill Last paid Municipal Tax Receipt	Documents Provided Total 02 documents provided Sale Deed Site Plan Relationship	vided to us and/ or confirmed to us at site. vith revenue officers for site and is not covered in this Documents Reference No. Dated: 11.12.2009				
All.	(a) List of documents produced for perusal (Documents has been referred only for reference purpose as provided. Authenticity to be ascertained by legal practitioner)	given in the copy of by the owner/ owner o	Documents Provided Total 02 documents provided Sale Deed Site Plan	vided to us and/ or confirmed to us at site. vith revenue officers for site and is not covered in this S Documents Reference No. Dated: 11.12.2009 with Contact Number				



REINFORCING YOUR BUSINESS ASSOCIATES

VALUERS & TECHNO ENGINEERING CONSULTANTS (P) LTD.

WALLATION CENTER OF EXCELLENCE
OR IS SANCH CENTER.

World's first fully digital Automated Platform for Integrating Valuation Life Cycle -A product of R.K. Associates www.valuationintelligentsystem.com

			V	Identified by own					
			~	Done from the na			The state of the s		
	A. Identification procedure followed of the property			☐ Cross checked from boundaries or address of the property mentioned in the deed					
				Enquired from loa	cal reside	ents/ public			
				Identification of the	ne prope	rty could not l	be done properly		
				Survey was not o	done				
	B. Type of Survey		survey (inside-out tographs).	with app	roximate mea	surements &			
	C. Is property clearly demand permanent/ temporary bosite	Yes	demarcated prope	rly					
	Is the property merged or colluded with any other property			It is an independen	nt single l	oounded prop	perty		
	E. City Categorization			Village			Rural		
	The state of the s	F. Characteristics of the locality				Within	good village area		
	G. Property location classification H. Property Facing			rmal location within locality	loca	Ordinary ation within e locality	None		
				North Facing					
b.	Area description of the Property			Land		Co	nstruction		
	Also please refer to Padescription of the prope	Also please refer to Part-B Area description of the property. Area				Bu	ilt-up Area		
	measurements considered in the Valuation Report is adopted from relevant approved documents or actual site measurement whichever is less, unless otherwise mentioned. Verification of the area measurement of the property is done only based on sample random checking.			8.89 Acres / 35,977 sq.mtr. 2,00,634 sq.ft. / 18,640 s					
c.	Boundaries schedule of the					And the second s			
i.	Are Boundaries matched	- Composite value on ♥ II.	No.	boundaries are not	mention	ed in the doc	uments.		
ii.	Directions	As p	A	e Deed/TIR	Actual found at Site				
	East	Not mention	oned in the documents			M/s. Jindal Steels			
	West			n the documents		Forest Land			
	North			n the documents		Road			
	South			the documents		Agricultu	iral Land		
3.	TOWN PLANNING/ ZONIN	STILL SUVERABLICATIONS STATE							
a.	Master Plan provisions related terms of Land use	to property i	in	Area not notified under Master Plan					
	i. Any conversion of land	d use done		From Agricultura certificate is pro			ver, no conversion		
	ii. Current activity done in the property			The state of the					
	II. Current activity done in	n the propert	-	industrial and de	ecorative	pairits	- 8 learne Ligino		
	iii. Is property usage as p zoning		e	It is a village are		· · · · · · · · · · · · · · · · · · ·	011/9		
	iii. Is property usage as p	er applicable		CHARLES AND A CONTROL OF THE PARTY OF THE PA	ea, no zo	ning regulation	011/0		





World's first fully digital Automated Platform for Integrating Valuation Life Cycle -A product of R.K. Associates www.valuationintelligentsystem.com

b.	Provision of Building by-laws as applicable	PERMITTED	CONSUMED			
	i. FAR/FSI	(===)				
	ii. Ground coverage					
	iii. Number of floors	()				
	iv. Height restrictions					
	v. Front/ Back/Side Setback					
	vi. Status of Completion/ Occupational	No information provided	No information provided			
	certificate		The information provided			
C.	Comment on unauthorized construction if any	Cannot comment, since ap	proved map is not provided			
d.	Comment on Transferability of developmental rights	Free hold, complete transfe	erable rights			
e.	i. Planning Area/ Zone	Not notified				
	ii. Master Plan Currently in Force	Not applicable				
	iii. Municipal Limits	Gram Panchayat				
f.	Developmental controls/ Authority	Gram Panchayat				
g.	Zoning regulations	Not yet under zoning regula	ation			
h.	Comment on the surrounding land uses & adjoining properties in terms of uses	Rural area and most of the	nearby land is lying barron			
i.	Comment of Demolition proceedings if any	Not in our knowledge				
j.	Comment on Compounding/ Regularization proceedings	Not in our knowledge				
j.	Any other aspect					
	i. Any information on encroachment	No				
	ii. Is the area part of unauthorized area/ colony	No (As per general information available)				
4.	DOCUMENT DETAILS AND LEGAL ASPEC	CTS OF THE PROPERTY	Contract to the contract of th			
a.	Ownership documents provided	Sale deed No	one None			
b.	Names of the Legal Owner/s	M/s. Shalimar Paints Limite	ed			
C.	Constitution of the Property	Free hold, complete transfe	erable rights			
d.	Agreement of easement if any	Not required				
e.	Notice of acquisition if any and area under acquisition	No such information came i on public domain	n front of us and could be fou			
f.	Notification of road widening if any and area	No such information came in front of us and could be fo				
	under acquisition	on public domain				
g.	Heritage restrictions, if any	No				
h.	Comment on Transferability of the property ownership	Free hold, complete transfe				
i.	Comment on existing mortgages/ charges/ encumbrances on the property, if any	Yes	State Bank of India			
j.	Comment on whether the owners of the property have issued any guarantee (personal or corporate) as the case may be	Not known to us	NA			
k.	Building plan sanction:		SE TECHNO ENGIN			
	i. Is Building Plan sanctioned	Cannot comment since no on our request	approved map provided to us			
	ii. Authority approving the plan	Not applicable	Soci			
	iii. Any violation from the approved Building Plan	Cannot say.	La L			





World's first fully digital Automated Platform for Integrating Valuation Life Cycle -A product of R.K. Associates. www.valuationintelligentsystem.com

	 iv. Details of alterations/ deviations/ illegal construction/ encroachment noticed in the 	☐ Permissible Alterations	
	structure from the original approved plan	☐ Not permitted alteration	
1.	Whether Property is Agricultural Land if yes, any conversion is contemplated	No not an agricultural pro	perty
m.	Whether the property SARFAESI complaint	Yes	
n.	 Information regarding municipal taxes 	Property Tax	No information available
	(property tax, water tax, electricity bill)	Water Tax	No information available
		Electricity Bill	No information available
	ii. Observation on Dispute or Dues if any in payment of bills/ taxes	No such information came	to knowledge on site
	iii. Is property tax been paid for this property	Not available	
	iv. Property or Tax Id No.	Not available	
0.	Whether entire piece of land on which the unit is set up / property is situated has been mortgaged or to be mortgaged	Yes, as informed by owner	r/ owner representative.
p.	Qualification in TIR/Mitigation suggested if any	Can't comment since not a	a legal expert
q.	Any other aspect	copy of the documents/ in client and has been reliproperty found as per documents provided to us owner representative to us Legal aspects, Title verific of documents from original Govt. deptt. of the property expert/ Advocate.	port on Valuation based on the formation provided to us by the ed upon in good faith of the the information given in the and/ or confirmed by the owner/s on site. ation, Verification of authenticity als or cross checking from any y have to be taken care by legal
	i. Property presently occupied/ possessed by	Owner	

*NOTE: Please see point 6 of Enclosure: VIII - Valuer's Important Remarks

5.	ECONOMIC ASPECTS OF THE PROPERTY						
a.	Reasonable letting value/ Expected market monthly rental	NA					
b.	Is property presently on rent	No					
	i. Number of tenants	NA					
	ii. Since how long lease is in place	NA					
	iii. Status of tenancy right	NA					
	iv. Amount of monthly rent received	NA					
C.	Taxes and other outgoing	200					
d.	Property Insurance details						
e.	Monthly maintenance charges payable						
f.	Security charges, etc.						
g.	Any other aspect	NA					
6.	SOCIO - CULTURAL ASPECTS OF THE P	ROPERTY S Techno Engine					
а	Descriptive account of the location of the property in terms of Social structure of the area in terms of population, social stratification, regional origin, age groups, economic levels, location of slums/squatter settlements nearby, etc.	Rural Area					





World's first fully digital Automated Platform for Integrating Valuation Life Cycle -A product of R.K. Associates www.valuationintelligentsystem.com

b		oroperty belo e like hospital	0	social I age	No					
7.	FUNCTIONAL AND UTILITARIAN SERVICES, FACILITIES & AMENITIES									
a.	Description of	of the functional	ity & utility of t	the pro	perty in term	ns of:	o a parti manusana			
	i. Spac	ce allocation			Yes	2000				
	ii. Storage spaces			Yes						
	iii. Utility of spaces provided within the building				Yes					
	iv. Car parking facilities			Yes						
	v. Balconies			No						
b.	Any other as	pect	Maria Maria						-///	
		nage arrangem			Yes					
	ii. Water Treatment Plant				No					
	iii. Power Supply Permanent			Yes						
	arrangements Auxiliary			Marian Control of the	ets (100 K	VA, 1010	(AVA)			
	iv. HVAC system			No						
	v. Security provisions				te security	guards				
	vi. Lift/ Elevators			No						
	vii. Compound wall/ Main Gate			Yes						
	viii. Whether gated society			No						
	Internal development									
	Garden/ Pa	ng	r bodies	Int	ernal roads	·	Pavemen	ts	Boundary V	
	No		No		Yes		Yes			Yes
3.	INFRASTRU	CTURE AVAIL	ABILITY							
a.	Description of	of Aqua Infrastru	ucture availabi	ility in t	erms of:					
	i. Wate	er Supply			Yes from borewell/ submersible					
	ii. Sew	erage/ sanitatio	n system		Underground					
	iii. Storr	m water drainag	je		Yes					
b.	Description of	of other Physica	I Infrastructure	e facilit	ies in terms	of:				
	i. Solid	waste manage	ement		Yes, by the	local Auth	ority			
	ii. Elec	tricity			Yes					
		d and Public Tra	ansport		Yes					
	iv. Avai near	ability of other	public utilities		Transport, Market, Hospital etc. available in close vicinity					
C.		availability of civ	vic amenities 8	& socia	l infrastructu	re	HLL			III. Lai
	School	Hospital	Market		Bus Stop	Railwa Statio		Metro		Airport
	~ 2 km.	~ 11 km.	~ 2 km.		~10 km.	~ 10.5	km.		No.	
	The state of the s	recreation faci	lities (parks,		, This is a ru	ral remote a	area. No	recreation	al facilit	y is availal
1	open spaces		070 05 7::-		arby.			15/5		a Consu
9.		BILITY ASPE	STATES SELECTION	= PRO	PERTY			ciates		Suitan
a.				2339				/	32	100
	i. Location attribute of the subject property				Good				0 1	. Dil



Id's first fully digital Automated Platform, Integrating Valuation Life Cycle -A product of 8 K. Associates www.valuation.ortelliaentsystem.com

A pron	luct of R.K. Associal tionintelligentsysl	ars .				
	iii. De	emand and supply of the kind of the bject property in the locality	Good demand of s	such proper	ties in the marke	et.
	iv. Co	emparable Sale Prices in the locality	Please refer to Pa	rt D: Proced	dure of Valuation	Assessment
b.	Any other aspect which has relevance on the value or marketability of the property		Property is locate	d on main r	oad.	
	i. An	y New Development in surrounding ea	No		NA	
		y negativity/ defect/ disadvantages in e property/ location	Moderate demar property because location.		NA	
10.	ENGINE	ERING AND TECHNOLOGY ASP	ECTS OF THE PR	OPERTY		
a.	Type of c	onstruction	Structure	SI	ab	Walls
			Please re	fer to the b	uilding sheet atta	ached
b.	Material 8	& Technology used	Material U	sed	Technol	ogy used
	CHEST STATES	See the Line verses of parameters.	Please re	fer to the b	uilding sheet atta	
C.	Specifica	tions				
	i. F	Roof	Floors/ Blo	cks	Туре	of Roof
			Please refer to the building sheet attached			
	ii. Floor height		Please refer to the building sheet attached			
	iii. Type of flooring		PCC, Vitrified tiles			
	iv. Doors/ Windows		Aluminum flushed doors & windows (In admin building)			
	v. Class of construction/ Appearance/ Condition of structures		Internal - Class B construction (Good)			
			External - Class B construction (Good)			
	vi. Ir	nterior Finishing & Design	The state of the s	rchitecture,	ecture, Plain ordinary finishing,	
	vii. E	xterior Finishing & Design			Plain ordinary fir	ain ordinary finishing, Simple
		nterior decoration/ Special rchitectural or decorative feature	Simple plain lookir	Simple plain looking structure.		
	ix. C	lass of electrical fittings	Internal / Normal of	uality fitting	s used	
		lass of sanitary & water supply ttings	Internal / Normal o	uality fitting	s used	
d.	Maintena	nce issues	No maintenance is	sue, structi	ure is maintained	properly
e.	Age of bu	ilding/ Year of construction	Approx. 8 ye			ear-2015
f.	Total life of expected	of the structure/ Remaining life	Please refer to the sheet attached	•	Please refer t	
g.	Extent of	deterioration in the structure	No deterioration ca			
h.	Structural	safety	The structure stab			
i.	Protection earthquak	against natural disasters viz.	Since this is a RC0 moderate intensity only based on vitesting.	Structure : earthquake	so should be ab es. Comments a	e to withstand re been made
j.	Visible da	mage in the building if any	No visible damage	s in the stru	icture 1818	hno Engine
k.	System of	f air conditioning	Partially covered w		180	130
I.		of firefighting	Fire Extinguishers		lifes Sal	Consul
-	Canina	the plan and alcosting of the body in	F 1 1 11 11 11		181	(5)

Enclosed with the report

Copies of the plan and elevation of the building

to be included





World's first fully digital Automated Platform for Integrating Valuation Life Cycle - A product of R.K. Associates www.valuationintelligentsystem.com

11.	environmental factors	
		No regular building techniques of BCC and burnt alov
a.	Use of environment friendly building materials like fly ash brick, other Green building techniques if any	bricks are used
b.	Provision of rainwater harvesting	No
C.	Use of solar heating and lighting systems, etc.	No
d.	Presence of environmental pollution in the vicinity of the property in terms of industries heavy traffic, etc. if any	
12.	ARCHITECTURAL AND AESTHETIC QU	ALITY OF THE PROPERTY
a.	Descriptive account on whether the building is modern, old fashioned, etc., plain looking o with decorative elements, heritage value is applicable, presence of landscape elements, etc.	r
13.	VALUATION	
a.	Methodology of Valuation - Procedures	Please refer to Part D: Procedure of Valuation
	adopted for arriving at the Valuation	Assessment of the report.
b.	Prevailing Market Rate/ Price trend of the	The Control of the Co
	Property in the locality/ city from property	
	search sites	the report, if available.
C.	Guideline Rate obtained from Registrar's office State Govt. gazette/ Income Tax Notification	the state of the property of the state of th
		Assessment of the report and the screenshot annexure in the report, if available.
d.	Summary of Valuation	For detailed Valuation calculation please refer to Part D : Procedure of Valuation Assessment of the report.
	i. Guideline Value	Rs.80,01,000/- (Land Value Only)
	1. Land	Rs.80,01,000/-
	2. Building	
	ii. Indicative Prospective Estimated Fair Market Value	Rs.55,53,00,000/-
	iii. Expected Estimated Realizable Value	Rs.47,20,05,000/-
	iv. Expected Forced/ Distress Sale Value	Rs.41,64,75,000/-
	v. Valuation of structure for Insurance purpose	~Rs.21,00,00,000/-
e.	i. Justification for more than 20% difference in Market & Circle Rate	Circle rates are determined by the District administration as per their own theoretical internal policy for fixing the minimum valuation of the property for property registration tax collection purpose and Market rates are adopted based on prevailing market dynamics found as per the discrete market enquiries which is explained clearly in Valuation assessment factors.
	 Details of last two transactions in the locality/ area to be provided, if available 	(3)





Integrating Valuation Life Cycle

A product of R.K. Associates

www.valuationintelligentsystem.com

14.	Declaration a. The inform belief.	ation provided by us is true and correct to the best of our knowledge and
	b. The analys	sis and conclusions are limited by the reported assumptions, limiting
	Valuation be the provision ability and above Hand d. Procedures Part-D of the standards in the end of the	remarks. read the Handbook on Policy, Standards and Procedures for Real Estate by Banks and HFIs in India, 2009 issued by IBA and NHB, fully understood ons of the same and followed the provisions of the same to the best of our this report is in conformity to the Standards of Reporting enshrined in the dbook as much as practically possible in the limited time available. It is and standards adopted in carrying out the valuation and is mentioned in the report which may have certain departures to the said IBA and IVS in order to provide better, just & fair valuation. The order to provide better, just & fair valuation. The order to provide better, just & fair valuation. The order to provide better, just & fair valuation. The order to provide better, just & fair valuation. The order to provide better, just & fair valuation. The order to provide better, just & fair valuation. The order to provide better, just & fair valuation. The order to provide better, just & fair valuation. The order to provide better, just & fair valuation. The order to provide better, just & fair valuation. The order to provide better, just & fair valuation. The order to provide better, just & fair valuation. The order to provide better, just & fair valuation. The order to provide better, just & fair valuation. The order to provide better, just & fair valuation. The order to provide better to the said IBA and IVS in order to provide better to the said IBA and IVS in order to provide better to the said IBA and IVS in order to provide better to the said IBA and IVS in order to provide better to the said IBA and IVS in order to provide better to the said IBA and IVS in order to provide better to the said IBA and IVS in order to provide better to the said IBA and IVS in order to provide better to the said IBA and IVS in order to provide better to the said IBA and IVS in order to provide better to the said IBA and IVS in order to provide better to the said IBA and IVS in order to provide better to the said IBA and IVS in order to pro
		ubmitted the Valuation Report directly to the Bank.
15.	ENCLOSED DOCUMENTS	
a.	Layout plan sketch of the area i	ng garan naggaraga na magalawan sa katan na magan na mag
b.	property is located with latitude and Building Plan	Not Available
C.	Floor Plan	Not Available Not Available
d.	Photograph of the property (inc	
u.	stamping with date) and owner housing loans, if borrower is available a "Selfie" of the Valuer at the site	(in case of photographs
e.	Certified copy of the approved / sar wherever applicable from the conc	
f.	Google Map location of the propert	ty Enclosed with the Report
g.	Price trend of the property in the from property search Magickbricks.com, 99Acres.com, etc.	sites viz
h.	Any other relevant documents/extra (All enclosures & annexures to resport & parcel of the main report)	
	Total Number of Pages in the Re	
i.	rotal stamper of rages in the ste	port with



www.valuationintelligentsystem.com

VALUATION ASSESSMENT M/S. SHALIMAR PAINTS LIMITED



PART C

AREA DESCRIPTION OF THE PROPERTY

	Land Area considered for Valuation	8.89 Acres / 35,977 sq.mtr.				
1.	Area adopted on the basis of	Property documents	& site survey both			
	Remarks & observations, if any	The land area is considered as per the document provided to us and has been cross checked via measurement through satellite measurement tools.				
2.	Constructed Area considered for Valuation (As per IS 3861-1966)	Built-up Area	2,00,634 sq.ft. / 18,640 sq.mtr.			
750	Area adopted on the basis of	Site survey measurement only since no relevant document was available				
	Remarks & observations, if any	The built-up area is considered as per the measurement during the site survey.				

Note:

- Area measurements considered in the Valuation Report pertaining to Land & Building is adopted from relevant approved documents or actual site measurement whichever is less. All area measurements are on approximate basis only.
- 2. Verification of the area measurement of the property is done based on sample random checking only.
- Area of the large land parcels of more than 2500 sq.mtr or of uneven shape, is taken as per property documents verified with digital survey through google which has been relied upon.
- Drawing Map, design & detailed estimation of the property/ building is out of scope of the Valuation services.





REINFORCING YOUR BUSINESS ASSOCIATES

VALUERS & TECHNO ENGINEERING CONSULTANTS (P) LTD.

WALMARDIN CENTER OF EXCELLENCE

1 THE STANCES CENTER

World's first fully digital Automated Platform for Integrating Valuation Life Cycle -A product of R.K. Associates www.valuationintelligentsystem.com

PART D

PROCEDURE OF VALUATION ASSESSMENT

1.		GENERAL	INFORMATION		使要的走出事情	
ì.	Important Dates	Date of Appointment	Date of Inspection of the Property	Date of Valuation Assessment	Date of Valuation Report	
		1 August 2023	22 August 2023	28 August 2023	28 August 2023	
ii.	Client		, IFB Branch, Mumb			
iii.	Intended User		, IFB Branch, Mumb			
iv.	Intended Use	free market transac	ction. This report is r	not intended to cov	f the property as per er any other internal s per their own need,	
٧.	Purpose of Valuation	For Periodic Re-va	luation of the mortga	aged property		
vi.						
vii.	Restrictions	This report should r for any other date certification of owner	not be referred for an e other then as s	ny other purpose, by pecified above. The property num	y any other user and his report is not a ber/ Khasra number	
viii.	Manner in which the proper is		y the owner			
	identified	✓ Identified by owner's representative				
		✓ Done from the name plate displayed on the property				
		☐ Cross check in the deed	ked from boundarie	s or address of the	property mentioned	
		☐ Enquired from local residents/ public				
	The second secon	☐ Identification of the property could not be done properly				
		□ Survey was not done				
ix.	Is property number/ survey number displayed on the property for proper identification?		name is mentioned	at the entry gate.		
X.	Type of Survey conducted	Full survey (inside-	out with approximate	e measurements &	photographs).	

		ASSES	SMEN	NT FACTORS	
i.	Valuation Standards considered	and improvised by to derive at a reason	the Riconable definition	(A internal research team as , logical & scientific approach	ndian authorities & institutions s and where it is felt necessary th. In this regard proper basis, below which may have certain
ii.	Nature of the Valuation	Fixed Assets Valu	ation		
iii.	The state of the s	Nature		Category	Type
	Classification of Asset under Valuation	LAND & BUILDING		INDUSTRIAL	INDUSTRIAL PROJECT LAND & BUILDING
71.07		Classificatio	n	Income/ Revenue Genera	ating Asset
iv.	Type of Valuation (Basis of Valuation as per IVS)	Primary Basis	Mark	et Value & Govt. Guideline	
	valuation as per 1v3)	Secondary Basis	On-g	oing concern basis	1
V.	Present market state of the	Under Normal Mar	rketabl	e State	8 Techno Engine
	Asset assumed (Premise of Value as per IVS)	Reason: Asset un	der fre	e market transaction state	S. Constitution of the Con
vi.	Property Use factor	Current/ Existing	y Use	Highest & Best Use (in consonance to surrounding use, zoning and statutory norms)	Considered for Valuation purpose
		Industrial		Industrial	Industrial



REINFORCING YOUR BUSINESS ASSOCIATES

VALUERS & TECHNO ENGINEERING CONSULTANTS (P) LTD.

WALLIATION CENTER OF EXCELLENCE

SPECEAGOR CENTRE

Integrating Valuation Life Cycle A product of 8 K. Associates

www.valuationintelligentsystem.com

vii.	Legality Aspect Factor	However Legal a Valuation Service provided to us in Verification of aut	ne as per copy of the caspects of the proper es. In terms of the lega good faith. henticity of documents to be taken care by L.	ty of any nature are ality, we have only gon a from originals or cros	out-of-scope of the ne by the documents ss checking from any	
viii.	Class/ Category of the locality	Middle Class (Or				
ix.	Property Physical Factors	Shape	Siz		Layout	
124	D	Irregular	Lar		Normal Layout	
X.	Property Location Category Factor	City Categorization	Locality Characteristics	Property location characteristics	Floor Level	
	77-13-1	Village	Ordinary	Ordinary location within the locality	Ground + 1st Floor	
		Rural	Normal Within good village area	None None		
			1500.5.50	ty Facing		
				Facing		
xi.	Physical Infrastructure availability factors of the locality	Water Supply	Sewerage/ sanitation system	Electricity	Road and Public Transport connectivity	
		Yes from municipal connection	Underground	Yes	Easily available	
			ther public utilities earby	Availability of communication facilities		
		9.	et, Hospital etc. are n close vicinity	Provider & ISP	unication Service connections are lable	
xii.	Social structure of the area (in terms of population, social stratification, regional origin, age groups, economic levels, location of slums/ squatter settlements nearby, etc.)	Rural Area				
xiii.	Neighbourhood amenities	Average				
xiv.	Any New Development in surrounding area	None				
XV.	Any specific advantage in the property	Not as such.				
xvi.	Any specific drawback in the property	None				
	Property overall usability/ utility Factor	Good				
xviii.	alternate use?	Yes, for agricultur			State Engineering	
	Is property clearly demarcated by permanent/ temporary boundary on site		permanent boundary	2	Consultants	
XX.	Is the property merged or colluded with any other	No		AA.	The state of the s	
	property	Comments:		('V		



REINFORCING YOUR BUSINESS ASSOCIATES VALUATION CENTER OF EXCELLENCE as he sealich centre

A product of R.K. Associates www.valuationintelligentsystem.com	
xxi. Is independent access	Clear independent access is avai

xxi.	Is independent access available to the property	Clear independent access is available					
xxii.	Is property clearly possessable upon sale	Yes					
xxiii.	Best Sale procedure to	Fair Market Value					
	realize maximum Value (in respect to Present market state or premise of the Asset as per point (iv) above)		th wherein the parties, after full market rudently and without any compulsion.				
xxiv.	Hypothetical Sale transaction	Fair Market Value					
19.11	method assumed for the computation of valuation			th wherein the parties, after full market rudently and without any compulsion.			
XXV.	Approach & Method of		Approach of Valuation	Method of Valuation			
	Valuation Used	Land	Market Approach	Market Comparable Sales Method			
			Cost Approach	Depreciated Replacement Cost Method			
xxvi.	Type of Source of Information	Lev	el 3 Input (Tertiary)				
xxvii.	Market Comparable						
	References on prevailing	1.	Name:	Mr. Nagarjan Ranjan			
	market Rate/ Price trend of		Contact No.:	+91- 98941 00134			
	the property and Details of		Nature of reference:	Property Consultant			
11 = 11	the sources from where the		Size of the Property:	~8 Acres			
	information is gathered (from property search sites & local information)		Location:	Similar			
			Rates/ Price informed:	Around Rs.2 Cr per Acre			
				(on main road) (Negotiable)			
			Any other details/ Discussion held:	As per the discussion with the property dealer of the subject locality we came to know that the plots are available for sale at the above-mentioned rate. The land is already converted for industrial use (red zone).			
		2.	Name:	Mr. Chandrasekar Mani Nadar			
			Contact No.:	+91- 9994474240			
			Nature of reference:	Property Consultant			
			Size of the Property:	7.5 Acres			
			Location:	In close proximity			
			Rates/ Price informed:	Around Rs.1.1 Cr per Acre			
			Any other details/ Discussion held:	As per the discussion with the property dealer of the subject locality we came to know that the agricultural plots are available for sale within the abovementioned range at a distance of 1 km. from the main road.			
		3.	Name:	Reference on public domain			
			Contact No.:				
			Nature of reference:	Property Consultant			
			Size of the Property:	1504 sq.ft.			
			Location:	Similar			
			Rates/ Price informed:	Around Rs.6.5 Lake			
			Any other details/ Discussion held:	As per the reference the price for a residential plot of 1504 sq ft is around			



VALUATION ASSESSMENT

REINFORCING YOUR BUSINESS"

xxix. Other Market Factors

Current Market condition

xxvi

XX

XXX

System	M/S. SHALIMAR PAINTS LIMITED	VALUERS & TECHNO ENGINEERING CONSULTANTS (P) LTD. VALUATION CENTER OF EXCELLE			
t fully digital Automated Platform for grating Valuation Life Cycle - A product of R.K. Associates valuationintelligentsystem.com		A RESCARCH CENTRE			
		Rs.6.5 Lakh which works out to approx. Rs.1.4 Cr. per Acre.			
	NOTE: The given information above can be independently verified to know its authenticity.				
viii. Adopted Rates Justification	As per our discussion with the prope	rty dealers and habitants of the subject			

location we have gathered the following information: Rates for the plots having similar size as our subject property will be around Rs.1.1

Cr. to Rs.2 Cr. per Acre depending on the type and location of the property from the main road.

Based on the above information and keeping in mind the availability, size and location of plots in subject locality we are of the view to adopt a rate of Rs.1,30,00,000/- per Acre for the purpose of this valuation assessment.

go down or become worse, property market may change due to impact of Govt. policies or effect of domestic/ world economy, usability prospects of the property may change, etc. Hence before financing, Banker/ FI/should take into

Rs.1,23,50,000/- per Acre

NOTE: We have taken due care to take the information from reliable sources. The given information above can be independently verified from the provided numbers to know its authenticity. However due to the nature of the information most of the market information came to knowledge is only through verbal discussion with market participants which we have to rely upon where generally there is no written record.

Related postings for similar properties on sale are also annexed with the Report wherever available.

Adjustments (-/+): 0%

Normal Remarks: ---

		Adjustments (-1+): 0%			
	Comment on Property Salability Outlook	Depending upon market conditions			
		Adjustments (-/+): 0%			
	Comment on Demand &	Demand	Supply		
	Supply in the Market	Good	Adequately available		
		Remarks: Moderate demand of the	property because of its large size		
		Adjustments (-/+): 0%			
XX.	Any other special	Reason: Due to its location, uneven	approach road, and irregular parcel of land.		
	consideration	Adjustments (-/+): -5%	•		
xxi. Any other	Any other aspect which has relevance on the value or marketability of the property	circumstances & situations. For eg. V factory will fetch better value and in considerably lower value. Similarly, a market through free market arm's ler and if the same asset/ property is senforcement agency due to any kind	rty can fetch different values under different valuation of a running/ operational shop/ hotel/case of closed shop/ hotel/ factory it will fetch an asset sold directly by an owner in the openingth transaction then it will fetch better value old by any financer or court decree or Govt. of encumbrance on it then it will fetch lower er/ FI should take into consideration all such		
		situation on the date of the survey. It any asset varies with time & socio-e country. In future property market ma	ased on the facts of the property & market is a well-known fact that the market value of economic conditions prevailing in the region/ay go down, property conditions may change in may differ, property vicinity conditions may		

consideration all such future risk while financing.

Adjustments (-/+): 0%

FILE NO.: VIS(2023-24)-PL223-Q037-193-277

Valuation TOR is available at www.rkassociat-s.org

Final adjusted & weighted Rates considered for the

subject property

Page 17 of 57



xxxiii. Considered Rates
Justification

VALUATION ASSESSMENT M/S. SHALIMAR PAINTS LIMITED

REINFORCING YOUR BUSINESS ASSOCIATES

VALUES & TECHNO ENGINEERING CONSULTANTS (P) LTD.

WALLETON CENTER OF FIRST LINES

Integrating Valuation Life Cycle

A product of R.K. Associates

www.valuationinelliaentsystem.com

As per the thorough property & market factors analysis as described above, and
considering that the property is away from the main city of Chennai, it is considered
that the estimated market rates appears to be reasonable in our opinion.

xxxiv. Basis of computation & working

- Valuation of the asset is done as found on as-is-where basis on the site as identified to us by client/ owner/ owner representative during site inspection by our engineer/s unless otherwise mentioned in the report.
- Analysis and conclusions adopted in the report are limited to the reported assumptions, conditions and information came to our knowledge during the course of the work and based on the Standard Operating Procedures, Best Practices, Caveats, Limitations, Conditions, Remarks, Important Notes, Valuation TOR and definition of different nature of values.
- For knowing comparable market rates, significant discreet local enquiries have been made from our side based
 on the hypothetical/virtual representation of ourselves as both buyer and seller for the similar type of properties
 in the subject location and thereafter based on this information and various factors of the property, rate has
 been judiciously taken considering the factors of the subject property, market scenario and weighted adjusted
 comparison with the comparable properties unless otherwise stated.
- References regarding the prevailing market rates and comparable are based on the verbal/ informal/ secondary/ tertiary information which are collected by our team from the local people/ property consultants/ recent deals/ demand-supply/ internet postings are relied upon as may be available or can be fetched within the limited time & resources of the assignment during market survey in the subject location. No written record is generally available for such market information and analysis has to be derived mostly based on the verbal information which has to be relied upon.
- Market Rates are rationally adopted based on the facts of the property which came to our knowledge during
 the course of the assessment considering many factors like nature of the property, size, location, approach,
 market situation and trends and comparative analysis with the similar assets. During comparative analysis,
 valuation metrics is prepared and necessary adjustments are made on the subject asset.
- The indicative value has been suggested based on the prevailing market rates that came to our knowledge during secondary & tertiary market research and is not split into formal & informal payment arrangements. Most of the deals takes place which includes both formal & informal payment components. Deals which takes place in complete formal payment component may realize relatively less actual transaction value due to inherent added tax, stamp registration liabilities on the buyer.
- Secondary/ Tertiary costs related to asset transaction like Stamp Duty, Registration charges, Brokerage, Commission, Bank interest, Selling cost, Marketing cost, etc. pertaining to the sale/purchase of this property are not considered while assessing the indicative estimated Market Value.
- This report includes both, Govt. Guideline Value and Indicative Estimated Prospective Market Value as
 described above. As per the current market practice, in most of the cases, formal transaction takes place for
 an amount less than the actual transaction amount and rest of the payment is normally done informally.
- Area measurements considered in the Valuation Report pertaining to asset/ property is adopted from relevant approved documents or sample site measurement whichever is less unless otherwise mentioned. All area measurements are on approximate basis only.
- Verification of the area measurement of the property is done based on sample random checking only.
- Area of the large land parcels of more than 2500 sq.mtr or of uneven shape in which there can be practical
 difficulty in sample measurement, is taken as per property documents which has been relied upon unless
 otherwise stated.
- Drawing, Map, design & detailed estimation of the property/ building is out of scope of the Valuation services.
- Construction rates are adopted based on the present market replacement cost of construction and calculating
 applicable depreciation & deterioration factor as per its age, existing condition & specifications based on visual
 observation only of the structure. No structural, physical tests have been carried out in respect of it. No
 responsibility is assumed for latent defects of any nature whatsoever, which may affect value, or for any
 expertise required to disclose such conditions.
- Construction rates are adopted based on the plinth area rates prevailing in the market for the structure as a whole and not based on item wise estimation or Bills of Quantity method unless otherwise stated.
- The condition assessment and the estimation of the residual economic life of the structure are only based on the visual observations and appearance found during the site survey. We have not canded out any structural design or stability study; nor carried out any physical tests to assess structural integrity & strength.
- Any kind of unpaid statutory, utilities, lease, interest or any other pecuniary dues on the asset or on its owners

Page 18 of 57





rld's first fully digital Automated Platform for Integrating Valuation Life Cycle -A product of R.K. Associates www.valuationintelligentsystem.com

has not been factored in the Valuation.

- This Valuation is conducted based on the macro analysis of the asset/ property considering it in totality and not based on the micro, component or item wise analysis. Analysis done is a general assessment and is neither investigative in nature nor an audit activity.
- Valuation is done for the asset found on as-is-where basis which owner/owner representative/client/bank has shown to us on site of which some reference has been taken from the information/data given in the copy of documents provided to us which have been relied upon in good faith and we have assumed that it to be true and correct.

XXXV. ASSUMPTIONS

- a. Documents/ Information/ Data provided by the client/ property owner or his representative both written & verbally is true and correct without any fabrication and has been relied upon in good faith.
- b. Local verbal enquiries during micro market research came to our knowledge are assumed to be taken on record as true & factual.
- c. The assets and interests therein have been valued free and clear of any liens or encumbrances unless stated otherwise. No hidden or apparent conditions regarding the subject assets or their ownership are assumed to exist. No opinion of title is rendered in this report and a good title is assumed unless stated otherwise.
- d. It is assumed that the concerned Lender/ Financial Institution has asked for the valuation of that property after satisfying the authenticity of the documents given to us and for which the legal verification has been already taken and cleared by the competent Advocate before requesting for the Valuation report. I/ We assume no responsibility for the legal matters including, but not limited to, legal or title concerns.
- e. Payment condition during transaction in the Valuation has been considered on all cash bases which includes both formal & informal payment components as per market trend.
- f. Sale transaction method of the asset is assumed as Free market transaction without any compulsion unless otherwise mentioned while assessing Indicative & Estimated Fair Prospective Market Value of the asset unless otherwise stated.
- g. If this Valuation Report is prepared for the Flat/ dwelling unit situated in a Group Housing Society or Integrated Township then approvals, maps of the complete group housing society/ township is out of scope of this report. This valuation report is prepared for the specific unit based on the assumption that complete Group Housing Society/ Integrated Township is approved and complied with all relevant laws and the subject unit is also approved within the Group Housing Society/ Township.

xxxvi.	SPECIAL ASSUMPTIONS	
	None	
xxxvii.	LIMITATIONS	
	None	

3.		VALUATION OF LAND	
	Particulars	Govt. Circle/ Guideline Value	Indicative & Estimated Prospective Fair Market Value
a.	Prevailing Rate range	Rs.9,00,000/- per Acre	Rs.1,10,00,000/- to Rs.2,00,00,000/- per Acre
b.	Rate adopted considering all characteristics of the property	Rs.9,00,000/- per Acre	Rs.1,23,50,000/- per Acre
C.	Total Land Area considered (documents vs site survey whichever is less)	8.89 Acres / 35,977 sq.mtr.	8.89 Acres / 35,977 sq.mtr.
d.	Total Value of land (A)	8.89 Acres x Rs.9,00,000/- per Acre	8.89 Acres x Rs.1,23,50,000/- per
		Rs.80,01,000/-	Rs.10,97,9/1,500/-





World's first fully digital Automated Platform for Integrating Valuation Life Cycle -A product of R.K. Associates www.valuationintelligentsystem.com

4.

VALUATION COMPUTATION OF BUILDING & CIVIL WORKS

Sr. No.	Particulars	Type of Structure	Area (in sq.ft)	Height	Year of Construction	Total Life Consumed (in years)	Total Economical Life (in years)	Plinth Area Rate (in per sq.ft)	Gross Replacement Value (INR)	Depreciated Replacement Market Value (INR)
1	Production Area	Tin Shed bounded on R.C.C Column	19,510	35	2015	8	45	1,800	3,51,18,000	2,94,99,120
2	QC Area	Tin Shed bounded on R.C.C Column	1,584	35	2015	8	45	1,800	28,51,200	23,95,008
3	RM Storage	Tin Shed bounded on R.C.C Column	26,320	35	2015	8	45	1,800	4,73,76,000	3,97,95,840
4	Utility Area	Tin Shed bounded on R.C.C Column	1,000	15	2015	8	45	1,200	12,00,000	10,08,000
5	Barrel Shed	Tin Shed bounded on R.C.C Column	3,520	25	2015	8	45	1,300	45,76,000	38,43,840
6	DP Godown	Tin Shed bounded on R.C.C Column	1,100	25	2015	8	45	1,300	14,30,000	12,01,200
7	Hazardous waste	Tin Shed bounded on R.C.C Column	1,350	25	2015	8	45	1,300	17,55,000	14,74,200
8	Non-Hazardous waste	Tin Shed bounded on R.C.C Column	1,350	25	2015	8	45	1,300	17,55,000	14,74,200
9	LT Panel Room	R.C.C Framed structure	1,225	15	2015	8	65	1,500	18,37,500	16,33,962
10	UPS Room	R.C.C Framed structure	1,050	15	2015	8	65	1,500	15,75,000	14,00,538
11	MCC Panel	R.C.C Framed structure	800	15	2015	8	65	1,500	12,00,000	10,67,077
12	Finished Goods Storage	Tin Shed bounded on R.C.C Column	16,200	45	2015	8	45	1,900	3,07,80,000	2,58,55,200
13	New Shed (Under construction)	Tin Shed bounded on R.C.C Column	23,400	45	2015	8	45	1,900	4,44,60,000	3,73,46,400
14	Packing material storage shed	R.C.C Framed structure	21,600	15	2015	8	65	1,500	3,24,00,000	2,88,11,077
15	Production Area (Ground)	R.C.C Framed structure	20,075	18	2015	8	65	1,550	3,11,16,250	2,76,69,527
16	Production Area (High)	Tin Shed bounded on R.C.C Column	1,600	45	2015	8	45	1,900	30,40,000	25,53,600
17	Admin Block	R.C.C Framed structure	13,700	10	2015	8	65	1,500	2,05,50,000	1,82,73,692
18	Weigh Bridge	R.C.C Framed structure	100	10	2015	8	65	1,200	1,20,000	1,06,708
19	Guard Room	R.C.C Framed structure	150	10	2015	8	65	1,200	1,80,000	1,60,062
20	Hard standing for solvent tank	R.C.C Hard standing	45,000		2015	8	65	400	1,80,00,000	1,60,06,154
	Tota	al	2,00,634						28,13,19,950	24,15,75,404

Remarks:

1. All the details pertaining to the building area statement such as area, floor, type of structure is as per the measurment carried out, during site survey as no approved plan was provided by the company and the same has been relied upon and considered for the valuation.

FILE NO.: VIS(2023-24)-PL223-Q037-193-277

^{2.} Construction year of the plant has been taken from the information provided by the client during site survey.

^{3.} All the structure that has been taken in the area statement belonging to M/s. Shalimar Paints Limited, Chennai plant.

^{4.} The valuation is done by considering the depreciated replacement cost approach.





World's first fully digital Automated Platform for Integrating Valuation Life Cycle - A product of R.K. Associates www.valuationintelligentsystem.com

5.			THE STATE OF THE PARTY OF THE P		
. No.	Particulars	Specifications	Depreciated Replacement Value		
a.	Add extra for Architectural aesthetic developments, improvements (add lump sum cost)				
b.	Add extra for fittings & fixtures (Doors, windows, wood work, cupboards, modular kitchen, electrical/ sanitary fittings)				
C.	Add extra for services (Water, Electricity, Sewerage, Main gate, Boundary, Lift, Auxiliary power, AC, HVAC, Firefighting etc.)	For boundary wall	Rs.30,00,000/-		
d.	Add extra for internal & external development (Internal roads, Landscaping, Pavements, Street lights, Green area development, External area landscaping, Land development, Approach road, etc.)	For loading and unloading bay, weigh bridge ramp, drainage along the road, etc.	Rs.50,00,000/-		
e.	Depreciated Replacement Value (B)		Rs.80,00,000/-		
f.	 Value for Additional Building & Site Aesthetic Works is considered only if it is having exclusive/ super fine work specification above ordinary/ normal work. Ordinary/ normal work value is already covered under basic rates above. Value of common facilities of society are not included in the valuation of Flat/ Built-up unit. 				





www.valuationintelligentsystem.com

VALUATION ASSESSMENT M/S. SHALIMAR PAINTS LIMITED



PART E

CHARACTERISTICS DESCRIPTION OF PLANT/ MACHINERY

	CONTENTS	DESCI	RIPTION		
16.	TECHNICAL DESCRIPTION OF THE P	LANT/ MACHINERY			
a.	Nature of Plant & Machinery	Paint manufacturing machinery & equipment			
b.	Size of the Plant	Medium scale Plant			
c.	Type of the Plant	Semi Automatic			
d.	Year of Installation/ Commissioning/ COD (Commercial Operation Date)	2017 (as per information provide	d to us).		
e.	Production Capacity	Max.: 3000 kL per month			
f.	Capacity at which Plant was running at the time of Survey	No specific production line			
g.	Number of Production Lines				
h.	Condition of Machines	Good.			
i.	Status of the Plant	Fully operational			
j.	Products Manufactured in this Plant	Decorative Paint & Industrial Pair	nt (Allied products)		
k.	Recent maintenance carried out on	Regular maintenance has been done (As per information provide to us.)			
1.	Recent upgradation, improvements if done any				
m.	Total Gross Block & Net Block of Assets	Gross Block	Net Block		
			0/06/2023		
	Any other Details if any	Rs.23,96,43,203/- Rs.12,13,57,462/-			
n.	This still betails it any	is into manufacturing of Decorative	rified the machines & equipments		
17.	MANUFACTURING PROCESS				
	General Paint manufacturing flow chart Tank Farm Up to 2000 Raw Materia s 3. Labeling 1		Cuntomer sales of the Consultant of the Consulta		





Integrating Valuation Life Cycle -A product of 8 K. Associates www.valuationintelligentsystem.com

came to our knowledge during site inspection. Number of Labours working in the Factory ~100 22. SALES TRANSACTIONAL PROSPECTS OF SUCH PLANTS/ MACHINERY On-going concern basis Reason: This is a Mid scale Plant and all are general used machines which can be used in similar industrated cost of dismantling and transporation will not be very high. So for fetching maximum value is through strated.	18.	TECHNOLOGY TYPE/ GENERATION U	ISED AND TECHNOLOGICAL COLLABORATIONS IF ANY			
b. Technological Collaborations If Any c. Current Technology used for this Industry in Market Super paint with sanitizing technology 19. RAW MATERIALS REQUIRED & AVAILABILITY Type of Raw Material Solvent, Raisin, Extender, Binder, Additives, etc. Availability Adequately available 20. AVAILABILITY & STATUS OF UTILITIES Power/ Electricity Available Water Available Road/ Transport Available 21. COMMENT ON AVAILABILITY OF LABOUR Availability Appears to be easily & adequately available and no labour came to our knowledge during site inspection. Number of Labours working in the Factory -100 22. SALES TRANSACTIONAL PROSPECTS OF SUCH PLANTS/ MACHINERY On-going concern basis Reason: This is a Mid scale Plant and all are general used machines which can be used in similar industry cost of dismantling and transporation will not be very high. So for fetching maximum value is through strate to the players who are already into same or similar Industry who have plans for expansion or an conglomefrate who plans to enter into this new Industry 23. DEMAND OF SUCH PLANT & MACHINERY IN THE MARKET Appears to be good as per general information available in public domain. 24. SURVEY DETAILS a. Plant has been surveyed by our Engineering Team on dated 22/08/2023 b. Site inspection was done in the presence of Owner's representatives Mr. Sarevanan & Mr. Bhaskar who we available from the company to furnish any specific detail about the Plant & Machinery. c. Our team examined & verified the machines and utilities from the FAR provided by the Company. Only machinery, process line & equipment has been verified. d. Photographs have also been taken of all the Machines and its accessories installed there. e. Plant was found operational at the time of survey. f. Details have been cross checked as per the documents provided to us by the company and what was obset the site. g. Condition of the machines is checked through visual observation only. No technical/ mechanical/ operational has been carried out to ascertain the condition and ef	a.	Technology Type/ Generation Used in this	Indigenous			
c. Current Technology used for this Industry in Market 19. RAW MATERIALS REQUIRED & AVAILABILITY Type of Raw Material Availability Availability 20. AVAILABILITY & STATUS OF UTILITIES Power/ Electricity Water Road/ Transport Available 21. COMMENT ON AVAILABILITY OF LABOUR Availability Availability Availability Appears to be easily & adequately available and no labour came to our knowledge during site inspection. Number of Labours working in the Factory Ton-going concern basis Reason: This is a Mid scale Plant and all are general used machines which can be used in similar indust cost of dismantling and transporation will not be very high. So for fetching maximum value is through strate to the players who are already into same or similar Industry who have plans for expansion or an conglomefrate who plans to enter into this new Industry 23. DEMAND OF SUCH PLANT & MACHINERY IN THE MARKET Appears to be good as per general information available in public domain. 24. SURVEY DETAILS a. Plant has been surveyed by our Engineering Team on dated 22/08/2023 b. Site inspection was done in the presence of Owner's representatives Mr. Sarevanan & Mr. Bhaskar who we available from the company to furnish any specific detail about the Plant & Machinery. C. Our team examined & verified the machines and utilities from the FAR provided by the Company. Only machinery, process line & equipment has been verified. d. Photographs have also been taken of all the Machines and its accessories installed there. Plant was found operational at the time of survey. f. Details have been cross checked as per the documents provided to us by the company and what was obset the site. g. Condition of the machines is checked through visual observation only. No technical/ mechanical/ operational has been carried out to ascertain the condition and efficiency of machines.		Plant				
19. RAW MATERIALS REQUIRED & AVAILABILITY Type of Raw Material Availability Availability Availability Availability Availability Availabile 20. AVAILABILITY & STATUS OF UTILITIES Power/ Electricity Availabile Water Road/ Transport Availabile 21. COMMENT ON AVAILABILITY OF LABOUR Availability Availability Availability Appears to be easily & adequately available and no labour came to our knowledge during site inspection. Number of Labours working in the Factory -100 22. SALES TRANSACTIONAL PROSPECTS OF SUCH PLANTS/ MACHINERY On-going concern basis Reason: This is a Mid scale Plant and all are general used machines which can be used in similar indust cost of dismantling and transporation will not be very high. So for fetching maximum value is through strate to the players who are already into same or similar Industry who have plans for expansion or an conglomefrate who plans to enter into this new Industry 23. DEMAND OF SUCH PLANT & MACHINERY IN THE MARKET Appears to be good as per general information available in public domain. 24. SURVEY DETAILS a. Plant has been surveyed by our Engineering Team on dated 22/08/2023 b. Site inspection was done in the presence of Owner's representatives Mr. Sarevanan & Mr. Bhaskar who we available from the company to furnish any specific detail about the Plant & Machinery. c. Our team examined & verified the machines and utilities from the FAR provided by the Company. Only machinery, process line & equipment has been verified. d. Photographs have also been taken of all the Machines and its accessories installed there. Plant was found operational at the time of survey. f. Details have been cross checked as per the documents provided to us by the company and what was obset the site. C. Condition of the machines is checked through visual observation only. No technical/ mechanical/ operational has been carried out to ascertain the condition and efficiency of machines.	b.	Technological Collaborations If Any	No			
19. RAW MATERIALS REQUIRED & AVAILABILITY Type of Raw Material Solvent, Raisin, Extender, Binder, Additives, etc. Availability Adequately available 20. AVAILABILITY & STATUS OF UTILITIES Power/ Electricity Available Road/ Transport Available Available Availablity Appears to be easily & adequately available and no labour came to our knowledge during site inspection. Number of Labours working in the Factory -100 22. SALES TRANSACTIONAL PROSPECTS OF SUCH PLANTS/ MACHINERY On-going concern basis Reason: This is a Mid scale Plant and all are general used machines which can be used in similar indust cost of dismantling and transporation will not be very high. So for fetching maximum value is through strate to the players who are already into same or similar Industry who have plans for expansion or an conglomefrate who plans to enter into this new Industry 23. DEMAND OF SUCH PLANT & MACHINERY IN THE MARKET Appears to be good as per general information available in public domain. 24. SURVEY DETAILS a. Plant has been surveyed by our Engineering Team on dated 22/08/2023 b. Site inspection was done in the presence of Owner's representatives Mr. Sarevanan & Mr. Bhaskar who we available from the company to furnish any specific detail about the Plant & Machinery. c. Our team examined & verified the machines and utilities from the FAR provided by the Company. Only machinery, process line & equipment has been verified. d. Photographs have also been taken of all the Machines and its accessories installed there. e. Plant was found operational at the time of survey. f. Details have been cross checked as per the documents provided to us by the company and what was obset the site. g. Condition of the machines is checked through visual observation only. No technical/ mechanical/ operational has been carried out to ascertain the condition and efficiency of machines.	c.	Current Technology used for this Industry in				
Type of Raw Material Availability Adequately available 20. AVAILABILITY & STATUS OF UTILITIES Power/ Electricity Available Road/ Transport Available Available Available Available Road/ Transport Available Available Available Road/ Transport Available Road/ Transport Available Available Available Road/ Transport Available Available Available Road/ Transport Available		Market	Super paint with sanitizing technology			
Type of Raw Material Availability Adequately available 20. AVAILABILITY & STATUS OF UTILITIES Power/ Electricity Available Road/ Transport Availabile Road/ Transport Availabile Road/ Transport Availabile Road/ Transport Available Road/ Transport Availabile Road/ Transport Availabile 21. COMMENT ON AVAILABILITY OF LABOUR Availability Appears to be easily & adequately available and no labour came to our knowledge during site inspection. Number of Labours working in the Factory -100 22. SALES TRANSACTIONAL PROSPECTS OF SUCH PLANTS/ MACHINERY On-going concern basis Reason: This is a Mid scale Plant and all are general used machines which can be used in similar indust cost of dismantling and transporation will not be very high. So for fetching maximum value is through strate to the players who are already into same or similar Industry who have plans for expansion or an conglomefrate who plans to enter into this new Industry 23. DEMAND OF SUCH PLANT & MACHINERY IN THE MARKET Appears to be good as per general information available in public domain. 24. SURVEY DETAILS a. Plant has been surveyed by our Engineering Team on dated 22/08/2023 b. Site inspection was done in the presence of Owner's representatives Mr. Sarevanan & Mr. Bhaskar who we available from the company to furnish any specific detail about the Plant & Machinery. C. Our team examined & verified the machines and utilities from the FAR provided by the Company. Only machinery, process line & equipment has been verified. d. Photographs have also been taken of all the Machines and its accessories installed there. e. Plant was found operational at the time of survey. f. Details have been cross checked as per the documents provided to us by the company and what was obset the site. C. Condition of the machines is checked through visual observation only. No technical/ mechanical/ operational has been carried out to ascertain the condition and efficiency of machines.	19.	RAW MATERIALS REQUIRED & AVAIL	ABILITY			
Availability Adequately available 20. AVAILABILITY & STATUS OF UTILITIES Power/ Electricity Available Votater Available Road/ Transport Available COMMENT ON AVAILABILITY OF LABOUR Availability Appears to be easily & adequately available and no labour came to our knowledge during site inspection. Number of Labours working in the Factory ~100 22. SALES TRANSACTIONAL PROSPECTS OF SUCH PLANTS/ MACHINERY On-going concern basis Reason: This is a Mid scale Plant and all are general used machines which can be used in similar induse cost of dismantling and transporation will not be very high. So for fetching maximum value is through strate to the players who are already into same or similar Industry who have plans for expansion or an conglomefrate who plans to enter into this new Industry 23. DEMAND OF SUCH PLANT & MACHINERY IN THE MARKET Appears to be good as per general information available in public domain. 24. SURVEY DETAILS a. Plant has been surveyed by our Engineering Team on dated 22/08/2023 b. Site inspection was done in the presence of Owner's representatives Mr. Sarevanan & Mr. Bhaskar who we available from the company to furnish any specific detail about the Plant & Machinery. c. Our team examined & verified the machines and utilities from the FAR provided by the Company. Only machinery, process line & equipment has been verified. d. Photographs have also been taken of all the Machines and its accessories installed there. e. Plant was found operational at the time of survey. f. Details have been cross checked as per the documents provided to us by the company and what was obset the site. Condition of the machines is checked through visual observation only. No technical/ mechanical/ operational has been carried out to ascertain the condition and efficiency of machines.						
20. AVAILABILITY & STATUS OF UTILITIES Power/ Electricity Vater Available Road/ Transport Available COMMENT ON AVAILABILITY OF LABOUR Availability Availability Availability Appears to be easily & adequately available and no labour came to our knowledge during site inspection. Number of Labours working in the Factory -100 22. SALES TRANSACTIONAL PROSPECTS OF SUCH PLANTS/ MACHINERY On-going concern basis Reason: This is a Mid scale Plant and all are general used machines which can be used in similar induse cost of dismantling and transporation will not be very high. So for fetching maximum value is through strate to the players who are already into same or similar Industry who have plans for expansion or an conglomefrate who plans to enter into this new Industry 23. DEMAND OF SUCH PLANT & MACHINERY IN THE MARKET Appears to be good as per general information available in public domain. 24. SURVEY DETAILS a. Plant has been surveyed by our Engineering Team on dated 22/08/2023 b. Site inspection was done in the presence of Owner's representatives Mr. Sarevanan & Mr. Bhaskar who we available from the company to furnish any specific detail about the Plant & Machinery. c. Our team examined & verified the machines and utilities from the FAR provided by the Company. Only machinery, process line & equipment has been verified. d. Photographs have also been taken of all the Machines and its accessories installed there. Plant was found operational at the time of survey. f. Details have been cross checked as per the documents provided to us by the company and what was obset the site. Condition of the machines is checked through visual observation only. No technical/ mechanical/ operational has been carried out to ascertain the condition and efficiency of machines.		Availability	Adequately available			
Power/ Electricity Water Road/ Transport Available Road/ Transport Available Road/ Transport Available Available 21. COMMENT ON AVAILABILITY OF LABOUR Availability Appears to be easily & adequately available and no labour came to our knowledge during site inspection. Number of Labours working in the Factory -100 22. SALES TRANSACTIONAL PROSPECTS OF SUCH PLANTS/ MACHINERY On-going concern basis Reason: This is a Mid scale Plant and all are general used machines which can be used in similar indus cost of dismantling and transporation will not be very high. So for fetching maximum value is through strate to the players who are already into same or similar Industry who have plans for expansion or an conglomefrate who plans to enter into this new Industry 23. DEMAND OF SUCH PLANT & MACHINERY IN THE MARKET Appears to be good as per general information available in public domain. 24. SURVEY DETAILS a. Plant has been surveyed by our Engineering Team on dated 22/08/2023 b. Site inspection was done in the presence of Owner's representatives Mr. Sarevanan & Mr. Bhaskar who we available from the company to furnish any specific detail about the Plant & Machinery. c. Our team examined & verified the machines and utilities from the FAR provided by the Company. Only machinery, process line & equipment has been verified. d. Photographs have also been taken of all the Machines and its accessories installed there. e. Plant was found operational at the time of survey. f. Details have been cross checked as per the documents provided to us by the company and what was obset the site. Condition of the machines is checked through visual observation only. No technical/ mechanical/ operational has been carried out to ascertain the condition and efficiency of machines. Site Survey has been carried out on the basis of the physical existence of the assets rather than their te expediency.	20		CONTRACTOR			
Water Road/Transport Available Available	20.					
Parameter Surveyed by our Engineering Team on dated 22/08/2023 Burvey Details 21. COMMENT ON AVAILABILITY OF LABOUR Availability Appears to be easily & adequately available and no labour came to our knowledge during site inspection. Number of Labours working in the Factory ~100 22. SALES TRANSACTIONAL PROSPECTS OF SUCH PLANTS/ MACHINERY On-going concern basis Reason: This is a Mid scale Plant and all are general used machines which can be used in similar indust cost of dismantling and transporation will not be very high. So for fetching maximum value is through strate to the players who are already into same or similar Industry who have plans for expansion or an conglomefrate who plans to enter into this new Industry 23. DEMAND OF SUCH PLANT & MACHINERY IN THE MARKET Appears to be good as per general information available in public domain. 24. SURVEY DETAILS a. Plant has been surveyed by our Engineering Team on dated 22/08/2023 b. Site inspection was done in the presence of Owner's representatives Mr. Sarevanan & Mr. Bhaskar who we available from the company to furnish any specific detail about the Plant & Machinery. c. Our team examined & verified the machines and utilities from the FAR provided by the Company. Only machinery, process line & equipment has been verified. d. Photographs have also been taken of all the Machines and its accessories installed there. e. Plant was found operational at the time of survey. Details have been cross checked as per the documents provided to us by the company and what was obset the site. g. Condition of the machines is checked through visual observation only. No technical/ mechanical/ operational has been carried out to ascertain the condition and efficiency of machines. h. Site Survey has been carried out on the basis of the physical existence of the assets rather than their texpediency.		*				
21. COMMENT ON AVAILABILITY OF LABOUR Availability Appears to be easily & adequately available and no labour came to our knowledge during site inspection. Number of Labours working in the Factory ~100 22. SALES TRANSACTIONAL PROSPECTS OF SUCH PLANTS/ MACHINERY On-going concern basis Reason: This is a Mid scale Plant and all are general used machines which can be used in similar indust cost of dismantling and transporation will not be very high. So for fetching maximum value is through strate to the players who are already into same or similar Industry who have plans for expansion or an conglomefrate who plans to enter into this new Industry 23. DEMAND OF SUCH PLANT & MACHINERY IN THE MARKET Appears to be good as per general information available in public domain. 24. SURVEY DETAILS a. Plant has been surveyed by our Engineering Team on dated 22/08/2023 b. Site inspection was done in the presence of Owner's representatives Mr. Sarevanan & Mr. Bhaskar who we available from the company to furnish any specific detail about the Plant & Machinery. c. Our team examined & verified the machines and utilities from the FAR provided by the Company. Only machinery, process line & equipment has been verified. d. Photographs have also been taken of all the Machines and its accessories installed there. Plant was found operational at the time of survey. f. Details have been cross checked as per the documents provided to us by the company and what was obset the site. g. Condition of the machines is checked through visual observation only. No technical/ mechanical/ operational has been carried out to ascertain the condition and efficiency of machines. Site Survey has been carried out on the basis of the physical existence of the assets rather than their texpediency.		Road/ Transport	0.5000000000000000000000000000000000000			
Availability Appears to be easily & adequately available and no labour came to our knowledge during site inspection. Number of Labours working in the Factory 22. SALES TRANSACTIONAL PROSPECTS OF SUCH PLANTS/ MACHINERY On-going concern basis Reason: This is a Mid scale Plant and all are general used machines which can be used in similar industry cost of dismantling and transporation will not be very high. So for fetching maximum value is through strate to the players who are already into same or similar Industry who have plans for expansion or an conglomefrate who plans to enter into this new Industry 23. DEMAND OF SUCH PLANT & MACHINERY IN THE MARKET Appears to be good as per general information available in public domain. 24. SURVEY DETAILS a. Plant has been surveyed by our Engineering Team on dated 22/08/2023 b. Site inspection was done in the presence of Owner's representatives Mr. Sarevanan & Mr. Bhaskar who we available from the company to furnish any specific detail about the Plant & Machinery. c. Our team examined & verified the machines and utilities from the FAR provided by the Company. Only machinery, process line & equipment has been verified. d. Photographs have also been taken of all the Machines and its accessories installed there. e. Plant was found operational at the time of survey. Details have been cross checked as per the documents provided to us by the company and what was obset the site. C. Condition of the machines is checked through visual observation only. No technical/ mechanical/ operational has been carried out to ascertain the condition and efficiency of machines. h. Site Survey has been carried out on the basis of the physical existence of the assets rather than their te expediency.	21.	COMMENT ON AVAILABILITY OF LAB	BOUR			
came to our knowledge during site inspection. Number of Labours working in the Factory ~100 22. SALES TRANSACTIONAL PROSPECTS OF SUCH PLANTS/ MACHINERY On-going concern basis Reason: This is a Mid scale Plant and all are general used machines which can be used in similar indus cost of dismantling and transporation will not be very high. So for fetching maximum value is through strate to the players who are already into same or similar Industry who have plans for expansion or an conglomefrate who plans to enter into this new Industry 23. DEMAND OF SUCH PLANT & MACHINERY IN THE MARKET Appears to be good as per general information available in public domain. 24. SURVEY DETAILS a. Plant has been surveyed by our Engineering Team on dated 22/08/2023 b. Site inspection was done in the presence of Owner's representatives Mr. Sarevanan & Mr. Bhaskar who we available from the company to furnish any specific detail about the Plant & Machinery. c. Our team examined & verified the machines and utilities from the FAR provided by the Company. Only machinery, process line & equipment has been verified. d. Photographs have also been taken of all the Machines and its accessories installed there. e. Plant was found operational at the time of survey. f. Details have been cross checked as per the documents provided to us by the company and what was obset the site. g. Condition of the machines is checked through visual observation only. No technical/ mechanical/ operational has been carried out to ascertain the condition and efficiency of machines. h. Site Survey has been carried out on the basis of the physical existence of the assets rather than their te expediency.		Availability	Appears to be easily & adequately available and no labour issue			
22. SALES TRANSACTIONAL PROSPECTS OF SUCH PLANTS/ MACHINERY On-going concern basis Reason: This is a Mid scale Plant and all are general used machines which can be used in similar indust cost of dismantling and transporation will not be very high. So for fetching maximum value is through strate to the players who are already into same or similar Industry who have plans for expansion or an conglomefrate who plans to enter into this new Industry 23. DEMAND OF SUCH PLANT & MACHINERY IN THE MARKET Appears to be good as per general information available in public domain. 24. SURVEY DETAILS a. Plant has been surveyed by our Engineering Team on dated 22/08/2023 b. Site inspection was done in the presence of Owner's representatives Mr. Sarevanan & Mr. Bhaskar who we available from the company to furnish any specific detail about the Plant & Machinery. c. Our team examined & verified the machines and utilities from the FAR provided by the Company. Only machinery, process line & equipment has been verified. d. Photographs have also been taken of all the Machines and its accessories installed there. e. Plant was found operational at the time of survey. f. Details have been cross checked as per the documents provided to us by the company and what was obset the site. g. Condition of the machines is checked through visual observation only. No technical/ mechanical/ operational has been carried out to ascertain the condition and efficiency of machines. h. Site Survey has been carried out on the basis of the physical existence of the assets rather than their te expediency.			The state of the s			
22. SALES TRANSACTIONAL PROSPECTS OF SUCH PLANTS/ MACHINERY On-going concern basis Reason: This is a Mid scale Plant and all are general used machines which can be used in similar indust cost of dismantling and transporation will not be very high. So for fetching maximum value is through strate to the players who are already into same or similar Industry who have plans for expansion or an conglomefrate who plans to enter into this new Industry 23. DEMAND OF SUCH PLANT & MACHINERY IN THE MARKET Appears to be good as per general information available in public domain. 24. SURVEY DETAILS a. Plant has been surveyed by our Engineering Team on dated 22/08/2023 b. Site inspection was done in the presence of Owner's representatives Mr. Sarevanan & Mr. Bhaskar who we available from the company to furnish any specific detail about the Plant & Machinery. c. Our team examined & verified the machines and utilities from the FAR provided by the Company. Only machinery, process line & equipment has been verified. d. Photographs have also been taken of all the Machines and its accessories installed there. e. Plant was found operational at the time of survey. f. Details have been cross checked as per the documents provided to us by the company and what was obset the site. g. Condition of the machines is checked through visual observation only. No technical/ mechanical/ operational has been carried out to ascertain the condition and efficiency of machines. h. Site Survey has been carried out on the basis of the physical existence of the assets rather than their te expediency.						
On-going concern basis Reason: This is a Mid scale Plant and all are general used machines which can be used in similar indus cost of dismantling and transporation will not be very high. So for fetching maximum value is through strate to the players who are already into same or similar Industry who have plans for expansion or an conglomefrate who plans to enter into this new Industry 23. DEMAND OF SUCH PLANT & MACHINERY IN THE MARKET Appears to be good as per general information available in public domain. 24. SURVEY DETAILS a. Plant has been surveyed by our Engineering Team on dated 22/08/2023 b. Site inspection was done in the presence of Owner's representatives Mr. Sarevanan & Mr. Bhaskar who we available from the company to furnish any specific detail about the Plant & Machinery. c. Our team examined & verified the machines and utilities from the FAR provided by the Company. Only machinery, process line & equipment has been verified. d. Photographs have also been taken of all the Machines and its accessories installed there. e. Plant was found operational at the time of survey. f. Details have been cross checked as per the documents provided to us by the company and what was obset the site. g. Condition of the machines is checked through visual observation only. No technical/ mechanical/ operational has been carried out to ascertain the condition and efficiency of machines. h. Site Survey has been carried out on the basis of the physical existence of the assets rather than their teexpediency.	The second of th		S OF SLICH DI ANTS/ MACHINEDY			
Reason: This is a Mid scale Plant and all are general used machines which can be used in similar indus cost of dismantling and transporation will not be very high. So for fetching maximum value is through strate to the players who are already into same or similar Industry who have plans for expansion or an conglomefrate who plans to enter into this new Industry 23. DEMAND OF SUCH PLANT & MACHINERY IN THE MARKET Appears to be good as per general information available in public domain. 24. SURVEY DETAILS a. Plant has been surveyed by our Engineering Team on dated 22/08/2023 b. Site inspection was done in the presence of Owner's representatives Mr. Sarevanan & Mr. Bhaskar who we available from the company to furnish any specific detail about the Plant & Machinery. c. Our team examined & verified the machines and utilities from the FAR provided by the Company. Only machinery, process line & equipment has been verified. d. Photographs have also been taken of all the Machines and its accessories installed there. e. Plant was found operational at the time of survey. f. Details have been cross checked as per the documents provided to us by the company and what was obset the site. g. Condition of the machines is checked through visual observation only. No technical/ mechanical/ operational has been carried out to ascertain the condition and efficiency of machines. h. Site Survey has been carried out on the basis of the physical existence of the assets rather than their teexpediency.	22.		S OF SUCH PLANTS/ MACHINERY			
cost of dismantling and transporation will not be very high. So for fetching maximum value is through strate to the players who are already into same or similar Industry who have plans for expansion or an conglomefrate who plans to enter into this new Industry 23. DEMAND OF SUCH PLANT & MACHINERY IN THE MARKET Appears to be good as per general information available in public domain. 24. SURVEY DETAILS a. Plant has been surveyed by our Engineering Team on dated 22/08/2023 b. Site inspection was done in the presence of Owner's representatives Mr. Sarevanan & Mr. Bhaskar who we available from the company to furnish any specific detail about the Plant & Machinery. C. Our team examined & verified the machines and utilities from the FAR provided by the Company. Only machinery, process line & equipment has been verified. d. Photographs have also been taken of all the Machines and its accessories installed there. e. Plant was found operational at the time of survey. f. Details have been cross checked as per the documents provided to us by the company and what was obset the site. g. Condition of the machines is checked through visual observation only. No technical/ mechanical/ operational has been carried out to ascertain the condition and efficiency of machines. h. Site Survey has been carried out on the basis of the physical existence of the assets rather than their teexpediency.						
to the players who are already into same or similar Industry who have plans for expansion or an conglomefrate who plans to enter into this new Industry 23. DEMAND OF SUCH PLANT & MACHINERY IN THE MARKET Appears to be good as per general information available in public domain. 24. SURVEY DETAILS a. Plant has been surveyed by our Engineering Team on dated 22/08/2023 b. Site inspection was done in the presence of Owner's representatives Mr. Sarevanan & Mr. Bhaskar who we available from the company to furnish any specific detail about the Plant & Machinery. c. Our team examined & verified the machines and utilities from the FAR provided by the Company. Only machinery, process line & equipment has been verified. d. Photographs have also been taken of all the Machines and its accessories installed there. e. Plant was found operational at the time of survey. f. Details have been cross checked as per the documents provided to us by the company and what was obset the site. g. Condition of the machines is checked through visual observation only. No technical/ mechanical/ operational has been carried out to ascertain the condition and efficiency of machines. h. Site Survey has been carried out on the basis of the physical existence of the assets rather than their te expediency.						
23. DEMAND OF SUCH PLANT & MACHINERY IN THE MARKET Appears to be good as per general information available in public domain. 24. SURVEY DETAILS a. Plant has been surveyed by our Engineering Team on dated 22/08/2023 b. Site inspection was done in the presence of Owner's representatives Mr. Sarevanan & Mr. Bhaskar who we available from the company to furnish any specific detail about the Plant & Machinery. c. Our team examined & verified the machines and utilities from the FAR provided by the Company. Only machinery, process line & equipment has been verified. d. Photographs have also been taken of all the Machines and its accessories installed there. e. Plant was found operational at the time of survey. f. Details have been cross checked as per the documents provided to us by the company and what was obset the site. g. Condition of the machines is checked through visual observation only. No technical/ mechanical/ operational has been carried out to ascertain the condition and efficiency of machines. h. Site Survey has been carried out on the basis of the physical existence of the assets rather than their te expediency.						
23. DEMAND OF SUCH PLANT & MACHINERY IN THE MARKET Appears to be good as per general information available in public domain. 24. SURVEY DETAILS a. Plant has been surveyed by our Engineering Team on dated 22/08/2023 b. Site inspection was done in the presence of Owner's representatives Mr. Sarevanan & Mr. Bhaskar who we available from the company to furnish any specific detail about the Plant & Machinery. c. Our team examined & verified the machines and utilities from the FAR provided by the Company. Only machinery, process line & equipment has been verified. d. Photographs have also been taken of all the Machines and its accessories installed there. e. Plant was found operational at the time of survey. f. Details have been cross checked as per the documents provided to us by the company and what was obsethe site. g. Condition of the machines is checked through visual observation only. No technical/ mechanical/ operational has been carried out to ascertain the condition and efficiency of machines. h. Site Survey has been carried out on the basis of the physical existence of the assets rather than their teexpediency.		to the players who are already into same or similar Industry who have plans for expansion or any larg				
Appears to be good as per general information available in public domain. 24. SURVEY DETAILS a. Plant has been surveyed by our Engineering Team on dated 22/08/2023 b. Site inspection was done in the presence of Owner's representatives Mr. Sarevanan & Mr. Bhaskar who we available from the company to furnish any specific detail about the Plant & Machinery. c. Our team examined & verified the machines and utilities from the FAR provided by the Company. Only machinery, process line & equipment has been verified. d. Photographs have also been taken of all the Machines and its accessories installed there. e. Plant was found operational at the time of survey. f. Details have been cross checked as per the documents provided to us by the company and what was obset the site. g. Condition of the machines is checked through visual observation only. No technical/ mechanical/ operational has been carried out to ascertain the condition and efficiency of machines. h. Site Survey has been carried out on the basis of the physical existence of the assets rather than their te expediency.		conglomefrate who plans to enter into this new Industry				
24. SURVEY DETAILS a. Plant has been surveyed by our Engineering Team on dated 22/08/2023 b. Site inspection was done in the presence of Owner's representatives Mr. Sarevanan & Mr. Bhaskar who we available from the company to furnish any specific detail about the Plant & Machinery. c. Our team examined & verified the machines and utilities from the FAR provided by the Company. Only machinery, process line & equipment has been verified. d. Photographs have also been taken of all the Machines and its accessories installed there. e. Plant was found operational at the time of survey. f. Details have been cross checked as per the documents provided to us by the company and what was obset the site. g. Condition of the machines is checked through visual observation only. No technical/ mechanical/ operational has been carried out to ascertain the condition and efficiency of machines. h. Site Survey has been carried out on the basis of the physical existence of the assets rather than their te expediency.	23.	DEMAND OF SUCH PLANT & MACHINERY IN THE MARKET				
 a. Plant has been surveyed by our Engineering Team on dated 22/08/2023 b. Site inspection was done in the presence of Owner's representatives Mr. Sarevanan & Mr. Bhaskar who we available from the company to furnish any specific detail about the Plant & Machinery. c. Our team examined & verified the machines and utilities from the FAR provided by the Company. Only machinery, process line & equipment has been verified. d. Photographs have also been taken of all the Machines and its accessories installed there. e. Plant was found operational at the time of survey. f. Details have been cross checked as per the documents provided to us by the company and what was obset the site. g. Condition of the machines is checked through visual observation only. No technical/ mechanical/ operational has been carried out to ascertain the condition and efficiency of machines. h. Site Survey has been carried out on the basis of the physical existence of the assets rather than their teexpediency. 		Appears to be good as per general information available in public domain.				
 b. Site inspection was done in the presence of Owner's representatives Mr. Sarevanan & Mr. Bhaskar who we available from the company to furnish any specific detail about the Plant & Machinery. c. Our team examined & verified the machines and utilities from the FAR provided by the Company. Only machinery, process line & equipment has been verified. d. Photographs have also been taken of all the Machines and its accessories installed there. e. Plant was found operational at the time of survey. f. Details have been cross checked as per the documents provided to us by the company and what was obsethe site. g. Condition of the machines is checked through visual observation only. No technical/ mechanical/ operational has been carried out to ascertain the condition and efficiency of machines. h. Site Survey has been carried out on the basis of the physical existence of the assets rather than their te expediency. 	24.	SURVEY DETAILS				
 b. Site inspection was done in the presence of Owner's representatives Mr. Sarevanan & Mr. Bhaskar who we available from the company to furnish any specific detail about the Plant & Machinery. c. Our team examined & verified the machines and utilities from the FAR provided by the Company. Only machinery, process line & equipment has been verified. d. Photographs have also been taken of all the Machines and its accessories installed there. e. Plant was found operational at the time of survey. f. Details have been cross checked as per the documents provided to us by the company and what was obsethe site. g. Condition of the machines is checked through visual observation only. No technical/ mechanical/ operational has been carried out to ascertain the condition and efficiency of machines. h. Site Survey has been carried out on the basis of the physical existence of the assets rather than their te expediency. 	a.	Plant has been surveyed by our Engineering	Team on dated 22/08/2023			
available from the company to furnish any specific detail about the Plant & Machinery. C. Our team examined & verified the machines and utilities from the FAR provided by the Company. Only machinery, process line & equipment has been verified. d. Photographs have also been taken of all the Machines and its accessories installed there. e. Plant was found operational at the time of survey. f. Details have been cross checked as per the documents provided to us by the company and what was obset the site. g. Condition of the machines is checked through visual observation only. No technical/ mechanical/ operational has been carried out to ascertain the condition and efficiency of machines. h. Site Survey has been carried out on the basis of the physical existence of the assets rather than their te expediency.	b.	Site inspection was done in the presence of C	Owner's representatives Mr. Sarevanan & Mr. Bhaskar who were			
d. Photographs have also been taken of all the Machines and its accessories installed there. e. Plant was found operational at the time of survey. f. Details have been cross checked as per the documents provided to us by the company and what was obse the site. g. Condition of the machines is checked through visual observation only. No technical/ mechanical/ operational has been carried out to ascertain the condition and efficiency of machines. h. Site Survey has been carried out on the basis of the physical existence of the assets rather than their te expediency.		available from the company to furnish any spe	ecific detail about the Plant & Machinery.			
 d. Photographs have also been taken of all the Machines and its accessories installed there. e. Plant was found operational at the time of survey. f. Details have been cross checked as per the documents provided to us by the company and what was obset the site. g. Condition of the machines is checked through visual observation only. No technical/ mechanical/ operational has been carried out to ascertain the condition and efficiency of machines. h. Site Survey has been carried out on the basis of the physical existence of the assets rather than their te expediency. 	c.	Our team examined & verified the machines	s and utilities from the FAR provided by the Company. Only major			
 e. Plant was found operational at the time of survey. f. Details have been cross checked as per the documents provided to us by the company and what was obsethe site. g. Condition of the machines is checked through visual observation only. No technical/ mechanical/ operational has been carried out to ascertain the condition and efficiency of machines. h. Site Survey has been carried out on the basis of the physical existence of the assets rather than their te expediency. 	J		The state of the s			
 f. Details have been cross checked as per the documents provided to us by the company and what was obse the site. g. Condition of the machines is checked through visual observation only. No technical/ mechanical/ operational has been carried out to ascertain the condition and efficiency of machines. h. Site Survey has been carried out on the basis of the physical existence of the assets rather than their te expediency. 						
g. Condition of the machines is checked through visual observation only. No technical/ mechanical/ operational has been carried out to ascertain the condition and efficiency of machines. h. Site Survey has been carried out on the basis of the physical existence of the assets rather than their te expediency.	-51-					
 g. Condition of the machines is checked through visual observation only. No technical/ mechanical/ operational has been carried out to ascertain the condition and efficiency of machines. h. Site Survey has been carried out on the basis of the physical existence of the assets rather than their te expediency. 	1.	betails have been cross checked as per the d the site.	documents provided to us by the company and what was observed a			
has been carried out to ascertain the condition and efficiency of machines. h. Site Survey has been carried out on the basis of the physical existence of the assets rather than their te expediency.	g.	V0.F1 50 (\$E. 6.00.60) (3)	visual observation only. No technical/ mechanical/ operational testing			
h. Site Survey has been carried out on the basis of the physical existence of the assets rather than their te expediency.		has been carried out to ascertain the condition	n and efficiency of machines.			
	h.	Site Survey has been carried out on the basi	is of the physical existence of the assets rather than their technical			
The post and overall site visit summary, Flant appeared to be in good condition.	i.		opeared to be in good condition			
* PI	5.00	The politic of ordinal site visit summary, Flam ap				

Valuation TOR is available at www.rkassocia es.org



integrating Valuation Life Cycle -A product of R.K. Associates www.valuationintelligentsystem.com

VALUATION ASSESSMENT M/S. SHALIMAR PAINTS LIMITED



PART F

PROCEDURE OF VALUATION ASSESMENT - PLANT & MACHINERY

1.		GENERAL INF	ORMATION						
i.	Important Dates	Date of Inspection of the Property							
1271 5700		22 August 2023	28 August 2023	28 August 2023					
ii.	Client	State Bank of India, IFB Bra	nch, Mumbai						
iii.	Intended User	State Bank of India, IFB Bra	State Bank of India, IFB Branch, Mumbai						
iv.	Intended Use	To know the general idea o market transaction. This report criteria, and considerations of		ny other internal mechanism					
v.	Purpose of Valuation		For Periodic Re-valuation of the mortgaged property						
vi.	Scope of the Assessment		Non binding opinion on the assessment of Plain Physical Asset Valuation of the property identified to us by the owner or through his representative.						
vii.	Restrictions	This report should not be re any other date other then as	ferred for any other purpose	e, by any other user and fo					
viii.	Identification of the Assets	Cross checked from the name of the machines mentioned in the FAR Inventory list name plate displayed on the machine							
		Identified by the company's representative							
		☐ Identified from the available Invoices							
		Identification of the machines could not be done properly							
		Due to large number of machines/ inventories, only major production lines a machines have been checked							
		Physical inspection of the machines could not be done							
ix.	Type of Survey conducted	Full survey (inside-out with v	erification & photographs)						

2.		ASSES	SMENT	FACTORS			
i.	Nature of the Valuation	Fixed Assets Valuation	on				
ii.	Nature/ Category/ Type/	Nature		Cate	gory	Type	
	Classification of Asset under Valuation	PLANT & MACHINERY				INDUSTRIAL PLANT & MACHINERY	
		Classification	1	Income/ Reve	nue Generating	Asset	
iii.	Type of Valuation (Basis of	Primary Basis	Fair N	Market Value &	Govt. Guideline	Value	
	Valuation as per IVS)	Secondary Basis On-goi			On-going concern basis		
iv.	Present market state of the	Under Normal Marketable State					
land, reconst	Asset assumed (Premise of Value as per IVS)	Reason: Asset under	free ma	n state			
v.	Physical Infrastructure availability factors of the locality	Water Supply	Sa	ewerage/ anitation system	Electricit	y Road and Public Transport connectivity	
		Yes from municipal connection	Un	derground	Yes	Easily available	
		Availability of other public utilities nearby		lic utilities	Availability of communication		
		Transport, Market available in d				Service Servic	





id's first fully digital Automated Platform for Integrating Valuation Life Cycle -A product of R.K. Associates www.valuationintelligentsystem.com

vi.	Neighborhood amenities	Good			
vii.	Any New Development in surrounding area	None	NA		
viii.	Any specific advantage/ drawback in the plant and machines	No such specific advantage			
ix.	Machines overall usability/ utility Factor	Normal			
X.	Best Sale procedure to realize maximum Value (in respect to Present market state or premise of the Asset as per point (iv) above)	Fair Market Value Free market transaction at arm's length wherein the parties, after full market surve each acted knowledgeably, prudently and without any compulsion.			
xi.	Hypothetical Sale transaction method assumed for the computation of valuation		at arm's length v	rket Value wherein the parties, after full market survey lently and without any compulsion.	
xii.	Approach & Method of	Approach of Va	luation	Method of Valuation	
	Valuation Used	Cost Approa	ach	Depreciated Replacement Cost Method	
xiii.	Type of Source of Information	Level 3 Input (Tertiary)			

Any other aspect which has relevance on the value or marketability of the machines The marketability for the machines depends upon the industry outlook, make, market condition, raw material, maintenance, raw material, usability, capacity. This Valuation report is prepared based on the facts of the assets & market situation on the date of the survey. It is a well-known fact that the market value of any asset varies with time & socio-economic conditions prevailing in the region/ country. In future assets market may go down, asset conditions may change or may go worse, plant vicinity conditions may go down or become worse, plant market may change due to impact of Govt. policies or effect of domestic/ world economy, usability prospects of the Plant may change, etc. Hence before financing, Banker/ FI should take into consideration all such future risk while financing.

xv. Basis of computation & working

Main Basis:

- a. Basic Methodology: For arriving at fair market value of P&M & other fixed assets our engineering team has rationally applied the mixture of 'sales comparison approach (market approach)' and the 'cost approach (depreciated replacement cost)'. The fair market value of Plant & Machinery on the date of valuation is its cost of reproduction & commissioning on that date less the depreciation & other deterioration deductions (Technological, Economic, Functional obsolescence) or additions for good maintenance from the date of commissioning of the machinery to the date of its valuation.
- b. Core P&M Asset Valuation is done keeping in mind various factors like technology used, machines availability, its condition, average age, maintenance & service and parts replacement availability of the machines and more importantly demand in the market.
- c. Main Machinery of this Plant are specific purpose machines.
- d. The main data point for the Valuation of Plant & Machinery is the Fixed Asset Register maintained by the company. Plant & Machinery FAR has been provided by the company which has been relied upon in good faith. Provided FAR included assets in different heads like Land, Building, Plant & Machinery, Electrical equipments, Furniture & fittings, Office equipment, etc. Assets under different heads are segregated and are evaluated separately. From the Fixed Asset Register List two key inputs, Date of Capitalization and Cost of capitalization are taken which play vital role in evaluating used Plant & Machinery valuation.

e. Provided Capitalization cost in FAR doesn't include any kind of soft cost like pre-operative, home IDC expenses, etc. incurred during establishment of the Project.

W





World's first fully digital Automated Platform for Integrating Valuation Life Cycle -A product of R.K. Associates www.valuationintelligentsystem.com

f. For calculating Replacement Cost of the machines as on date, Whole Sale Price Index (WPI) is used issued by Department Economic Advisor, Govt. of India.

g. For evaluating depreciation, Chart of Companies Act-2013, Central Electricity Commission Guidelines & Industry & institutional standards are used for ascertaining useful life of different types of machines are followed.

h. Market & Industry scenario is also explored for demand of such Plants.

- i. On the Depreciated Replacement Cost (DRC) deduction for obsolescence/ deterioration or addition for good maintenance has been taken to arrive at the estimated Prospective Fair Market Value of the machines.
- j. Underline assumption for the evaluation of this Plant & Machinery is that it will be sold as an Integrated Plant and not as discrete/ piecemeal machinery basis.
- k. Valuation of the asset is done as found on as-is-where basis on the site as identified to us by client/ owner/ owner representative during site inspection by our engineer/s unless otherwise mentioned in the report.
- I. The valuation of the Plant/ Machinery has been done considering the plant as a whole. The indivisual cost for machines shown is for illustration purpose, and may vary from market rates since the valuation is done using cost approach method and finally cross verified from market approach as a whole plant and not individual machine.
- m. Consolidated valuation sheet of Plant & Machinery and other asset items are mentioned below with depreciated current market value as per different category of the machines/assets cumulated together. Our engineering team has separated the Cost of Equipment's in the different sections of the plant. The cost of equipment considered from P&M List doesn't includes Pre-operative, Finance, and IDC Charges etc. The capitalized/ purchase cost of machinery considered from P&M List consists of final commissioning of machines which includes freight, taxes, insurance, etc.

Other Basis:

- n. Analysis and conclusions adopted in the report are limited to the reported assumptions, conditions and information came to our knowledge during the course of the work and based on the Standard Operating Procedures, Best Practices, Caveats, Limitations, Conditions, Remarks, Important Notes, Valuation TOR and definition of different nature of values.
- o. The indicative value has been suggested based on the prevailing market rates that came to our knowledge during secondary & tertiary market research and is not split into formal & informal payment arrangements. Most of the deals takes place which includes both formal & informal payment components. Deals which take place in complete formal payment component may realize relatively less actual transaction value due to inherent added tax, stamp registration liabilities on the buyer.
- p. Secondary/ Tertiary costs related to asset transaction like Installation, maintenance and Logistics costs pertaining to the sale/ purchase of the assets are not considered separately while assessing the indicative estimated Market Value and is assumed to be included in the Cost of capitalization provided by the client.
- q. The condition assessment and the estimation of the residual economic life of the machinery and assets are only based on the visual observations and appearance found during the site survey. We have not carried out any physical tests to assess the working and efficiency of the machines and assets.
- r. Any kind of unpaid statutory, utilities, lease, interest or any other pecuniary dues on the asset or on its owners has not been factored in the Valuation.
- s. Valuation is done for the asset found on as-is-where basis which owner/ owner representative/ client/ bank has shown to us on site of which some reference has been taken from the information/ data given in the copy of documents provided to us which have been relied upon in good faith and we have assumed that it to be true and correct.
- t. This is just the fixed asset valuation of the project based on the cost & market approach methodologies considering the utility of the asset for the business & the company as on-ongoing concern basis. This Valuation shall not be construed as the transactional value of the Project which may be determined through Enterprise/ Business Valuation based on Income approach methodologies

xvi. ASSUMPTIONS

- u. Documents/ Information/ Data provided by the client/ property owner or his representative both writter & verbally is true and correct without any fabrication and has been relied upon in good faith.
- v. The assets and interests therein have been valued free and clear of any liens or encumbrances unless stated otherwise. No hidden or apparent conditions regarding the subject assets or their ownership are assumed to exist. No opinion of title is rendered in this report and a good title is assumed unless stated otherwise.
- w. It is assumed that the concerned Lender/ Financial Institution has asked for the valuation of that property after





Integrating Valuation Life Cycle -A product of R.K. Associates www.valuationintelligentsystem.com

satisfying the authenticity of the documents given to us and for which the legal verification has been already taken
and cleared by the competent Advocate before requesting for the Valuation report. If We assume no responsibility
for the legal matters including, but not limited to, legal or title concerns.

x. Payment condition during transaction in the Valuation has been considered on all cash basis which includes both formal & informal payment components as per market trend.

y. Sale transaction method of the asset is assumed as Free market transaction without any compulsion unless otherwise mentioned while assessing Indicative & Estimated Fair Prospective Market Value of the asset unless otherwise stated.
SPECIAL ASSUMPTIONS
None
LIMITATIONS
None

	VALUATION SUMMARY PLANT & MACHINERY & OTHER EQUIPMENTS								
S.No.	Particulars	Total Acquisition Cost (INR)	Book Value (INR)	Gross Current Replacement Cost (INR)	Fair Market				
1	Plant & Machinery and other equipments	23,96,43,203	12,13,57,462	28,39,81,077	19,59,10,422				

Notes:

- Asset like Plant & Machinery and other related equipments pertaining to M/s. Shalimar Paints Limited located at No. 19, Chinna Puliyur Village, Gummidipundi Taluk, Thiruvallur District, Tamil Nadu, are considered in this section of valuation report.
- 2. For evaluating useful life of assets, chart of Companies Act-2013 and generally accepted market standards are referred in this assessment to reach the final economical life of a particular asset.
- 3. During the site visit conducted by our engineering team on 17/08/2023, the plant was physically inspected by our team. Different sections set up inside the plant were visually inspected. As per the information available in the public domain, such industries have a useful life of ~20 years.
- 4. Rate of Inflation has been assessed with the help of price indices of commodities. Price indices have been referred from the Office of Economic Advisor (Government of India). Further Inflation in respective commodity has been evaluated and applied to the respective capitalization cost to reach its Gross Current Reproduction Cost.
- 5. Final valuation includes design, erection, procurement, installation & commissioning charges as well.
- 6. Only those assets / equipments have been considered which have been physically inspected at the time of site survey.
- 7. The plant was operational at the time of site inspection.

Salabase Lechno Engineer Annual Lines Annual





Integrating Valuation Life Cycle A product of R.K. Associates
www.valuationintelligentsystem.com

6.	CONSOLIDATED VALUATION ASSESSMENT OF THE ASSET			
S. No.	Particulars	Govt. Circle/ Guideline Value	Indicative & Estimated Prospective Fair Market Value	
1.	Land Value (A)	Rs.80,01,000/-	Rs.10,97,91,500/-	
2.	Total Building & Civil Works (B)		Rs.24,15,75,404/-	
3.	Additional Aesthetic Works Value (C)		Rs.80,00,000/-	
4.	Plant & Machinery Value (D)		Rs.19,59,10,422/-	
5.	Total Add (A+B+C+D)	Rs.80,01,000/- (Land Value Only)	Rs.55,52,77,326/-	
6.	Additional Premium if any		; === X	
о.	Details/ Justification			
7.	Deductions charged if any			
7.	Details/ Justification			
8.	Total Indicative & Estimated Prospective Fair Market Value		Rs.55,52,77,326/-	
9.	Rounded Off		Rs.55,53,00,000/-	
10.	Indicative & Estimated Prospective Fair Market Value in words		Rupees Fifty-Five Crore Fifty- Three Lakh Only	
11.	Expected Realizable Value (@ ~15% less)		Rs.47,20,05,000/-	
12.	Expected Distress Sale Value (@ ~25% less)		Rs.41,64,75,000/-	
13.	Percentage difference between Circle Rate and Fair Market Value	More than 20%		
14	Concluding Comments/ Disclosures in	ente/ Disclosuros if any		

14. Concluding Comments/ Disclosures if any

- a. We are independent of client/ company and do not have any direct/ indirect interest in the property.
- b. This valuation has been conducted by R.K Associates Valuers & Techno Engineering Consultants (P) Ltd. and its team of experts.
- c. This Valuation is done for the property found on as-is-where basis as shown on the site by the Bank/ customer of which photographs is also attached with the report.
- d. Reference of the property is also taken from the copies of the documents/ information which interested organization or customer could provide to us out of the standard checklist of documents sought from them and further based on our assumptions and limiting conditions. All such information provided to us has been relied upon in good faith and we have assumed that it is true and correct. However, we do not vouch the absolute correctness of the property identification, exact address, physical conditions, etc. based on the documents provided to us since property shown to us may differ on site Vs as mentioned in the documents or incorrect/ fabricated documents may have been provided to us.
- e. Legal aspects for eg. investigation of title, ownership rights, lien, charge, mortgage, lease, verification of documents from originals or from any Govt. department, etc. has to be taken care by legal experts/ Advocates and same has not been done at our end.
- f. The valuation of an asset is an estimate of the worth of that asset which is arrived at by the Valuer in his expert opinion after factoring in multiple parameters and externalities. This may not be the actual price of that asset and the market may discover a different price for that asset.
- g. This report only contains opinion based on technical & market information which dame to our knowledge during the course of the assignment. It doesn't contain any recommendations.
- h. This report is prepared following our Standard Operating Procedures & Best Practices and will be subject to Limitations, Conditions, Valuer's Remarks, Important Notes, Valuation TOS and basis of computation & working as described above.

FILE NO.: VIS(2023-24)-PL223-Q037-193-277

Page 28 of 57





rld's first fully digital Automated Platform for Integrating Valuation Life Cycle -A product of R.K. Associates www.valuationintelligentsystem.com

> i. The use of this report will become valid only after payment of full fees as per the Payment Terms. Using this report or any part content created in this report without payment of charges will be seen as misuse and unauthorized use of the report.

15. IMPORTANT KEY DEFINITIONS

Fair Value suggested by the competent Valuer is that prospective estimated amount in his expert & prudent opinion of the subject asset/ property without any prejudice after he has carefully & exhaustively evaluated the facts & information came in front of him or which he could reasonably collect during the course of the assessment related to the subject asset on an as-is, where-is basis in its existing conditions, with all its existing advantages & disadvantages and its potential possibilities which is just & equitable at which the subject asset/ property should be exchanged between a willing buyer and willing seller at an arm's length transaction in an open & unrestricted market, in an orderly transaction after proper marketing, wherein the parties, each acted knowledgeably, prudently without any compulsion on the date of the Valuation.

Fair Value without using the term "Market" in it describes that the value suggested by the Valuer may not mandatorily follow or may not be in complete consonance to the established Market in his expert opinion. It may or may not follow market dynamics. But if the suggested value by the valuer is not within the prevailing Market range or is assessed for an asset is located in an un-established Market then the valuer will give reasonable justification & reasoning that for what reasons the value suggested by him doesn't follow the prevailing market dynamics.

Fair Market Value suggested by the competent Valuer is that prospective estimated amount in his expert & prudent opinion of the subject asset/ property without any prejudice in consonance to the Market dynamics after he has carefully & exhaustively evaluated the facts & information came in front of him or which he could reasonably collect during the course of assessment related to the subject asset on an as-is, where-is basis in its existing conditions, with all its existing advantages & disadvantages and its potential possibilities which is just & equitable at which the subject asset/ property should be exchanged between a willing buyer and willing seller at an arm's length transaction in an open & unrestricted market, in an orderly transaction after proper marketing, wherein the parties, each acted knowledgeably, prudently without any compulsion on the date of the Valuation. Here the words "in consonance to the established Market" means that the Valuer will give opinion within the realms & dynamics of the prevailing market rates after exhaustively doing the micro market research. However due to the element of "Fair" in it, valuer will always look for the factors if the value should be better than the market realms which is just & equitable backed by strong justification and reasoning.

Market Value suggested by the competent Valuer is that prospective estimated amount which is average price of the similar comparable assets prevailing in an open & established market during the near period of the date of valuation at which the subject asset/ property should be exchanged between a willing buyer and willing seller on an as-is, where-is basis in its existing conditions, with all its existing advantages & disadvantages and its potential possibilities at an arm's length transaction in an open, established & unrestricted market, in an orderly transaction, wherein the parties, each acted without any compulsion on the date of the Valuation.

Using the term "Market Value" without "Fair" omits the elements of proper marketing, acting knowledgeably & prudently.

Market and market participants can be sentimental, inclined towards the transaction without the element of complete knowledge & prudence about facts or due diligence of the asset therefore "each acted knowledgeably, prudently" has been removed from the marker Value definition.

Realizable Value is that minimum prospective estimated value of the asset/ property which it may be able to fetch at the time of actual property transaction factoring in the element of discount due to the prospects of deep negotiations between the buyer & seller when the parties in-principally find Fair Market Value reasonable and sits together to close the deal and the transaction across the table. Discount percentage on the Fair Market Value due to negotiation will depend on the nature, size, various salability prospects of the subject asset, the needs of the buyer & the seller and kind of payment terms. In some of the cases Realizable and Fair Market Value may also be equal.

Distress Sale Value* is that value when the property is attached with any process such as mortgaged financing, financial or operational dues which is under any stress condition or situation and the stakeholders are under process of finding resolution towards it to save the property from being attached to a formal recovery process. In this type of sale, minimum fetch value assessed will always be less than the estimated fair Market Value where the discount of percentage will depend upon various circumstances and factors such as nature, size, salability prospects of the property and kind of encumbrance on the property. In this type of sale, negotiation power of the buyer is always more than the seller and eagerness & pressure of selling the property will be more on the seller than the buyer.

Liquidation Value is the amount that would be realized when an asset or group of assets are sold due to bring compulsion or constraints such as in a recovery process guided by statute, law or legal process, clearance sale or any such condition or situation thereof where the pressure of selling the asset/ property is very high to realize

M



REINFORCING YOUR BUSINESS ASSOCIATES

VALUERS & TECHNO ENGINEERING CONSULTANTS (P) LTD.

WALLIATION CENTER OF EXCELLENCE

eld's first fully digital Automated Platform for Integrating Valuation Life Cycle -A product of R.K. Associates www.valuationintelligentsystem.com

whatever maximum amount can be from the sale of the assets in a limited time for clearance of dues or due to closure of business. In other words, this kind of value is also called as forced sale value.

Difference between Cost, Price & Value: Generally, these words are used and understood synonymously. However, in reality each of these has a completely different meaning, premise and also having different definitions in professional & legal terms. Therefore, it is our professional responsibility to describe the definitions of these words to avoid ambiguity & confusion in the minds of the user of this report.


The **Cost** of an asset represents the actual amount spend in the construction/ actual creation of the asset. The **Price** is the amount paid for the procurement of the same asset.

The **Value** is defined as the present worth of future rights in the property/ asset and is a hypothetical or notional price that buyers and sellers are most likely to conclude for a good or service. Value is not a fact, but an estimate of the likely price to be paid for a good or service at a given time in accordance with a particular definition of value.

Therefore, in actual for the same asset/ property, cost, price & value remain different since these terms have different usage & meaning.

16. Enclosures with the Report:

- Enclosure: I- Google Map
- Enclosure: II- References on price trend of the similar related properties available on public domain, if available
- Enclosure: III- Photographs of the property
- Enclosure: IV- Copy of Circle Rate
- Enclosure: V- Important property documents exhibit
- Enclosure: VI- SBI Annexure: VI Declaration-Cum-Undertaking
- Enclosure: VII- SBI Annexure: VII Model Code of Conduct for Valuers
- Enclosure: VIII- Part E: Valuer's Important Remarks







IMPORTANT NOTES

<u>DEFECT LIABILITY PERIOD</u> - In case of any query/ issue or escalation you may please contact Incident Manager by writing at valuers@rkassociates.org. We try our level best to ensure maximum accuracy in the Calculations done, Rates adopted and various other data points & information mentioned in the report but still can't rule out typing, human errors, assessment or any other mistakes. In case you find any mistake, variation, discrepancy or inaccuracy in any data point mentioned in the report, please help us by bringing all such points into our notice in writing at <u>valuers@rkassociates.org</u> within 30 days of the report delivery, to get these rectified timely, failing which R.K Associates shouldn't be held responsible for any inaccuracy in any manner. Also, if we do not hear back anything from you within 30 days, we will assume that the report is correct in all respect and no further claim of any sort will be entertained thereafter. We would welcome and appreciate your feedback & suggestions in order to improve our services.

Our **DATA RETENTION POLICY** is of **ONE YEAR**. After this period we remove all the concerned records related to the assignment from our repository. No clarification or query can be answered after this period due to unavailability of the data.

COPYRIGHT FORMAT - This report is prepared on the copyright format of R.K. Associates to serve our clients in the best possible way. Legally no one can copy or distribute this format without prior approval from R.K. Associates. It is meant only for the organization as mentioned on the cover page of this report. Distribution or use of this format or any content of this report wholly or partially other than R.K. Associates will be seen as unlawful act and necessary legal action can be taken against the defaulters.

IF REPORT IS USED FOR BANK/ FIS

NOTE: As per IBA Guidelines in case the valuation report submitted by the valuer is not in order, the banks / Fls shall bring the same to the notice of the valuer within 15 days of submission for rectification and resubmission. In case no such communication is received, it shall be presumed that the valuation report has been accepted.

At our end we have not verified the authenticity of any documents provided to us. Bank is advised to verify the genuineness of the property documents before taking any credit decision.

Valuation Terms of Services & Valuer's Important Remarks are available at www.rkassociates.org for reference.

FOR L&B:

SURVEY ANALYST	VALUATION ENGINEER	L1/ L2 REVIEWER
Manas Upmanyu, Vishal Singh	Manas Upmanyu	Anil Kumar
Sim M	No	

FOR P&M:


SURVEY ANALYST	VALUATION ENGINEER	L1/ L2 REVIEWER
Manas Upmanyu, Vishal Singh	Manas Upmanyu	Abhinav Chaturvedi
wins.	W	Ash.
M	V	







ENCLOSURE: I - GOOGLE MAP LOCATION









ENCLOSURE: II - REFERENCES ON PRICE TREND OF THE SIMILAR RELATED PROPERTIES AVAILABLE ON PUBLIC DOMAIN



Note: No specific price trend references were available on the public domain, however, a reference of residential plot was available and the same has been attached above.









World's first fully digital Automated Platform for Integrating Valuation Life Cycle -A product of R.K. Associates www.valuationintelligentsystem.com

ENCLOSURE: III - PHOTOGRAPHS OF THE PROPERTY



















World's first fully digital Automated Platform for Integrating Valuation Life Cycle -A product of R.K. Associates www.valuationintelligentsystem.com




















World's first fully digital Automated Platform for Integrating Valuation Life Cycle -A product of R.K. Associates www.valuationintelligentsystem.com









World's first fully digital Automated Platform for Integrating Valuation Life Cycle -A product of R.K. Associates www.valuationintelligentsystem.com










www.valuationintelligentsystem.com

VALUATION ASSESSMENT M/S. SHALIMAR PAINTS LIMITED



ENCLOSURE: IV - COPY OF CIRCLE RATE










ld's first fully digital Automated Platform for Integrating Valuation Life Cycle -A product of R.K. Associates www.valuationintelligentsystem.com


ENCLOSURE V: IMPORTANT PROPERTY DOCUMENTS EXHIBIT







orld's first fully digital Automated Platform for Integrating Valuation Life Cycle -A product of R.K. Associates www.valuationintelligentsystem.com







World's first fully digital Automated Platform for Integrating Valuation Life Cycle -A product of R.K. Associates www.valuationintelligentsystem.com

13

The Vendors covenant with the Purchasers that the holding of the Vendors was not affected by any of the provisions of the Agricultural land Ceiling Act or Land Reforms Act or any other statute in force.

The Vendors hereby give consent for mutation of records in the name of the Purchasers in respect of the Schedule. "B" mentioned Agricultural lands with Revenue, Panchavat or all other authorities concerned.

The Vendors represent that the Schedule "B" mentioned Agricultural lands hereby conveyed has always been under their personal cultivation and it never formed part of any tenancy in favour of any Agricultural tenants. The Property State A Force.

The Vendors have this dip placed the Purchasers in vacant possession of the Schedule "B" mentioned Agricultural lands and henceforth the Purchasers may possess and enjoy the same absolutely with full powers of alienation and without any manner of claim, right, title, share, demand, interest, lawful let, hindrance, interruption or interference from the Vendors or any person or persons claiming through the Vendors.

(Total property)

Agricultural lands of an extent of 8 31 Acres, comprised in Survey Nos.

Old Survey No.	New Survey No.	Extent
1/1	1/2A	3.49 Acres out of 4.42 Acres (as per doc. 4.45 Acres)
3 part	3/2	3.32 Acres
9 pert	3/1	1.50 Acres
fotal		8.31 Acres

situated in No.19 Chinna Puliyur Village, Gummidipoondi Taluk, Thiruvallur District, within the Registration Sub-District of Arani and Registration District of North Chennal.

SCHEDULE "B" (Lands hereby conveyed)

A portion of the Schedule "A" mentioned Agricultural Punja lands of an extent of 3.49.

Acres or thereabouts, comprised in Survey Nos.1/1A1 of No.19 Chinna Puliyar Village,

For Shalimar Paints Limited

Executive Director -

DOCUMENT

Proceeds al fale

Director

For Shalimar Paints Limited

Managing Director and CEO

-





www.valuationintelligentsystem.com

VALUATION ASSESSMENT M/S. SHALIMAR PAINTS LIMITED



R.C.No.2522/2017/A1 DATE 19/07/2017

TAHSILDAR OFFICE GUMMUDIPOONDI

CERTIFICATE

This is to certify that M/s.Shalimar Paints Ltd., having the register office at Stainless Center, 4th Floor, Plot No. 50, Sector 32, Gurugram – 122001, is the possessing and enjoying the properties mentioned here under situated at Factory No. 19, Chinnapuliyur village, Satyavedu Road, Sripulalpettal Post, GummudipoondiTaluk, Thiruvallur- District., Pin Code: 601201.

Survey Number	Area of the land	Land Type	Patta Number & Owner of the Patta Number land
15/1A	0.11.5	Dry land	Pattä number .323 Shalimar Paints Ltd
15/18	0.06.5		sta number .323 Shallmar Paints Ltd
15/10	0.05.5		
3/1	0.58.5		
3/2	1.34.5		
1/1A1B	1.41.5	Dry land	Patta number .325 Shalimar Paints Ltd

14717

The Above survey Number

- 1) There is no promboke land merged
- 2) No Proceedings are pending under land acquisition Act 1984 Section 4(1)
- 3) Not coming under the purview of land reforms Act 1961
- 4) There is no building, Temples, mosque and archeologicalmonuments
- 5) There is no high tension wire passing through
- 6) There will not be any flood thread

Note: This certificate is being is sued in order to establish a new industry.

To:

M/s Shalimar Paints Ltd .
No.19, Chinnapuliyur village,
Satyavedu Road, Sripulalpetta
GummudipoondiTaluk
Thiruvallur District

Pin - 601201.

TA Tahsilder DAR







ld's first fully digital Automated Platform fo Integrating Valuation Life Cycle -A product of R.K. Associates www.valuationintelligentsystem.com

> தமிழ்நாடு அரசு தொழிலகப் பாதுகாப்பு மற்றும் சகாதார இயக்ககம்



Government of Tamil Nadu

Directorate of Industrial Safety and Health

Form No.4 - Registration and Licence to work a factory [Prescribed under Rule 4 (6) of the Tamil Nadu Factories Rules 1950]



Registration Number

TVR10071

Licence Fee : ₹ 144,000/-

Licence is hereby granted / renewed to Mr. ASHOK KUMAR GUPTA valid only for the premises detailed below for use as a factory employing not more than 250 workers on any one day during the year and using installed horse power inclusive of mobile equipment not exceeding 5000 horse power subject to the provisions of the Factories Act, 1948 and the Rules made thereunder.

This licence shall remain in force till the 31st day of December 2023 unless such licence is cancelled before that date under rule 109.

Name of the factory : SHALIMAR PAINTS LIMITED

Description of Licensed Premises

The licensed premises shown on Plan No. 12102/2015 dated 18/05/2015 are situated in Survey No.: 1/1A1B, 3/1, 2, 15/1A, 1B, IC, Door No. / Plot No.: NO.19, Satyavedu Road, Sirupzhalpettai Post, CHINNAPULLIYUR VILLAGE, GUMMIDIPOONDI, Gummidipoondi Taluk, Thiruvallur District - 601201.

This License renewal is auto Generated through Portal. Hence no signature required.

Date: 06/12/2022

Joint Director of Industrial Safety and Health - I, Chennai

		Renew	als	
		Amendme	nts	
SLNo.	Amended to Install horse power	Amended to Employ maximum number of workers	Additional fee	Signature of Joint Director
1.				
2.				
		Transfer	5	
SLNo.	Name of the po to whom trans		e of the factory	Signature of Joint Director
1.				
2.			Si .	



FILE NO.: VIS(2023-24)-PL223-Q037-193-277





World's first fully digital Automated Platform for Integrating Valuation Life Cycle -A product of R.K. Associates www.valuationintelligentsystem.com

FIRE LICENCE

Under Section 13 of the Tamil Nadu Fire Service Act No.40 - 1985 and With Tamil Nadu Fire Service Rules 1990-Appendix-111

Licence No.2162/A/2023

Date : 03-2023

Licence is hereby granted under section 13 of the Tamil Nadu Fire Service act 1985 for Manufacturing of Paint & Varnishes and Storage of Solvent (MTO - 52 KL, — Xylene – 52 KL, Butanol – 25 KL, C9 - 25 KL) (Mention whichever is applicable) Within the Jurisdiction of ChinnaPuliyur Municipality / Panchayat / P.Union Township at the Name of Company M/s. Shalimar Paints Ltd., No.19, Chinnapuliyur, Gummidipoondi Taluk, Thiruvallur District. Subject to the conditions noted thereon and such other conditions as may be prescribed (Inspected by Station Officer, Thervoy Kandigai Sipcot on 09-03-2023)

CONDITIONS

As per Tamil Nadu Fire Service Act 1985 Section 13 of Chapter II and appendix V of this Act

- 1. This Licence is Valid for ONE YEAR from the date of Issue.
- 2. Regular Licence has to be obtained from the competent authority.
- Fire & Life Safety Systems / Arrangements have to be provided in accordance with the requirements of NBC Part IV Fire & Life Safety 2016.
- The First Aid Fire Fighting equipments should be maintained at all floors in accordance with the IS 2190:2010 requirements.
- If there is any deviation from the Govt. Rules and Act the Licence issue will be stand cancelled.
- Staffs should be trained in preliminary fire fighting as per G.O.No.713, Home(Police-17) Dated.17-08-2005 with Fire and Rescue Services Department.
- Fire Drill should be conducted once in a six month with the local Fire & Rescue Service authorities and a permanent register should be maintained in part-II.

Office Seal with Date

District Officer
Fire & Rescue Services,
Thiruvallur District,
Thiruvallur.

To. M/s. Shalimar Paints Ltd., No.19, Chinnapuliyur, Gummidipoondi Taluk, Thiruvallur District.





REINFORCING YOUR BUSINESS ASSOCIATES

VALUERS & TECHNO ENGINEERING CONSULTANTS (P) LTD.

WALLATION CENTER OF FIXEL LINES

World's first fully digital Automated Platform for Integrating Valuation Life Cycle -A product of R.K. Associates www.valuationintelligentsystem.com

> प्ररूप XV (प्रथम अनुसूची का अनुबहेद ६ देखिए) FORM XV (see Article 6 of the First Schedule)

अधिष्ठापनों में पेट्रोलियम के आयात और भंडारकरण के लिए अनुवधि LICENCE TO IMPORT AND STORE PETROLEUM IN AN INSTALLATION

अनुवर्धित सं. (Licence No.) : P/HQ/TN/15/5175(P383510)

फीस रूपए (Fee Rs.) 11450:- per year

Mis. Shalimar Paints Ltd... No 19, Chinnapulliyur Village, Satyavedu road, Sirupzhalpettai post... Chinnapulliyur Village, Gummidipoondi, Taluka: Gummidipoondi, District: THIRUVALLUR, State: Tamil Nadu, PIN: 601201 को कवल इसमें पर्था विनिर्दिष्टु वर्ग और माजाओं में पेट्रॉलियम 179.00 KL आयात करने के लिए और उसका, नीचे वर्षित। और अनुमोदित नक्या संख्या PING/TN/15/5175(P383510) तारीख 29/11/2017 जो कि इससे उपाबद्ध हैं. में दिखाए गए स्थान पर भणडारकरण के लिए पेट्रॉलियम ऑप्टिनयम, 1934 के उपबंधों या उसके अचीन बनाए गए नियमों तथा इस अनुमंदित की अतिरिक्त शर्तों के अचीन रहते हुए, यह अनुमंदित अनुदत्त की जाती हैं।

Licence is hereby granted to M/s. Shalimar Paints Ltd... No 19, Chinnapulliyur Village, Satyavedu road, Sirupzhalpettai post, Chinnapulliyur Village, Gummidipoondi, Taluka: Gummidipoondi, District: THIRUVALLUR, State: Tamil Nadu, Plih: 601201 valid only for the importation and storage of 179.00 KL Petroleum of the class and quantities as herein specified and storage thereof in the place described below and shown on the approved plan No PiHQ/TN/15/5175(P383510) dated 29/11/2017 attached hereto subject to the provisions of the Petroleum Act, 1934 and the rule made thereunder and to the further conditions of this Licence.

यह अनुज्ञांदि 31st day of December **2023** तक प्रवृत रहेगी। The Licence shall remain in force till the 31st day of December **2023**

पेट्रोतियम का विवरण /Description of Petroleum	अनुबादा मात्रा (किलोलीटरॉ में) /Quantity licenced in KL	
वर्ग क प्रयुज पेट्रोलियम (Petroleum Class A in bulk	NIL	
वर्ग क प्रपुंज पेट्रोलियम से भिन्न Petroleum Class A, otherwise than in bulk	NIL	
वर्ग ख प्रपुत्र पेट्रोलियम /Petroleum Class B in bulk	154.00 KL	
वर्ग स प्रयुज पेट्रोलियम से भिन्न Petroleum Class B, otherwise than in bulk	25.00 KL	
वर्ग ग प्रयुंज पेट्रोतियम /Petrolcum Class C in bulk	NIL	
वर्ग ग प्रपुज पेट्रोसियम से भिन्न /Petroleum Class C,otherwise than in bulk	NIL	
한편 설립에 /Total Capacity	179.00 KL	

June 22, 2017

For Chief Controller of Explosives HQ, Nagpur

1). Amendment dated - 30/11/2021

अनुज्ञप्त परिसरों का विवरण और अवस्थान DESCRIPTION AND LOCATION OF THE LICENSED PREMISES

अनुजात परिसर जिसकी विन्यास सीमाएं अन्य वि शष्ट्रण संलक्ष अनुमादित नक्षीं में दिशाई गई हैं Survey No: 1/1A, 1B, 3/1, 3/2, 15/1A, 15/1B, 15/1C, -, Chinna Pullyar, Thiruvallur, Taluka: Gummidipoondi, District: THIRUVALLUR, State: Tamil Nadu, PIN: 601201 स्थान पर अवस्थित है तथा उसमें निम्नलिखित 4 Above Ground tank(s) for CLASS B and storage shed for non bulk petroleum समिलित हैं।

The licensed premises, the layout, boundaries and other particulars of which are shown in the attached approved plan are situated at Survey No: 1/1A, 18, 3/1, 3/2, 15/1A, 15/1B, 15/1C, ... Chinna Pulliyar, Thiruvallur, Taluka: Gummidipoondi, District: THIRUVALLUR, State: Tamil Nadu, PIN: 601201 and consists of 4 Above Ground tank(s) for CLASS B and storage shed for non-bulk petroleum together with connected facilities.

Note:-This is system generated document does not require

signature.

Digitily signed by Dr T L THANULINGAM Revisor Literce No. PRIQ:TN15:5175 Location South Circle Office (P383510) Date 01-02-2023 1143:31 AM

Consultary sales





Yorld's first fully digital Automated Platform for Integrating Valuation Life Cycle -A product of R.K. Associates www.valuationintelligentsystem.com

DEPARTMENT OF PUBLIC HEALTH AND PREVENTIVE MEDICINE SANITARY CERTIFICATE

[Issued under the Tamil Nadu Public Health Act 1939 - Act III of 1939]

L.Dis. No. 0806 / E2 / 2023

Date: 15/03/2023

Building premises situated at No. 19, Chinna Puliyoor village, Sathyavedu Road, Sirupuzhal Pettai Post, Gummidipoordi Taluk, Thiruvallur District for the unit of Manufacturing Solvent & Water Based Paints has been inspected on 06.03.2023 and found

- That the accommodation provided for each of the several divisions is sufficient and is properly vents ated and lighted.
- That is neat and clean.
- · That the supply of d inking water is wholesome.
- That the liquid and solid wastages are disposed in a sanitary manner.
- That the sewage discosal pit (Septic Tank) etc. is maintained as per rules.

Conditions:

- 1.All the workers as d visitors should be examined by thermal scanner before enter in the premises.
- 2. All area of the surfaces should be disinfected minimum three times par day
- 3. All the staff and v orkers should wear face mask, hand gloves and should maintain the physical distance not below the distance of 6 feet.
- If anybody found the symptoms of fever, cold, cough and breathing difficulties should be informed to the local health authority.
- The occurrence of any contagious diseases should be informed to the undersigned to take necessary action
- The Establishme it should provide necessary Latrine and Urinal arrangements according to the increasing of the strength of the workers.
- The establishment should vaccinate two doses of covid vaccination to all workers and no visitor should not be allowed inside the premises without vaccinated.

8. This Sanitary Certificate should be valid up to 31.03.2024...

Counter signed :

Deputy Director Health Services, Thiruvallur BLOCK HEALTH SUPERVISOR
Gummidipoondi Block,

Govt. Primary Health Centre, Eguvarpalayam, Thiruvallur District.



FILE NO.: VIS(2023-24)-PL223-Q037-193-277

Page 46 of 57





Yorld's first fully digital Automated Platform for Integrating Valuation Life Cycle -A product of R.K. Associates www.valuationintelligentsystem.com

PROCEEDINGS OF THE DISTRICT MAGISTRATE AND DISTRICT COLLECTOR, TIRUVALLUR DISTRICT

PRESENT: Dr. ALBY JOHN VARGHESE, I.A.S.,

K.Dis. 23355/2022/ S4

Dated: .12.2022.

Sub: Control Orders Raffinate and Slop [Acquisition, Sale Storage & Prevention of use in Automobiles] Order 2000
Tiruvallur District Gummidipoond: Taluk
Chini apulliyur village M/s Shalimar Panats Limited
License Bearing No.02/2018 Renewal for the period from

01.01 2023 to 31 12.2024 Orders Issued

Read 1) Application from M/s. Shalimar Parits Limited, Chinnapulliyur Village. Gummidiporndi Taluk

2) An I Connected reports

4.7.4.4.0

ORDER:

Upon perusing the records cited and above in exercise of powers conferred under Sup clause (i) of the Solvent, Raffinate and Slop (Acquisition, Sale, Storage & Prevention of use in Automobiles) Order 2000, the License bearing No 02/20/8. M/s. Shalimar paints Limited, located at No.19, Chinnapulliyur village, Gummidipoondi Taluk, Tiruvallur District is hereby renewed for 2 years for the period from 01.01.2023 to 31.1.1.2024.

As required under sub-clause(3) of the Solvent Raffinate and Slop (Acquisition, Sale Storage & Prevention of use in Automobiles) Order 2000, the licensee should furnish End-use certificate for every quarter of the calendar year till the next recewal of license.

DISTRICT MAGISTRATE
AND DISTRICT COLLECTOR,
TIRUVALLUR.

To

M. S. Shalamar Paints lamited. No 19, Channapulliyur Village, Sirupulalpettai Post. Gummidipoondi Talu i.









World's first fully digital Automated Platform for Integrating Valuation Life Cycle www.valuationintelligentsystem.com

September 21, 2021 [INSPECTION & CERTIFICATION]

R.SRINIVASAN Competent Person Under Factories Act DISH APPROVAL NO: H1/3491/2021/DT:16.04.2021 No. 18/42, Naga Flat, Nagatthamman Koil Street, West Mambalam, Chennai - 600033

CERTIFICATE OF BUILDING STABILITY [As Per Section 7 (1) Under Rule 12-B (3) & (4) of the Factories Act 1948 & Rules, 1950]

NAME OF THE FACTORY

M/S. SHALIMAR PAINTS LTD

VILLAGE, TOWN & DISTRICT IN WHICH THE FACTORY IS SITUATED

NO.19, CHINNAPULIYUR VILLAGE, SIRUPUZHAL PETTAI POST, GUMMIDIPOOND: TK, THIRUVALLUVAR-DT.

FULL POSTAL ADDRESS OF THE FACTORY

NO.19, CHINNAPULIYUR VILLAGE, SIRUPUZHAL PETTAI

POST, GUMMIDIPOONDI TK, THIRUVALLUVAR-DT.

NAME OF THE OCCUPIER OF THE FACTORY

MR ASHOK KUMAR GUPTA

NATURE OF MANUFACTURING PROCESS TO BE : CARRIED IN THE FACTORY

PAINTS, DISPERSION & MIXING OPERATION

NUMBER OF FLOORS ON WHICH WORKERS WILL BE EMPLOYED

GROUND & FIRST FLOOR ONLY

I CERTIFY THAT I HAVE INSPECTED THE BUILDINGS ON 21.09.2021 IN WHICH M/S. SHALIMAR PAINTS LTD IS HOUSED AND EXAMINED THE VARIOUS PARTS INCLUDING THE FOUNDATIONS AS SHOWN IN COMPLETE PLANS APPROVED BY THE DIRECTOR OF INDUSTRIAL SAFETY & HEALTH, ROYAPETTAI, CHENNAI-600014. IN HIS LETTER NO. R.DIS.NO. (D1)/12102/2015 DATED:18.05.2015 FOR FACTORY LAYOUT WITH SPECIAL REFERENCE TO THE MACHINERY, PLANT ETC. THAT HAVE BEEN INSTALLED.

I AM OF THE OPINION THAT THE CONSTRUCTION HAS BEEN COMPLETED IN ACCORDANCE WITH THE PLANS APPROVED BY THE DIRECTOR OF INDUSTRIAL SAFETY & HEALTH, ROYAPETTAI, CHENNAI-600014. IN HIS LETTER NO. R.DIS.NO. (D1)/12102/2015 DATED:18.05.2015 THAT IT IS STRUCTURALLY SOUND AND THAT IT'S STABILITY WILL NOT BE ENDANGERED BY ITS USE AS A FACTORY FOR THE MANUFACTURER OF "PAINTS, DISPERSION & MIXING OPERATION" FOR WHICH THE MACHINERY, PLANT ETC., INSTALLED ARE INTENDED.

DATE OF INSPECTION: 21.09.2021 NEXT INSPECTION DUE ON: 20.09.2024



Er. R. SRINIVASAN, B.E., COMPETENT PERSON No. H1/3491/2021 Dt. 16-4-2021 Approved by The Director Industrial Safety and Health, Govt. of Tamilnadu Ph: 9444379105

THIS CERTIFICATE IS VALID FOR 3 YEARS FROM THE DATE OF ISSUE SUBJECTED TO MAINTAINING THE BUILDING AS PER THE ACCEPTED STANDARDS, ANY ALTERATIONS/ADDITIONS/DEMOLITIONS OR SHIFTING OF THE EQUIPMENTS TO BE CARRIED OUT WITH THE APPROVAL OF THE FACTORY INSPECTORATE FOLLOWED BY FRESH STABILITY CERTIFICATE





Integrating Valuation Life Cycle
A product of R.K. Associates www.valuationintelligentsystem.com

VALUATION ASSESSMENT

M/S. SHALIMAR PAINTS LIMITED





GOVERNMENT OF TAMIL NADU

DIRECTORATE OF INDUSTRIAL SAFETY AND HEALTH

Chennai- 32.

No.H1/3491/2021

Dated: 16.04.2021

CERTIFICATE OF COMPETENCY ISSUED TO A PERSON

(Under Sub-Rule (3) of Rule 2A)

I, M.V.Senthilkumar, the Director (FAC), Industrial Safety and Health in exercise of the powers conferred on me under Section 2 (ca) of the Factories Act and the rules made there under, hereby recognize THIRU.R.SRINIVASAN, No.18/43, Naga flat, Nagatthamman Koil Street, West Mambalam, Chennal - 600 033. to be the Competent Person for the purpose of carrying out examinations and certification of Stability of buildings used in a factory located in the State of Tamil Nadu under section 6 of the Factories Act, 1948 and the Rules made there under.

This certificate is valid for Three Years from 16.04.2021 to 15.04.2024

This certificate is issued subject to the conditions stipulated hereunder:

- i) Tests, Examinations and Inspections shall be carried out in accordance with the provisions of the Act and Rules made there under.
- Tests, Examinations Inspections shall be carried out under the direct 11) supervision of the competent person.
- The Director, Industrial Safety and Health, Chennal 32 reserves the right to revoke or amend this order at anytime during its validity period in accordance with the provisions under Sub-rule (4) of Rule 2-A of the Tamil Nadu Factories Rules 1950.
- Record of the daily work done by the Competent Person should be maintained in a log book, Incorporating therein the name of the factories, the details of work done, observations made, directions given, etc.,
 - All the test certificates issued by the Competent Person shall contain the latest No. and date of the Certificate of competency issued to a person (or) Institute by this office, along with the validity period of the competency.

The Competent Person shall make an application with all relevant documents for issuance of fresh certificate, if needed 30 days before the expiry of this certificate.

> Director (FAC), Industrial Safety and Health,

Chennal-32

To Thiru.R.Srinivasan, No.18/43, Naga flat, Nagatthamman Koil Street, West Mambalam Chennai - 600 033.

74443 79105

echno Eno



A product of R.K. Associates www.valuationintelligentsystem.com

WALUATION ASSESSMENT M/S. SHALIMAR PAINTS LIMITED



ENCLOSURE VI: ANNEXURE: DECLARATION-CUM-UNDERTAKING

- a Persons worked on this report are citizen of India.
- b No employee or member of R.K Associates has any direct/ indirect interest in the property or become so interested at any time during a period of three years prior to our appointment as valuer or three years after the valuation of assets was conducted by us.
- c The information furnished in our valuation report dated 28/8/2023 is true and correct to the best of our knowledge and belief and we have made an impartial and true valuation of the property.
- d Our authorized Engineer/ surveyors Manas & Vishal have personally inspected the property on 22/8/2023 the work is not subcontracted to any other valuation firm and is carried out by us.
- e We have not been depanelled/ delisted by any other bank and in case any such depanelment by other banks during my empanelment with you, we will inform you within 3 days of such depanelment.
- f We have not been removed/ dismissed from service/employment earlier.
- g We have not been convicted of any offence and sentenced to a term of imprisonment.
- h Company is not found guilty of misconduct in professional capacity.
- i Persons worked on this report are not declared to be unsound mind.
- j Company is not undischarged bankrupt or has not applied to be adjudicated as a bankrupt.
- k Company is not an undischarged insolvent.
- No penalty is levied under section 271J of Income-tax Act, 1961 (43 of 1961) and time limit for filing appeal before Commissioner of Income tax (Appeals) or Income-tax Appellate Tribunal, as the case may be has expired, or such penalty has been confirmed by Income-tax Appellate Tribunal, and five years have not elapsed after levy of such penalty.
- m Company is not been convicted of an offence connected with any proceeding under the Income Tax Act 1961, Wealth Tax Act 1957 or Gift Tax Act 1958 and
- n Our PAN Card number/ GST number as applicable is AAHCR0845G/ 09AAHCR0845G1ZP.
- o We undertake to keep you informed of any events or happenings which would make us ineligible for empanelment as a valuer.
- b We have not concealed or suppressed any material information, facts and records and we have made a complete and full disclosure.
- q We have read the Handbook on Policy, Standards and procedure for Real Estate Valuation, 2009 of the IBA and has tried to apply the "Standards" enshrined for valuation in the Part-B of the above handbook to the best of our ability as much as practically possible in the limited time available.
- r We have read the International Valuation Standards (IVS) and the report submitted to the Bank for the respective asset class and has tried to apply the "Standards" as enshrined for valuation in the IVS in "General Standards" and "Asset Standards" as applicable to the best of our ability as much as practically possible in the limited time available.
- Procedures and standards adopted in carrying out the valuation and is mentioned in Part-D of the report which may have certain departures to the said IBA and IVS standards in order to provide better, just & fair valuation.
- t We abide by the Model Code of Conduct for empanelment of valuer in the Bank.
- The authorized Engineers of the company who has worked on the assignment has signed this valuation report.
- v The work is taken on the instructions of the Bank.
- w Further, we hereby provide the following information.

S. No.	Particulars	Valuer comment
1.	Background information of the asset being valued	This is an industrial property located at aforesaid address having total land area admeasuring 8.31 Acres / 33,629 sq.mtr. as found on as-is-where basis which owner/owner representative/ client/ bank has shown/ identified to us on the site physically unless otherwise mentioned in the report of which some reference has been taken from the information/data given in the copy of documents provided to us and informed verbally or in writing.
2.	Purpose of valuation and appointing authority	Please refer to Part-D of the Report.
		N .



REINFORCING YOUR BUSINESS ASSOCIATES

VALUERS & TECHNO ENGINEERING CONSULTANTS (P) LTD.

VALUETS OF EXCELLENCE

S RS PRACE LEST TR

World's first fully digital Automated Platform for Integrating Valuation Life Cycle -A product of R.K. Associates www.valuationintelligentsystem.com

the valuation Valuation Engi		Survey Analyst: Manas Upm Valuation Engineer: Manas L1/ L2 Reviewer: Anil Kumar	Upmanyu	
4.	Disclosure of valuer interest or conflict, if any	No relationship with the borrower and no conflict of interest.		
5.	Date of appointment, valuation date and date of report	Date of Appointment: Date of Survey: Valuation Date:	1/8/2023 22/8/2023 28/8/2023	
		Date of Report:	28/8/2023	
6.	Inspections and/ or investigations undertaken	Yes, by our authorized Survey Engineers Manas Upmanyu & Vishal Singh on 22/8/2023. Property was shown and identified by Mr. Krishna (2+91-81783 34434).		
7.	Nature and sources of the information used or relied upon	Please refer to Part-D of the I has been relied upon.	Report. Level 3 Input (Tertiary)	
8.	Procedures adopted in carrying out the valuation and valuation standards followed	Please refer to Part-D of the F	Report.	
9.	Restrictions on use of the report, if any	Condition & Situation pre- recommend not to refer prospective Value of the asset these points are different from in the Report. This report has been prepared report and should not be relie Our client is the only authori restricted for the purpose indic take any responsibility for the in During the course of the assivarious information, data, doo by Bank/ client both verbally a time in future it comes to kn given to us is untrue, fabricated of this report at very moment. This report only contains gen the indicative, estimated Mar which Bank has asked to cond as found on as-is-where representative/ client/ bank ha site unless otherwise mention reference has been taken from the copy of documents provid or in writing which has been doesn't contain any other re including but not limited to e suitability or otherwise of ente the borrower. This report is not a certifica number/ property number/ Kha referred from the copy of the of	eral assessment & opinion on the Value of the property for duct the Valuation for the asset basis which owner/ owner is shown/ identified to us on the ed in the report of which some in the information/ data given in ed to us and informed verbally in relied upon in good faith. It ecommendations of any sort express of any opinion on the earing into any transaction with attorn of ownership or survey as a number which are merely documents provided to us.	
10.	Major factors that were taken into account during the valuation	Please refer to Part A, B & C	R Techno Engine	
11.	Major factors that were not taken into account during the valuation	Please refer to Part A, B & C	of the Report.	





World's first fully digital Automated Platform for Integrating Valuation Life Cycle -A product of R.K. Associates www.valuationintelligentsystem.com

12.	Caveats, limitations and disclaimers to the extent they explain or elucidate the limitations faced by valuer, which shall not be for the purpose of limiting his responsibility for the valuation report.	
-----	---	--

Date: 28/8/2023 Place: Noida

(Authorized Person of R.K Associates Valuers & Techno Engg. Consultants (P) Ltd.)

Signatur



www.valuationintelligentsystem.com

VALUATION ASSESSMENT M/S. SHALIMAR PAINTS LIMITED



ENCLOSURE VII: ANNEXURE: MODEL CODE OF CONDUCT FOR VALUERS

Integrity and Fairness

- 1. A valuer shall, in the conduct of his/its business, follow high standards of integrity and fairness in all his/its dealings with his/its clients and other valuers.
- 2. A valuer shall maintain integrity by being honest, straightforward, and forthright in all professional relationships.
- A valuer shall endeavor to ensure that he/it provides true and adequate information and shall not misrepresent any facts or situations.
- A valuer shall refrain from being involved in any action that would bring disrepute to the profession.
- 5. A valuer shall keep public interest foremost while delivering his services.

Professional Competence and Due Care

- 6. A valuer shall render at all times high standards of service, exercise due diligence, ensure proper care and exercise independent professional judgment.
- A valuer shall carry out professional services in accordance with the relevant technical and professional standards that may be specified from time to time.
- 8. A valuer shall continuously maintain professional knowledge and skill to provide competent professional service based on up-to-date developments in practice, prevailing regulations/guidelines and techniques.
- 9. In the preparation of a valuation report, the valuer shall not disclaim liability for his/its expertise or deny his/its duty of care, except to the extent that the assumptions are based on statements of fact provided by the company or its auditors or consultants or information available in public domain and not generated by the valuer.
- 10. A valuer shall not carry out any instruction of the client in so far as they are incompatible with the requirements of integrity, objectivity and independence.
- 11. A valuer shall clearly state to his client the services that he would be competent to provide and the services for which he would be relying on other valuers or professionals or for which the client can have a separate arrangement with other valuers.

Independence and Disclosure of Interest

- 12. A valuer shall act with objectivity in his/its professional dealings by ensuring that his/its decisions are made without the presence of any bias, conflict of interest, coercion, or undue influence of any party, whether directly connected to the valuation assignment or not.
- 13. A valuer shall not take up an assignment if he/it or any of his/its relatives or associates is not independent in terms of association to the company.
- 14. A valuer shall maintain complete independence in his/its professional relationships and shall conduct the valuation independent of external influences.
- 15. A valuer shall wherever necessary disclose to the clients, possible sources of conflicts of duties and interests, while providing unbiased services.
- 16. A valuer shall not deal in securities of any subject company after any time when he/it first becomes aware of the possibility of his/its association with the valuation, and in accordance with the Securities and Exchange Board of India (Prohibition of Insider Trading) Regulations, 2015 or till the time the valuation report becomes public, whichever is earlier.
- A valuer shall not indulge in "mandate snatching or offering" convenience valuations" in order to cater to a company or client's needs.
- 18. As an independent valuer, the valuer shall not charge success fee.
- 19. In any fairness opinion or independent expert opinion submitted by a valuer, if there has been a prior engagement in an unconnected transaction, the valuer shall declare the association with the company during the last five years.

Confidentiality

FILE NO.: VIS(2023-24)-PL223-Q037-193-277 Page 53 of 57



REINFORCING YOUR BUSINESS ASSOCIATES

VALUERS & TECHNO ENGINEERING CONSULTANTS (P) LTD.

WALLARDIN CENTER OF EXCELLENCE

20.A valuer shall not use or divulge to other clients or any other party any confidential information about the subject company, which has come to his/its knowledge without proper and specific authority or unless there is a legal or professional right or duty to disclose.

Information Management

- 21. A valuer shall ensure that he/ it maintains written contemporaneous records for any decision taken, the reasons for taking the decision, and the information and evidence in support of such decision. This shall be maintained so as to sufficiently enable a reasonable person to take a view on the appropriateness of his/its decisions and actions.
- 22. A valuer shall appear, co-operate and be available for inspections and investigations carried out by the authority, any person authorised by the authority, the registered valuers organization with which he/it is registered or any other statutory regulatory body.
- 23. A valuer shall provide all information and records as may be required by the authority, the Tribunal, Appellate Tribunal, the registered valuers organization with which he/it is registered, or any other statutory regulatory body.
- 24. A valuer while respecting the confidentiality of information acquired during the course of performing professional services, shall maintain proper working papers for a period of three years or such longer period as required in its contract for a specific valuation, for production before a regulatory authority or for a peer review. In the event of a pending case before the Tribunal or Appellate Tribunal, the record shall be maintained till the disposal of the case.

Gifts and hospitality.

25. A valuer or his/its relative shall not accept gifts or hospitality which undermines or affects his independence as a valuer.

Explanation: For the purposes of this code the term 'relative' shall have the same meaning as defined in clause (77) of Section 2 of the Companies Act, 2013 (18 of 2013).

26. A valuer shall not offer gifts or hospitality or a financial or any other advantage to a public servant or any other person with a view to obtain or retain work for himself/ itself, or to obtain or retain an advantage in the conduct of profession for himself/ itself.

Remuneration and Costs.

- 27. A valuer shall provide services for remuneration which is charged in a transparent manner, is a reasonable reflection of the work necessarily and properly undertaken, and is not inconsistent with the applicable rules.
- 28. A valuer shall not accept any fees or charges other than those which are disclosed in a written contract with the person to whom he would be rendering service.

Occupation, employability and restrictions.

- 29. A valuer shall refrain from accepting too many assignments, if he/it is unlikely to be able to devote adequate time to each of his/ its assignments.
- A valuer shall not conduct business which in the opinion of the authority or the registered valuer organisation discredits the profession.

Miscellaneous

31. A valuer shall refrain from undertaking to review the work of another valuer of the same client except under written orders from the bank or housing finance institutions and with knowledge of the concerned valuer.

32. A valuer shall follow this code as amended or revised from time to time

Signature of the Authorized Person:

Name of the Valuation company: R.K. sociates Valuers & Techno Engg. Consultants (P) Ltd.

Address of the Valuer: D-39, Sector-2, Noida-20130

Date: 28/8/2023 Place: Noida

FILE NO.: VIS(2023-24)-PL223-Q037-193-277

Page 54 of 57





www.valuationintelligentsystem.com

PART E **ENCLOSURE: VIII - VALUER'S IMPORTANT REMARKS**

1.	Valuation is done for the asset found on as-is-where basis which owner/ owner representative/ client/ bank has shown/ identified to us on the site unless otherwise mentioned in the report of which some reference has been taken from the information/ data		
	given in the copy of documents provided to us and informed verbally or in writing out of the standard checklist of documents sought from the client & its customer which they could provide within the reasonable expected time out of the standard checklist of documents sought from them and further based on certain assumptions and limiting conditions. The information, facts, documents, data which has become primary basis of the report has been supplied by the client which has been relied upon in		
	good faith and is not generated by the Valuer.		
2.	The client/ owner and its management/ representatives warranted to us that the information they have supplied was complete, accurate and true and correct to the best of their knowledge. All such information provided to us either verbally, in writing or through documents has been relied upon in good faith and we have assumed that it is true & correct without any fabrication or misrepresentation. I/We shall not be held liable for any loss, damages, cost or expenses arising from fraudulent acts, misrepresentations, or willful default on part of the owner, company, its directors, employee, representative or agents.		
3.	Legal aspects for eg. Investigation of title, ownership rights, lien, charge, mortgage, lease, sanctioned maps, verification of documents provided to us such as title documents, Map, etc. from any concerned Govt. office etc. have to be taken care by legal expert/ Advocate and same is not done at our end. It is assumed that the concerned Lender/ Financial Institution has asked for the valuation of that property after satisfying the authenticity of the documents given to us for which the legal verification has been already taken and cleared by the competent Advocate before requesting for the Valuation report. I/ We assume no responsibility for the legal matters including, but not limited to, legal or title concerns.		
4.	In the course of the valuation, we were provided with both written and verbal information. We have however, evaluated the information provided to us through broad inquiry, analysis and review but have not carried out a due diligence or audit of the information provided for the purpose of this engagement. Our conclusions are based on the assumptions and other information provided to us by the client during the course of the assessment.		
5.	Getting cizra map or coordination with revenue officers for site identification is a separate activity and is not part of the Valuation services and same has not been done in this report unless otherwise stated.		
6.	Wherever any details are mentioned in the report in relation to any legal aspect of the property such as name of the owner, leases, etc. is only for illustration purpose and should not be construed as a professional opinion. Legal aspects are out of scope of this report. Details mentioned related to legal aspect are only based on the copy of the documents provided to us and whatever we can interpret as a non-legally trained person. This should be cross validated with a legal expert. We do not vouch any responsibility regarding the same.		
7.	We have made certain assumptions in relation to facts, conditions & situations affecting the subject of, or approach to this exercise that has not been verified as part of the engagement rather, treated as "a supposition taken to be true". If any of these assumptions prove to be incorrect then our estimate on value will need to be reviewed.		
8.	This is just an opinion report based on technical & market information having general assessment & opinion on the indicati estimated Market Value of the property for which Bank has asked to conduct the Valuation. It doesn't contain any off recommendations of any sort including but not limited to express of any opinion on the suitability or otherwise of entering in any transaction with the borrower.		
9.	We have relied on the data from third party, external sources & information available on public domain to conclude the valuation. These sources are believed to be reliable and therefore, we assume no liability for the truth or accuracy of any data, opinions or estimates furnished by others that have been used in this analysis. Where we have relied on the data, opinions or estimates from external sources, reasonable care has been taken to ensure that such data is extracted from authentic sources, however we still can't vouch its authenticity, correctness, or accuracy.		
10.	Analysis and conclusions adopted in the report are limited to the reported assumptions, conditions and information came to our knowledge during the course of the work and based on the Standard Operating Procedures, Best Practices, Caveats, Limitations, Conditions, Remarks, Important Notes, Valuation TOR and definition of different nature of values.		
11.	Value varies with the Purpose/ Date/ Asset Condition & situation/ Market condition, demand & supply, asset utility prevailing on a particular date/ Mode of sale. The indicative & estimated prospective Value of the asset given in this report is restricted only for the purpose and other points mentioned above prevailing on a particular date as mentioned in the report. If any of these points are different from the one mentioned aforesaid in the Report then this report should not be referred.		
12.	Our report is meant ONLY for the purpose mentioned in the report and should not be used for any other purpose. The Report should not be copied or reproduced for any purpose other than the purpose for which it is prepared for. I/we do not take any responsibility for the unauthorized use of this report.		
13.	We owe responsibility only to the authority/client that has appointed us as per the scope of work mentioned in the report. We will not be liable for any losses, claims, damages or liabilities arising out of the actions taken, omissions or advice given by any other person. In no event shall we be liable for any loss, damages, cost or expenses arising in any way from fraudulent acts, misrepresentations or willful default on part of the client or companies, their directors, employees or agents.		
14.	This report is having limited scope as per its fields & format to provide only the general basic idea of the value of the property prevailing in the market based on the site inspection and documents/ data/ information provided by the client. The suggested indicative prospective estimated value should be considered only if transaction is happened as free market transaction.		
15.	The sale of the subject property is assumed to be on an all cash basis. Financial arrangements would affect the price at which the property may sell for if placed on the market.		
16.	The actual realizable value that is likely to be fetched upon sale of the asset under consideration shall entirely depend on the		



VALUATION ASSESSMENT

REINFORCING YOUR BUSINESS VALUERS & TECHNO ENGINEERING CONSULTANTS (PLITO

M/S. SHALIMAR PAINTS LIMITED

VALUATION CENTER OF EXCELLENCE

World's first fully digital Automated Platform for Integrating Valuation Life Cycle product of R.K. As www.valuationintelligentsystem.com

17.	While our work has involved an analysis & computation of valuation, it does not include detailed estimation, design/ technical/
	engineering/ financial/ structural/ environmental/ architectural/ compliance survey/ safety audit & works in accordance with
	apparelly prepared a fault 2 of the architectural compliance survey, salety audit & works in accordance with
	generally accepted standards of audit & other such works. The report in this work in not investigative in nature. It is mere an
	opinion on the likely estimated valuation based on the facts & details presented to us by the client and third party market
	information came in front of us within the limited time of this assignment, which may vary from situation to situation.

Where a sketched plan is attached to this report, it does not purport to represent accurate architectural plans. Sketch plans and photographs are provided as general illustrations only.

- Documents, information, data including title deeds provided to us during the course of this assessment by the client is reviewed 19. only upto the extent required in relation to the scope of the work. No document has been reviewed beyond the scope of the work. These are not reviewed in terms of legal rights for which we do not have expertise. Wherever any information mentioned in this report is mentioned from the documents like owners name, etc., it is only for illustration purpose and may not necessary represent accuracy.
- The report assumes that the borrower/company/business/asset complies fully with relevant laws and regulations applicable in its area of operations and usage unless otherwise stated, and that the companies/business/assets is managed in a competent and responsible manner. Further, as specifically stated to the contrary, this report has given no consideration to matters of a legal nature, including issues of legal title and compliance with relevant laws, and litigations and other contingent liabilities that are not recorded/reflected in the documents/ details/ information/ data provided to us.
- This valuation report is not a qualification for accuracy of land boundaries, schedule (in physical terms), dimensions & identification. For this land/ property survey report can be sought from a qualified private or Govt. surveyor.
- 22. This Valuation report is prepared based on the facts of the property on the date of the survey. Due to possible changes in market forces, socio-economic conditions, property conditions and circumstances, this valuation report can only be regarded as relevant as at the valuation date. Hence before financing, Banker/ FI should take into consideration all such future risk and should loan conservatively to keep the advanced money safe in case of the downward trend of the property value.
- 23. Valuation of the same asset/ property can fetch different values under different circumstances & situations. For eg. Valuation of a running/ operational shop/ hotel/ factory will fetch better value and in case of closed shop/ hotel/ factory it will have considerable lower value. Similarly, an asset sold directly by an owner in the open market through free market transaction then it will fetch better value and if the same asset/ property is sold by any financer due to encumbrance on it, will fetch lower value. Hence before financing, Lender/ FI should take into consideration all such future risks while financing and take decision accordingly.
- Valuation is done for the property identified to us by the owner/owner representative. At our end we have just visually matched the land boundaries, schedule (in physical terms) & dimensions of the property with reference to the documents produced for perusal. Method by which identification of the property is carried out is also mentioned in the report clearly. Responsibility of identifying the correct property to the Valuer/ its authorized surveyor is solely of the client/ owner for which Valuation has to be carried out. It is requested from the Bank to cross check from their own records/ information if this is the same property for which Valuation has to be carried out to ensure that owner has not misled the Valuer company or misrepresented the property due to any vested interest. Where there is a doubt about the precision position of the boundaries, schedule, dimensions of site & structures, it is recommended that a Licensed Surveyor be contacted.
- 25 In India more than 70% of the geographical area is lying under rural/remote/non municipal/unplanned area where the subject property is surrounded by vacant lands having no physical demarcation or having any display of property survey or municipal number / name plate on the property clearly. Even in old locations of towns, small cities & districts where property number is either not assigned or not displayed on the properties clearly and also due to the presence of multiple/ parallel departments due to which ownership/ rights/ illegal possession/ encroachment issues are rampant across India and due to these limitations at many occasions it becomes tough to identify the property with 100% surety from the available documents, information & site whereabouts and thus chances of error, misrepresentation by the borrower and margin of chances of error always persists in such cases. To avoid any such chances of error it is advised to the Bank to engage municipal/ revenue department officials to get the confirmation of the property to ensure that the property shown to Valuer/ Banker is the same as for which documents
- 26. If this Valuation Report is prepared for the Flat/ dwelling unit situated in a Group Housing Society or Integrated Township then approvals, maps of the complete group housing society/ township is out of scope of this report and this report will be made for the specific unit based on the assumption that complete Group Housing Society/ Integrated Township and the subject unit must be approved in all respect.
- Due to fragmented & frequent change in building/ urban planning laws/ guidelines from time to time, different laws/ guidelines 27. between regions/ states and no strict enforceability of Building Bye-Laws in India specially in non-metro and scale b & c cities & Industrial areas, property owners many times extend or make changes in the covered area/ layout from the approved/ applicable limits. There are also situations where properties are decades old when there was no formal Building Bye-Laws applicable the time when the construction must have been done. Due to such discrete/ unplanned development in many regions sometimes it becomes tough for the Valuer to determine the exact lawful situation on ground. Unless otherwise mentioned in the report, the covered area present on the site as per site survey will be considered in the Valuation.
- Area of the large land parcels of more than 2500 sq.mtr or of uneven shape in which there can be practical differences. measurement, is taken as per property documents which has been relied upon unless otherwise stated
- 29. Drawing Map, design & detailed estimation of the property/ building is out of scope of the Valuation services.
- 30 Valuation is a subjective field and opinion may differ from consultant to consultant. To check the right opinion, it is in portant to evaluate the methodology adopted and various data point/ information/ factors/ assumption considered by the consultant which became the basis for the Valuation report before reaching to any conclusion.
- Although every scientific method has been employed in systematically arriving at the value, there is, therefore, no indisputable single value and the estimate of the value is normally expressed as falling within a likely range.



VALUATION ASSESSMENT

REINFORCING YOUR BUSINESS ASSOCIATES

VALUATION CENTER OF EXCELLENCE & RESEARCH CENTRE

M/S. SHALIMAR PAINTS LIMITED

	roduct of R.K. Associates uptionintelligentsystem.com
32.	Value analysis of any asset cannot be regarded as an exact science and the conclusions arrived at in many cases will, necessity, be subjective and dependent on the exercise of individual judgment. Given the same set of facts and using the san assumptions, expert opinions may differ due to the number of separate judgment decisions, which have to be made. Therefor there can be no standard formula to establish an indisputable exchange ratio. In the event of a transaction, the actual transactive value achieved may be higher or lower than our indicative analysis of value depending upon the circumstances of the transaction. The knowledge, negotiability and motivations of the buyers and sellers, demand & supply prevailing in the mark and the applicability of a discount or premium for control will also affect actual price achieved. Accordingly, our indicative analysis of value will not necessarily be the price at which any agreement proceeds. The final transaction price is something on which the parties themselves have to agree. However, our Valuation analysis can definitely help the stakeholders to take informed and wise decision about the Value of the asset and can help in facilitating the arm's length transaction.
33.	This Valuation is conducted based on the macro analysis of the asset/ property considering it in totality and not based on the
34.	micro, component, or item wise analysis. Analysis done is a general assessment and is not investigative in nature. This report is prepared on the RKA V-L1 (Basic) Valuation format as per the client requirement and scope of work. This report is prepared on the RKA V-L1 (Basic) Valuation format as per the client requirement and scope of work.
	is having limited scope as per its fields & format to provide only the general estimated & indicative basic idea of the value of the property prevailing in the market based on the information provided by the client. No detailed analysis, audit or verification have been carried out of the subject property. There may be matters, other than those noted in this report, which might be relevation the context of the transaction and which a wider scope might uncover.
35.	This is just an opinion report and doesn't hold any binding on anyone. It is requested from the concerned Client/ Bank/ Finance Institution which is using this report for mortgaging the property that they should consider all the different associated relevative and the factors & risks before taking any business decision based on the content of this report.
36.	All Pages of the report including annexures are signed and stamped from our office. In case any paper in the report is with stamp & signature then this should not be considered a valid paper issued from this office.
37.	As per IBA Guidelines & Bank Policy, in case the valuation report submitted by the valuer is not in order, the banks / Fls st bring the same to the notice of the valuer within 15 days of submission for rectification and resubmission. In case no su communication is received, it shall be presumed that the valuation report has been accepted.
38.	Defect Liability Period is 15 DAYS. We request the concerned authorized reader of this report to check the contents, dainformation, and calculations in the report within this period and intimate us in writing at valuers@rkassociates.org within days of report delivery, if any corrections are required or in case of any other concern with the contents or opinion mention in the report. If no intimation is received within 15 (Fifteen) days in writing from the date of issuance of the report, then it she considered that the report is complete in all respect and has been accepted by the client up to their satisfaction & use a further to which R.K Associates shall not be held responsible in any manner. After this period no concern/complain proceedings in connection with the Valuation Services will be entertained due to possible change in situation and condition the property.
19.	Though adequate care has been taken while preparing this report as per its scope, but still we can't rule out typing, hum errors, over sightedness of any information or any other mistakes. Therefore, the concerned organization is advised to satisfactory that the report is complete & satisfactory in all respect. Intimation regarding any discrepancy shall be brought if our notice immediately. If no intimation is received within 15 (Fifteen) days in writing from the date of issuance of the report rectify these timely, then it shall be considered that the report is complete in all respect and has been accepted by the cli upto their satisfaction & use and further to which R.K Associates shall not be held responsible in any manner.
Ю.	Our Data retention policy is of <u>ONE YEAR</u> . After this period we remove all the concerned records related to the assignm from our repository. No clarification or query can be answered after this period due to unavailability of the data.
41.	This Valuation report is governed by our (1) Internal Policies, Processes & Standard Operating Procedures, (2) R.K Associa Quality Policy, (3) Valuation & Survey Best Practices Guidelines formulated by management of R.K Associates, (4) Informat input given to us by the customer and (4) Information/ Data/ Facts given to us by our field/ office technical team. Managem of R.K Associates never gives acceptance to any unethical or unprofessional practice which may affect fair, correct & impar assessment and which is against any prevailing law. In case of any indication of any negligence, default, incorrect, misleadi misrepresentation or distortion of facts in the report then we request the user of this report to immediately or at least within defect liability period to bring all such act into notice of R.K Associates management so that corrective measures can be takinstantly.
12.	R.K Associates never releases any report doing alterations or modifications by pen. In case any information/ figure of this rep is found altered with pen then this report will automatically become null & void.
3.	We are fully aware that based on the opinion of value expressed in this report, we may be required to give testimony or attercourt / judicial proceedings with regard to the subject assets, although it is out of scope of the assignment, unless speciarrangements to do so have been made in advance, or as otherwise required by law. In such event, the party seeking evidence in the proceedings shall bear the cost/professional fee of attending court / judicial proceedings and my / our tender evidence before such authority shall be under the applicable laws.
4.	The final copy of the report shall be considered valid only if it is in hard copy on the company's original letter head with pro
	stamp and sign on it of the authorized official upon payment of the agreed fees. User shall not use the content of the report the purpose it is prepared for only on draft report, scanned copy, email copy of the report and without payment of the agree