
File No. RKA/DNCR/ / Date of Receiving 13/12/123
File Receiver Name Phawal



# CASE COLLECTION FORM (Version 5.0) Date of implementation: 9.02.2011 | Last Revision: 30.01.2020 | Latest Revision: 31.10.2020

Items	Assigned To	Assigned to Date	To be completed by date	Submitted On date	Grade	HOD Engg. Signature
File Received By	Dhama	NA	NA	ele m		
Survey	Arit Bhauji					
Preparation	Shary			100	1	
A - Very Good, E	3 - Satisfactory, C -	Average, D -	Poor E - Extra	emely Poor		
File Returned to HOD Engg, unprepared due to reason	Survey not rates is not properly done	done properly done.  Deperly done.  Photogram photo not ta	y, □ Survey F □ Identification graphs not cl ken, □ Owner	orm not proper is not clearly early taken,	done,  Selfie/	Market survey Measurement is r Owner or own signature not take

In case File is returned by the preparer - HOD Engg. comment &
Signature

Minor defects in the survey hence approved for preparation with warming to Surveyor. Report preparer to collect the missing information on his own.

Major defects in the survey. Survey has to be done again.

		GENER/	AL DETAILS	With the second
1.	Proposal/ Work Order or Ref. No.	The state of the s	-24) PL559-4	75-7205
2.	Type of Service	Valuation Report	, ☐ Construction cost estima ates, ☐ TEV Report, ☐ LIE	ate,  Cost vetting certificate
3.	Type of customer	Bank	☐ PSU ☐ NBFC ☐ Private client ☐ Direct	Corporate
4.	Bank/ FI/ Organization Name & Address	SBI SAMI	Tulsiani chamba	ers, 1st \$1002, au foint Mumbai 400021
5.	Case Allotment Officer/	Name	Contact Number	Email Id
	Fees paying party Details	Me Jagdish. Adangale	9860885606	+cam2.61341@Sbi.co.
6.	Case Type	LJ Case for Fres	h Account Case	or exiting account/ customer
7.	Fees Details	Amount of Fees	Advance Amount if any	Fees will be paid by
		10563		☐ Bank ☐ Customer
8.	Billing Details	Rilled To P	net Aleman	

	CASE DETAILS	STEED STATE STATE OF THE STATE	The state of the s
	Commercial of	lice - I	
Type of Property	Commercial of	died bo	w collatoral man
	Value assessment of the as	sset for creating nev	le for NPA A/c
Purpose of Valuation/	U Value assessment of the as	lank, M Distress sa	Wealth Tax purpose
Assignment	Periodic Re-Valuation for B	e, Capital Gains	onl
	☐ For DRT Recovery purpose. ☐ Gener	ral Value Assessme	
	Any other:		
		Contact Number	r Email Id
Owner/ Applicant Details	Name ny Hisalal Godhani		
	m Hiralal Godhani & Manoj kumar.		
	The last way		170
Account Name	Ms. Godhani	Jens PVT	ing known "Pat va"  sur koad " Navagan  Contact Number
Property Address	Poom 1,2,83,Ax+,	floor Bauild	ing known as livee
	Millage Navagam	Dationa Ma	in Road, Navagran
	Digtisweet Warter	at 39500 8	Contact Number
Who will coordinate on site for the site survey	1	100	1041540
site for the site survey	Mr. Mukesh Bhai	922	7944568
Preferred time of survey	Date 20 12 23	Time	12 pm.
Documents Received	1. Ownership Documents:		
Any one ownership document and approved sile plan/ map is	☐ Registered Will, ☐ Rel	Color State Color	
	☐ Conveyance Deed, ☐ .  2. Map: ☐ Cizra Map. ☐ Ap		
			ceipt,  Water Bill & payment
	receipt, ☐ House Tax der		
	4. Any Other document:	CLU,   TIR Repo	rt, ☐ Agreement to Sale,
	☐ Old Valuation Report		
	5. No documents provided	i: La maze	
Documents received from	Customer & b	ank.	
Special Instructions if		Wall Property	
any.			
on Valuer firm to distort any	entioned above for the preparation	on of Valuation Repo	rt. I agree that I'll not put pressure
vested interest and to benefit	racts and would not try to influe I any individual or organization by	any member or or any means illegitima	official of the firm in the ill spirit or tely.
mruke 61	and an	and mognified	
Customer Signature:			

FILE RECEIVER CASE COLLECTION P	ROCESS COMPLIANCE CHECKLIST
(To be filled by	Surveyor

5.NO.	COMPLIANCE CHECKLIST	STATUS	APPROVER SIGNATURE REMARKS IN CASE OF ANY O
1.	Is Case collection Form properly filled by Receiver?	2	
2.	Is purpose of the assignment understood clearly by the receiver?	0	
3.	Has receiver checked if this is a new case or existing case of the Bank?	N.	
4.	Has receiver fixed the fees with the manager/ client and sent quotation properly or have taken approval of the work over email?		
5.	Has receiver taken proper Work Order/ Email	1	
6.	In case of private case or for fresh case 50% advance is received?	0	
7.	Is document checklist email sent to the customer?	1	
8.	Has the received documents is having 'documents provided by stamp'?		THE VOR

## IMPORTANT INSTRUCTIONS TO SURVEYOR

Please fill the above compliance checklist before moving for the survey Please do not do the survey if you do not have proper documents. For Vacant Plot/ Land - Cizra Map/ Master/ Zonal/ Site Plan is must to identify the Plot Agriculture or converted land from agriculture - Mutation documents, CLU is must 3 Firstly please first study the documents of the property which needs to get surveyed Mark the Owner/ Area/ Boundaries mentioned in the ownership documents with bold florescent marker pen before moving for the survey. During site survey if any difference is found in the 1 above fields from the ownership documents then please contact the owner immediately to 5. Confirm ongoing property rates in the subject location through public domain, property sites and contact dealers to show you the available properties in that area during your survey Identify the Property clearly by matching the boundaries and area mentioned in the property 6 Do sample physical or google measurements of the property. 8. PHOTOGRAPH INSTRUCTIONS: a. Take owner/ representative photograph along with the property. 9. b. Take your selfie along with the property and the owner/ representative. c. Take full scale photo of the property with gate. d. Take photo of the property along with abutting road, towards left, right and center. e. Take multiple photos of inside-out of the property f. Take nearby photographs of the Property. g. Take a short video to cover property and neighborhood. Take Google Map location. 10. Check main road name & width and approach road width and distance of property from main road 11. Check Jurisdiction Municipal Limits & Ward Name 12. Fill each column of survey form diligently in detail and tick the appropriate option clearly 13. Check any defects or negativity in the property and comment in detail on survey form. 14. Do extensive market rate enquiries and confirm for any recent past transactions. 15. In case customer appears to be providing misleading information to you or trying to influence you may

money or cash then immediately report to the Management & Bank.

### SURVEY PROCESS COMPLIANCE CHECKLIST

(To be submitted by Surveyor with each Survey) STATUS COMPLIANCE CHECKLIST POINTS NO. Did you take proper property documents to carry out the survey? 1. Have you properly studied & highlighted Owner/ Area/ Boundaries in the property 2.

documents with bold florescent before moving for the survey? Did you check prominent landmark nearby the subject property and mentioned in the survey 3. form?

Did you identified the Property clearly by matching the boundaries and area mentioned 4. in the property papers?

Did you check if property is merged with any other property or it is an independent property?

Did you checked the flat size with eye estimation or based on number of bed rooms?

6. Did you check for any construction violations in the flat?

7. Did you check municipal limits/ jurisdiction/ ward? 8.

Did you take Google Map location and shared it to Maps whatsapp group? 9.

Did you check society reputation? 10.

5.

22.

Have you taken property full scale photograph with gate? 11.

Have you taken owner/ representative photograph with the property? 12.

Have you taken your selfie with the property along with owner/ representative?

Have you taken photograph of the society gate along with abutting road and towards left 13. 14. and right of the property?

Have you taken multiple photographs of the property from inside-out?

Did you check nearby development and whereabouts and commented on survey 15. 16.

Did you check any defects or negativity in the society & flat in terms of location, legality, disputes, marketability, salability, etc. and commented on survey form in 17.

Have you filled all the columns of survey form including survey summary sheet 18.

Have you taken self-attested documents from owner/ representative and stamped 19. "documents provided by stamp"?

Did you check any defects or negativity in the property in terms of location, legality, disputes, marketability, salability, etc. and commented on survey form in detail? 20.

Have you confirmed any recent past transactions during market enquiries and 21. enquired property rates locally very rigorously?

Did you take signatures of the owner/ representative on undertaking and survey summary sheet?

Did you signed the undertaking? 23.

For File No.	VIS (2023-24) PL 559-475-725
Surveyor Name	Aut Bhanji
Signature	Thay
Date	20/12/23

#### Version 5.0) 10 of implementation: 09.02/2017 | Date of Revision: 04.01.2018 | Latest Revision: 31.10.2020 Date 20 12 23 Time: 12 Pm File No. RKA/DNCR/... GENERAL DETAILS Owner, Representative, No one was available, Property is Name of the Surveyor locked, survey could not be done from inside Property shown by Contact No. 922-1944 568. Name Me Mukesh Bhou V1 Full survey (inside-out with measurements & photographs) Survey Type ☐ Half Survey (Measurements from outside & photographs) Only photographs taken (No measurements) ☐ Property was locked, ☐ Possessee didn't allow to inspect the Reason for Half survey or only property, NPA property so couldn't be surveyed completely photographs taken $\square$ From schedule of the properties mentioned in the deed, $\square$ From How Property is Identified name plate displayed on the property, I Identified by the owner, owner representative, Enquired from nearby people, Identification of the property could not be done, Survey was not done ☐ Self-measured, ☑ Sample measurement only, ☐ No measurement Property Measurement ☐ Value assessment of the asset for creating collateral mortgage, Purpose of Valuation ☐ Periodic Re-Valuation for Bank, ☑ Distress sale for NPA A/c., □ For DRT Recovery purpose, □ Capital Gains Wealth Tax purpose ☐ Partition purpose, ☐ General Value Assessment Type of Loan ☐ Housing Loan, ☐ Housing Take Over Loan, ☐ Home Improvement Loan, Loan against Property, Construction Loan, Educational Loan, ☐ Car Loan, ☐ Project Loan, ☐ Term Loan, ☐ CC Limit enhancement, Cash Credit Limit, Industrial Loan, NA Loan Amount

legal Owner Name/s	OWNERSHIP DETAILS
Property Purchaser Name	MIS Godhani Genes PVT LTD Mikalal. Navij bhai Godheini & Manor kungar hidlani
Property Address under Valuation	CTS 1198 2 1288 1/11age Navagam, Fut neolow
Present Residence Address of the	State Schaff State This Said Main Food Navagan
Owner/ Purchaser	

	A residence or insure to married to proton a day or long			ATTONIO		21111			Mont
	1. Adjoining Properties			rth	Sout		East		West
	(Match it with papers with I		anter	Las	Shiv	1.01	Internal	The	lerval
	of compass or Sun direction		Poa	d	Varace	ha	friterral	for	d.
1	also confirm it with nearby	people)			Alana Com	the same of			
	Property Facing						Facing, 🗆 Sout		
			□ North-Ea	st Facing.	☐ South-W	est Facir	ng, 🗆 South-Ea	st Facil	151
			☐ North-W						
3	Landmark		Near !	vou '	Dianu	ond	Market		
4.	. Ward Name/ No.								
5.	Zone Name						Dietano	e from	property
6.	Main Road Name & Width		Na	ame		Width	LOC	21-4	
			Surat	amre	1 70	HS;	100	, ,,,	مندلية
7.	Approach Road Name & W	/idth	30 Juga	mit	renal 1	Road	j'kolimoor	. bu	laing
	Location consideration of th								
8.									
	Society	1	☐ Ordinary,	☐ In interi	ors, $\square$ Ref	Hote arc	a,		
	ATLANCE ME MARKET	1	Poor			Dond F	Facing,   Entr	ance I	North Fast
9.	Location of the Flat		Park Facin	ig, 🗆 Pool	Facing, V	Roau	acing, in the		
		F	acing,   Su	nlight facing	Johan days	Jonina [	☐ Semi Urban,	Ru	ral.
10.	Characteristics of the Locality	y [	Urban deve	eloped, V	Jipan deve	tional			
			Backward,			Metro	Railway S	tation	Airport
11.	Proximity to civic amenities		School	Hospital		Metro	5 km		12km
11.	1 TOXIIIII I		2 lem.	5km	our	Ceta	Skir	^ .	THEIR
-			lem.	7	L				
12.	Any new Development in	6	lands						
13	surrounding area			I Alegor	Danchava	at 🗆 Gr	am Panchayat		
3.	Jurisdiction limits	V	Nagar Nigan	ı, 🗔 Nagai	randiaye		any municipal	limits	
			Vagar Palika	Parishad,	☐ Area no	ot within	any municipal	a 171 i	ACTION
1	. I. C Davolanment	In	DDA. GDA	. NOID	A, 🗆 GNII	DA, 🗆 Y	EIDA, 🗆 HUD	)A, 1.1 ?	XIVILDA.
	urisdiction Development		IDDA, ☑ An	v other De	velopment	Authori	ty:		
A	uthority Name		IDDA, W AN	y other be	l ont o	uthority	limits		
1		DA	rea not withi	n any deve	elopment	luthority	IIIIII		
100	unicipal Corporation Name	TON	DMC. SDI	MC. [] ED	MC, G	naziabad	Municipal Co	rporau	Offi
. Mu	incipal Corporation . Tame	23 146	,,,,,,		e - 10	Eoridal	and Municipal	Corpo	ration.
		G	urgaon Muni	cipal Corp	oration,	T arroat	ad Municipal	ornor	tion
	W. C.	□ Ko	olkata Munici	pal Corpor	ation, 🗆 I	Dehradu	in Municipal C	Orpora	
		□ Are	a not within	any munic	ipal limits	, MAny	other Municip	al Cor	porations
7	The second secon		ipality:						
			The same of the sa						

	PHYSICAL DETAILS	AND ASSOCIATION ASSOCI
Covered Built-up Area	Covered Area, Eleor Area, Super Area	I. Carpet Are
(Tick one on the basis of which	As per Title deed As per Map	As per site sur,
	TOUNDA SOUTH	Surgetti.
Are Boundaries matched	V Yes No	
is Independent access available	V Clear independent access is available.	Access available in
to the property?	sharing of other adjoining property.   No cle	ar access is available,
	Access is closed due to dispute	
Is the property merged or		
colleded with any other property	No	
Construction Status	Built-up property in use.  Under construct	ion,  Construction not
	started	
Total Number of Floors in the Building	& floor.	
Floor on which Flat is situated	1st the r.	
Type of Flat	1st took floor.	
Age of Building/ Recent Improvements done	26 415,	
Type of Group Housing Society		
Appearance/ Condition of the	☐ High End. Normal, ☐ Affordable Group H	
Building	Internal -    Excellent, Very Good,	
	☐ Average, ☐ Poor ☐ Under construction, ☐	No construction,
	□ No Survey	
	External -   Excellent,   Very Good,	Good C Ordinan
	Average, ☐ Poor ☐ Under construction, ☐	No construction
Maintenance of the Building	☐ Very Good, ☑ Average, ☐ Poor	TTO GOTISTI UCTION
Fixed Wooden Work	☐ Excellent, Very Good, ☐ Good, ☐	Simple [] Ordina
	☐ Average, ☐ Below Average, ☐ No wooden	Simple, U Ordinary,
Interior decoration	☐ Excellent, ☑ Very Good, ☐ Good, ☐	work, 🗆 No survey
	Average Below Average DNs	Simple, U Ordinary,
Any defects in the Group Housing	☐ Average, ☐ Below Average, ☐ No wooden	work,  No Survey
Society	No	
Any violation done in the flat	No.	
Utilities/ Facilities in the Group	√ Lifts, □ Garden, □ Landscaping, □ Swimm	ning Pool,  Gym.
Housing Society	☐ Club House, ☐ Walk Trails, ☐ Kids play	
	Backup	3577 5770
Property currently possessed by	Owner, □ Vacant, □ Lessee, □ Under C	onstruction.   Couldn't
	be Surveyed, ☐ Property was locked, ☐	
The second second	sealed	Julia Scaleu, 🗆 Court

2700. - Sqot by site Survey.

Page 8 of 12

	I	onice,	Vacant, Locked, L	Any other use:		
20.	Special Comments if any					
	MARKETABIL	ITY/SEL	ABILITY/UTLITY/DE	TAILS	MIRE IN	
1.	Reputation/ class of developer		Good, Good, Aver			
2.	Reputation of society		Good, Good, Aver			
3.	Any issues in marketability of the					
	property?	Reason in case of No: Location, Surrounding.				
			aspects,   Demand,			
4.	How is Demand & Supply condition	Demand	Very Good, Good	od,   Average,   Low		
	in the Market of such properties?	Supply	V Very Good, ★ Goo	d,   Average,   Low.		
5.	Is property easily sellable &	V Yes,	No			
	marketable?	Commen	ts:			
		ILLAND.				
6.	How is the current utility of the property?	□ Excelle	ent. Very Good, G		w, El Pao	
7.	At what True rate Owner bought	Year of p	urchase	2005		
	this Property?	Purchase	Price	N. FT. H. H. H.		

Residential purpose Commercial purpose, Godown.

current activity carried out in the

USE THIS SPACE FOR PROVIDING ANY ADDITIONAL DETAILS/ INFORMATION

		-		MPARABLE RATE	NFORMATION DETAIL	LS
		211	. ale	MPARABLE RATE  OF Transaction Ulready  Comparable 1	NFORMA in past)	Comparabi
		pro	THE PROPERTY OF	MPARABLE RA	Camparable 2	Comparable
		PROPER	in blater Sale			
	No	Lean attendance	Subject	L	190 Halakee	
	140		NA	SM proper	Eddle Brand	
		Name (source of		column	1.112210220	
		information) Contact No.	NA	960146280	The state of the s	
			NA	property	property dealer	
		Type of source of	1107	pholored	1, 100	
		information (Seller/ Property dealer/ nearby			1800-5300	
		ananin)		5000-5500	48,00-3300	
		Rates/ Price informed	NA	8000 3 90	RATE	
				1sqfit	0	
		Rates Type (Sale/ Buy)	NA	Sile	Jala	
		Police 1 year 1		Oxlo		
		ros Chi		Anna katt	2500 5914	
		Area/ Size of the Flat		4000 kg fd		
				1 .	Clear.	
		Ingal Status (clear,		'Cloos	Clear.	
		negative, weak)/ No. of owners		,		
		location/ surrounding/	Base Case	0 1	0 1	
		neighborhood		Imilae	Simila	
		comparison with the		Jimalac	Dimer	
	1	Similar, Lower, Better,				
		lighly Better than the				
		ubject Property)	0		0 10	
		Islance from the	0	1.5km	2. km	
		object Property		^		
		ociety comparison		() -1.	Rinutae	
		Similar, Lower, Better, Ighly Better than the		Similar	Kimilae	
		biect society)				
		her factors (Corner,				
		side open, North-				
		ist facing, Park				
		omg, Legal/ Financial cumbrance, etc.)				
		y other details/	NA			
		cussion held	INA			
					TOWNS	
			1179			
n	Pre:	sent expected Sale	1			
	Valu	ie of the overall				
911	orop	erty?				

#### UNDERTAKING BY THE CUSTOMER

Lonfirm that I have made the inspection of the subject property to the surveyor of R.K. Associates, which is correct property in question for which the documents have been provided submitted by me. I further confirm that I am aware of all the information related to the subject property and I have provided all its information to this surveyor true to the best of my knowledge. I understand that any false or manipulative information provided by me will be considered as cheating with the professional organization since it will lead to incorrect valuation report and I'd be solely responsible for this unlawful act and will bear the charges for the changes modifications which have to undergo due to the false information. I also undertake that I have not given any cash or in kind to any member of R.K. Associates to influence the Value of the Property or favor any individual or organization and the same is not accepted or asked by the member of R.K. Associates. Any such act will lead to cancellation of the material prepared by R.K. Associates with forfeiting of the fees and FII be completely responsible for its repercussions and legal actions taken for it.

IMPORTANT: We have not authorized any of our person/ Surveyor to take Cash or kind from the customers in any situation. In case Surveyor or any member of R.K. Associates asks for any money or kind from you then kindly please inform on number +91-9958632707, 0120-4110117. Our Valuation process is very stringent and have multiple check points to ensure correct & error free reports to keep the lending agency risk free. In case Surveyor claims that he would be able to arbitrary effect the Valuation figures unfairly or as per your requirement & need, then he is making a false claim to you and we request you to complaint such act immediately on the number provided above.

Name	Mukesh.
Relationship with owner	acora. Employee
Signature	mucest
Mobile No.	9227944568.
Date	20/12/23

#### UNDERTAKING BY THE SURVEYOR

I confirm that I have carried out the Survey of the property properly as per the fair professional best practices and Valuation & Survey policy guidelines issued by R.K Associates. I have not taken any cash or kind from the customer nor have I come into any kind of influence of the customer / bank for arbitrary providing the Property Valuation as per one's need. I further state that I have not given any assurances to the customer nor given any wrong or false information or statement. In case at any point of time it is found that I have done any kind of fraudulent activity in this case and misled the company then I understand its legal consequences and appropriate penal action which company can take against me. Also in regard to it any monetary or reputation loss will be recovered from me by the company.

For File No.	VX5(23-24)PL559-475-725
Surveyor Name	Avit Bhanji
Signature	Ahax
Date	20/12/23.



# SURVEY SUMMARY SHEET (TO BE ENCLOSED WITH VALUATION REPORT)

(Version 1.0) | Date of implementation, 10.04.2017

Every Valuation report at R.K. Associates is prepared based on the thorough survey of the property carried out by our Engineering Surveyor. This Survey Summary Sheet is for the information of Banker/ concerned interested organization. Detailed Survey Form can also be made available to the interested organization of case it is required to cross check what information our surveyor has given in site inspection report based on which Valuation report is prepared.

1.	File No.	NJS (2015-24) 1 509-113			
2.	Name of the Surveyor	VIS (2015-24) 11 559-175-705  Anit Thomas General LID  MIS: To Godham General VIII Come Miller Not			
3.	Borrower Name	mis: I Godinary General IT			
4.	Name of the Owner	MIS. God have Gentlery Patria of Magko			
5.	Property Address which has to be valued	MIS: God have Gens Pit LTT  MIS: God have Gens Pit LTT  MIS: God have Gens Pit LTT  No my No Catra Colomy Nesse arped Gens Property is located and again (atra Colomy) No one was available. Property is located and again of the colomy of the			
5.	Property shown & identified by at spot	Owner, Representative,	J NO O		
		could not be done from inside		Contact No.	
		Name	922	7944 568	
		Mr Mukesh	1.2	E COLUMN TO THE PARTY OF THE PA	
7.	How Property is Identified by the	My My Mesh  From schedule of the properties mentioned in the deed, From name plate displayed on the property, V Identified by the owner/ owner representative displayed on the property. Identification of the property could not be appole.			
	Surveyor	displayed on the property, Wildentification of the property could not be			
		required from nearby people,			
		✓ Yes, ☐ No. No relevant papers available to match the boundary			
		Yes, No, No relevant papers available			
8.	Are Boundaries matched	W Yes, □ No.  Boundaries not mentioned in available documents  Boundaries not mentioned in available documents  Boundaries not mentioned in available documents			
		☐ Boundaries not mentioned in available  Full survey (inside out with measurements & photographs)  Form outside & photographs)			
9.	Survey Type	- VC /Measurements from outs			
		☐ Only photographs taken (No measurements) ☐ Only photographs taken (No measurements)			
		Indeed   Possessee die.			
10.	Reason for Half survey or only	property was locked, a Property was locked, be surveyed completely property so couldn't be surveyed completely so couldn't be surveyed completely so couldn't be surveyed completely so couldn't be su			
10.	photographs taken	property so couldn't be surveyed completely property so couldn't b			
11.	Type of Property	☐ Flat in Multistoried Apartment, ☐ Residential House, ☐ Commercial Office  Residential Builder Floor, ☐ Commercial Land & Building, ✓ Commercial Office  Residential Builder Floor, ☐ Shopping Mall, ☐ Hotel, ☐ Industrial			
11.		Residential Builder Floor, Commercial Land & Building,  Commercial Shop, Commercial Floor, Shopping Mall, Hotel, Industrial  Commercial Shop, Vacant Residential Plot, Vacant Industrial			
		Commercial Shop, ☐ Commercial Floor, ☐ Shopping Wash			
		☐ Institutional, ☐ School Building, ☐ Vacant			
		- thulland			
		Sample measurement, LI No measurement			
12.	Property Measurement	☐ Self-measured, (a) Sample Management and required ☐ It's a flat in multi storey building so measurement not required ☐ NPA property so			
13.	Reason for no measurement	☐ It's a flat in multi storey building so measurement not required. ☐ NPA property so ☐ Property was locked, ☐ Owner/ possessee didn't allow it, ☐ NPA property of the proper			
	Le report de	☐ Property was locked, ☐ Owner/ possessee didn't another, didn't enter the property, ☐ Very Large Property, practically not possible to measure the area within limited time ☐ Any other Reason:			
				As per site survey	
-	Land Area of the Property	As per Title deed	As per Map	The part of the pa	
14.	Land Area of the Froperty	,			
15.	Covered Built-up Area	As per Title deed	As per Map	As per site survey	
		2865 895		5200 70/4	
	II the state of	As per Title deed  As per Title deed  2 8 6 5 Sq (7)  1 Owner, L. Vacant, L. Lessee, L. Under Construction, L. Couldn't be Survey  1 Preparty was locked L. Bank sealed, L. Court sealed			
16.	Property possessed by at the time of survey   Vacant,   Lessee,   Under Construction   Property was locked,   Bank sealed,   Court sealed				
21 10 2	survey	The state of the s			
7	Any negative observation of the				

properly during survey
is elilependent arcess available to
the property
is appearly clearly demandated with
personnels Desardance?
in properly recipili problinded,
with any infer property
(acal Information References on
property rates.)

Clear independent access is available, 

Access available in sharing of other adjoining memory. 

No clear access is available, 

Access is closed due to dispute 

Ves. No. Only with Temporary boundaries

No.

Please refer at sched sheet named. Property rate Information Details."

#### Endersement.

### Signature of the Person who was present from the owner side to identify the property:

Undertaking I have shown the correct property and provided the correct information about the property to the surveyor of R.K. Associates to the best of my knowledge for which Valuation has to be prepared. In case I have shown wrong property or misled the valuer company in any way then I'll be solely responsible for this unlawful act.

Name of the Person Trit Mr Mykosh

mukest,

The signed then mention the reason for it. I No one was available, I Property is locked, I Owner/

#### Surveyor Signature who did site inspection:

Undertaking: I have inspected the property and cross verified the property details at site to the extent of a. Matching boundaries of the property, b. Sample measurement of its area, c. Physical condition, d. Property rates as per local information with what is mentioned in the property documents provided to me by the Bank/merested organization. I have not come under influence of anyone during site inspection and have only retorted the true and factual details in the survey form which I come across during the site survey. I and that giving any manipulative information in the survey form will lead to incorrect Valuation report which is an unlawful act and i'll be solely responsible for doing it.

Name of the Surveyor

Signature

Date