

File No.	RKA/DNCR/
Date of Receiving	3/10/24
File Receiver Name	Anil Bhargava

CASE COLLECTION FORM

(Version 5.0)
Date of implementation: 9.02.2011 | Last Revision: 30.01.2020 | Latest Revision: 31.10.2020

Items	Assigned To	Assigned to Date	To be completed by date	Submitted On date	Grade	HOD Engg Signature
File Received By	Anil Bhargava	NA	NA			
Survey						
Preparation						

A - Very Good, B - Satisfactory, C - Average, D - Poor, E - Extremely Poor

File Returned to HOD Engg. unprepared due to reason	<input type="checkbox"/> Survey not done properly, <input type="checkbox"/> Survey Form not properly filled, <input type="checkbox"/> Market survey for rates is not properly done, <input type="checkbox"/> Identification is not clearly done, <input type="checkbox"/> Measurement is not properly done, <input type="checkbox"/> Photographs not clearly taken, <input type="checkbox"/> Selfie/ Owner or owner representative photo not taken, <input type="checkbox"/> Owner/ owner representative signature not taken, <input type="checkbox"/> Google Map not taken, <input type="checkbox"/> Survey summary sheet not filled
In case File is returned by the preparer - HOD Engg. comment & Signature	<input type="checkbox"/> Minor defects in the survey hence approved for preparation with warning to Surveyor. Report preparer to collect the missing information on his own
	<input type="checkbox"/> Major defects in the survey Survey has to be done again

GENERAL DETAILS			
1.	Proposal/ Work Order or Ref. No	VIS (24-25) - PL417-367-492	
2.	Type of Service	<input checked="" type="checkbox"/> Valuation Report, <input type="checkbox"/> Construction cost estimate, <input type="checkbox"/> Cost vetting certificate <input type="checkbox"/> Other CE Certificates, <input type="checkbox"/> TEV Report, <input type="checkbox"/> LIE	
3.	Type of customer	<input checked="" type="checkbox"/> Bank <input type="checkbox"/> PSU <input type="checkbox"/> NBFC <input type="checkbox"/> Corporate <input type="checkbox"/> Company <input type="checkbox"/> Private client <input type="checkbox"/> Direct client through Bank	
4.	Bank/ FI/ Organization Name & Address	central bank of India, corporate finance branch, fort, 3rd floor, mmgh building, MG Road fort - Mumbai - 400001	
5.	Case Allotment Officer/ Fees paying party Details	Name Mr. Nikhilesh Mohod	Contact Number 9022949828
		Email Id cbilgb@gmail.com	
6.	Case Type	<input checked="" type="checkbox"/> Case for Fresh Account <input type="checkbox"/> Case for exiting account/ customer	
7.	Fees Details	Amount of Fees 50,000 + 4st	Advance Amount if any Fees will be paid by <input type="checkbox"/> Bank <input checked="" type="checkbox"/> Cash
8.	Billing Details	Billed To Party Name	GSTIN

CASE DETAILS

Residential Unit

1	Type of Property	Residential Unit		
2	Purpose of Valuation/ Assignment	<input checked="" type="checkbox"/> Value assessment of the asset for creating new collateral <small>measured by</small> <input type="checkbox"/> Periodic Re-Valuation for Bank, <input type="checkbox"/> Distress sale for NPA A/c. <input type="checkbox"/> For DRT Recovery purpose, <input type="checkbox"/> Capital Gains Wealth Tax purposes <input type="checkbox"/> Partition purpose, <input type="checkbox"/> General Value Assessment <input type="checkbox"/> Any other:		
3	Owner/ Applicant Details	Name	Contact Number	Email Id
		Mrs. Sushma Ravi Arya.		
4	Account Name	Nachiketa Power & Steel Pvt Ltd		
5	Property Address	Flat No 6902, 69th floor, A Tower, Omkar 1973, Worli, Bandra Marg, Worli Mumbai 400030		
6	Who will coordinate on site for the site survey	Name	Contact Number	
		Mr. Saifce	9773252786	
7	Preferred time of survey	Date	Time	
		4/10/24	11:00 am	
8	Documents Received <small>(Any one ownership document and approved site plan/ map is must)</small>	1. Ownership Documents: <input checked="" type="checkbox"/> Sale Deed, <input type="checkbox"/> Power of Attorney, <input type="checkbox"/> Registered Will, <input type="checkbox"/> Relinquishment Deed, <input type="checkbox"/> Transfer Deed, <input type="checkbox"/> Conveyance Deed, <input type="checkbox"/> Allotment Letter, <input type="checkbox"/> Possession Letter 2. Map: <input type="checkbox"/> Cizra Map, <input type="checkbox"/> Approved Map, <input checked="" type="checkbox"/> Site Plan 3. Utility Bills: <input type="checkbox"/> Electricity Bill & payment receipt, <input type="checkbox"/> Water Bill & payment receipt, <input type="checkbox"/> House Tax demand & payment receipt 4. Any Other document: <input type="checkbox"/> CLU, <input type="checkbox"/> TIR Report, <input type="checkbox"/> Agreement to Sale, <input type="checkbox"/> Old Valuation Report <i>OC Certificate</i> 5. No documents provided: <input type="checkbox"/>		
9	Documents received from	Customer		
10	Special Instructions if any			

I agree to pay the amount mentioned above for the preparation of Valuation Report. I agree that I'll not put pressure on Valuer firm to distort any facts and would not try to influence any member or official of the firm in the ill spirit or to benefit any individual or organization by any means illegitimately.

Customer Signature:

FILE RECEIVER CASE COLLECTION PROCESS COMPLIANCE CHECKLIST

(To be filled by Surveyor)

S.NO.	COMPLIANCE CHECKLIST	STATUS	APPROVER SIGNATURE/ REMARKS IN CASE OF ANY (X)
1.	Is Case collection Form properly filled by Receiver?	✓	
2.	Is purpose of the assignment understood clearly by the receiver?	✓	
3.	Has receiver checked if this is a new case or existing case of the Bank?	✓	
4.	Has receiver fixed the fees with the manager/ client and sent quotation properly or have taken approval of the work over email?	✓	
5.	Has receiver taken proper Work Order/ Email/ CESA form formality?	✓	
6.	In case of private case or for fresh case 50% advance is received?	✓	
7.	Is document checklist email sent to the customer?	✓	
8.	Has the received documents is having 'documents provided by stamp'?	✓	

IMPORTANT INSTRUCTIONS TO SURVEYOR

- Please fill the above compliance checklist before moving for the survey.
- Please do not do the survey if you do not have proper documents.
- For Vacant Plot/ Land – Cizra Map/ Master/ Zonal/ Site Plan is must to identify the Plot. For Agriculture or converted land from agriculture – Mutation documents, CLU is must.
- Firstly please first study the documents of the property which needs to get surveyed.
- Mark the **Owner/ Area/ Boundaries** mentioned in the ownership documents with bold florescent marker pen before moving for the survey. **During site survey if any difference is found in the above fields from the ownership documents then please contact the owner immediately to know the reason for the difference.**
- Confirm ongoing property rates in the subject location through public domain, property sites and contact dealers to show you the available properties in that area during your survey.
- Identify the Property clearly by matching the boundaries and area mentioned in the property papers.**
- Do sample physical or google measurements of the property.**
- PHOTOGRAPH INSTRUCTIONS:**
 - Take owner/ representative photograph along with the property.
 - Take your selfie along with the property and the owner/ representative.
 - Take full scale photo of the property with gate.
 - Take photo of the property along with abutting road, towards left, right and center.
 - Take multiple photos of inside-out of the property.
 - Take nearby photographs of the Property.
 - Take a short video to cover property and neighborhood.
- Take Google Map location.
- Check main road name & width and approach road width and distance of property from main road.
- Check Jurisdiction Municipal Limits & Ward Name.
- Fill each column of survey form diligently in detail and tick the appropriate option clearly**
- Check any defects or negativity in the property and comment in detail on survey form.**
- Do extensive market rate enquiries and confirm for any recent past transactions.**
- In case customer appears to be providing misleading information to you or trying to influence you by money or cash then immediately report to the Management & Bank

SURVEY GRADING MATRIX PARAMETERS/ CRITERIA

GRADE

A	In case all the points below are done properly, timely with full care and diligence <ol style="list-style-type: none"> 1. Survey started with proper work order and knowing the source of payment 2. Survey done with proper documents. 3. Done complete homework and studied the documents properly with highlighting the main points before moving for the survey. 4. Chosen correct survey form as per the property type. 5. All fields of Survey form are properly filled. 6. All site special observations and negative and positive factors are clearly mentioned. 7. Self & client signatures taken on survey form. 8. Property rates information properly taken, mentioned and verified. 9. Site rough sketch plan made 10. Proper photographs taken. 11. Selfie with property taken. 12. Selfie and owner photograph with property taken.
B	In case of 3 minor mistakes in any of the above points except Point 1, 2, 3, 4, 6, 8, 10, 11, 12 but all the points are covered.
C	In case of more than 3 minor mistakes and any 1 major mistake in any of the above points and if any points are completely missing except Point 1, 2, 3, 4, 6, 8, 10, 11, 12.
D	In case of 1 major mistake or missing of any 1 point out of 1, 2, 3, 4, 6, 8, 10, 11, 12.
E	In case of more than 1 major mistakes or missing of more than 1 point out of 1, 2, 3, 4, 6, 8, 10, 11, 12.

Note (Survey Grading Matrix):

1. For special assignments like LIE, Stock Valuation, etc. where till date survey format is not specified or released, in such cases point wise site observation report has to be submitted by the Surveyor duly signing it properly. Without signed Site Observation report, Point 4 will be considered as not done and will fall under Category E.
2. Similar Grading Matrix is issued for Case Collection & Report Preparation as well.


Note (Overall Grading Matrix):

1. In case client reports any careless mistake in the report for which revision has to be done in the report then in that case Grading Matrix may be revised and Grade E will be awarded.

SURVEY PROCESS COMPLIANCE CHECKLIST

(To be submitted by Surveyor with each Survey)

Sl. No.	COMPLIANCE CHECKLIST POINTS	STATUS
1.	Did you take proper property documents to carry out the survey?	✓
2.	Have you properly studied & highlighted Owner/ Area/ Boundaries in the property documents with bold florescent before moving for the survey?	✓
3.	Did you check prominent landmark nearby the subject property and mentioned in the survey form?	✓
4.	Did you identified the Property clearly by matching the boundaries and area mentioned in the property papers?	✓
5.	Did you check if property is merged with any other property or it is an independent property?	✓
6.	Did you checked the flat size with eye estimation or based on number of bed rooms?	✓
7.	Did you check for any construction violations in the flat?	✓
8.	Did you check municipal limits/ jurisdiction/ ward?	✓
9.	Did you take Google Map location and shared it to Maps whatsapp group?	✓
10.	Did you check society reputation?	✓
11.	Have you taken property full scale photograph with gate?	✓
12.	Have you taken owner/ representative photograph with the property?	✓
13.	Have you taken your selfie with the property along with owner/ representative?	✓
14.	Have you taken photograph of the society gate along with abutting road and towards left and right of the property?	✓
15.	Have you taken multiple photographs of the property from inside-out?	✓
16.	Did you check nearby development and whereabouts and commented on survey form?	✓
17.	Did you check any defects or negativity in the society & flat in terms of location, legality, disputes, marketability, salability, etc. and commented on survey form in detail?	✓
18.	Have you filled all the columns of survey form including survey summary sheet properly?	✓
19.	Have you taken self-attested documents from owner/ representative and stamped "documents provided by stamp"?	✓
20.	Did you check any defects or negativity in the property in terms of location, legality, disputes, marketability, salability, etc. and commented on survey form in detail?	✓
21.	Have you confirmed any recent past transactions during market enquiries and enquired property rates locally very rigorously?	✓
22.	Did you take signatures of the owner/ representative on undertaking and survey summary sheet?	✓
23.	Did you signed the undertaking?	✓

For File No.	VIS(24-25)P1 417-364-492
Surveyor Name	Amit Bhargi
Signature	
Date	4/10/24

MULTI STORIED FLATS SURVEY FORM

(Version 5.0)

Date of implementation: 09.02.2017 | Date of Revision: 04.01.2018 | Latest Revision: 31.10.2022

File No. RKA/DNCR/...../.....

Date:

4/10/24

Time: 11:00 am

GENERAL DETAILS

1	Name of the Surveyor	Anil . V. Bhargava	
2	Property shown by	<input type="checkbox"/> Owner, <input checked="" type="checkbox"/> Representative, <input type="checkbox"/> No one was available, <input type="checkbox"/> Property is locked, survey could not be done from inside	
		Name	Contact No.
		Mr. Saijee .	9773252486
3	Survey Type	<input checked="" type="checkbox"/> Full survey (inside-out with measurements & photographs) <input type="checkbox"/> Half Survey (Measurements from outside & photographs) <input type="checkbox"/> Only photographs taken (No measurements)	
4	Reason for Half survey or only photographs taken	<input type="checkbox"/> Property was locked, <input type="checkbox"/> Possessee didn't allow to inspect the property, <input type="checkbox"/> NPA property so couldn't be surveyed completely	
5	How Property is Identified	<input checked="" type="checkbox"/> From schedule of the properties mentioned in the deed, <input type="checkbox"/> From name plate displayed on the property, <input checked="" type="checkbox"/> Identified by the owner, owner representative, <input type="checkbox"/> Enquired from nearby people, <input type="checkbox"/> Identification of the property could not be done, <input type="checkbox"/> Survey was not done	
6	Property Measurement	<input checked="" type="checkbox"/> Self-measured, <input checked="" type="checkbox"/> Sample measurement only, <input type="checkbox"/> No measurement	
7	Purpose of Valuation	<input checked="" type="checkbox"/> Value assessment of the asset for creating collateral mortgage, <input type="checkbox"/> Periodic Re-Valuation for Bank, <input type="checkbox"/> Distress sale for NPA A/c., <input type="checkbox"/> For DRT Recovery purpose, <input type="checkbox"/> Capital Gains Wealth Tax purpose <input type="checkbox"/> Partition purpose, <input type="checkbox"/> General Value Assessment	
8	Type of Loan	<input type="checkbox"/> Housing Loan, <input type="checkbox"/> Housing Take Over Loan, <input type="checkbox"/> Home Improvement Loan, <input type="checkbox"/> Loan against Property, <input type="checkbox"/> Construction Loan, <input type="checkbox"/> Educational Loan, <input type="checkbox"/> Car Loan, <input type="checkbox"/> Project Loan, <input type="checkbox"/> Term Loan, <input type="checkbox"/> CC Limit enhancement, <input type="checkbox"/> Cash Credit Limit, <input type="checkbox"/> Industrial Loan, <input type="checkbox"/> NA	
	Loan Amount		

OWNERSHIP DETAILS

1	Legal Owner Name/s	M/s. Nachiketa Power & Steel Pvt Ltd.
2	Property Purchaser Name	Sushma Ravi Arya.
3	Property Address under Valuation	6th floor, A Tower, Omkar, 1973, Worli, Bandra
4	Present Residence Address of the Owner/ Purchaser	Bandra, Worli, Mumbai - 400050.

LOCATION DETAILS

Adjoining Properties

(Match it with papers with the help of compass or Sun direction and also confirm it with nearby people)

North

South

East

West

Obseoi 360

Nahalamy
SRACenturion
Mills.Hind cycle
Marg

2. Property Facing

- ☐ East Facing, ☐ North Facing, ☒ West Facing, ☐ South Facing
☐ North-East Facing, ☐ South-West Facing, ☐ South-East Facing
☐ North-West Facing

3. Landmark

4. Ward Name/ No.

Omkae 1073

5. Zone Name

6. Main Road Name & Width

Name

Width

Distance from property

Pandurang bukar

70 fts

100 mtrs

7. Approach Road Name & Width

Hind cycle Marg - 30 fts

8. Location consideration of the Society

- ☒ Within Main city, ☐ Within Good Urban developed Area, ☐ Within developing area, ☒ Highly posh locality, ☐ Very Good, ☐ Good,
☐ Ordinary, ☐ In interiors, ☐ Remote area, ☐ Backward, ☐ Average,
☐ Poor

9. Location of the Flat

- ☐ Park Facing, ☐ Pool Facing, ☒ Road Facing, ☐ Entrance North East Facing, ☒ Sunlight facing

10. Characteristics of the Locality

- ☐ Urban developed, ☒ Urban developing, ☐ Semi Urban, ☐ Rural
☐ Backward, ☐ Industrial, ☐ Institutional

11. Proximity to civic amenities

School

Hospital

Market

Metro

Railway Station

Airport

0.4 km

0.3 km

0.5 km

-

2 km

15 km

12. Any new Development in surrounding area

Real estate, PWD,

13. Jurisdiction limits

- ☐ Nagar Nigam, ☐ Nagar Panchayat, ☐ Gram Panchayat
☒ Nagar Palika Parishad, ☐ Area not within any municipal limits

14. Jurisdiction Development Authority Name

- ☐ DDA, ☐ GDA, ☐ NOIDA, ☐ GNIDA, ☐ YEIDA, ☐ HUDA, ☐ KMDA
☐ MDDA, ☐ Any other Development Authority: Mumbai Jurisdiction
☐ Area not within any development authority limits

15. Municipal Corporation Name

- ☐ NDMC, ☐ SDMC, ☐ EDMC, ☐ Ghaziabad Municipal Corporation
☐ Gurgaon Municipal Corporation, ☐ Faridabad Municipal Corporation
☐ Kolkata Municipal Corporation, ☐ Dehradun Municipal Corporation
☐ Area not within any municipal limits, ☐ Any other Municipal Corporation
 Municipality: BMC

PHYSICAL DETAILS

	Covered Area, <input type="checkbox"/> Floor Area, <input type="checkbox"/> Super Area, <input checked="" type="checkbox"/> Carpet Area
	As per Title deed As per Map As per site
1 Covered Built-up Area (Tick one on the basis of which valuation is to be calculated)	212172 sqft 2172 sqft 1950 sqft
2 Are Boundaries matched	<input checked="" type="checkbox"/> Yes, <input type="checkbox"/> No
3 Is independent access available to the property?	<input checked="" type="checkbox"/> Clear independent access is available, <input type="checkbox"/> Access available, sharing of other adjoining property, <input type="checkbox"/> No clear access is available <input type="checkbox"/> Access is closed due to dispute
4 Is the property merged or colluded with any other property	No
5 Construction Status	<input type="checkbox"/> Built-up property in use, <input checked="" type="checkbox"/> Under construction, <input type="checkbox"/> Construction not started Internal work pending
6 Total Number of Floors in the Building	3 level basement + 4 + 3rd floor to 10th podium 10th to 16th podium + 16th to 75th floor.
7 Floor on which Flat is situated	69th floor
8 Type of Flat	Residential Unit
9 Age of Building/ Recent Improvements done	8 yrs
10 Type of Group Housing Society	<input checked="" type="checkbox"/> High End, <input type="checkbox"/> Normal, <input type="checkbox"/> Affordable Group Housing
11 Appearance/ Condition of the Building	Internal - <input checked="" type="checkbox"/> Excellent, <input checked="" type="checkbox"/> Very Good, <input type="checkbox"/> Good, <input type="checkbox"/> Ordinary, <input type="checkbox"/> Average, <input type="checkbox"/> Poor <input type="checkbox"/> Under construction, <input type="checkbox"/> No construction, <input type="checkbox"/> No Survey External - <input checked="" type="checkbox"/> Excellent, <input type="checkbox"/> Very Good, <input type="checkbox"/> Good, <input type="checkbox"/> Ordinary, <input type="checkbox"/> Average, <input type="checkbox"/> Poor <input type="checkbox"/> Under construction, <input type="checkbox"/> No construction
12 Maintenance of the Building	<input checked="" type="checkbox"/> Very Good, <input type="checkbox"/> Average, <input type="checkbox"/> Poor
13 Fixed Wooden Work Internal work to be done	<input type="checkbox"/> Excellent, <input type="checkbox"/> Very Good, <input type="checkbox"/> Good, <input type="checkbox"/> Simple, <input type="checkbox"/> Ordinary, <input type="checkbox"/> Average, <input type="checkbox"/> Below Average, <input type="checkbox"/> No wooden work, <input type="checkbox"/> No survey
14 Interior decoration	<input type="checkbox"/> Excellent, <input type="checkbox"/> Very Good, <input type="checkbox"/> Good, <input type="checkbox"/> Simple, <input type="checkbox"/> Ordinary, <input type="checkbox"/> Average, <input type="checkbox"/> Below Average, <input type="checkbox"/> No wooden work, <input type="checkbox"/> No Survey
15 Any defects in the Group Housing Society	No
16 Any violation done in the flat	No
17 Utilities/ Facilities in the Group Housing Society	<input checked="" type="checkbox"/> Lifts, <input checked="" type="checkbox"/> Garden, <input checked="" type="checkbox"/> Landscaping, <input checked="" type="checkbox"/> Swimming Pool, <input checked="" type="checkbox"/> Gym, <input checked="" type="checkbox"/> Club House, <input type="checkbox"/> Walk Trails, <input type="checkbox"/> Kids play zone, <input type="checkbox"/> 100% Power Backup
18 Property currently possessed by	<input checked="" type="checkbox"/> Owner, <input type="checkbox"/> Vacant, <input type="checkbox"/> Lessee, <input type="checkbox"/> Under Construction, <input type="checkbox"/> Couldn't be Surveyed, <input type="checkbox"/> Property was locked, <input type="checkbox"/> Bank sealed, <input type="checkbox"/> Court sealed

Current activity carried out in the property work going on

Special Comments if any Internal work is going on yet to be completed.

☒ Residential purpose, ☐ Commercial purpose, ☐ Godown,
☐ Office, ☐ Vacant, ☐ Locked, ☐ Any other use:

MARKETABILITY/SELABILITY/UTILITY DETAILS	
1. Reputation/ class of developer	<input checked="" type="checkbox"/> Very Good, <input type="checkbox"/> Good, <input type="checkbox"/> Average, <input type="checkbox"/> Low, <input type="checkbox"/> Poor
2. Reputation of society	<input checked="" type="checkbox"/> Very Good, <input type="checkbox"/> Good, <input type="checkbox"/> Average, <input type="checkbox"/> Low, <input type="checkbox"/> Poor
3. Any issues in marketability of the property?	<input type="checkbox"/> Yes, <input checked="" type="checkbox"/> No Reason in case of No: <input type="checkbox"/> Location, <input checked="" type="checkbox"/> Surrounding, <input type="checkbox"/> Legal aspects, <input checked="" type="checkbox"/> Demand, <input checked="" type="checkbox"/> Shape, <input type="checkbox"/> Any Other:
4. How is Demand & Supply condition in the Market of such properties?	Demand <input checked="" type="checkbox"/> Very Good, <input type="checkbox"/> Good, <input type="checkbox"/> Average, <input type="checkbox"/> Low, <input type="checkbox"/> Poor Supply <input checked="" type="checkbox"/> Very Good, <input checked="" type="checkbox"/> Good, <input type="checkbox"/> Average, <input type="checkbox"/> Low, <input type="checkbox"/> Poor
5. Is property easily sellable & marketable?	<input checked="" type="checkbox"/> Yes, <input type="checkbox"/> No Comments: <u>It is the posh Area & costliest Place in Mumbai for Residential & commercial purpose.</u>
6. How is the current utility of the property?	<input type="checkbox"/> Excellent, <input checked="" type="checkbox"/> Very Good, <input type="checkbox"/> Good, <input type="checkbox"/> Average, <input type="checkbox"/> Low, <input type="checkbox"/> Poor
7. At what True rate Owner bought this Property?	Year of purchase Purchase Price

USE THIS SPACE FOR PROVIDING ANY ADDITIONAL DETAILS/ INFORMATION

Parking lots

① flat No 6902 :- Podium - 05
Space No : 114 & 115.

② flat No 6903 :- Podium - 05
Space No : 108 & 109.

③ flat No 6904 :- Podium - 05
Space No :- 112 & 113.

④ flat No 6905 :- Podium 05
Space No :- 110 & 111.

PROPERTY MARKET COMPARABLE RATE INFORMATION DETAILS

(Available for Sale or Transaction already happened in past)

S.No	Particulars	Subject Property	Comparable 1	Comparable 2	Comparison
1.	Name (source of information)	NA	Panchava Properties	Fortune Realty	
2.	Contact No.	NA	9987505593	9892602882	
3.	Type of source of information (Seller/ Property dealer/ nearby people)	NA	Property dealer	Property dealer	
4.	Rates/ Price informed	NA	80k - 1L / sq ft	75k - 1L / sq ft	
5.	Rates Type (Sale/ Buy)	NA	Sale	Sale	
6.	Area/ Size of the Flat		2500 sq ft	3000 - 3500 sq ft	
7.	Legal Status (clear, negative, weak)/ No. of owners		Clear.	Clear.	
8.	Location/ surrounding/ neighborhood comparison with the subject property (Similar, Lower, Better, Highly Better than the subject Property)	Base Case	Similar. Standard. luxury flats.	Similar. luxury Standard	
9.	Distance from the subject Property	0	0.3 to 0.5 KM.	0.2 km	
10.	Society comparison (Similar, Lower, Better, Highly Better than the subject society)		Similar	Similar	
11.	Other factors (Corner, 2 side open, North-East facing, Park facing, Legal/ Financial encumbrance, etc.)		-		
12.	Any other details/ Discussion held	NA	Rates Confirmed are between the project of Oberoi 360 Raheja, & Cordia	11.11	
13.	Present expected Sale Value of the overall property?				

Flat having 2 Parking lot each Value of 30,00,000/- X 2 = 50,00,000/-

UNDERTAKING BY THE CUSTOMER

I confirm that I have made the inspection of the subject property to the surveyor of R K Associates, which is correct property in question for which the documents have been provided/ submitted by me. I further confirm that I am aware of all the information related to the subject property and I have provided all its information to the surveyor true to the best of my knowledge. I understand that any false or manipulative information provided by me will be considered as cheating with the professional organization since it will lead to incorrect valuation report and I'd be solely responsible for this unlawful act and will bear the charges for the changes/modifications which have to undergo due to the false information. I also undertake that I have not given any cash or in kind to any member of R K Associates to influence the Value of the Property or favor any individual or organization and the same is not accepted or asked by the member of R K Associates. Any such act will lead to cancellation of the material prepared by R K Associates with forfeiting of the fees and I'll be completely responsible for its repercussions and legal actions taken for it.

IMPORTANT: We have not authorized any of our person/ Surveyor to take Cash or kind from the customers in any situation. In case Surveyor or any member of R K Associates asks for any money or kind from you then kindly please inform on number +91-9958632707, 0120-4110117. Our Valuation process is very stringent and have multiple check points to ensure correct & error free reports to keep the lending agency risk free. In case Surveyor claims that he would be able to arbitrary effect the Valuation figures unfairly or as per your requirement & need, then he is making a false claim to you and we request you to complaint such act immediately on the number provided above.

Name	Mr Ranje
Relationship with owner	Employee.
Signature	Ranje
Mobile No.	97732 52186.
Date	4/10/24

UNDERTAKING BY THE SURVEYOR

I confirm that I have carried out the Survey of the property properly as per the fair professional best practices and Valuation & Survey policy guidelines issued by R K Associates. I have not taken any cash or kind from the customer nor have I come into any kind of influence of the customer / bank for arbitrary providing the Property Valuation as per one's need. I further state that I have not given any assurances to the customer nor given any wrong or false information or statement. In case at any point of time it is found that I have done any kind of fraudulent activity in this case and misled the company then I understand its legal consequences and appropriate penal action which company can take against me. Also in regard to it any monetary or reputation loss will be recovered from me by the company.

For File No.	N/SR4-25/P2417-36A - 492
Surveyor Name	Amit Bhargava
Signature	Amit Bhargava
Date	4/10/24

SURVEY SUMMARY SHEET

(TO BE ENCLOSED WITH VALUATION REPORT)

(Version 1.0) | Date of Implementation: 10.04.2017

Every Valuation report at RKK Associates is prepared based on the thorough survey of the property carried out by our Engineering Surveyor. This Survey Summary Sheet is for the information of Banker/ concerned interested organization. Detailed Survey Form can also be made available to the interested organization in case it is required to cross check what information our surveyor has given in site inspection report based on which Valuation report is prepared.

1.	File No.	V45CP4-25) P1413-367-492
2.	Name of the Surveyor	Arpit V. Bhargava
3.	Borrower Name	Architeta Source 2 Steel Pvt Ltd.
4.	Name of the Owner	Bushma Rajesh Bala
5.	Property Address which has to be valued	Flat No 6902, 2nd Floor, A Tower, on Kar MH3, Vols Bhubanag, Subkar Nagar, Mumbai - 400030.
6.	Property shown & identified by at spot	<input type="checkbox"/> Owner, <input checked="" type="checkbox"/> Representative, <input type="checkbox"/> No one was available, <input type="checkbox"/> Property is locked, survey could not be done from inside
7.	How Property is identified by the Surveyor	Name <u>Me Rajee</u> Contact No. <u>9773252486</u> <input checked="" type="checkbox"/> From schedule of the properties mentioned in the deed, <input type="checkbox"/> From name plate displayed on the property, <input checked="" type="checkbox"/> Identified by the owner/ owner representative, <input type="checkbox"/> Inquired from nearby people, <input type="checkbox"/> Identification of the property could not be done, <input type="checkbox"/> Survey was not done
8.	Are Boundaries matched	<input checked="" type="checkbox"/> Yes, <input type="checkbox"/> No, <input type="checkbox"/> No relevant papers available to match the boundaries, <input type="checkbox"/> Boundaries not mentioned in available documents
9.	Survey Type	<input checked="" type="checkbox"/> Full survey (inside out with measurements & photographs) <input type="checkbox"/> Half Survey (Measurements from outside & photographs) <input type="checkbox"/> Only photographs taken (No measurements)
10.	Reason for Half survey or only photographs taken	<input type="checkbox"/> Property was locked, <input type="checkbox"/> Possessee didn't allow to inspect the property, <input type="checkbox"/> NPA property so couldn't be surveyed completely
11.	Type of Property	<input checked="" type="checkbox"/> Flat in Multistoried Apartment, <input type="checkbox"/> Residential House, <input type="checkbox"/> Low Rise Apartment, <input type="checkbox"/> Residential Builder Floor, <input type="checkbox"/> Commercial Land & Building, <input type="checkbox"/> Commercial Office, <input type="checkbox"/> Commercial Shop, <input type="checkbox"/> Commercial Floor, <input type="checkbox"/> Shopping Mall, <input type="checkbox"/> Hotel, <input type="checkbox"/> Industrial, <input type="checkbox"/> Institutional, <input type="checkbox"/> School Building, <input type="checkbox"/> Vacant Residential Plot, <input type="checkbox"/> Vacant Industrial Plot, <input type="checkbox"/> Agricultural Land
12.	Property Measurement	<input type="checkbox"/> Self-measured, <input checked="" type="checkbox"/> Sample measurement, <input type="checkbox"/> No measurement
13.	Reason for no measurement	<input checked="" type="checkbox"/> It's a flat in multi storey building so measurement not required <input type="checkbox"/> Property was locked, <input type="checkbox"/> Owner/ possessee didn't allow it, <input type="checkbox"/> NPA property so didn't enter the property, <input type="checkbox"/> Very Large Property, practically not possible to measure the area within limited time <input type="checkbox"/> Any other Reason:
14.	Land Area of the Property	As per Title deed As per Map As per site survey
15.	Covered Built up Area	As per Title deed As per Map As per site survey
16.	Property possessed by at the time of survey	<input checked="" type="checkbox"/> Owner, <input type="checkbox"/> Vacant, <input type="checkbox"/> Lessee, <input type="checkbox"/> Under Construction, <input type="checkbox"/> Could not be surveyed
17.	Any negative observation of the	Property was locked, <input type="checkbox"/> Bank sealed, <input type="checkbox"/> Court sealed No Negative Observation.

property during survey	
18. Is Independent access available to the property	<input checked="" type="checkbox"/> Clear independent access is available, <input type="checkbox"/> Access available in sharing with adjoining property, <input type="checkbox"/> No clear access is available, <input type="checkbox"/> Access is closed due to other reasons
19. Is property clearly demarcated with permanent boundaries?	<input checked="" type="checkbox"/> Yes, <input type="checkbox"/> No, <input type="checkbox"/> Only with Temporary boundaries
20. Is the property merged or colluded with any other property	No.
Local Information References on property rates	Please refer attached sheet named 'Property rate Information Details.'

Endorsement:

1. Signature of the Person who was present from the owner side to identify the property:

Undertaking: I have shown the correct property and provided the correct information about the property to the surveyor of R K Associates to the best of my knowledge for which Valuation has to be prepared. In case I have shown wrong property or misled the valuer company in any way then I'll be solely responsible for this unlawful act.

- a. Name of the Person: Mr. Rajee
b. Relation: employee
c. Signature: *Rajee*
d. Date: 4/10/24.

In case not signed then mention the reason for it: ☐ No one was available, ☐ Property is locked, ☐ Owner/representative refused to sign it, ☐ Any other reason:

2. Surveyor Signature who did site inspection:

Undertaking: I have inspected the property and cross verified the property details at site to the extent of a. Matching boundaries of the property, b. Sample measurement of its area, c. Physical condition, d. Property rates as per local information with what is mentioned in the property documents provided to me by the Bank/interested organization. I have not come under influence of anyone during site inspection and have only recorded the true and factual details in the survey form which I come across during the site survey. I understand that giving any manipulative information in the survey form will lead to incorrect Valuation report which is an unlawful act and I'll be solely responsible for doing it.

- a. Name of the Surveyor: Amit Bhargava
b. Signature: *Amit Bhargava*
c. Date: 4/10/24.