

Date : 06 / 11 / 2019

STRUCTURAL FITNESS REPORT

Client: Mittal Bhawan I.

At Kemps Corner, MUMBAI. 4000 .


Structural Audit Report for the society building has been carried out by us in the month of October 2019.

The clients have successfully carried out the internal as well as external structural repairs to the building. All the defects, which were noticed and enumerated by us in the above report have been attended by the society in a proper manner.

We hereby certify that these repairs have been carried out Under our guidance and supervision by us, during its execution by the contractors.

OUR OPINION

In our view, it is our opinion, that the said building structure of Mittal Bhawan is safe and stable from the STRUCTURAL STABILITY point for its intended use as residential building.


M.P.SACHDEV.

(Regn. No. STR/S/122)

