V25 (2024-25) - 82660 -591 - 8	29 - MIS Jai Shiva Infra JV REINFORCING YOUR BUSINESS
File No. VIS-2020 PL-	M ASSOCIATES
Date of Receiving	VALUERS & TECHNO ENGINEERING CONSULTANTS (P) LTD.
File Receiver Name	

CASE COLLECTION FORM (Version 5.0) Date of implementation: 9.02.2011 | Last Revision: 30.01.2020 | Latest Revision: 31.10.2020

	Items	Assigne	ed To	Assigned to Date	To be completed by date	Submitted On date	Grade	HOD Ei Signat	STATE OF THE PARTY OF THE PARTY.
File Received By			24	NA	NA				
Survey		Lam	8-1-25	15-1-25					
Preparation			- ((
	A - Very Good, E		A II	Contract of the Party of the Contract of the C					17
File Returned to HOD Engg. unprepared due to reason □ Survey not done properly, □ Survey Form not properly filled, □ Market survey rates is not properly done, □ Identification is not clearly done, □ Measurement is properly done, □ Photographs not clearly taken, □ Selfie/ Owner or or representative photo not taken, □ Owner/ owner representative signature not taken Google Map not taken, □ Survey summary sheet not filled					nt is no r owne				
In case File is returned by the preparer - HOD Engg. comment & Signature Minor defects in the survey hence approved for preparation with warning to Sur Report preparer to collect the missing information on his own. Major defects in the survey. Survey has to be done again.				urveyor					
			7.	GENERA	L DETAILS				
1. Proposal/ Work Order or Ref. No.			Vra	mail	detect	7-1-2	J-		
2.	Type of Service				□ Construction		te, 🗆 Cos	t vetting cert	ificate
3.	Type of custome	r	□ Ban	k	□ PSU	□ NBFC			
4.	Bank/ FI/ Organi Name & Address			100000	ignal Ban	h, Sec 3	, No	ida	
Ę.	Case Allotment (Officer/		Name	Conta	ct Number	1986	Email Id	
	Fees paying part	y Details	Nom	rata La	emi.				
6.	Case Type			Case for Fres	h Account	☐ Case f	or exiting a	account/ cus	tomer
7.	Fees Details		Amou	ınt of Fees	Advance An	nount if any	Fees	will be paid	by
		Rs	1500	so L+CST			☑ Banl	k 🗷 Cu	stomer
8.	Billing Details			Billed To P	arty Name		G	STIN	

		CASE DET	AILS		
1.	Type of Property	Commerced	Shop Und	+	
2.	Purpose of Valuation/ Assignment	Periodic Re-Valuation For DRT Recovery pu	□ Value assessment of the asset for creating new collateral mortgage □ Periodic Re-Valuation for Bank, □ Distress sale for NPA A/c., □ For DRT Recovery purpose, □ Capital Gains Wealth Tax purpose □ Partition purpose, □ General Value Assessment □ Any other:		
3.	Owner/ Applicant Details	Raj Kumor Shor	Contact Number 35888592		
4.	Account Name				
5.	Property Address	Shoff Effree No. 3 Sector Alfha,	Con Sh Floor	in Rosana Tower, -2013/0	
6.	Who will coordinate on site for the site survey	Sinendra Gau		Contact Number 25888 59 23 4	
7.	Preferred time of survey	Date 5-1-	? S Time	12:15 PM	
8.	Documents Received (Any one ownership document and approved site plan/ map is must)	 Ownership Documents: □ Sale Deed, □ Power of Attorney, □ Registered Will, □ Relinquishment Deed, □ Transfer Deed, □ Conveyance Deed, □ Allotment Letter, □ Possession Letter □ Let			
9.	Documents received from	Banker			
10.	Special Instructions if any:				
11.	Valuer firm to distort any fact		e any member or official	I agree that I'll not put pressure on of the firm in the ill spirit or vested	

File No. VIS-20 34-20 25 PL-660 - 591 - 829 - MIS Jai Shive	File No. V	IS-2024-2025 PL-660	-591-	829 -	MIS Jai Shive
-------------------------------------------------------------	------------	---------------------	-------	-------	---------------

	FILE RECEIVER CASE COLLECTION PROC (To be filled by Su	THE RESERVE AND ADDRESS OF THE PARTY OF THE	PLIANCE CHECKLIST
S.NO.	COMPLIANCE CHECKLIST	STATUS	APPROVER SIGNATURE/ REMARKS IN CASE OF ANY (X)
1.	Is Case collection Form properly filled by Receiver?	0	
2.	Is purpose of the assignment understood clearly by the receiver?		
3.	Has receiver checked if this is a new case or existing case of the Bank?	4	
4.	Has receiver fixed the fees with the manager/ client and sent quotation properly or have taken approval of the work over email?	V	
5.	Has receiver taken proper Work Order/ Email/ CESA form formality?	A	
6.	In case of private case or for fresh case 50% advance is received?	~=	
7.	Is document checklist email sent to the customer?	Ā	
8.	Has the received documents is having 'documents		

IMPORTANT INSTRUCTIONS TO SURVEYOR

provided by stamp'?

Mel Mill			
1.	Please fill the above compliance checklist before moving for the survey.		
2.	Please do not do the survey if you do not have proper documents.		
3.	For Vacant Plot/ Land - Cizra Map/ Master/ Zonal/ Site Plan is must to identify the Plot. For Agriculture		
	or converted land from agriculture – Mutation documents, CLU is must.		
4.	Firstly please first study the documents of the property which needs to get surveyed.		
5.	Mark the Owner/ Area/ Boundaries mentioned in the ownership documents with bold florescent		
	marker pen before moving for the survey. During site survey if any difference is found in the above		
	fields from the ownership documents then please contact the owner immediately to know the		
	reason for the difference.		
6.	Confirm ongoing property rates in the subject location through public domain, property sites and contact		
	dealers to show you the available properties in that area during your survey.		
7.	Identify the Property clearly by matching the boundaries and area mentioned in the property		
	papers.		
8.	Do sample physical or google measurements of the property.		
9.	PHOTOGRAPH INSTRUCTIONS:		
	a. Take owner/ representative photograph along with the property.		
	b. Take your selfie along with the property and the owner/ representative.		
	c. Take full scale photo of the property with gate.		
	d. Take photo of the property along with abutting road, towards left, right and center.		
	e. Take multiple photos of inside-out of the property.		
	f. Take nearby photographs of the Property.		
10	g. Take a short video to cover property and neighborhood.		
10.	Take Google Map location.		
11.	Check main road name & width and approach road width and distance of property from main road.		
12.	Check Jurisdiction Municipal Limits & Ward Name.		
13.	Fill each column of survey form diligently in detail and tick the appropriate option clearly.		
14.	Check any defects or negativity in the property and comment in detail on survey form.		
15.	Do extensive market rate enquiries and confirm for any recent past transactions.		
16.	In case customer appears to be providing misleading information to you or trying to influence you by		
	money or cash then immediately report to the Management & Bank.		

	SURVEY GRADING MATRIX		
GRADE	PARAMETERS/ CRITERIA		
Α	In case all the points below are done properly, timely with full care and diligence:		
	 Survey started with proper work order and knowing the source of payment. Survey done with proper documents. Done complete homework and studied the documents properly with highlighting the main points before moving for the survey. Chosen correct survey form as per the property type. All fields of Survey form are properly filled. All site special observations and negative and positive factors are clearly mentioned. Self & client signatures taken on survey form. Property rates information properly taken, mentioned and verified. Site rough sketch plan made. Proper photographs taken. Selfie with property taken. Selfie and owner photograph with property taken. 		
В	In case of 3 minor mistakes in any of the above points except Point 1, 2, 3, 4, 6, 8, 10, 11, 12 but all the points are covered.		
С	In case of more than 3 minor mistakes and any 1 major mistake in any of the above points and if any points are completely missing except Point 1, 2, 3, 4, 6, 8, 10, 11, 12.		
D	In case of 1 major mistake or missing of any 1 point out of 1, 2, 3, 4, 6, 8, 10, 11, 12.		
E	In case of more than 1 major mistakes or missing of more than 1 point out of 1, 2, 3, 4, 6, 8, 10, 11, 12.		

Note (Survey Grading Matrix):

- For special assignments like LIE, Stock Valuation, etc. where till date survey format is not specified or released, in such cases point wise site observation report has to be submitted by the Surveyor duly signing it properly. Without signed Site Observation report, Point 4 will be considered as not done and will fall under Category E.
- 2. Similar Grading Matrix is issued for Case Collection & Report Preparation as well.

Note (Overall Grading Matrix):

 In case client reports any careless mistake in the report for which revision has to be done in the report then in that case Grading Matrix may be revised and Grade E will be awarded.

	SURVEY PROCESS COMPLIANCE CHECKLIST (To be submitted by Surveyor with each Survey)	
S.NO.	COMPLIANCE CHECKLIST POINTS	STATUS
1.	Did you take proper property documents to carry out the survey?	JATOS
2.	Have you properly studied & highlighted Owner/ Area/ Boundaries in the property documents with bold florescent before moving for the survey?	
3.	Did you check prominent landmark nearby the subject property and mentioned in the survey form?	12
4.	Did you identified the Property clearly by matching the boundaries and area mentioned in the property papers?	
5.	Did you check if property is merged with any other property or it is an independent property?	
6.	Did you do sample physical or google measurements of the property in case of property more than 2500 sq.mtr?	4
7.	Did you check for any building violations in the property?	V
8.	Did you check municipal limits/ jurisdiction/ ward?	1
9.	Did you take Google Map location and shared it to Maps whatsapp group?	10
10.	Did you check Main road name & width and its distance from the subject property?	10
11.	Did you check approach Lane width on which property is located?	0
12.	Have you taken property full scale photograph with gate?	
13.	Have you taken owner/ representative photograph with the property?	0
14.	Have you taken your selfie with the property along with owner/ representative?	10
15.	Have you taken photograph of the property along with abutting road and towards left and right of the property?	Ā
16.	Have you taken multiple photographs of the property from inside-out?	4
17.	Did you check nearby development and whereabouts and commented on survey form?	V
18.	Did you check any defects or negativity in the property in terms of location, legality, disputes, marketability, salability, etc. and commented on survey form in detail?	
19.	Have you filled all the columns of survey form including survey summary sheet properly?	Ø
20	Did you draw site key plan (location map)?	V
21.	Did you draw rough site sketch plan?	4
22.	Have you taken self-attested documents from owner/ representative and stamped "documents provided by stamp"?	
23.	Did you check any defects or negativity in the property in terms of location, legality, disputes, marketability, salability, etc. and commented on survey form in detail?	
24.	Have you confirmed any recent past transactions during market enquiries and enquired property rates locally very rigorously?	W
25.	Did you take signatures of the owner/ representative on undertaking and survey summary sheet?	1
26.	Did you signed the undertaking?	

For File No.	VIS (2024-25) - PL660-591-8
Surveyor Name	Shubbary Jush
Signature	Siohi-
Date	15-1-25

GENERAL SURVEY FORM (FOR PROPERTIES OTHER THAN FLATS) (Version 5.0) Date of implementation: 9.02.2011 | Last Revision: 04.01.2018 | Latest Revision: 31.10.2020

File No. VIS-2024-2025 PL-660 - 591-829 Date: 15-1-25 Time: 12:15 Mm

		GENERAL DETAILS		
1.	Name of the Surveyor	Shubbarn Joshi		
2.	Property shown by	☐ Owner, ☐ Representative, ☐ No one was available, ☐ Property		
		locked, survey could not be done fr	om inside ACs Employee	
-		Name	Contact No.	
		Novesh Paroshon	8588859276	
3.	Survey Type	Full survey (inside-out with mea	surements & photographs)	
		☐ Half Survey (Measurements from	m outside & photographs)	
		☐ Only photographs taken (No me	easurements)	
4.	Reason for Half survey or only	☐ Property was locked, ☐ Poss	sessee didn't allow to inspect the	
	photographs taken	property, NPA property so could	n't be surveyed completely	
5.	How Property is Identified	From schedule of the properties	es mentioned in the deed, From	
		name plate displayed on the proper	ty, 'I'dentified by the owner/ owner	
		representative, Enquired from n	earby people,	
		☐ Identification of the property con	uld not be done, □ Survey was not	
		done		
6.	Type of Property		□ Residential House, □ Low Rise	
			er Floor, Commercial Land &	
		Building, Commercial Office,	Commercial Shop, Commercial	
		Floor, ☐ Shopping Mall, ☐ Hotel, ☐	☐ Industrial, ☐ Institutional,	
			ential Plot, ☐ Vacant Industrial Plot,	
		☐ Agricultural Land		
7.	Property Measurement		surement only, No measurement	
8.	Reason for no measurement	☐ It's a flat in multi storey building		
		☐ Property was locked, ☐ Owner/		
		☐ NPA property so didn't enter the	e property, Very Large Property,	
		practically not possible to measure	the entire area □ Any other Reason:	
9.	Purpose of Valuation		or creating new collateral mortgage	
		Periodic Re-Valuation for Bank,		
		☐ For DRT Recovery purpose, ☐		
		☐ Partition purpose, ☐ General Va	alue Assessment	
10.	Type of Loan		Over Loan, Home Improvement	
			Construction Loan, Educational	
			oan, Term Loan, CC Limit	
11	1 - 1	enhancement, Cash Credit Limit	, □ Industrial Loan, □ NA	
11.	Loan Amount			


1.	Legal Owner Name/s	Ray Kumay Charma
2.	Property Purchaser Name	Par Ruma Starma
3.	Property Address under	Shop/Office No. 3 on 5th floor in Kasara Tomer, Sector Alpha, G. Noida -201310
	Valuation	Sector Alpha G. Noida -201310
4.	Present Residence Address of	
	the Owner/ Purchaser	
5.	Property constitution	☐ Free Hold, ☑ Lease Hold
	i i i i i i i i i i i i i i i i i i i	LOCATION DETAILS
1.	Adjoining Properties	East West North South
	(Match it with papers with the help	Office - open, open. I - Stairs
	of compass or Sun direction and	tall (-2) space
	also confirm it with nearby people)	- office 309
2.	Property Facing	☐ East Facing, ☐ North Facing, ☐ West Facing, ☐ South Facing,
		☐ North-East Facing, ☐ South-West Facing, ☐ South-East Facing,
		□ North-West Facing
3.	Landmark	
4.	Ward Name/ No.	Kasana Tower
5.	Zone Name	
6.	Main Road Name & Width	Nome Winter Distance
0.	Ivialii Road Name & Width	Name Width Distance from property
		Sector Alpha Rd. 40 m on Road
7.	Approach Road Name & Width	Alfa Morg 15 m on Road
8.	Location consideration of the	Within Main city, Within Good Urban developed Area, Within
	Society	developing area, □ Highly posh locality, □ Very Good, □ Good
		□ Ordinary, □ In interiors, □ Remote area, □ Backward, □ Average,
		□ Poor
9.	Special Location consideration	☐ Park Facing, ☐ Pool Facing, ☐ Road Facing, ☐ Entrance North-East
	of the property	Facing, □ Sunlight facing
10.	Characteristics of the locality	Urban developed, □ Urban developing, □ Semi Urban, □ Rural,
10.	Onal acteristics of the locality	Orban developed, Orban developing, Senti Orban, Rufai,
		□ Backward, □ Industrial, □ Institutional
11.	Category of Society/ locality	☐ High End, ☐ Normal, ☐ Affordable Group Housing, ☐ EWS, ☐ HIG,
		□ MIG, □ LIG
12.	Utilities/ Facilities in the locality	Lifts, ☐ Garden, ☐ Landscaping, ☐ Swimming Pool, ☐ Gym,
		☐ Club House, ☐ Walk Trails, ☐ Kids play zone, ☑ 100% Power
		Backup
13.	Proximity to civic amenities	School Hospital Market Metro Railway Station Airport
	<u>~</u>	1 km 4 1 km 4 1 km 300 m 9 km m 33 1
14.	Any new development in	m ahamidad To
	surrounding area	No Railway Ji
		Station Str


15.	Jurisdiction limits	✓ Nagar Nigam, ☐ Nagar Panchayat, ☐ Gram Panchayat, ☐ Nagar	
		Palika Parishad, ☐ Area not within any municipal limits	
16.	Jurisdiction Development	□ DDA, □ GDA, □ NOIDA, □ GNIDA, □ YEIDA, □ HUDA, □KMDA,	
	Authority Name	☐ MDDA, ☐ Any other Development Authority:	
		☐ Area not within any development authority limits	
17.	Municipal Corporation Name	□ NDMC, □ SDMC, □ EDMC, □ Ghaziabad Municipal Corporation, □	
		Gurgaon Municipal Corporation, Faridabad Municipal Corporation,	
		Kolkata Municipal Corporation, Dehradun Municipal Corporation,	
		Area not within any municipal limits, Any other Municipal Corporation/	
		Municipality:	
1.	-Land Area	As per Title deed	
	Coverd Area Super		
2.	Any conversion to the land use	1381.97 59 H 1384 34 H 1933 Covered	
	No_	of course area.	
3.	Land Type	Solid, Rocky, Marsh Land, Reclaimed Land, Water	
		logged, □ Land locked	
4.	Shape of the Land	□ Square, 🗹 Rectangular, □ Trapezium, □ Triangular, □ Trapezoid,	
		□ Irregular, □ NA	
5.	Level of Land	♥ On road level, □ Below road level, □ Above road level, □ NA	
6.	Frontage to depth ratio	Normal frontage, ☐ Less frontage, ☐ Large frontage, ☐ NA	
7.	Are Boundaries matched	☐ Yes, ☐ No, ☐ No relevant papers available to match the boundaries,	
		Boundaries not mentioned in available documents	
3.	Is Independent access available	Clear independent access is available, Access available in	
	to the property	sharing of other adjoining property, \square No clear access is available, \square	
		Access is closed due to dispute	
9.	Is property clearly demarcated with permanent boundaries?		
10.	Is the property merged or colluded with any other property	Me .	
11.	Property possessed by at the time of survey	Owner, Vacant, Lessee, Under Construction, Couldn't be Surveyed, Property was locked, Bank sealed, Court sealed	
12.	Current activity carried out in the property	☐ Residential purpose, ☐ Commercial purpose, ☐ Godown, ☐ Office, ☐ Industrial, ☐ Vacant, ☐ Locked, ☐ Any other use:	

1.	Construction Status	Built-up property in use, Under construction, No construction				
2.	Covered Built-up Area	Covered Area, ☐ Floor Area, ☐ Super Area, ☐ Carpe				
		As per Title deed	As per Map	As per site s		
	(Tick one on the basis of which valuation is to be calculated)	998 39 HCO		1032 81 6	1/10	
3.	Total Number of Floors in the		red area)	1, 23,10	a	
0,	Building	B+9+9.				
4.	Floor on which property is situated	Sm floor.				
5.	Type of Unit/ Number of Rooms/ Cabins/ Cubicles	7 Cabins, 2 Wo	rk Stations, 1 Re	ception 1	Panto	
6.	Building Type	RCC Framed Struct	ure, Load bearing F	Pillar Beam colum	n 🗆	
		Ordinary brick wall st	ructure. Iron trus	ses & Pillars	Scran	
		abandoned structure	,	occ a rimars, L	Остар	
7.	Roof	a. Make: 🗆 RBC, 🖹	RCC. GI Shed.	Tin Shed Stor	e Patla	
			Folse lily ht			
		c. Finish: Simple p	laster POD Dunnie	DOD Fold	000	
		□ Coved roof, □ N	lo plaster	19, POP Faise	Celling,	
8.	Flooring	✓ Vitrified tiles, □ Cera		marble Marble	e chine	
		☐ Mosaic, ☐ Granite,	☐ Italian Marble. ☐ I	Kota stone	e cinps,	
		☐ Wooden, ☐ PCC, [guered	
		Tiles, □ Brick Tiles, □	No Flooring, Un	der construction,	Any	
0	A	other type:				
9.	Appearance/ Condition of the	Internal - Excellent,				
	Building	Average, Poor Ur	nder construction,	No Survey		
		External - Excellent,	☐ Very Good, ♥☐ Go	od, Ordinary,		
40		Average, Poor Ur				
10.	Maintenance of the Building	☐ Very Good, ☑ Avera				
11.	Interior decoration	☐ Excellent, ☐ Very Go				
12.	Interior Finishing	Average, Below aver	rage, Under constr	uction, 🗆 No Sur	vey	
12.	interior Finishing	Simple plastered wa	lls, Brick walls with	nout plaster,		
		☐ Designer textured wa		☐ Coved roof,		
10	F.A. S.	☐ Under construction, ☐				
13.	Exterior Finishing	Simple plastered wal				
		Architecturally designed				
		Structural glazing, Al				
14.	Kitchen	☐ Glass façade, ☐ Dor				
		☐ Simple with no cupb Modular with chimney,	oard, □ Ordinary Wi	th cupboard, U	Normal	
		construction, ☐ No Sur		with chimney,	Under	
15.	Class of Electrical fittings	☐ External, 1 Internal	vcy			
		☐ Ordinary fixtures & fitt	tings. Fancy lights	Chandeliers	Hin	
		Concealed lightning, □	Under construction	□ No Survey		
16.	Class of Sanitary/ Plumbing &	☐ External, ☐ Internal	12			
	water supply fittings	☐ Excellent, ☐ Very Go	ood, Good, Sim	ple, Average		
		☐ Below average, ☐ U				
17.	Water arrangements	☐ Jet pump, ☐ Submer	rsible, 🗵 Jal board su	apply		
18.	Fixed Wooden Work	☐ Excellent, ☐ Very Go				
		Average, Below Aver			V	
Part Contract						
19.	Age of Building/ Recent	2009 201	2			

Time Page 9 of 15

20	Maintenance of the Delibline	EV 0 10 ED			
20.	Maintenance of the Building	☐ Very Good, M Average, ☐ Po	the second secon		
21.	Any defects in the building	 ☐ Maintenance issues, ☐ Finishing issues, ☐ Seepage issues, ☐ Water supply issues, ☐ Electricity issues, ☐ Structural issues, ☐ Visible cracks in the building 			
22.	Any violation done in the property	☐ Construction done without Map, ☐ Construction not as per approved Map, ☐ Extra covered without sanctioned Map, ☐ Joined adjacent property, ☐ Encroached adjacent area illegally			
23.	Boundary Wall (Only for individual property)	☐ Yes, ☐ No, ☐ Common boun Running Mtr. Height	dary wall of a complex Width Finish		
24.	Lift/ elevators	Passenger/ Commercial Make:	Capacity:		
25.	Power backup	Inverter, DG Set Make:	Capacity:		
26.	Garden/ Landscaping	☐ Yes, ☐ No, ☐ Beautiful, ☑ O	rdinary		
27.	Parking facilities	☐ Available within the property	¹☑ On Ground, ☒In Basement, ☐ On stilt		
28.	Special Comments/ Observations,	☐ Not available within the property	☐ On road, ☐ Acute parking problem		
Barren	if any				
1.	Any issues in marketability of the	LITY/ SELABILITY/ UTLITY D	ETAILS		
	property?	☐ Yes, ☑ No Reason in case of No: ☑ aspects, ☐ Demand, ☐ Shape,			
2.	How is Demand & Supply condition in the Market of such properties?	Demand ☐ Very Good, ☑ Good, ☐ Average, ☐ Low, ☐ Poor Supply ☐ Very Good, ☑ Good, ☐ Average, ☐ Low, ☐ Poor			
3.	Is property easily sellable & marketable?	✓ Yes, □ No Comments:			
4.	How is the current utility of the property?	☐ Excellent, ☐ Very Good, ☑ 0	Good, □ Average, □ Low, □ Poor		
5.	At what True rate Owner bought this Property?	Year of purchase Purchase Price			
6.	Present expected Sale Value of the overall property?		Indeverything		





	PRUPERTY (Avail)	MARKET CO able for Sale o	MPARABLE RATE INFO	DRMATION DETA	ILS
S.No	Particulars	Subject Property		Comparable 2	Comparable 3
1.	Name (source of information)	NA	Golf View Propertie	x Tilmdi	Alfatah Re
2.	Contact No.	NA	9873434716		1650001
3.	Type of source of information (Seller/ Property dealer/ nearby people)	NA	Property Deder.	Prope	
4.	Rates/ Price informed (in Rs. with unit)	NA	9000-10,000)- psp (ppullo	5 /6	0,000 /- Pol-
5.	Rates Type (Sale/ Buy)	NA	Rude		de
6.	Shape of the Property (Square, Rectangular, Irregular)		Rectangular.	0	Loydon
7.	Area/ Size of the Property		~ 1000 SIH		0
8.	Legal Status (clear, negative, weak)/ No. of owners	-	Clean.	de	100 left
9.	Location/ surrounding/ neighborhood comparison with the subject property (Similar, Lower, Better, Highly Better than the subject Property)	Base Case	Kosana Tourer.	Kosa Toi	
10.	Distance from the subject Property	0	Same Building	Came	Buldy
11.	Other factors (Corner, 2 side open, North-East facing, Park facing, Legal/ Financial encumbrance, etc.)			Same	Mileting
12.	Approach road width		40 m midekd	400	n wide Rd.
13.	Level of Land (Below/ On/ Above road level)		0.0111	an O	sed bul.
14.	Frontage to depth ratio (Normal, Less, Large)		Normal. Comme cial.	Non	1.
15.	Present Use		(000000	1000	
16.	Any other details/ Discussion held	NA	comme cial.	Com	mer'of,
17.	Present expected Sale Value of the overall property?				

UNDERTAKING BY THE CUSTOMER

I confirm that I have made the inspection of the subject property to the surveyor of R.K Associates, which is correct property in question for which the documents have been provided/ submitted by me. I further confirm that I am aware of all the information related to the subject property and I have provided all its information to the surveyor true to the best of my knowledge. I understand that any false or manipulative information provided by me will be considered as cheating with the professional organization since it will lead to incorrect valuation report and I'd be solely responsible for this unlawful act and will bear the charges for the changes/ modifications which have to undergo due to the false information. I also undertake that I have not given any cash or in kind to any member of R.K Associates to influence the Value of the Property or favor any individual or organization and the same is not accepted or asked by the member of R.K Associates. Any such act will lead to cancellation of the material prepared by R.K Associates with forfeiting of the fees and i'll be completely responsible for its repercussions and legal actions taken for it.

IMPORTANT: We have not authorized any of our person/ Surveyor to take Cash or kind from the customers in any situation. In case Surveyor or any member of R.K Associates asks for any money or kind from you then kindly please inform on number +91-9958632707, 0120-4110117. Our Valuation process is very stringent and have multiple check points to ensure correct & error free reports to keep the lending agency risk free. In case Surveyor claims that he would be able to arbitrary effect the Valuation figures unfairly or as per your requirement & need, then he is making a false claim to you and we request you to complaint such act immediately on the number provided above.

Name	Norosty Paroston. 1
Relationship with owner	Employee 1
Signature	Manual Comments
Mobile No.	0500059234
Date	15-1-25

UNDERTAKING BY THE SURVEYOR

I confirm that I have carried out the Survey of the property properly as per the fair professional best practices and Valuation & Survey policy guidelines issued by R.K Associates. I have not taken any cash or kind from the customer nor have I come into any kind of influence of the customer / bank for arbitrary providing the Property Valuation as per one's need. I further state that I have not given any assurances to the customer nor given any wrong or false information or statement. In case at any point of time it is found that I have done any kind of fraudulent activity in this case and misled the company then I understand its legal consequences and appropriate penal action which company can take against me. Also in regard to it any monetary or reputation loss will be recovered from me by the company.

For File No.	VT (2021-28) (111 car ena
Surveyor Name	Shellow Tool '
Signature	and it
Date	18-1-20

UNDERTAKING BY THE PREPARER

I confirm that this Valuation Report is prepared as per the fair professional best practices and Valuation & Survey Policy Guidelines issued by the organization. I also confirm that without any personal interest, partiality or prejudice, I have worked on this Valuation assignment. Rates adopted for the asset is based on various facts, information collected from the site came to my knowledge during the course of the assignment and I have taken all sincere efforts to review, cross check & confirm this data/ information from all different angles using my prudent approach without any biasedness or pressure. I have prepared the report based on true facts & information as per best of my knowledge & case facts. I understand that any false information provided by me will lead to the incorrect valuation report and I'd be solely responsible for it and will bear the losses which will be put on the Company in form of monetary or reputation loss by its client or statutory bodies.

I also undertake that I did not come into any influence by the customer, Bank representative (officer or agent), colleagues, coworkers or any other person to arbitrary change the Valuation figures or facts unethically or illegitimately which may put the public money at risk which is in the form of Bank deposits.

In case at any point of time in future, if I am found guilty of illegitimately distorting the facts in the Valuation or any other professional services which company offers in the market on being influenced by the customer or Bank representative (officer or agent) or for whatsoever reason then I'd solely responsible of any such act and I understand that the Company can take appropriate legal action against me which may include suspension from the current roles & responsibilities or termination from the employment with immediate effect.

I also undertake that I have not taken any cash, favor or in kind from the customer for favoring any individual or organization by unfair means.

I also undertake that I'll not prepare any report on incomplete Survey form which is not properly filled as per the Company guidelines and in case I am preparing it which is creating an incorrect report then I'd be responsible for its consequences.

For File No.	VIS	12021	1-25	1-12	1/20	-591	- 82
Preparer Name			1	0 - 1			
Signature	11						
Date			7 77				





SURVEY SUMMARY SHEET (TO BE ENCLOSED WITH VALUATION REPORT)

(Version 1.0) | Date of implementation: 10.04.2017

Every Valuation report at R.K Associates is prepared based on the thorough survey of the property carried out by our Engineering Surveyor. This Survey Summary Sheet is for the information of Banker/ concerned interested organization. Detailed Survey Form can also be made available to the interested organization in case it is required to cross check what information our surveyor has given in site inspection report based on which Valuation report is prepared.

1.	File No.	1/1(/20/4-20)-81//	0-591-	V) 9
2.	Name of the Surveyor	Shullong Justi	0-211-	02
3.	Borrower Name	Shiptang Josh		
4.	Name of the Owner	faj Kumor Shan	mr.	
5.	Property Address which has to be valued			ma Town, Seta
6.	Property shown & identified by at spot	☐ Owner, ☐ Representative, ☐ No or could not be done from inside	ne was available	e, 🗆 Property is locked, survey
		Name	LAST OF	Contact No.
7.	II- B	Mr. Novesh Paroshor	85	88859236
<i>/</i> .	How Property is Identified by the Surveyor	displayed on the property, dentification of the property of the pr	ied by the own	er/ owner representative,
8.	Are Boundaries matched	☐ Yes, ☐ No, ☐ No relevant pa	pers available	to match the boundaries,
9.	Survey Type	Full survey (inside-out with measure		granhs)
		☐ Half Survey (Measurements from ou☐ Only photographs taken (No measur	itside & photog	
10.	Reason for Half survey or only	☐ Property was locked, ☐ Possessee didn't allow to inspect the property, ☐ NPA		
	photographs taken	property so couldn't be surveyed compl	letely	inspect the property, \(\square\) NPA
1.	Type of Property	☐ Flat in Multistoried Apartment, ☐ R Residential Builder Floor, ☐ Commercial Commercial Shop, ☐ Commercial Floo ☐ Institutional, ☐ School Building, ☐ Plot, ☐ Agricultural Land	esidential Hous al Land & Buildi r, Shopping	ing, Commercial Office, Mall, Hotel, Industrial,
12.	Property Measurement	☐ Self-measured, ☐ Sample measuren	nent 🗆 No me:	asurement
13.	Reason for no measurement	☐ It's a flat in multi storey building so n☐ Property was locked, ☐ Owner/ podidn't enter the property, ☐ Very L measure the area within limited time ☐	neasurement no ossessee didn't arge Property,	ot required allow it, NPA property so practically not possible to
14.	Land Area of the Property	As per Title deed As p	oer Map	As per site survey
5.	Covered Built-up Area		oer Map	As per site survey
6.	Property possessed by at the time of survey	Owner, 🗆 Vacant, 🗆 Lessee, 🗆 Un	der Constructio	on, Couldn't be Surveyed,
7.	Any negative observation of the	☐ Property was locked, ☐ Bank sealed,	☐ Court sealed	
	, garage and the	100		

	property during survey	
18.	Is Independent access available to the property	Clear independent access is available, Access available in sharing of other adjoining property, No clear access is available, Access is closed due to dispute
19.	Is property clearly demarcated with permanent boundaries?	✓ Yes, ☐ No, ☐ Only with Temporary boundaries
20.	Is the property merged or colluded with any other property	No.
21.	Local Information References on property rates	Please refer attached sheet named 'Property rate Information Details.'

Endorsement:

1. Signature of the Person who was present from the owner side to identify the property:

Undertaking: I have shown the correct property and provided the correct information about the property to the surveyor of R.K Associates to the best of my knowledge for which Valuation has to be prepared. In case I have shown wrong property or misled the valuer company in any way then I'll be solely responsible for this unlawful act.

a.	Name of the Person	: Nored Po	who
b.	Name of the Person Relation: Employ	re 1	~

In case not signed then mention the reason for it: \Box No one was available, \Box Property is locked, \Box Owner/ representative refused to sign it, \square Any other reason:

2. Surveyor Signature who did site inspection:

Undertaking: I have inspected the property and cross verified the property details at site to the extent of a. Matching boundaries of the property, b. Sample measurement of its area, c. Physical condition, d. Property rates as per local information with what is mentioned in the property documents provided to me by the Bank/ interested organization. I have not come under influence of anyone during site inspection and have only recorded the true and factual details in the survey form which I come across during the site survey. I understand that giving any manipulative information in the survey form will lead to incorrect Valuation report which is an unlawful act and i'll be solely responsible for doing it.

a. Name of the Surveyor: Shullon Josh' b. Signature: \$25h' c. Date: 15-1-25